

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	7,687 hr & 354,179 km

Type	Scheduled	Due	Started	Closed
	Mar 9, 2024		Mar 9, 2024 4:14 PM	Mar 9, 2024 4:14 PM

Line	Task	Parts	Labor	Total
1	✓ Tires	\$0.00	\$0.00	\$0.00

Notes

#4LH inside flat

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	7,687 hr & 354,179 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 16, 2024	Mar 16, 2024		Mar 16, 2024 1:14 PM	Mar 16, 2024 1:14 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00

Notes

greased t796

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
grease tubes	Kropp Shop		3.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	7,687 hr & 354,179 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 25, 2024	Apr 25, 2024		May 16, 2024 5:38 AM	May 16, 2024 5:38 AM

Line	Task	Parts	Labor	Total
1	✓ Oil Leaking	\$0.00	\$0.00	\$0.00

Notes

Removed silencer from front gear cover, checked baring plug

Checked front gear cover bolts

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Notes

Notes	User	Time
Engine oil leak at front of engine	Trent Court	Apr 25, 2024 1:52 PM

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	7,790 hr & 361,668 km

Type	Created	Scheduled	Due	Started	Closed
Service	May 14, 2024	May 14, 2024		Jun 3, 2024 3:33 PM	Jun 3, 2024 3:33 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ Truck CVIP inspection	\$0.00	\$0.00	\$0.00
3	✓ Replace plastic fenders	\$0.00	\$0.00	\$0.00
4	✓ Hole in windshield washer tank	\$0.00	\$0.00	\$0.00
5	✓ brake pot	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 1131

Cam Nadeau

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	8,226 hr & 361,668 km

Type	Scheduled	Due	Started	Closed
	Jun 6, 2024		Jun 6, 2024 10:45 AM	Jun 6, 2024 10:45 AM

Line	Task	Parts	Labor	Total
1	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	8,226 hr & 369,824 km

Type	Created	Scheduled	Due	Started	Closed
	Jun 18, 2024	Jun 18, 2024		Jun 25, 2024 6:22 PM	Jun 25, 2024 6:22 PM

Line	Task	Parts	Labor	Total
1	✓ Carrier bearing failed	\$0.00	\$0.00	\$0.00

Notes

Dropped driveline in wab, replaced with rebuilt driveline

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Rebuilt driveshaft assembly	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	8,025 hr & 369,823 km

Type	Created	Scheduled	Due	Started	Closed
	Jun 21, 2024	Jun 21, 2024		Jun 21, 2024 12:24 PM	Jun 21, 2024 12:24 PM

Line	Task			Parts	Labor	Total
1	✓ Replace leaking radiator			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	T880 Radiator	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	8,366 hr & 383,902 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 12, 2024	Aug 12, 2024		Aug 13, 2024 5:51 AM	Aug 13, 2024 5:51 AM

Line	Task	Parts	Labor	Total
1	✓ Brakes on tractor will not release	\$0.00	\$0.00	\$0.00

Notes

Back left drive brake pot nfg

Rear quick release valve would not seat

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
QR-1 - Quick release valve	Kropp Shop		1.0	\$0.00	\$0.00
3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	8,366 hr & 383,902 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 13, 2024	Aug 13, 2024		Aug 13, 2024 4:36 AM	Aug 13, 2024 4:36 AM

Line	Task			Parts	Labor	Total
1	✓ Replace radiator			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	T880 Radiator	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ #4 LH brake pot bypassing			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	8,429 hr & 387,366 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 19, 2024	Aug 19, 2024		Aug 22, 2024 6:32 AM	Aug 22, 2024 6:32 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	8,429 hr & 387,366 km

Type	Created	Scheduled	Due	Started	Closed
Service	Aug 22, 2024	Aug 22, 2024	Aug 22, 2024	Aug 22, 2024 5:21 AM	Aug 22, 2024 5:53 AM

Line	Task	Parts	Labor	Total
1	✓ Clutch slave cylinder <u>Notes</u> Leaking externally, replaced with new unit	\$0.00	\$0.00	\$0.00
2	✓ Backup light <u>Notes</u> Lower R/H and upper L/H work light replaced	\$0.00	\$0.00	\$0.00
3	✓ Mirror cracked, replace <u>Notes</u> Changed l/h lower convex, changed r/h upper and lower mirrors	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	8,458 hr & 388,227 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 30, 2024	Aug 30, 2024		Aug 30, 2024 4:51 PM	Aug 30, 2024 4:51 PM

Line	Task	Parts	Labor	Total
1	✓ Clutch brake/clutch not working correctly	\$0.00	\$0.00	\$0.00

Notes

Clutch backs off while holding, suspect air in line, bled and oil came out of nipple on servo, replaced servo and bled clutch still backed off, while slow press clutch pedal could feel oil bypass, replaced master cylinder And bled clutch now functioning properly

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Clutch servo	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	8,771 hr & 405,990 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 19, 2024	Oct 19, 2024		Oct 20, 2024 9:49 AM	Oct 20, 2024 9:49 AM

Line	Task	Parts	Labor	Total																		
1	✓ Frame & Assembly	\$0.00	\$0.00	\$0.00																		
	<u>Notes</u>																					
	LH T-rail bolts loose																					
2	✓ Mirrors	\$0.00	\$0.00	\$0.00																		
	<u>Notes</u>																					
	LH convex broke, RH side both cracked																					
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>convex mirror t880</td><td>Kropp Shop</td><td></td><td>2.0</td><td>\$0.00</td><td>\$0.00</td></tr><tr><td>mirror t880</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	convex mirror t880	Kropp Shop		2.0	\$0.00	\$0.00	mirror t880	Kropp Shop		1.0	\$0.00	\$0.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost																	
convex mirror t880	Kropp Shop		2.0	\$0.00	\$0.00																	
mirror t880	Kropp Shop		1.0	\$0.00	\$0.00																	
3	✓ Service Brakes	\$0.00	\$0.00	\$0.00																		
	<u>Notes</u>																					
	set drive brakes, Front RH shoe not coming off of drum																					
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>Es2 shoe kit</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	Es2 shoe kit	Kropp Shop		1.0	\$0.00	\$0.00									
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost																	
Es2 shoe kit	Kropp Shop		1.0	\$0.00	\$0.00																	
4	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00																		
		Part Cost		\$0.00																		
		Labor		\$0.00																		
		Subtotal		\$0.00																		
		Tax 1 (0.0%)		\$0.00																		
		Tax 2 (0.0%)		\$0.00																		
		Credit		(\$0.00)																		
		Total Cost		\$0.00																		

Kropp Contracting
Shop

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 1355
Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	8,771 hr & 405,990 km

Type	Scheduled	Due	Started	Closed
	Oct 20, 2024		Oct 20, 2024 10:14 AM	Oct 20, 2024 10:14 AM

Line	Task	Parts	Labor	Total
1	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 1411

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	8,882 hr & 411,852 km

Type	Scheduled	Due	Started	Closed
	Nov 4, 2024		Nov 4, 2024 6:24 AM	Nov 4, 2024 6:24 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 1446
Everett Twin, Trent Court
CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	8,993 hr & 418,044 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 16, 2024	Nov 16, 2024		Nov 17, 2024 10:49 AM	Nov 17, 2024 10:49 AM

Line	Task	Parts	Labor	Total
1	✓ Adjust Brakes	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 1490

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	8,993 hr & 418,044 km

Type	Scheduled	Due	Started	Closed
	Dec 1, 2024		Dec 1, 2024 6:01 PM	Dec 1, 2024 6:01 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	9,234 hr & 430,456 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 14, 2024	Dec 14, 2024		Dec 14, 2024 10:08 AM	Dec 14, 2024 10:08 AM

Line	Task	Parts	Labor	Total
1	✓ Driveline	\$0.00	\$0.00	\$0.00
	Notes			
	main shaft yoke loose			
2	✓ Exhaust	\$0.00	\$0.00	\$0.00
	Notes			
	RH stack loose			
3	✓ Frame & Assembly	\$0.00	\$0.00	\$0.00
	Notes			
	T rail bolts loose LH side front			
4	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
5	✓ Steering System	\$0.00	\$0.00	\$0.00
	Notes			
	RH drag link no good			

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
346-634 - RH drag link t880 (283/284)	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	9,396 hr & 430,456 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 10, 2025	Jan 10, 2025		Jan 10, 2025 11:35 AM	Jan 10, 2025 11:35 AM

Line	Task	Parts	Labor	Total
1	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 1573

Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	9,470 hr & 442,706 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 15, 2025	Jan 15, 2025		Jan 15, 2025 6:20 PM	Jan 15, 2025 6:20 PM

Line	Task	Parts	Labor	Total
1	✓ particulate matter sensor code	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	9,488 hr & 443,448 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 18, 2025	Jan 18, 2025		Jan 18, 2025 4:32 PM	Jan 18, 2025 4:32 PM

Line	Task	Parts	Labor	Total													
1	✓ Air Lines	\$0.00	\$0.00	\$0.00													
	<u>Notes</u>																
	glad hand rubbers nfg																
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>glad hand rubber</td><td>Kropp Shop</td><td></td><td>2.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	glad hand rubber	Kropp Shop		2.0	\$0.00	\$0.00				
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost												
glad hand rubber	Kropp Shop		2.0	\$0.00	\$0.00												
2	✓ Exhaust	\$0.00	\$0.00	\$0.00													
	<u>Notes</u>																
	RH stack loose																
3	✓ Frame & Assembly	\$0.00	\$0.00	\$0.00													
	<u>Notes</u>																
	T rail bolts loose																
4	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00													
5	✓ Lights - All	\$0.00	\$0.00	\$0.00													
	<u>Notes</u>																
	top rh work light out																
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>Work light</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	Work light	Kropp Shop		1.0	\$0.00	\$0.00				
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost												
Work light	Kropp Shop		1.0	\$0.00	\$0.00												

Kropp Contracting
Shop

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 1585

Nate Vandenberghe

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	9,627 hr & 449,493 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 2, 2025	Feb 2, 2025		Feb 2, 2025 6:29 PM	Feb 2, 2025 6:29 PM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Lights - All	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	lh lower work light out					
3	✓ Service Brakes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	adjust drive brakes					
4	✓ Tires	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	steer tires 150,000					
5	✓ Steer Tires	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	steer tires	Kropp Shop		2.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	9,708 hr & 456,378 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 13, 2025	Feb 13, 2025		Feb 13, 2025 8:12 PM	Feb 13, 2025 8:12 PM

Line	Task	Parts	Labor	Total
------	------	-------	-------	-------

1	✓ Brake Accessories	\$0.00	\$0.00	\$0.00
---	---------------------	--------	--------	--------

Notes

#2 & #4 RH S-cam U-bolt loose

2	✓ Check all fluid levels	\$0.00	\$0.00	\$0.00
---	--------------------------	--------	--------	--------

Notes

LH steer wheel seal leaking

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
2137 Wheel seal	Kropp Shop		1.0	\$0.00	\$0.00

3	✓ Engine	\$0.00	\$0.00	\$0.00
---	----------	--------	--------	--------

Notes

Gear cover leak

4	✓ Service Brakes	\$0.00	\$0.00	\$0.00
---	------------------	--------	--------	--------

Notes

Adjust brake stroke

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	9,931 hr & 464,112 km

Type	Scheduled	Due	Started	Closed
	Mar 3, 2025		Mar 3, 2025 12:08 PM	Mar 3, 2025 12:08 PM

Line	Task	Parts	Labor	Total
1	✓ Check all fluid levels	\$0.00	\$0.00	\$0.00
	Notes			
	LH steer hub low			
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
3	✓ Mirrors	\$0.00	\$0.00	\$0.00

Notes

lh mirror cracked

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	10,003 hr & 467,124 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 7, 2025	Mar 7, 2025		Mar 7, 2025 1:03 PM	Mar 7, 2025 1:03 PM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	oil 15w-40	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ RH mirror cracked			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	mirror t880	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	10,003 hr & 467,845 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 9, 2025	Mar 9, 2025		Mar 9, 2025 4:42 PM	Mar 9, 2025 4:42 PM

Line	Task	Parts	Labor	Total
1	✓ Low boost	\$0.00	\$0.00	\$0.00

Notes

Ran regen found hole in CAC removed and welded hole as we did not have one in stock re installed check for leaks all good

2	✓ Fan belt tore	\$0.00	\$0.00	\$0.00
---	-----------------	--------	--------	--------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
fan belt	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	10,193 hr & 475,310 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 25, 2025	Apr 25, 2025		Apr 29, 2025 4:27 PM	Apr 29, 2025 4:29 PM

Line	Task	Parts	Labor	Total
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
2	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
3	✓ replace plastic mudflaps	\$0.00	\$0.00	\$0.00
4	✓ replace broken anti sails	\$0.00	\$0.00	\$0.00
5	✓ exhaust leak ontop of dpf box	\$0.00	\$0.00	\$0.00

Notes

Replace bellows pipe

6	✓ change air filters	\$0.00	\$0.00	\$0.00
7	✓ check diff levels	\$0.00	\$0.00	\$0.00
8	✓ change diff filters	\$0.00	\$0.00	\$0.00
9	✓ RH stack guard hitting cab	\$0.00	\$0.00	\$0.00
10	✓ replace A/C belt	\$0.00	\$0.00	\$0.00
11	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 1850

Cam Nadeau

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	10,208.6 hr & 475,932 km

Type	Created	Scheduled	Due	Started	Closed
Service	May 5, 2025	May 5, 2025		May 5, 2025 5:00 PM	May 5, 2025 5:00 PM

Line	Task	Parts	Labor	Total
1	✓ Brake hose	\$0.00	\$0.00	\$0.00

Notes

#4LHS rubbed through

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	10,595 hr & 494,411 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 21, 2025	Jul 21, 2025		Jul 30, 2025 2:05 PM	Jul 30, 2025 2:05 PM

Line	Task	Parts	Labor	Total
1	✓ Adjust Brakes	\$0.00	\$0.00	\$0.00
2	✓ Tighten brake pot nut	\$0.00	\$0.00	\$0.00
3	✓ Check batteries	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 1995

Cam Nadeau

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	10,595 hr & 494,411 km

Type	Created	Scheduled	Due	Started	Closed
Service	Jul 22, 2025	Jul 22, 2025		Jul 22, 2025 11:19 AM	Jul 22, 2025 11:19 AM

Line	Task	Parts	Labor	Total
1	✓ Mirror cracked, replace	\$0.00	\$0.00	\$0.00

Notes

Replace R/H mirror

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	10,670 hr & 498,991 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 18, 2025	Aug 18, 2025		Aug 18, 2025 4:08 AM	Aug 18, 2025 4:08 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	10,716 hr & 501,935 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 25, 2025	Aug 25, 2025		Aug 25, 2025 4:30 PM	Aug 25, 2025 4:30 PM

Line	Task	Parts	Labor	Total		
1	✓ LH window switch not working	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Q27-1048-1200 - T880 LH window module	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	10,729 hr & 502,821 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 26, 2025	Aug 26, 2025		Aug 26, 2025 5:42 PM	Aug 26, 2025 5:43 PM

Line	Task			Parts	Labor	Total
1	✓ Battery boiling over			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Group 31S battery	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 2090

Cam Nadeau

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	10,766 hr & 505,214 km

Type	Scheduled	Due	Started	Closed
	Aug 29, 2025		Aug 29, 2025 3:33 PM	Aug 29, 2025 3:33 PM

Line	Task	Parts	Labor	Total
1	✓ Adjust 5th wheel	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	10,855 hr & 510,819 km

Type	Scheduled	Due	Started	Closed
	Sep 12, 2025		Sep 12, 2025 7:16 PM	Sep 12, 2025 7:16 PM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	FS20172 - Cummins water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
	oil 15w-40	Kropp Shop		42.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	10,947 hr & 515,898 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 1, 2025	Oct 1, 2025		Oct 1, 2025 5:03 PM	Oct 1, 2025 5:03 PM

Line	Task	Parts	Labor	Total												
1	✓ T rail bolt loose	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	LF bout loose, install new washer and lock washet															
2	✓ Steady bearing yolk loose	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	Tighten steady bearing yolk and reinstall driveshaft															
3	✓ Replace Stack bushings and bearing	\$0.00	\$0.00	\$0.00												
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>EM75-69000-HT - Stack bushing kit</td><td>Kropp Shop</td><td></td><td>2.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	EM75-69000-HT - Stack bushing kit	Kropp Shop		2.0	\$0.00	\$0.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost											
EM75-69000-HT - Stack bushing kit	Kropp Shop		2.0	\$0.00	\$0.00											
			Part Cost		\$0.00											
			Labor		\$0.00											
			Subtotal		\$0.00											
			Tax 1 (0.0%)		\$0.00											
			Tax 2 (0.0%)		\$0.00											
			Credit		(\$0.00)											
			Total Cost		\$0.00											

Kropp Contracting
Shop

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 2187

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	11,044 hr & 520,940 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 13, 2025	Oct 13, 2025		Oct 13, 2025 4:28 PM	Oct 13, 2025 4:28 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	11,044 hr & 520,940 km

Type	Scheduled	Due	Started	Closed
	Oct 20, 2025		Oct 20, 2025 5:46 PM	Oct 20, 2025 5:46 PM

Line	Task	Parts	Labor	Total		
1	✓ LH middle drive brake spring broke	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Es2 shoe kit	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	11,142 hr & 525,625 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 31, 2025	Oct 31, 2025		Nov 3, 2025 8:19 AM	Nov 3, 2025 8:19 AM

Line	Task	Parts	Labor	Total
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
2	✓ Herbs warranty claim- new DPF new reman injectors	\$0.00	\$0.00	\$0.00
3	✓ Replace drivers seat	\$0.00	\$0.00	\$0.00
4	✓ Rh stack moves	\$0.00	\$0.00	\$0.00
5	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 2284

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	11,142 hr & 525,625 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 21, 2025	Nov 21, 2025		Nov 21, 2025 8:27 PM	Nov 21, 2025 8:27 PM

Line	Task	Parts	Labor	Total
1	✓ Replaced def line	\$0.00	\$0.00	\$0.00
2	✓ Put rubber back in under headache rack	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 2297

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	11,319 hr & 534,639 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 24, 2025	Nov 24, 2025		Nov 24, 2025 5:22 PM	Nov 24, 2025 5:22 PM

Line	Task	Parts	Labor	Total
1	✓ Work light out	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	11,319 hr & 534,639 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 1, 2025	Dec 1, 2025		Dec 1, 2025 5:33 PM	Dec 1, 2025 5:33 PM

Line	Task	Parts	Labor	Total		
1	✓ Air Lines	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	mux bracket bent lines pinched					
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
3	✓ Lights - All	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	bottom LH work light					
4	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ Herbs warranty injector (code 322)	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	11,319 hr & 540,182 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 5, 2025	Dec 5, 2025		Dec 5, 2025 5:03 PM	Dec 5, 2025 6:19 PM

Line	Task	Parts	Labor	Total
1	✓ Retorque	\$0.00	\$0.00	\$0.00
2	✓ brake pod	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	11,513 hr & 543,590 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 14, 2025	Dec 14, 2025		Dec 14, 2025 4:03 PM	Dec 14, 2025 5:58 PM

Line	Task	Parts	Labor	Total		
1	✓ Air Lines	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	leaking above transmission					
2	✓ Body	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	spring fix					
	fender front right					
3	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
4	✓ Lights - All	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	top right work light					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Work light	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ Mirrors	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Right hand convex and both left hand mirrors					
6	✓ Service Brakes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Brake stroke out on front left and right and middle left					

Kropp Contracting
Shop

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 2378

Trent Court

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	11,609 hr & 548,049 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 22, 2025	Dec 22, 2025		Dec 22, 2025 11:47 AM	Dec 26, 2025 8:18 AM

Line	Task	Parts	Labor	Total
1	✓ air leak	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	11,620 hr & 548,516 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 29, 2025	Dec 29, 2025		Dec 29, 2025 10:37 AM	Dec 29, 2025 10:37 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 2421

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	11,673 hr & 551,060 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 6, 2026	Jan 6, 2026		Jan 8, 2026 5:56 AM	Jan 8, 2026 5:56 AM

Line	Task	Parts	Labor	Total
1	✓ Changed drivers side headlight	\$0.00	\$0.00	\$0.00
2	✓ Fixed work light right sude	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	11,763 hr & 555,480 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 13, 2026	Jan 13, 2026		Jan 14, 2026 7:12 PM	Jan 14, 2026 7:12 PM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 2462

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	11,763 hr & 555,480 km

Type	Scheduled	Due	Started	Closed
	Jan 17, 2026		Jan 17, 2026 6:45 AM	Jan 17, 2026 6:45 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 2482

Aiden Kenny

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	11,885 hr & 561,888 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 26, 2026	Jan 26, 2026		Jan 26, 2026 7:53 PM	Jan 26, 2026 7:53 PM

Line	Task	Parts	Labor	Total
1	✓ Drive tires (set of 12)	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	11,935 hr & 564,474 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 30, 2026	Jan 30, 2026		Jan 30, 2026 8:43 PM	Jan 30, 2026 8:43 PM

Line	Task	Parts	Labor	Total
1	✓ Body	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Grill bolts MIA			
2	✓ Exhaust	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Rh stack turning into cab			
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

Kropp Contracting
Shop

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 2515

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	11,978 hr & 564,474 km

Type	Scheduled	Due	Started	Closed
	Feb 2, 2026		Feb 2, 2026 6:04 PM	Feb 2, 2026 6:04 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	12,071 hr & 571,137 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 13, 2026	Feb 13, 2026		Feb 13, 2026 2:46 PM	Feb 13, 2026 5:24 PM

Line	Task	Parts	Labor	Total
1	✓ Right front shock steer axle	\$0.00	\$0.00	\$0.00
2	✓ Left steer tires	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 2560

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	12,100 hr & 571,137 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 18, 2026	Feb 18, 2026		Feb 24, 2026 2:19 PM	Feb 24, 2026 2:19 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	12,192 hr & 576,169 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 24, 2026	Feb 24, 2026		Feb 24, 2026 9:27 PM	Feb 24, 2026 9:27 PM

Line	Task	Parts	Labor	Total
1	✓ Air Lines <u>Notes</u> discharge line loose	\$0.00	\$0.00	\$0.00
2	✓ Lights - All <u>Notes</u> chafed wire to light harness front bumper	\$0.00	\$0.00	\$0.00
3	✓ Mirrors <u>Notes</u> bottom lh convex	\$0.00	\$0.00	\$0.00
4	✓ Parking Brake <u>Notes</u> drive brake stroke off	\$0.00	\$0.00	\$0.00
5	✓ Service Brakes <u>Notes</u> blue glad hand hose leaking	\$0.00	\$0.00	\$0.00
6	✓ Windows <u>Notes</u> windshield nfg	\$0.00	\$0.00	\$0.00

Kropp Contracting
Shop

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 2571

Unassigned

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	12,229 hr & 577,716 km

Type	Scheduled	Due	Started	Closed
	Mar 6, 2026		Mar 6, 2026 7:30 PM	Mar 6, 2026 7:30 PM

Line	Task			Parts	Labor	Total
1	✓ Water pump failed			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	5719751 - X15 water pump core	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 2618
Aiden Kenny, Trent Court
CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	12,229 hr & 577,716 km

Type	Scheduled	Due	Started	Closed
	Mar 6, 2026		Mar 6, 2026 8:05 PM	Mar 6, 2026 8:05 PM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	12,319 hr & 580,526 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 17, 2026	Mar 17, 2026		Mar 17, 2026 2:14 PM	Mar 19, 2026 11:57 AM

Line	Task	Parts	Labor	Total		
1	✓ Brake Accessories	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Rh front drive brake not releasing on the spring					
2	✓ Check all fluid levels	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Power steering low					
3	✓ Engine	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Coolant leak dripping from rh rear structure					
4	✓ Rear End	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Front diff output yoke loose					
5	✓ Rear plywood bungee straps tore off	\$0.00	\$0.00	\$0.00		
6	✓ Replace batteries	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Group 31S battery	Kropp Shop		4.0	\$0.00	\$0.00
7	✓ Replace cab filters	\$0.00	\$0.00	\$0.00		

Kropp Contracting
Shop

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 2638

Trent Court

CLOSED

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	12,495.7 hr & 589,720 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 15, 2026	Apr 15, 2026		Apr 16, 2026 5:45 AM	Apr 16, 2026 5:46 AM

Line	Task	Parts	Labor	Total
1	✓ Fixed broken wire and replaced coolant level sensor	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	12,507 hr & 590,350 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 20, 2026	Apr 20, 2026		Apr 21, 2026 9:19 PM	Apr 29, 2026 7:04 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ Adjust all brakes	\$0.00	\$0.00	\$0.00
3	✓ Power steering leak	\$0.00	\$0.00	\$0.00
4	✓ Chaffed fuel lines	\$0.00	\$0.00	\$0.00
5	✓ Coolant leak on down pipe	\$0.00	\$0.00	\$0.00

Notes

Get cooler outlet pipe, changed 2 prongs and square gasket

6	✓ Coolant sensor			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Coolant level sensor	Kropp Shop		1.0	\$0.00	\$0.00
7	✓ CVIP inspection (wheels off)			\$0.00	\$0.00	\$0.00
8	✓ Engine light			\$0.00	\$0.00	\$0.00
9	✓ 5th wheel pin bushings			\$0.00	\$0.00	\$0.00
10	✓ Spring pins LH and RH			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	B13-1002 - Spring pin bushing (T800,T880)	Kropp Shop		4.0	\$0.00	\$0.00
	B65-6008 - Rear spring pin (T800,T880)	Kropp Shop		4.0	\$0.00	\$0.00
11	✓ change diff filters			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

	LF3311 - Rockwell diff filter	Kropp Shop	2.0	\$0.00	\$0.00	
12	✓ Air filters		\$0.00	\$0.00	\$0.00	
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	air filter T880	Kropp Shop		1.0	\$0.00	\$0.00
13	✓ Engine oil leak front of engine		\$0.00	\$0.00	\$0.00	
	<u>Notes</u>					
	Front cover bolts loose behind damper					
14	✓ beacon cover broke		\$0.00	\$0.00	\$0.00	
15	✓ rh stack twists		\$0.00	\$0.00	\$0.00	
16	✓ re tape umbilical cord		\$0.00	\$0.00	\$0.00	
17	✓ clutch fluid top up(check for leak)		\$0.00	\$0.00	\$0.00	
18	✓ Rh front drive brake pot will not retract		\$0.00	\$0.00	\$0.00	
19	✓ Fan stat will not exhaust		\$0.00	\$0.00	\$0.00	
20	✓ Preform Scheduled Maintenance		\$0.00	\$0.00	\$0.00	
			Part Cost		\$0.00	
			Labor		\$0.00	
			Subtotal		\$0.00	
			Tax 1 (0.0%)		\$0.00	
			Tax 2 (0.0%)		\$0.00	
			Credit		(\$0.00)	
			Total Cost		\$0.00	

Kropp Contracting
Shop

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 2734

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	12,668 hr & 596,861 km

Type	Created	Scheduled	Due	Started	Closed
	Jun 10, 2026	Jun 10, 2026		Jun 12, 2026 7:26 AM	Jun 12, 2026 7:26 AM

Line	Task	Parts	Labor	Total
1	✓ Windshield washer pump	\$0.00	\$0.00	\$0.00
2	✓ Engine codes	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	12,668 hr & 596,861 km

Type	Scheduled	Due	Started	Closed
	Jun 12, 2026		Jun 12, 2026 1:47 PM	Jun 12, 2026 1:47 PM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Notes

Notes	User	Time
Done by Dave H	Trent Court	Jun 12, 2026 1:47 PM

Kropp Contracting
Shop

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

Work Order 2775

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	12,955 hr & 611,636 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 26, 2026	Jul 26, 2026		Jul 26, 2026 6:50 AM	Jul 26, 2026 6:51 AM

Line	Task	Parts	Labor	Total
1	✓ Steer Tires	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

284 - 2022 Kenworth T880

Parent: T796 - 2017 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKZX4EX8NJ980027	U68443	12,988 hr & 613,493 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 1, 2026	Aug 1, 2026		Aug 1, 2026 7:34 AM	Aug 1, 2026 7:37 AM

Line	Task	Parts	Labor	Total
1	✓ Headlight	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Repair L/H headlight wiring change bulbs			
2	✓ Lights	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Repair L/h Mickey Mouse wiring			
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00