

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

# CLOSED

| Serial            | Tag    | Closed Meters        |
|-------------------|--------|----------------------|
| 1NKDX4EXXLR966459 | E91025 | 54.5 hr & 565,973 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Mar 27, 2024 | Mar 27, 2024 |     | Mar 27, 2024 9:11 AM | Mar 27, 2024 9:11 AM |

| Line | Task             | Parts  | Labor  | Total  |
|------|------------------|--------|--------|--------|
| 1    | ✓ Headlights out | \$0.00 | \$0.00 | \$0.00 |

### Notes

Weather pack RH side broken wire

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

# 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters        |
|-------------------|--------|----------------------|
| 1NKDX4EXXLR966459 | E91025 | 76.2 hr & 567,093 km |

| Type | Created      | Scheduled    | Due | Started               | Closed               |
|------|--------------|--------------|-----|-----------------------|----------------------|
|      | Apr 17, 2024 | Apr 17, 2024 |     | Apr 19, 2024 12:47 PM | Apr 22, 2024 1:10 PM |

| Line | Task                              | Parts      | Labor      | Total  |           |        |
|------|-----------------------------------|------------|------------|--------|-----------|--------|
| 1    | ✓ Wheels off CVIP inspection      | \$0.00     | \$0.00     | \$0.00 |           |        |
| 2    | ✓ LH stack guard to rotate        | \$0.00     | \$0.00     | \$0.00 |           |        |
| 3    | ✓ replace front drive mudflaps    | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                              | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | 24" plastic mudflap               | Kropp Shop |            | 2.0    | \$0.00    | \$0.00 |
| 4    | ✓ battery box bolts missing       | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                              | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | M10 SS bolt                       | Kropp Shop |            | 2.0    | \$0.00    | \$0.00 |
|      | KW battery box washer             | Kropp Shop |            | 2.0    | \$0.00    | \$0.00 |
| 5    | ✓ lower LH side step loose        | \$0.00     | \$0.00     | \$0.00 |           |        |
| 6    | ✓ King pins                       | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <b><u>Notes</u></b>               |            |            |        |           |        |
|      | bushing lack of grease both sides |            |            |        |           |        |
|      | Part                              | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | King pin kit                      | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 7    | ✓ spring pins                     | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <b><u>Notes</u></b>               |            |            |        |           |        |
|      | rear both sides wore out          |            |            |        |           |        |
|      | Part                              | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | spring pins                       | Kropp Shop |            | 4.0    | \$0.00    | \$0.00 |

# 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

**CLOSED**

|    |                                          |            |            |        |           |        |
|----|------------------------------------------|------------|------------|--------|-----------|--------|
|    | spring pin bushings                      | Kropp Shop |            | 4.0    | \$0.00    | \$0.00 |
| 8  | ✓ check lights                           |            |            | \$0.00 | \$0.00    | \$0.00 |
| 9  | ✓ change diff filters                    |            |            | \$0.00 | \$0.00    | \$0.00 |
|    | Part                                     | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | LF3311 - Rockwell diff filter            | Kropp Shop |            | 2.0    | \$0.00    | \$0.00 |
| 10 | ✓ rear skirt lights out                  |            |            | \$0.00 | \$0.00    | \$0.00 |
|    | Part                                     | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | 4" red light                             | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
|    | 3 wire pigtail                           | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 11 | ✓ rear drive s cam u bolts loose         |            |            | \$0.00 | \$0.00    | \$0.00 |
| 12 | ✓ abs codes                              |            |            | \$0.00 | \$0.00    | \$0.00 |
|    | <b><u>Notes</u></b>                      |            |            |        |           |        |
|    | DA left code                             |            |            |        |           |        |
|    | Part                                     | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | K181625 - 6' 90 ABS WSS                  | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 13 | ✓ tie rod bar bent                       |            |            | \$0.00 | \$0.00    | \$0.00 |
|    | Part                                     | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | R230072 - Tie rod end                    | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
|    | R230073 - Tie rod end                    | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 14 | ✓ drain air tanks                        |            |            | \$0.00 | \$0.00    | \$0.00 |
| 15 | ✓ 5th wheel grease nipples missing       |            |            | \$0.00 | \$0.00    | \$0.00 |
| 16 | ✓ Grease truck and trailer               |            |            | \$0.00 | \$0.00    | \$0.00 |
| 17 | ✓ LH windshield                          |            |            | \$0.00 | \$0.00    | \$0.00 |
|    | Part                                     | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | Windshield LH                            | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 18 | ✓ steady bearing crossmember bolts loose |            |            | \$0.00 | \$0.00    | \$0.00 |

Kropp Contracting  
Shop

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

**Work Order 1068**  
Nate Vandenberghe, Trent Court

**CLOSED**

19    ✓ adjust steer axle toe

\$0.00                      \$0.00                      \$0.00

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters       |
|-------------------|--------|---------------------|
| 1NKDX4EXXLR966459 | E91025 | 415 hr & 586,956 km |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Jul 9, 2024 | Jul 9, 2024 |     | Jul 9, 2024 6:18 AM | Jul 9, 2024 6:18 AM |

| Line | Task                                     |            |            | Parts        | Labor     | Total    |
|------|------------------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Oil change                             |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                                     | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | oil 15w-40                               | Kropp Shop |            | 42.0         | \$0.00    | \$0.00   |
|      | LF14000 - Cummins oil filter             | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | FF5825NN - Cummins fuel filter           | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | FS20172 - Cummins water separator filter | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
| 2    | ✓ Grease truck and trailer               |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                                     | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | grease tubes                             | Kropp Shop |            | 3.0          | \$0.00    | \$0.00   |
|      |                                          |            |            | Part Cost    |           | \$0.00   |
|      |                                          |            |            | Labor        |           | \$0.00   |
|      |                                          |            |            | Subtotal     |           | \$0.00   |
|      |                                          |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                          |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                          |            |            | Credit       |           | (\$0.00) |
|      |                                          |            |            | Total Cost   |           | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

# CLOSED

| Serial            | Tag    | Closed Meters       |
|-------------------|--------|---------------------|
| 1NKDX4EXXLR966459 | E91025 | 615 hr & 599,413 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Aug 12, 2024 | Aug 12, 2024 |     | Aug 12, 2024 6:31 PM | Aug 12, 2024 6:31 PM |

| Line | Task                          | Parts  | Labor  | Total  |
|------|-------------------------------|--------|--------|--------|
| 1    | ✓ Clean out rad - running hot | \$0.00 | \$0.00 | \$0.00 |

### Notes

Removed ac condenser

Removed cold air cooler

Washed rad air to air

Washed rad and put back together

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

Kropp Contracting  
Shop

855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

Work Order 1244  
Trent Court

CLOSED

| Serial            | Tag    | Closed Meters       |
|-------------------|--------|---------------------|
| 1NKDX4EXXLR966459 | E91025 | 721 hr & 602,675 km |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Aug 20, 2024 |     | Aug 20, 2024 6:59 AM | Aug 20, 2024 6:59 AM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters       |
|-------------------|--------|---------------------|
| 1NKDX4EXXLR966459 | E91025 | 748 hr & 604,496 km |

| Type    | Scheduled    | Due          | Started              | Closed               |
|---------|--------------|--------------|----------------------|----------------------|
| Service | Aug 21, 2024 | Aug 21, 2024 | Aug 21, 2024 6:09 PM | Aug 21, 2024 6:09 PM |

| Line | Task      | Parts  | Labor  | Total  |
|------|-----------|--------|--------|--------|
| 1    | ✓ air bag | \$0.00 | \$0.00 | \$0.00 |

Notes

Left-hand side lift axle lift bag

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters       |
|-------------------|--------|---------------------|
| 1NKDX4EXXLR966459 | E91025 | 816 hr & 608,603 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Aug 29, 2024 | Aug 29, 2024 |     | Aug 29, 2024 1:58 PM | Aug 29, 2024 1:58 PM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Oil change               | \$0.00       | \$0.00 | \$0.00   |
| 2    | ✓ Adjust clutch            | \$0.00       | \$0.00 | \$0.00   |
| 3    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

Kropp Contracting  
Shop

855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

Work Order 1261

Trent Court

CLOSED

| Serial            | Tag    | Closed Meters       |
|-------------------|--------|---------------------|
| 1NKDX4EXXLR966459 | E91025 | 816 hr & 608,603 km |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Aug 29, 2024 |     | Aug 29, 2024 1:59 PM | Aug 29, 2024 1:59 PM |

| Line | Task         | Parts        | Labor  | Total    |
|------|--------------|--------------|--------|----------|
| 1    | ✓ Oil change | \$0.00       | \$0.00 | \$0.00   |
|      |              | Part Cost    |        | \$0.00   |
|      |              | Labor        |        | \$0.00   |
|      |              | Subtotal     |        | \$0.00   |
|      |              | Tax 1 (0.0%) |        | \$0.00   |
|      |              | Tax 2 (0.0%) |        | \$0.00   |
|      |              | Credit       |        | (\$0.00) |
|      |              | Total Cost   |        | \$0.00   |

Kropp Contracting  
Shop

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

Work Order 1270

Trent Court

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 1,104 hr & 625,320 km |

| Type | Created      | Scheduled    | Due | Started               | Closed                |
|------|--------------|--------------|-----|-----------------------|-----------------------|
|      | Aug 31, 2024 | Aug 31, 2024 |     | Oct 20, 2024 11:04 AM | Oct 20, 2024 11:04 AM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

# 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 1,104 hr & 625,320 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Oct 18, 2024 | Oct 18, 2024 |     | Oct 18, 2024 6:20 AM | Oct 18, 2024 8:29 AM |

| Line | Task      | Parts  | Labor  | Total  |
|------|-----------|--------|--------|--------|
| 1    | ✓ Battery | \$0.00 | \$0.00 | \$0.00 |

**Notes**

load test failed- replaced all 4

load test batteries (barely started)

| Part              | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|-------------------|------------|------------|-----|-----------|--------|
| Group 31S battery | Kropp Shop |            | 4.0 | \$0.00    | \$0.00 |

|   |        |        |        |        |
|---|--------|--------|--------|--------|
| 2 | ✓ Body | \$0.00 | \$0.00 | \$0.00 |
|---|--------|--------|--------|--------|

**Notes**

made brackets and bolted back down

both bottom steps loose

|   |          |        |        |        |
|---|----------|--------|--------|--------|
| 3 | ✓ Clutch | \$0.00 | \$0.00 | \$0.00 |
|---|----------|--------|--------|--------|

**Notes**

clutch brake not working

| Part                         | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|------------------------------|------------|------------|-----|-----------|--------|
| SB200 - Clutch brake 2 piece | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

|   |             |        |        |        |
|---|-------------|--------|--------|--------|
| 4 | ✓ Driveline | \$0.00 | \$0.00 | \$0.00 |
|---|-------------|--------|--------|--------|

**Notes**

Front diff Input yoke loose

|   |                |        |        |        |
|---|----------------|--------|--------|--------|
| 5 | ✓ Fluid Levels | \$0.00 | \$0.00 | \$0.00 |
|---|----------------|--------|--------|--------|

**Notes**

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

coolant level low, leak on back of head RH side

|   |              |        |        |        |
|---|--------------|--------|--------|--------|
| 6 | ✓ Front Axle | \$0.00 | \$0.00 | \$0.00 |
|---|--------------|--------|--------|--------|

**Notes**

dust covers missing, loose shock LH side

| Part                           | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|--------------------------------|------------|------------|-----|-----------|--------|
| K024564 - LH spicer dust cover | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |
| K024563 - RH Spicer dust cover | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

|   |                |        |        |        |
|---|----------------|--------|--------|--------|
| 7 | ✓ Lights - All | \$0.00 | \$0.00 | \$0.00 |
|---|----------------|--------|--------|--------|

**Notes**

LH hood light marker out, Fog lights not working (both broken wires at weather pack)

|   |         |        |        |        |
|---|---------|--------|--------|--------|
| 8 | ✓ Tires | \$0.00 | \$0.00 | \$0.00 |
|---|---------|--------|--------|--------|

**Notes**

RH steer tire bulge on side wall

|   |                     |        |        |        |
|---|---------------------|--------|--------|--------|
| 9 | ✓ Windshield Wipers | \$0.00 | \$0.00 | \$0.00 |
|---|---------------------|--------|--------|--------|

**Notes**

LH wiper blade no good

| Part            | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|-----------------|------------|------------|-----|-----------|--------|
| 15" wiper blade | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

|    |               |        |        |        |
|----|---------------|--------|--------|--------|
| 10 | ✓ Steer Tires | \$0.00 | \$0.00 | \$0.00 |
|----|---------------|--------|--------|--------|

**Notes**

changed both steer tires due to bulge on RH

|    |                            |        |        |        |
|----|----------------------------|--------|--------|--------|
| 11 | ✓ Grease truck and trailer | \$0.00 | \$0.00 | \$0.00 |
|----|----------------------------|--------|--------|--------|

| Part         | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|--------------|------------|------------|-----|-----------|--------|
| grease tubes | Kropp Shop |            | 4.0 | \$0.00    | \$0.00 |

Kropp Contracting  
Shop

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

**Work Order 1336**  
Trent Court, Nate Vandenberghe

# CLOSED

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

**CLOSED**

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 1,179 hr & 629,369 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Oct 28, 2024 | Oct 28, 2024 |     | Oct 31, 2024 5:05 AM | Oct 31, 2024 5:05 AM |

| Line | Task                       | Parts        | Labor      | Total  |           |          |
|------|----------------------------|--------------|------------|--------|-----------|----------|
| 1    | ✓ loose yoke on diff       | \$0.00       | \$0.00     | \$0.00 |           |          |
|      | <b><u>Notes</u></b>        |              |            |        |           |          |
|      | #1 input,#2 input          |              |            |        |           |          |
| 2    | ✓ loose yoke on tranny     | \$0.00       | \$0.00     | \$0.00 |           |          |
|      | Part                       | Warehouse    | Vendor/Bin | Qty    | Unit Cost | Cost     |
|      | RTLO-18918B - Transmission | Kropp Shop   |            | 1.0    | \$0.00    | \$0.00   |
| 3    | ✓ Grease truck and trailer | \$0.00       | \$0.00     | \$0.00 |           |          |
|      |                            | Part Cost    |            |        |           | \$0.00   |
|      |                            | Labor        |            |        |           | \$0.00   |
|      |                            | Subtotal     |            |        |           | \$0.00   |
|      |                            | Tax 1 (0.0%) |            |        |           | \$0.00   |
|      |                            | Tax 2 (0.0%) |            |        |           | \$0.00   |
|      |                            | Credit       |            |        |           | (\$0.00) |
|      |                            | Total Cost   |            |        |           | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 1,179 hr & 629,369 km |

| Type | Created     | Scheduled   | Due | Started              | Closed               |
|------|-------------|-------------|-----|----------------------|----------------------|
|      | Nov 8, 2024 | Nov 8, 2024 |     | Nov 13, 2024 3:51 PM | Nov 13, 2024 3:51 PM |

| Line | Task                 | Parts  | Labor  | Total  |
|------|----------------------|--------|--------|--------|
| 1    | ✓ Broken Crossmember | \$0.00 | \$0.00 | \$0.00 |

### Notes

next crossmember cracked behind steady bearing

| Part                    | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost     |
|-------------------------|------------|------------|-----|-----------|----------|
| K140-2437-5 - Gusset LH | Kropp Shop |            | 2.0 | \$0.00    | \$0.00   |
| P12024375R - Gusset RH  | Kropp Shop |            | 2.0 | \$0.00    | \$0.00   |
| K100-1148 - Crossmember | Kropp Shop |            | 1.0 | \$0.00    | \$0.00   |
| Part Cost               |            |            |     |           | \$0.00   |
| Labor                   |            |            |     |           | \$0.00   |
| Subtotal                |            |            |     |           | \$0.00   |
| Tax 1 (0.0%)            |            |            |     |           | \$0.00   |
| Tax 2 (0.0%)            |            |            |     |           | \$0.00   |
| Credit                  |            |            |     |           | (\$0.00) |
| Total Cost              |            |            |     |           | \$0.00   |

# 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 1,325 hr & 638,151 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Nov 16, 2024 | Nov 16, 2024 |     | Nov 16, 2024 4:59 PM | Nov 16, 2024 4:59 PM |

| Line | Task                                      | Parts        | Labor      | Total  |           |          |
|------|-------------------------------------------|--------------|------------|--------|-----------|----------|
| 1    | ✓ Tail light                              | \$0.00       | \$0.00     | \$0.00 |           |          |
| 2    | ✓ S cam u bolt loose left hand rear drive | \$0.00       | \$0.00     | \$0.00 |           |          |
| 3    | ✓ Compressor line                         | \$0.00       | \$0.00     | \$0.00 |           |          |
| 4    | ✓ Bellows pipe                            | \$0.00       | \$0.00     | \$0.00 |           |          |
|      | Part                                      | Warehouse    | Vendor/Bin | Qty    | Unit Cost | Cost     |
|      | EBPB11861 - Bellows kit                   | Kropp Shop   |            | 1.0    | \$0.00    | \$0.00   |
| 5    | ✓ Tighten oil filter                      | \$0.00       | \$0.00     |        |           | \$0.00   |
|      |                                           | Part Cost    |            |        |           | \$0.00   |
|      |                                           | Labor        |            |        |           | \$0.00   |
|      |                                           | Subtotal     |            |        |           | \$0.00   |
|      |                                           | Tax 1 (0.0%) |            |        |           | \$0.00   |
|      |                                           | Tax 2 (0.0%) |            |        |           | \$0.00   |
|      |                                           | Credit       |            |        |           | (\$0.00) |
|      |                                           | Total Cost   |            |        |           | \$0.00   |

Kropp Contracting  
Shop

855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

Work Order 1443  
Unassigned

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 1,325 hr & 638,151 km |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Nov 16, 2024 |     | Nov 16, 2024 5:00 PM | Nov 16, 2024 5:00 PM |

| Line | Task         | Parts        | Labor  | Total    |
|------|--------------|--------------|--------|----------|
| 1    | ✓ Oil change | \$0.00       | \$0.00 | \$0.00   |
|      |              | Part Cost    |        | \$0.00   |
|      |              | Labor        |        | \$0.00   |
|      |              | Subtotal     |        | \$0.00   |
|      |              | Tax 1 (0.0%) |        | \$0.00   |
|      |              | Tax 2 (0.0%) |        | \$0.00   |
|      |              | Credit       |        | (\$0.00) |
|      |              | Total Cost   |        | \$0.00   |

Kropp Contracting  
Shop

855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

Work Order 1453

Trent Court

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 1,325 hr & 638,151 km |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Nov 18, 2024 |     | Nov 18, 2024 8:07 PM | Nov 18, 2024 8:07 PM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 1,448 hr & 645,159 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Nov 27, 2024 | Nov 27, 2024 |     | Nov 28, 2024 9:24 AM | Nov 29, 2024 8:12 PM |

| Line                   | Task                                                                                                                                                                                                                                 | Parts      | Labor     | Total      |        |           |      |                        |            |  |      |        |        |  |  |  |
|------------------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|-----------|------------|--------|-----------|------|------------------------|------------|--|------|--------|--------|--|--|--|
| 1                      | ✓ ABS codes                                                                                                                                                                                                                          | \$0.00     | \$0.00    | \$0.00     |        |           |      |                        |            |  |      |        |        |  |  |  |
|                        | <b><u>Notes</u></b>                                                                                                                                                                                                                  |            |           |            |        |           |      |                        |            |  |      |        |        |  |  |  |
|                        | Middle LH speed sensor wire tore off                                                                                                                                                                                                 |            |           |            |        |           |      |                        |            |  |      |        |        |  |  |  |
| 2                      | ✓ Drive tires (set of 12)                                                                                                                                                                                                            | \$0.00     | \$0.00    | \$0.00     |        |           |      |                        |            |  |      |        |        |  |  |  |
|                        | <table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>245 Truck - Drive tire</td><td>Kropp Shop</td><td></td><td>12.0</td><td>\$0.00</td><td>\$0.00</td></tr></table> | Part       | Warehouse | Vendor/Bin | Qty    | Unit Cost | Cost | 245 Truck - Drive tire | Kropp Shop |  | 12.0 | \$0.00 | \$0.00 |  |  |  |
| Part                   | Warehouse                                                                                                                                                                                                                            | Vendor/Bin | Qty       | Unit Cost  | Cost   |           |      |                        |            |  |      |        |        |  |  |  |
| 245 Truck - Drive tire | Kropp Shop                                                                                                                                                                                                                           |            | 12.0      | \$0.00     | \$0.00 |           |      |                        |            |  |      |        |        |  |  |  |
| 3                      | ✓ air bag                                                                                                                                                                                                                            | \$0.00     | \$0.00    | \$0.00     |        |           |      |                        |            |  |      |        |        |  |  |  |
|                        | <b><u>Notes</u></b>                                                                                                                                                                                                                  |            |           |            |        |           |      |                        |            |  |      |        |        |  |  |  |
|                        | All but rear LH drive no good                                                                                                                                                                                                        |            |           |            |        |           |      |                        |            |  |      |        |        |  |  |  |
|                        | <table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>9501 - drive airbag</td><td>Kropp Shop</td><td></td><td>5.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>     | Part       | Warehouse | Vendor/Bin | Qty    | Unit Cost | Cost | 9501 - drive airbag    | Kropp Shop |  | 5.0  | \$0.00 | \$0.00 |  |  |  |
| Part                   | Warehouse                                                                                                                                                                                                                            | Vendor/Bin | Qty       | Unit Cost  | Cost   |           |      |                        |            |  |      |        |        |  |  |  |
| 9501 - drive airbag    | Kropp Shop                                                                                                                                                                                                                           |            | 5.0       | \$0.00     | \$0.00 |           |      |                        |            |  |      |        |        |  |  |  |
| 4                      | ✓ change windshield                                                                                                                                                                                                                  | \$0.00     | \$0.00    | \$0.00     |        |           |      |                        |            |  |      |        |        |  |  |  |
|                        | <b><u>Notes</u></b>                                                                                                                                                                                                                  |            |           |            |        |           |      |                        |            |  |      |        |        |  |  |  |
|                        | Rh windshield nfg                                                                                                                                                                                                                    |            |           |            |        |           |      |                        |            |  |      |        |        |  |  |  |
|                        | <table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>Windshield LH</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>           | Part       | Warehouse | Vendor/Bin | Qty    | Unit Cost | Cost | Windshield LH          | Kropp Shop |  | 1.0  | \$0.00 | \$0.00 |  |  |  |
| Part                   | Warehouse                                                                                                                                                                                                                            | Vendor/Bin | Qty       | Unit Cost  | Cost   |           |      |                        |            |  |      |        |        |  |  |  |
| Windshield LH          | Kropp Shop                                                                                                                                                                                                                           |            | 1.0       | \$0.00     | \$0.00 |           |      |                        |            |  |      |        |        |  |  |  |
| 5                      | ✓ coolant leaks                                                                                                                                                                                                                      | \$0.00     | \$0.00    | \$0.00     |        |           |      |                        |            |  |      |        |        |  |  |  |
|                        | <b><u>Notes</u></b>                                                                                                                                                                                                                  |            |           |            |        |           |      |                        |            |  |      |        |        |  |  |  |
|                        | Loose clamp                                                                                                                                                                                                                          |            |           |            |        |           |      |                        |            |  |      |        |        |  |  |  |
| 6                      | ✓ Rh chain hanger mud flap and anti sail                                                                                                                                                                                             | \$0.00     | \$0.00    | \$0.00     |        |           |      |                        |            |  |      |        |        |  |  |  |
|                        | <table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr></table>                                                                                                                | Part       | Warehouse | Vendor/Bin | Qty    | Unit Cost | Cost |                        |            |  |      |        |        |  |  |  |
| Part                   | Warehouse                                                                                                                                                                                                                            | Vendor/Bin | Qty       | Unit Cost  | Cost   |           |      |                        |            |  |      |        |        |  |  |  |

Kropp Contracting  
Shop

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

**Work Order 1469**

Everett Twin, Trent Court

# CLOSED

|   |                             |            |              |        |          |
|---|-----------------------------|------------|--------------|--------|----------|
|   | 24" plastic mudflap         | Kropp Shop | 1.0          | \$0.00 | \$0.00   |
|   | anti sail bracket           | Kropp Shop | 1.0          | \$0.00 | \$0.00   |
| 7 | ✓ Battery box bolts loose   |            | \$0.00       | \$0.00 | \$0.00   |
| 8 | ✓ LH rear drive shock loose |            | \$0.00       | \$0.00 | \$0.00   |
|   |                             |            | Part Cost    |        | \$0.00   |
|   |                             |            | Labor        |        | \$0.00   |
|   |                             |            | Subtotal     |        | \$0.00   |
|   |                             |            | Tax 1 (0.0%) |        | \$0.00   |
|   |                             |            | Tax 2 (0.0%) |        | \$0.00   |
|   |                             |            | Credit       |        | (\$0.00) |
|   |                             |            | Total Cost   |        | \$0.00   |

Kropp Contracting  
Shop

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

Work Order 1491

Trent Court

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 1,448 hr & 645,159 km |

| Type | Scheduled   | Due | Started             | Closed              |
|------|-------------|-----|---------------------|---------------------|
|      | Dec 1, 2024 |     | Dec 1, 2024 6:01 PM | Dec 1, 2024 6:01 PM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 1,602 hr & 653,953 km |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Dec 15, 2024 |     | Dec 15, 2024 8:32 PM | Dec 15, 2024 8:32 PM |

| Line | Task                                                                         | Parts  | Labor  | Total  |
|------|------------------------------------------------------------------------------|--------|--------|--------|
| 1    | ✓ Exhaust<br><br><u>Notes</u><br>flex pipe clamp broke                       | \$0.00 | \$0.00 | \$0.00 |
| 2    | ✓ Lights - All<br><br><u>Notes</u><br>mirror lights out                      | \$0.00 | \$0.00 | \$0.00 |
| 3    | ✓ Mirrors<br><br><u>Notes</u><br>rh mirror heat not working                  | \$0.00 | \$0.00 | \$0.00 |
| 4    | ✓ Other<br><br><u>Notes</u><br>transmission cooler coolant line clamps loose | \$0.00 | \$0.00 | \$0.00 |

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

Kropp Contracting  
Shop

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

Work Order 1540

Trent Court

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 1,631 hr & 655,425 km |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Dec 17, 2024 |     | Dec 17, 2024 3:35 PM | Dec 17, 2024 3:35 PM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
| 2    | ✓ Oil change               | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 1,949 hr & 673,340 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Jan 19, 2025 | Jan 19, 2025 |     | Jan 19, 2025 9:23 PM | Jan 19, 2025 9:23 PM |

| Line | Task                                                                               | Parts  | Labor  | Total  |
|------|------------------------------------------------------------------------------------|--------|--------|--------|
| 1    | ✓ Air Lines<br><br><u>Notes</u><br>Red glad hand line broke and leaking            | \$0.00 | \$0.00 | \$0.00 |
| 2    | ✓ Battery<br><br><u>Notes</u><br>battery box bolt loose                            | \$0.00 | \$0.00 | \$0.00 |
| 3    | ✓ Brake Accessories<br><br><u>Notes</u><br>lh front drive lines rubbing            | \$0.00 | \$0.00 | \$0.00 |
| 4    | ✓ Check all fluid levels<br><br><u>Notes</u><br>coolant leak bottom rad hose clamp | \$0.00 | \$0.00 | \$0.00 |
| 5    | ✓ Windows<br><br><u>Notes</u><br>LH windshield cracked                             | \$0.00 | \$0.00 | \$0.00 |

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

Kropp Contracting  
Shop

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

Work Order 1616

Trent Court

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 2,053 hr & 678,632 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Jan 28, 2025 | Jan 28, 2025 |     | Jan 28, 2025 5:25 PM | Jan 28, 2025 5:25 PM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 2,090 hr & 680,231 km |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Feb 2, 2025 | Feb 2, 2025 |     | Feb 2, 2025 6:42 PM | Feb 2, 2025 6:42 PM |

| Line | Task                                                                 | Parts  | Labor  | Total  |
|------|----------------------------------------------------------------------|--------|--------|--------|
| 1    | ✓ Air Lines<br><br><u>Notes</u><br>blue glad hand leak               | \$0.00 | \$0.00 | \$0.00 |
| 2    | ✓ Battery<br><br><u>Notes</u><br>box bolts loose                     | \$0.00 | \$0.00 | \$0.00 |
| 3    | ✓ Brake Accessories<br><br><u>Notes</u><br>LH middle drive pot loose | \$0.00 | \$0.00 | \$0.00 |
| 4    | ✓ Clutch<br><br><u>Notes</u><br>grease whip MIA                      | \$0.00 | \$0.00 | \$0.00 |
| 5    | ✓ Driveline<br><br><u>Notes</u><br>Front diff output yoke loose      | \$0.00 | \$0.00 | \$0.00 |
| 6    | ✓ Mirrors<br><br><u>Notes</u><br>rh mirror heat not working          | \$0.00 | \$0.00 | \$0.00 |
| 7    | ✓ Parking Brake                                                      | \$0.00 | \$0.00 | \$0.00 |

Kropp Contracting  
Shop

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

**Work Order 1646**

Everett Twin

# CLOSED

### Notes

LH rear pot NFG

| Part           | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost     |
|----------------|------------|------------|-----|-----------|----------|
| 3030 brake pot | Kropp Shop |            | 1.0 | \$0.00    | \$0.00   |
| Part Cost      |            |            |     |           | \$0.00   |
| Labor          |            |            |     |           | \$0.00   |
| Subtotal       |            |            |     |           | \$0.00   |
| Tax 1 (0.0%)   |            |            |     |           | \$0.00   |
| Tax 2 (0.0%)   |            |            |     |           | \$0.00   |
| Credit         |            |            |     |           | (\$0.00) |
| Total Cost     |            |            |     |           | \$0.00   |

Kropp Contracting  
Shop

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

Work Order 1657

Trent Court

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 2,113 hr & 681,255 km |

| Type | Scheduled   | Due | Started              | Closed               |
|------|-------------|-----|----------------------|----------------------|
|      | Feb 4, 2025 |     | Feb 4, 2025 10:07 AM | Feb 4, 2025 10:07 AM |

| Line | Task                         |            |            | Parts        | Labor     | Total    |
|------|------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Oil change                 |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                         | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | LF14000 - Cummins oil filter | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | oil 15w-40                   | Kropp Shop |            | 42.0         | \$0.00    | \$0.00   |
|      |                              |            |            | Part Cost    |           | \$0.00   |
|      |                              |            |            | Labor        |           | \$0.00   |
|      |                              |            |            | Subtotal     |           | \$0.00   |
|      |                              |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                              |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                              |            |            | Credit       |           | (\$0.00) |
|      |                              |            |            | Total Cost   |           | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 2,411 hr & 696,768 km |

| Type | Scheduled    | Due | Started               | Closed                |
|------|--------------|-----|-----------------------|-----------------------|
|      | Mar 11, 2025 |     | Mar 11, 2025 11:05 AM | Mar 11, 2025 11:05 AM |

| Line | Task                                      |            |            | Parts        | Labor     | Total    |
|------|-------------------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Doser cracked and leaking pressure code |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                                      | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 5578983RX - Doser                         | Kropp Shop | EKW        | 1.0          | \$0.00    | \$0.00   |
|      |                                           |            |            | Part Cost    |           | \$0.00   |
|      |                                           |            |            | Labor        |           | \$0.00   |
|      |                                           |            |            | Subtotal     |           | \$0.00   |
|      |                                           |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                           |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                           |            |            | Credit       |           | (\$0.00) |
|      |                                           |            |            | Total Cost   |           | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 2,411 hr & 696,768 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Mar 13, 2025 | Mar 13, 2025 |     | Mar 13, 2025 7:12 AM | Mar 13, 2025 7:12 AM |

| Line | Task                                              | Parts      | Labor      | Total        |           |          |
|------|---------------------------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ transmission supply line rubbing on output yoke | \$0.00     | \$0.00     | \$0.00       |           |          |
| 2    | ✓ flex pipe on y pipe MIA                         | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                                              | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 5" flex pipe                                      | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | 5" step clamp                                     | Kropp Shop |            | 2.0          | \$0.00    | \$0.00   |
|      |                                                   |            |            | Part Cost    |           | \$0.00   |
|      |                                                   |            |            | Labor        |           | \$0.00   |
|      |                                                   |            |            | Subtotal     |           | \$0.00   |
|      |                                                   |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                                   |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                                   |            |            | Credit       |           | (\$0.00) |
|      |                                                   |            |            | Total Cost   |           | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 2,549 hr & 703,115 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Mar 17, 2025 | Mar 17, 2025 |     | Mar 17, 2025 6:37 PM | Mar 17, 2025 6:37 PM |

| Line | Task                         |            |            | Parts        | Labor     | Total    |
|------|------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ front LH steer Pot leaking |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                         | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | Type 24 service pot          | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                              |            |            | Part Cost    |           | \$0.00   |
|      |                              |            |            | Labor        |           | \$0.00   |
|      |                              |            |            | Subtotal     |           | \$0.00   |
|      |                              |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                              |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                              |            |            | Credit       |           | (\$0.00) |
|      |                              |            |            | Total Cost   |           | \$0.00   |

Kropp Contracting  
Shop

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

**Work Order 1802**

Nate Vandenberghe

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 2,592 hr & 705,126 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Mar 21, 2025 | Mar 21, 2025 |     | Mar 21, 2025 2:09 PM | Mar 21, 2025 2:09 PM |

| Line | Task                | Parts        | Labor  | Total    |
|------|---------------------|--------------|--------|----------|
| 1    | ✓ def filter change | \$0.00       | \$0.00 | \$0.00   |
|      |                     | Part Cost    |        | \$0.00   |
|      |                     | Labor        |        | \$0.00   |
|      |                     | Subtotal     |        | \$0.00   |
|      |                     | Tax 1 (0.0%) |        | \$0.00   |
|      |                     | Tax 2 (0.0%) |        | \$0.00   |
|      |                     | Credit       |        | (\$0.00) |
|      |                     | Total Cost   |        | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 2,592 hr & 705,126 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Mar 27, 2025 | Mar 27, 2025 |     | Mar 28, 2025 8:39 PM | Mar 28, 2025 8:39 PM |

| Line | Task                         | Parts      | Labor      | Total        |           |          |
|------|------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Grease truck and trailer   | \$0.00     | \$0.00     | \$0.00       |           |          |
| 2    | ✓ Oil change                 | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                         | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | LF14000 - Cummins oil filter | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                              |            |            | Part Cost    |           | \$0.00   |
|      |                              |            |            | Labor        |           | \$0.00   |
|      |                              |            |            | Subtotal     |           | \$0.00   |
|      |                              |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                              |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                              |            |            | Credit       |           | (\$0.00) |
|      |                              |            |            | Total Cost   |           | \$0.00   |

# 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

**CLOSED**

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 2,631 hr & 706,985 km |

| Type | Created     | Scheduled   | Due | Started              | Closed              |
|------|-------------|-------------|-----|----------------------|---------------------|
|      | May 5, 2025 | May 5, 2025 |     | May 5, 2025 10:07 AM | May 6, 2025 8:57 AM |

| Line | Task                            | Parts  | Labor  | Total  |
|------|---------------------------------|--------|--------|--------|
| 1    | ✓ Preform Scheduled Maintenance | \$0.00 | \$0.00 | \$0.00 |
| 2    | ✓ Power steering fluid leak     | \$0.00 | \$0.00 | \$0.00 |

**Notes**

ORB fitting leaking from O-ring

|   |                 |        |        |        |
|---|-----------------|--------|--------|--------|
| 3 | ✓ Drag Link NFG | \$0.00 | \$0.00 | \$0.00 |
|---|-----------------|--------|--------|--------|

| Part                        | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|-----------------------------|------------|------------|-----|-----------|--------|
| 346-574 - RH drag link T800 | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

|   |                                |        |        |        |
|---|--------------------------------|--------|--------|--------|
| 4 | ✓ Middle axle cross member NFG | \$0.00 | \$0.00 | \$0.00 |
|---|--------------------------------|--------|--------|--------|

| Part                             | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|----------------------------------|------------|------------|-----|-----------|--------|
| 48100581 - Neway crossmember kit | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

|   |                    |        |        |        |
|---|--------------------|--------|--------|--------|
| 5 | ✓ Tail lights INOP | \$0.00 | \$0.00 | \$0.00 |
|---|--------------------|--------|--------|--------|

| Part           | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|----------------|------------|------------|-----|-----------|--------|
| 4" red light   | Kropp Shop |            | 2.0 | \$0.00    | \$0.00 |
| 3 wire pigtail | Kropp Shop |            | 2.0 | \$0.00    | \$0.00 |

|   |                      |        |        |        |
|---|----------------------|--------|--------|--------|
| 6 | ✓ Marker lights INOP | \$0.00 | \$0.00 | \$0.00 |
|---|----------------------|--------|--------|--------|

**Notes**

LHS mickey mouse light marker lights INOP

| Part                       | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|----------------------------|------------|------------|-----|-----------|--------|
| Mickey Mouse light harness | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

|   |                           |        |        |        |
|---|---------------------------|--------|--------|--------|
| 7 | ✓ Mirror cracked, replace | \$0.00 | \$0.00 | \$0.00 |
|---|---------------------------|--------|--------|--------|

| Part | Warehouse | Vendor/Bin | Qty | Unit Cost | Cost |
|------|-----------|------------|-----|-----------|------|
|------|-----------|------------|-----|-----------|------|

# 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

**CLOSED**

|    |                                |            |              |        |           |        |
|----|--------------------------------|------------|--------------|--------|-----------|--------|
|    | T800 west coast mirror         | Kropp Shop | 1.0          | \$0.00 | \$0.00    |        |
| 8  | ✓ Air filters                  |            | \$0.00       | \$0.00 | \$0.00    |        |
|    | Part                           | Warehouse  | Vendor/Bin   | Qty    | Unit Cost | Cost   |
|    | AF4195 - air filters T800      | Kropp Shop |              | 2.0    | \$0.00    | \$0.00 |
| 9  | ✓ change diff filters          |            | \$0.00       | \$0.00 | \$0.00    |        |
|    | Part                           | Warehouse  | Vendor/Bin   | Qty    | Unit Cost | Cost   |
|    | LF3311 - Rockwell diff filter  | Kropp Shop |              | 2.0    | \$0.00    | \$0.00 |
| 10 | ✓ Adjust Brakes                |            | \$0.00       | \$0.00 | \$0.00    |        |
| 11 | ✓ Diff breather tore off       |            | \$0.00       | \$0.00 | \$0.00    |        |
|    | <b><u>Notes</u></b>            |            |              |        |           |        |
|    | middle axle                    |            |              |        |           |        |
| 12 | ✓ Replace shock                |            | \$0.00       | \$0.00 | \$0.00    |        |
|    | <b><u>Notes</u></b>            |            |              |        |           |        |
|    | miidle axle L/H                |            |              |        |           |        |
| 13 | ✓ CVIP inspection (wheels off) |            | \$0.00       | \$0.00 | \$0.00    |        |
|    |                                |            | Part Cost    |        | \$0.00    |        |
|    |                                |            | Labor        |        | \$0.00    |        |
|    |                                |            | Subtotal     |        | \$0.00    |        |
|    |                                |            | Tax 1 (0.0%) |        | \$0.00    |        |
|    |                                |            | Tax 2 (0.0%) |        | \$0.00    |        |
|    |                                |            | Credit       |        | (\$0.00)  |        |
|    |                                |            | Total Cost   |        | \$0.00    |        |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 2,735 hr & 712,928 km |

| Type   | Created      | Scheduled    | Due | Started              | Closed               |
|--------|--------------|--------------|-----|----------------------|----------------------|
| engine | May 22, 2025 | May 22, 2025 |     | May 22, 2025 4:59 AM | May 22, 2025 4:59 AM |

| Line | Task                   | Parts  | Labor  | Total    |
|------|------------------------|--------|--------|----------|
| 1    | ✓ DEF codes            | \$0.00 | \$0.00 | \$0.00   |
|      | <b>Notes</b>           |        |        |          |
|      | DEF pressure codes     |        |        |          |
| 2    | ✓ Replace Def injector | \$0.00 | \$0.00 | \$0.00   |
|      | Part Cost              |        |        | \$0.00   |
|      | Labor                  |        |        | \$0.00   |
|      | Subtotal               |        |        | \$0.00   |
|      | Tax 1 (0.0%)           |        |        | \$0.00   |
|      | Tax 2 (0.0%)           |        |        | \$0.00   |
|      | Credit                 |        |        | (\$0.00) |
|      | Total Cost             |        |        | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 2,791 hr & 715,693 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | May 27, 2025 | May 27, 2025 |     | May 27, 2025 7:16 PM | May 27, 2025 7:16 PM |

| Line | Task                          | Parts  | Labor  | Total  |
|------|-------------------------------|--------|--------|--------|
| 1    | ✓ diagnose Check engine light | \$0.00 | \$0.00 | \$0.00 |

### Notes

Replaced DEF pump, fixed additional chafed wire near engine head,  
after treatment harness #1

| Part                      | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost     |
|---------------------------|------------|------------|-----|-----------|----------|
| 5509448RX - DEF pump t880 | Kropp Shop |            | 1.0 | \$0.00    | \$0.00   |
| Part Cost                 |            |            |     |           | \$0.00   |
| Labor                     |            |            |     |           | \$0.00   |
| Subtotal                  |            |            |     |           | \$0.00   |
| Tax 1 (0.0%)              |            |            |     |           | \$0.00   |
| Tax 2 (0.0%)              |            |            |     |           | \$0.00   |
| Credit                    |            |            |     |           | (\$0.00) |
| Total Cost                |            |            |     |           | \$0.00   |

Kropp Contracting  
Shop

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

Work Order 1891

Cam Nadeau

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 2,857 hr & 719,792 km |

| Type       | Created     | Scheduled   | Due | Started             | Closed              |
|------------|-------------|-------------|-----|---------------------|---------------------|
| electrical | Jun 3, 2025 | Jun 3, 2025 |     | Jun 3, 2025 1:46 PM | Jun 3, 2025 1:46 PM |

| Line | Task        | Parts        | Labor  | Total    |
|------|-------------|--------------|--------|----------|
| 1    | ✓ DEF codes | \$0.00       | \$0.00 | \$0.00   |
|      |             | Part Cost    |        | \$0.00   |
|      |             | Labor        |        | \$0.00   |
|      |             | Subtotal     |        | \$0.00   |
|      |             | Tax 1 (0.0%) |        | \$0.00   |
|      |             | Tax 2 (0.0%) |        | \$0.00   |
|      |             | Credit       |        | (\$0.00) |
|      |             | Total Cost   |        | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 2,888 hr & 721,781 km |

| Type | Created      | Scheduled    | Due | Started               | Closed                |
|------|--------------|--------------|-----|-----------------------|-----------------------|
|      | Jun 10, 2025 | Jun 10, 2025 |     | Jun 10, 2025 11:04 AM | Jun 10, 2025 11:06 AM |

| Line | Task                    | Parts        | Labor      | Total  |           |          |
|------|-------------------------|--------------|------------|--------|-----------|----------|
| 1    | ✓ Hood light INOP       | \$0.00       | \$0.00     | \$0.00 |           |          |
|      | Part                    | Warehouse    | Vendor/Bin | Qty    | Unit Cost | Cost     |
|      | G5543 - hood light T800 | Kropp Shop   |            | 1.0    | \$0.00    | \$0.00   |
| 2    | ✓ Replace shock         | \$0.00       | \$0.00     | \$0.00 |           |          |
|      | <b><u>Notes</u></b>     |              |            |        |           |          |
|      | RM and RF leaking       |              |            |        |           |          |
| 3    | ✓ Loose shock           | \$0.00       | \$0.00     | \$0.00 |           |          |
|      | <b><u>Notes</u></b>     |              |            |        |           |          |
|      | LR and LM               |              |            |        |           |          |
| 4    | ✓ Bondo hood            | \$0.00       | \$0.00     | \$0.00 |           |          |
| 5    | ✓ Check fluid levels    | \$0.00       | \$0.00     | \$0.00 |           |          |
|      |                         | Part Cost    |            |        |           | \$0.00   |
|      |                         | Labor        |            |        |           | \$0.00   |
|      |                         | Subtotal     |            |        |           | \$0.00   |
|      |                         | Tax 1 (0.0%) |            |        |           | \$0.00   |
|      |                         | Tax 2 (0.0%) |            |        |           | \$0.00   |
|      |                         | Credit       |            |        |           | (\$0.00) |
|      |                         | Total Cost   |            |        |           | \$0.00   |

Kropp Contracting  
Shop

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

Work Order 1925

Cam Nadeau

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 2,954 hr & 725,561 km |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Jun 22, 2025 |     | Jun 22, 2025 8:05 AM | Jun 22, 2025 8:05 AM |

| Line | Task         | Parts  | Labor  | Total  |
|------|--------------|--------|--------|--------|
| 1    | ✓ Oil change | \$0.00 | \$0.00 | \$0.00 |

### Notes

oil and fuel filters changed as well

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

Kropp Contracting  
Shop

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

Work Order 1948

Everett Twin

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 3,018 hr & 729,372 km |

| Type | Scheduled   | Due | Started             | Closed              |
|------|-------------|-----|---------------------|---------------------|
|      | Jul 1, 2025 |     | Jul 1, 2025 8:24 PM | Jul 1, 2025 8:24 PM |

| Line | Task                 | Parts  | Labor  | Total  |
|------|----------------------|--------|--------|--------|
| 1    | ✓ Broken Crossmember | \$0.00 | \$0.00 | \$0.00 |

### Notes

Carrier bearing crossmember NFG

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

Kropp Contracting  
Shop

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

Work Order 1952

Trent Court

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 3,018 hr & 729,372 km |

| Type | Scheduled   | Due | Started             | Closed              |
|------|-------------|-----|---------------------|---------------------|
|      | Jul 3, 2025 |     | Jul 3, 2025 7:35 AM | Jul 3, 2025 7:35 AM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

Kropp Contracting  
Shop

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

Work Order 2007

Trent Court

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 3,217 hr & 743,226 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Jul 25, 2025 | Jul 25, 2025 |     | Jul 25, 2025 3:46 PM | Jul 25, 2025 3:46 PM |

| Line | Task                | Parts        | Labor  | Total    |
|------|---------------------|--------------|--------|----------|
| 1    | ✓ LH steer tire nfg | \$0.00       | \$0.00 | \$0.00   |
|      |                     | Part Cost    |        | \$0.00   |
|      |                     | Labor        |        | \$0.00   |
|      |                     | Subtotal     |        | \$0.00   |
|      |                     | Tax 1 (0.0%) |        | \$0.00   |
|      |                     | Tax 2 (0.0%) |        | \$0.00   |
|      |                     | Credit       |        | (\$0.00) |
|      |                     | Total Cost   |        | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 3,233 hr & 744,401 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Jul 29, 2025 | Jul 29, 2025 |     | Jul 29, 2025 2:36 PM | Jul 29, 2025 2:36 PM |

| Line | Task                            | Parts      | Labor      | Total        |           |          |
|------|---------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Hood pushing into wipers      | \$0.00     | \$0.00     | \$0.00       |           |          |
| 2    | ✓ A/c not working               | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                            | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 1000534258BSM - Expansion valve | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                                 |            |            | Part Cost    |           | \$0.00   |
|      |                                 |            |            | Labor        |           | \$0.00   |
|      |                                 |            |            | Subtotal     |           | \$0.00   |
|      |                                 |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                 |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                 |            |            | Credit       |           | (\$0.00) |
|      |                                 |            |            | Total Cost   |           | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 3,250 hr & 745,577 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Jul 31, 2025 | Jul 31, 2025 |     | Jul 31, 2025 2:42 PM | Jul 31, 2025 3:10 PM |

| Line | Task           | Parts  | Labor  | Total  |
|------|----------------|--------|--------|--------|
| 1    | ✓ Exhaust leak | \$0.00 | \$0.00 | \$0.00 |

**Notes**

Exhaust leak off of turbo pipe, tighten and check for leaks. No noise or leaks

|   |                   |        |        |        |
|---|-------------------|--------|--------|--------|
| 2 | ✓ Scam tube loose | \$0.00 | \$0.00 | \$0.00 |
|---|-------------------|--------|--------|--------|

| Part         | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost     |
|--------------|------------|------------|-----|-----------|----------|
| 2-1/2 u bolt | Kropp Shop |            | 1.0 | \$0.00    | \$0.00   |
| Part Cost    |            |            |     |           | \$0.00   |
| Labor        |            |            |     |           | \$0.00   |
| Subtotal     |            |            |     |           | \$0.00   |
| Tax 1 (0.0%) |            |            |     |           | \$0.00   |
| Tax 2 (0.0%) |            |            |     |           | \$0.00   |
| Credit       |            |            |     |           | (\$0.00) |
| Total Cost   |            |            |     |           | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 3,265 hr & 746,648 km |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Aug 5, 2025 | Aug 5, 2025 |     | Aug 5, 2025 7:23 AM | Aug 5, 2025 7:23 AM |

| Line | Task            | Parts  | Labor  | Total  |
|------|-----------------|--------|--------|--------|
| 1    | ✓ Headlamp inop | \$0.00 | \$0.00 | \$0.00 |

### Notes

Bad terminal connection, new terminal pins. Found lights okay after new terminal pins

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 3,373 hr & 754,158 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Aug 22, 2025 | Aug 22, 2025 |     | Aug 22, 2025 6:52 PM | Aug 22, 2025 6:52 PM |

| Line | Task                                |            |            | Parts        | Labor     | Total    |
|------|-------------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Alternator not charging           |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                                | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | D27-1019-0200P - Alternator Cummins | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                                     |            |            | Part Cost    |           | \$0.00   |
|      |                                     |            |            | Labor        |           | \$0.00   |
|      |                                     |            |            | Subtotal     |           | \$0.00   |
|      |                                     |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                     |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                     |            |            | Credit       |           | (\$0.00) |
|      |                                     |            |            | Total Cost   |           | \$0.00   |

# 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

**CLOSED**

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 3,417 hr & 757,131 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Aug 29, 2025 | Aug 29, 2025 |     | Aug 29, 2025 3:34 PM | Aug 29, 2025 3:36 PM |

| Line | Task                                 | Parts      | Labor      | Total  |           |        |
|------|--------------------------------------|------------|------------|--------|-----------|--------|
| 1    | ✓ Steer Tires                        | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                 | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | steer tires                          | Kropp Shop |            | 2.0    | \$0.00    | \$0.00 |
| 2    | ✓ Loose scam u bolt                  | \$0.00     | \$0.00     | \$0.00 |           |        |
| 3    | ✓ Loose shock                        | \$0.00     | \$0.00     | \$0.00 |           |        |
| 4    | ✓ Replace Stack bushings and bearing | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                 | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | EM75-69000-HT - Stack bushing kit    | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 5    | ✓ coolant leaks                      | \$0.00     | \$0.00     | \$0.00 |           |        |

## Notes

Tighten clamp off of tranny cooler

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 3,531 hr & 765,086 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Sep 16, 2025 | Sep 16, 2025 |     | Sep 16, 2025 6:58 PM | Sep 16, 2025 6:58 PM |

| Line | Task                                     | Parts      | Labor      | Total        |           |          |
|------|------------------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Grease truck and trailer               | \$0.00     | \$0.00     | \$0.00       |           |          |
| 2    | ✓ Oil change                             | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                                     | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | LF14000 - Cummins oil filter             | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | oil 15w-40                               | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | FF5825NN - Cummins fuel filter           | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | FS20172 - Cummins water separator filter | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                                          |            |            | Part Cost    |           | \$0.00   |
|      |                                          |            |            | Labor        |           | \$0.00   |
|      |                                          |            |            | Subtotal     |           | \$0.00   |
|      |                                          |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                          |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                          |            |            | Credit       |           | (\$0.00) |
|      |                                          |            |            | Total Cost   |           | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 3,670 hr & 774,354 km |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Oct 3, 2025 | Oct 3, 2025 |     | Oct 3, 2025 4:34 PM | Oct 3, 2025 4:34 PM |

| Line | Task           | Parts  | Labor  | Total  |
|------|----------------|--------|--------|--------|
| 1    | ✓ Exhaust leak | \$0.00 | \$0.00 | \$0.00 |

### Notes

Exhaust pipe blew off of turbo due to work flange, remove exhaust pipe and weld new flange on. Reinstall exhaust and test for leaks, no leaks

|   |            |        |        |        |
|---|------------|--------|--------|--------|
| 2 | ✓ Air leak | \$0.00 | \$0.00 | \$0.00 |
|---|------------|--------|--------|--------|

### Notes

Air leak on splitter, replace union and test. No leaks

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

Kropp Contracting  
Shop

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

Work Order 2186

Trent Court

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 3,725 hr & 777,716 km |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Oct 13, 2025 |     | Oct 13, 2025 8:24 AM | Oct 13, 2025 8:24 AM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 3,819 hr & 782,785 km |

| Type | Created      | Scheduled    | Due | Started              | Closed              |
|------|--------------|--------------|-----|----------------------|---------------------|
|      | Oct 30, 2025 | Oct 30, 2025 |     | Oct 30, 2025 3:53 PM | Nov 4, 2025 5:00 PM |

| Line | Task               | Parts  | Labor  | Total  |
|------|--------------------|--------|--------|--------|
| 1    | ✓ Adjust Brakes    | \$0.00 | \$0.00 | \$0.00 |
| 2    | ✓ Replace wishbone | \$0.00 | \$0.00 | \$0.00 |

**Notes**

Front wishbone NFG, replace wishbone and set aside for bushing replacement

|   |                           |        |        |        |
|---|---------------------------|--------|--------|--------|
| 3 | ✓ Mirror cracked, replace | \$0.00 | \$0.00 | \$0.00 |
|---|---------------------------|--------|--------|--------|

| Part                   | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|------------------------|------------|------------|-----|-----------|--------|
| T800 west coast mirror | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

|   |                                                         |        |        |        |
|---|---------------------------------------------------------|--------|--------|--------|
| 4 | ✓ Transmission cooler coolant lines leaking-<br>Replace | \$0.00 | \$0.00 | \$0.00 |
|---|---------------------------------------------------------|--------|--------|--------|

**Notes**

Replaced both transmission cooler coolant lines, test for leaks after replacement. No leaks, top rad up

|   |                                      |        |        |        |
|---|--------------------------------------|--------|--------|--------|
| 5 | ✓ Tie up wires chafing on driveshaft | \$0.00 | \$0.00 | \$0.00 |
|---|--------------------------------------|--------|--------|--------|

|   |                                 |        |        |        |
|---|---------------------------------|--------|--------|--------|
| 6 | ✓ Preform Scheduled Maintenance | \$0.00 | \$0.00 | \$0.00 |
|---|---------------------------------|--------|--------|--------|

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 3,899 hr & 787,418 km |

| Type | Created      | Scheduled    | Due | Started              | Closed                |
|------|--------------|--------------|-----|----------------------|-----------------------|
|      | Nov 11, 2025 | Nov 11, 2025 |     | Nov 11, 2025 4:02 PM | Nov 12, 2025 11:26 AM |

| Line         | Task                              | Parts  | Labor  | Total    |
|--------------|-----------------------------------|--------|--------|----------|
| 1            | ✓ King pin drivers side           | \$0.00 | \$0.00 | \$0.00   |
| 2            | ✓ Rear right dust sheild          | \$0.00 | \$0.00 | \$0.00   |
| 3            | ✓ Down pipe                       | \$0.00 | \$0.00 | \$0.00   |
| 4            | ✓ Bellows pipe                    | \$0.00 | \$0.00 | \$0.00   |
| 5            | ✓ Top rad hose coolant leak       | \$0.00 | \$0.00 | \$0.00   |
| 6            | ✓ Bottom rad hose leak            | \$0.00 | \$0.00 | \$0.00   |
| 7            | ✓ Coolant return hose             | \$0.00 | \$0.00 | \$0.00   |
| 8            | ✓ Loose can shock right sude      | \$0.00 | \$0.00 | \$0.00   |
| 9            | ✓ Fix air leak on spliter         | \$0.00 | \$0.00 | \$0.00   |
| 10           | ✓ Tightened Left rear drive shock | \$0.00 | \$0.00 | \$0.00   |
| 11           | ✓ Checked dif levels              | \$0.00 | \$0.00 | \$0.00   |
| 12           | ✓ Checked hub levels              | \$0.00 | \$0.00 | \$0.00   |
| 13           | ✓ Grease truck and trailer        | \$0.00 | \$0.00 | \$0.00   |
| Part Cost    |                                   |        |        | \$0.00   |
| Labor        |                                   |        |        | \$0.00   |
| Subtotal     |                                   |        |        | \$0.00   |
| Tax 1 (0.0%) |                                   |        |        | \$0.00   |
| Tax 2 (0.0%) |                                   |        |        | \$0.00   |
| Credit       |                                   |        |        | (\$0.00) |
| Total Cost   |                                   |        |        | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 3,899 hr & 787,418 km |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Nov 14, 2025 |     | Nov 14, 2025 2:05 PM | Nov 14, 2025 2:05 PM |

| Line | Task                                                                           | Parts  | Labor  | Total  |
|------|--------------------------------------------------------------------------------|--------|--------|--------|
| 1    | ✓ Check all fluid levels<br><b>Notes</b><br>coolant and power steering low     | \$0.00 | \$0.00 | \$0.00 |
| 2    | ✓ Lights - All<br><b>Notes</b><br>bent MM light brackets                       | \$0.00 | \$0.00 | \$0.00 |
| 3    | ✓ Radiator<br><b>Notes</b><br>coolant filter leaking                           | \$0.00 | \$0.00 | \$0.00 |
| 4    | ✓ Steering System<br><b>Notes</b><br>LH steering box leaking out of shaft seal | \$0.00 | \$0.00 | \$0.00 |

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 3,988 hr & 792,462 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Nov 21, 2025 | Nov 21, 2025 |     | Nov 22, 2025 8:27 AM | Nov 22, 2025 8:27 AM |

| Line | Task                         |            |            | Parts        | Labor     | Total    |
|------|------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Oil change                 |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                         | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | LF14000 - Cummins oil filter | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                              |            |            | Part Cost    |           | \$0.00   |
|      |                              |            |            | Labor        |           | \$0.00   |
|      |                              |            |            | Subtotal     |           | \$0.00   |
|      |                              |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                              |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                              |            |            | Credit       |           | (\$0.00) |
|      |                              |            |            | Total Cost   |           | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 4,191 hr & 803,716 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Dec 11, 2025 | Dec 11, 2025 |     | Dec 13, 2025 8:22 AM | Dec 13, 2025 8:22 AM |

| Line | Task                                       | Parts        | Labor  | Total    |
|------|--------------------------------------------|--------------|--------|----------|
| 1    | ✓ Changed all after treatment temp sensors | \$0.00       | \$0.00 | \$0.00   |
|      |                                            | Part Cost    |        | \$0.00   |
|      |                                            | Labor        |        | \$0.00   |
|      |                                            | Subtotal     |        | \$0.00   |
|      |                                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                                            | Credit       |        | (\$0.00) |
|      |                                            | Total Cost   |        | \$0.00   |

# 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 4,230 hr & 804,953 km |

| Type | Created      | Scheduled    | Due | Started               | Closed                |
|------|--------------|--------------|-----|-----------------------|-----------------------|
|      | Dec 14, 2025 | Dec 14, 2025 |     | Dec 14, 2025 11:07 AM | Dec 14, 2025 11:07 AM |

| Line | Task                                                                                                     | Parts  | Labor  | Total  |
|------|----------------------------------------------------------------------------------------------------------|--------|--------|--------|
| 1    | ✓ Body<br><br><u>Notes</u><br>battery box bolt mia                                                       | \$0.00 | \$0.00 | \$0.00 |
| 2    | ✓ Brake Accessories<br><br><u>Notes</u><br>rh front dust cover loose                                     | \$0.00 | \$0.00 | \$0.00 |
| 3    | ✓ Driveline<br><br><u>Notes</u><br>wire rubbing on mainshaft                                             | \$0.00 | \$0.00 | \$0.00 |
| 4    | ✓ Lights - All<br><br><u>Notes</u><br>LH mirror light out, top lh work light                             | \$0.00 | \$0.00 | \$0.00 |
| 5    | ✓ Parking Brake<br><br><u>Notes</u><br>jam nuts on rear rh axle backed off, middle lh brake pot is loose | \$0.00 | \$0.00 | \$0.00 |
| 6    | ✓ Rear End<br><br><u>Notes</u><br>front diff filter cover and bolt MIA                                   | \$0.00 | \$0.00 | \$0.00 |
| 7    | ✓ Service Brakes                                                                                         | \$0.00 | \$0.00 | \$0.00 |

Kropp Contracting  
Shop

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

**Work Order 2371**

Trent Court

# CLOSED

### Notes

rear drive brakes need adjstment

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 4,370 hr & 811,416 km |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Jan 3, 2026 | Jan 3, 2026 |     | Jan 3, 2026 4:17 PM | Jan 3, 2026 4:17 PM |

| Line | Task                                  |            |            | Parts        | Labor     | Total    |
|------|---------------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Def pressure low but operating code |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                                  | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 5578983RX - Doser                     | Kropp Shop | EKW        | 1.0          | \$0.00    | \$0.00   |
|      | 5509448RX - DEF pump t880             | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                                       |            |            | Part Cost    |           | \$0.00   |
|      |                                       |            |            | Labor        |           | \$0.00   |
|      |                                       |            |            | Subtotal     |           | \$0.00   |
|      |                                       |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                       |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                       |            |            | Credit       |           | (\$0.00) |
|      |                                       |            |            | Total Cost   |           | \$0.00   |

Kropp Contracting  
Shop

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

Work Order 2416

Trent Court

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 4,370 hr & 811,416 km |

| Type | Scheduled   | Due | Started             | Closed              |
|------|-------------|-----|---------------------|---------------------|
|      | Jan 3, 2026 |     | Jan 3, 2026 4:21 PM | Jan 3, 2026 4:21 PM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 4,425 hr & 814,875 km |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Jan 8, 2026 | Jan 8, 2026 |     | Jan 8, 2026 6:04 AM | Jan 8, 2026 6:04 AM |

| Line | Task                     |            |            | Parts        | Labor     | Total    |
|------|--------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Change rh wiper blade  |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                     | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 15" wiper blade          | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
| 2    | ✓ Rh steer brake pot nfg |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                     | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | Type 24 service pot      | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                          |            |            | Part Cost    |           | \$0.00   |
|      |                          |            |            | Labor        |           | \$0.00   |
|      |                          |            |            | Subtotal     |           | \$0.00   |
|      |                          |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                          |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                          |            |            | Credit       |           | (\$0.00) |
|      |                          |            |            | Total Cost   |           | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 4,425 hr & 814,875 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Jan 11, 2026 | Jan 11, 2026 |     | Jan 12, 2026 7:15 PM | Jan 12, 2026 7:15 PM |

| Line | Task                          | Parts      | Labor      | Total        |           |          |
|------|-------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ LH rear drive air bag blown | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                          | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 9501 - drive airbag           | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                               |            |            | Part Cost    |           | \$0.00   |
|      |                               |            |            | Labor        |           | \$0.00   |
|      |                               |            |            | Subtotal     |           | \$0.00   |
|      |                               |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                               |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                               |            |            | Credit       |           | (\$0.00) |
|      |                               |            |            | Total Cost   |           | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 4,425 hr & 814,875 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Jan 17, 2026 | Jan 17, 2026 |     | Jan 17, 2026 6:45 AM | Jan 17, 2026 6:45 AM |

| Line | Task                         | Parts        | Labor      | Total  |           |          |
|------|------------------------------|--------------|------------|--------|-----------|----------|
| 1    | ✓ Oil change                 | \$0.00       | \$0.00     | \$0.00 |           |          |
|      | Part                         | Warehouse    | Vendor/Bin | Qty    | Unit Cost | Cost     |
|      | LF14000 - Cummins oil filter | Kropp Shop   |            | 1.0    | \$0.00    | \$0.00   |
| 2    | ✓ Grease truck and trailer   | \$0.00       | \$0.00     | \$0.00 |           |          |
|      |                              | Part Cost    |            |        |           | \$0.00   |
|      |                              | Labor        |            |        |           | \$0.00   |
|      |                              | Subtotal     |            |        |           | \$0.00   |
|      |                              | Tax 1 (0.0%) |            |        |           | \$0.00   |
|      |                              | Tax 2 (0.0%) |            |        |           | \$0.00   |
|      |                              | Credit       |            |        |           | (\$0.00) |
|      |                              | Total Cost   |            |        |           | \$0.00   |

# 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 4,666 hr & 872,027 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Jan 31, 2026 | Jan 31, 2026 |     | Jan 31, 2026 4:53 PM | Jan 31, 2026 4:53 PM |

| Line | Task                                   | Parts      | Labor      | Total  |           |        |
|------|----------------------------------------|------------|------------|--------|-----------|--------|
| 1    | ✓ Body                                 | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <u>Notes</u>                           |            |            |        |           |        |
|      | LH step loose                          |            |            |        |           |        |
| 2    | ✓ Brake Accessories                    | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <u>Notes</u>                           |            |            |        |           |        |
|      | LH middle drive pot loose              |            |            |        |           |        |
|      | Part                                   | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | 3030 brake pot                         | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 3    | ✓ Check all fluid levels               | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <u>Notes</u>                           |            |            |        |           |        |
|      | coolant leak somewhere (pressure test) |            |            |        |           |        |
| 4    | ✓ Clutch                               | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <u>Notes</u>                           |            |            |        |           |        |
|      | grease pivot arm bearing               |            |            |        |           |        |
| 5    | ✓ Parking Brake                        | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <u>Notes</u>                           |            |            |        |           |        |
|      | rh rear s cam u bolt loose             |            |            |        |           |        |
| 6    | ✓ Rear End                             | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <u>Notes</u>                           |            |            |        |           |        |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

# CLOSED

rear diff wishbone loose bolts (bottom right)

|   |                  |        |        |        |
|---|------------------|--------|--------|--------|
| 7 | ✓ Service Brakes | \$0.00 | \$0.00 | \$0.00 |
|---|------------------|--------|--------|--------|

**Notes**

adjust rear drive brakes

|   |                     |        |        |        |
|---|---------------------|--------|--------|--------|
| 8 | ✓ Suspension System | \$0.00 | \$0.00 | \$0.00 |
|---|---------------------|--------|--------|--------|

**Notes**

rear drive LH shock bolt MIA

|   |         |        |        |        |
|---|---------|--------|--------|--------|
| 9 | ✓ Tires | \$0.00 | \$0.00 | \$0.00 |
|---|---------|--------|--------|--------|

**Notes**

LHRI flat

| Part                   | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost     |
|------------------------|------------|------------|-----|-----------|----------|
| 245 Truck - Drive tire | Kropp Shop |            | 1.0 | \$0.00    | \$0.00   |
| Part Cost              |            |            |     |           | \$0.00   |
| Labor                  |            |            |     |           | \$0.00   |
| Subtotal               |            |            |     |           | \$0.00   |
| Tax 1 (0.0%)           |            |            |     |           | \$0.00   |
| Tax 2 (0.0%)           |            |            |     |           | \$0.00   |
| Credit                 |            |            |     |           | (\$0.00) |
| Total Cost             |            |            |     |           | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 4,682 hr & 872,027 km |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Feb 2, 2026 | Feb 2, 2026 |     | Feb 2, 2026 5:47 PM | Feb 2, 2026 5:47 PM |

| Line | Task                       | Parts      | Labor      | Total        |           |          |
|------|----------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Grease truck and trailer | \$0.00     | \$0.00     | \$0.00       |           |          |
| 2    | ✓ LH wiper                 | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                       | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 15" wiper blade            | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                            |            |            | Part Cost    |           | \$0.00   |
|      |                            |            |            | Labor        |           | \$0.00   |
|      |                            |            |            | Subtotal     |           | \$0.00   |
|      |                            |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                            |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                            |            |            | Credit       |           | (\$0.00) |
|      |                            |            |            | Total Cost   |           | \$0.00   |

# 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

**CLOSED**

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 4,868 hr & 872,027 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Feb 22, 2026 | Feb 22, 2026 |     | Feb 22, 2026 9:30 AM | Feb 22, 2026 9:30 AM |

| Line | Task                                  |            |            | Parts        | Labor      | Total      |
|------|---------------------------------------|------------|------------|--------------|------------|------------|
| 1    | ✓ Transmission shift colar split in 2 |            |            | \$4,800.00   | \$0.00     | \$4,800.00 |
|      | Part                                  | Warehouse  | Vendor/Bin | Qty          | Unit Cost  | Cost       |
|      | RTLO-18918B - Transmission            | Kropp Shop |            | 1.0          | \$4,800.00 | \$4,800.00 |
| 2    | ✓ Change clutch                       |            |            | \$2,175.00   | \$0.00     | \$2,175.00 |
|      | Part                                  | Warehouse  | Vendor/Bin | Qty          | Unit Cost  | Cost       |
|      | 308925-25-pac - Clutch                | Kropp Shop |            | 1.0          | \$2,175.00 | \$2,175.00 |
| 3    | ✓ Def Doser code                      |            |            | \$0.00       | \$0.00     | \$0.00     |
|      | Part                                  | Warehouse  | Vendor/Bin | Qty          | Unit Cost  | Cost       |
|      | 5578983RX - Doser                     | Kropp Shop | EKW        | 1.0          | \$0.00     | \$0.00     |
|      |                                       |            |            | Part Cost    |            | \$6,975.00 |
|      |                                       |            |            | Labor        |            | \$0.00     |
|      |                                       |            |            | Subtotal     |            | \$6,975.00 |
|      |                                       |            |            | Tax 1 (0.0%) |            | \$0.00     |
|      |                                       |            |            | Tax 2 (0.0%) |            | \$0.00     |
|      |                                       |            |            | Credit       |            | (\$0.00)   |
|      |                                       |            |            | Total Cost   |            | \$6,975.00 |

## Notes

| Notes     | User        | Time                 |
|-----------|-------------|----------------------|
| 835669 km | Trent Court | Feb 22, 2026 9:31 AM |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

Work Order 2587

Sam Hawksley

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 4,894 hr & 837,782 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Feb 25, 2026 | Feb 25, 2026 |     | Feb 26, 2026 4:37 AM | Feb 26, 2026 4:37 AM |

| Line | Task                              | Parts        | Labor  | Total    |
|------|-----------------------------------|--------------|--------|----------|
| 1    | ✓ Tighten input yoak on first dif | \$0.00       | \$0.00 | \$0.00   |
|      |                                   | Part Cost    |        | \$0.00   |
|      |                                   | Labor        |        | \$0.00   |
|      |                                   | Subtotal     |        | \$0.00   |
|      |                                   | Tax 1 (0.0%) |        | \$0.00   |
|      |                                   | Tax 2 (0.0%) |        | \$0.00   |
|      |                                   | Credit       |        | (\$0.00) |
|      |                                   | Total Cost   |        | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 4,894 hr & 872,027 km |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Feb 26, 2026 |     | Feb 26, 2026 4:36 AM | Feb 26, 2026 4:36 AM |

| Line | Task                                   | Parts        | Labor  | Total    |
|------|----------------------------------------|--------------|--------|----------|
| 1    | ✓ DPF box                              | \$0.00       | \$0.00 | \$0.00   |
|      | <b>Notes</b>                           |              |        |          |
|      | Def pump prime code                    |              |        |          |
| 2    | ✓ Service Brakes                       | \$0.00       | \$0.00 | \$0.00   |
|      | <b>Notes</b>                           |              |        |          |
|      | Middle LH brake pot service line loose |              |        |          |
|      |                                        | Part Cost    |        | \$0.00   |
|      |                                        | Labor        |        | \$0.00   |
|      |                                        | Subtotal     |        | \$0.00   |
|      |                                        | Tax 1 (0.0%) |        | \$0.00   |
|      |                                        | Tax 2 (0.0%) |        | \$0.00   |
|      |                                        | Credit       |        | (\$0.00) |
|      |                                        | Total Cost   |        | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 4,922 hr & 872,027 km |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Mar 1, 2026 | Mar 1, 2026 |     | Mar 2, 2026 8:31 AM | Mar 2, 2026 8:31 AM |

| Line | Task                         | Parts      | Labor      | Total        |           |          |
|------|------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Grease truck and trailer   | \$0.00     | \$0.00     | \$0.00       |           |          |
| 2    | ✓ Oil change                 | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                         | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | LF14000 - Cummins oil filter | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                              |            |            | Part Cost    |           | \$0.00   |
|      |                              |            |            | Labor        |           | \$0.00   |
|      |                              |            |            | Subtotal     |           | \$0.00   |
|      |                              |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                              |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                              |            |            | Credit       |           | (\$0.00) |
|      |                              |            |            | Total Cost   |           | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 4,992 hr & 842,108 km |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Mar 6, 2026 | Mar 6, 2026 |     | Mar 6, 2026 7:32 PM | Mar 6, 2026 7:32 PM |

| Line | Task    | Parts  | Labor  | Total  |
|------|---------|--------|--------|--------|
| 1    | ✓ Drate | \$0.00 | \$0.00 | \$0.00 |

### Notes

Changed def pump harness and level sensor

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 4,992 hr & 872,027 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Mar 11, 2026 | Mar 11, 2026 |     | Mar 11, 2026 6:35 PM | Mar 11, 2026 6:35 PM |

| Line | Task                               |            |            | Parts        | Labor     | Total    |
|------|------------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Front diff thru shaft broken     |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                               | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | A23226T1112S - Rockwell thru shaft | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                                    |            |            | Part Cost    |           | \$0.00   |
|      |                                    |            |            | Labor        |           | \$0.00   |
|      |                                    |            |            | Subtotal     |           | \$0.00   |
|      |                                    |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                    |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                    |            |            | Credit       |           | (\$0.00) |
|      |                                    |            |            | Total Cost   |           | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 5,164 hr & 872,027 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Mar 24, 2026 | Mar 24, 2026 |     | Mar 24, 2026 5:18 AM | Mar 24, 2026 5:18 AM |

| Line | Task               |            |            | Parts        | Labor     | Total    |
|------|--------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Radiator leaking |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part               | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | t800 radiator      | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                    |            |            | Part Cost    |           | \$0.00   |
|      |                    |            |            | Labor        |           | \$0.00   |
|      |                    |            |            | Subtotal     |           | \$0.00   |
|      |                    |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                    |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                    |            |            | Credit       |           | (\$0.00) |
|      |                    |            |            | Total Cost   |           | \$0.00   |

Kropp Contracting  
Shop

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

Work Order 2655

Trent Court

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 5,164 hr & 872,027 km |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Mar 24, 2026 |     | Mar 24, 2026 5:19 AM | Mar 24, 2026 5:19 AM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 5,604 hr & 872,027 km |

| Type | Created     | Scheduled   | Due | Started             | Closed               |
|------|-------------|-------------|-----|---------------------|----------------------|
|      | Jun 2, 2026 | Jun 2, 2026 |     | Jun 2, 2026 5:08 PM | Jun 12, 2026 8:42 PM |

| Line | Task                                            | Parts      | Labor      | Total  |           |        |
|------|-------------------------------------------------|------------|------------|--------|-----------|--------|
| 1    | ✓ CVIP inspection (wheels off)                  | \$0.00     | \$0.00     | \$0.00 |           |        |
| 2    | ✓ Preform Scheduled Maintenance                 | \$0.00     | \$0.00     | \$0.00 |           |        |
| 3    | ✓ T rail bolt loose                             | \$0.00     | \$0.00     | \$0.00 |           |        |
| 4    | ✓ front diff input yoke                         | \$0.00     | \$0.00     | \$0.00 |           |        |
| 5    | ✓ back Lh Clevis nut                            | \$0.00     | \$0.00     | \$0.00 |           |        |
| 6    | ✓ air line front Lh drive                       | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                            | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | hab 6 28 fs - Rubber air brake supply           | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
|      | HAB 8 28 FS - Rubber air brake service 28" long | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 7    | ✓ middle Lh airline nfg                         | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                            | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | HAB 8 28 FS - Rubber air brake service 28" long | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 8    | ✓ replace air filters                           | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                            | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | AF4195 - air filters T800                       | Kropp Shop |            | 2.0    | \$0.00    | \$0.00 |
| 9    | ✓ change diff filters                           | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                            | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | LF3311 - Rockwell diff filter                   | Kropp Shop |            | 2.0    | \$0.00    | \$0.00 |
| 10   | ✓ Change belts                                  | \$0.00     | \$0.00     | \$0.00 |           |        |

# 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

|    | Part                                              | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|----|---------------------------------------------------|------------|------------|--------|-----------|--------|
|    | fan belt                                          | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
|    | ac belt                                           | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 11 | ✓ transmission shifter boot                       |            |            | \$0.00 | \$0.00    | \$0.00 |
|    | Part                                              | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | 562.7592 - Shifter boot                           | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 12 | ✓ Hanger bearing yoke loose                       |            |            | \$0.00 | \$0.00    | \$0.00 |
| 13 | ✓ Lh drive fender                                 |            |            | \$0.00 | \$0.00    | \$0.00 |
|    | Part                                              | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | Polly fender                                      | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 14 | ✓ Lh front steer clevis pin                       |            |            | \$0.00 | \$0.00    | \$0.00 |
| 15 | ✓ rh steer dust cover                             |            |            | \$0.00 | \$0.00    | \$0.00 |
| 16 | ✓ rear spring pins                                |            |            | \$0.00 | \$0.00    | \$0.00 |
|    | Part                                              | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | B13-1002 - Spring pin bushing (T800,T880)         | Kropp Shop |            | 4.0    | \$0.00    | \$0.00 |
|    | B65-6008 - Rear spring pin (T800,T880)            | Kropp Shop |            | 4.0    | \$0.00    | \$0.00 |
| 17 | ✓ stack broke off at y pipe                       |            |            | \$0.00 | \$0.00    | \$0.00 |
| 18 | ✓ fuel tank gaskets leaking                       |            |            | \$0.00 | \$0.00    | \$0.00 |
|    | Part                                              | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | fuel tank gasket                                  | Kropp Shop |            | 2.0    | \$0.00    | \$0.00 |
| 19 | ✓ Lh steer tire wore funny                        |            |            | \$0.00 | \$0.00    | \$0.00 |
| 20 | ✓ Lh drag link nfg                                |            |            | \$0.00 | \$0.00    | \$0.00 |
|    | Part                                              | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | 346-572 - LH drag link T800                       | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 21 | ✓ tranny cooler coolant line L clip broke on head |            |            | \$0.00 | \$0.00    | \$0.00 |
| 22 | ✓ back Lh drive dust cover Mia                    |            |            | \$0.00 | \$0.00    | \$0.00 |

# 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

| 23                                | ✓ coolant leak egr o rings                     |            |     | \$0.00    | \$0.00 | \$0.00 |
|-----------------------------------|------------------------------------------------|------------|-----|-----------|--------|--------|
| 24                                | ✓ cab filter plugged                           |            |     | \$0.00    | \$0.00 | \$0.00 |
| Part                              | Warehouse                                      | Vendor/Bin | Qty | Unit Cost | Cost   |        |
| R-19501 - T800 cab filter         | Kropp Shop                                     |            | 1.0 | \$0.00    | \$0.00 |        |
| 25                                | ✓ Power steering fluid low                     |            |     | \$0.00    | \$0.00 | \$0.00 |
| <b>Notes</b>                      |                                                |            |     |           |        |        |
| Return lines clamps loose         |                                                |            |     |           |        |        |
| 26                                | ✓ Air to air cooler missing bolt Lh side       |            |     | \$0.00    | \$0.00 | \$0.00 |
| 27                                | ✓ Battery cables rubbing on top of battery box |            |     | \$0.00    | \$0.00 | \$0.00 |
| 28                                | ✓ front 1/4 fender mudflats tore off           |            |     | \$0.00    | \$0.00 | \$0.00 |
| 29                                | ✓ Lh fuel tank strap rubber falling out        |            |     | \$0.00    | \$0.00 | \$0.00 |
| 30                                | ✓ Adjust clutch                                |            |     | \$0.00    | \$0.00 | \$0.00 |
| 31                                | ✓ Lh window motor                              |            |     | \$0.00    | \$0.00 | \$0.00 |
| Part                              | Warehouse                                      | Vendor/Bin | Qty | Unit Cost | Cost   |        |
| Wnr011000-L - Trp Lh window motor | Kropp Shop                                     |            | 1.0 | \$0.00    | \$0.00 |        |
| 32                                | ✓ Replace mirrors                              |            |     | \$0.00    | \$0.00 | \$0.00 |
| Part                              | Warehouse                                      | Vendor/Bin | Qty | Unit Cost | Cost   |        |
| T800 west coast mirror            | Kropp Shop                                     |            | 2.0 | \$0.00    | \$0.00 |        |
| Convex mirror t800                | Kropp Shop                                     |            | 1.0 | \$0.00    | \$0.00 |        |
| 33                                | ✓ windshield's nfg                             |            |     | \$0.00    | \$0.00 | \$0.00 |
| Part                              | Warehouse                                      | Vendor/Bin | Qty | Unit Cost | Cost   |        |
| Windshield LH                     | Kropp Shop                                     |            | 1.0 | \$0.00    | \$0.00 |        |
| windshield RH                     | Kropp Shop                                     |            | 1.0 | \$0.00    | \$0.00 |        |
| 34                                | ✓ Rear window no good                          |            |     | \$0.00    | \$0.00 | \$0.00 |
| 35                                | ✓ Tool box broke                               |            |     | \$0.00    | \$0.00 | \$0.00 |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

36 ✓ Hood hits wipers \$0.00 \$0.00 \$0.00

**Notes**

Hood pocket bracket broke

37 ✓ Air dryer purging \$0.00 \$0.00 \$0.00

| Part                            | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|---------------------------------|------------|------------|-----|-----------|--------|
| K022105 - AD-IS purge valve     | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |
| 5008414 - ADIS air dryer filter | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

38 ✓ Mv3 valve not popping \$0.00 \$0.00 \$0.00

| Part                | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|---------------------|------------|------------|-----|-----------|--------|
| 800260 - MV-3 valve | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

39 ✓ 5th wheel riser bolt loose lh \$0.00 \$0.00 \$0.00

40 ✓ riser bushings \$0.00 \$0.00 \$0.00

| Part                  | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|-----------------------|------------|------------|-----|-----------|--------|
| Kp118 - Fw 70 bushing | Kropp Shop |            | 2.0 | \$0.00    | \$0.00 |

41 ✓ jaw rebuild \$0.00 \$0.00 \$0.00

42 ✓ Rear leveling rod fucked \$0.00 \$0.00 \$0.00

43 ✓ Rear wishbone fucked \$0.00 \$0.00 \$0.00

| Part                                  | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|---------------------------------------|------------|------------|-----|-----------|--------|
| 48100511 - Neway wishbone bushing kit | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

44 ✓ crossmember bolts loose behind tranny \$0.00 \$0.00 \$0.00

45 ✓ lh tie rod no good \$0.00 \$0.00 \$0.00

| Part                  | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|-----------------------|------------|------------|-----|-----------|--------|
| R230072 - Tie rod end | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

46 ✓ flex pipe and clamp broken \$0.00 \$0.00 \$0.00

47 ✓ cab torque rod loose \$0.00 \$0.00 \$0.00

48 ✓ Weld Lh fender bracket (cracked) \$0.00 \$0.00 \$0.00

Kropp Contracting  
Shop

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

**Work Order 2730**  
Sam Hawksley, Trent Court  
**CLOSED**

|    |                            |              |        |          |
|----|----------------------------|--------------|--------|----------|
| 49 | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
| 50 | ✓ Window modulator         | \$0.00       | \$0.00 | \$0.00   |
| 51 | ✓ Oil change               | \$0.00       | \$0.00 | \$0.00   |
|    |                            | Part Cost    |        | \$0.00   |
|    |                            | Labor        |        | \$0.00   |
|    |                            | Subtotal     |        | \$0.00   |
|    |                            | Tax 1 (0.0%) |        | \$0.00   |
|    |                            | Tax 2 (0.0%) |        | \$0.00   |
|    |                            | Credit       |        | (\$0.00) |
|    |                            | Total Cost   |        | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 5,814 hr & 880,606 km |

| Type    | Created      | Scheduled    | Due | Started              | Closed               |
|---------|--------------|--------------|-----|----------------------|----------------------|
| Service | Jul 15, 2026 | Jul 15, 2026 |     | Jul 15, 2026 6:12 AM | Jul 15, 2026 6:16 AM |

| Line | Task                                                   | Parts  | Labor  | Total    |
|------|--------------------------------------------------------|--------|--------|----------|
| 1    | ✓ Air bag                                              | \$0.00 | \$0.00 | \$0.00   |
|      | <b>Notes</b>                                           |        |        |          |
|      | Change both airbags center drive axle                  |        |        |          |
| 2    | ✓ Replace shock                                        | \$0.00 | \$0.00 | \$0.00   |
|      | <b>Notes</b>                                           |        |        |          |
|      | Change #2 and #3 axle shocks both sides 4 shocks total |        |        |          |
| 3    | ✓ Wiper mechanism                                      | \$0.00 | \$0.00 | \$0.00   |
|      | <b>Notes</b>                                           |        |        |          |
|      | Change wiper drive spline pivot shaft                  |        |        |          |
| 4    | ✓ Grease truck and trailer                             | \$0.00 | \$0.00 | \$0.00   |
|      | Part Cost                                              |        |        | \$0.00   |
|      | Labor                                                  |        |        | \$0.00   |
|      | Subtotal                                               |        |        | \$0.00   |
|      | Tax 1 (0.0%)                                           |        |        | \$0.00   |
|      | Tax 2 (0.0%)                                           |        |        | \$0.00   |
|      | Credit                                                 |        |        | (\$0.00) |
|      | Total Cost                                             |        |        | \$0.00   |

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 6,048 hr & 889,063 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Aug 12, 2026 | Aug 12, 2026 |     | Aug 12, 2026 5:05 AM | Aug 12, 2026 5:05 AM |

| Line | Task                                   | Parts        | Labor      | Total    |           |        |
|------|----------------------------------------|--------------|------------|----------|-----------|--------|
| 1    | ✓ No trailer brake lights              | \$0.00       | \$0.00     | \$0.00   |           |        |
|      | Part                                   | Warehouse    | Vendor/Bin | Qty      | Unit Cost | Cost   |
|      | 7 wire male plug                       | Kropp Shop   |            | 1.0      | \$0.00    | \$0.00 |
| 2    | ✓ Fan stays on                         | \$0.00       | \$0.00     | \$0.00   |           |        |
|      | <b><u>Notes</u></b>                    |              |            |          |           |        |
|      | Ac not circulating and triggering high |              |            |          |           |        |
| 3    | ✓ Ac compressor nfg                    | \$0.00       | \$0.00     | \$0.00   |           |        |
|      |                                        | Part Cost    |            | \$0.00   |           |        |
|      |                                        | Labor        |            | \$0.00   |           |        |
|      |                                        | Subtotal     |            | \$0.00   |           |        |
|      |                                        | Tax 1 (0.0%) |            | \$0.00   |           |        |
|      |                                        | Tax 2 (0.0%) |            | \$0.00   |           |        |
|      |                                        | Credit       |            | (\$0.00) |           |        |
|      |                                        | Total Cost   |            | \$0.00   |           |        |

Kropp Contracting  
Shop

## 855 - 2020 Kenworth t800

Parent: T89 - 2019 Cross Country Cross Country Mfg.

Work Order 2794

Trent Court

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EXXLR966459 | E91025 | 6,048 hr & 889,063 km |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Aug 12, 2026 |     | Aug 12, 2026 5:06 AM | Aug 12, 2026 5:06 AM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
| 2    | ✓ Oil change               | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |