

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	12,200 hr & 554,440 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 26, 2024	Mar 26, 2024		Apr 22, 2024 6:10 PM	Apr 22, 2024 6:10 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00

Notes

Greased t436

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
grease tubes	Kropp Shop		3.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	12,200 hr & 554,440 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 30, 2024	Apr 30, 2024		May 1, 2024 6:04 AM	May 1, 2024 6:04 AM

Line	Task			Parts	Labor	Total
1	✓ coolant leaks			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3/4" heater hose	Kropp Shop		1.0	\$0.00	\$0.00
	3/4" barb - ORB 45	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ DEF codes			\$0.00	\$0.00	\$0.00

Notes

Outlet NOX sensor short code

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
4326874RX - Outlet NOX sensor	Kropp Shop	EKW	1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	12,215 hr & 556,908 km

Type	Created	Scheduled	Due	Started	Closed
	May 6, 2024	May 6, 2024		May 9, 2024 5:47 AM	May 10, 2024 11:04 AM

Line	Task	Parts	Labor	Total		
1	✓ Wheels off CVIP inspection	\$0.00	\$0.00	\$0.00		
2	✓ ABS codes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	AA right wheel speed					
	DA left wheel speed					
3	✓ Check engine light on	\$0.00	\$0.00	\$0.00		
4	✓ change diff filters	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF3311 - Rockwell diff filter	Kropp Shop		2.0	\$0.00	\$0.00
5	✓ Air filters	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	air filters	Kropp Shop		2.0	\$0.00	\$0.00
6	✓ change windshield	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	LH side cracked					
7	✓ Power steering whine	\$0.00	\$0.00	\$0.00		
8	✓ Adjust 5th wheel	\$0.00	\$0.00	\$0.00		
9	✓ Replace missing/tore mudflaps	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Plastic mudflaps/anti sails on chain hangers					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

	24" plastic mudflap	Kropp Shop	1.0	\$0.00	\$0.00
	anti sail bracket	Kropp Shop	1.0	\$0.00	\$0.00
10	✓ loose yoke on diff		\$0.00	\$0.00	\$0.00

Notes

Middle diff output

11	✓ Rear diff wishbone bolt loose		\$0.00	\$0.00	\$0.00
12	✓ LH steer tire no good		\$0.00	\$0.00	\$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
steer tires	Kropp Shop		1.0	\$0.00	\$0.00

13	✓ Mirrors loose		\$0.00	\$0.00	\$0.00
14	✓ King pins		\$0.00	\$0.00	\$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
King pin kit	Kropp Shop		1.0	\$0.00	\$0.00

15	✓ Top RH cab light out		\$0.00	\$0.00	\$0.00
----	------------------------	--	--------	--------	--------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
KW cab light T800	Kropp Shop		1.0	\$0.00	\$0.00

16	✓ Loose grille		\$0.00	\$0.00	\$0.00
17	✓ Hood pin loose		\$0.00	\$0.00	\$0.00

Notes

RH side spinning

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 1113

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	12,225 hr & 557,216 km

Type	Created	Scheduled	Due	Started	Closed
	May 16, 2024	May 16, 2024		May 17, 2024 11:18 AM	May 17, 2024 11:18 AM

Line	Task	Parts	Labor	Total
1	✓ Engine derated regen required message	\$0.00	\$0.00	\$0.00

Notes

Incomplete regen code

Diff pressure data code

Egr flex tube exhaust leak

Loose v clamps on bellows pipe

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	12,406 hr & 566,321 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 10, 2024	Jul 10, 2024		Jul 10, 2024 4:26 AM	Jul 10, 2024 4:26 AM

Line	Task			Parts	Labor	Total
1	✓ Air conditioning			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	F50-1794-001 - Ac line	Kropp Shop		1.0	\$0.00	\$0.00
	R134a	Kropp Shop		3.8	\$0.00	\$0.00
2	✓ Wash out rad			\$0.00	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	12,443 hr & 567,905 km

Type	Scheduled	Due	Started	Closed
Tire	Jul 15, 2024	Jul 15, 2024	Jul 15, 2024 9:14 AM	Jul 15, 2024 9:14 AM

Line	Task	Parts	Labor	Total
1	✓ Flat tire	\$0.00	\$0.00	\$0.00

Notes

Change # LHS outside

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 1197

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	12,443 hr & 567,905 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 18, 2024	Jul 18, 2024		Jul 18, 2024 10:55 AM	Jul 18, 2024 10:55 AM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	FS20172 - Cummins water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 1213
Cam Nadeau

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	12,491 hr & 570,676 km

Type	Scheduled	Due	Started	Closed
engine	Jul 24, 2024	Jul 24, 2024	Jul 24, 2024 2:19 PM	Jul 24, 2024 2:19 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	12,491 hr & 570,676 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 27, 2024	Aug 27, 2024		Aug 29, 2024 11:01 AM	Aug 29, 2024 11:01 AM

Line	Task	Parts	Labor	Total
1	✓ Running hot (coolant temp)	\$0.00	\$0.00	\$0.00

Notes

Truck running 220 empty 240-250 loaded

Checked fan hub-good

Belt seems to slip easy checked tensioner, replaced and tested

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Tentioner	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	12,621 hr & 577,179 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 4, 2024	Sep 4, 2024		Sep 4, 2024 12:08 PM	Sep 4, 2024 12:08 PM

Line	Task	Parts	Labor	Total
1	✓ Belts and Hoses	\$0.00	\$0.00	\$0.00

Notes

Zip tied back into place

Coolant line from surge tank ties loose

2	✓ Brake Accessories	\$0.00	\$0.00	\$0.00
---	---------------------	--------	--------	--------

Notes

New hose and tie up

Middle LH drive brake hose hitting driveshaft

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
HAB 8 28 FS - Rubber air brake service 28" long	Kropp Shop		1.0	\$0.00	\$0.00

3	✓ Fluid Levels	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

Middle diff low oil level

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
75 W 90 gear oil	Kropp Shop		1.0	\$0.00	\$0.00

4	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
---	----------------------------	--------	--------	--------

5	✓ Lights - All	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

Bottom rh work light out

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Work light	Kropp Shop		1.0	\$0.00	\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

6 ✓ Transmission \$0.00 \$0.00 \$0.00

Notes

Tranny temp sensor broke off

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Tranny temp sensor	Kropp Shop		1.0	\$0.00	\$0.00
Temp sensor pig tail	Kropp Shop		1.0	\$0.00	\$0.00

7 ✓ Wheels & Rims \$0.00 \$0.00 \$0.00

Notes

Front rh drive outside wheel cracked

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
24.5 rim	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	12,761 hr & 585,029 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 20, 2024	Oct 20, 2024		Oct 20, 2024 3:37 PM	Oct 20, 2024 6:00 PM

Line	Task	Parts	Labor	Total		
1	✓ Air Lines	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	loose airline					
2	✓ Belts and Hoses	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	lower rad hose clamp loose					
3	✓ Check all fluid levels	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	power steering level low					
4	✓ Exhaust	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	bellows pipe cracked					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	EBPB11861 - Bellows kit	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ Mirrors	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	rh mirrors broke					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Convex mirror t800	Kropp Shop		1.0	\$0.00	\$0.00
	T800 west coast mirror	Kropp Shop		1.0	\$0.00	\$0.00
6	✓ Windows	\$0.00	\$0.00	\$0.00		

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 1357
Nate Vandenberghe, Sam Hawksley

CLOSED

Notes

fuse loose

lh window not working

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 1363
Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	12,761 hr & 585,029 km

Type	Scheduled	Due	Started	Closed
	Oct 20, 2024		Oct 20, 2024 6:01 PM	Oct 20, 2024 6:01 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	12,826 hr & 588,090 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 2, 2024	Nov 2, 2024		Nov 2, 2024 9:51 PM	Nov 2, 2024 9:51 PM

Line	Task	Parts	Labor	Total
1	✓ Lights - All	\$0.00	\$0.00	\$0.00
	Notes			
	top rh work light out			
2	✓ power steering leak	\$0.00	\$0.00	\$0.00
3	✓ lh rad support bushing loose	\$0.00	\$0.00	\$0.00
4	✓ tie up battery cables around oil pan	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	12,925 hr & 593,551 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 16, 2024	Nov 16, 2024		Nov 16, 2024 1:48 PM	Nov 16, 2024 3:42 PM

Line	Task	Parts	Labor	Total		
1	✓ Flat tire	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Trailer - Trailer Tire	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ LH mirror heat not working	\$0.00	\$0.00	\$0.00		
3	✓ decomposition tube to SCR clamp leaking	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	5417859 - Cummins Can gaskets	Kropp Shop		1.0	\$0.00	\$0.00
	5304849 - Can V clamp	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ #8 airbag bolt loose	\$0.00	\$0.00	\$0.00		
5	✓ #8 RH airbag bolt loose/missing hardware	\$0.00	\$0.00	\$0.00		
6	✓ Exhaust leak - DPF	\$0.00	\$0.00	\$0.00		
	Notes					
	egr cooler clamp leaking					
7	✓ License plate light inop	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	licence plate light	Kropp Shop		1.0	\$0.00	\$0.00
					Part Cost	\$0.00
					Labor	\$0.00
					Tax 1 (0.0%)	\$0.00
					Tax 2 (0.0%)	\$0.00
					Credit	(\$0.00)
					Total Cost	\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 1445

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	12,925 hr & 593,551 km

Type	Scheduled	Due	Started	Closed
	Nov 16, 2024		Nov 16, 2024 5:53 PM	Nov 16, 2024 5:53 PM

Line	Task	Parts	Labor	Total
1	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 1452
Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	12,935 hr & 593,551 km

Type	Scheduled	Due	Started	Closed
	Nov 18, 2024		Nov 18, 2024 8:06 PM	Nov 18, 2024 8:06 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	13,144 hr & 604,568 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 12, 2024	Dec 12, 2024		Dec 12, 2024 1:23 AM	Dec 14, 2024 10:10 AM

Line	Task	Parts	Labor	Total												
1	✓ Derated engine 25%	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	Soot level moderately severe, regen required															
2	✓ Replace exhaust gasket out of turbo	\$0.00	\$0.00	\$0.00												
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>2866636 - 4" exhaust gasket</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	2866636 - 4" exhaust gasket	Kropp Shop		1.0	\$0.00	\$0.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost											
2866636 - 4" exhaust gasket	Kropp Shop		1.0	\$0.00	\$0.00											
3	✓ Replace pipe ontop of bellows will not seal	\$0.00	\$0.00	\$0.00												
4	✓ Replace intake actuator	\$0.00	\$0.00	\$0.00												
5	✓ Replace intake NOX sensor	\$0.00	\$0.00	\$0.00												
6	✓ Check and diagnose coolant level sensor shorted to high code	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	Broken wires/rubbed at corner of head															
7	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00												
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>grease tubes</td><td>Kropp Shop</td><td></td><td>3.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	grease tubes	Kropp Shop		3.0	\$0.00	\$0.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost											
grease tubes	Kropp Shop		3.0	\$0.00	\$0.00											
8	✓ Bellows pipe no good	\$0.00	\$0.00	\$0.00												
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>EBPB11861 - Bellows kit</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	EBPB11861 - Bellows kit	Kropp Shop		1.0	\$0.00	\$0.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost											
EBPB11861 - Bellows kit	Kropp Shop		1.0	\$0.00	\$0.00											
9	✓ DPF and DOC breached	\$0.00	\$0.00	\$0.00												
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>cleaned DPF</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	cleaned DPF	Kropp Shop		1.0	\$0.00	\$0.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost											
cleaned DPF	Kropp Shop		1.0	\$0.00	\$0.00											

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

	Cleaned DOC	Kropp Shop	1.0	\$0.00	\$0.00	
	2880215 - DOC inlet gasket 5"	Kropp Shop	1.0	\$0.00	\$0.00	
	5417859 - Cummins Can gaskets	Kropp Shop	3.0	\$0.00	\$0.00	
	5304849 - Can V clamp	Kropp Shop	1.0	\$0.00	\$0.00	
10	✓ Doser injector leaking def		\$0.00	\$0.00	\$0.00	
11	✓ Def pressure line broke		\$0.00	\$0.00	\$0.00	
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Def pressure line	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Notes

Notes	User	Time
Diff pressure, throttle body code, particulate matter code,	Trent Court	Dec 12, 2024 1:19 AM

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 1546

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	13,210 hr & 607,399 km

Type	Scheduled	Due	Started	Closed
	Dec 19, 2024		Dec 19, 2024 9:47 AM	Dec 19, 2024 9:47 AM

Line	Task	Parts	Labor	Total
1	✓ Oil change	\$0.00	\$0.00	\$0.00
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	13,274 hr & 610,888 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 6, 2025	Jan 6, 2025		Jan 14, 2025 5:03 PM	Jan 17, 2025 11:32 AM

Line	Task	Parts	Labor	Total
1	✓ Coolant leak behind EGR outlet pipe (manifold block)	\$0.00	\$0.00	\$0.00
2	✓ Oil leak coming out of air compressor gasket	\$0.00	\$0.00	\$0.00
3	✓ Head gasket leaking coolant	\$0.00	\$0.00	\$0.00
4	✓ Head bolt pulled threads out of deck	\$0.00	\$0.00	\$0.00
5	✓ Oil change	\$0.00	\$0.00	\$0.00
6	✓ t rail bolts loose	\$0.00	\$0.00	\$0.00
7	✓ tie up pan heater wire	\$0.00	\$0.00	\$0.00
8	✓ release bearing grease whip broke	\$0.00	\$0.00	\$0.00
9	✓ front axle diff breather tube MIA	\$0.00	\$0.00	\$0.00
10	✓ LH hood light weather pack rebuild	\$0.00	\$0.00	\$0.00
11	✓ Wash engine off to find oil leak	\$0.00	\$0.00	\$0.00
12	✓ Engine oil leak	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Notes

Notes	User	Time
-------	------	------

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Coolant leaking externally from head gasket #6 exhaust side corner, upon removal of back head bolt found threads to be pulled, tried to clean threads and measure tried to torque but would not hold, used thread salvage kit with Cummins insert and followed procedure, measured protrusion at 11 thou on all cylinders, noted that cylinder liners may be loose at top of deck but not disassembling further to verify

Trent Court

Jan 14, 2025 5:03 PM



282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	13,393 hr & 615,861 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 1, 2025	Feb 1, 2025		Feb 1, 2025 5:04 PM	Feb 1, 2025 5:04 PM

Line	Task	Parts	Labor	Total												
1	✓ Belts and Hoses	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	top rad hose															
	<table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>FLX7967 - Top rad hose</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	FLX7967 - Top rad hose	Kropp Shop		1.0	\$0.00	\$0.00			
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost											
FLX7967 - Top rad hose	Kropp Shop		1.0	\$0.00	\$0.00											
2	✓ Check all fluid levels	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	power steering supply line fitting o ring nfg															
3	✓ Driveline	\$0.00	\$0.00	\$0.00												
	<u>Notes</u>															
	middle u joint needs grease															
4	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00												
		Part Cost		\$0.00												
		Labor		\$0.00												
		Tax 1 (0.0%)		\$0.00												
		Tax 2 (0.0%)		\$0.00												
		Credit		(\$0.00)												
		Total Cost		\$0.00												

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 1655

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	13,393 hr & 615,861 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 3, 2025	Feb 3, 2025		Feb 3, 2025 3:08 PM	Feb 3, 2025 3:08 PM

Line	Task	Parts	Labor	Total
1	✓ no start, block heater not working	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 1676

Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	13,493 hr & 620,311 km

Type	Scheduled	Due	Started	Closed
	Feb 12, 2025		Feb 12, 2025 9:24 PM	Feb 12, 2025 9:24 PM

Line	Task	Parts	Labor	Total
1	✓ DPF box	\$0.00	\$0.00	\$0.00

Notes

Def derate- incomplete regen

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	13,571 hr & 624,178 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 21, 2025	Feb 21, 2025		Feb 21, 2025 9:31 PM	Feb 21, 2025 9:31 PM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ VGT actuator code	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	13,690 hr & 629,831 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 3, 2025	Mar 3, 2025		Mar 6, 2025 3:14 PM	Mar 6, 2025 4:23 PM

Line	Task	Parts	Labor	Total		
1	✓ Battery	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	battery box bolt MIA					
2	✓ Exhaust	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	"Y" pipe cracked					
3	✓ DOC inlet clamp leaking	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	2880213 - DOC inlet v clamp 5"	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ LH windshield NFG	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Windshield LH	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ Replace DEF pump filter	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 1761

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	13,722 hr & 631,050 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 9, 2025	Mar 9, 2025		Mar 9, 2025 1:29 PM	Mar 9, 2025 1:29 PM

Line	Task	Parts	Labor	Total		
1	✓ RH steer tire low (slow leak)	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	steer tires	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 1787
Nate Vandenberghe, Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	13,722 hr & 632,775 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 17, 2025	Mar 17, 2025		Mar 18, 2025 10:42 AM	Mar 18, 2025 10:42 AM

Line	Task	Parts	Labor	Total		
1	✓ LH hood fender cracked	\$0.00	\$0.00	\$0.00		
2	✓ Tie rod bar bent	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	347-205 - t800 tie rod bar	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ LH bottom step bent back into tank	\$0.00	\$0.00	\$0.00		
4	✓ LH steer brake pot line fitting broke off	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 1805

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	13,783 hr & 633,296 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 21, 2025	Mar 21, 2025		Mar 21, 2025 4:21 PM	Mar 21, 2025 4:21 PM

Line	Task	Parts	Labor	Total
1	✓ LH low beam out	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 1810
Nate Vandenberghe, Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	13,786 hr & 633,297 km

Type	Scheduled	Due	Started	Closed
	Mar 22, 2025		Mar 22, 2025 3:24 PM	Mar 22, 2025 3:24 PM

Line	Task	Parts	Labor	Total		
1	✓ DOC filter breached	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Cleaned DOC	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Pneumatic clean DPF filter	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	13,898 hr & 638,476 km

Type	Created	Scheduled	Due	Started	Closed
	May 10, 2025	May 10, 2025		May 10, 2025 10:23 AM	May 24, 2025 3:28 PM

Line	Task	Parts	Labor	Total
1	✓ Too frequent regeneration code	\$0.00	\$0.00	\$0.00
2	✓ Air filters	\$0.00	\$0.00	\$0.00
	Part Warehouse Vendor/Bin Qty Unit Cost Cost			
	air filters Kropp Shop 2.0 \$0.00 \$0.00			
3	✓ Broken exhaust at bellows clamp	\$0.00	\$0.00	\$0.00
	Part Warehouse Vendor/Bin Qty Unit Cost Cost			
	90-0012 - 4" v clamp Kropp Shop 1.0 \$0.00 \$0.00			
	2866636 - 4" exhaust gasket Kropp Shop 1.0 \$0.00 \$0.00			
4	✓ Doc inlet exhaust pipe cracked and flange wore off	\$0.00	\$0.00	\$0.00
5	✓ Crank case vent pipe leaking	\$0.00	\$0.00	\$0.00
6	✓ power steering pump loose	\$0.00	\$0.00	\$0.00
7	✓ air compressor bracket bolt MIA	\$0.00	\$0.00	\$0.00
8	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
9	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
10	✓ LH west coast mirror nfg	\$0.00	\$0.00	\$0.00
	Part Warehouse Vendor/Bin Qty Unit Cost Cost			
	T800 west coast mirror Kropp Shop 1.0 \$0.00 \$0.00			
11	✓ change diff filters	\$0.00	\$0.00	\$0.00
	Part Warehouse Vendor/Bin Qty Unit Cost Cost			
	LF3311 - Rockwell diff filter Kropp Shop 2.0 \$0.00 \$0.00			

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

12	✓ replace fan belt			\$0.00	\$0.00	\$0.00
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	
fan belt	Kropp Shop		1.0	\$0.00	\$0.00	
ac belt	Kropp Shop		1.0	\$0.00	\$0.00	
13	✓ Rh steer tire separated			\$0.00	\$0.00	\$0.00
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	
steer tires	Kropp Shop		1.0	\$0.00	\$0.00	
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	13,873 hr & 637,228 km

Type	Created	Scheduled	Due	Started	Closed
	May 21, 2025	May 21, 2025		May 21, 2025 8:27 PM	May 21, 2025 8:27 PM

Line	Task	Parts	Labor	Total
1	✓ Lights INOP	\$0.00	\$0.00	\$0.00

Notes

LH Mickey Mouse light inop. RH hood light inop

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Mickey Mouse light harness	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 1898

Cam Nadeau

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	14,000 hr & 640,123 km

Type	Scheduled	Due	Started	Closed
	Jun 6, 2025		Jun 6, 2025 6:35 AM	Jun 6, 2025 6:35 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00

Notes

Completed by Norman

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	14,080 hr & 649,466 km

Type	Created	Scheduled	Due	Started	Closed
	Jun 20, 2025	Jun 20, 2025		Jun 20, 2025 8:11 PM	Jun 20, 2025 8:11 PM

Line	Task	Parts	Labor	Total
1	✓ Fab hub leaking	\$0.00	\$0.00	\$0.00

Notes

Replace fan hub air line due to broken line at the fitting

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	14,088 hr & 649,739 km

Type	Created	Scheduled	Due	Started	Closed
	Jun 23, 2025	Jun 23, 2025		Jun 23, 2025 5:04 PM	Jun 23, 2025 5:04 PM

Line	Task	Parts	Labor	Total		
1	✓ Air leak behind dash	\$0.00	\$0.00	\$0.00		
	Technician	Hours	Rate	Cost		
	Trent Court	0.0	\$0.00	\$0.00		
2	✓ Cabin air filter	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	R-19501 - T800 cab filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	14,099 hr & 650,284 km

Type	Scheduled	Due	Started	Closed
	Jun 25, 2025		Jun 25, 2025 5:16 PM	Jun 25, 2025 5:16 PM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	Bh216 - Water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Fan hub not coming on			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	79A9782 - Horton Fan hub	Kropp Shop	EKW	1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	14,139 hr & 652,494 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 15, 2025	Jul 15, 2025		Jul 16, 2025 2:36 PM	Jul 16, 2025 2:37 PM

Line	Task	Parts	Labor	Total
1	✓ U joint	\$0.00	\$0.00	\$0.00
2	✓ spring pins	\$0.00	\$0.00	\$0.00
3	✓ Weld beaver tail	\$0.00	\$0.00	\$0.00
4	✓ Mudflap left hand front drive	\$0.00	\$0.00	\$0.00
5	✓ coolant leaks	\$0.00	\$0.00	\$0.00
6	✓ Middle left hand drive break pot loose	\$0.00	\$0.00	\$0.00
7	✓ Outlet nox heater code	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 2012

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	14,139 hr & 652,494 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 28, 2025	Jul 28, 2025		Jul 28, 2025 5:40 AM	Jul 28, 2025 5:40 AM

Line	Task	Parts	Labor	Total
1	✓ Drive tires (set of 12)	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	14,139 hr & 652,494 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 11, 2025	Aug 11, 2025		Aug 14, 2025 5:11 AM	Aug 14, 2025 5:11 AM

Line	Task	Parts	Labor	Total		
1	✓ Air compressor crankshaft broken	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Broken down on road, aux drive gear “floating” in gear train... remove gear cover and inspect for damage nothing visible... replaced compressor and found main discharge line plugged					
2	✓ Replace air compressor discharge line	\$0.00	\$0.00	\$0.00		
3	✓ replace purge valve	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	K022105 - AD-IS purge valve	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ replace air dryer filter	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	5008414 - ADIS air dryer filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 2049

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	14,139 hr & 652,494 km

Type	Scheduled	Due	Started	Closed
	Aug 11, 2025		Aug 11, 2025 4:04 PM	Aug 11, 2025 4:04 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ Replace right rear air bag	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 2056

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	14,179 hr & 654,863 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 14, 2025	Aug 14, 2025		Aug 14, 2025 4:37 PM	Aug 14, 2025 4:37 PM

Line	Task	Parts	Labor	Total
1	✓ Rh rear drive outside flat	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	14,402 hr & 669,155 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 18, 2025	Sep 18, 2025		Sep 18, 2025 8:02 AM	Sep 18, 2025 8:02 AM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
	FS20172 - Cummins water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Change surge tank			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	st3008d - T800 surge tank	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ RH low beam wire short			\$0.00	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 2130

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	14,402 hr & 669,155 km

Type	Scheduled	Due	Started	Closed
	Sep 18, 2025		Sep 18, 2025 8:03 AM	Sep 18, 2025 8:03 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 2142

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	14,402 hr & 669,155 km

Type	Scheduled	Due	Started	Closed
	Sep 22, 2025		Sep 22, 2025 1:10 PM	Sep 22, 2025 1:10 PM

Line	Task	Parts	Labor	Total		
1	✓ Steer Tires	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	steer tires	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 2155

Unassigned

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	14,439 hr & 671,304 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 30, 2025	Sep 30, 2025		Sep 30, 2025 5:25 PM	Sep 30, 2025 5:25 PM

Line	Task	Parts	Labor	Total		
1	✓ RH low beam headlight bulb replace	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	0551771 - Speaker low beam bulb	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Air leak under cab	\$0.00	\$0.00	\$0.00		
3	✓ RH bottom step loose	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	14,459 hr & 672,295 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 3, 2025	Oct 3, 2025		Oct 3, 2025 9:26 AM	Oct 3, 2025 1:57 PM

Line	Task	Parts	Labor	Total
1	✓ Lights	\$0.00	\$0.00	\$0.00
	Notes LH upper MM light INOP. Connector unplugged, tape connector to light			
2	✓ Power steering fluid low	\$0.00	\$0.00	\$0.00
3	✓ loose yoke on diff	\$0.00	\$0.00	\$0.00
4	✓ Steady bearing yolk loose	\$0.00	\$0.00	\$0.00
5	✓ Check fluid levels	\$0.00	\$0.00	\$0.00

Notes

Tranny okay, #1 low, #2&3 okay

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 2176

Unassigned

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	14,459 hr & 672,295 km

Type	Scheduled	Due	Started	Closed
	Oct 3, 2025		Oct 3, 2025 4:32 PM	Oct 3, 2025 4:32 PM

Line	Task	Parts	Labor	Total
1	✓ Clutch	\$0.00	\$0.00	\$0.00
	Notes			
	Short linkage worn			
2	✓ Driveline	\$0.00	\$0.00	\$0.00
	Notes			
	Steady bearing and #1 diff loose			
3	✓ Lights - All	\$0.00	\$0.00	\$0.00
	Notes			
	LH upper red MM light INOP			
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	14,493 hr & 674,071 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 17, 2025	Nov 17, 2025		Nov 17, 2025 6:20 PM	Nov 17, 2025 6:20 PM

Line	Task	Parts	Labor	Total
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
2	✓ Replace shift knob	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 2286

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	14,611 hr & 680,056 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 21, 2025	Nov 21, 2025		Nov 21, 2025 6:50 PM	Nov 21, 2025 8:27 PM

Line	Task	Parts	Labor	Total
1	✓ Replaced battery	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	14,692 hr & 684,270 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 1, 2025	Dec 1, 2025		Dec 1, 2025 5:34 PM	Dec 1, 2025 5:34 PM

Line	Task	Parts	Labor	Total
1	✓ Belts and Hoses	\$0.00	\$0.00	\$0.00
	Notes			
	coolant leaks			
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
3	✓ Mirrors	\$0.00	\$0.00	\$0.00
	Notes			
	RH convex broken			
4	✓ Windows	\$0.00	\$0.00	\$0.00
	Notes			
	both windshields nfg			
Part Cost				\$0.00
Labor				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	14,789 hr & 689,121 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 9, 2025	Dec 9, 2025		Dec 9, 2025 9:55 PM	Dec 9, 2025 9:55 PM

Line	Task	Parts	Labor	Total
1	✓ coolant leaks	\$0.00	\$0.00	\$0.00
2	✓ Wire up air dryer heater	\$0.00	\$0.00	\$0.00
3	✓ Service call- no air building	\$0.00	\$0.00	\$0.00

Notes

Removed discharge line to dryer found line frozen due to heater not being wired and plug broke

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	14,832 hr & 690,699 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 14, 2025	Dec 14, 2025		Dec 14, 2025 4:05 PM	Dec 14, 2025 5:57 PM

Line	Task	Parts	Labor	Total		
1	✓ ABS codes	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	ABS light on					
2	✓ Belts and Hoses	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	coolant leak off bottom of tank hose					
3	✓ Check all fluid levels	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	coolant low					
4	✓ Driveline	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	driveshaft NFG					
5	✓ Frame & Assembly	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Middle wishbone NFG					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	48100511 - Neway wishbone bushing kit	Kropp Shop		1.0	\$0.00	\$0.00
6	✓ Lights - All	\$0.00	\$0.00	\$0.00		
	<u>Notes</u>					
	Left middle light on headache rack, skirt light got a green wire					
7	✓ Other	\$0.00	\$0.00	\$0.00		

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Notes

grease release bearing

8	✓ Service Brakes	\$0.00	\$0.00	\$0.00
---	------------------	--------	--------	--------

Notes

right rear brake out of adjustment

9	✓ Tires	\$0.00	\$0.00	\$0.00
---	---------	--------	--------	--------

Notes

#3 right hand inside flat

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
245 Truck - Drive tire	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	14,940 hr & 695,676 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 1, 2026	Jan 1, 2026		Jan 2, 2026 7:36 PM	Jan 2, 2026 7:36 PM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 2512

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	15,258 hr & 710,959 km

Type	Scheduled	Due	Started	Closed
	Feb 1, 2026		Feb 1, 2026 8:25 PM	Feb 1, 2026 8:25 PM

Line	Task	Parts	Labor	Total
1	✓ Lights - All	\$0.00	\$0.00	\$0.00
	Notes			
	hood light lh out			
2	✓ Other	\$0.00	\$0.00	\$0.00
	Notes			
	relay valve pilot line broke off back axle, blue glad hand nfg			

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 2516

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	15,273 hr & 711,453 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 3, 2026	Feb 3, 2026		Feb 3, 2026 4:14 PM	Feb 3, 2026 4:14 PM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Airbag front right drive	\$0.00	\$0.00	\$0.00		
3	✓ Oil change	\$0.00	\$0.00	\$0.00		
Part		Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
LF14000 - Cummins oil filter		Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 2520
Sam Hawksley, Trent Court
CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	15,273 hr & 711,453 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 6, 2026	Feb 6, 2026		Feb 7, 2026 5:34 PM	Feb 7, 2026 5:34 PM

Line	Task	Parts	Labor	Total		
1	✓ Middle diff carrier shaft broken	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Rockwell diff	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	15,375 hr & 715,906 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 25, 2026	Feb 25, 2026		Feb 25, 2026 7:41 PM	Feb 25, 2026 7:41 PM

Line	Task	Parts	Labor	Total
1	✓ LH mirror tore off	\$1,300.00	\$0.00	\$1,300.00

Notes

Broke extension and mirror with sensor

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
T800 west coast mirror	Kropp Shop		1.0	\$1,300.00	\$1,300.00
Part Cost					\$1,300.00
Labor					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$1,300.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 2603

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	15,375 hr & 715,906 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 1, 2026	Mar 1, 2026		Mar 2, 2026 8:34 AM	Mar 2, 2026 8:34 AM

Line	Task	Parts	Labor	Total
1	✓ Retorque middle right drive	\$0.00	\$0.00	\$0.00
2	✓ Tighten axle bolt middle drive right side	\$0.00	\$0.00	\$0.00
3	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	15,622 hr & 724,058 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 13, 2026	Mar 13, 2026		Mar 13, 2026 8:25 PM	Mar 13, 2026 8:25 PM

Line	Task	Parts	Labor	Total
1	✓ ABS codes	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	ABS on truck			
2	✓ Air Lines	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Leak somewhere on truck			
3	✓ Check all fluid levels	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Needs power steering fluid and needs coolant			
4	✓ Lights - All	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Lh signal out on hood			
5	✓ Other	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Dust shield missing on middle lh			
6	✓ Wheels & Rims	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Flat on 3lh			
7	✓ Windows	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 2631
Aiden Kenny, Trent Court
CLOSED

Driver side

8	✓ Mud flap on lh side	\$0.00	\$0.00	\$0.00
9	✓ Blue glad hand leaking	\$0.00	\$0.00	\$0.00
10	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 2650

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	15,675 hr & 724,058 km

Type	Scheduled	Due	Started	Closed
	Mar 23, 2026		Mar 23, 2026 4:04 PM	Mar 23, 2026 4:04 PM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Grease truck and trailer			\$0.00	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 2662

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	15,790 hr & 732,930 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 5, 2026	Apr 5, 2026		Apr 5, 2026 7:13 PM	Apr 5, 2026 7:13 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ LH rear outside rim cracked	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 2668

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	15,813 hr & 734,178 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 7, 2026	Apr 7, 2026		Apr 7, 2026 6:18 PM	Apr 7, 2026 6:18 PM

Line	Task	Parts	Labor	Total
1	✓ Lh wiper nfg	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

Kropp Contracting
Shop

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

Work Order 2678

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	15,854 hr & 736,461 km

Type	Scheduled	Due	Started	Closed
	Apr 13, 2026		Apr 13, 2026 12:33 PM	Apr 13, 2026 12:33 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX0LR963957	0AZ866	15,854 hr & 736,461 km

Type	Created	Scheduled	Due	Started	Closed
	May 27, 2026	May 27, 2026		May 28, 2026 10:55 AM	Jun 11, 2026 5:42 AM

Line	Task	Parts	Labor	Total		
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00		
2	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00		
3	✓ Top thermostat housing pipe leaking coolant	\$0.00	\$0.00	\$0.00		
4	✓ change windshield	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Windshield LH	Kropp Shop		1.0	\$0.00	\$0.00
	windshield RH	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ Power steering box shaft seal leaking	\$0.00	\$0.00	\$0.00		
6	✓ change diff filters	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF3311 - Rockwell diff filter	Kropp Shop		2.0	\$0.00	\$0.00
7	✓ Change air filters	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	air filters	Kropp Shop		2.0	\$0.00	\$0.00
8	✓ change belts	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	ac belt	Kropp Shop		1.0	\$0.00	\$0.00
	fan belt	Kropp Shop		1.0	\$0.00	\$0.00
9	✓ Ac not working	\$0.00	\$0.00	\$0.00		

Notes

Plug in compressor

282 - 2020 Kenworth t800

Parent: T436 - 2015 Peerless

CLOSED

10	✓ Rh stack bushing			\$0.00	\$0.00	\$0.00
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	
EM75-69000-HT - Stack bushing kit	Kropp Shop		1.0	\$0.00	\$0.00	

11	✓ Lh MM light not working right			\$0.00	\$0.00	\$0.00
----	---------------------------------	--	--	--------	--------	--------

12	✓ Engine oil leak from front			\$0.00	\$0.00	\$0.00
----	------------------------------	--	--	--------	--------	--------

Notes

Loose gear cover bolts

13	✓ Service SCR/dpf message			\$0.00	\$0.00	\$0.00
Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	
4326874RX - Outlet NOX sensor	Kropp Shop	EKW	1.0	\$0.00	\$0.00	

14	✓ Lh front drive mudflap and anti sail			\$0.00	\$0.00	\$0.00
----	--	--	--	--------	--------	--------

15	✓ Rh middle scam loose			\$0.00	\$0.00	\$0.00
----	------------------------	--	--	--------	--------	--------

16	✓ Rh drag link nfg			\$0.00	\$0.00	\$0.00
----	--------------------	--	--	--------	--------	--------

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost	
346-574 - RH drag link T800	Kropp Shop		1.0	\$0.00	\$0.00	

17	✓ Mirror brackets loose, vibrate when running truck			\$0.00	\$0.00	\$0.00
----	---	--	--	--------	--------	--------

Part Cost	\$0.00
Labor	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00