

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	1,973 hr & 501,743 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 16, 2024	Mar 16, 2024		Mar 16, 2024 1:14 PM	Mar 16, 2024 1:14 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00

Notes

greased t241

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
grease tubes	Kropp Shop		5.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	4 hr & 520,643 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 26, 2024	Apr 26, 2024		Apr 26, 2024 1:51 PM	May 1, 2024 6:10 AM

Line	Task	Parts	Labor	Total		
1	✓ Wheels off CVIP inspection	\$0.00	\$0.00	\$0.00		
2	✓ loose yoke on diff	\$0.00	\$0.00	\$0.00		
3	✓ spring pins	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	spring pins	Kropp Shop		2.0	\$0.00	\$0.00
	spring pin bushings	Kropp Shop		2.0	\$0.00	\$0.00
4	✓ change diff filters	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF3311 - Rockwell diff filter	Kropp Shop		2.0	\$0.00	\$0.00
5	✓ Convex mirror cracked	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Convex mirror t800	Kropp Shop		1.0	\$0.00	\$0.00
6	✓ Drop in engine	\$0.00	\$0.00	\$0.00		
	Notes					
	HER Cummins warranty April 24,2024 323,512 KM					
7	✓ Rh beacon not working	\$0.00	\$0.00	\$0.00		
8	✓ Rh leveling valve on middle drive leaking	\$0.00	\$0.00	\$0.00		
9	✓ Quarter fenders cracked	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Hood glue epoxy	Kropp Shop		1.0	\$0.00	\$0.00
10	✓ King pins	\$0.00	\$0.00	\$0.00		

Kropp Contracting
Shop

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Work Order 1081

Trent Court

CLOSED

	King pin kit	Kropp Shop	1.0	\$0.00	\$0.00
	King pin kit	Kropp Shop	1.0	\$0.00	\$0.00
11	✓ Oil change		\$0.00	\$0.00	\$0.00

Notes

New oil with drop in reset hours to 0

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Work Order 1152

Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	193 hr & 529,789 km

Type	Created	Scheduled	Due	Started	Closed
	Jun 27, 2024	Jun 27, 2024		Jun 27, 2024 9:27 AM	Jun 27, 2024 9:27 AM

Line	Task	Parts	Labor	Total
1	✓ Radiator leaking	\$0.00	\$0.00	\$0.00
2	✓ Hood bracket broke off RH side	\$0.00	\$0.00	\$0.00
3	✓ LH kingpin bottom grease nipple won't take grease	\$0.00	\$0.00	\$0.00
Part Cost				\$0.00
Labor				\$0.00
Subtotal				\$0.00
Tax 1 (0.0%)				\$0.00
Tax 2 (0.0%)				\$0.00
Credit				(\$0.00)
Total Cost				\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	245 hr & 532,264 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 2, 2024	Jul 2, 2024	Jul 2, 2024	Jul 2, 2024 3:41 AM	Jul 2, 2024 3:51 AM

Line	Task	Parts	Labor	Total
1	✓ Air conditioning not working	\$0.00	\$0.00	\$0.00
	Notes			
	Recharge 3lbs 8ox 134A			
2	✓ Lights not working	\$0.00	\$0.00	\$0.00
	Notes			
	Left fender, left Mickey Mouse. Repair witing			
	Part Cost			\$0.00
	Labor			\$0.00
	Subtotal			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

Kropp Contracting
Shop

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Work Order 1157

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	245 hr & 532,264 km

Type	Scheduled	Due	Started	Closed
	Jul 2, 2024		Jul 2, 2024 1:34 PM	Jul 2, 2024 1:34 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	319 hr & 534,897 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 8, 2024	Jul 8, 2024		Jul 8, 2024 1:02 PM	Jul 8, 2024 1:02 PM

Line	Task			Parts	Labor	Total
1	✓ Grease truck and trailer			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	grease tubes	Kropp Shop		3.0	\$0.00	\$0.00
2	✓ LH drivers step loose			\$0.00	\$0.00	\$0.00
3	✓ Red glad hand line tore			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	red glad hand	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	319 hr & 534,987 km

Type	Created	Scheduled	Due	Started	Closed
Service	Jul 8, 2024	Jul 8, 2024	Jul 7, 2024	Jul 8, 2024 2:15 PM	Jul 8, 2024 2:18 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00

Notes

Dwayne July 7 change Broken grease fittings as well

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Work Order 1177

Cam Nadeau

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	319 hr & 534,987 km

Type	Created	Scheduled	Due	Started	Closed
Service	Jul 10, 2024	Jul 10, 2024		Jul 12, 2024 7:24 AM	Jul 12, 2024 7:24 AM

Line	Task	Parts	Labor	Total
1	✓ Air conditioning	\$0.00	\$0.00	\$0.00

Notes

Charge a/c small condenser leak

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	390 hr & 537,544 km

Type	Created	Scheduled	Due	Started	Closed
Service	Jul 15, 2024	Jul 15, 2024	Jul 14, 2024	Jul 15, 2024 4:33 AM	Jul 15, 2024 4:33 AM

Line	Task	Parts	Labor	Total
1	✓ Flat tire	\$0.00	\$0.00	\$0.00

Notes

#3 RHS outside drive flat, replaced with new drive

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	407 hr & 538,278 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 15, 2024	Jul 15, 2024		Jul 15, 2024 12:35 PM	Jul 15, 2024 12:35 PM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	oil 15w-40	Kropp Shop		1.0	\$0.00	\$0.00
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
	FS20172 - Cummins water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	415 hr & 538,587 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 16, 2024	Jul 16, 2024		Jul 16, 2024 4:55 AM	Jul 16, 2024 4:55 AM

Line	Task			Parts	Labor	Total
1	✓ DEF codes			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	4326874RX - Outlet NOX sensor	Kropp Shop	EKW	1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Trent Court

CLOSED

Part Code	Status	Cost	Lamp	Description	PO	SD	J187	J188	J189	Qty
~ C022504	ECM Test (Qty Ch Time)	000422 34.00		retest-elm SS						
	Engine Hours	000415 22.20		retest-elm SS						
	Keyhole	133								
X 0 1887	Active	9	Amber	After startup 1 Cold NOx Sensor CH			4			3226
				- Village Drive Normal or Shutoff to L6 Source						
X 0 3583	Active	9	Amber	After startup 1 Cold NOx Sensor Hour			10			4021
				- Abnormal Rate of Change						
X 0 1645	Inactive	9	Maintenance	When in Fuel Ind-Low Status, Check			3			97
				- After Above Normal or Shutoff to Hg 97 Source						



280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	450 hr & 540,093 km

Type	Created	Scheduled	Due	Started	Closed
engine	Jul 23, 2024	Jul 23, 2024	Jul 22, 2024	Jul 23, 2024 5:35 AM	Jul 23, 2024 5:35 AM

Line	Task	Parts	Labor	Total
1	✓ Broken spring	\$0.00	\$0.00	\$0.00

Notes

Front right hand, changed complete with spring pin bushings

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	463 hr & 540,526 km

Type	Created	Scheduled	Due	Started	Closed
Tire	Jul 23, 2024	Jul 23, 2024	Jul 23, 2024	Jul 23, 2024 6:27 PM	Jul 23, 2024 6:27 PM

Line	Task	Parts	Labor	Total
1	✓ Steer Tires	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Changed both			
2	✓ Change steer tires	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Changed both			
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	606 hr & 541,733 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 16, 2024	Aug 16, 2024		Aug 16, 2024 5:43 AM	Aug 16, 2024 5:43 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ 2nd u joint nipple mia	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	622 hr & 548,169 km

Type	Created	Scheduled	Due	Started	Closed
Tire	Aug 21, 2024	Aug 21, 2024	Aug 21, 2024	Aug 21, 2024 6:13 AM	Aug 21, 2024 6:13 AM

Line	Task	Parts	Labor	Total
1	✓ Replace tire	\$0.00	\$0.00	\$0.00

Notes

#6LHS CD 59

Replaced with used tire

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	696 hr & 551,858 km

Type	Created	Scheduled	Due	Started	Closed
	Aug 29, 2024	Aug 29, 2024		Aug 29, 2024 5:17 AM	Aug 29, 2024 5:17 AM

Line	Task	Parts	Labor	Total
1	✓ Replace tire	\$0.00	\$0.00	\$0.00

Notes

LH rear drive inside no good

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
tire	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	770 hr & 555,842 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 16, 2024	Sep 16, 2024		Sep 20, 2024 7:43 AM	Oct 12, 2024 10:38 AM

Line	Task	Parts	Labor	Total
1	✓ Belts and Hoses	\$0.00	\$0.00	\$0.00

Notes

Filter leak, 1" frame hose clamps, heater core clamps, lower rad hose clamp

Coolant leaks various hose clamps

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Wf2127 - Cummins water filter	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Driveline	\$0.00	\$0.00	\$0.00
---	-------------	--------	--------	--------

Notes

Remove bolts and red locktite back in and torque

Loose strap bolts

3	✓ Exhaust	\$0.00	\$0.00	\$0.00
---	-----------	--------	--------	--------

Notes

Loosen exhaust clamps and move stack back into place

LH stack hitting step

4	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
---	----------------------------	--------	--------	--------

5	✓ Windows	\$0.00	\$0.00	\$0.00
---	-----------	--------	--------	--------

Notes

LH windshield cracked

6	✓ LH quarter fender tore off	\$0.00	\$0.00	\$0.00
---	------------------------------	--------	--------	--------

Notes

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Remove and replace with used spare

7 ✓ LH steer scam tube bent \$0.00 \$0.00 \$0.00

Notes

Remove and make straight

8 ✓ Both leaf packs center pin broke \$0.00 \$0.00 \$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Leaf spring center pin	Kropp Shop		2.0	\$0.00	\$0.00

9 ✓ LH drive fender broke \$0.00 \$0.00 \$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
plastic fender	Kropp Shop		1.0	\$0.00	\$0.00

10 ✓ LH chain hanger broke \$0.00 \$0.00 \$0.00

Notes

Straighten and weld cracks

11 ✓ LH hood pin bracket bent \$0.00 \$0.00 \$0.00

12 ✓ cab kick plate bent \$0.00 \$0.00 \$0.00

13 ✓ front drive axle frame bent \$0.00 \$0.00 \$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
48100581 - Neway crossmember kit	Kropp Shop		1.0	\$0.00	\$0.00
New way ski assembly	Kropp Shop		1.0	\$0.00	\$0.00
48100510 - Neway center ski bushing kit	Kropp Shop		1.0	\$0.00	\$0.00
48100509 - Neway front ski bushing kit	Kropp Shop		1.0	\$0.00	\$0.00
48100511 - Neway wishbone bushing kit	Kropp Shop		1.0	\$0.00	\$0.00

14 ✓ LH bump stop broke off \$0.00 \$0.00 \$0.00

15 ✓ LH steer brake pot bent and hose tore off \$0.00 \$0.00 \$0.00

16 ✓ Water separator housing broke off \$0.00 \$0.00 \$0.00

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
K37-1010-100101120 - 1029 water separator	Kropp Shop		1.0	\$0.00	\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

17	✓ LH steer shock bent			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	85070 - Steer shock T800	Kropp Shop		1.0	\$0.00	\$0.00
18	✓ Straighten LH cab corner			\$0.00	\$0.00	\$0.00
19	✓ LH mirrors broke			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	T800 west coast mirror	Kropp Shop		1.0	\$0.00	\$0.00
	Convex mirror t800	Kropp Shop		1.0	\$0.00	\$0.00
20	✓ Adjust hood pushed back			\$0.00	\$0.00	\$0.00
21	✓ Front engine mounts no good			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	K066-404 - Front engine mount cummins	Kropp Shop		2.0	\$0.00	\$0.00
	K066-423 - Front engine mount rubber washer cummins	Kropp Shop		2.0	\$0.00	\$0.00
22	✓ wrap umbilical cord			\$0.00	\$0.00	\$0.00
23	✓ Blue glad hand no good			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Glad hand blue	Kropp Shop		1.0	\$0.00	\$0.00
24	✓ Drive tires (set of 12)			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Truck - Drive tire	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Notes

Notes	User	Time
-------	------	------

Kropp Contracting
Shop

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Work Order 1279
Nate Vandenberghe, Trent Court

CLOSED

Dwayne ditch hit September 2024

Trent Court Sep 16, 2024 10:30 AM

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	770 hr & 555,842 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 15, 2024	Oct 15, 2024		Oct 15, 2024 4:52 PM	Oct 15, 2024 4:52 PM

Line	Task	Parts	Labor	Total		
1	✓ Power steering pump no good	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Sp33126 - TRP power steering pump Cummins	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	845 hr & 557,164 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 25, 2024	Oct 25, 2024		Oct 25, 2024 9:12 AM	Oct 25, 2024 9:12 AM

Line	Task	Parts	Labor	Total
1	✓ DEF line heater 3 open or short code	\$0.00	\$0.00	\$0.00

Notes

plugged in new line, code still active, continuity in jumper harness,
traced back main truck harness and found break in wire, repaired
code went inactive,

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Work Order 1375
Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	845 hr & 557,164 km

Type	Scheduled	Due	Started	Closed
	Oct 25, 2024		Oct 25, 2024 9:13 AM	Oct 25, 2024 9:13 AM

Line	Task	Parts	Labor	Total
1	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	918 hr & 562,633 km

Type	Scheduled	Due	Started	Closed
	Nov 1, 2024		Nov 1, 2024 6:29 PM	Nov 1, 2024 6:29 PM

Line	Task	Parts	Labor	Total
1	✓ Air Lines	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	chafed front diff lines			
2	✓ Driveline	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	steady bearing nfg			
3	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	931 hr & 563,315 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 4, 2024	Nov 4, 2024		Nov 4, 2024 6:32 PM	Nov 4, 2024 6:32 PM

Line	Task	Parts	Labor	Total		
1	✓ Rh mirror heat not working	\$0.00	\$0.00	\$0.00		
2	✓ #4 LH brake pot nfg	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3030 brake pot	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	931 hr & 563,315 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 8, 2024	Nov 8, 2024		Nov 8, 2024 6:18 AM	Nov 8, 2024 6:18 AM

Line	Task	Parts	Labor	Total
1	✓ mirror heat shorting out	\$0.00	\$0.00	\$0.00

Notes

resettable breaker keeps tripping, LH west coast shorted replaced and tested

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
T800 west coast mirror	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	1,021 hr & 568,076 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 14, 2024	Nov 14, 2024		Nov 14, 2024 6:01 PM	Nov 14, 2024 6:01 PM

Line	Task	Parts	Labor	Total
1	✓ air bag	\$0.00	\$0.00	\$0.00

Notes

left hand rear drive

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
9501 - drive airbag	Kropp Shop		1.0	\$0.00	\$0.00

2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
---	----------------------------	--------	--------	--------

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	1,107 hr & 572,675 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 20, 2024	Nov 20, 2024		Nov 22, 2024 9:17 PM	Nov 22, 2024 9:17 PM

Line	Task	Parts	Labor	Total		
1	✓ Blower motor inop	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	1001401792BSM - linear power module	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Headlights INOP	\$0.00	\$0.00	\$0.00		
	Technician	Hours	Rate	Cost		
	Everett Twin	0.0	\$0.00	\$0.00		
3	✓ Rh stack broke off at bottom	\$0.00	\$0.00	\$0.00		
		Part Cost		\$0.00		
		Labor		\$0.00		
		Subtotal		\$0.00		
		Tax 1 (0.0%)		\$0.00		
		Tax 2 (0.0%)		\$0.00		
		Credit		(\$0.00)		
		Total Cost		\$0.00		

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	1,148 hr & 574,708 km

Type	Scheduled	Due	Started	Closed
	Nov 26, 2024		Nov 26, 2024 3:39 AM	Nov 26, 2024 3:39 AM

Line	Task			Parts	Labor	Total
1	✓ Replace water valve			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	Water valve	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	1,224 hr & 578,013 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 30, 2024	Nov 30, 2024		Dec 1, 2024 6:55 AM	Dec 1, 2024 6:55 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Work Order 1484

Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	1,224 hr & 578,013 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 1, 2024	Dec 1, 2024		Dec 1, 2024 6:57 AM	Dec 1, 2024 6:57 AM

Line	Task	Parts	Labor	Total
1	✓ Brake Accessories	\$0.00	\$0.00	\$0.00

Notes

brake bot jam nut loose rear LH drive

2	✓ Driveline	\$0.00	\$0.00	\$0.00
---	-------------	--------	--------	--------

Notes

output transmission ujoint straps loose

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
SPL250 Strap - SPL 250 Strap Kit	Kropp Shop		1.0	\$0.00	\$0.00

3	✓ Lights - All	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

rh mirror lights out

4	✓ Windows	\$0.00	\$0.00	\$0.00
---	-----------	--------	--------	--------

Notes

lh windshield pitted

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Windshield LH	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	1,380 hr & 586,269 km

Type	Scheduled	Due	Started	Closed
	Dec 15, 2024		Dec 15, 2024 8:29 PM	Dec 15, 2024 8:29 PM

Line	Task	Parts	Labor	Total
1	✓ Check all fluid levels <u>Notes</u> rh steer hub low	\$0.00	\$0.00	\$0.00
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
3	✓ Lights - All <u>Notes</u> RH hood light out	\$0.00	\$0.00	\$0.00
4	✓ Rear End <u>Notes</u> middle diff breather tube	\$0.00	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	1,380 hr & 586,269 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 17, 2024	Dec 17, 2024		Dec 21, 2024 4:29 PM	Dec 21, 2024 4:29 PM

Line	Task	Parts	Labor	Total
1	✓ DEF codes	\$0.00	\$0.00	\$0.00

Notes

Def pump failed leak test by leak out of head of pump replaced def pump and ran leak test found no leaks

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
5506956RX - Pump, doser	Kropp Shop	EKW	1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

Kropp Contracting
Shop

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Work Order 1571
Trent Court, Everett Twin
CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	1,674 hr & 601,475 km

Type	Scheduled	Due	Started	Closed
	Jan 14, 2025		Jan 14, 2025 7:02 PM	Jan 14, 2025 7:02 PM

Line	Task			Parts	Labor	Total
1	✓ Radiator leaking			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	t800 radiator	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	1,700 hr & 602,947 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 16, 2025	Jan 16, 2025		Jan 16, 2025 6:48 PM	Jan 16, 2025 6:48 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	1,722 hr & 603,495 km

Type	Scheduled	Due	Started	Closed
	Jan 19, 2025		Jan 19, 2025 6:39 PM	Jan 19, 2025 6:39 PM

Line	Task	Parts	Labor	Total
1	✓ Lights - All	\$0.00	\$0.00	\$0.00
	Notes			
	rh mirror lights out, center headache rack light out, rh hood light			
2	✓ Service Brakes	\$0.00	\$0.00	\$0.00
	Notes			
	middle LH brake pot			
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	1,864 hr & 610,104 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 31, 2025	Jan 31, 2025		Jan 31, 2025 4:30 PM	Jan 31, 2025 4:31 PM

Line	Task	Parts	Labor	Total		
1	✓ Air Lines	\$0.00	\$0.00	\$0.00		
	<u>Notes</u> line cracked by fitting, cut and repaierd blue glad hand leak					
2	✓ Brake Accessories	\$0.00	\$0.00	\$0.00		
	<u>Notes</u> rh rear s cam ubolt broke					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	2-1/2 u bolt	Kropp Shop		1.0	\$0.00	\$0.00
3	✓ Driveline	\$0.00	\$0.00	\$0.00		
	<u>Notes</u> u joint NFG tranny output					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	SPL250-3x - SPL 250 U joint	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ Exhaust	\$0.00	\$0.00	\$0.00		
	<u>Notes</u> stack bushings no good					
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	EM75-69000-HT - Stack bushing kit	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	grease tubes	Kropp Shop		1.0	\$0.00	\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

6	✓ Lights - All	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

wiring broken repaired-
rh low beam out rh hood marker out

7	✓ Mirrors	\$0.00	\$0.00	\$0.00
---	-----------	--------	--------	--------

Notes

RH mirror bracket Missing

8	✓ Steering System	\$0.00	\$0.00	\$0.00
---	-------------------	--------	--------	--------

Notes

LH drag link

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
346-572 - LH drag link T800	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	1,927 hr & 612,818 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 7, 2025	Feb 7, 2025		Feb 7, 2025 5:36 PM	Feb 7, 2025 5:36 PM

Line	Task	Parts	Labor	Total
1	✓ Def line broke	\$0.00	\$0.00	\$0.00

Notes

Def pressure line broke code for def pressure

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Def pressure line	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

Kropp Contracting
Shop

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Work Order 1695

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	2,103 hr & 621,133 km

Type	Scheduled	Due	Started	Closed
	Feb 22, 2025		Feb 22, 2025 4:23 PM	Feb 22, 2025 4:23 PM

Line	Task	Parts	Labor	Total
1	✓ Oil change	\$0.00	\$0.00	\$0.00
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	2,171 hr & 624,596 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 3, 2025	Mar 3, 2025		Mar 5, 2025 8:16 PM	Mar 5, 2025 8:16 PM

Line	Task	Parts	Labor	Total
1	✓ Lights - All	\$0.00	\$0.00	\$0.00
	Notes			
	center headache rack marker out			
2	✓ Windows	\$0.00	\$0.00	\$0.00
	Notes			
	LH windshield cracked			
3	✓ LH rear lights not working chasis node power input	\$0.00	\$0.00	\$0.00
4	✓ LH rad support bar hitting steering shaft	\$0.00	\$0.00	\$0.00
5	✓ RH cab shock NFG	\$0.00	\$0.00	\$0.00
6	✓ RH steer shock NFG	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Subtotal			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

Kropp Contracting
Shop

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Work Order 1743

Nate Vandenberghe

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	2,222 hr & 626,939 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 6, 2025	Mar 6, 2025		Mar 6, 2025 4:26 PM	Mar 6, 2025 4:26 PM

Line	Task	Parts	Labor	Total
1	✓ shift knob leaking on the splitter circuit	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Work Order 1754

Unassigned

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	2,236 hr & 627,430 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 7, 2025	Mar 7, 2025		Mar 7, 2025 1:00 PM	Mar 7, 2025 1:00 PM

Line	Task	Parts	Labor	Total
1	✓ broken RH mickey mouse light	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	2,265 hr & 628,681 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 11, 2025	Mar 11, 2025		Mar 11, 2025 8:15 PM	Mar 11, 2025 8:15 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ Convex rh mirror	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	2,350 hr & 632,438 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 18, 2025	Mar 18, 2025		Mar 19, 2025 2:41 PM	Mar 19, 2025 2:41 PM

Line	Task	Parts	Labor	Total
1	✓ Auxiliary section grinding in low	\$0.00	\$0.00	\$0.00

Notes

Remove aux, found aux drive gear teeth MIA and countershaft teeth
MIA replaced with rebuilt auxiliary section

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Rebuilt auxiliary section	Kropp Shop		1.0	\$0.00	\$0.00
14335 - Auxiliary housing gasket RTLO	Kropp Shop		1.0	\$0.00	\$0.00
4307247 - Bearing cap cover gasket RTLO	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	2,374 hr & 633,699 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 20, 2025	Mar 20, 2025		Mar 20, 2025 10:49 AM	Mar 20, 2025 10:49 AM

Line	Task	Parts	Labor	Total		
1	✓ LH rear air bag blown	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	9501 - drive airbag	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ LH rear bottom bag mount cracked	\$0.00	\$0.00	\$0.00		
		Part Cost				\$0.00
		Labor				\$0.00
		Subtotal				\$0.00
		Tax 1 (0.0%)				\$0.00
		Tax 2 (0.0%)				\$0.00
		Credit				(\$0.00)
		Total Cost				\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	2,374 hr & 633,699 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 21, 2025	Mar 21, 2025		Mar 21, 2025 2:11 PM	Mar 21, 2025 2:11 PM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ lh rear drive air bag	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	9501 - drive airbag	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	2,421 hr & 635,842 km

Type	Created	Scheduled	Due	Started	Closed
Cvip inspection	May 13, 2025	May 13, 2025		May 13, 2025 5:02 PM	May 13, 2025 5:07 PM

Line	Task	Parts	Labor	Total
1	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
2	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
3	✓ replace air filters	\$0.00	\$0.00	\$0.00
4	✓ Replace Belt	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Both belts			
5	✓ change windshield	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Both windsheilds			
6	✓ Change grille	\$0.00	\$0.00	\$0.00
7	✓ Hood hinge bushings	\$0.00	\$0.00	\$0.00
8	✓ Adjust stack	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	RH			
9	✓ brake pot	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	#2LHS			
10	✓ #2 input yoke loose	\$0.00	\$0.00	\$0.00
11	✓ Top up fluids	\$0.00	\$0.00	\$0.00

Kropp Contracting
Shop

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Work Order 1859

Cam Nadeau

CLOSED

Notes

All diffs low

12	✓ Replace light bar	\$0.00	\$0.00	\$0.00
----	---------------------	--------	--------	--------

Notes

Rear brake and tail

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

Kropp Contracting
Shop

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Work Order 1889

Cam Nadeau

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	2,478 hr & 639,230 km

Type	Scheduled	Due	Started	Closed
Service	Jun 2, 2025		Jun 2, 2025 5:14 PM	Jun 2, 2025 5:14 PM

Line	Task	Parts	Labor	Total
1	✓ Change clutch brake	\$0.00	\$0.00	\$0.00

Notes

Changed two piece clutch brake

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	2,500 hr & 640,000 km

Type	Created	Scheduled	Due	Started	Closed
	Jun 8, 2025	Jun 8, 2025		Jun 8, 2025 9:27 PM	Jun 8, 2025 9:27 PM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	oil 15w-40	Kropp Shop		42.0	\$0.00	\$0.00
3	✓ 1h steer tire nfg	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	steer tires	Kropp Shop		1.0	\$0.00	\$0.00
4	✓ Lh MM light pigtail brpke	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	3 wire pigtail	Kropp Shop		1.0	\$0.00	\$0.00
	6050A oval light	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	2,525 hr & 641,512 km

Type	Created	Scheduled	Due	Started	Closed
	Jun 9, 2025	Jun 9, 2025		Jun 9, 2025 6:34 PM	Jun 9, 2025 6:34 PM

Line	Task	Parts	Labor	Total
1	✓ Diff leak	\$0.00	\$0.00	\$0.00

Notes

Middle diff input leaking, check breather, breather okay. Remove driveshaft, yolk and old seal. Install new seal and top up diff oil

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
R945007 - Input diff seal rockwell	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	2,665 hr & 648,841 km

Type	Created	Scheduled	Due	Started	Closed
	Jul 3, 2025	Jul 3, 2025		Jul 3, 2025 5:12 AM	Jul 3, 2025 5:12 AM

Line	Task	Parts	Labor	Total
1	✓ Steer Tires	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	2,876 hr & 660,622 km

Type	Scheduled	Due	Started	Closed
	Aug 7, 2025		Aug 7, 2025 7:09 AM	Aug 7, 2025 7:09 AM

Line	Task	Parts	Labor	Total
1	✓ air bag	\$0.00	\$0.00	\$0.00

Notes

LH front drive airbag blew, replace airbag

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
9501 - drive airbag	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	2,900 hr & 660,622 km

Type	Scheduled	Due	Started	Closed
	Aug 14, 2025		Aug 14, 2025 5:11 AM	Aug 14, 2025 5:11 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
2	✓ Oil change	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	3,067 hr & 671,635 km

Type	Created	Scheduled	Due	Started	Closed
	Sep 2, 2025	Sep 2, 2025		Sep 2, 2025 1:45 PM	Sep 2, 2025 1:45 PM

Line	Task	Parts	Labor	Total		
1	✓ Drive tires (set of 12)	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	245 Truck - Drive tire	Kropp Shop		12.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Work Order 2107

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	3,099 hr & 672,414 km

Type	Scheduled	Due	Started	Closed
	Sep 8, 2025		Sep 8, 2025 6:52 AM	Sep 8, 2025 6:52 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Work Order 2126

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	3,185 hr & 678,588 km

Type	Scheduled	Due	Started	Closed
	Sep 17, 2025		Sep 17, 2025 3:07 PM	Sep 17, 2025 3:07 PM

Line	Task	Parts	Labor	Total
1	✓ Front diff low	\$0.00	\$0.00	\$0.00
2	✓ Check hub levels	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Work Order 2144

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	3,197 hr & 679,250 km

Type	Scheduled	Due	Started	Closed
	Sep 22, 2025		Sep 22, 2025 5:52 PM	Sep 22, 2025 5:52 PM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	3,333 hr & 686,641 km

Type	Created	Scheduled	Due	Started	Closed
	Oct 11, 2025	Oct 11, 2025		Oct 11, 2025 3:36 PM	Oct 11, 2025 3:36 PM

Line	Task			Parts	Labor	Total
1	✓ Oil change			\$0.00	\$0.00	\$0.00
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
	FF5825NN - Cummins fuel filter	Kropp Shop		1.0	\$0.00	\$0.00
	FS20172 - Cummins water separator filter	Kropp Shop		1.0	\$0.00	\$0.00
	oil 15w-40	Kropp Shop		1.0	\$0.00	\$0.00
2	✓ Grease truck and trailer			\$0.00	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	3,421.2 hr & 691,260 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 5, 2025	Nov 5, 2025		Nov 6, 2025 10:18 AM	Nov 7, 2025 1:37 PM

Line	Task	Parts	Labor	Total
1	✓ Exhust leak	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Inspected and found no leak			
2	✓ Flat drive tire	\$0.00	\$0.00	\$0.00
3	✓ Top rad hose	\$0.00	\$0.00	\$0.00
4	✓ Fix bumper latch	\$0.00	\$0.00	\$0.00
5	✓ Inspect streer tire issue	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Bent drag link, checked alignment fixed alignment			
6	✓ Coolant leak at back of motor	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Tightened hose clamp			
7	✓ Out put seal on transmission	\$0.00	\$0.00	\$0.00
8	✓ Inspect number one u joint	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Yoak was deformed, replaced yoak			
9	✓ Inspect last u joint	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	Replaced			
10	✓ Dust cover	\$0.00	\$0.00	\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

11	✓ Passenger side drag link	\$0.00	\$0.00	\$0.00
----	----------------------------	--------	--------	--------

Notes

Replaced

12	✓ Lower rad hose	\$0.00	\$0.00	\$0.00
----	------------------	--------	--------	--------

13	✓ Leaking tranny cooler hoses	\$0.00	\$0.00	\$0.00
----	-------------------------------	--------	--------	--------

Notes

Tightened clamps

14	✓ Windshield	\$0.00	\$0.00	\$0.00
----	--------------	--------	--------	--------

15	✓ Broken drivers mirror	\$0.00	\$0.00	\$0.00
----	-------------------------	--------	--------	--------

16	✓ Broken latch on bumper	\$0.00	\$0.00	\$0.00
----	--------------------------	--------	--------	--------

17	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
----	---------------------------------	--------	--------	--------

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	3,473 hr & 694,115 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 18, 2025	Nov 18, 2025		Nov 18, 2025 12:55 PM	Nov 18, 2025 12:57 PM

Line	Task	Parts	Labor	Total
1	✓ Alternator	\$0.00	\$0.00	\$0.00

Notes

Not charging RandR

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
D27-1019-0200P - Alternator Cummins	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Work Order 2293

Sam Hawksley

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	3,541 hr & 697,792 km

Type	Created	Scheduled	Due	Started	Closed
	Nov 24, 2025	Nov 24, 2025		Nov 24, 2025 5:22 PM	Nov 24, 2025 5:22 PM

Line	Task	Parts	Labor	Total
1	✓ Tighten bunk two	\$0.00	\$0.00	\$0.00
2	✓ Tires	\$0.00	\$0.00	\$0.00

Notes

Front LH outside rear rh inside

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	3,599 hr & 700,948 km

Type	Scheduled	Due	Started	Closed
	Nov 30, 2025		Nov 30, 2025 12:10 PM	Nov 30, 2025 12:10 PM

Line	Task	Parts	Labor	Total
1	✓ Air Lines	\$0.00	\$0.00	\$0.00
	Notes			
	tie up rubbing lines			
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
3	✓ Lights - All	\$0.00	\$0.00	\$0.00
	Notes			
	bottom LH work light			
4	✓ Radiator	\$0.00	\$0.00	\$0.00
	Notes			
	top rad hose leaking			
5	✓ Windows	\$0.00	\$0.00	\$0.00
	Notes			
	both windshields nfg			

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	3,745 hr & 706,431 km

Type	Created	Scheduled	Due	Started	Closed
	Dec 12, 2025	Dec 12, 2025		Dec 12, 2025 7:36 AM	Dec 13, 2025 8:21 AM

Line	Task	Parts	Labor	Total
1	✓ Air Lines	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	blue glad hand			
2	✓ replace front right steer tire	\$0.00	\$0.00	\$0.00
3	✓ replace right hand steer shock	\$0.00	\$0.00	\$0.00
4	✓ ABS codes	\$0.00	\$0.00	\$0.00
5	✓ Check all fluid levels	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	coolant low			
6	✓ Frame & Assembly	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	cracked cross member			
7	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
8	✓ Mirrors	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	left hand mirror			
9	✓ Oil change	\$0.00	\$0.00	\$0.00
10	✓ Rear End	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

11	✓ Steering System	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	steering box needs grease			
12	✓ Transmission	\$0.00	\$0.00	\$0.00
	<u>Notes</u>			
	needs grease U joint			
13	✓ upper rad boot chaffing	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Subtotal			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

Kropp Contracting
Shop

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Work Order 2393

Terren Page, Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	3,745 hr & 706,431 km

Type	Scheduled	Due	Started	Closed
	Dec 19, 2025		Dec 19, 2025 12:19 PM	Dec 19, 2025 12:19 PM

Line	Task	Parts	Labor	Total
1	✓ Exhaust clamp from turbo to bellows loose	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

Kropp Contracting
Shop

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Work Order 2406

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	3,884 hr & 710,101 km

Type	Scheduled	Due	Started	Closed
	Dec 29, 2025		Dec 29, 2025 2:34 PM	Dec 29, 2025 2:34 PM

Line	Task	Parts	Labor	Total
1	✓ Rh leaf spring broken	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	3,918 hr & 710,789 km

Type	Created	Scheduled	Due	Started	Closed
	Jan 4, 2026	Jan 4, 2026		Jan 8, 2026 5:57 AM	Jan 8, 2026 5:57 AM

Line	Task	Parts	Labor	Total		
1	✓ Front diff power divider broken	\$0.00	\$0.00	\$0.00		
2	✓ Output transmission yoke broken	\$0.00	\$0.00	\$0.00		
3	✓ Fuel leak at crossover fitting	\$0.00	\$0.00	\$0.00		
4	✓ Mainshaft u joint sheared apart	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	SPL250-3x - SPL 250 U joint	Kropp Shop		1.0	\$0.00	\$0.00
5	✓ Def level sensor no good	\$0.00	\$0.00			\$0.00
6	✓ Grease truck and trailer	\$0.00	\$0.00			\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

Kropp Contracting
Shop

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Work Order 2460

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	4,022 hr & 715,250 km

Type	Scheduled	Due	Started	Closed
	Jan 17, 2026		Jan 17, 2026 6:44 AM	Jan 17, 2026 6:44 AM

Line	Task	Parts	Labor	Total
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	4,196 hr & 722,725 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 1, 2026	Feb 1, 2026		Feb 1, 2026 5:29 PM	Feb 1, 2026 5:29 PM

Line	Task	Parts	Labor	Total
1	✓ Exhaust	\$0.00	\$0.00	\$0.00

Notes

Y pipe loose, flex pipe broke

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
5" flex pipe	Kropp Shop		1.0	\$0.00	\$0.00
5" step clamp	Kropp Shop		3.0	\$0.00	\$0.00

2	✓ Lights - All	\$0.00	\$0.00	\$0.00
---	----------------	--------	--------	--------

Notes

top LH mm marker out

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	4,226 hr & 724,249 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 6, 2026	Feb 6, 2026		Feb 6, 2026 9:07 PM	Feb 6, 2026 9:07 PM

Line	Task	Parts	Labor	Total		
1	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00		
2	✓ Oil change	\$0.00	\$0.00	\$0.00		
	Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
	LF14000 - Cummins oil filter	Kropp Shop		1.0	\$0.00	\$0.00
				Part Cost		\$0.00
				Labor		\$0.00
				Subtotal		\$0.00
				Tax 1 (0.0%)		\$0.00
				Tax 2 (0.0%)		\$0.00
				Credit		(\$0.00)
				Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	4,284 hr & 727,298 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 15, 2026	Feb 15, 2026		Feb 15, 2026 3:03 PM	Feb 15, 2026 3:03 PM

Line	Task	Parts	Labor	Total
1	✓ ABS codes	\$100.00	\$0.00	\$100.00

Notes

abs code

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
K181268 - 6' straight ABS WSS	Kropp Shop		1.0	\$100.00	\$100.00

2	✓ Windows	\$0.00	\$0.00	\$0.00
---	-----------	--------	--------	--------

Notes

LH windshield cracked

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Windshield LH	Kropp Shop		1.0	\$0.00	\$0.00

Part Cost	\$100.00
Labor	\$0.00
Subtotal	\$100.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$100.00

Kropp Contracting
Shop

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

Work Order 2577

Trent Court

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	4,388 hr & 730,997 km

Type	Scheduled	Due	Started	Closed
	Feb 25, 2026		Feb 25, 2026 4:01 AM	Feb 25, 2026 4:01 AM

Line	Task	Parts	Labor	Total
1	✓ Derate- def level, chafed wire by air tank	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	4,433 hr & 732,408 km

Type	Created	Scheduled	Due	Started	Closed
	Feb 27, 2026	Feb 27, 2026		Mar 1, 2026 11:02 AM	Mar 2, 2026 8:33 AM

Line	Task	Parts	Labor	Total
1	✓ Loose yolk input on first and second diff	\$0.00	\$0.00	\$0.00
2	✓ Steer tires	\$0.00	\$0.00	\$0.00
3	✓ Abs	\$0.00	\$0.00	\$0.00
4	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	4,433 hr & 732,408 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 2, 2026	Mar 2, 2026		Mar 2, 2026 7:05 PM	Mar 2, 2026 7:05 PM

Line	Task	Parts	Labor	Total
1	✓ ABS codes	\$0.00	\$0.00	\$0.00
2	✓ Driveline	\$0.00	\$0.00	\$0.00
	Notes			
	Loose yoke input on first diff			
3	✓ Horn	\$0.00	\$0.00	\$0.00
	Notes			
	Air horn dosent work			
4	✓ Tires	\$0.00	\$0.00	\$0.00
	Notes			
	Needs steer tires			
5	✓ Steer Tires	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Subtotal			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	4,434.8 hr & 732,408 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 3, 2026	Mar 3, 2026		Mar 3, 2026 3:39 PM	Mar 4, 2026 8:36 PM

Line	Task	Parts	Labor	Total
1	✓ New right hand windshield	\$0.00	\$0.00	\$0.00
2	✓ Fixed broken wires at coolant level sensor	\$0.00	\$0.00	\$0.00
3	✓ Fixed 3 chaffed wires in after treatment harness	\$0.00	\$0.00	\$0.00
4	✓ Middle diff input yoke fell off	\$0.00	\$0.00	\$0.00

Notes

Brokedown... repaired by trent

Part	Warehouse	Vendor/Bin	Qty	Unit Cost	Cost
Spl 170 input yoke	Kropp Shop		1.0	\$0.00	\$0.00
Spl 170 strap kit	Kropp Shop		1.0	\$0.00	\$0.00
Part Cost					\$0.00
Labor					\$0.00
Subtotal					\$0.00
Tax 1 (0.0%)					\$0.00
Tax 2 (0.0%)					\$0.00
Credit					(\$0.00)
Total Cost					\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	4,583 hr & 737,237 km

Type	Created	Scheduled	Due	Started	Closed
	Mar 17, 2026	Mar 17, 2026		Mar 24, 2026 5:17 AM	Mar 24, 2026 5:17 AM

Line	Task	Parts	Labor	Total
1	✓ ABS codes	\$0.00	\$0.00	\$0.00
2	✓ Brake Accessories	\$0.00	\$0.00	\$0.00
	Notes			
	Steer brake pot left side leaking			
3	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
4	✓ Suspension System	\$0.00	\$0.00	\$0.00
	Notes			
	Left leveling valve leaking			
5	✓ Windows	\$0.00	\$0.00	\$0.00
	Notes			
	Drivers side windshield			
6	✓ Coolant level sensor	\$0.00	\$0.00	\$0.00
	Part Cost			\$0.00
	Labor			\$0.00
	Subtotal			\$0.00
	Tax 1 (0.0%)			\$0.00
	Tax 2 (0.0%)			\$0.00
	Credit			(\$0.00)
	Total Cost			\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	4,640 hr & 737,237 km

Type	Created	Scheduled	Due	Started	Closed
	Apr 10, 2026	Apr 10, 2026		Apr 10, 2026 4:06 PM	Apr 10, 2026 4:06 PM

Line	Task	Parts	Labor	Total
1	✓ Oil change	\$0.00	\$0.00	\$0.00
2	✓ Grease truck and trailer	\$0.00	\$0.00	\$0.00
		Part Cost		\$0.00
		Labor		\$0.00
		Subtotal		\$0.00
		Tax 1 (0.0%)		\$0.00
		Tax 2 (0.0%)		\$0.00
		Credit		(\$0.00)
		Total Cost		\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

Serial	Tag	Closed Meters
1NKDX4EX5LR963954	U00888	4,640 hr & 737,237 km

Type	Created	Scheduled	Due	Started	Closed
	May 19, 2026	May 19, 2026		May 20, 2026 4:57 PM	Jun 11, 2026 5:43 AM

Line	Task	Parts	Labor	Total
1	✓ CVIP inspection (wheels off)	\$0.00	\$0.00	\$0.00
2	✓ Preform Scheduled Maintenance	\$0.00	\$0.00	\$0.00
3	✓ Tire Chains	\$0.00	\$0.00	\$0.00
Notes				
Tire chains missing and rack destroyed				
4	✓ Drive tires (set of 12)	\$0.00	\$0.00	\$0.00
5	✓ air dryer check valves sticking	\$0.00	\$0.00	\$0.00
6	✓ tape umbilical cord	\$0.00	\$0.00	\$0.00
7	✓ wires chafing on oil pan	\$0.00	\$0.00	\$0.00
8	✓ middle drive chafing air lines on diff	\$0.00	\$0.00	\$0.00
9	✓ front diff input seal	\$0.00	\$0.00	\$0.00
10	✓ no LH signal headache rack	\$0.00	\$0.00	\$0.00
11	✓ broken cross member behind tranny	\$0.00	\$0.00	\$0.00
12	✓ abs tie up	\$0.00	\$0.00	\$0.00
13	✓ change belts	\$0.00	\$0.00	\$0.00
14	✓ change diff filters	\$0.00	\$0.00	\$0.00
15	✓ Air filters	\$0.00	\$0.00	\$0.00
16	✓ loose t rail bolts	\$0.00	\$0.00	\$0.00

280 - 2020 Kenworth t800

Parent: T241 - 2020 Cross Country Cross Country Mfg.

CLOSED

17	✓ loose rad	\$0.00	\$0.00	\$0.00
18	✓ lh spring pins	\$0.00	\$0.00	\$0.00
19	✓ power steering leak	\$0.00	\$0.00	\$0.00
20	✓ fan air line leak	\$0.00	\$0.00	\$0.00
21	✓ coolant filter remove and check for oil	\$0.00	\$0.00	\$0.00

Notes

diagnose if oil cooler is required to be changed

22	✓ tie up headlight harness rh	\$0.00	\$0.00	\$0.00
23	✓ tie up tail light harness	\$0.00	\$0.00	\$0.00
24	✓ lh mirror light	\$0.00	\$0.00	\$0.00
25	✓ cab light flickering	\$0.00	\$0.00	\$0.00
26	✓ tranny air leak	\$0.00	\$0.00	\$0.00
27	✓ no ac clutch spinning	\$0.00	\$0.00	\$0.00
28	✓ steering u joint	\$0.00	\$0.00	\$0.00
29	✓ #4 rh s-cam clamp loose	\$0.00	\$0.00	\$0.00

Part Cost	\$0.00
Labor	\$0.00
Subtotal	\$0.00
Tax 1 (0.0%)	\$0.00
Tax 2 (0.0%)	\$0.00
Credit	(\$0.00)
Total Cost	\$0.00