

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 14,095 hr & 632,404 km |

| Type   | Created     | Scheduled   | Due          | Started             | Closed              |
|--------|-------------|-------------|--------------|---------------------|---------------------|
| engine | Mar 9, 2024 | Mar 9, 2024 | Mar 10, 2024 | Mar 9, 2024 1:24 PM | Mar 9, 2024 1:24 PM |

| Line | Task                | Parts      | Labor  | Total      |
|------|---------------------|------------|--------|------------|
| 1    | ✓ replace injectors | \$9,018.00 | \$0.00 | \$9,018.00 |

### Notes

Diagnosed 6 injectors high rate of return at 900 ML

| Part                 | Warehouse  | Vendor/Bin    | Qty | Unit Cost  | Cost       |
|----------------------|------------|---------------|-----|------------|------------|
| 5579421PX - Injector | Kropp Shop | Sunset Diesel | 6.0 | \$1,503.00 | \$9,018.00 |
| Part Cost            |            |               |     |            | \$9,018.00 |
| Labor                |            |               |     |            | \$0.00     |
| Subtotal             |            |               |     |            | \$9,018.00 |
| Tax 1 (0.0%)         |            |               |     |            | \$0.00     |
| Tax 2 (0.0%)         |            |               |     |            | \$0.00     |
| Credit               |            |               |     |            | (\$0.00)   |
| Total Cost           |            |               |     |            | \$9,018.00 |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 14,122 hr & 633,615 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Mar 11, 2024 | Mar 11, 2024 |     | Mar 11, 2024 5:30 PM | Mar 11, 2024 5:30 PM |

| Line | Task                   |            |            | Parts        | Labor     | Total    |
|------|------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Drive tires          |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                   | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 245 Truck - Drive tire | Kropp Shop |            | 12.0         | \$0.00    | \$0.00   |
|      |                        |            |            | Part Cost    |           | \$0.00   |
|      |                        |            |            | Labor        |           | \$0.00   |
|      |                        |            |            | Subtotal     |           | \$0.00   |
|      |                        |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                        |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                        |            |            | Credit       |           | (\$0.00) |
|      |                        |            |            | Total Cost   |           | \$0.00   |

# 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 14,181 hr & 636,340 km |

| Type | Created      | Scheduled    | Due | Started               | Closed                |
|------|--------------|--------------|-----|-----------------------|-----------------------|
|      | Mar 19, 2024 | Mar 19, 2024 |     | Mar 19, 2024 11:41 AM | Mar 19, 2024 11:41 AM |

| Line | Task | Parts | Labor | Total |
|------|------|-------|-------|-------|
|------|------|-------|-------|-------|

|   |                            |        |        |        |
|---|----------------------------|--------|--------|--------|
| 1 | ✓ Grease truck and trailer | \$0.00 | \$0.00 | \$0.00 |
|---|----------------------------|--------|--------|--------|

**Notes**

Greased truck and t366

| Part         | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|--------------|------------|------------|-----|-----------|--------|
| grease tubes | Kropp Shop |            | 3.0 | \$0.00    | \$0.00 |

|   |                 |        |        |        |
|---|-----------------|--------|--------|--------|
| 2 | ✓ mirror broken | \$0.00 | \$0.00 | \$0.00 |
|---|-----------------|--------|--------|--------|

**Notes**

RH west coast mirror broken

| Part              | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|-------------------|------------|------------|-----|-----------|--------|
| west coast mirror | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

|   |                                 |        |        |        |
|---|---------------------------------|--------|--------|--------|
| 3 | ✓ check pressure in steer tires | \$0.00 | \$0.00 | \$0.00 |
|---|---------------------------------|--------|--------|--------|

**Notes**

Set pressure to 95 psi

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

# 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 14,306 hr & 642,904 km |

| Type            | Created      | Scheduled    | Due | Started              | Closed               |
|-----------------|--------------|--------------|-----|----------------------|----------------------|
| Cvip inspection | Apr 10, 2024 | Apr 10, 2024 |     | Apr 11, 2024 5:01 PM | Apr 17, 2024 7:31 PM |

| Line         | Task                                                                                                                                                                                                                                                                                                                     | Parts      | Labor     | Total      |        |           |      |              |            |  |     |        |        |          |            |  |     |        |        |  |  |  |
|--------------|--------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|-----------|------------|--------|-----------|------|--------------|------------|--|-----|--------|--------|----------|------------|--|-----|--------|--------|--|--|--|
| 1            | ✓ Truck Cvip inspection                                                                                                                                                                                                                                                                                                  | \$0.00     | \$0.00    | \$0.00     |        |           |      |              |            |  |     |        |        |          |            |  |     |        |        |  |  |  |
|              | <b><u>Notes</u></b>                                                                                                                                                                                                                                                                                                      |            |           |            |        |           |      |              |            |  |     |        |        |          |            |  |     |        |        |  |  |  |
|              | Wheels off inspection                                                                                                                                                                                                                                                                                                    |            |           |            |        |           |      |              |            |  |     |        |        |          |            |  |     |        |        |  |  |  |
| 2            | ✓ Rear spring pins                                                                                                                                                                                                                                                                                                       | \$0.00     | \$0.00    | \$0.00     |        |           |      |              |            |  |     |        |        |          |            |  |     |        |        |  |  |  |
|              | <table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>spring pins</td><td>Kropp Shop</td><td></td><td>4.0</td><td>\$0.00</td><td>\$0.00</td></tr><tr><td>bushings</td><td>Kropp Shop</td><td></td><td>2.0</td><td>\$0.00</td><td>\$0.00</td></tr></table> | Part       | Warehouse | Vendor/Bin | Qty    | Unit Cost | Cost | spring pins  | Kropp Shop |  | 4.0 | \$0.00 | \$0.00 | bushings | Kropp Shop |  | 2.0 | \$0.00 | \$0.00 |  |  |  |
| Part         | Warehouse                                                                                                                                                                                                                                                                                                                | Vendor/Bin | Qty       | Unit Cost  | Cost   |           |      |              |            |  |     |        |        |          |            |  |     |        |        |  |  |  |
| spring pins  | Kropp Shop                                                                                                                                                                                                                                                                                                               |            | 4.0       | \$0.00     | \$0.00 |           |      |              |            |  |     |        |        |          |            |  |     |        |        |  |  |  |
| bushings     | Kropp Shop                                                                                                                                                                                                                                                                                                               |            | 2.0       | \$0.00     | \$0.00 |           |      |              |            |  |     |        |        |          |            |  |     |        |        |  |  |  |
| 3            | ✓ king pin                                                                                                                                                                                                                                                                                                               | \$0.00     | \$0.00    | \$0.00     |        |           |      |              |            |  |     |        |        |          |            |  |     |        |        |  |  |  |
|              | <b><u>Notes</u></b>                                                                                                                                                                                                                                                                                                      |            |           |            |        |           |      |              |            |  |     |        |        |          |            |  |     |        |        |  |  |  |
|              | R/H side wore                                                                                                                                                                                                                                                                                                            |            |           |            |        |           |      |              |            |  |     |        |        |          |            |  |     |        |        |  |  |  |
|              | <table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>King pin kit</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>                                                                                                | Part       | Warehouse | Vendor/Bin | Qty    | Unit Cost | Cost | King pin kit | Kropp Shop |  | 1.0 | \$0.00 | \$0.00 |          |            |  |     |        |        |  |  |  |
| Part         | Warehouse                                                                                                                                                                                                                                                                                                                | Vendor/Bin | Qty       | Unit Cost  | Cost   |           |      |              |            |  |     |        |        |          |            |  |     |        |        |  |  |  |
| King pin kit | Kropp Shop                                                                                                                                                                                                                                                                                                               |            | 1.0       | \$0.00     | \$0.00 |           |      |              |            |  |     |        |        |          |            |  |     |        |        |  |  |  |
| 4            | ✓ transmission air leak                                                                                                                                                                                                                                                                                                  | \$0.00     | \$0.00    | \$0.00     |        |           |      |              |            |  |     |        |        |          |            |  |     |        |        |  |  |  |
|              | <b><u>Notes</u></b>                                                                                                                                                                                                                                                                                                      |            |           |            |        |           |      |              |            |  |     |        |        |          |            |  |     |        |        |  |  |  |
|              | Bottom L/H on Auxiliary                                                                                                                                                                                                                                                                                                  |            |           |            |        |           |      |              |            |  |     |        |        |          |            |  |     |        |        |  |  |  |
| 5            | ✓ transmission cooler coolant leak                                                                                                                                                                                                                                                                                       | \$0.00     | \$0.00    | \$0.00     |        |           |      |              |            |  |     |        |        |          |            |  |     |        |        |  |  |  |
|              | <b><u>Notes</u></b>                                                                                                                                                                                                                                                                                                      |            |           |            |        |           |      |              |            |  |     |        |        |          |            |  |     |        |        |  |  |  |
|              | loose clamp tightened                                                                                                                                                                                                                                                                                                    |            |           |            |        |           |      |              |            |  |     |        |        |          |            |  |     |        |        |  |  |  |
| 6            | ✓ diff input seals                                                                                                                                                                                                                                                                                                       | \$0.00     | \$0.00    | \$0.00     |        |           |      |              |            |  |     |        |        |          |            |  |     |        |        |  |  |  |
|              | <b><u>Notes</u></b>                                                                                                                                                                                                                                                                                                      |            |           |            |        |           |      |              |            |  |     |        |        |          |            |  |     |        |        |  |  |  |

# 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

Front diff input

| Part                               | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|------------------------------------|------------|------------|--------|-----------|--------|
| R945007 - Input diff seal rockwell | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 7 ✓ diff output seals              |            |            | \$0.00 | \$0.00    | \$0.00 |

## Notes

Middle diff output

| Part                           | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|--------------------------------|------------|------------|--------|-----------|--------|
| R945008 - Rockwell output seal | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 8 ✓ brake pot bracket bent     |            |            | \$0.00 | \$0.00    | \$0.00 |

## Notes

Middle Drive R/H bracket

|                        |  |  |        |        |        |
|------------------------|--|--|--------|--------|--------|
| 9 ✓ t rail bolts loose |  |  | \$0.00 | \$0.00 | \$0.00 |
|------------------------|--|--|--------|--------|--------|

| Part                   | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|------------------------|------------|------------|--------|-----------|--------|
| 3/4 bolts              | Kropp Shop |            | 2.0    | \$0.00    | \$0.00 |
| 10 ✓ battery box cover |            |            | \$0.00 | \$0.00    | \$0.00 |

## Notes

Fix mounting bolt holes for step

|                         |  |  |        |        |        |
|-------------------------|--|--|--------|--------|--------|
| 11 ✓ replace windshield |  |  | \$0.00 | \$0.00 | \$0.00 |
|-------------------------|--|--|--------|--------|--------|

## Notes

R/H cracked

| Part                  | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|-----------------------|------------|------------|--------|-----------|--------|
| windshield RH         | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 12 ✓ replace fan belt |            |            | \$0.00 | \$0.00    | \$0.00 |

| Part     | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|----------|------------|------------|-----|-----------|--------|
| fan belt | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

|                       |  |  |        |        |        |
|-----------------------|--|--|--------|--------|--------|
| 13 ✓ replace A/C belt |  |  | \$0.00 | \$0.00 | \$0.00 |
|-----------------------|--|--|--------|--------|--------|

| Part | Warehouse | Vendor/Bin | Qty | Unit Cost | Cost |
|------|-----------|------------|-----|-----------|------|
|------|-----------|------------|-----|-----------|------|

# 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

|    |                                                 |            |            |        |           |        |
|----|-------------------------------------------------|------------|------------|--------|-----------|--------|
|    | ac belt                                         | Kropp Shop | 1.0        | \$0.00 | \$0.00    |        |
| 14 | ✓ coolant leaks                                 |            | \$0.00     | \$0.00 | \$0.00    |        |
|    | <b><u>Notes</u></b>                             |            |            |        |           |        |
|    | water valve coolant leak loose clamp            |            |            |        |           |        |
| 15 | ✓ Stack heat shields adjust                     |            | \$0.00     | \$0.00 | \$0.00    |        |
|    | <b><u>Notes</u></b>                             |            |            |        |           |        |
|    | R/H stack bolts MIA and twist away from sleeper |            |            |        |           |        |
| 16 | ✓ replace air filters                           |            | \$0.00     | \$0.00 | \$0.00    |        |
|    | Part                                            | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | air filters                                     | Kropp Shop |            | 2.0    | \$0.00    | \$0.00 |
| 17 | ✓ replace diff filters                          |            | \$0.00     | \$0.00 | \$0.00    |        |
|    | Part                                            | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | LF3311 - Rockwell diff filter                   | Kropp Shop |            | 2.0    | \$0.00    | \$0.00 |
| 18 | ✓ Inspect and diagnose CEL                      |            | \$0.00     | \$0.00 | \$0.00    |        |
|    | <b><u>Notes</u></b>                             |            |            |        |           |        |
|    | DEF line heater 2 relay fault                   |            |            |        |           |        |
|    | Part                                            | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | relay                                           | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 19 | ✓ Wrap umbilical cord                           |            | \$0.00     | \$0.00 | \$0.00    |        |
| 20 | ✓ replace tarp straps on plywood                |            | \$0.00     | \$0.00 | \$0.00    |        |
|    | <b><u>Notes</u></b>                             |            |            |        |           |        |
|    | Front Deck strap broke                          |            |            |        |           |        |
|    | Part                                            | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | strap 20"                                       | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 21 | ✓ rear plywood to put on                        |            | \$0.00     | \$0.00 | \$0.00    |        |

**Notes**

# 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

MIA put back on

| Part               | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|--------------------|------------|------------|--------|-----------|--------|
| strap 20"          | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 22 ✓ convex mirror |            |            | \$0.00 | \$0.00    | \$0.00 |

## Notes

R/H mirror

| Part                             | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|----------------------------------|------------|------------|--------|-----------|--------|
| Convex mirror t800               | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 23 ✓ turbo actuator coolant leak |            |            | \$0.00 | \$0.00    | \$0.00 |

| Part                           | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|--------------------------------|------------|------------|--------|-----------|--------|
| turbo actuator                 | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 24 ✓ Loose yoke on output diff |            |            | \$0.00 | \$0.00    | \$0.00 |

## Notes

Front diff output

| 25 ✓ RH plastic fender broke |            |            | \$0.00 | \$0.00    | \$0.00 |
|------------------------------|------------|------------|--------|-----------|--------|
| Part                         | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
| plastic fender               | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |

|                       |  |  |        |        |        |
|-----------------------|--|--|--------|--------|--------|
| 26 ✓ Rubber air lines |  |  | \$0.00 | \$0.00 | \$0.00 |
|-----------------------|--|--|--------|--------|--------|

## Notes

Front LH drive Wore thru and leaking

| Part           | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|----------------|------------|------------|-----|-----------|--------|
| #8 rubber hose | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |
| #6 rubber hose | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

| 27 ✓ Grease truck and trailer |            |            | \$0.00 | \$0.00    | \$0.00 |
|-------------------------------|------------|------------|--------|-----------|--------|
| Part                          | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
| grease tubes                  | Kropp Shop |            | 5.0    | \$0.00    | \$0.00 |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

**Work Order 1063**

Trent Court

# CLOSED

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

# 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 14,367 hr & 645,594 km |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | May 3, 2024 | May 3, 2024 |     | May 3, 2024 5:32 PM | May 3, 2024 5:32 PM |

| Line | Task                                     |            |            | Parts        | Labor     | Total    |
|------|------------------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Oil change                             |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                                     | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | oil 15w-40                               | Kropp Shop |            | 42.0         | \$0.00    | \$0.00   |
|      | LF14000 - Cummins oil filter             | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | FF5825NN - Cummins fuel filter           | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | FS20172 - Cummins water separator filter | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
| 2    | ✓ Grease truck and trailer               |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                                     | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | grease tubes                             | Kropp Shop |            | 4.0          | \$0.00    | \$0.00   |
|      |                                          |            |            | Part Cost    |           | \$0.00   |
|      |                                          |            |            | Labor        |           | \$0.00   |
|      |                                          |            |            | Subtotal     |           | \$0.00   |
|      |                                          |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                          |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                          |            |            | Credit       |           | (\$0.00) |
|      |                                          |            |            | Total Cost   |           | \$0.00   |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

Work Order 1117

Trent Court

# CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 14,451 hr & 650,722 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | May 23, 2024 | May 23, 2024 |     | May 24, 2024 7:29 AM | May 24, 2024 7:29 AM |

| Line | Task                                    | Parts  | Labor  | Total  |
|------|-----------------------------------------|--------|--------|--------|
| 1    | ✓ truck stalling/low rail pressure code | \$0.00 | \$0.00 | \$0.00 |

### Notes

#3,#5 injector failed on return

applied for warranty on May 23,2024

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

Work Order 1151

Cam Nadeau

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 14,451 hr & 650,722 km |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Jun 27, 2024 |     | Jun 27, 2024 6:40 AM | Jun 27, 2024 6:40 AM |

| Line | Task                  | Parts        | Labor  | Total    |
|------|-----------------------|--------------|--------|----------|
| 1    | ✓ Replace water valve | \$0.00       | \$0.00 | \$0.00   |
|      |                       | Part Cost    |        | \$0.00   |
|      |                       | Labor        |        | \$0.00   |
|      |                       | Subtotal     |        | \$0.00   |
|      |                       | Tax 1 (0.0%) |        | \$0.00   |
|      |                       | Tax 2 (0.0%) |        | \$0.00   |
|      |                       | Credit       |        | (\$0.00) |
|      |                       | Total Cost   |        | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

# CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 14,744 hr & 666,193 km |

| Type    | Created      | Scheduled    | Due          | Started              | Closed               |
|---------|--------------|--------------|--------------|----------------------|----------------------|
| Service | Jul 15, 2024 | Jul 15, 2024 | Jul 15, 2024 | Jul 15, 2024 8:45 AM | Jul 15, 2024 8:49 AM |

| Line | Task                                                           | Parts  | Labor  | Total  |
|------|----------------------------------------------------------------|--------|--------|--------|
| 1    | ✓ Replace seat                                                 | \$0.00 | \$0.00 | \$0.00 |
| 2    | ✓ saddle crack                                                 | \$0.00 | \$0.00 | \$0.00 |
|      | <b>Notes</b>                                                   |        |        |        |
|      | #6RHS                                                          |        |        |        |
| 3    | ✓ Lights not working                                           | \$0.00 | \$0.00 | \$0.00 |
|      | <b>Notes</b>                                                   |        |        |        |
|      | Repair truck 7 wire                                            |        |        |        |
| 4    | ✓ Flat tire                                                    | \$0.00 | \$0.00 | \$0.00 |
|      | <b>Notes</b>                                                   |        |        |        |
|      | #6 LH outside, #6 RH outside, # 8 RH outside                   |        |        |        |
| 5    | ✓ Replace missing/tore mudflaps                                | \$0.00 | \$0.00 | \$0.00 |
|      | <b>Notes</b>                                                   |        |        |        |
|      | Re-install mid trailer flap in front of lift axle, weld mounts |        |        |        |

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

Work Order 1189

Trent Court

# CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 14,744 hr & 666,194 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Jul 15, 2024 | Jul 15, 2024 |     | Jul 15, 2024 3:52 PM | Jul 15, 2024 3:52 PM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

# CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 14,744 hr & 687,573 km |

| Type | Created      | Scheduled    | Due | Started               | Closed                |
|------|--------------|--------------|-----|-----------------------|-----------------------|
|      | Jul 18, 2024 | Jul 18, 2024 |     | Jul 18, 2024 10:52 AM | Jul 18, 2024 10:52 AM |

| Line | Task                                     |            |            | Parts        | Labor     | Total    |
|------|------------------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Oil change                             |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                                     | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | LF14000 - Cummins oil filter             | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | FS20172 - Cummins water separator filter | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | FF5825NN - Cummins fuel filter           | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | oil 15w-40                               | Kropp Shop |            | 42.0         | \$0.00    | \$0.00   |
|      |                                          |            |            | Part Cost    |           | \$0.00   |
|      |                                          |            |            | Labor        |           | \$0.00   |
|      |                                          |            |            | Subtotal     |           | \$0.00   |
|      |                                          |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                          |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                          |            |            | Credit       |           | (\$0.00) |
|      |                                          |            |            | Total Cost   |           | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

# CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 14,744 hr & 687,573 km |

| Type | Created      | Scheduled    | Due | Started               | Closed                |
|------|--------------|--------------|-----|-----------------------|-----------------------|
|      | Jul 20, 2024 | Jul 20, 2024 |     | Jul 20, 2024 12:09 PM | Jul 20, 2024 12:09 PM |

| Line | Task                                                                     | Parts      | Labor      | Total        |           |          |
|------|--------------------------------------------------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Breakdown: go out and replace coolant line blown ontop of transmission | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                                                                     | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 3/4" heater hose                                                         | Kropp Shop |            | 2.0          | \$0.00    | \$0.00   |
|      | Coolant                                                                  | Kropp Shop |            | 8.0          | \$0.00    | \$0.00   |
|      |                                                                          |            |            | Part Cost    |           | \$0.00   |
|      |                                                                          |            |            | Labor        |           | \$0.00   |
|      |                                                                          |            |            | Subtotal     |           | \$0.00   |
|      |                                                                          |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                                                          |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                                                          |            |            | Credit       |           | (\$0.00) |
|      |                                                                          |            |            | Total Cost   |           | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 14,863 hr & 671,896 km |

| Type   | Created      | Scheduled    | Due          | Started              | Closed               |
|--------|--------------|--------------|--------------|----------------------|----------------------|
| engine | Jul 26, 2024 | Jul 26, 2024 | Jul 26, 2024 | Jul 26, 2024 9:13 AM | Jul 26, 2024 9:16 AM |

| Line | Task | Parts | Labor | Total |
|------|------|-------|-------|-------|
|------|------|-------|-------|-------|

|   |                               |        |        |        |
|---|-------------------------------|--------|--------|--------|
| 1 | ✓ diagnose Check engine light | \$0.00 | \$0.00 | \$0.00 |
|---|-------------------------------|--------|--------|--------|

**Notes**

Perform regen, re torque injector tubes, tighten lines to fix fuel leaks

|   |                 |        |        |        |
|---|-----------------|--------|--------|--------|
| 2 | ✓ Repair Lights | \$0.00 | \$0.00 | \$0.00 |
|---|-----------------|--------|--------|--------|

**Notes**

Clean and fix headlight plugs, replace chassis node

Replace LH fender light

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

# 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 14,890 hr & 673,201 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Aug 15, 2024 | Aug 15, 2024 |     | Aug 15, 2024 4:08 AM | Aug 15, 2024 4:08 AM |

| Line | Task                                    | Parts      | Labor      | Total        |           |          |
|------|-----------------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Grease truck and trailer              | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                                    | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | grease tubes                            | Kropp Shop |            | 3.0          | \$0.00    | \$0.00   |
| 2    | ✓ Broken air line over top middle drive | \$0.00     | \$0.00     | \$0.00       |           |          |
| 3    | ✓ #4 LH outside tire low                | \$0.00     | \$0.00     | \$0.00       |           |          |
| 4    | ✓ RH wiper nfg                          | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                                    | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 15" wiper blade                         | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                                         |            |            | Part Cost    |           | \$0.00   |
|      |                                         |            |            | Labor        |           | \$0.00   |
|      |                                         |            |            | Subtotal     |           | \$0.00   |
|      |                                         |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                         |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                         |            |            | Credit       |           | (\$0.00) |
|      |                                         |            |            | Total Cost   |           | \$0.00   |

# 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 15,020 hr & 681,127 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Aug 30, 2024 | Aug 30, 2024 |     | Aug 30, 2024 3:38 PM | Aug 30, 2024 3:38 PM |

| Line | Task                                              | Parts      | Labor      | Total  |           |        |
|------|---------------------------------------------------|------------|------------|--------|-----------|--------|
| 1    | ✓ Belts and Hoses                                 | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <b><u>Notes</u></b>                               |            |            |        |           |        |
|      | Coolant hose leaking from transmission cooler     |            |            |        |           |        |
|      | Part                                              | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | 3/4" heater hose                                  | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 2    | ✓ Brake Accessories                               | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <b><u>Notes</u></b>                               |            |            |        |           |        |
|      | S cam u bolt LH middle drive loose                |            |            |        |           |        |
| 3    | ✓ Exhaust                                         | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <b><u>Notes</u></b>                               |            |            |        |           |        |
|      | Bellows pipe leaking                              |            |            |        |           |        |
|      | Part                                              | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | EBPB11861 - Bellows kit                           | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 4    | ✓ Grease truck and trailer                        | \$0.00     | \$0.00     | \$0.00 |           |        |
| 5    | ✓ Lights - All                                    | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <b><u>Notes</u></b>                               |            |            |        |           |        |
|      | Headlights not coming on, hood lights not working |            |            |        |           |        |
| 6    | ✓ Tires                                           | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <b><u>Notes</u></b>                               |            |            |        |           |        |
|      | Steer tires wore out                              |            |            |        |           |        |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

Work Order 1265

Trent Court

# CLOSED

| 7           | ✓ Steer Tires |            |              | \$0.00    | \$0.00   | \$0.00 |
|-------------|---------------|------------|--------------|-----------|----------|--------|
| Part        | Warehouse     | Vendor/Bin | Qty          | Unit Cost | Cost     |        |
| steer tires | Kropp Shop    |            | 2.0          | \$0.00    | \$0.00   |        |
|             |               |            | Part Cost    |           | \$0.00   |        |
|             |               |            | Labor        |           | \$0.00   |        |
|             |               |            | Subtotal     |           | \$0.00   |        |
|             |               |            | Tax 1 (0.0%) |           | \$0.00   |        |
|             |               |            | Tax 2 (0.0%) |           | \$0.00   |        |
|             |               |            | Credit       |           | (\$0.00) |        |
|             |               |            | Total Cost   |           | \$0.00   |        |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 15,144 hr & 686,662 km |

| Type | Created      | Scheduled   | Due | Started              | Closed               |
|------|--------------|-------------|-----|----------------------|----------------------|
|      | Sep 26, 2024 | Sep 9, 2024 |     | Sep 26, 2024 2:15 PM | Sep 26, 2024 2:15 PM |

| Line | Task                      | Parts        | Labor  | Total    |
|------|---------------------------|--------------|--------|----------|
| 1    | ✓ Steer Tires             | \$0.00       | \$0.00 | \$0.00   |
| 2    | ✓ Landing gear on trailer | \$0.00       | \$0.00 | \$0.00   |
|      |                           | Part Cost    |        | \$0.00   |
|      |                           | Labor        |        | \$0.00   |
|      |                           | Subtotal     |        | \$0.00   |
|      |                           | Tax 1 (0.0%) |        | \$0.00   |
|      |                           | Tax 2 (0.0%) |        | \$0.00   |
|      |                           | Credit       |        | (\$0.00) |
|      |                           | Total Cost   |        | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

# CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 15,144 hr & 686,662 km |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Oct 4, 2024 | Oct 4, 2024 |     | Oct 4, 2024 4:35 PM | Oct 4, 2024 4:35 PM |

| Line | Task                       | Parts  | Labor  | Total  |
|------|----------------------------|--------|--------|--------|
| 1    | ✓ Grease truck and trailer | \$0.00 | \$0.00 | \$0.00 |
| 2    | ✓ Mirrors                  | \$0.00 | \$0.00 | \$0.00 |

### Notes

Convex mirror no heat

| Part               | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|--------------------|------------|------------|-----|-----------|--------|
| Convex mirror t800 | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

|   |              |        |        |        |
|---|--------------|--------|--------|--------|
| 3 | ✓ Oil change | \$0.00 | \$0.00 | \$0.00 |
| 4 | ✓ Windows    | \$0.00 | \$0.00 | \$0.00 |

### Notes

LH windshield no good

| Part          | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|---------------|------------|------------|-----|-----------|--------|
| Windshield LH | Kropp Shop |            | 1.0 | \$0.00    | \$0.00 |

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

# CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 15,155 hr & 689,331 km |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Oct 8, 2024 | Oct 8, 2024 |     | Oct 8, 2024 6:59 AM | Oct 8, 2024 6:59 AM |

| Line | Task                               | Parts  | Labor  | Total  |
|------|------------------------------------|--------|--------|--------|
| 1    | ✓ Lights - All                     | \$0.00 | \$0.00 | \$0.00 |
|      | <b>Notes</b>                       |        |        |        |
|      | ground in fuse panel dirty cleaned |        |        |        |
|      | Roof lights not working            |        |        |        |
| 2    | ✓ RH hood light not working        | \$0.00 | \$0.00 | \$0.00 |
|      | <b>Notes</b>                       |        |        |        |
|      | weather pack tore off              |        |        |        |

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

# CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 15,221 hr & 693,174 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Oct 20, 2024 | Oct 20, 2024 |     | Oct 20, 2024 2:39 PM | Oct 20, 2024 2:39 PM |

| Line | Task                                                        | Parts  | Labor  | Total  |
|------|-------------------------------------------------------------|--------|--------|--------|
| 1    | ✓ Body<br><b>Notes</b><br>Roof loose                        | \$0.00 | \$0.00 | \$0.00 |
| 2    | ✓ Coupling Device/Hitch<br><b>Notes</b><br>Adjust 5th wheel | \$0.00 | \$0.00 | \$0.00 |
| 3    | ✓ Other<br><b>Notes</b><br>work light shorting              | \$0.00 | \$0.00 | \$0.00 |

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

**Work Order 1384**  
Nate Vandenberghe, Sam Hawksley

# CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 15,296 hr & 697,490 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Oct 30, 2024 | Oct 30, 2024 |     | Oct 30, 2024 8:01 PM | Oct 30, 2024 8:01 PM |

| Line | Task                                       | Parts        | Labor      | Total  |           |          |
|------|--------------------------------------------|--------------|------------|--------|-----------|----------|
| 1    | ✓ Replace air dryer                        | \$0.00       | \$0.00     | \$0.00 |           |          |
|      | Part                                       | Warehouse    | Vendor/Bin | Qty    | Unit Cost | Cost     |
|      | 801266 - Air dryer ADIS                    | Kropp Shop   |            | 1.0    | \$0.00    | \$0.00   |
| 2    | ✓ Replace compressor hose with braided one | \$0.00       | \$0.00     | \$0.00 |           |          |
|      |                                            | Part Cost    |            |        |           | \$0.00   |
|      |                                            | Labor        |            |        |           | \$0.00   |
|      |                                            | Subtotal     |            |        |           | \$0.00   |
|      |                                            | Tax 1 (0.0%) |            |        |           | \$0.00   |
|      |                                            | Tax 2 (0.0%) |            |        |           | \$0.00   |
|      |                                            | Credit       |            |        |           | (\$0.00) |
|      |                                            | Total Cost   |            |        |           | \$0.00   |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

Work Order 1389

Trent Court

# CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 15,310 hr & 698,339 km |

| Type | Scheduled   | Due | Started             | Closed              |
|------|-------------|-----|---------------------|---------------------|
|      | Nov 1, 2024 |     | Nov 1, 2024 6:29 PM | Nov 1, 2024 6:29 PM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

Work Order 1434

Nate Vandenberghe

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 15,446 hr & 706,781 km |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | Nov 16, 2024 |     | Nov 16, 2024 6:36 AM | Nov 16, 2024 6:36 AM |

| Line | Task                            | Parts        | Labor  | Total    |
|------|---------------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer      | \$0.00       | \$0.00 | \$0.00   |
| 2    | ✓ LH stack bushing              | \$0.00       | \$0.00 | \$0.00   |
| 3    | ✓ coolant leaks                 | \$0.00       | \$0.00 | \$0.00   |
| 4    | ✓ Steer RH hub low              | \$0.00       | \$0.00 | \$0.00   |
| 5    | ✓ Chafed airlines in front diff | \$0.00       | \$0.00 | \$0.00   |
|      |                                 | Part Cost    |        | \$0.00   |
|      |                                 | Labor        |        | \$0.00   |
|      |                                 | Subtotal     |        | \$0.00   |
|      |                                 | Tax 1 (0.0%) |        | \$0.00   |
|      |                                 | Tax 2 (0.0%) |        | \$0.00   |
|      |                                 | Credit       |        | (\$0.00) |
|      |                                 | Total Cost   |        | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

# CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 15,520 hr & 711,150 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Nov 22, 2024 | Nov 22, 2024 |     | Nov 22, 2024 4:09 PM | Nov 22, 2024 4:09 PM |

| Line | Task                           | Parts        | Labor  | Total    |
|------|--------------------------------|--------------|--------|----------|
| 1    | ✓ Oil change                   | \$0.00       | \$0.00 | \$0.00   |
| 2    | ✓ Grease truck and trailer     | \$0.00       | \$0.00 | \$0.00   |
| 3    | ✓ Multi function valve cracked | \$0.00       | \$0.00 | \$0.00   |
| 4    | ✓ stack twisted rh             | \$0.00       | \$0.00 | \$0.00   |
| 5    | ✓ set brakes                   | \$0.00       | \$0.00 | \$0.00   |
| 6    | ✓ battery box bolts mia        | \$0.00       | \$0.00 | \$0.00   |
|      |                                | Part Cost    |        | \$0.00   |
|      |                                | Labor        |        | \$0.00   |
|      |                                | Subtotal     |        | \$0.00   |
|      |                                | Tax 1 (0.0%) |        | \$0.00   |
|      |                                | Tax 2 (0.0%) |        | \$0.00   |
|      |                                | Credit       |        | (\$0.00) |
|      |                                | Total Cost   |        | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

# CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 15,573 hr & 714,335 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Nov 26, 2024 | Nov 26, 2024 |     | Nov 26, 2024 5:25 PM | Nov 26, 2024 5:25 PM |

| Line | Task                          | Parts  | Labor  | Total  |
|------|-------------------------------|--------|--------|--------|
| 1    | ✓ #4 LHO flat                 | \$0.00 | \$0.00 | \$0.00 |
| 2    | ✓ Low coolant alarm going off | \$0.00 | \$0.00 | \$0.00 |

### Notes

Plug tore off and replaced, brakes in wire along corner of head and repaired

| Part                    | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost     |
|-------------------------|------------|------------|-----|-----------|----------|
| Low coolant pigtail kit | Kropp Shop |            | 1.0 | \$0.00    | \$0.00   |
| Part Cost               |            |            |     |           | \$0.00   |
| Labor                   |            |            |     |           | \$0.00   |
| Subtotal                |            |            |     |           | \$0.00   |
| Tax 1 (0.0%)            |            |            |     |           | \$0.00   |
| Tax 2 (0.0%)            |            |            |     |           | \$0.00   |
| Credit                  |            |            |     |           | (\$0.00) |
| Total Cost              |            |            |     |           | \$0.00   |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

**Work Order 1475**

Everett Twin, Trent Court

# CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 15,617 hr & 717,012 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Nov 30, 2024 | Nov 30, 2024 |     | Nov 30, 2024 2:15 PM | Nov 30, 2024 2:15 PM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
| 2    | ✓ clutch linkage           | \$0.00       | \$0.00 | \$0.00   |
| 3    | ✓ trailer light(s) out     | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

# 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 15,794 hr & 727,659 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Dec 13, 2024 | Dec 13, 2024 |     | Dec 13, 2024 8:46 PM | Dec 13, 2024 8:46 PM |

| Line | Task                       | Parts      |            | Labor  | Total     |        |
|------|----------------------------|------------|------------|--------|-----------|--------|
| 1    | ✓ Grease truck and trailer | \$0.00     |            | \$0.00 | \$0.00    |        |
|      | Part                       | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | grease tubes               | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 2    | ✓ Lights - All             | \$0.00     |            | \$0.00 | \$0.00    |        |
|      | <u>Notes</u>               |            |            |        |           |        |
|      | LH mirror light out        |            |            |        |           |        |
| 3    | ✓ Radiator                 | \$0.00     |            | \$0.00 | \$0.00    |        |
|      | <u>Notes</u>               |            |            |        |           |        |
|      | Top rad hose clamp loose   |            |            |        |           |        |
| 4    | ✓ Transmission             | \$0.00     |            | \$0.00 | \$0.00    |        |
|      | <u>Notes</u>               |            |            |        |           |        |
|      | Cooler leaking             |            |            |        |           |        |
|      | Part                       | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | Transmission cooler        | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
|      | 3/4" heater hose           | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 5    | ✓ Windows                  | \$0.00     |            | \$0.00 | \$0.00    |        |
|      | <u>Notes</u>               |            |            |        |           |        |
|      | RH windshield cracked      |            |            |        |           |        |
|      | Part                       | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | Rh window glass            | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

**Work Order 1513**

Nate Vandenberghe

# CLOSED

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

Work Order 1577

Trent Court

# CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 16,086 hr & 743,390 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Jan 16, 2025 | Jan 16, 2025 |     | Jan 17, 2025 2:25 PM | Jan 17, 2025 2:25 PM |

| Line | Task                              | Parts        | Labor  | Total    |
|------|-----------------------------------|--------------|--------|----------|
| 1    | ✓ alternator no good not charging | \$0.00       | \$0.00 | \$0.00   |
|      |                                   | Part Cost    |        | \$0.00   |
|      |                                   | Labor        |        | \$0.00   |
|      |                                   | Subtotal     |        | \$0.00   |
|      |                                   | Tax 1 (0.0%) |        | \$0.00   |
|      |                                   | Tax 2 (0.0%) |        | \$0.00   |
|      |                                   | Credit       |        | (\$0.00) |
|      |                                   | Total Cost   |        | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 16,097 hr & 743,930 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Jan 17, 2025 | Jan 17, 2025 |     | Jan 17, 2025 2:26 PM | Jan 17, 2025 2:26 PM |

| Line | Task                                   | Parts  | Labor  | Total  |
|------|----------------------------------------|--------|--------|--------|
| 1    | ✓ Engine                               | \$0.00 | \$0.00 | \$0.00 |
|      | <b><u>Notes</u></b>                    |        |        |        |
|      | fuel lines leaking off connector tubes |        |        |        |
| 2    | ✓ Exhaust                              | \$0.00 | \$0.00 | \$0.00 |
|      | <b><u>Notes</u></b>                    |        |        |        |
|      | bellows pipe cracked                   |        |        |        |
| 3    | ✓ Fifth Wheel                          | \$0.00 | \$0.00 | \$0.00 |
|      | <b><u>Notes</u></b>                    |        |        |        |
|      | adjust 5th wheel sloppy                |        |        |        |
| 4    | ✓ Grease truck and trailer             | \$0.00 | \$0.00 | \$0.00 |
| 5    | ✓ Lights - All                         | \$0.00 | \$0.00 | \$0.00 |
|      | <b><u>Notes</u></b>                    |        |        |        |
|      | top rh work light pointing into truck  |        |        |        |
| 6    | ✓ Oil change                           | \$0.00 | \$0.00 | \$0.00 |
| 7    | ✓ Transmission                         | \$0.00 | \$0.00 | \$0.00 |
|      | <b><u>Notes</u></b>                    |        |        |        |
|      | speed sensor loose                     |        |        |        |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

**Work Order 1579**

Unassigned

# CLOSED

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

**Work Order 1607**  
Nate Vandenberghe, Everett Twin

# CLOSED

| Serial            | Tag    | Closed Meters          |
|-------------------|--------|------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 16,124 hr & 744,687 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Jan 20, 2025 | Jan 20, 2025 |     | Jan 20, 2025 7:48 PM | Jan 20, 2025 7:48 PM |

| Line | Task                      | Parts        | Labor  | Total    |
|------|---------------------------|--------------|--------|----------|
| 1    | ✓ Drive tires (set of 12) | \$0.00       | \$0.00 | \$0.00   |
|      |                           | Part Cost    |        | \$0.00   |
|      |                           | Labor        |        | \$0.00   |
|      |                           | Subtotal     |        | \$0.00   |
|      |                           | Tax 1 (0.0%) |        | \$0.00   |
|      |                           | Tax 2 (0.0%) |        | \$0.00   |
|      |                           | Credit       |        | (\$0.00) |
|      |                           | Total Cost   |        | \$0.00   |

# 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

**CLOSED**

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 2,170 hr & 744,687 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Jan 25, 2025 | Jan 25, 2025 |     | Jan 25, 2025 9:18 AM | Jan 25, 2025 9:18 AM |

| Line | Task                                       | Parts      | Labor      | Total        |           |          |
|------|--------------------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ engine pushing coolant, low oil pressure | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                                       | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | X15 Spare - stock X15                      | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | LF14000 - Cummins oil filter               | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | oil 15w-40                                 | Kropp Shop |            | 42.0         | \$0.00    | \$0.00   |
|      |                                            |            |            | Part Cost    |           | \$0.00   |
|      |                                            |            |            | Labor        |           | \$0.00   |
|      |                                            |            |            | Subtotal     |           | \$0.00   |
|      |                                            |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                            |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                            |            |            | Credit       |           | (\$0.00) |
|      |                                            |            |            | Total Cost   |           | \$0.00   |

## Notes

| Notes                                                                                                                                                                                  | User        | Time                 |
|----------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|-------------|----------------------|
| Replaced engine with spare engine in stock, will rebuild at a later date<br>engine was pushing coolant, and running at 18 PSI oil pressure<br>New ecm HRS at 2170.5<br>truck KM 747200 | Trent Court | Jan 25, 2025 9:07 AM |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

Work Order 1618

Trent Court

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 2,202 hr & 748,629 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Jan 28, 2025 | Jan 28, 2025 |     | Jan 28, 2025 3:59 PM | Jan 28, 2025 3:59 PM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 2,236 hr & 749,851 km |

| Type | Scheduled   | Due | Started             | Closed              |
|------|-------------|-----|---------------------|---------------------|
|      | Feb 1, 2025 |     | Feb 1, 2025 8:15 AM | Feb 1, 2025 8:15 AM |

| Line         | Task                             | Parts  | Labor  | Total    |
|--------------|----------------------------------|--------|--------|----------|
| 1            | ✓ Engine                         | \$0.00 | \$0.00 | \$0.00   |
|              | <b>Notes</b>                     |        |        |          |
|              | check engine light diff pressure |        |        |          |
| 2            | ✓ Lights - All                   | \$0.00 | \$0.00 | \$0.00   |
|              | <b>Notes</b>                     |        |        |          |
|              | rh mirror lights out             |        |        |          |
| Part Cost    |                                  |        |        | \$0.00   |
| Labor        |                                  |        |        | \$0.00   |
| Subtotal     |                                  |        |        | \$0.00   |
| Tax 1 (0.0%) |                                  |        |        | \$0.00   |
| Tax 2 (0.0%) |                                  |        |        | \$0.00   |
| Credit       |                                  |        |        | (\$0.00) |
| Total Cost   |                                  |        |        | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 2,293 hr & 752,401 km |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Feb 7, 2025 | Feb 7, 2025 |     | Feb 7, 2025 7:38 PM | Feb 7, 2025 8:03 PM |

| Line | Task                       |            |            | Parts        | Labor     | Total    |
|------|----------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Replace Radiator         |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                       | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | t800 radiator              | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
| 2    | ✓ Mirror heat switch       |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                       | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | BA80005-Mirror heat switch | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                            |            |            | Part Cost    |           | \$0.00   |
|      |                            |            |            | Labor        |           | \$0.00   |
|      |                            |            |            | Subtotal     |           | \$0.00   |
|      |                            |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                            |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                            |            |            | Credit       |           | (\$0.00) |
|      |                            |            |            | Total Cost   |           | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 2,339 hr & 754,653 km |

| Type | Created      | Scheduled    | Due | Started               | Closed                |
|------|--------------|--------------|-----|-----------------------|-----------------------|
|      | Feb 11, 2025 | Feb 11, 2025 |     | Feb 11, 2025 10:13 PM | Feb 11, 2025 10:13 PM |

| Line | Task                                                                                                     | Parts        | Labor  | Total    |
|------|----------------------------------------------------------------------------------------------------------|--------------|--------|----------|
| 1    | ✓ Check all fluid levels<br><br><u>Notes</u><br>Power steering level low, coolant low                    | \$0.00       | \$0.00 | \$0.00   |
| 2    | ✓ Driveline<br><br><u>Notes</u><br>Inspect output tranny yoke, inspect front diff input yoke, seem loose | \$0.00       | \$0.00 | \$0.00   |
| 3    | ✓ Grease truck and trailer                                                                               | \$0.00       | \$0.00 | \$0.00   |
| 4    | ✓ Steering System<br><br><u>Notes</u><br>Wheel alignment out- toe tie rod ends wore                      | \$0.00       | \$0.00 | \$0.00   |
|      |                                                                                                          | Part Cost    |        | \$0.00   |
|      |                                                                                                          | Labor        |        | \$0.00   |
|      |                                                                                                          | Subtotal     |        | \$0.00   |
|      |                                                                                                          | Tax 1 (0.0%) |        | \$0.00   |
|      |                                                                                                          | Tax 2 (0.0%) |        | \$0.00   |
|      |                                                                                                          | Credit       |        | (\$0.00) |
|      |                                                                                                          | Total Cost   |        | \$0.00   |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

Work Order 1694

Trent Court

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 2,426 hr & 759,294 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Feb 21, 2025 | Feb 21, 2025 |     | Feb 21, 2025 9:33 PM | Feb 21, 2025 9:33 PM |

| Line | Task                     | Parts  | Labor  | Total  |
|------|--------------------------|--------|--------|--------|
| 1    | ✓ No vehicle speedometer | \$0.00 | \$0.00 | \$0.00 |

### Notes

Checked harness found wire by cab mount rubbed thru

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

Work Order 1735

Nate Vandenberghe

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 2,518 hr & 764,789 km |

| Type | Scheduled   | Due | Started              | Closed               |
|------|-------------|-----|----------------------|----------------------|
|      | Mar 3, 2025 |     | Mar 3, 2025 12:09 PM | Mar 3, 2025 12:09 PM |

| Line | Task                       | Parts  | Labor  | Total  |
|------|----------------------------|--------|--------|--------|
| 1    | ✓ Check all fluid levels   | \$0.00 | \$0.00 | \$0.00 |
|      | <b>Notes</b>               |        |        |        |
|      | power steering level low   |        |        |        |
| 2    | ✓ Grease truck and trailer | \$0.00 | \$0.00 | \$0.00 |
| 3    | ✓ Lights - All             | \$0.00 | \$0.00 | \$0.00 |

**Notes**

mirror lights out rh

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 2,518 hr & 764,789 km |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Mar 3, 2025 | Mar 3, 2025 |     | Mar 5, 2025 8:15 PM | Mar 5, 2025 8:15 PM |

| Line | Task                         |            |            | Parts        | Labor     | Total    |
|------|------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Oil change                 |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                         | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | LF14000 - Cummins oil filter | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | oil 15w-40                   | Kropp Shop |            | 42.0         | \$0.00    | \$0.00   |
| 2    | ✓ change windshield          |            |            | \$0.00       | \$0.00    | \$0.00   |
|      |                              |            |            | Part Cost    |           | \$0.00   |
|      |                              |            |            | Labor        |           | \$0.00   |
|      |                              |            |            | Subtotal     |           | \$0.00   |
|      |                              |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                              |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                              |            |            | Credit       |           | (\$0.00) |
|      |                              |            |            | Total Cost   |           | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 2,676 hr & 772,372 km |

| Type | Created      | Scheduled    | Due | Started               | Closed                |
|------|--------------|--------------|-----|-----------------------|-----------------------|
|      | Mar 14, 2025 | Mar 14, 2025 |     | Mar 14, 2025 11:08 AM | Mar 14, 2025 11:08 AM |

| Line | Task                                | Parts  | Labor  | Total  |
|------|-------------------------------------|--------|--------|--------|
| 1    | ✓ Cab ride height pushing into hood | \$0.00 | \$0.00 | \$0.00 |

**Notes**

Leveling rod separated, put back together and adjust ride height

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

**Work Order 1781**

Nate Vandenberghe

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 2,691 hr & 773,112 km |

| Type | Scheduled    | Due | Started               | Closed                |
|------|--------------|-----|-----------------------|-----------------------|
|      | Mar 17, 2025 |     | Mar 17, 2025 10:40 AM | Mar 17, 2025 10:40 AM |

| Line | Task                           |            |            | Parts        | Labor     | Total    |
|------|--------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Front LH drive brake pot NFG |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                           | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 3030 brake pot                 | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                                |            |            | Part Cost    |           | \$0.00   |
|      |                                |            |            | Labor        |           | \$0.00   |
|      |                                |            |            | Subtotal     |           | \$0.00   |
|      |                                |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                |            |            | Credit       |           | (\$0.00) |
|      |                                |            |            | Total Cost   |           | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

Work Order 1812

Nate Vandenberghe

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 2,768 hr & 776,860 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Mar 22, 2025 | Mar 22, 2025 |     | Mar 22, 2025 3:28 PM | Mar 22, 2025 3:28 PM |

| Line | Task                              |            |            | Parts        | Labor     | Total    |
|------|-----------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Front LH steer center pin broke |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                              | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | Leaf spring center pin            | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | T800 X block                      | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | U bolts                           | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                                   |            |            | Part Cost    |           | \$0.00   |
|      |                                   |            |            | Labor        |           | \$0.00   |
|      |                                   |            |            | Subtotal     |           | \$0.00   |
|      |                                   |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                   |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                   |            |            | Credit       |           | (\$0.00) |
|      |                                   |            |            | Total Cost   |           | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 2,768 hr & 776,860 km |

| Type | Created     | Scheduled   | Due | Started              | Closed               |
|------|-------------|-------------|-----|----------------------|----------------------|
|      | Apr 7, 2025 | Apr 7, 2025 |     | Apr 11, 2025 5:47 AM | Apr 18, 2025 8:37 PM |

| Line | Task                                                        | Parts      | Labor      | Total  |           |        |
|------|-------------------------------------------------------------|------------|------------|--------|-----------|--------|
| 1    | ✓ Grease truck and trailer                                  | \$0.00     | \$0.00     | \$0.00 |           |        |
| 2    | ✓ Preform Scheduled Maintenance                             | \$0.00     | \$0.00     | \$0.00 |           |        |
| 3    | ✓ CVIP inspection (wheels off)                              | \$0.00     | \$0.00     | \$0.00 |           |        |
| 4    | ✓ check diff levels                                         | \$0.00     | \$0.00     | \$0.00 |           |        |
| 5    | ✓ change diff filters                                       | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                                        | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | LF3311 - Rockwell diff filter                               | Kropp Shop |            | 2.0    | \$0.00    | \$0.00 |
| 6    | ✓ transmission oil level                                    | \$0.00     | \$0.00     | \$0.00 |           |        |
| 7    | ✓ crossmember cracked behind air dryer                      | \$0.00     | \$0.00     | \$0.00 |           |        |
| 8    | ✓ middle diff output seal leaking                           | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                                        | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | R945008 - Rockwell output seal                              | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 9    | ✓ RH drag link NFG                                          | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                                        | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | 346-574 - RH drag link T800                                 | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 10   | ✓ fan hub leaking air                                       | \$0.00     | \$0.00     | \$0.00 |           |        |
| 11   | ✓ transmission rattle off gear shift (shift tower bushing?) | \$0.00     | \$0.00     | \$0.00 |           |        |
| 12   | ✓ rear light bar no tail lights                             | \$0.00     | \$0.00     | \$0.00 |           |        |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

|    |                                                                    |            |            |        |           |        |
|----|--------------------------------------------------------------------|------------|------------|--------|-----------|--------|
| 13 | ✓ Tie rod rh nfg                                                   |            |            | \$0.00 | \$0.00    | \$0.00 |
|    | Part                                                               | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | R230073 - Tie rod end                                              | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 14 | ✓ Rear spring pins both sides                                      |            |            | \$0.00 | \$0.00    | \$0.00 |
|    | Part                                                               | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | B13-1002 - Spring pin bushing (T800,T880)                          | Kropp Shop |            | 4.0    | \$0.00    | \$0.00 |
|    | B65-6008 - Rear spring pin (T800,T880)                             | Kropp Shop |            | 4.0    | \$0.00    | \$0.00 |
| 15 | ✓ lh front bump stop broke                                         |            |            | \$0.00 | \$0.00    | \$0.00 |
| 16 | ✓ power steering leak                                              |            |            | \$0.00 | \$0.00    | \$0.00 |
|    | <b>Notes</b>                                                       |            |            |        |           |        |
|    | ORB fitting off of pump O-ring?                                    |            |            |        |           |        |
| 17 | ✓ Hood crossmembers cracked                                        |            |            | \$0.00 | \$0.00    | \$0.00 |
| 18 | ✓ Mv3 valve sticking                                               |            |            | \$0.00 | \$0.00    | \$0.00 |
|    | Part                                                               | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | 800260 - MV-3 valve                                                | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 19 | ✓ LH windshield nfg                                                |            |            | \$0.00 | \$0.00    | \$0.00 |
|    | Part                                                               | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | Windshield LH                                                      | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 20 | ✓ Change air filters                                               |            |            | \$0.00 | \$0.00    | \$0.00 |
|    | Part                                                               | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | air filters                                                        | Kropp Shop |            | 2.0    | \$0.00    | \$0.00 |
| 21 | ✓ Plastic mud flaps and anti sails                                 |            |            | \$0.00 | \$0.00    | \$0.00 |
|    | Part                                                               | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|    | 24" plastic mudflap                                                | Kropp Shop |            | 2.0    | \$0.00    | \$0.00 |
|    | anti sail bracket                                                  | Kropp Shop |            | 2.0    | \$0.00    | \$0.00 |
| 22 | ✓ Lift axle 7 wire plug tire off probably have to make cord longer |            |            | \$0.00 | \$0.00    | \$0.00 |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

|    | Part                                   | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|----|----------------------------------------|------------|------------|--------------|-----------|----------|
|    | 7 wire male plug                       | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
| 23 | ✓ 5th wheel RH riser cracked           |            |            | \$0.00       | \$0.00    | \$0.00   |
| 24 | ✓ 5th wheel pin RH side siezed         |            |            | \$0.00       | \$0.00    | \$0.00   |
| 25 | ✓ Weld beaver tail                     |            |            | \$0.00       | \$0.00    | \$0.00   |
| 26 | ✓ Middle diff wishbone bushing no good |            |            | \$0.00       | \$0.00    | \$0.00   |
|    | Part                                   | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|    | 48100511 - Neway wishbone bushing kit  | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
| 27 | ✓ Complete brake job on all drives     |            |            | \$0.00       | \$0.00    | \$0.00   |
|    | Part                                   | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|    | Brake Drum                             | Kropp Shop |            | 6.0          | \$0.00    | \$0.00   |
|    | Es2 shoe kit                           | Kropp Shop |            | 6.0          | \$0.00    | \$0.00   |
|    |                                        |            |            | Part Cost    |           | \$0.00   |
|    |                                        |            |            | Labor        |           | \$0.00   |
|    |                                        |            |            | Subtotal     |           | \$0.00   |
|    |                                        |            |            | Tax 1 (0.0%) |           | \$0.00   |
|    |                                        |            |            | Tax 2 (0.0%) |           | \$0.00   |
|    |                                        |            |            | Credit       |           | (\$0.00) |
|    |                                        |            |            | Total Cost   |           | \$0.00   |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

Work Order 1896

Cam Nadeau

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 3,022 hr & 791,316 km |

| Type    | Created     | Scheduled   | Due | Started             | Closed              |
|---------|-------------|-------------|-----|---------------------|---------------------|
| Service | Jun 5, 2025 | Jun 5, 2025 |     | Jun 5, 2025 5:12 PM | Jun 5, 2025 5:12 PM |

| Line | Task              | Parts  | Labor  | Total  |
|------|-------------------|--------|--------|--------|
| 1    | ✓ Bent S-cam/tube | \$0.00 | \$0.00 | \$0.00 |

### Notes

#1LHS cam tube assm bent, change component

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

Work Order 1901

Everett Twin

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 3,028 hr & 791,693 km |

| Type | Scheduled   | Due | Started             | Closed              |
|------|-------------|-----|---------------------|---------------------|
|      | Jun 6, 2025 |     | Jun 6, 2025 9:41 AM | Jun 6, 2025 9:41 AM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Grease truck and trailer | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

# 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

**CLOSED**

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 3,029 hr & 791,700 km |

| Type | Created     | Scheduled   | Due | Started              | Closed               |
|------|-------------|-------------|-----|----------------------|----------------------|
|      | Jun 7, 2025 | Jun 7, 2025 |     | Jun 7, 2025 10:30 AM | Jun 7, 2025 10:32 AM |

| Line | Task                            | Parts      | Labor      | Total        |           |          |
|------|---------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Water in fuel light on        | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | <b><u>Notes</u></b>             |            |            |              |           |          |
|      | Broken wire, and not plugged in |            |            |              |           |          |
| 2    | ✓ Steer Tires                   | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                            | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | steer tires                     | Kropp Shop |            | 2.0          | \$0.00    | \$0.00   |
| 3    | ✓ Middle LH s cam u bolt loose  | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                            | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | s cam u bolt                    | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
| 4    | ✓ Coolant leak at water valve   | \$0.00     | \$0.00     | \$0.00       |           |          |
| 5    | ✓ RH west coast mirror nfg      | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                            | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | T800 west coast mirror          | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                                 |            |            | Part Cost    |           | \$0.00   |
|      |                                 |            |            | Labor        |           | \$0.00   |
|      |                                 |            |            | Subtotal     |           | \$0.00   |
|      |                                 |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                 |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                 |            |            | Credit       |           | (\$0.00) |
|      |                                 |            |            | Total Cost   |           | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 3,118 hr & 796,789 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Jun 19, 2025 | Jun 19, 2025 |     | Jun 19, 2025 4:44 PM | Jun 19, 2025 4:44 PM |

| Line | Task               | Parts        | Labor  | Total    |
|------|--------------------|--------------|--------|----------|
| 1    | ✓ Adjust 5th wheel | \$0.00       | \$0.00 | \$0.00   |
|      |                    | Part Cost    |        | \$0.00   |
|      |                    | Labor        |        | \$0.00   |
|      |                    | Subtotal     |        | \$0.00   |
|      |                    | Tax 1 (0.0%) |        | \$0.00   |
|      |                    | Tax 2 (0.0%) |        | \$0.00   |
|      |                    | Credit       |        | (\$0.00) |
|      |                    | Total Cost   |        | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 3,188 hr & 796,789 km |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Jul 3, 2025 | Jul 3, 2025 |     | Jul 3, 2025 8:21 AM | Jul 3, 2025 8:21 AM |

| Line | Task                                     |            |            | Parts        | Labor     | Total    |
|------|------------------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Oil change                             |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                                     | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | LF14000 - Cummins oil filter             | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | FF5825NN - Cummins fuel filter           | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | FS20172 - Cummins water separator filter | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
| 2    | ✓ Grease truck and trailer               |            |            | \$0.00       | \$0.00    | \$0.00   |
|      |                                          |            |            | Part Cost    |           | \$0.00   |
|      |                                          |            |            | Labor        |           | \$0.00   |
|      |                                          |            |            | Subtotal     |           | \$0.00   |
|      |                                          |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                          |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                          |            |            | Credit       |           | (\$0.00) |
|      |                                          |            |            | Total Cost   |           | \$0.00   |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

Work Order 1972

Sam Hawksley

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 3,233 hr & 804,093 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Jul 11, 2025 | Jul 11, 2025 |     | Jul 16, 2025 8:09 AM | Jul 16, 2025 8:09 AM |

| Line | Task               | Parts        | Labor  | Total    |
|------|--------------------|--------------|--------|----------|
| 1    | ✓ 5th wheel adjust | \$0.00       | \$0.00 | \$0.00   |
|      |                    | Part Cost    |        | \$0.00   |
|      |                    | Labor        |        | \$0.00   |
|      |                    | Subtotal     |        | \$0.00   |
|      |                    | Tax 1 (0.0%) |        | \$0.00   |
|      |                    | Tax 2 (0.0%) |        | \$0.00   |
|      |                    | Credit       |        | (\$0.00) |
|      |                    | Total Cost   |        | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 3,412 hr & 816,792 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Aug 18, 2025 | Aug 18, 2025 |     | Aug 18, 2025 5:53 PM | Aug 18, 2025 5:53 PM |

| Line | Task                |            |            | Parts        | Labor     | Total    |
|------|---------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ change windshield |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | Windshield LH       | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | windshield RH       | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                     |            |            | Part Cost    |           | \$0.00   |
|      |                     |            |            | Labor        |           | \$0.00   |
|      |                     |            |            | Subtotal     |           | \$0.00   |
|      |                     |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                     |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                     |            |            | Credit       |           | (\$0.00) |
|      |                     |            |            | Total Cost   |           | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

Work Order 2073

Sam Hawksley

# CLOSED

| Serial            | Tag    | Closed Meters           |
|-------------------|--------|-------------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 3,437.7 hr & 818,584 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Aug 22, 2025 | Aug 22, 2025 |     | Aug 22, 2025 3:29 PM | Aug 22, 2025 3:41 PM |

| Line | Task                     | Parts        | Labor  | Total    |
|------|--------------------------|--------------|--------|----------|
| 1    | ✓ Coolant leak           | \$0.00       | \$0.00 | \$0.00   |
| 2    | ✓ Loose steering u joint | \$0.00       | \$0.00 | \$0.00   |
| 3    | ✓ Top off dif            | \$0.00       | \$0.00 | \$0.00   |
| 4    | ✓ Air line rubbage       | \$0.00       | \$0.00 | \$0.00   |
| 5    | ✓ Snipe holder           | \$0.00       | \$0.00 | \$0.00   |
|      |                          | Part Cost    |        | \$0.00   |
|      |                          | Labor        |        | \$0.00   |
|      |                          | Subtotal     |        | \$0.00   |
|      |                          | Tax 1 (0.0%) |        | \$0.00   |
|      |                          | Tax 2 (0.0%) |        | \$0.00   |
|      |                          | Credit       |        | (\$0.00) |
|      |                          | Total Cost   |        | \$0.00   |

# 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 3,445 hr & 819,137 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Aug 25, 2025 | Aug 25, 2025 |     | Aug 25, 2025 4:40 PM | Aug 25, 2025 5:11 PM |

| Line | Task                                     | Parts      | Labor      | Total  |           |        |
|------|------------------------------------------|------------|------------|--------|-----------|--------|
| 1    | ✓ Grease truck and trailer               | \$0.00     | \$0.00     | \$0.00 |           |        |
| 2    | ✓ Replace radiator                       | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                     | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | t800 radiator                            | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
|      | Coolant                                  | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 3    | ✓ Exhaust leaks                          | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                     | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | M66-2920 - 4" exhaust pipe turbo-bellows | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
|      | 2866636 - 4" exhaust gasket              | Kropp Shop |            | 2.0    | \$0.00    | \$0.00 |
|      | 90-0012 - 4" v clamp                     | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 4    | ✓ loose yoke on diff                     | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <b><u>Notes</u></b>                      |            |            |        |           |        |
|      | Front diff output yolk loose             |            |            |        |           |        |
| 5    | ✓ Loose center bearing yolk              | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                     | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | SPL250 Strap - SPL 250 Strap Kit         | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 3,710 hr & 836,851 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Oct 11, 2025 | Oct 11, 2025 |     | Oct 11, 2025 3:38 PM | Oct 11, 2025 3:38 PM |

| Line | Task                                     | Parts        | Labor      | Total  |           |          |
|------|------------------------------------------|--------------|------------|--------|-----------|----------|
| 1    | ✓ Grease truck and trailer               | \$0.00       | \$0.00     | \$0.00 |           |          |
| 2    | ✓ Preform Scheduled Maintenance          | \$0.00       | \$0.00     | \$0.00 |           |          |
| 3    | ✓ Oil change                             | \$0.00       | \$0.00     | \$0.00 |           |          |
|      | Part                                     | Warehouse    | Vendor/Bin | Qty    | Unit Cost | Cost     |
|      | LF14000 - Cummins oil filter             | Kropp Shop   |            | 1.0    | \$0.00    | \$0.00   |
|      | FF5825NN - Cummins fuel filter           | Kropp Shop   |            | 1.0    | \$0.00    | \$0.00   |
|      | FS20172 - Cummins water separator filter | Kropp Shop   |            | 1.0    | \$0.00    | \$0.00   |
|      | oil 15w-40                               | Kropp Shop   |            | 1.0    | \$0.00    | \$0.00   |
| 4    | ✓ Drive tires (set of 12)                | \$0.00       | \$0.00     | \$0.00 |           |          |
|      |                                          | Part Cost    |            |        |           | \$0.00   |
|      |                                          | Labor        |            |        |           | \$0.00   |
|      |                                          | Subtotal     |            |        |           | \$0.00   |
|      |                                          | Tax 1 (0.0%) |            |        |           | \$0.00   |
|      |                                          | Tax 2 (0.0%) |            |        |           | \$0.00   |
|      |                                          | Credit       |            |        |           | (\$0.00) |
|      |                                          | Total Cost   |            |        |           | \$0.00   |

# 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 3,710 hr & 836,851 km |

| Type | Created      | Scheduled    | Due | Started               | Closed                |
|------|--------------|--------------|-----|-----------------------|-----------------------|
|      | Oct 13, 2025 | Oct 13, 2025 |     | Oct 13, 2025 12:02 PM | Oct 13, 2025 12:04 PM |

| Line | Task                                   | Parts      | Labor      | Total        |           |          |
|------|----------------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ dash buttons pushed in               | \$0.00     | \$0.00     | \$0.00       |           |          |
| 2    | ✓ top RH headache rack oval out        | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                                   | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 6050 - Oval Red light                  | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
| 3    | ✓ check air leaks                      | \$0.00     | \$0.00     | \$0.00       |           |          |
| 4    | ✓ RH middle drive ABS WSS code         | \$0.00     | \$0.00     | \$0.00       |           |          |
| 5    | ✓ differential pressure sensor shorted | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                                   | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 5492073 - Dfn pressure sensor          | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                                        |            |            | Part Cost    |           | \$0.00   |
|      |                                        |            |            | Labor        |           | \$0.00   |
|      |                                        |            |            | Subtotal     |           | \$0.00   |
|      |                                        |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                        |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                        |            |            | Credit       |           | (\$0.00) |
|      |                                        |            |            | Total Cost   |           | \$0.00   |

| Fault Code | Status   | Count | Lamp        | Description                                                                                                                     | PID | SD | J1587 FMI | J1939 FMI | SPN |
|------------|----------|-------|-------------|---------------------------------------------------------------------------------------------------------------------------------|-----|----|-----------|-----------|-----|
| 1117       | Inactive | 1     | None        | Power Supply Lost With Ignition On - Data Erratic, Intermittent, or Incorrect                                                   | 251 | 2  | 2         | 3597      |     |
| 1881       | Inactive | 3     | Amber       | Aftertreatment 1 Diesel Particulate Filter Differential Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source | 324 | 4  | 4         | 3251      |     |
| 1883       | Active   | 1     | Amber       | Aftertreatment 1 Diesel Particulate Filter Differential Pressure - Data Erratic, Intermittent, or Incorrect                     | 324 | 2  | 2         | 3251      |     |
| 2645       | Inactive | 1     | Amber       | Engine Coolant Temperature - Condition Fault                                                                                    | 110 | 14 | 31        | 110       |     |
| 2983       | Inactive | 1     | None        | Engine Coolant Temperature - Data Valid But Above Normal Operating Range - Level 1 Sensor Level                                 | 110 | 0  | 15        | 110       |     |
| 3134       | Inactive | 790   | Amber       | Aftertreatment 1 Diesel Particulate Filter Outlet Pressure Sensor Circuit - Voltage Below Normal or Shorted to Low Source       | 4   | 4  | 4         | 3610      |     |
| 3135       | Active   | 1     | Amber       | Aftertreatment 1 Diesel Particulate Filter Outlet Pressure - Data Erratic, Intermittent, or Incorrect                           | 2   | 2  | 2         | 3610      |     |
| 3423       | Inactive | 2     | Amber       | Aftertreatment 1 Diesel Exhaust Fluid Low Heater 3 Circuit - Voltage Below Normal or Shorted to Low Source                      | 4   | 4  | 4         | 4344      |     |
| 3497       | Inactive | 2     | Maintenance | Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Data Valid But Below Normal Operating Range - Level 1 Sensor Level           | 1   | 17 | 17        | 1761      |     |
| 3498       | Inactive | 1     | Maintenance | Aftertreatment 1 Diesel Exhaust Fluid Tank Level - Data Valid But Below Normal Operating Range - Moderately Severe Level        | 1   | 18 | 18        | 1761      |     |
| 6255       | Inactive | 1     | None        | Engine Protection Temp Sensor - Data Valid But Above Normal Operating Range - Level 1 Sensor Level                              | 0   | 15 | 15        | 1559      |     |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

**Work Order 2203**  
Aiden Kenny, Everett Twin  
**CLOSED**

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 3,710 hr & 836,851 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Oct 21, 2025 | Oct 21, 2025 |     | Oct 22, 2025 4:23 PM | Oct 22, 2025 4:23 PM |

| Line | Task                 | Parts        | Labor  | Total    |
|------|----------------------|--------------|--------|----------|
| 1    | ✓ T rail bolts loose | \$0.00       | \$0.00 | \$0.00   |
|      |                      | Part Cost    |        | \$0.00   |
|      |                      | Labor        |        | \$0.00   |
|      |                      | Subtotal     |        | \$0.00   |
|      |                      | Tax 1 (0.0%) |        | \$0.00   |
|      |                      | Tax 2 (0.0%) |        | \$0.00   |
|      |                      | Credit       |        | (\$0.00) |
|      |                      | Total Cost   |        | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 3,802 hr & 842,187 km |

| Type | Created      | Scheduled    | Due | Started              | Closed              |
|------|--------------|--------------|-----|----------------------|---------------------|
|      | Oct 30, 2025 | Oct 30, 2025 |     | Oct 31, 2025 9:19 AM | Nov 4, 2025 5:03 PM |

| Line | Task                                         | Parts      | Labor      | Total        |           |          |
|------|----------------------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ No heat                                    | \$0.00     | \$0.00     | \$0.00       |           |          |
| 2    | ✓ Fan always on                              | \$0.00     | \$0.00     | \$0.00       |           |          |
| 3    | ✓ Coolant leak                               | \$0.00     | \$0.00     | \$0.00       |           |          |
| 4    | ✓ Drag link                                  | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                                         | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 346-572 - LH drag link T800                  | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
| 5    | ✓ Transmission noise                         | \$0.00     | \$0.00     | \$0.00       |           |          |
| 6    | ✓ Middle right hand headache light no blinky | \$0.00     | \$0.00     | \$0.00       |           |          |
| 7    | ✓ Purge valve                                | \$0.00     | \$0.00     | \$0.00       |           |          |
| 8    | ✓ Grease truck and trailer                   | \$0.00     | \$0.00     | \$0.00       |           |          |
|      |                                              |            |            | Part Cost    |           | \$0.00   |
|      |                                              |            |            | Labor        |           | \$0.00   |
|      |                                              |            |            | Subtotal     |           | \$0.00   |
|      |                                              |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                              |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                              |            |            | Credit       |           | (\$0.00) |
|      |                                              |            |            | Total Cost   |           | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 3,837 hr & 844,223 km |

| Type | Created      | Scheduled    | Due | Started               | Closed               |
|------|--------------|--------------|-----|-----------------------|----------------------|
|      | Nov 12, 2025 | Nov 12, 2025 |     | Nov 12, 2025 11:23 AM | Nov 12, 2025 2:56 PM |

| Line                        | Task                                                                                                                                                                                                                                     | Parts      | Labor     | Total      |        |           |      |                             |            |  |     |        |        |  |  |  |
|-----------------------------|------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------------|------------|-----------|------------|--------|-----------|------|-----------------------------|------------|--|-----|--------|--------|--|--|--|
| 1                           | ✓ Battery                                                                                                                                                                                                                                | \$0.00     | \$0.00    | \$0.00     |        |           |      |                             |            |  |     |        |        |  |  |  |
|                             | <u>Notes</u>                                                                                                                                                                                                                             |            |           |            |        |           |      |                             |            |  |     |        |        |  |  |  |
|                             | Started hard                                                                                                                                                                                                                             |            |           |            |        |           |      |                             |            |  |     |        |        |  |  |  |
|                             | <table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>Group 31S battery</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table>           | Part       | Warehouse | Vendor/Bin | Qty    | Unit Cost | Cost | Group 31S battery           | Kropp Shop |  | 1.0 | \$0.00 | \$0.00 |  |  |  |
| Part                        | Warehouse                                                                                                                                                                                                                                | Vendor/Bin | Qty       | Unit Cost  | Cost   |           |      |                             |            |  |     |        |        |  |  |  |
| Group 31S battery           | Kropp Shop                                                                                                                                                                                                                               |            | 1.0       | \$0.00     | \$0.00 |           |      |                             |            |  |     |        |        |  |  |  |
| 2                           | ✓ Check all fluid levels                                                                                                                                                                                                                 | \$0.00     | \$0.00    | \$0.00     |        |           |      |                             |            |  |     |        |        |  |  |  |
|                             | <u>Notes</u>                                                                                                                                                                                                                             |            |           |            |        |           |      |                             |            |  |     |        |        |  |  |  |
|                             | Hockey stick 90 leaking                                                                                                                                                                                                                  |            |           |            |        |           |      |                             |            |  |     |        |        |  |  |  |
|                             | Coolant low                                                                                                                                                                                                                              |            |           |            |        |           |      |                             |            |  |     |        |        |  |  |  |
| 3                           | ✓ Clutch                                                                                                                                                                                                                                 | \$0.00     | \$0.00    | \$0.00     |        |           |      |                             |            |  |     |        |        |  |  |  |
|                             | <u>Notes</u>                                                                                                                                                                                                                             |            |           |            |        |           |      |                             |            |  |     |        |        |  |  |  |
|                             | Adjust clutch                                                                                                                                                                                                                            |            |           |            |        |           |      |                             |            |  |     |        |        |  |  |  |
| 4                           | ✓ Engine                                                                                                                                                                                                                                 | \$0.00     | \$0.00    | \$0.00     |        |           |      |                             |            |  |     |        |        |  |  |  |
|                             | <u>Notes</u>                                                                                                                                                                                                                             |            |           |            |        |           |      |                             |            |  |     |        |        |  |  |  |
|                             | Crankcase breather tube broke                                                                                                                                                                                                            |            |           |            |        |           |      |                             |            |  |     |        |        |  |  |  |
| 5                           | ✓ Lights - All                                                                                                                                                                                                                           | \$0.00     | \$0.00    | \$0.00     |        |           |      |                             |            |  |     |        |        |  |  |  |
|                             | <u>Notes</u>                                                                                                                                                                                                                             |            |           |            |        |           |      |                             |            |  |     |        |        |  |  |  |
|                             | Top rh MM light broke                                                                                                                                                                                                                    |            |           |            |        |           |      |                             |            |  |     |        |        |  |  |  |
|                             | <table><tr><th>Part</th><th>Warehouse</th><th>Vendor/Bin</th><th>Qty</th><th>Unit Cost</th><th>Cost</th></tr><tr><td>Mickey mouse light box assy</td><td>Kropp Shop</td><td></td><td>1.0</td><td>\$0.00</td><td>\$0.00</td></tr></table> | Part       | Warehouse | Vendor/Bin | Qty    | Unit Cost | Cost | Mickey mouse light box assy | Kropp Shop |  | 1.0 | \$0.00 | \$0.00 |  |  |  |
| Part                        | Warehouse                                                                                                                                                                                                                                | Vendor/Bin | Qty       | Unit Cost  | Cost   |           |      |                             |            |  |     |        |        |  |  |  |
| Mickey mouse light box assy | Kropp Shop                                                                                                                                                                                                                               |            | 1.0       | \$0.00     | \$0.00 |           |      |                             |            |  |     |        |        |  |  |  |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

**Work Order 2247**  
Sam Hawksley, Terren Page  
**CLOSED**

|   |                |        |        |        |
|---|----------------|--------|--------|--------|
| 6 | ✓ Transmission | \$0.00 | \$0.00 | \$0.00 |
|---|----------------|--------|--------|--------|

**Notes**

Top shift tower boot

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 3,871 hr & 846,151 km |

| Type | Created      | Scheduled    | Due | Started               | Closed                |
|------|--------------|--------------|-----|-----------------------|-----------------------|
|      | Nov 17, 2025 | Nov 17, 2025 |     | Nov 18, 2025 12:54 PM | Nov 18, 2025 12:54 PM |

| Line | Task                         |            |            | Parts        | Labor     | Total    |
|------|------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Fan hub staying engaged    |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                         | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 79A9782 - Horton Fan hub     | Kropp Shop | EKW        | 1.0          | \$0.00    | \$0.00   |
| 2    | ✓ Fan belt tensioner no good |            |            | \$0.00       | \$0.00    | \$0.00   |
|      |                              |            |            | Part Cost    |           | \$0.00   |
|      |                              |            |            | Labor        |           | \$0.00   |
|      |                              |            |            | Subtotal     |           | \$0.00   |
|      |                              |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                              |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                              |            |            | Credit       |           | (\$0.00) |
|      |                              |            |            | Total Cost   |           | \$0.00   |

# 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 4,013 hr & 854,110 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Nov 28, 2025 | Nov 28, 2025 |     | Nov 29, 2025 5:53 AM | Nov 29, 2025 5:53 AM |

| Line | Task                                                                          | Parts        | Labor  | Total    |
|------|-------------------------------------------------------------------------------|--------------|--------|----------|
| 1    | ✓ Driveline<br><br><u>Notes</u><br>first diff input yoke needs a shim removed | \$0.00       | \$0.00 | \$0.00   |
| 2    | ✓ Frame & Assembly<br><br><u>Notes</u><br>rh t rail bolt                      | \$0.00       | \$0.00 | \$0.00   |
| 3    | ✓ Mirrors<br><br><u>Notes</u><br>rh west coast nfg, lh convex nfg             | \$0.00       | \$0.00 | \$0.00   |
| 4    | ✓ Windshield Wipers<br><br><u>Notes</u><br>LH wiper nfg                       | \$0.00       | \$0.00 | \$0.00   |
| 5    | ✓ new seat to install                                                         | \$0.00       | \$0.00 | \$0.00   |
| 6    | ✓ coolant leaks                                                               | \$0.00       | \$0.00 | \$0.00   |
| 7    | ✓ Grease truck and trailer                                                    | \$0.00       | \$0.00 | \$0.00   |
|      |                                                                               | Part Cost    |        | \$0.00   |
|      |                                                                               | Labor        |        | \$0.00   |
|      |                                                                               | Subtotal     |        | \$0.00   |
|      |                                                                               | Tax 1 (0.0%) |        | \$0.00   |
|      |                                                                               | Tax 2 (0.0%) |        | \$0.00   |
|      |                                                                               | Credit       |        | (\$0.00) |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

**Work Order 2306**

Trent Court

# CLOSED

Total Cost

\$0.00

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 4,013 hr & 854,110 km |

| Type | Created     | Scheduled   | Due | Started             | Closed              |
|------|-------------|-------------|-----|---------------------|---------------------|
|      | Dec 5, 2025 | Dec 5, 2025 |     | Dec 5, 2025 6:23 PM | Dec 5, 2025 6:23 PM |

| Line | Task | Parts | Labor | Total |
|------|------|-------|-------|-------|
|------|------|-------|-------|-------|

|   |                                 |        |        |        |
|---|---------------------------------|--------|--------|--------|
| 1 | ✓ Engine fan cutting in and out | \$0.00 | \$0.00 | \$0.00 |
|---|---------------------------------|--------|--------|--------|

**Notes**

Test drove and found AC pressure switch trigger fan... pulled fuse to ac and problem went away chafed wire along harness

|   |                                  |        |        |        |
|---|----------------------------------|--------|--------|--------|
| 2 | ✓ Speedometer cutting in and out | \$0.00 | \$0.00 | \$0.00 |
|---|----------------------------------|--------|--------|--------|

**Notes**

Rear output yoke loose and tone ring not spinning

|   |                              |        |        |        |
|---|------------------------------|--------|--------|--------|
| 3 | ✓ Both high beam bulbs broke | \$0.00 | \$0.00 | \$0.00 |
|---|------------------------------|--------|--------|--------|

| Part         | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost   |
|--------------|------------|------------|-----|-----------|--------|
| 2 prong bulb | Kropp Shop |            | 2.0 | \$0.00    | \$0.00 |

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

# 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 4,185 hr & 863,032 km |

| Type | Created     | Scheduled   | Due | Started              | Closed               |
|------|-------------|-------------|-----|----------------------|----------------------|
|      | Dec 9, 2025 | Dec 9, 2025 |     | Dec 13, 2025 4:17 PM | Dec 13, 2025 4:17 PM |

| Line | Task                                     |            |            | Parts        | Labor     | Total    |
|------|------------------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Oil change                             |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                                     | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | LF14000 - Cummins oil filter             | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | oil 15w-40                               | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | FS20172 - Cummins water separator filter | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      | FF5825NN - Cummins fuel filter           | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
| 2    | ✓ Jump AC fan switch                     |            |            | \$0.00       | \$0.00    | \$0.00   |
| 3    | ✓ Replace broken bellows pipe            |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                                     | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | EBPB11861 - Bellows kit                  | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                                          |            |            | Part Cost    |           | \$0.00   |
|      |                                          |            |            | Labor        |           | \$0.00   |
|      |                                          |            |            | Subtotal     |           | \$0.00   |
|      |                                          |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                                          |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                                          |            |            | Credit       |           | (\$0.00) |
|      |                                          |            |            | Total Cost   |           | \$0.00   |

# 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 4,185 hr & 863,032 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Dec 13, 2025 | Dec 13, 2025 |     | Dec 13, 2025 4:17 PM | Dec 13, 2025 4:17 PM |

| Line | Task                                             | Parts  | Labor  | Total  |
|------|--------------------------------------------------|--------|--------|--------|
| 1    | ✓ Air Compressor                                 | \$0.00 | \$0.00 | \$0.00 |
|      | <b><u>Notes</u></b>                              |        |        |        |
|      | purge valve leaking air after purge              |        |        |        |
| 2    | ✓ Engine                                         | \$0.00 | \$0.00 | \$0.00 |
|      | <b><u>Notes</u></b>                              |        |        |        |
|      | loose exhaust clamp behind turbo to bellows      |        |        |        |
| 3    | ✓ Exhaust                                        | \$0.00 | \$0.00 | \$0.00 |
|      | <b><u>Notes</u></b>                              |        |        |        |
|      | RH stack loose                                   |        |        |        |
| 4    | ✓ Frame & Assembly                               | \$0.00 | \$0.00 | \$0.00 |
|      | <b><u>Notes</u></b>                              |        |        |        |
|      | front lh drive mudflap loose                     |        |        |        |
| 5    | ✓ Grease truck and trailer                       | \$0.00 | \$0.00 | \$0.00 |
| 6    | ✓ Lights - All                                   | \$0.00 | \$0.00 | \$0.00 |
|      | <b><u>Notes</u></b>                              |        |        |        |
|      | top LH work light out, rear skirt ling no signal |        |        |        |
| 7    | ✓ Other                                          | \$0.00 | \$0.00 | \$0.00 |
|      | <b><u>Notes</u></b>                              |        |        |        |
|      | rear leveling valve loose                        |        |        |        |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

Work Order 2359

Sam Hawksley

CLOSED

|   |            |        |        |        |
|---|------------|--------|--------|--------|
| 8 | ✓ Radiator | \$0.00 | \$0.00 | \$0.00 |
|---|------------|--------|--------|--------|

**Notes**

hockey stick 90 hose leaking above hose clamp

|   |         |        |        |        |
|---|---------|--------|--------|--------|
| 9 | ✓ Tires | \$0.00 | \$0.00 | \$0.00 |
|---|---------|--------|--------|--------|

**Notes**

lh rear drive outside flat

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 4,185 hr & 863,032 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Dec 17, 2025 | Dec 17, 2025 |     | Dec 19, 2025 9:11 AM | Dec 19, 2025 9:11 AM |

| Line | Task                         | Parts  | Labor  | Total  |
|------|------------------------------|--------|--------|--------|
| 1    | ✓ Def pressure too high code | \$0.00 | \$0.00 | \$0.00 |

### Notes

Def pressure test reading at -13 psi

| Part              | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost     |
|-------------------|------------|------------|-----|-----------|----------|
| 5578983RX - Doser | Kropp Shop | EKW        | 1.0 | \$0.00    | \$0.00   |
| Part Cost         |            |            |     |           | \$0.00   |
| Labor             |            |            |     |           | \$0.00   |
| Subtotal          |            |            |     |           | \$0.00   |
| Tax 1 (0.0%)      |            |            |     |           | \$0.00   |
| Tax 2 (0.0%)      |            |            |     |           | \$0.00   |
| Credit            |            |            |     |           | (\$0.00) |
| Total Cost        |            |            |     |           | \$0.00   |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

Work Order 2398

Trent Court

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 4,185 hr & 863,032 km |

| Type | Created      | Scheduled    | Due | Started             | Closed              |
|------|--------------|--------------|-----|---------------------|---------------------|
|      | Dec 21, 2025 | Dec 21, 2025 |     | Jan 4, 2026 8:17 AM | Jan 4, 2026 8:17 AM |

| Line | Task                       | Parts        | Labor  | Total    |
|------|----------------------------|--------------|--------|----------|
| 1    | ✓ Blower motor not working | \$0.00       | \$0.00 | \$0.00   |
|      |                            | Part Cost    |        | \$0.00   |
|      |                            | Labor        |        | \$0.00   |
|      |                            | Subtotal     |        | \$0.00   |
|      |                            | Tax 1 (0.0%) |        | \$0.00   |
|      |                            | Tax 2 (0.0%) |        | \$0.00   |
|      |                            | Credit       |        | (\$0.00) |
|      |                            | Total Cost   |        | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 4,489 hr & 878,302 km |

| Type | Created      | Scheduled    | Due | Started               | Closed               |
|------|--------------|--------------|-----|-----------------------|----------------------|
|      | Jan 15, 2026 | Jan 15, 2026 |     | Jan 15, 2026 12:20 PM | Jan 15, 2026 3:59 PM |

| Line | Task                                              | Parts      | Labor      | Total  |           |        |
|------|---------------------------------------------------|------------|------------|--------|-----------|--------|
| 1    | ✓ Hockey hose coolant leak                        | \$0.00     | \$0.00     | \$0.00 |           |        |
| 2    | ✓ First Dif filter cover missing and missing bolt | \$0.00     | \$0.00     | \$0.00 |           |        |
| 3    | ✓ Second diff leaking                             | \$0.00     | \$0.00     | \$0.00 |           |        |
| 4    | ✓ First diff airline rubbing diff                 | \$0.00     | \$0.00     | \$0.00 |           |        |
| 5    | ✓ Work light out top left                         | \$0.00     | \$0.00     | \$0.00 |           |        |
| 6    | ✓ Drivers mirror heat                             | \$0.00     | \$0.00     | \$0.00 |           |        |
| 7    | ✓ Battery box rattle                              | \$0.00     | \$0.00     | \$0.00 |           |        |
| 8    | ✓ Good bushing                                    | \$0.00     | \$0.00     | \$0.00 |           |        |
| 9    | ✓ Passenger wiper                                 | \$0.00     | \$0.00     | \$0.00 |           |        |
| 10   | ✓ Tighten micky mouse light                       | \$0.00     | \$0.00     | \$0.00 |           |        |
| 11   | ✓ Oil change                                      | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                              | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | LF14000 - Cummins oil filter                      | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 12   | ✓ Grease truck and trailer                        | \$0.00     | \$0.00     | \$0.00 |           |        |
| 13   | ✓ Fix roof                                        | \$0.00     | \$0.00     | \$0.00 |           |        |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

**Work Order 2451**  
Sam Hawksley, Trent Court

# CLOSED

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 4,657 hr & 887,960 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Jan 30, 2026 | Jan 30, 2026 |     | Jan 30, 2026 3:29 PM | Jan 30, 2026 6:40 PM |

| Line | Task                             | Parts      | Labor      | Total  |           |        |
|------|----------------------------------|------------|------------|--------|-----------|--------|
| 1    | ✓ Body                           | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <u>Notes</u>                     |            |            |        |           |        |
|      | grill bar loose                  |            |            |        |           |        |
| 2    | ✓ Frame & Assembly               | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <u>Notes</u>                     |            |            |        |           |        |
|      | T rail bolts loose LH side front |            |            |        |           |        |
| 3    | ✓ Lights - All                   | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <u>Notes</u>                     |            |            |        |           |        |
|      | lh rear lightbar out             |            |            |        |           |        |
|      | Part                             | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | 3 wire pigtail                   | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 4    | ✓ Rear End                       | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <u>Notes</u>                     |            |            |        |           |        |
|      | front diff oil leak              |            |            |        |           |        |
| 5    | ✓ Windows                        | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | <u>Notes</u>                     |            |            |        |           |        |
|      | LH windshield cracked            |            |            |        |           |        |
| 6    | ✓ Grease truck and trailer       | \$0.00     | \$0.00     | \$0.00 |           |        |
| 7    | ✓ Weld LH rear fender bracket    | \$0.00     | \$0.00     | \$0.00 |           |        |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

**Work Order 2487**  
Trent Court, Sam Hawksley  
**CLOSED**

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 4,657 hr & 894,000 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Feb 12, 2026 | Feb 12, 2026 |     | Feb 12, 2026 8:05 PM | Feb 12, 2026 8:05 PM |

| Line | Task                      | Parts      | Labor      | Total        |           |          |
|------|---------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Steer Tires             | \$0.00     | \$0.00     | \$0.00       |           |          |
| 2    | ✓ LH spring broke         | \$0.00     | \$0.00     | \$0.00       |           |          |
|      | Part                      | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | 59-576 - T800 spring pack | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                           |            |            | Part Cost    |           | \$0.00   |
|      |                           |            |            | Labor        |           | \$0.00   |
|      |                           |            |            | Subtotal     |           | \$0.00   |
|      |                           |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                           |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                           |            |            | Credit       |           | (\$0.00) |
|      |                           |            |            | Total Cost   |           | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 4,791 hr & 895,042 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Feb 13, 2026 | Feb 13, 2026 |     | Feb 13, 2026 1:12 PM | Feb 13, 2026 5:25 PM |

| Line         | Task                                                | Parts  | Labor  | Total    |
|--------------|-----------------------------------------------------|--------|--------|----------|
| 1            | ✓ ABS codes                                         | \$0.00 | \$0.00 | \$0.00   |
|              | <b>Notes</b>                                        |        |        |          |
|              | Middle LH drive broken wire                         |        |        |          |
| 2            | ✓ Grease truck and trailer                          | \$0.00 | \$0.00 | \$0.00   |
| 3            | ✓ Lights - All                                      | \$0.00 | \$0.00 | \$0.00   |
|              | <b>Notes</b>                                        |        |        |          |
|              | Back LH tail light bar bulb change                  |        |        |          |
| 4            | ✓ High beam bulbs broke                             | \$0.00 | \$0.00 | \$0.00   |
| 5            | ✓ Top left hand making most light marker wire short | \$0.00 | \$0.00 | \$0.00   |
| Part Cost    |                                                     |        |        | \$0.00   |
| Labor        |                                                     |        |        | \$0.00   |
| Subtotal     |                                                     |        |        | \$0.00   |
| Tax 1 (0.0%) |                                                     |        |        | \$0.00   |
| Tax 2 (0.0%) |                                                     |        |        | \$0.00   |
| Credit       |                                                     |        |        | (\$0.00) |
| Total Cost   |                                                     |        |        | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 4,902 hr & 895,042 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | Feb 22, 2026 | Feb 22, 2026 |     | Feb 22, 2026 9:28 AM | Feb 22, 2026 9:28 AM |

| Line | Task                         |            |            | Parts        | Labor     | Total    |
|------|------------------------------|------------|------------|--------------|-----------|----------|
| 1    | ✓ Oil change                 |            |            | \$0.00       | \$0.00    | \$0.00   |
|      | Part                         | Warehouse  | Vendor/Bin | Qty          | Unit Cost | Cost     |
|      | LF14000 - Cummins oil filter | Kropp Shop |            | 1.0          | \$0.00    | \$0.00   |
|      |                              |            |            | Part Cost    |           | \$0.00   |
|      |                              |            |            | Labor        |           | \$0.00   |
|      |                              |            |            | Subtotal     |           | \$0.00   |
|      |                              |            |            | Tax 1 (0.0%) |           | \$0.00   |
|      |                              |            |            | Tax 2 (0.0%) |           | \$0.00   |
|      |                              |            |            | Credit       |           | (\$0.00) |
|      |                              |            |            | Total Cost   |           | \$0.00   |

# 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

# CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 4,974 hr & 903,054 km |

| Type | Created      | Scheduled    | Due | Started             | Closed              |
|------|--------------|--------------|-----|---------------------|---------------------|
|      | Feb 27, 2026 | Feb 27, 2026 |     | Mar 1, 2026 1:30 PM | Mar 1, 2026 1:30 PM |

| Line | Task                       | Parts  | Labor  | Total  |
|------|----------------------------|--------|--------|--------|
| 1    | ✓ Engine                   | \$0.00 | \$0.00 | \$0.00 |
|      | <b><u>Notes</u></b>        |        |        |        |
|      | Bellows pipe clamp loose   |        |        |        |
| 2    | ✓ Exhaust                  | \$0.00 | \$0.00 | \$0.00 |
|      | <b><u>Notes</u></b>        |        |        |        |
|      | Rh stack clamp loose       |        |        |        |
| 3    | ✓ Front Axle               | \$0.00 | \$0.00 | \$0.00 |
|      | <b><u>Notes</u></b>        |        |        |        |
|      | Rh spring weak             |        |        |        |
| 4    | ✓ Grease truck and trailer | \$0.00 | \$0.00 | \$0.00 |
| 5    | ✓ Lights - All             | \$0.00 | \$0.00 | \$0.00 |
|      | <b><u>Notes</u></b>        |        |        |        |
|      | Top rh work light          |        |        |        |
| 6    | ✓ Steering System          | \$0.00 | \$0.00 | \$0.00 |
|      | <b><u>Notes</u></b>        |        |        |        |
|      | Steering whine             |        |        |        |

Kropp Contracting  
Shop

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

**Work Order 2597**

Trent Court

# CLOSED

|              |          |
|--------------|----------|
| Part Cost    | \$0.00   |
| Labor        | \$0.00   |
| Subtotal     | \$0.00   |
| Tax 1 (0.0%) | \$0.00   |
| Tax 2 (0.0%) | \$0.00   |
| Credit       | (\$0.00) |
| Total Cost   | \$0.00   |

# 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 4,974 hr & 903,054 km |

| Type | Created      | Scheduled    | Due | Started              | Closed               |
|------|--------------|--------------|-----|----------------------|----------------------|
|      | May 19, 2026 | May 19, 2026 |     | May 21, 2026 5:22 PM | May 27, 2026 6:54 AM |

| Line | Task                                      | Parts      | Labor      | Total  |           |        |
|------|-------------------------------------------|------------|------------|--------|-----------|--------|
| 1    | ✓ CVIP inspection (wheels off)            | \$0.00     | \$0.00     | \$0.00 |           |        |
| 2    | ✓ Preform Scheduled Maintenance           | \$0.00     | \$0.00     | \$0.00 |           |        |
| 3    | ✓ Air filters                             | \$0.00     | \$0.00     | \$0.00 |           |        |
| 4    | ✓ change diff filters                     | \$0.00     | \$0.00     | \$0.00 |           |        |
| 5    | ✓ change belts                            | \$0.00     | \$0.00     | \$0.00 |           |        |
| 6    | ✓ windshields nfg                         | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                      | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | Windshield LH                             | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
|      | windshield RH                             | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 7    | ✓ lh battery box cover loose              | \$0.00     | \$0.00     | \$0.00 |           |        |
| 8    | ✓ coolant level sensor                    | \$0.00     | \$0.00     | \$0.00 |           |        |
| 9    | ✓ steering shaft loose                    | \$0.00     | \$0.00     | \$0.00 |           |        |
| 10   | ✓ power steering whine                    | \$0.00     | \$0.00     | \$0.00 |           |        |
|      | Part                                      | Warehouse  | Vendor/Bin | Qty    | Unit Cost | Cost   |
|      | Sp33126 - TRP power steering pump Cummins | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
|      | Capital gear steering box                 | Kropp Shop |            | 1.0    | \$0.00    | \$0.00 |
| 11   | ✓ middle diff output seal                 | \$0.00     | \$0.00     | \$0.00 |           |        |
| 12   | ✓ front diff input seal                   | \$0.00     | \$0.00     | \$0.00 |           |        |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

# CLOSED

|    |                                                |        |        |        |
|----|------------------------------------------------|--------|--------|--------|
| 13 | ✓ skirt light wiring corroded                  | \$0.00 | \$0.00 | \$0.00 |
| 14 | ✓ rh mirror light out                          | \$0.00 | \$0.00 | \$0.00 |
| 15 | ✓ air dryer wont stop leaking air after purge  | \$0.00 | \$0.00 | \$0.00 |
| 16 | ✓ cigarette lighter wiring hanging out of dash | \$0.00 | \$0.00 | \$0.00 |
| 17 | ✓ Particulate matter sensor no good            | \$0.00 | \$0.00 | \$0.00 |

| Part                                  | Warehouse  | Vendor/Bin | Qty | Unit Cost | Cost     |
|---------------------------------------|------------|------------|-----|-----------|----------|
| 5461553RX - Particulate matter sensor | Kropp Shop |            | 1.0 | \$0.00    | \$0.00   |
| Part Cost                             |            |            |     |           | \$0.00   |
| Labor                                 |            |            |     |           | \$0.00   |
| Subtotal                              |            |            |     |           | \$0.00   |
| Tax 1 (0.0%)                          |            |            |     |           | \$0.00   |
| Tax 2 (0.0%)                          |            |            |     |           | \$0.00   |
| Credit                                |            |            |     |           | (\$0.00) |
| Total Cost                            |            |            |     |           | \$0.00   |

## 868 - 2019 Kenworth t800

Parent: T366 - 2015 Peerless

CLOSED

| Serial            | Tag    | Closed Meters         |
|-------------------|--------|-----------------------|
| 1NKDX4EX9KR951076 | 0AZ868 | 5,200 hr & 903,054 km |

| Type | Scheduled    | Due | Started              | Closed               |
|------|--------------|-----|----------------------|----------------------|
|      | May 29, 2026 |     | May 29, 2026 8:52 AM | May 29, 2026 8:52 AM |

| Line | Task                         | Parts        | Labor      | Total  |           |          |
|------|------------------------------|--------------|------------|--------|-----------|----------|
| 1    | ✓ Oil change                 | \$0.00       | \$0.00     | \$0.00 |           |          |
|      | Part                         | Warehouse    | Vendor/Bin | Qty    | Unit Cost | Cost     |
|      | LF14000 - Cummins oil filter | Kropp Shop   |            | 1.0    | \$0.00    | \$0.00   |
| 2    | ✓ Grease truck and trailer   | \$0.00       | \$0.00     | \$0.00 |           |          |
|      |                              | Part Cost    |            |        |           | \$0.00   |
|      |                              | Labor        |            |        |           | \$0.00   |
|      |                              | Subtotal     |            |        |           | \$0.00   |
|      |                              | Tax 1 (0.0%) |            |        |           | \$0.00   |
|      |                              | Tax 2 (0.0%) |            |        |           | \$0.00   |
|      |                              | Credit       |            |        |           | (\$0.00) |
|      |                              | Total Cost   |            |        |           | \$0.00   |