

RT10

Date: 22JAN2025
Time: 16:21

BRANDT TRACTOR LTD.
Service History Summary
SRT: SERNO,W0,CUST

Page: 1
(SHHIST-1)

SERIAL NUMBER: 1DW410ETVEE666069 MAKE: JD MODEL: 410E

WORKORDER-SEG	E/Q	TYPE	METER	SPG CODE	SPG DESCRIPTION	INV DT
CUSTOMER:		5	INTERNAL	CUSTOMER		
1152330-01		WTY	1.0			11JUN15
3612938-01		CGD		15TX573	15TX573 - ADT STEERING VALVE UPDA	21JAN15
3612938-02		CGD			PDI UNIT	21JAN15
3612938-03		CGD			FUEL	21JAN15
3614361-01		CGD			INSTALL DIESEL FIRED HEATER KIT	30JUN15
3614361-02		CGD		BST080-0	INSTALL FIRE EXTINGUISHER - 20LBS	30JUN15
1922038-01		INT	14.0	BST080-0	INSTALL POSITIVE AIR SHUT OFF	23JUL15
1922038-02		INT	14.0		PERFORM CHECK IN	23JUL15
1922038-04		INT	14.0		INSTALL CUSTOMER TWO WAY RADIO	23JUL15
1937737-01	E	EXP	4707.0		ENSURE ALL FLUIDS LEVELS ARE GOOD/OPER	30APR21
1922542-01		WTY	36.0		INTERNAL - TIME OVER PIP ALLOWANCE	17SEP15
1922542-02	E	WTY	36.0	15TX586	15TX586 - ADT BIN LOCK BAR REPLAC	17SEP15
1922935-01		CHG	286.0		TRAVEL FOR PIP WORK	29OCT15
1922935-02		CHG	286.0		TRAVEL TO AND FROM MACHINE	29OCT15
1922999-01		INT	350.0		DIAGNOSE AND REPAIR TIRE PRESSURE CODE	31OCT15
1922999-02		INT	350.0		TRAVEL TO AND FROM MACHINE	31OCT15
1924029-01		WTY	1024.0		INITIAL SERVICE - ASI	27MAY16
1924311-01		WTY	1093.0	16TX629	16TX629 - ADT CHARGE AIR TUBE CLA	30JUN16
1924178-01		CHG	1024.0	16TX578B	16TX578B - ADT 13.5L EXHAUST MANI	30JUN16
1924178-03		CHG	1024.0		REPLACE DAMAGED HEAT SHIELDS	30JUN16
1924178-02		WTY	1024.0		STRAIGHTEN BELLY PAN	06JUL16
1925154-01		WTY	1600.0		DIAGNOSE AND REPAIR COOLANT LEAK UNDER	27JAN17
1925154-02		WTY	1600.0	16TX633	16TX633 - ARTICULATED DUMP TRUCK	27JAN17
1927703-01		WTY	1697.0		TRAVEL FOR PIP WORK	25OCT17
				17TX800	17TX800-ARTICULATED DUMP TRUCK SE	

Date: 22JAN2025
Time: 16:21

BRANDT TRACTOR LTD.
Service History Summary
SRT: SERNO,W0,CUST

Page: 2
(SHHIST-1)

SERIAL NUMBER: 1DW410ETVEE666069 MAKE: JD MODEL: 410E

WORKORDER-SEG	E/Q	TYPE	METER	SPG CODE	SPG DESCRIPTION	INV DT
CUSTOMER:	9652288		TRACKER CONTRACTING LTD			
1927703-02	WTY		1697.0		TRAVEL FOR PIP WORK	25OCT17
1928403-02	CHG		1710.0		TRAVEL TO AND FROM MACHINE - IN SITE C	30JAN18
1928403-04	E CHG		1710.0		O/T NOT COVERED BY WARRANTY	30JAN18
1928403-01	E WTY		1710.0		DIAGNOSE AND REPAIR PARK BRAKE NOT RELE	30JAN18
1929557-01	E WTY		2713.0		PARK BRAKE WON'T RELEASE	28JUN18
1929564-02	CHG		2714.0		TRAVEL TO AND FROM MACHINE	06JUL18
1929564-01	E WTY		2714.0		HYDRAULIC OVERHEAT - RH FAN NOT TURNIN	07JUL18
1929655-01	E WTY		2839.0		FIX AS FAIL PIP MH142 - REQUESTED BY DI	10AUG18
1929655-02	E WTY		2839.0		TRAVEL FOR FAF PIP WORK	10AUG18
1932467-01	CHG		3779.0		STALLS WHEN PUT IN GEAR	25JUN19
1934058-01	E CHG		3779.0		CUSTOMER CREDIT WO 4986359 POLICY	12FEB20
1934161-01	CHG		4224.0		CHECK TRANS FILTERS / CODES / LEAKS	07MAR20
1937554-01	E EXP		4705.0		TIME OVER PIP ALLOWANCE	14APR21
1937556-01	CHG		4707.0		REPLACE CAB MOUNT ISOLATORS	17APR21
1937465-01	E WTY		4705.0	17TX753A	17TX753A - ADT TRANSMISSION REPLA	15MAY21
1937563-01	E WTY		4707.0	20TX986A	20TX986A - 13.5L IT4 HEAD BOLT UPDATE	30APR21
1937704-01	CHG		4707.0		CHANGE ENGINE OIL AND FILTER	30APR21
1937917-01	E EXP				REPAIR OIL IN COOLANT	29MAY21
1941031-01	CHG		5484.0		EXHAUST LEAK	18MAY22
1941029-01	E WTY		5485.0			28MAY22
1941029-02	E WTY		5485.0	21TX059B	21TX059B - IT4 ADT ECU & SOFT	28MAY22
1946974-01	CHG		6395.0		PIP TRAVEL	24MAR24
1946974-02	CHG		6395.0		DIAGNOSE/ REPAIR LOSS OF POWER WHEN P	24MAR24
1946974-03	E CHG		6395.0		TROUBLESHOOT TRANSMISSION	24MAR24

** CUST. TOTALS

**** TOTALS

ENTRIES -