



JOHN DEERE

PRAIRIECOAST

equipment

15102 101 Street • Grande Prairie, AB T8V 0P7
 Phone: (780) 532-8402 • Fax: (780) 539-3348
 Toll Free: (877) 553-3373
 www.prairiecoastequipment.com

Ship To: SAME AS BELOW

Invoice To: Darwin Thiessen
 RR 1
 WEMBLEY AB T0H 3S0

Branch			
GRANDE PRAIRIE			
Date	Time	Page	
07/21/25	15:41:49 (O)	01	
Account No.	Phone No.	Invoice No.	
EZRA001	780-933-9424	W54754	
Ship Via		Purchase Order	
PST No.		GST No.	
		Salesperson	
		771	

SERVICE PRELIMINARY

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
128754	3140	9119	3140T 431927		
	3140				

SEGMENT# 1 S 1230 NA 05/27/25 05/30/25
 INSPECT FUEL LEAK
 10100001

SEGMENT# 9 S 1230 NA 06/17/25 06/17/25

chech for fuel leak

COMPLAINT:

leaking fuel

CAUSE:

diagnose leak, found leaking at fuel sender

CORRECTION:

change o ring on sender, better but leaking at the pipe on
 the fuel sender, change fuel sender- level sensor

ADDITIONAL DESCRIPTION:

fuel leaking out of fuel sender seal

AL41315	SENDER	1 N	344.94	344.94
L33601	O-RING	RETAIL	10.04	
		1	9.70	9.70
W30770	U-Bolt	1 N	47.48	47.48
40M7040	SNAP RING	2	2.71	5.42
			PARTS	407.54
			LABOR	362.50
10100001		SEGMENT TOTAL==>		770.04

SEGMENT#10 S 1230 NA 06/17/25 06/17/25

multiple hyd leaks

COMPLAINT:

many hydraulic leaks

CAUSE:

CONTINUED ON PAGE 02

I hereby authorize the above repair work to be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspections, or delivery at my risk. I agree to pay for work completed by your dealer upon completion, satisfactory with you in full express. Mechanic's Lien is acknowledged on the above machine to secure the amount of repairs thereto. It is understood that this company assumes no responsibility for loss or damage by theft or fire to machine placed with them for storage, repair, or while field testing. We request that finished units be picked up within 30 days of completion or the owner will pay reasonable fees associated with the storage of equipment. If equipment is not claimed by the owner within 6 months of notification, the dealer will assume full ownership of the equipment to be recycled/disposed of.

X

Customer Signature

SAME AS BELOW

GRANDE PRAIRIE

07/21/25 15:41:49 (O) 02
EZRA001 780-933-9424 W54754

Darwin Thiessen
RR 1
WEMBLEY AB T0H 3S0

771

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
128754 3140	9119	3140T 431927		
3140				
diagnose leaks, wash off, get oil hot, hoses, coupler valve stack, loader valve, trans shift cover leaking				
<u>CORRECTION:</u>				
reseal, external seals on coupler valve, reseal loader valve, change hose on loader valve, change burnt return lines on top of transmission, reseal top of trans.				
<u>ADDITIONAL DESCRIPTION:</u>				
control valve housing leaking under RH cab, loader quick coupler leak, pump supply line leak at o ring to trans.				
AL28922	SEAL	1 S	22.37	22.37
GANG13-8-8	PIP SWIVEL MALE	1	59.10	59.10
GANG50-8-8	MALE ORB #8	1	40.80	40.80
GA8M2T	1/2" 2 WIRE HYD	21	1.14	23.94
H36256	O-RING	RETAIL	3.78	
		2	3.65	7.30
L33701	O-RING	1	7.97	7.97
RE10924	KIT	RETAIL	74.85	
		2 S	72.29	144.58
R26375	O-RING	RETAIL	3.96	
		8	3.84	30.72
R375R	O-RING	RETAIL	2.75	
		2	2.74	5.48
34740808	8MORB-8ORB STRA	1	7.33	7.33
			PARTS	349.59
			LABOR	725.00
10100001			SEGMENT TOTAL==>	1074.59

SEGMENT#11 S 1230 NA 06/17/25 06/17/25
Repair AC
COMPLAINT:

CONTINUED ON PAGE 03

SAME AS BELOW

GRANDE PRAIRIE

07/21/25 15:41:49 (O) 03
EZRA001 780-933-9424 W54754

Darwin Thiessen
RR 1
WEMBLEY AB T0H 3S0

771

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
128754 3140	9119	3140T 431927		
3140				
ac not working, no belt				
<u>CAUSE:</u>				
diagnose low charge, found loose fitting on expansion valve, pin holes in low side hose under muffler				
<u>CORRECTION:</u>				
change o ring on expansion valve fitting, blow out condenser and evaporator, change low side hose, install thermal fuse, test, found pump leaking at the back of the pump, changed pump and receiver dryer, evac. and charge system, test (OK)				
<u>ADDITIONAL DESCRIPTION:</u>				
diagnose leak, pin holes in low side hose at pump under muffler, loose fitting at expansion valve, o rings (done), belt missing, thermal fuse missing				
AL70896	REFRIGERANT	RETAIL	503.04	
		1 N	485.82	485.82
Refrigerant Hose				
AR77344	FUSE	RETAIL	17.69	
		1	17.09	17.09
B15646	O-RING	RETAIL	2.97	
		1	2.86	2.86
CRRM100298	LESS CORE	1-	37.80	37.80-
L41330	V-BELT	1	27.33	27.33
P51212	O-RING	1	2.19	2.19
RE576834	Receiver-Dryer	1	102.11	102.11
RM100298	Compressor Rema	1	895.13	895.13
Compressor Reman				
R10093	O-RING	RETAIL	3.01	
		1	2.99	2.99
TY15709	TAPE	3	1.44	4.32

CONTINUED ON PAGE 04

SAME AS BELOW

GRANDE PRAIRIE

07/21/25 15:41:49 (O) 04
EZRA001 780-933-9424 W54754

Darwin Thiessen
RR 1
WEMBLEY AB T0H 3S0

771

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
128754 3140	9119	3140T 431927		
TY22465		HOSE CLAMP	4 2.79	11.16
			PARTS	1513.20
			LABOR	1740.00
10100001			SEGMENT TOTAL==>	3253.20

SEGMENT#12 S 0416 WASH 06/17/25 07/17/25

WASH & DETAIL BY THE HOUR

CORRECTION:

wash to find leaks, final wash

ADDITIONAL DESCRIPTION:

wash to find leaks, final wash

	LABOR	300.00
10100001	SEGMENT TOTAL==>	300.00

SEGMENT#13 S 1230 NA 06/17/25 06/17/25

Oil leak in cab

COMPLAINT:

leak in cab

CAUSE:

found leaking brake pedal seals

CORRECTION:

remove brake valve from unit, reseal and reinstall in cab, test ok

ADDITIONAL DESCRIPTION:

brake valve leaking in cab, reseal

R26375	O-RING	RETAIL 3.96	
		3 3.84	11.52
R29936	O-RING	2 7.55	15.10
R495R	O-RING	RETAIL 5.31	
		2 5.12	10.24

CONTINUED ON PAGE 05

SAME AS BELOW

GRANDE PRAIRIE

07/21/25 15:41:49 (O) 05
EZRA001 780-933-9424 W54754

Darwin Thiessen
RR 1
WEMBLEY AB T0H 3S0

771

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
128754 3140	9119	3140T 431927		
	3140			
TY22419	BULK HOSE	8	3.27	26.16
TY22462	CLAMP	3	2.39	7.17
TY22561	BULK HOSE	4	11.90	47.60
T22101	SEAL	RETAIL	8.99	
		2	8.68	17.36
U12547	O-RING	RETAIL	4.13	
		2	3.98	7.96
			PARTS	143.11
			LABOR	435.00
10100001		SEGMENT TOTAL==>		578.11

SEGMENT#14 S 1230 NA 06/17/25 06/17/25

Tach not working

COMPLAINT:

no tach

CAUSE:

broken wires at tach

CORRECTION:

change damaged sender and short harness, test, wiring ok,
tach needs to be replaced, not available in parts, advise
customer (cluster part number AL56411)

ADDITIONAL DESCRIPTION:

wire broken on tach sender, front of engine, change sender

AL32267	WIRING LEAD	RETAIL	58.61	
		1 N	56.61	56.61
AR96480	SENSOR	RETAIL	133.13	
		1 N	128.58	128.58
R55967	TUBE	1 N	61.99	61.99
R79915	O-RING	1	3.23	3.23
			PARTS	250.41

CONTINUED ON PAGE 06

SAME AS BELOW

GRANDE PRAIRIE

07/21/25 15:41:49 (O) 06
EZRA001 780-933-9424 W54754

Darwin Thiessen
RR 1
WEMBLEY AB T0H 3S0

771

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS	
128754	3140	9119	3140T 431927			
	3140					
				LABOR		290.00
10100001				SEGMENT TOTAL==>		540.41

SEGMENT#15 S 1230 NA 06/17/25 06/17/25
fan pulley loose
COMPLAINT:
fan wobble
CAUSE:
bearings failing in water pump
CORRECTION:
remove water pump, rebearing and reseal water pump, install
new belt along with AC belt, change hyd. pump coupler worn
out, reassemble fan shroud fan and ac pump and alternator
ADDITIONAL DESCRIPTION:
water pump bearings need replacing, change belt
new water pump = AR92641 \$1192.08 out of Bruschal, germany
(4-7+ days lead time for international transit)

RE70143	Pump Kit	RETAIL	355.83	
		1 N	343.64	343.64
R73785	BELT SET	RETAIL	46.17	
		1	44.58	44.58
R78202	CUSHION	1	32.61	32.61
		PARTS		420.83
		LABOR		507.50
10100001		SEGMENT TOTAL==>		928.33

SEGMENT#16 S 1230 PCI3FAMILY 06/17/25 06/02/25
INSPECTION FOR ALL 3 SERIES COMPACT TRACTORS
CORRECTION:
inspect all complaints, on work order, leaks and operation

CONTINUED ON PAGE 07

SAME AS BELOW

GRANDE PRAIRIE

07/21/25 15:41:49 (O) 07
EZRA001 780-933-9424 W54754

Darwin Thiessen
RR 1
WEMBLEY AB T0H 3S0

771

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
128754 3140	9119	3140T 431927		
3140				

of trans and AC

ADDITIONAL DESCRIPTION:

REFER TO INSPECTION CHECK LIST FOR DETAILS

INSPECTION INCLUDES

- GREASING OF ALL FITTINGS
- UPDATE TO ALL SOFTWARE (IF APPLICABLE)
- VERIFY ALL PIPS ARE COMPLETE
- DETAIL WASH AND CAB CLEAN AVAILABLE FOR ADDITIONAL CHARGE.
- WRITTEN QUOTE FOR ALL RECOMMENDED WORK

..

	LABOR	945.00
10100001	SEGMENT TOTAL==>	945.00

SEGMENT#17 S 1230 NA 06/17/25 06/17/25

Hi Low shift not working

COMPLAINT:

hi low shift not working

CAUSE:

diagnose low oil pressure, found leaking supply tubes, and low brake piston seal failure, high clutch disks burnt and warped

CORRECTION:

remove loader and split tractor, remove HI - LOW clutches and brake assembly, HI clutch disks burnt and warped, Low brake piston seals hard and falling apart, changed piston seals and damaged disks, found trans pump scored and damaged from too much wear, changed pump with new one and input seals, changed supply tubes damaged at seal area, changed o rings and reassembled changed HI-LOW valve housing and shaft worn out at shaft sealing area.

CONTINUED ON PAGE 08

SAME AS BELOW

GRANDE PRAIRIE

07/21/25 15:41:49 (O) 08
EZRA001 780-933-9424 W54754

Darwin Thiessen
RR 1
WEMBLEY AB T0H 3S0

771

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
128754 3140	9119	3140T 431927		
3140				

ADDITIONAL DESCRIPTION:

Hi Low dumping flow when shifted, de stroking hydraulic pump. diagnose problem , found low lube when shifting to high, linkage worn out in valve, tube leaking from valve to clutch split tractor to access and remove loader

A-AL120106	Oil Pump	1 N	734.45	734.45
AL37565	TUNE-UP KIT	RETAIL	84.63	
		1 N	81.73	81.73
AL39575	Lever	1 N	283.46	283.46
AL69559	DISK WITH	2 N	30.78	61.56
	Disk With Inner Spline			
AR75603	Trans Filter	RETAIL	23.46	
		1	22.66	22.66
A3917R	O-RING	RETAIL	2.96	
		14	2.95	41.30
A4723R	WASHER	1	4.19	4.19
FRT JD MD	JD MD FREIGHT	1	30.00	30.00
	John Deere Machine Down Priority Charge			
L33155	RING	2	54.45	108.90
L33333	Tube	4 N	39.26	157.04
L33374	O-RING	RETAIL	5.95	
		1	5.75	5.75
L34345	GASKET	RETAIL	13.79	
		1	13.31	13.31
L34352	O-RING	RETAIL	5.12	
		1	4.96	4.96
L35226	GASKET	1	2.77	2.77
L36237	O-RING	RETAIL	2.02	
		2	2.01	4.02
L36622	PLUG	RETAIL	20.72	

CONTINUED ON PAGE 09

SAME AS BELOW

GRANDE PRAIRIE

07/21/25 15:41:49 (O) 09
EZRA001 780-933-9424 W54754

Darwin Thiessen
RR 1
WEMBLEY AB T0H 3S0

771

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
128754 3140	9119	3140T 431927		
	3140			
			2 N 20.01	40.02
L40773	GASKET	RETAIL	20.19	
		2	19.49	38.98
L40965	WASHER	RETAIL	8.15	
		1	7.87	7.87
L40966	WASHER	1	3.86	3.86
L41039	OIL LINE	RETAIL	148.47	
		1 N	143.39	143.39
L41075	Oil Line	RETAIL	163.81	
		1 N	158.21	158.21
L57983	GUARD	RETAIL	45.52	
		2	43.96	87.92
L59830	COVER	RETAIL	324.18	
		1 N	313.09	313.09
L61964	GASKET	RETAIL	14.71	
		2	14.21	28.42
L62161	SEAL	1	35.47	35.47
L62272	SEAL	1	44.94	44.94
L62427	GASKET	1 N	42.02	42.02
R213663	bolt-on zip tie	4	12.57	50.28
R234266	GASKET	RETAIL	7.57	
		1	7.31	7.31
R234311	GASKET	RETAIL	8.15	
		1 N	7.87	7.87
R26287	O-RING	5	2.54	12.70
R26375	O-RING	1-	3.84	3.84-
R26552	BALL	1	3.47	3.47
R28782	O-RING	RETAIL	2.93	
		1	2.83	2.83
R29936	O-RING	RETAIL	7.81	

CONTINUED ON PAGE 10

SAME AS BELOW

GRANDE PRAIRIE

07/21/25 15:41:49 (O) 10
EZRA001 780-933-9424 W54754

Darwin Thiessen
RR 1
WEMBLEY AB T0H 3S0

771

STK#/FLEET#	HRS	PIN/EIN	WARRANTY DATE	HRS
128754 3140	9119	3140T 431927		
	3140			
			2	7.55
				15.10
R34733	WASHER	RETAIL	4.49	
		1	4.34	4.34
R375R	O-RING	RETAIL	2.75	
		3	2.74	8.22
R39280	PISTON RIN	1	24.47	24.47
R39304	WASHER	1	5.49	5.49
R394R	O-RING	2	3.42	6.84
R50349	WASHER	1	18.94	18.94
R56463	O-RING	1	4.51	4.51
R64197	CLUTCH PLATE	3 N	33.75	101.25
SM-FLTR-LEVY	< 5" FLTR LEVY	1	.55	.55
TY22062	9.46L HY-GARD	5	83.11	415.55
TY26180	BRAKE FLUI	1	11.28	11.28
T13119	O-RING	RETAIL	3.50	
		1	3.39	3.39
T28807	PISTON RIN	2	13.83	27.66
T44604	O-RING	RETAIL	1.94	
		1	1.91	1.91
03M7195	BOLT	1	3.74	3.74
10L-OIL-LEVY	10L OIL LEVY	5	1.70	8.50
12H301	LOCK WASHE	1	1.76	1.76
14H1040	NUT	1	2.44	2.44
14M7296	FLANGE NUT	1	3.10	3.10
4020P	2/0 positive	1	21.30	21.30
45M7065	SPRING LOC	2	12.42	24.84
	Spring Locking Pin			
		PARTS		3296.09
		LABOR		8400.00
10100001		SEGMENT TOTAL==>		11696.09
		CONTINUED ON PAGE 11		

SAME AS BELOW

GRANDE PRAIRIE

07/21/25 15:41:49 (O) 11
EZRA001 780-933-9424 W54754

Darwin Thiessen
RR 1
WEMBLEY AB T0H 3S0

771

STK#/FLEET#		HRS	PIN/EIN	WARRANTY DATE	HRS
128754	3140	9119	3140T 431927		
	3140				

***** WORK ORDER TOTALS *****

PARTS	6380.77
LABOR	13705.00
A/C RECOVERY	10.00
SHOP SUPP/ENVIR	250.00
WASHBAY DISCT	300.00-
SUB TOTAL==>	20045.77
GST 89966-3603 5%	1002.36
CUSTOMER TOTAL	21048.13