

Engine History

H06 - 1

VIN: 462743 / ESN: 80086139

17/03/2022

710,249 km / 9,386 hrs / 324,671 L

Complaint: Low liner

Cause: low liner #2

Correction: Replace the following components:

- ODB Liners
- Piston rings and circlips
- Upper gasket set
- Oil pan gasket & Pickup o-ring

19/07/2024

1,140,408km / 15,404 hrs / 519,205 L

Complaint: Noisy geartrain

Cause: Spun upper idler gear bushing, vibration dampener measured outside of spec.

Correction: Replace the following components:

- Upper idler gear
- Upper idler gear shaft
- Lower idler gear shaft
- Idler gear retaining bolts
- Fuel pump idler gear shaft
- Rekit oil cooler
- Main and Big End Bearings
- Vibration dampener

Campaign C2740 has been completed on this ESN.