

# ADAPT-A-LIFT GROUP PTY LTD

## Service History Listing Active Units

Date: 19/06/2026

Time: 11:09:25AM

For Equipment Code From: H14410 To: H14410

For Customer Code From: All To: All

For Date Posted From: All To: All

For Branch Code From: All To: All

Don't Show Cost

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H14410		<b>Description:</b> YALE GDP25RK FORKLIFTS INT. F/P - 55H-FPB-A201					
<b>Make:</b> YALE		<b>Model:</b> GDP25RK		<b>Serial No.:</b> B871R09769K			
1825341	Prep for Auction	NWILLIAMS	12/05/2026	Internal	5058.0	\$0.00	Carry out equipment condition assessment  Steam clean equipment as necessary.  Checke all hydrualic functions on the unit and engine runs well this is a good unit Pressure washed unit and placed in allocated area

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H14410		<b>Description:</b> YALE GDP25RK FORKLIFTS INT. F/P - 55H-FPB-A201					
<b>Make:</b> YALE		<b>Model:</b> GDP25RK		<b>Serial No.:</b> B871R09769K			
1785084	Used Sale - Price & Speed containers	RABINAL	9/02/2026	Cap Prep	5058.0	\$0.00	<ul style="list-style-type: none"> <li>- Ensure unit is operational</li> <li>- Remove hire number</li> <li>- Remove fork track if fitted</li> <li>- Remove any error codes if present</li> <li>- Check all fluid levels and top up as required</li> </ul> <p>Fit Jump Start Plug to Equipment,</p> <p>Carry out equipment condition assessment</p> <p>Remove ancillary items and Repair Wiring as necessary, Refit ancillary items,</p> <p>Repair Ignition Circuit as required,</p> <p>Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,</p> <p>Steam clean equipment as necessary.</p> <p>Prepare For Sale - Workshop</p> <p>Conduct visual inspection check all function and accessories Used jumpstarter to start the machine Check the wiring for horn haven't function Wash and clean machine</p> <p>Replace Seat,</p> <p>Replace the seat assy. and repair wiring Replace gas spring Horn wiring no current supply, and check the fuse and relay good, furthermore wiring has damage Repair wiring horn because they had been before Fit body frame cover Repair lodguard</p>
1744044	Advertise online - Used	SMALONISIO	27/08/2025	Internal	5057.0	\$0.00	<p>Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,</p> <p>Carry out equipment condition assessment</p> <p>Dig the machine out, take photos and upload</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H14410		<b>Description:</b> YALE GDP25RK FORKLIFTS INT. F/P - 55H-FPB-A201					
<b>Make:</b> YALE		<b>Model:</b> GDP25RK		<b>Serial No.:</b> B871R09769K			
1737553	Condition Assessment - USED	SMALONISIO	31/07/2025	Internal	5057.0	\$0.00	<p>Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,</p> <p>Carry out equipment condition assessment</p> <p>Carry out Inspection and Diagnosis of Brake System</p> <p>Repair Attachment as necessary,</p> <p>Remove wheel/s, Remove Brake drum/s,</p> <p>Carry out Inspection and Diagnosis of Mast/Carriage</p> <p>Overhaul Brakes components as required,</p> <p>Refit Brake drum/s and refit Wheel/s,</p> <p>Refit Wheel/s and ancillary items,</p> <p>Bleed Brake System</p>
1713090	CANCELED - Replace seat base	901QUOTE SENT01	28/04/2025	Internal	50313.0	\$0.00	<p>Block up unit, Adjust brakes and handbrake,</p> <p>No approval provided to proceed with damaged repairs - quotes cancelled pending review at a later date or time of de-hire</p>
1706482	Broken lift chain - Ptk 1065083	201WSHOP-ALLOCATOIN	1/04/2025	Internal	50313.0	\$0.00	<p>Travel to site,</p> <p>Carry out equipment condition assessment</p> <p>travel to site</p> <p>carry out equipment assesment</p> <p>found that carriage chain has snapped and top of ram assembly is bent.</p> <p>please refer to job photos for parts required.</p> <p>Carry out Inspection and Diagnosis of Attachment</p> <p>Labour</p> <p>Could not find parts at droppoint. Raj from parts and he said parts have been returned.</p>
1684511	WORKSHOP Scheduled Service - KM IC 2000hr SM - 6000hrs .2000 Hour Service	201WSHOP-ALLOCATOIN	16/02/2025	Internal	5057.0	\$0.00	<p>Returned parts.</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H14410		<b>Description:</b> YALE GDP25RK FORKLIFTS INT. F/P - 55H-FPB-A201					
<b>Make:</b> YALE		<b>Model:</b> GDP25RK		<b>Serial No.:</b> B871R09769K			
1690566	Running rough - possible fuel filter issue - horn beeps when steering-site closes at 12:00 on Fridays -Ptk 1003201	MPERIA	30/01/2025	Internal	5057.0	\$0.00	<p>Travel to site,</p> <p>Carry out equipment condition assessment</p> <p>Repair Fuel Line as necessary,</p> <p>Carry out Inspection and Diagnosis of Electrical System</p> <p>Remove ancillary items and Repair Wiring as necessary, Refit ancillary items,</p> <p>Travel to site Sign in onsite Locate machine Waiting on machine Carry out equipment condition assesment Carry out inspection, Diagnose of fuel line system and electrical system</p> <p>CONCERN-Running rough - possible fuel filter issue - horn beeps when steering-site closes at 12:00 on Fridays -Ptk 1003201</p> <p>Remove ancillary items Check fuel filter Check fuel filter in line The clogged fuel filter and inline fuel filter require replacement,resulting in poor engine performance and rough idling. Check horn,wire and cable. When you turn the steering wheel,it locks up on itd own,theres a broken plate attached to steering</p> <p>NOTE For order of fuel filter,fuel filter inline</p> <p>Labour</p> <p>Remove ancillary items and Fuel Filter and Replace, Refit Fuel Filter and ancillary items,</p> <p>Travel pick up parts Travel to site Locate machine,move to safe areaa Fit new Fuel filter,Fuel filter inline Test drive machine okay</p> <p>Note</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001 <b>Equip. Code:</b> H14410 <b>Description:</b> YALE GDP25RK FORKLIFTS INT. F/P - 55H-FPB-A201 <b>Make:</b> YALE <b>Model:</b> GDP25RK <b>Serial No.:</b> B871R09769K							
							for order Horn contact 2pcs RP5133 - for verification of part number  Repair Horn  Travel to site Locate machine Carry out equipment condition assesment Remove ancillary items Remove steer wheel Machine horn had no contact,so just found a way to make the horn work Refit ancillary items Connect all conections Test horn,horn works  NOTE For return of horn contact Carry out equipment condition assessment Carry out equipment condition assesment Check hoses For replacement of hoses (freelift) 2 hose I spoke to hai to organise with pirtek
1687754	FW from 1687084 - -Sideshift hoses over freelift worn . Horn button on rear grab handle operates relay but not horn . Right brake light still not working with new globe Seat base cushion worn	MPERIA	21/01/2025	Internal	5057.0	\$0.00	For return of horn contact Carry out equipment condition assessment Carry out equipment condition assesment Check hoses For replacement of hoses (freelift) 2 hose I spoke to hai to organise with pirtek
1687084	Wont start- not battery related- starter or alternator- Ptk 990864	DMackay	17/01/2025	Internal	5057.0	\$0.00	Travel to site, Carry out equipment condition assessment Labour Replace Battery, Top up Engine Oil as required, Top up Transmission Oil to correct level,, Repair Light/s Excess travel to site, locate onsite contact & machine. Drive in warehouse to machine & assess for won't start - battery faulty & too small for machine. Travel to local supplier & cross reference genuine part # but account on hold. Sought parts advice, travel 2nd supplier, collect battery & return to site. Renew battery & test - starter/alternator good. Top up engine & transmission oil levels from van stock. Renew both sides reverse & brake/tailight globes ask none working. REPAIRS REQUIRED: -Sideshift hoses over freelift worn -Horn button on rear grab handle operates relay but not horn -Right brake light still not working with new globe -Seat base cushion worn

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H14410		<b>Description:</b> YALE GDP25RK FORKLIFTS INT. F/P - 55H-FPB-A201					
<b>Make:</b> YALE		<b>Model:</b> GDP25RK		<b>Serial No.:</b> B871R09769K			
1652605	Tech to inspect and measure old tynes of this unit	DPhangnalay	30/08/2024	Internal	5051.0	\$0.00	Travel to site,  Carry out Inspection and Diagnosis of Attachment  Carried out inspection on tynes. Tyne type is a 1220mm please see photos for refs.
1651378	FW 1640521 - Replace Front 7.00-12 and Rear tyres 6.00-9 (all solid white tyres)	SUBC-RNT20102	26/08/2024	Internal	5051.0	\$0.00	
1650218	FW- 1640521 Need replacing a faulty dash display unit, hour meter is not working.	MPERIA	21/08/2024	Internal	5051.0	\$0.00	Travel to site,  Carry out equipment condition assessment  Travel to site Locate machine  CONCERN-Need replacing a faulty dash display unit  Carry Out equipment Condition assesment Carry out inspection on machine The dashboard is new,but the hour meter doesn't work Machine ok
1640521	Scheduled Service - DG IC 500HR SM .0500 Hour Service	ALI	20/08/2024	Internal	5051.0	\$0.00	Travel to site, Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. to site , locate unit. unsafe. need replacing all 4 worn out tyres.(shane requested all solid white tyres). need replacing 2 damaged 40mm*120mm*1220mm tynes (worn out & bent). need replacing a faulty dash display unit, hour meter is not working.. see photos. pls quote a.s.a.p. unable get signature , because no one. on site.. leave key under floor mat as instructed by ces. complaint none. cause sm. correction report.
1626373	Horn not working Neither of the two horn buttons fitted to unit are activating.. Etk 758519	DPhangnalay	22/05/2024	Internal	7986.0	\$0.00	Labour  Carry out Inspection and Diagnosis of Electrical System  Carried out inspection on the horn. Checked the buttons and fuse. Unit has a faulty horn. will replace. Parts ordered.  Replace Horn  Repair Horn  Removed and replaced horn. Repaired horn contacts. Return to service

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H14410		<b>Description:</b> YALE GDP25RK FORKLIFTS INT. F/P - 55H-FPB-A201					
<b>Make:</b> YALE		<b>Model:</b> GDP25RK		<b>Serial No.:</b> B871R09769K			
1613006	Issue with the forward and reverse lever-PTKT-712110	CZARIS	5/04/2024	Internal	51350.0	\$0.00	Travel to site,  Carry out equipment condition assessment  travel to site remove steering wheel and covers found plastic mount broken wear forward abd reverse lever mounts order parts  Labour  pick up parts travel to site supply and fit combination lever test unit Replace Forks/Tynes,
1603600	Replace tynes	DPhangnalay	26/02/2024	External	5057.0	\$634.08	Removed and replaced tynes s required. Carry out Inspection and Diagnosis of Attachment
1602598	FW 1571313- Hourmeter not working. Need to replace Hose at mast 2pcs wear and tear.	DPhangnalay	21/02/2024	Internal	60118.0	\$0.00	Carriedout inspection on the hydraulic hose and found it was ok. Checked the hour meter and found you had to go through the dash to get it. Return to service.
1571313	Scheduled Service - KM IC 1000hr SM - 5000hrs .1000 Hour Service	AGUTIERREZ	19/02/2024	Internal	51338.0	\$0.00	Travel to site, 1000hr Service Travel to site , Service 1000hr, Carry out preventive maintainance service and safety inspection in the line with agreed scope of work. Report on condition of equipment and additional work requirements. Lubricate all grease point mast and chain. Test All function. Ok Hourmeter not working. Need to replace Hose at mast 2pcs wear and tear. Need to replace Front and Rear wheels costumer request to replace in color white Size: 7.00-12 and 6.00-9 For return fuel filter double supply.
1599383	Tech assess to prepare for possible quote. Tynes damaging timber packs, appearing jagged on one side. Ptk 658502	DPhangnalay	9/02/2024	Internal	51338.0	\$0.00	Carry out Inspection and Diagnosis of Attachment Carried out inspection on tynes and found the are worn out. Both tynes have 5mm wear on the heel. LH tyne is slightly bent down causing the tip to strick loads damaging it. Grid down the tip. Need to replace.
1521376	Scheduled Service - KM IC 500hr SM - 4500hrs .0500 Hour Service	DPhangnalay	26/06/2023	Internal	50511.0	\$0.00	Labour  Travel to site,  Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H14410		<b>Description:</b> YALE GDP25RK FORKLIFTS INT. F/P - 55H-FPB-A201					
<b>Make:</b> YALE		<b>Model:</b> GDP25RK		<b>Serial No.:</b> B871R09769K			
1531083	The unit cuts out-Tagged Out-PTKT-402425	DPhangnalay	1/05/2023	Internal	6994.0	\$0.00	Carry out Inspection and Diagnosis of Electrical System  Repair Forks/Tynes as necessary,  Carried out diagnosis on cut out. Found the unit had very low oil. Topped up and checked coolant ok. Carried out repair on LH tyne. Return to service.
1514307	FW 1457690 - need to replace FAN for radiator	DPhangnalay	16/02/2023	Internal	6908.0	\$0.00	Labour  Travel to site,  remove ancillary items and Fan assembly from unit and Replace. Refit Fan assembly to unit, refit ancillary items,  assisted danny  Removed and replaced engine fan. Test check function. return to service.
1457690	Scheduled Service - 4000hr SM - 4000hrs .4000 Hour Service	AGUTIERREZ	15/02/2023	Internal	6908.0	\$0.00	Labour 4000hr Service, Service 4000hr Carry out preventive maintainance Service and safety inspection in the line with agreed scope of work. need to replace FAN for radiator

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H14410		<b>Description:</b> YALE GDP25RK FORKLIFTS INT. F/P - 55H-FPB-A201					
<b>Make:</b> YALE		<b>Model:</b> GDP25RK		<b>Serial No.:</b> B871R09769K			
1507790	Lights out and brake issues. sometime fails. Etkk 306765	GSINGH	17/01/2023	Internal	6023.0	\$0.00	<p>Travel to site,</p> <p>Carry out Inspection and Diagnosis of Electrical System</p> <p>Carry out Inspection and Diagnosis of Brake System</p> <p>Adjust Inching Valve to correct specification ,</p> <p>travel to site, access truck to safe work area, check lights, check and adjust brakes, diagnose and order master cylinder and lights,</p> <p>Carry out equipment condition assessment</p> <p>Replace Brake master cylinder,</p> <p>Bleed Brake System</p> <p>Block up unit, Adjust brakes and handbrake,</p> <p>Install Light/s</p> <p>travel to site, request chstomer to clear work space, access truck, replace master cyl, bleed and adjust brakes, replace head lights and secure connections, operate and check ok.</p> <p>Carry out Inspection and Diagnosis of Electrical System</p> <p>Remove ancillary items and Fuel Filter and Replace, Refit Fuel Filter and ancillary items,</p> <p>Check/Inspect/Diagnose Fuel system, bleed Fuel system to remove air,</p> <p>Carried out diagnosis on surging and found inline fuel filter was blocked. Removed and replaced. Test check function, Return unit to service.</p>
1506528	fuel blockage, engine is surging ptkk #301806	DPhangnalay	11/01/2023	Internal	5735.0	\$0.00	<p>Carry out Inspection and Diagnosis of Electrical System</p> <p>Remove ancillary items and Fuel Filter and Replace, Refit Fuel Filter and ancillary items,</p> <p>Check/Inspect/Diagnose Fuel system, bleed Fuel system to remove air,</p> <p>Carried out diagnosis on surging and found inline fuel filter was blocked. Removed and replaced. Test check function, Return unit to service.</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H14410		<b>Description:</b> YALE GDP25RK FORKLIFTS INT. F/P - 55H-FPB-A201					
<b>Make:</b> YALE		<b>Model:</b> GDP25RK		<b>Serial No.:</b> B871R09769K			
1474050	Unit has a broken fan belt. Ptkk 196996	DPhangnalay	23/08/2022	Internal	5091.0	\$0.00	Travel to site,  Carry out Inspection and Diagnosis of Attachment  Labour  Replace Fan Belt,  Carried out inspeciion on unit. Fan belt had failed, Travelled to parts. Removed and replaced fan belt. topped up coolant.
1428289	PRW - 1418677 - As soon as the unit got warmed up, it got sluggish and has no power/	SPETERSON	1/02/2022	Internal	5023.0	\$0.00	Carry out Inspection and Diagnosis of Electrical System Clean Diesel Tank as required,  locate unit, move to work area, daignois fuel issue, drained and cleaned fuel tank, test unit. complaint, loosing power cause: fuel pickup had blockage correction: drain and clean fuel tank and fuel lines  locate forklift diagnose machine fuel issue drain fuel tank and clean test unit machine tested ok complaint forklift loosing power cause fuel blockage corection clean fuel tank and fuel lines

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H14410		<b>Description:</b> YALE GDP25RK FORKLIFTS INT. F/P - 55H-FPB-A201					
<b>Make:</b> YALE		<b>Model:</b> GDP25RK		<b>Serial No.:</b> B871R09769K			
1418677	Loosing power won't rev up.- Still using it but it is very slow	DPhangnalay	31/01/2022	Internal	5022.0	\$0.00	<p>Travel to site,  Carry out equipment condition assessment  Repair Fuel Line as necessary,  Check/Inspect/Diagnose Fuel system, bleed Fuel system to remove air,  to site. locate unit. hour meter is still not working.  report sometime jerky, some time dosent want to lift load.  check, surging in max engine rev. trouble shooting.  replace an in-line fuel filter. bleeding air. test ok.  Labour  Carry out Inspection and Diagnosis of Electrical System  Replace Starter Motor,  check DP. none. to site . check unit . no start . found fuel is droppig from a water drain plug. ring glenn. replace a O-ring. no more fue drop from the plug. keep bleeding air.  still no start. wait for diagnosis. to base, pick up a starter.back to site. replace starter motor. test, same.  Carried out inpection and diagnosis on no start, found battery was dead and needed replacing. Replaced battery and found unit would start but would loose power.  Checked fuel system and found primary inline fuel filter was dirty and completely blocked. Travelled to Repco to pick up part. Site was closed for the day need to return first thing to finish job.  Remove ancillary items and Fuel Filter and Replace, Refit Fuel Filter and ancillary items,  Carried out fitting fuel filter. Unit started up ok but ran only for a few minutes before losing power. Unit has a fuel issue. Fuel primer might be blocked cause fuel in the fuel keeps drianing out. Further diagnosis needed.  Continued diagnosis, Found unit has an air leak in the fuel system. Fuel is leaking from the prime pump when pumping, suspect air may be leaking from the pump. Unit needs prime pump replaced.</p> <p>Replace Primary Diesel Filter as necessary,</p> <p>Carried out removing and replacing fuel primer. Test check ok. Return unit to service.</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H14410		<b>Description:</b> YALE GDP25RK FORKLIFTS INT. F/P - 55H-FPB-A201					
<b>Make:</b> YALE		<b>Model:</b> GDP25RK		<b>Serial No.:</b> B871R09769K			
1369813	Scheduled Service - RH. 1000Hr service .1000 Hour Service	ALI	12/05/2021	Internal	1.0	\$0.00	<p>Travel to site,</p> <p>1000hr Service</p> <p>to site. locate unit. received wrong service kit. requested correct parts. hour meter is not working. stretched free lift chains, need replace(bl634-10 *1, bl634cl*3).</p> <p>Replace Engine Oil Filter,</p> <p>Repair Light/s</p> <p>locate unit. replace oil filter. repair reversing light. see photos. fill sheet.</p> <p>complaint:none.cause:SM.correction:report.</p>
1375417	FW - Replace free lift chains	ALI	10/05/2021	Internal	1.0	\$0.00	<p>Labour</p> <p>pick up in DP.</p> <p>Travel to site,</p> <p>site close. check van. request van stock.</p> <p>Replace Lift Chain,</p> <p>pick up in DP. to site, wait for access unit. remove stretched chains. make 2 new free lift chains. fit to unit. adjust. test ok.</p> <p>complaint:stretched free lift chains. cause:fatigue. correction:replace.</p> <p>the same as 1375417.</p>
1375248	Replace free lift chain	ALI	10/05/2021	Internal	1.0	\$0.00	the same as 1375417.
1364034	Prep for Hire - 1200mm tines plus LRP	MLUMAY	15/03/2021	Internal	1.0	\$0.00	<p>Carry out equipment condition assessment</p> <p>Steam clean equipment as necessary.</p> <p>Replace Forks/Tynes,</p> <p>Repair Visual display unit as necessary,</p> <p>Remove ancillary items and Repair Wiring as necessary, Refit ancillary items,</p> <p>Replace Visual display unit,</p> <p>Prepare For Hire - Workshop</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H14410		<b>Description:</b> YALE GDP25RK FORKLIFTS INT. F/P - 55H-FPB-A201					
<b>Make:</b> YALE		<b>Model:</b> GDP25RK		<b>Serial No.:</b> B871R09769K			
1358629	Green Tag Inspection	MLUMAY	16/02/2021	Internal	3075.0	\$0.00	Carry out equipment condition assessment  Steam clean equipment as necessary.  Grease All Points on Unit,  Repair Light/s
1334654	Fleet Inspection	GGUERRERO	19/10/2020	Internal	3040.0	\$0.00	Prepare For Hire - Workshop Carry out equipment condition assessment  Steam clean equipment as necessary.  Remove ancillary items, prepare and Paint unit as required,  Prepare For Hire - Workshop  Performed 50 point checks. Washed/cleaned machine. Replaced tail light bulb. Top-up coolant. Replaced stickers. Touched up paint. Lubricate and greased machine. Test machine performance. Carry out equipment condition assessment
1314073	green tag inspection	CALABA	15/07/2020	Internal	2995.0	\$0.00	Carry out equipment condition assessment  Steam clean equipment as necessary.  Remove ancillary items, prepare and Paint unit as required,  Grease All Points on Unit,
1287166	Scheduled Service - 2000 Hour Service 2000 Hour Service. 2000 Hour Service	SPETERSON	1/04/2020	Internal	2984.0	\$0.00	Prepare For Hire - Workshop 2000hr Service  carry out 2000hr scheduled maintenance

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H14410		<b>Description:</b> YALE GDP25RK FORKLIFTS INT. F/P - 55H-FPB-A201					
<b>Make:</b> YALE		<b>Model:</b> GDP25RK		<b>Serial No.:</b> B871R09769K			
1201404	INSPECT AND PREP	JRODGER	15/04/2019	Internal	2904.0	\$0.00	<p>Repair Seat Switch Wiring,</p> <p>Repair Light/s</p> <p>Remove ancillary items and Steering Wheel, Strip, Inspect and report,</p> <p>Adjust Inching Valve to correct specification ,</p> <p>Remove ancillary items and Wheel/s, Inspect and report,</p> <p>Repair Steer Axle as necessary,</p> <p>H/BRAKE AND BELT INTERLOCK NOT WORKING,ACTIVATE THROUGH DASH,WIRE UP BUCKLE AND TEST,ADJUST CHAINS,REMOVE HORN CONTACT PLATES AND CLEAN,STILL NOT WORKING,REMOVE PANELS AND CHECK CONTACTS,NOT MACKINK CONTACT WITH WHEEL,REMOVE WHEEL FOUND COMBINATION LEVER BROCKEN ORDER NEW ONE,REMOVE STEER WHEELS,REMOVE OUTER STEER PINS AND BUSHERS,ADJUST INCHING CABLE,</p> <p>Refit Steering Wheel and ancillary items,</p> <p>FIT F/R LEVER,NEW HORN CONTACTS,FIT ASSY BACK ON STEERING SHAFT,FIT PANALS,FIT NEW OUTER STEER PINS AND BUSHES</p> <p>Replace Linkage/Lever as required,</p> <p>Steam clean equipment as necessary.</p> <p>Prepare For Hire - Workshop</p> <p>REPLACE PINS AND BUSHES ON HYD LEVERS,FIT,PREP FOR HIRE,STEER TYRES NEED REPLACING.</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H14410		<b>Description:</b> YALE GDP25RK FORKLIFTS INT. F/P - 55H-FPB-A201					
<b>Make:</b> YALE		<b>Model:</b> GDP25RK		<b>Serial No.:</b> B871R09769K			
1199077	De-hire. (via Toni)	RNESBIT	5/04/2019	Internal	2902.0	\$0.00	De-hire. (via Toni)  Travel to site,  Carry out equipment condition assessment  signed into site, located unit, carried out dehire inspection. checked seat and tines as asked by Ash. has new seat and tines, steer tyres needed-6.00x9 black' horn doesnt work several lights not working. scrapes on counterweight.
1164562	Scheduled Service - Level B Service	DTOM	23/11/2018	Internal	2800.0	\$0.00	pics attached. Scheduled Service -  Travel to site,  Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.  PLEASE QUOTE New seat required New steer tyres 600x9 New tynes required , class two 1070mm
1134372	losing power, goes really slow- tagged out- Louis 07 4634 0199	AFLOWERS	3/08/2018	Internal	2541.0	\$0.00	losing power, goes really slow- tagged out- Louis 07 4634 0199  Travel to site,  Carry out Inspection and Diagnosis of Electrical System  Travel to site and inspect unit, test drive unit, blow down, find fuel filter fill of rust blocking filter, blow out filter, check inside tank find bottom of tank rusted, has had water in tank, put all back together, test operation all ok, NOTE INCHING CABLE BROKEN,  Adjust Inching Valve to correct specification ,

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
<b>Owner:</b> ADAP001							
<b>Equip. Code:</b> H14410		<b>Description:</b> YALE GDP25RK FORKLIFTS INT. F/P - 55H-FPB-A201					
<b>Make:</b> YALE		<b>Model:</b> GDP25RK		<b>Serial No.:</b> B871R09769K			
1113657	Unit doing a lot of hours so may need a service, brakes are spongy as well. Backrest on seat needs replacement. Site contact Lewis Cantwell 07 4634 0199 Level B Service	DTOM	23/05/2018	Internal	2425.0	\$0.00	<p>Unit doing a lot of hours so may need a service, brakes are spongy as well. Backrest on seat needs replacement. Site contact Lewis Cantwell 07 4634 0199</p> <p>Block up unit, Adjust brakes and handbrake,</p> <p>Repair Visual display unit as necessary ,</p> <p>Travel to site,</p> <p>Replace Seat,</p> <p>Adjust Inching Valve to correct specification ,</p> <p>Replace Light/s</p> <p>Repaired inching spool and adjust Replace headlamps to LED for night works Replaced seat and wire in safety circuit Adjusted brakes Inspected weight gauge, head unit failure/ picture enclosed</p>
1087612	Scheduled Service Level B Service	DTOM	19/02/2018	Internal	1984.0	\$0.00	<p>Repaired siezed mirrors Scheduled Service</p> <p>Travel to site,</p> <p>Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.</p> <p>Seat requires replacement 500HR service completed Change oil and filter Repair RHS tail light assembly Grease and lube all pivot points Adjust park brake and brakes Clean engine bay Hydraulic load test done Full safety audit done Unit in safe condition</p>
<b>Equipment Total:</b>						<u>\$634.08</u>	
<b>Customer Total:</b>						<u>\$634.08</u>	