

ADAPT-A-LIFT GROUP PTY LTD

Service History Listing Active Units

Date: 19/06/2026

Time: 11:27:45AM

For Equipment Code From: H15949 To: H15949

For Customer Code From: All To: All

For Date Posted From: All To: All

For Branch Code From: All To: All

Don't Show Cost

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H15949		Description: HYSTER H155FT					
Make: HYSTER		Model: H155FT		Serial No.: L006V03573T			
1828865	Dehire Inspection	GOSMOND	26/05/2026	Internal	11910.0	\$0.00	Steam clean equipment as necessary. Carry out equipment condition assessment
1824234	Leaking hydraulic hose on the mast	SPitman	8/05/2026	Internal	11818.0	\$0.00	Clean truck. Perform dehire inspection. Drive to yard ready for pickup. Remove ancillary items and Repair Hydraulic Oil Leak as necessary. Refit ancillary items,
1812972	11750hr II 250hr Service	GOSMOND	30/04/2026	Internal	11774.0	\$0.00	replace blown hose tine positioner hose,steam clean 250hr Service
1819169	parked in our despatch area and it wont start	GOSMOND	20/04/2026	Internal	11723.0	\$0.00	Clean truck. Perform 11750hr pm service. Topup coolant. Tynes 49.1mm Chains 1.25%. Put back online Carry out Inspection and Diagnosis of Electrical System jump start unit gdt back to workshop,check rate of charge,load test batteries,put on charge. Repair Charging Circuit as required,
1789945	replace water pump	GOSMOND	24/02/2026	Internal	11505.0	\$0.00	Go to despatch and diagnose non crank. Batteries at 9.4v. Return to workshop and pickup jump leads and spare fork. Jumpstart truck and charging ok. Return to workshop. Load test batteries and the passed just. Hook up battery charger and let charge. Test start ok. Charging 14.0v ok. Put back online. Replace Water Pump, Diagnose failing bearing in water pump during PM service. Remove old water pump and fit new one. Refill coolant and test ok. Put back online.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H15949		Description: HYSTER H155FT					
Make: HYSTER		Model: H155FT		Serial No.: L006V03573T			
1752790	11000hr II 1000hr Service	GOSMOND	24/02/2026	Internal	11505.0	\$0.00	Steam clean equipment as necessary. Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.
1786344	limp mode in our Despatch area.	GOSMOND	12/02/2026	Internal	11478.0	\$0.00	Clean truck. Perform 11500hr pm service. Chains 1.25%. Tynes 47.3mm. Put back online. Carry out Inspection and Diagnosis of Transmission Go to despatch. Pickup truck and return to workshop. Unable to recreate fault code. Clear codes from truck and put back online to see if issue reappears.
1769531	repair a/c	GOSMOND	3/12/2025	Internal	11249.0	\$0.00	Truck has been back online for multiple shifts. Suspect water got into wiring somewhere?. Completed. Labour Repair Air Conditioner as necessary,
1763279	stopped working in the yard	GOSMOND	11/11/2025	Internal	11249.0	\$0.00	Test a/c. System stoping due to high pressure. Condensor fans failed. Replace fans and test. OK. Put back online. Remove ancillary items and Repair Wiring as necessary, Refit ancillary items, Diagnose fault code 523607-4. DTC 523607-4 - PRV Drive Line Short to Ground at Power Supply Side (COM3) or All Driver Line short to Ground Simultaneously. Follow diagnostic manual. End up with faulty ECM. Do all tests again with same results. Order new ecm. Carry out Inspection and Diagnosis of Electrical System
1760735	Scheduled Service - SL IC 250HR SM .0250 Hour Service	SPitman	31/10/2025	Internal	11118.0	\$0.00	Fit new parts still has problem. Completely split wiring loom and find S398 wire has only 1 strand left. (Enough to pass continuity test but no drive PRV.) Repair wire and test ok. Rewrap loom and put truck back online. Travel to site, 250hr Service carry out 250hr service

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H15949		Description: HYSTER H155FT					
Make: HYSTER		Model: H155FT		Serial No.: L006V03573T			
1737599	Left tyne jamming on H15949	GOSMOND	30/09/2025	Internal	10852.0	\$0.00	<p>Repair Forks/Tynes as necessary,</p> <p>Reseal Hydraulic Valve Section as necessary ,</p> <p>Diagnose jamming Lhs tyne at full out. Remove tyne pin and grind down raised burr causing the jam. Reassemble and test ok. Tynes coming out of sync. Remove valves from combination valve. Match up with kits on hand to reseal. Order extra kits to complete the job.</p>
1741993	10750hr II 250hr Service	GOSMOND	9/09/2025	Internal	10756.0	\$0.00	<p>Picup kits. Finish resealing valve. Put back online. Steam clean equipment as necessary.</p> <p>250hr Service</p> <p>Clean truck. Perfrom 10750hr pm service. Chains 0.5% Tynes 49mm. Put back online.</p>
1729811	10500hr II 500hr Service	GOSMOND	24/07/2025	Internal	10486.0	\$0.00	<p>Steam clean equipment as necessary.</p> <p>Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.</p> <p>Fit Full Camera Kit,</p> <p>Remove ancillary items and Repair Hydraulic Oil Leak as necessary. Refit ancillary items,</p> <p>Clean truck. Perform 10500hr pm service. Clean out wiper washer lines to get working again. Diagnose front camera faulty. Test with 2nd hand camera. Fixed. Remove faulty camera and fit working one. Oil weeping around control valve. Tighten clamps around the return hoses. Repair broken door latch mechanism. Tighten loose rhs tyne positioner yoke. Chains 0.5% Tynes 49.5mm. Put back online.</p>
1730550	H15949 Transmission not selecting gears	GOSMOND	4/07/2025	Internal	10486.0	\$0.00	<p>Replace Transmission Control Lever, Diagnose trans not going into gear sometimes. All wiring and solenoids ok. Shift lever if held down wouldn't trigger the direction shift. Fit ok 2nd hand unit. Problem fixed. ordered new part and will fit at next service.</p> <p>Fit new shift lever. test ok. put back online.</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H15949		Description: HYSTER H155FT					
Make: HYSTER		Model: H155FT		Serial No.: L006V03573T			
1729883	Replace lift tynes	GOSMOND	2/07/2025	Internal	10393.0	\$0.00	Remove ancillary items and Forks/Tynes, Inspect and report, Refit Forks/Tynes and ancillary items, Swap tynes around from H15945, H15951 and H15949 to get the most from the tynes in different jobs . Fit tynes from H15951 to H15949. put back online. Steam clean equipment as necessary.
1717426	10250hr II 250hr Service	GOSMOND	10/06/2025	Internal	10250.0	\$0.00	250hr Service Clean truck. Perform 10250hr pm service. Diagnose horn not working. Contact in column worn. Order new part. Tynes at wear limit, 45mm. New tynes are on order. Chains 0.3%. Put back online.
1719932	DTC 172-3	AFOX	23/05/2025	Internal	10313.0	\$0.00	Travel to site, Remove ancillary items and Repair Wiring as necessary, Refit ancillary items, Diagnose fault code. Assist Andrew with repair Fault code relates to wiring open circuit to manifold intake sensor traced wires found broken wire near plug. Replaced plug extended wires unit tested ok. Repair Horn
1713077	Fault code 1239-1 Non start	GOSMOND	28/04/2025	Internal	10010.0	\$0.00	Ordered horn contact on service job. Parts arrived and fitted to truck. Test ok. Put back online. Carry out Inspection and Diagnosis of Electrical System Repair Fuel Line as necessary, Diagnose no start. Code 1239-1 fault in fuel pressure system. Disconnect sensor and ecu. Pin out all wiring ok. Repair wiring which was rubbed through. Reassemble and test. Still no start. Check oil level and was high. Suspect internal fuel leak. Tighten fuel lines and now started. Drain and flush engine oil as was now contaminated with diesel. Run engine and check oil level. Appears to not change. Put back online.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H15949		Description: HYSTER H155FT					
Make: HYSTER		Model: H155FT		Serial No.: L006V03573T			
1709030	10000 II 2000hr Service	GOSMOND	28/04/2025	Internal	10010.0	\$0.00	<p>Steam clean equipment as necessary.</p> <p>5000hr Service</p> <p>Clean truck. Perform 10000hr pm service. Calibrate transmission. Tynes 45.2mm Chains 0.02%.</p> <p>Replace Steer Wheel Bearings,</p> <p>Carry our valve clearence adjustments</p> <p>Repack lhs steer wheel bearings. Replace hub and bearings rhs due to cup loose in hub.</p> <p>Carry out valve adjustment. None needed adjustment.. Cleanup after job. Put back online.</p>
1702104	Parkbrake fault	GOSMOND	17/03/2025	Internal	9785.0	\$0.00	<p>Repair Handbrake Lever as required,</p> <p>Replace Handbrake Lever,</p> <p>Locking mech on park brake lever failed. Replace with new unit. Test ok. Put back online.</p>
1704087	Removal of duplicate lines on job 1701441 (baseplan error)	BIG TRUCK SA	12/03/2025	Internal	9817.0	\$0.00	
1701443	Replace worn LHS tie ends	GOSMOND	12/03/2025	Internal	9757.0	\$0.00	<p>Replace Tie Rod End/s,</p>
1701441	Replace worn lift chains	GOSMOND	12/03/2025	Internal	9760.0	\$0.00	<p>Replace lhs tie rod end. Put back online. Replace Lift Chain,</p> <p>Adjust Lift Chain to correct specification,</p> <p>Chains worn out as checked on service 2%. Remove worn chains. Cut new chains to length and fit to truck. Adjust chains and hoses. Test ok. Put back online.</p> <p>Chains worn out as checked on service 2%. Remove worn chains. Cut new chains to length and fit to truck. Adjust chains and hoses. Test ok. Put back online.</p> <p>Chains worn out as checked on service 2%. Remove worn chains. Cut new chains to length and fit to truck. Adjust chains and hoses. Test ok. Put back online.</p> <p>Chains worn out as checked on service 2%. Remove worn chains. Cut new chains to length and fit to truck. Adjust chains and hoses. Test ok. Put back online.</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H15949		Description: HYSTER H155FT					
Make: HYSTER		Model: H155FT		Serial No.: L006V03573T			
1699584	Steering column is hard to tilt & lock	GOSMOND	12/03/2025	Internal	9756.0	\$0.00	Repair Steering Column as required, Dismantle cowl and investigate column not locking. Gas strut failed. Order parts and reassemble truck.
1697857	9750hr II 250hr Service	GOSMOND	12/03/2025	Internal	9756.0	\$0.00	Dismantle cowl and replace failed gas strut. Test ok. Reassemble and put back online. Steam clean equipment as necessary. 250hr Service
1693857	Chain inspection & sheeve roller assessment	GOSMOND	14/02/2025	Internal	9602.0	\$0.00	Clean truck. Perform 9750hr pm service. Chains at 2%. Replaced at this time.Put back online. Carry out Inspection and Diagnosis of Mast/Carriage
1691820	9500hr II 500hr Service	GOSMOND	4/02/2025	Internal	9526.0	\$0.00	Perform sheave and chain inspection. No movement in sheave. Chain is 50% worn. Put back online. Steam clean equipment as necessary.
1678129	9500hr II 500hr Service	GOSMOND	5/12/2024	Internal	9275.0	\$0.00	Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. Clean truck. Perform 9500hr pm service. Put back online. Steam clean equipment as necessary. 250hr Service
1671219	Oil leak on mast	WHILL	7/11/2024	Internal	9084.0	\$0.00	Clean truck. Perform 9250hr pm service. Put back online. Travel to site, Check/Inspect/Diagnose Hydraulic Oil Leak and test operation, Repair Hydraulic Hose/s as necessary,
1671094	Carry Out A/C modification as per quote 34815 (H15949)	GOSMOND	7/11/2024	External	9393.0	\$6,081.23	Located unit and confirmed fault. Traced leak to sideshift fitting on the back of the carriage. Removed, cleaned and refitted. Rechecked operation and returned unit to service. Supply and install custom air conditioning modules to Hyster 7 tonne fleets across Bellbay and Mount Gambia sites.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H15949		Description: HYSTER H155FT					
Make: HYSTER		Model: H155FT		Serial No.: L006V03573T			
1668510	oil leak	GOSMOND	29/10/2024	Internal	9034.0	\$0.00	Travel to site, Remove ancillary items and Repair Hydraulic Oil Leak as necessary. Refit ancillary items, Travel to site. Diagnose oil leak. Crack in hardline to side shift cylinder. Weld up and refit. Test. ok. Put back online. Steam clean equipment as necessary.
1655403	9000hr II 1000hr Service	GOSMOND	15/10/2024	Internal	9008.0	\$0.00	3000hr Service Contiue 9000hr pm service. Calibrate transmission. Finish 9000hr pm service. Adjust fan belt. Put back online.
1653247	Replace Dash Display	GOSMOND	3/09/2024	Internal	8721.0	\$0.00	Replace Gauge/s
1653224	Side shift is not moving	GOSMOND	3/09/2024	Internal	8720.0	\$0.00	Replace unreadable dash display. Put back online. Steam clean equipment as necessary. Repair Carriage as necessary, Remove ancillary items and Carriage Rollers, Strip, Inspect and report, Sideshift bracket failed. Clean truck and remove carriage. Remove cylinder and straighten pipes. Weld prep bracket and tack in place. Notice carriage rollers poor and falied. Order parts. Replace failed carriage rollers. Weld bracket back on and refit cylinder. Driil out /rethread broken bolts. Refit mast and connect lines. Test ok. Put back online. Steam clean equipment as necessary.
1648440	8750hr II 250hr Service	BIG TRUCK SA	3/09/2024	Internal	8730.0	\$0.00	250hr Service
1652238	repair door latch	GOSMOND	29/08/2024	Internal	8702.0	\$0.00	Clean truck. Perform 8750hr pm service. Put back online. Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items, Door latch falling out. Replace bolts and add lock washers as threads u/s. Adjust striker. ok. Put back online.
1649012	has broken the water pump belt and is parked.	GOSMOND	16/08/2024	Internal	8654.0	\$0.00	Replace Fan Belt, Diagnose broken fan belt. All baerings ok. Fit new belt and put back online.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H15949		Description: HYSTER H155FT					
Make: HYSTER		Model: H155FT		Serial No.: L006V03573T			
1635006	8500hr II 500hr Service	BIG TRUCK SA	24/07/2024	Internal	8498.0	\$0.00	<p>Steam clean equipment as necessary.</p> <p>Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.</p> <p>Repair Sideshift Cylinder as necessary,</p> <p>Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,</p> <p>Clean truck. Perform 8500hr pm service. Tighten fan belt. Tighten rhs tyne positioner ram yoke. Repair lhs door latch falling apart. Put back online.</p>
1627681	8250hr II 250hr Service	BIG TRUCK SA	14/06/2024	Internal	8242.0	\$0.00	<p>Steam clean equipment as necessary.</p> <p>250hr Service</p> <p>Clean truck. Perform 8250hr pm service. Trim tynes. Put back online.</p>
1607564	3G Sunset Device Swap (FM1 to VAM)	GOSMOND	9/05/2024	Internal	7964.0	\$0.00	<p>Replace Fleet Management System as required,</p> <p>Remove FM1 and fit VAM s/s update. Configure VAM and test ok. Put back online.</p>
1615889	8000hr II 4000hr Service	GOSMOND	8/05/2024	Internal	7964.0	\$0.00	<p>Steam clean equipment as necessary.</p> <p>4000hr Service,</p> <p>Clean truck, Perform 8000hr pm service. Change hyd. oil. Calibrate trans.</p>
1614091	Assess Steer Cylinder and Oil Pressure Gauge	GOSMOND	8/05/2024	Internal	7964.0	\$0.00	<p>Remove ancillary items and Repair Wiring as necessary, Refit ancillary items,</p> <p>Diagnose fault with no oil pressure light on dash. In the dash was reporting 432kpa with the engine off. Checked wiring loom for continuity. Found fault open circuit to wire 275A 5v power to sensor. Stripped loom to find break. Found and repaired.</p> <p>Reassemble truck and put back online. Issue with movement in steer cylinder seems to have resolved by itself.</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001 Equip. Code: H15949 Description: HYSTER H155FT Make: HYSTER Model: H155FT Serial No.: L006V03573T							
1599987	Aircon issues	GOSMOND	15/03/2024	Internal	7596.0	\$0.00	Repair Air Conditioner as necessary, Diagnose no a/c. Bypass switch system kicks on. No Gas in system. Pressurize with nitrogen to find leak. Unable to find leak. Will organise a/c tech to repair. Experiment with a/c ducting. Finish new ducting. Refit casb fan. Mount fire extinguisher externally. Re-gas Air Conditioner to correct specification, Assist a/c man. Put back online. Travel to site. Check A/C system - out of gas. Pressurise with LokTrace blend, locate leak from front seal of compressor. Remove compressor, fit new compressor, modify wiring as necessary. Examine hoses and locate deep rub marks on discharge and liquid hoses. Replace damaged sections of hose. Replace receiver drier. Add oil and evacuate A/C system. Charge with R134a, check operation. Steam clean equipment as necessary.
1601997	250hr service 0250 Hour Service	GOSMOND	14/03/2024	Internal	7749.0	\$0.00	250hr Service Clean truck. Perform 7750hr pm service. Adjust fan belt. Cleanup after days work. Put back online. Steam clean equipment as necessary.
1588050	7500hr II 500hr Service	GOSMOND	7/02/2024	Internal	7503.0	\$0.00	Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. Clean truck. Perform 7500hr pm service. Top up coolant. Rplace failed reverse buzzer with good second hand one. Put back online. Carry out Inspection and Diagnosis of Transmission
1594502	UNIT IN LIMP MODE - ERROR CODE 520317-2	GOSMOND	19/01/2024	Internal	7395.0	\$0.00	Remove ancillary items and Repair Wiring as necessary, Refit ancillary items, Diagnose 520317-2 code. Replaced tiss sensor with known good one. No change. Limp back to workshop. Continue diagnosis. Follow procedure and find broken power wire to sensor and another wire almost rubbed through. Repair wiring loom and test ok. Reassemble and put back online.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H15949		Description: HYSTER H155FT					
Make: HYSTER		Model: H155FT		Serial No.: L006V03573T			
1591723	wiper motor issue	GOSMOND	9/01/2024	Internal	7395.0	\$0.00	<p>Repair Windscreen Wiper as necessary,</p> <p>Diagnose no front wiper. Wiper linkage seized and burnt out motor. Order parts for repair.</p> <p>Replace Windscreen Wiper,</p> <p>Due to breakdowns. Stole parts from H15952 and fit to H15949. Put back online.</p>
1584653	7250hr II 250hr Service 0250 Hour Service	BIG TRUCK SA	14/12/2023	Internal	7263.0	\$0.00	<p>Pickup and fit new parts. Test ok. Put back online. Steam clean equipment as necessary.</p> <p>250hr Service</p> <p>Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,</p> <p>Clean Truck. Perform 7250hr pm service. Adjust fan belt. Drill out broken bolt in side shift pin retaining bracket. Put back online.</p>
1587322	INSPECT A/C	GOSMOND	13/12/2023	Internal	7264.0	\$0.00	<p>Repair Air Conditioner as necessary,</p> <p>Diagnose a/c poor. Blow out all cores. Fans ok. Repair split ducting. Clean all filters. Test air flow and a/c performance. OK. Put back online.</p>
1584006	broken fan belt	SPitman	1/12/2023	Internal	7162.0	\$0.00	<p>Replace Fan Belt,</p>
1582999	broken door handle	GOSMOND	28/11/2023	Internal	7264.0	\$0.00	<p>replace broken fanbelt.</p> <p>Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,</p> <p>Wind caught door and ripped door strap mount off. Welded back on. Paint and test. OK. Put back online.</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H15949		Description: HYSTER H155FT					
Make: HYSTER		Model: H155FT		Serial No.: L006V03573T			
1579078	possible flat battery	SPitman	13/11/2023	Internal	7053.0	\$0.00	Travel to site, Carry out Repairs to Jump Start Plug , load test batteries found both batteries need replacing,supplier has stock but will supply them thursday? Remove ancillary items and Remove Battery from unit and Inspect and report, Refit Battery to unit, Refit ancillary items, Adjust fan belt as required collect batteries from vendor,remove and fit new batteries,adjust alt and air con belts.
1577725	Replace tie rods and steer pins	SPitman	7/11/2023	Internal	6998.0	\$0.00	Travel to site, Replace Tie Rod End/s, Replace steering tie rod assemblies and pins.
1570351	7000hr II 1000hr Service	SPitman	7/11/2023	Internal	6998.0	\$0.00	Travel to site, Steam clean equipment as necessary. 1000hr Service Steam clean unit,perform 1000hr service as per scope of work,tighten loose mast cylinder boltsadjust parkbrake and test.
1570628	unit requires jump start / new battery	GOSMOND	9/10/2023	Internal	6778.0	\$0.00	Remove ancillary items and Remove Battery from unit and Inspect and report, Jumpstart off another H155ft truck. Check charge rate ok. Suspect lights left on? Put back online.
1561802	6750hr II 250hr Service 0250 Hour Service	GOSMOND	3/10/2023	Internal	6739.0	\$0.00	Steam clean equipment as necessary. 250hr Service
1567930	REPLACE SEAT BASE	GOSMOND	26/09/2023	Internal	6707.0	\$0.00	Clean truck. Perform 6750hr pm service. Put back online. Repair Seat as necessary, Replace seat switch. Test ok. Put back online.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H15949		Description: HYSTER H155FT					
Make: HYSTER		Model: H155FT		Serial No.: L006V03573T			
1554044	6500hr II 500hr Service	BIG TRUCK SA	31/08/2023	Internal	6506.0	\$0.00	<p>Steam clean equipment as necessary.</p> <p>Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.</p> <p>Clean truck. Perform 6500hr pm service. Suspect coolant leak. Pressurized the system but no leaks found. Tighten fan belt. Tighten loose rhs tyne positioner yoke. Put back online.</p>
1548382	6250hr II 250hr Service	GOSMOND	1/08/2023	Internal	6285.0	\$0.00	<p>Steam clean equipment as necessary.</p> <p>250hr Service</p> <p>Clean truck. Perform 6250hr pm service. Replace lhs door strap. Put back online.</p>
1530992	6000hr II 3000hr Service	GOSMOND	12/06/2023	Internal	6070.0	\$0.00	<p>Steam clean equipment as necessary.</p> <p>2000hr Service</p> <p>Clean truck. Perform 6000hr pm service.</p> <p>Calibrate transmission.</p> <p>Adjust fan belt.</p> <p>Put back online.</p>
1533970	Wiring faults in transmission	GOSMOND	7/06/2023	Internal	5846.0	\$0.00	<p>Remove ancillary items and Traction card from unit.</p> <p>Repair Traction card as necessary and Refit to unit, Refit ancillary items,</p> <p>investigate complaint, unit in limp mode with code 91-4,</p> <p>throttle pedal sensor reading at 108%, voltage values changing with pedal movement but not within spec, removed covers and begin physically checking sensor and wiring. further tests to come</p> <p>Carry out Inspection and Diagnosis of Electrical System</p> <p>Remove ancillary items and Repair Wiring as necessary, Refit ancillary items,</p> <p>Fit Seat Belt,</p> <p>Continue with diagnosis of code 91-4. Found break in wire 370 from pedal sensor to engine ecm. Replaced wire and test. OK. Replace worn out seat belt. Put back online.</p>
1531677	Hydraulic controls worn out	GOSMOND	2/05/2023	Internal	5846.0	\$0.00	<p>Order Parts</p> <p>Repair Hydraulic Control Valve as necessary,</p> <p>Pickup parts. Remove old knobs and fit new ones.</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H15949		Description: HYSTER H155FT					
Make: HYSTER		Model: H155FT		Serial No.: L006V03573T			
1525552	5750 II 250hr service	GOSMOND	26/04/2023	Internal	5717.0	\$0.00	Steam clean equipment as necessary. 250hr Service Clean truck. Perform 5750hr pm service. Adjust fan belt. Put back online. Steam clean equipment as necessary.
1519248	5500 II 500hr Service	GOSMOND	30/03/2023	Internal	5515.0	\$0.00	Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. Clean truck. Perform 5500hr pm service. Replace worn out fan belt. Put back online. Steam clean equipment as necessary.
1510387	5250 II 250hr service 0250 Hour Service	GOSMOND	27/02/2023	Internal	5268.0	\$0.00	Clean truck. Perform 5250hr pm service. Put back online. Repair Hydraulic Tilt Cylinder as required, Reseal LHS tilt cylinder. Refit to truck. Test ok. Put back online. Steam clean equipment as necessary. 250hr Service
1508704	Reseal LH tilt cylinder	GOSMOND	20/01/2023	Internal	4985.0	\$0.00	Clean truck. Perform 5250hr pm service. Put back online. Repair Hydraulic Tilt Cylinder as required, Reseal LHS tilt cylinder. Refit to truck. Test ok. Put back online. Steam clean equipment as necessary.
1500655	5000 II 5000hr service	GOSMOND	19/01/2023	Internal	4985.0	\$0.00	5000hr Service Clean truck. Perform 5000hr pm service. Calibrate transmission.
1493347	4750 II 250hr service 0250 Hour Service	GOSMOND	6/12/2022	Internal	4784.0	\$0.00	Complete service. Cleanup workshop. Clean truck. Perform 4750hr pm service
1491126	Replace lift chains	GOSMOND	4/11/2022	Internal	4559.0	\$0.00	Replace Lift Chain, Remove worn out lift chains. Cut new chains to length. Fit to truck. Adjust chains. Put back online. Steam clean equipment as necessary.
1483104	4500 II 500hr service Hyster L006_0500Hr Service Kit_Dsl_H155FT MB. 0500 Hour Service Hyster L006_0500Hr Service Kit_Dsl_H155FT MB. 0500 Hour Service	511 Planning B	4/11/2022	Internal	4559.0	\$0.00	Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. Clean truck. Perform 4500hr pm service.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H15949		Description: HYSTER H155FT					
Make: HYSTER		Model: H155FT		Serial No.: L006V03573T			
1486308	Will not start, suspected seat switch	WHILL	17/10/2022	Internal	4353.0	\$0.00	Carry out Inspection and Diagnosis of Electrical System Repair Fleet Management System as required, Travelled to dispatch and located unit. Confirmed seat switch issue. Suspected relay. Bypassed relay and moved unit back to the work shop. Checked supply and signal voltage to the seat switch relay. Found only 10v signal from the fm1 to the relay. Sourced new fm1 module and fitted. Got programmed up and rechecked operation. Returned unit to service. 250hr Service
1475610	4250 II 250hr service 0250 Hour Service	511 Planning B	20/09/2022	Internal	4262.0	\$0.00	Steam clean equipment as necessary.
1464321	4000 II 4000hr service Hyster L006_4000Hr Service Kit_Dsl_H155FT MB. 4000 Hour Service	511 Planning A	13/08/2022	Internal	3974.0	\$0.00	Clean truck. Perform 4250hr pm service. Put back online. Steam clean equipment as necessary. 4000hr Service, Clean truck. Start 4000hr pm service. Complete 4000hr pm service. Calibrate trans. Put back online. Replace Lift Chain,
1470485	Further works: Replace lift chains	GOSMOND	9/08/2022	Internal	3974.0	\$0.00	Check chains. At worn limit. Order parts. Replace Tie Rod End/s,
1470234	Fit steering links- labour only	GOSMOND	8/08/2022	Internal	3974.0	\$0.00	Replace worn out steering tie rod ends. Put back online.NOTE: parts booked to previous job. Put back online. Replace Tie Rod End/s,
1463886	Replace worn steering tie rod link and pins	GOSMOND	7/07/2022	Internal	10.0	\$0.00	Order parts Steam clean equipment as necessary.
1456483	3750 II 250hr service. 0250 Hour Service	GOSMOND	7/07/2022	Internal	3781.0	\$0.00	250hr Service Clean truck. Perform 3750hr pm service. Put back to work.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H15949		Description: HYSTER H155FT					
Make: HYSTER		Model: H155FT		Serial No.: L006V03573T			
1456278	Steer wheel bearing failure	GOSMOND	29/06/2022	Internal	3720.0	\$0.00	Clean and re-pack Steer Wheel Bearings, Replace Steer Wheel Bearings, Cleaned up reusable parts. Found RHS hub is damaged in inner bearing bore. Fit new bearings to new hub and reassemble. Clean up and reuse parts from LHS. Reassemble and fit wheels ok. Put back online.
1451366	3500 II 500hr service. Hyster L006_0500Hr Service Kit_Dsl_H155FT MB. 0500 Hour Service	GOSMOND	3/06/2022	Internal	3619.0	\$0.00	Pickup new parts. Cleanup after job. Steam clean equipment as necessary. Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.
1439405	3250hr service II 250hr type service. 0250 Hour Service	GOSMOND	22/04/2022	Internal	3307.0	\$0.00	Clean truck. Perform 3500hr pm service. Steam clean equipment as necessary. 250hr Service Clean truck. Perform 3250hr pm service. Adjust drive belts. Top up coolant. Tighten loose bolts on carriage. Put back online.
1441715	Further works from Oil Sample – Drop in Viscosity could be due to oil quality or extreme heat. As the oil had been changed no further actions required.	GOSMOND	30/03/2022	Internal	3174.0	\$0.00	Check Diff oil level, top up oil level as required, As per recommendation, I have placed a note to make sure to sample at next service.
1438553	Wiring issue on fuel pump	GOSMOND	15/03/2022	Internal	3056.0	\$0.00	Remove ancillary items and Repair Wiring as necessary, Refit ancillary items, Repair wiring to Fuel pump solenoid and air temp sensor. Modify bracket and reposition loom to better path. Put back online.
1438552	Cracked mount for the rotating beacon	GOSMOND	15/03/2022	Internal	3056.0	\$0.00	Repair Revolving/Flashing/Strobe light as required, Remove Beacon and rear lights. Repair and strengthen bracket. Refit all parts. Put back online.
1431228	Scheduled Service - 3000hr service II 1000hr type. .1000 Hour Service	GOSMOND	11/03/2022	Internal	3055.0	\$0.00	3000hr Service Carry out 3000hr pm service. Travel to site, Steam clean equipment as necessary.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H15949		Description: HYSTER H155FT					
Make: HYSTER		Model: H155FT		Serial No.: L006V03573T			
1429931	The seat switch in forklift H15949 is playing up, (not allowing fork to start) so can Wade pls check.	WHILL	7/02/2022	Internal	2818.0	\$0.00	Travel to site, Carry out Inspection and Diagnosis of Telemetry System Repair Fleet Management System as required, Travelled to site and located unit. Confirmed unit int not starting. Checked operation of the seat switch. Found switch operating correctly. Traced through and found the ignition relay on the forktrack side not switching. Checked operation of the relay and found a low relay trigger voltage. Traced back to a faulty module. Replaced module and got it reprogrammed. Rechecked operation and returned unit to service.
1417208	Scheduled Service - 2750hr service.	WHILL	28/12/2021	Internal	2743.0	\$0.00	Travel to site, 250hr Service Labour Replace Fan Belt, Steam clean equipment as necessary. Travelled to site and located unit. Cleaned unit. Carried out service as per schedule. Found alternator belt badly cracked. Sourced and replaced Steam clean equipment as necessary.
1409804	Scheduled Service - 2500hr service II 500hr type. .0500 Hour Service	GOSMOND	15/11/2021	Internal	2501.0	\$0.00	Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. Repair Accumulator as necessary, Clean truck. Perform 2500hr pm service. Make and fit soft ride acculator bracket. Put back online. Replace Switch/es
1409382	Seat sensor is faulty sometimes. Apparently the ignition goes blank and the forklift doesn't start.	GOSMOND	20/10/2021	Internal	2387.0	\$0.00	Repair Forks/Tynes as necessary, Diagnose issue with seat switch. Check all wiring and plugs, ok. Replace seat switch as showing signs of wear. Test ok. Trim tynes. Put back online.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H15949		Description: HYSTER H155FT					
Make: HYSTER		Model: H155FT		Serial No.: L006V03573T			
1401192	Scheduled Service - 2250hr service II 250hr type. .0250 Hour Service	GOSMOND	30/09/2021	Internal	2228.0	\$0.00	Steam clean equipment as necessary. 250hr Service Clean truck. Perform 2250hr pm service. Tighten fan belt. Put back online.
1394486	Scheduled Service - 2000hr service. .2000 Hour Service	GOSMOND	17/08/2021	Internal	1975.0	\$0.00	Steam clean equipment as necessary. 2000hr Service Adjust Lift Chain to correct specification, Adjust lift chains and clean up. Put back online.
1383761	Scheduled Service - 1750hr service II 250hr type. .0250 Hour Service	GOSMOND	30/06/2021	Internal	1740.0	\$0.00	Steam clean equipment as necessary. 250hr Service
1369134	Scheduled Service - 1500hr service II 500hr type .0500 Hour Service	GOSMOND	29/04/2021	Internal	1485.0	\$0.00	Repair Air Conditioner as necessary, Steam clean equipment as necessary. Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. Clean truck. Perform 1500hr pm service. Tighten fan belt. Top up coolant. Refit cb mic bracket which had fallen off. Put back online
1360791	Scheduled Service - 1250hr service II 250hr type.	GOSMOND	10/03/2021	Internal	1268.0	\$0.00	Steam clean equipment as necessary. 250hr Service
1357515	CHECK FORKTRACK SYSTEM	GOSMOND	11/02/2021	Internal	1108.0	\$0.00	Clean truck. Perform 1250hr pm service. Put back online Repair Attachment as necessary,
1350033	Scheduled Service - 1000 Hour Service	GOSMOND	19/01/2021	Internal	984.0	\$0.00	Diagnose report of impact sensor not reporting to ft display. Test operation ok. Put back online. Steam clean equipment as necessary. 1000hr Service Adjust Transmission Control Valve to correct specification , Clean truck. Perform 1000hr pm service. Modify wiring around fuel filter for better access. Make and fit spacer blocks under cab air filter to allow filter to be changed. Calibrate transmission. Clean up w/shop. Put back online.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H15949		Description: HYSTER H155FT					
Make: HYSTER		Model: H155FT		Serial No.: L006V03573T			
1327809	Scheduled Service - 750hr service II 250hr type	GOSMOND	20/10/2020	Internal	722.0	\$0.00	Steam clean equipment as necessary. 250hr Service Repair Air Conditioner as necessary, Clean truck. Carry out 750hr pm service. Replace fuse holder with circuit bracker in a/c fan wiring. Carry out Inspection and Diagnosis of Transmission
1333639	CW-Transmission needs to be re-calibrated. Parked up.	GOSMOND	14/10/2020	Internal	722.0	\$0.00	Diagnose rough trans operation. Fault code 520324-3. Not in manual. Lodge CM ticket and get fast response. Fault lies with trans temp sensor. Check sensor and has been damaged. Make temporary repair and order new sensor. Will fit at next service as oil is to be changed.
1321933	Scheduled Service - 0500 Hour Service	GOSMOND	9/09/2020	Internal	511.0	\$0.00	Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements. Perform 500hr pm service. Labour Travel to site, Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items, Steam clean equipment as necessary.
1321560	CW- Unit has loose mast chains. Tagged out	WBRAZIL	20/08/2020	Internal	390.0	\$0.00	
1320985	Rework Job: 1319288 - Loose mast chain - Tagged out.	WBRAZIL	18/08/2020	Internal	400.0	\$0.00	Travel to site, Adjust Lift Chain Anchors to correct specification, Steam clean equipment as necessary. Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,
1319288	CW - Lose mast chain. Tagged out.	GOSMOND	10/08/2020	Internal	293.0	\$0.00	readjust chain anchors loctite into place Adjust Lift Chain to correct specification, Diagnose loose chain. Lock nuts lhs chain loose. Tighten nuts and adjust chain. Lubricate carriage. Set time and date on camera recorders.

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H15949		Description: HYSTER H155FT					
Make: HYSTER		Model: H155FT		Serial No.: L006V03573T			
1318191	Scheduled Service - 250hr service	GOSMOND	4/08/2020	Internal	260.0	\$0.00	Steam clean equipment as necessary. 250hr Service Clean truck. Carry out 250hr pm service.
1312895	Tighten lift chains	GOSMOND	9/07/2020	Internal	174.0	\$0.00	Clean up after service. Adjust Lift Chain to correct specification,
1312317	Realign Tynes	GOSMOND	7/07/2020	External	136.0	\$238.40	Tighten loose lhs lift chain. Check adjustment. Tighten lock nuts. Repair Forks/Tynes as necessary,
1302923	Scheduled Service- 100hr service	GOSMOND	6/07/2020	Internal	136.0	\$0.00	Diagnose tyne tips 20mm misaligned. Lhs tyne bent at end. Swapped tynes side to side and reduced the misalignment. Put back to work. Steam clean equipment as necessary. 100Hr Service Adjust Transmission Control Valve to correct specification ,
1311092	Tynes to be realigned	GOSMOND	1/07/2020	Internal	76.0	\$0.00	Steam clean truck. Carry out 100hr initial pm service. Calibrate trans. Repair Forks/Tynes as necessary,
1309870	CW - Loose mast chain - Tech to assess for cust damage - Parked up	GOSMOND	26/06/2020	Internal	54.0	\$0.00	Check tyne alignment. Worked out the lhs tyne bent 300 mm from tip. Put back online. Adjust Lift Chain to correct specification,
1308864	CW-Mast chain has come loose. Tagged out.	GOSMOND	23/06/2020	Internal	25.0	\$0.00	Tighten loos rhs lower lift chain nuts. Adjust both chains. Tighter tyne carrier pin retainer bolts. Lubricate door latch. Travel to site, Adjust Lift Chain to correct specification, Tighten loose lhs lift chain. Nock nut on bottom had come loose. Adjust and test. Ok

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H15949		Description: HYSTER H155FT					
Make: HYSTER		Model: H155FT		Serial No.: L006V03573T			
1302116	Rework before unit goes in service	GOSMOND	29/05/2020	Internal	3.0	\$0.00	<p>Repair Switch/es</p> <p>Diagnose no drive.</p> <p>Travel to site,</p> <p>Adjust Accumulator Pressure</p> <p>Top up Hydraulic Oil to correct level,</p> <p>Travel to site. Replace FT plunger type switch with pad type. Adjust accumulator pressure. Set speed limit. Top up hydraulic oil.</p>
1299109	Warranty - Cabin Dust Ingress	501WORKSHOP	19/05/2020	External	4.0	\$32.01	
1297741	Modify Load Guard	TBIRBAS	13/05/2020	Cap Prep	4.0	\$0.00	<p>Repair Load Guard as necessary,</p> <p>travened to steel suplier to collect steel waited 15 nin as they had not been suplied order number and had only been asked for a quote loaded into ute returned to workshop un loades steel for all units</p> <p>*ADDITIONAL TIME TAKEN DUE TO BEING FIRST UNIT TO HAVE WORKS PERFORMED</p> <p>brought unit into welding bay messured all assosiated components for correct specs cut standard gaurds as requirterd</p> <p>tac wilded and test fitted</p> <p>removed and completed weld</p> <p>cleamed up surface to appear astheticly pleasing</p> <p>painted gaurd in nugget yellow as per factory inspected by Mell and unit is ready to be installed to site</p>
1297555	Add A/C Filtration	511 Planning D	12/05/2020	Internal	3.0	\$0.00	

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H15949		Description: HYSTER H155FT					
Make: HYSTER		Model: H155FT		Serial No.: L006V03573T			
1200002	Prep for Rent; Timberlink	ECACERES	9/04/2019	Cap Prep	3.0	\$0.00	<p>Refit Mast and ancillary items,</p> <p>Refit Hydraulic Hose/s and ancillary items,</p> <p>Install Light/s</p> <p>Remove ancillary items and Load Guard, inspect and report,</p> <p>Refit Forks/Tynes and ancillary items,</p> <p>Refit Load Guard and ancillary items,</p> <p>Install Hard Labels,</p> <p>Fit Fleet Management System as required,</p> <p>install arials in multiple units</p> <p>Travel to site,</p> <p>Install Radio,</p> <p>tavel to site and start installing radios</p> <p>travel to workshop to install forktrack</p> <p>Remove ancillary items and Repair Wiring as necessary, Refit ancillary items,</p> <p>install lights on multiple units</p> <p>start to install forktrack</p> <p>Carry out Inspection and Diagnosis of Telemetry System</p> <p>Repair Fleet Management System as required,</p> <p>Install Battery Isolator,</p> <p>Removed varios panels. Wired up and fitted forktrack. Fitted new seat switch. Removed roof panel and fitted radio and speakers. Fitted uhf.</p> <p>Fit Full Camera Kit,</p> <p>Repair Revolving/Flashing/Strobe light as required,</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
---------	-------------	----------	------	----------	----------	--------	-------

Owner: ADAP001

Equip. Code: H15949

Make: HYSTER

Description: HYSTER H155FT

Model: H155FT

Serial No.: L006V03573T

Remove and Replace Reverse buzzer, Refit to unit,

Carry out New Equipment Predelivery to correct specification.

Equipment Total:	<u>\$6,351.64</u>
Customer Total:	<u>\$6,351.64</u>