

# ADAPT-A-LIFT GROUP PTY LTD

## Service History Listing Active Units

Date: 19/06/2026

Time: 10:48:05AM

For Equipment Code From: H15952 To: H15952

For Customer Code From: All To: All

For Date Posted From: All To: All

For Branch Code From: All To: All

Don't Show Cost

| Job No.                    | Description              | Mechanic                          | Date       | Job Type                       | Eng. Hrs | Retail   | Notes   |
|----------------------------|--------------------------|-----------------------------------|------------|--------------------------------|----------|----------|---|
| <b>Owner:</b> ADAP001      |                          |                                   |            |                                |          |          |   |
| <b>Equip. Code:</b> H15952 |                          | <b>Description:</b> HYSTER H155FT |            |                                |          |          |   |
| <b>Make:</b> HYSTER        |                          | <b>Model:</b> H155FT              |            | <b>Serial No.:</b> L006V03566T |          |          |   |
| 1829502                    | Dehire Inspection        | GOSMOND                           | 28/05/2026 | External                       | 11704.0  | \$520.09 | <p>Steam clean equipment as necessary.</p> <p>Carry out equipment condition assessment</p> <p>Clean truck. Perform dehire inspection. Top up transmission oil. Drive truck to yard ready for pickup.</p>  |
| 1824143                    | 11750hr II 250hr Service | GOSMOND                           | 16/05/2026 | Internal                       | 11665.0  | \$0.00   | <p>Replace Hydraulic Hose/s and ancillary items,</p> <p>Remove panels to diagnose oil leak. Found the new hose replaced recently has a split in it. Ordered new hose again.</p> <p>Repair Hydraulic Hose/s as necessary,</p> <p>Remove hose and do temperary repair to hose and refit. Only to get to workshop to replace lift chains.</p> <p>Pickup new hose. Remove temp hose and fit new one. Topup hydraulic oil. Test ok. Clean truck and refit panels etc. Put back online.</p> |
| 1814754                    | Leaking hydraulic oil    | GOSMOND                           | 9/04/2026  | Internal                       | 11557.0  | \$0.00   |   |
| 1816055                    | Repair camera fault      | GOSMOND                           | 8/04/2026  | Internal                       | 11557.0  | \$0.00   | <p>Fit Full Camera Kit,</p> <p>Forward facing camera out if focus. Check wiring ok. Test with rear camera screen input ok. Remove front camera and dismantle. Focus locking screw has come loose. Adjust fogus correctly and fit locking screw. Reassemble camera and fit to truck. Test ok. Put back online.</p>   |
| 1812180                    | Replace lift chains      | GOSMOND                           | 7/04/2026  | Internal                       | 11557.0  | \$0.00   | <p>Replace Lift Chain,</p> <p>Steam clean equipment as necessary.</p> <p>Clean truck. Replace worn lift chain with new ones. Adjust chains and hoses. Put back online.</p>  |

| Job No.                    | Description   | Mechanic                          | Date       | Job Type                       | Eng. Hrs | Retail | Notes  |
|----------------------------|---|-----------------------------------|------------|--------------------------------|----------|--------|--|
| <b>Owner:</b> ADAP001      |   |                                   |            |                                |          |        |  |
| <b>Equip. Code:</b> H15952 |   | <b>Description:</b> HYSTER H155FT |            |                                |          |        |  |
| <b>Make:</b> HYSTER        |   | <b>Model:</b> H155FT              |            | <b>Serial No.:</b> L006V03566T |          |        |  |
| 1811877                    | oil leak  | GOSMOND                           | 24/03/2026 | Internal                       | 11488.0  | \$0.00 | Replace Hydraulic Hose/s and ancillary items,<br><br>Clean truck. Diagnose oil leak. Leak from small return hose under main control valve. Remove old hose and fit new one. Topup oil and test ok. Reassemble and put back online. Also tightened loose fan control knob. Steam clean equipment as necessary.  |
| 1806567                    | 11500hr II 500hr Service                                  | GOSMOND                           | 24/03/2026 | Internal                       | 11488.0  | \$0.00 | Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.<br><br>Clean truck. Perform 11500hr pm service. Replace worn fan belt.<br><br>Tynes 51mm. Chains need replacement, at 2.0% worn. Put back online. Repair Seat as necessary, |
| 1787496                    | there is a lot of movement in the seat when its locked in | GOSMOND                           | 3/03/2026  | Internal                       | 11347.0  | \$0.00 | Diagnose issue with seat. Seat is worn due to high hours, but most of the wear is in the locking seat adjustment slide. The slide off the replaced seat from H15955 is better so I swapped it out. Test ok. Put back online. Steam clean equipment as necessary.   |
| 1774066                    | 11250hr II 250hr Service                                  | GOSMOND                           | 16/02/2026 | Internal                       | 11241.0  | \$0.00 | 250hr Service<br><br>clean truck. Perform 11250hr pm service. Top up coolant. Adjusted the park brake. Chains 1.75%. Tynes 49.7mm. Put back online.  |

| Job No.  | Description                            | Mechanic | Date       | Job Type | Eng. Hrs | Retail | Notes   |
|--|--|----------|------------|----------|----------|--------|---|
| <b>Owner:</b> ADAP001<br><b>Equip. Code:</b> H15952 <b>Description:</b> HYSTER H155FT<br><b>Make:</b> HYSTER <b>Model:</b> H155FT <b>Serial No.:</b> L006V03566T |  |          |            |          |          |        |   |
| 1786255  | leaking oil                            | GOSMOND  | 11/02/2026 | Internal | 11241.0  | \$0.00 | <p>Check/Inspect/Diagnose Hydraulic Oil Leak and test operation,</p> <p>Remove ancillary items and Hydraulic Hose/s, inspect and report,</p> <p>Go to despatch where truck is broken down. Diagnose oil leak from hoses under the main control valve. Order parts. Remove suspect hoses.</p> <p>Labour</p> <p>Replace Hydraulic Hose/s and ancillary items,</p> <p>Replace Hydraulic Oil as Required</p> <p>Pickup parts. Fit new hoses. After MANY trips to other side of mill, topped up hydraulic tank. (was empty). Replace hyd filter. Drive back to workshop and clean oil from truck. Reassemble truck. Put back online.</p>   |
| 1776888  | Stopped in our yard and will not start | GOSMOND  | 12/01/2026 | Internal | 11161.0  | \$0.00 | <p>Remove ancillary items and Repair Wiring as necessary, Refit ancillary items,</p> <p>Repair Main Electrical Control Panel as necessary,</p> <p>Truck was stopping repeatedly. Diagnose issue. Went to truck and it started then stopped after 1 second with a truck disabled vsm-display mis match. It wouldn't restart. I could connect with pc service tool and there were no active fault codes. I isolated the batteries and then tried again. Now the display lights up all idiot lights and shows all zeros on the temp and fuel level displays. None of the buttons work and it won't crank. After a couple of seconds, it does a 30 second to shutdown and then powers off. Batteries have 12.3v. All fuses are ok. The canbus is 58.9Ohms. I back probed the wake up pin 513-A and it has 12v when the truck powers up. I swapped in a known good Display and VSM from another truck and the same problem happened again. Return both trucks back.</p> <p>After contacting contact management and going through the suggestions, still not resolved. Fault codes pointed to the display wiring. Dismantle dash and split loom. All wiring ok. No fault codes if rear can bus splice is isolated. Check can bus wiring to rest ok truck. Trans ok. Found damaged wiring on back of engine. Repaired and reassembled truck. Test ok. Put back online.</p> |

| Job No.                    | Description   | Mechanic                          | Date       | Job Type                       | Eng. Hrs | Retail | Notes  |
|----------------------------|---|-----------------------------------|------------|--------------------------------|----------|--------|--|
| <b>Owner:</b> ADAP001      |   |                                   |            |                                |          |        |  |
| <b>Equip. Code:</b> H15952 |   | <b>Description:</b> HYSTER H155FT |            |                                |          |        |  |
| <b>Make:</b> HYSTER        |   | <b>Model:</b> H155FT              |            | <b>Serial No.:</b> L006V03566T |          |        |  |
| 1769532                    | coming up with code 523612-5 and going into limp mode | GOSMOND                           | 3/12/2025  | Internal                       | 11069.0  | \$0.00 | Remove ancillary items and Repair Wiring as necessary, Refit ancillary items,<br><br>Diagnose fault code. Split loom and repair 5 suspect wires. Rewrap loom and test. ok. Reassemble truck and put back online.<br>Replace Switch/es  |
| 1767071                    | unit will not start                                   | GOSMOND                           | 25/11/2025 | Internal                       | 11016.0  | \$0.00 | Labour<br><br>Diagnose non crank. Operator reported after turning isolator on truck was dead. Operated isolation switch a few times and truck is ok. Travel to parts and get new switch. Replaced isolation switch and test. Ok. Put back online.  |
| 1761834                    | 11000hr II 1000hr Service + Replace Batteries         | SPitman                           | 16/11/2025 | Internal                       | 12345.0  | \$0.00 | Replace Battery,<br><br>1000hr Service<br><br>carry out service,didn't finish trans service.<br><br>Replace transfilter and oil. Rplace diff oil. Calibrate transmission. Investigate oil leak under control valve. Unable to pinpoint leak due to being so slow. Will check again at next service. Put back online. |
| 1760161                    | operators are having trouble locking in the seat      | SPitman                           | 29/10/2025 | Internal                       | 10850.0  | \$0.00 |  |
| 1756118                    | seat switch on forklift                               | GOSMOND                           | 13/10/2025 | Internal                       | 10794.0  | \$0.00 | Repair Switch/es<br><br>Complaint of seat switch. Pickup truck from inside mill. Return to workshop. Check wiring and switch. Ok. Adjust pressure needed to activate switch. Test ok. Put back online.   |
| 1752793                    | 10750hr II 250hr Service                              | GOSMOND                           | 8/10/2025  | Internal                       | 10745.0  | \$0.00 | Steam clean equipment as necessary.<br><br>250hr Service<br><br>Clean truck. Perform 10750hr pm service. Top up Hydraulic oil. Tynes 49mm. Chains 1.0%. Put back online.   |

| Job No.                    | Description   | Mechanic                          | Date       | Job Type                       | Eng. Hrs | Retail | Notes   |
|----------------------------|---|-----------------------------------|------------|--------------------------------|----------|--------|---|
| <b>Owner:</b> ADAP001      |   |                                   |            |                                |          |        |   |
| <b>Equip. Code:</b> H15952 |   | <b>Description:</b> HYSTER H155FT |            |                                |          |        |   |
| <b>Make:</b> HYSTER        |   | <b>Model:</b> H155FT              |            | <b>Serial No.:</b> L006V03566T |          |        |   |
| 1753396                    | leaking cylinder  | GOSMOND                           | 7/10/2025  | Internal                       | 10726.0  | \$0.00 | <p>Steam clean equipment as necessary.</p> <p>Remove ancillary items and Lift Cylinder, Strip, Inspect and report,</p> <p>Refit Lift Cylinder and ancillary items,</p> <p>Clean truck. Remove carriage. Remove leaking lhs lift cylinder. Reseal lift cylinder. Refit cylinder to truck.</p> <p>Refit Carriage and ancillary items,</p> <p>Refit carriage. Reconnect chains and adjust. Reconnect hoses and ziptie lines etc. Test for leaks ok. Put back online.</p> |
| 1751048                    | Seat switch playing up, stopping the machine intermittently | GOSMOND                           | 22/09/2025 | Internal                       | 10573.0  | \$0.00 | <p>Repair Seat Switch Wiring,</p> <p>Diagnose seat switch issue. Seat switch tests ok. Found bad connection in deutch plug. Rubber seal had rolled and not making full contact. Repinned wires with a new plug. Test ok. Put back online.</p>   |
| 1749576                    | Repair Seat   | GOSMOND                           | 17/09/2025 | Internal                       | 10532.0  | \$0.00 | <p>Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,</p> <p>Repair Tyne Latch as necessary,</p> <p>Replace seat base. Repair lhs door seal. Tighten loose rhs tyne positioner yoke. Put back online.</p>  |
| 1747326                    | 10500hr II 500hr Service                                    | BIG TRUCK SA                      | 17/09/2025 | Internal                       | 10532.0  | \$0.00 | <p>Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.</p> <p>Steam clean equipment as necessary.</p> <p>Clean truck. Perform 10500hr pm service. Adjust fan and a/c belts. Chains 1.5% Tynes 48.5mm. Put back online.</p>   |
| 1743440                    | 10250hr II 250hr Service                                    | GOSMOND                           | 29/08/2025 | Internal                       | 10273.0  | \$0.00 | <p>Steam clean equipment as necessary.</p> <p>250hr Service</p> <p>Clean truck. Perform 10250hr pm service. Adjust alternator belt. Chains 1.5% Tynes 48.5mm. Put back online.</p>  |

| Job No.                    | Description                                  | Mechanic                          | Date       | Job Type                       | Eng. Hrs | Retail | Notes  |
|----------------------------|--|-----------------------------------|------------|--------------------------------|----------|--------|--|
| <b>Owner:</b> ADAP001      |  |                                   |            |                                |          |        |  |
| <b>Equip. Code:</b> H15952 |  | <b>Description:</b> HYSTER H155FT |            |                                |          |        |  |
| <b>Make:</b> HYSTER        |  | <b>Model:</b> H155FT              |            | <b>Serial No.:</b> L006V03566T |          |        |  |
| 1738471                    | 10000hr II 2000hr Service                    | GOSMOND                           | 8/08/2025  | Internal                       | 10015.0  | \$0.00 | Steam clean equipment as necessary.<br><br>2000hr Service<br><br>5000hr Service<br><br>Clean truck. Perform 10000hr pm service. Valve set done on a seperate job. Chains 1.5% Tynes 48.5mm. Put back online.   |
| 1738821                    | H15952 - has a Fault 520306-1 Truck Disabled | GOSMOND                           | 6/08/2025  | Internal                       | 10015.0  | \$0.00 | Repair Charging Circuit as required,<br><br>Diagnose fault code. Unable to recreate fault. Put back online and check at service. Checked at service. Fault has not reappeared. Put back online.  |
| 1732619                    | H15952 - adjust valve set                    | GOSMOND                           | 14/07/2025 | Internal                       | 9757.0   | \$0.00 | Carry our valve clearence adjustments<br><br>Remove half the engine to access valves. Adjust valves. 2 inlet slightly loose and adjusted. Resr ok. Reassemble engine and test ok. Put back online.   |
| 1729813                    | 9750hr II 250hr Service                      | GOSMOND                           | 14/07/2025 | Internal                       | 9757.0   | \$0.00 | Steam clean equipment as necessary.<br><br>250hr Service<br><br>Clean truck. Perform 9750hr pm service. Top up coolant. Chains 1.5% Tynes 50 mm. Put back online.  |
| 1723030                    | Broken alternator belt                       | GOSMOND                           | 26/06/2025 | Internal                       | 9529.0   | \$0.00 | Repair Air Conditioner as necessary ,<br><br>Diagnose snapped a/c belt. Clutch bearing has failed. Organise with repairer to supply and regas system.<br><br>Replace Air Conditioner,<br><br>Re-gas Air Conditioner to correct specification ,<br><br>Remove and replace compressor and dryer after system was degassed. |
| 1727456                    | Replace carriage rollers                     | GOSMOND                           | 25/06/2025 | Internal                       | 9523.0   | \$0.00 | Repairer regassed system. Test ok. Put back online. Noticed failing carriage rollers on the service. Remove cariage and replace both lower rollers. Grease side rollers after dismantling and cleaning out grease ports. Refit carriage and put back online.   |
| 1724052                    | 9500hr II 500hr Service                      | GOSMOND                           | 23/06/2025 | Internal                       | 9506.0   | \$0.00 | Steam clean equipment as necessary.<br><br>Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.  |

| Job No.                    | Description              | Mechanic                          | Date       | Job Type                       | Eng. Hrs | Retail | Notes   |
|----------------------------|--------------------------|-----------------------------------|------------|--------------------------------|----------|--------|---|
| <b>Owner:</b> ADAP001      |                          |                                   |            |                                |          |        |   |
| <b>Equip. Code:</b> H15952 |                          | <b>Description:</b> HYSTER H155FT |            |                                |          |        |   |
| <b>Make:</b> HYSTER        |                          | <b>Model:</b> H155FT              |            | <b>Serial No.:</b> L006V03566T |          |        |   |
| 1721586                    | Fault Code 723-8         | GOSMOND                           | 2/06/2025  | Internal                       | 9466.0   | \$0.00 | Replace Switch/es<br><br>Diagnose fault code. Replaced cam sensor with known good due to broken mounting leg. Ordered a new part. Ordered new fan belt idler due to noisy bearing. Put back online.   |
| 1719181                    | 9250hr II 250hr Service  | GOSMOND                           | 30/05/2025 | Internal                       | 9307.0   | \$0.00 | Steam clean equipment as necessary.<br><br>250hr Service  |
| 1713472                    | 9000 II 1000hr Service   | GOSMOND                           | 8/05/2025  | Internal                       | 9031.0   | \$0.00 | Clean truck. Perform 9250hr pm service. Chains 1.3% tynes 50mm. Put back online.<br>Labour<br><br>Steam clean equipment as necessary.<br><br>3000hr Service<br><br>Clean and re-pack Steer Wheel Bearings,<br><br>Clean truck. Perform 9000hr pm service. Repack steer wheel bearings   |
| 1713596                    | Oil leak around carriage | GOSMOND                           | 29/04/2025 | Internal                       | 8910.0   | \$0.00 | Finish service. Tynes 50.00mm. Chains 1.25%. Put back online.<br>Remove ancillary items and Repair Hydraulic Oil Leak as necessary. Refit ancillary items,<br><br>Diagnose oil leak on carriage. Found loose fitting. Replace o ring and refit. Tighten to spec. Cleanup oil leak. Test ok. Put back online.  |
| 1707387                    | 8750hr II 250hr Service  | GOSMOND                           | 9/04/2025  | Internal                       | 8746.0   | \$0.00 | Steam clean equipment as necessary.<br><br>250hr Service<br><br>Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,<br><br>Repair Linkage/Lever as required,<br><br>Clean truck. Perform 8750hr pm service. Tighten alt belt. Topup coolant. Replace worn hydraulic control knobs. Repair sticking rhs door latch. Put back online. |

| Job No.                    | Description  | Mechanic                          | Date       | Job Type                       | Eng. Hrs | Retail | Notes   |
|----------------------------|--|-----------------------------------|------------|--------------------------------|----------|--------|---|
| <b>Owner:</b> ADAP001      |  |                                   |            |                                |          |        |   |
| <b>Equip. Code:</b> H15952 |  | <b>Description:</b> HYSTER H155FT |            |                                |          |        |   |
| <b>Make:</b> HYSTER        |  | <b>Model:</b> H155FT              |            | <b>Serial No.:</b> L006V03566T |          |        |   |
| 1704697                    | Codes appearing on dash & hard to start / feels underpowered | WHILL                             | 25/03/2025 | Internal                       | 8555.0   | \$0.00 | Travel to site,<br><br>Carry out Inspection and Diagnosis of Electrical System<br><br>Remove ancillary items and Repair Wiring as necessary, Refit ancillary items,<br><br>Travelled to site and located unit. Confirmed codes 636-8 & 636-2 on the dash and carried out diagnostic steps for each code. Checked sensors and found the locating tag broken. Ordered a new sensor. Carried out temp repair. Checked continuity of all wiring. Found the signal wire open circuit. Unable to locate the break. Fitted a bypass wire back to the ECU. Rechecked operation. Codes now cleared. Returned unit to service |
| 1704356                    | Wiper washers don't work                                     | WHILL                             | 24/03/2025 | Internal                       | 8555.0   | \$0.00 | Remove ancillary items and Repair Wiring as necessary, Refit ancillary items,<br><br>Travel to site,<br><br>Located unit. Checked all washers and wipers. Checked all pump connections. Checked wipers assemblies . All wipers amd washers now working. Returned unit to service. Returned to base<br>Steam clean equipment as necessary.   |
| 1701475                    | 8500hr II 500hr Service                                      | GOSMOND                           | 21/03/2025 | Internal                       | 8524.0   | \$0.00 | Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.<br><br>Clean truck. Perfrom 8500hr pm service. Tynes 51.3mm. Chains at 1.25%. Put back online.<br>250hr Service  |
| 1697858                    | 8250hr II 250hr Service                                      | GOSMOND                           | 5/03/2025  | Internal                       | 8327.0   | \$0.00 | carry out 250hr service<br><br>Perform 8250hr pm service. Chains 0.75% Put back online.   |
| 1699424                    | Tyne side shift carrier broken on one side                   | GOSMOND                           | 4/03/2025  | Internal                       | 8309.0   | \$0.00 | Replace Tyne Latch,<br><br>Remove broken tyne carrier from truck. Cut pin support off old carrier. Weld on to new carrier(customer supplied). Refit to truck and put back online.   |
| 1693862                    | Chain inspection & sheeve roller assessment                  | GOSMOND                           | 14/02/2025 | Internal                       | 8102.0   | \$0.00 | Carry out Inspection and Diagnosis of Mast/Carriage<br><br>Perform sheave and chain inspection. No movement in sheave. Chain is 50% worn. Put back online.  |

| Job No.                    | Description  | Mechanic                          | Date       | Job Type                       | Eng. Hrs | Retail     | Notes  |
|----------------------------|--|-----------------------------------|------------|--------------------------------|----------|------------|--|
| <b>Owner:</b> ADAP001      |  |                                   |            |                                |          |            |  |
| <b>Equip. Code:</b> H15952 |  | <b>Description:</b> HYSTER H155FT |            |                                |          |            |  |
| <b>Make:</b> HYSTER        |  | <b>Model:</b> H155FT              |            | <b>Serial No.:</b> L006V03566T |          |            |  |
| 1690878                    | 8000hr II 4000hr Service                               | GOSMOND                           | 11/02/2025 | Internal                       | 8047.0   | \$0.00     | Steam clean equipment as necessary.<br><br>4000hr Service,<br><br>Clean truck. Perform 8000hr pm service. Replace hyd oil and filter. Change trans oil and filter. Calibrate trans. Change diff oil. Change fan belt.  |
| 1671097                    | Carry Out A/C modification as per quote 34815 (H15952) | GOSMOND                           | 13/01/2025 | External                       | 7732.0   | \$6,081.23 | Put back online.<br>Supply and install custom air conditioning modules to Hyster 7 tonne fleets across Bellbay and Mount Gambia sites.   |
| 1682448                    | Replace tie rod ends                                   | GOSMOND                           | 19/12/2024 | Internal                       | 7729.0   | \$0.00     | Replace Tie Rod End/s,   |
| 1678134                    | 7750hr II 250hr Service                                | GOSMOND                           | 19/12/2024 | Internal                       | 7729.0   | \$0.00     | Replace worn out lhs tie rod. Put back online.<br>Steam clean equipment as necessary.<br><br>250hr Service   |
| 1676290                    | A/C Not Working  | GOSMOND                           | 27/11/2024 | Internal                       | 7523.0   | \$0.00     | Clean truck. Perform 7750hr pm service. Reroute a/c line from rubbing. Put back online.<br>Repair Air Conditioner as necessary,<br><br>Labour  |
| 1676022                    | Failing steer wheel bearing                            | GOSMOND                           | 26/11/2024 | Internal                       | 7729.0   | \$0.00     | Pickup parts. Replace both condensor fans. Check operation. Ok. Put back online.<br>Clean and re-pack Steer Wheel Bearings,<br><br>Bearings worn. No parts in stock. Regrease old bearings and reassemble. Order new parts as needed.<br><br>Labour<br><br>Replace Steer Wheel Bearings,   |
| 1674457                    | 7500hr II 500hr Service                                | GOSMOND                           | 26/11/2024 | Internal                       | 7511.0   | \$0.00     | Pickup parts. Remove RHS steer wheel and remove old bearings. Fit new bearings and reassemble. Put back online.<br>Steam clean equipment as necessary.<br><br>Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.<br><br>Clean truck. Perform 7500hr pm service. Put back online. |

| Job No.                    | Description                | Mechanic                          | Date       | Job Type                       | Eng. Hrs | Retail | Notes  |
|----------------------------|----------------------------|-----------------------------------|------------|--------------------------------|----------|--------|--|
| <b>Owner:</b> ADAP001      |                            |                                   |            |                                |          |        |  |
| <b>Equip. Code:</b> H15952 |                            | <b>Description:</b> HYSTER H155FT |            |                                |          |        |  |
| <b>Make:</b> HYSTER        |                            | <b>Model:</b> H155FT              |            | <b>Serial No.:</b> L006V03566T |          |        |  |
| 1675603                    | AC not working             | GOSMOND                           | 25/11/2024 | Internal                       | 7511.0   | \$0.00 | Repair Air Conditioner as necessary,<br><br>Diagnose poor a/c. Blow out coolers. Tighten belt. Test system. Works ok. Put back online.   |
| 1673126                    | UHF has come loose         | GOSMOND                           | 15/11/2024 | Internal                       | 7444.0   | \$0.00 | Repair Radio,<br><br>Uhf mounting loose. Replace bolts and secure. Refit radio and test. Ok. Put back to work.   |
| 1666798                    | oil leak underneath on RHS | GOSMOND                           | 23/10/2024 | Internal                       | 7260.0   | \$0.00 | Remove ancillary items and Repair Hydraulic Oil Leak as necessary. Refit ancillary items,<br><br>Oil leak rhs front. Diagnose. Found return line from control valve to tank loose at valve. Tighten and check for leaks. ok. Cleanup leak and reassemble truck. Put back online. |
| 1655407                    | 7250hr II 250hr Service    | GOSMOND                           | 23/10/2024 | Internal                       | 7260.0   | \$0.00 | Steam clean equipment as necessary.<br><br>250hr Service<br><br>Clean truck. Perform 7250hr pm service. Tidy up ends of tynes. Put back online.  |
| 1654775                    | Replace dash display       | GOSMOND                           | 9/09/2024  | Internal                       | 7021.0   | \$0.00 | Repair Gauge/s<br><br>Order part to replace unreadable dash display<br><br>Replace Visual display unit,<br><br>Finish fitting new dash display. Test ok. Put back online.  |
| 1639054                    | 7000hr II 1000hr Service   | BIG TRUCK SA                      | 5/09/2024  | Internal                       | 7012.0   | \$0.00 | Steam clean equipment as necessary.<br><br>1000hr Service  |
| 1627684                    | 6750hr II 250hr Service    | BIG TRUCK SA                      | 3/07/2024  | Internal                       | 6777.0   | \$0.00 | Clean truck. Perform 7000hr pm service. Put back online. Steam clean equipment as necessary.<br><br>250hr Service  |
| 1633308                    | Stuck tynes                | GOSMOND                           | 18/06/2024 | Internal                       | 6652.0   | \$0.00 | Clean truck. Perform 6750hr pm service. Tighten loose rhs tyne positioner yoke. Put back online.<br>Repair Tyne Latch as necessary,  |
| 1626751                    | No blue light              | GOSMOND                           | 23/05/2024 | Internal                       | 6597.0   | \$0.00 | Diagnose lh tyne getting stuck. Found a clearance issue on back of tyne. Rectified the issue and test. ok. Put back online.<br>Repair Light/s<br><br>No blue light but reverse buzzer ok. Trace wiring and make repairs. Test ok. Put back online                                |

| Job No.                    | Description                                  | Mechanic                          | Date       | Job Type                       | Eng. Hrs | Retail   | Notes  |
|----------------------------|--|-----------------------------------|------------|--------------------------------|----------|----------|--|
| <b>Owner:</b> ADAP001      |  |                                   |            |                                |          |          |  |
| <b>Equip. Code:</b> H15952 |  | <b>Description:</b> HYSTER H155FT |            |                                |          |          |  |
| <b>Make:</b> HYSTER        |  | <b>Model:</b> H155FT              |            | <b>Serial No.:</b> L006V03566T |          |          |  |
| 1625722                    | REPLACE WORN TYNES                           | GOSMOND                           | 21/05/2024 | External                       | 6595.0   | \$231.00 | Replace Forks/Tynes,<br><br>Swap worn out tynes for newish ones. Customer supplied. Check adjustment ok. Put back online.  |
| 1625490                    | Repair grease lines                          | GOSMOND                           | 20/05/2024 | Internal                       | 6502.0   | \$0.00   | Steam clean equipment as necessary.<br><br>Grease All Points on Unit,<br><br>Noticed damaged grease line. Shorten line and reroute out of danger. Fit connector and test ok. Put back online.  |
| 1623376                    | Failed fan belt                              | GOSMOND                           | 14/05/2024 | Internal                       | 6559.0   | \$0.00   | Replace Fan Belt,<br><br>Replace fan belt with 2nd hand one as no new ones in stock. Put back online.  |
| 1613865                    | 6500hr II 500hr Service                      | GOSMOND                           | 7/05/2024  | Internal                       | 6515.0   | \$0.00   | Steam clean equipment as necessary.<br><br>Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.  |
| 1607574                    | 3G Sunset Device Swap (FM1 to VAM)           | GOSMOND                           | 7/05/2024  | Internal                       | 6515.0   | \$0.00   | Clean truck. Perform 6500hr pm service. Put back online. Replace Fleet Management System as required,<br><br>Swap FM1 to VAM. Update settings. Test ok. Put back online.   |
| 1617060                    | Battery / Failing battery Smell inside cabin | SPitman                           | 19/04/2024 | Internal                       | 6411.0   | \$0.00   | Travel to site,<br><br>Repair Traction Battery<br><br>Remove ancillary items and Remove Battery from unit and Inspect and report,<br><br>Replace Battery,<br><br>check charge rate,load test batteries,found one battery below minimum spec,replace 2x batteries |
| 1604831                    | Replace camera system                        | GOSMOND                           | 17/04/2024 | Internal                       | 6398.0   | \$0.00   | Carry out Inspection and Diagnosis of Electrical System<br>Remove and Replace Camera,<br><br>Fit Full Camera Kit,<br><br>Remove camera kit. Fit new kit.<br><br>Fit camera kit. Test ok. Put back online.  |

| Job No.                    | Description                               | Mechanic                          | Date       | Job Type                       | Eng. Hrs | Retail | Notes   |
|----------------------------|---|-----------------------------------|------------|--------------------------------|----------|--------|---|
| <b>Owner: ADAP001</b>      |   |                                   |            |                                |          |        |   |
| <b>Equip. Code: H15952</b> |   | <b>Description: HYSTER H155FT</b> |            |                                |          |        |   |
| <b>Make: HYSTER</b>        |   | <b>Model: H155FT</b>              |            | <b>Serial No.: L006V03566T</b> |          |        |   |
| 1602002                    | 6250hr II 250hr Service                   | GOSMOND                           | 14/03/2024 | Internal                       | 6234.0   | \$0.00 | Steam clean equipment as necessary.<br><br>250hr Service  |
| 1602583                    | Blow out AC                               | SPitman                           | 21/02/2024 | Internal                       | 6058.0   | \$0.00 | Clean truck. Perform 6250hr pm service. Put back online.<br>Repair Air Conditioner as necessary,<br><br>remove ac box covers,blow out,rrfit,blow out condensor and evaporator cores,clean filters,test operation.   |
| 1584946                    | 6000hr II 2000hr Service                  | GOSMOND                           | 7/02/2024  | Internal                       | 5975.0   | \$0.00 | Steam clean equipment as necessary.<br><br>2000hr Service   |
| 1595647                    | fault code 523578-2                       | GOSMOND                           | 24/01/2024 | Internal                       | 4970.0   | \$0.00 | Complete pm service.<br>Remove ancillary items and Repair Wiring as necessary,<br>Refit ancillary items,<br><br>Follow diagnostic troubleshooting guide. Wiring and power supply ok. Test ok. Put back online.  |
| 1595103                    | ENGINE ERROR CODE                         | GOSMOND                           | 22/01/2024 | Internal                       | 5894.0   | \$0.00 | Truck back online for a week. No Codes<br>Remove ancillary items and Repair Wiring as necessary,<br>Refit ancillary items,<br><br>Diagnose 636-2 code. All wiring ok. Remove shim from crank sensor and test. OK. Reassemble truck and put back online.   |
| 1586225                    | code 636-2 appearing on screen            | GOSMOND                           | 22/12/2023 | Internal                       | 5894.0   | \$0.00 | Remove ancillary items and Repair Wiring as necessary,<br>Refit ancillary items,<br><br>unit has code 636-2 crank sensor fault,diagnose,sensor ground wire open circuit,tried to find break in wiring,run test wire,cde still present.<br><br>Pin out wiring and record<br><br>retraced crank sensor wiring from sensor to ecu checked wiring for faults couldn't fault,either sensor or ecu fault. |
| 1586476                    | COOLANT LEAK                              | GOSMOND                           | 11/12/2023 | Internal                       | 5894.0   | \$0.00 | Replace Water Pump,<br><br>Coolant leak. Replace water pump. Refill with coolant and test. Ok. Put back online.   |
| 1573632                    | 5750hr II 250hr Service 0250 Hour Service | BIG TRUCK SA                      | 29/11/2023 | Internal                       | 5776.0   | \$0.00 | Steam clean equipment as necessary.<br><br>250hr Service<br><br>carry out 250hr service,steam clean.  |

| Job No.                    | Description              | Mechanic                          | Date       | Job Type                       | Eng. Hrs | Retail | Notes  |
|----------------------------|--------------------------|-----------------------------------|------------|--------------------------------|----------|--------|--|
| <b>Owner:</b> ADAP001      |                          |                                   |            |                                |          |        |  |
| <b>Equip. Code:</b> H15952 |                          | <b>Description:</b> HYSTER H155FT |            |                                |          |        |  |
| <b>Make:</b> HYSTER        |                          | <b>Model:</b> H155FT              |            | <b>Serial No.:</b> L006V03566T |          |        |  |
| 1574307                    | NO START                 | GOSMOND                           | 23/10/2023 | Internal                       | 5505.0   | \$0.00 | Replace Battery,<br><br>Diagnose non crank. Jumpstart and load test batteries. One ok other u/s. Replace failed battery with known good spare. Test start ok. Charging at 13.8v. Put back online. Steam clean equipment as necessary.  |
| 1565174                    | 5500hr II 500hr Service  | GOSMOND                           | 17/10/2023 | Internal                       | 5495.0   | \$0.00 | Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.   |
| 1551626                    | 5250hr II 250hr Service  | GOSMOND                           | 29/08/2023 | Internal                       | 5240.0   | \$0.00 | Clean truck. Perform 5500hr pm service. Trim tynes. Put back online.<br>250hr Service<br><br>Perform 5250hr pm service. Adjust fan belt. Put back online<br><br>Perform 5250hr pm service. Adjust fan belt. Put back online  |
| 1549847                    | replace lift chains      | GOSMOND                           | 17/07/2023 | Internal                       | 5045.0   | \$0.00 | Replace Lift Chain,<br><br>Replace worn out lift chains. Tighten rhs tyne positioner yoke. Put back online.  |
| 1536839                    | 5000hr II 1000hr Service | GOSMOND                           | 14/07/2023 | Internal                       | 5044.0   | \$0.00 | Steam clean equipment as necessary.<br><br>5000hr Service<br><br>Perform 5000hr pm service. Replace fan belt. Calibrate transmission. Put back online.   |
| 1541258                    | No start                 | GOSMOND                           | 13/06/2023 | Internal                       | 4910.0   | \$0.00 | Repair Battery terminal/s as required,<br><br>No crank. Hookup jump batteries still no good. Charge jump pack and try again. Still no good.<br><br>Replace Battery,<br><br>Adjust Transmission Control Valve to correct specification ,<br><br>Diagnose no crank. Batteries failed internally. Swap batteries out of 56 and test. ok. Order new batteries. Calibrate trans to clear code. Put back online. |

| Job No.                    | Description  | Mechanic                          | Date       | Job Type                       | Eng. Hrs | Retail      | Notes  |
|----------------------------|--|-----------------------------------|------------|--------------------------------|----------|-------------|--|
| <b>Owner:</b> ADAP001      |  |                                   |            |                                |          |             |  |
| <b>Equip. Code:</b> H15952 |  | <b>Description:</b> HYSTER H155FT |            |                                |          |             |  |
| <b>Make:</b> HYSTER        |  | <b>Model:</b> H155FT              |            | <b>Serial No.:</b> L006V03566T |          |             |  |
| 1535172                    | FM1 fault  | WHILL                             | 16/05/2023 | Internal                       | 4794.0   | \$0.00      | Carry out Inspection and Diagnosis of Telemetry System<br><br>Repair Fleet Management System as required,<br><br>Travelled to site and located unit. Tested unit extensively and was unable to fault. Checked all connections and returned unit to service<br>Steam clean equipment as necessary.  |
| 1524190                    | 4750 II 250hr service  | WHILL                             | 16/05/2023 | Internal                       | 4785.0   | \$0.00      | 250hr Service<br><br>Located unit and cleaned. Carried out service as per schedule   |
| 1533039                    | Damaged carriage   | 511 Planning C                    | 8/05/2023  | External                       | 4722.0   | \$350.00    |  |
| 1522219                    | Hydraulic controls have come loose   | GOSMOND                           | 21/03/2023 | Internal                       | 4476.0   | \$0.00      |  |
| 1522151                    | Control levers falling off dash  | GOSMOND                           | 21/03/2023 | Internal                       | 4476.0   | \$0.00      | Repair Linkage/Lever as required,<br><br>Hyd levers loose. Remove dash lower cover and find missing bolt in pivot assembly. Refit bolt with loctite and tighten bolt at other end. Test ok. Refit covers and put back online.  |
| 1513610                    | 4500 II 500hr service<br>Hyster L006_0500Hr Service<br>Kit_Dsl_H155FT MB. 0500 Hour<br>Service | GOSMOND                           | 13/03/2023 | Internal                       | 4476.0   | \$0.00      | Steam clean equipment as necessary.<br><br>Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.  |
| 1517232                    | Damaged carriage   | GOSMOND                           | 28/02/2023 | External                       | 4428.0   | -\$1,787.36 | Clean truck. Perform 4500hr pm service. Adjust lhs steer wheel bearings. Put back online.<br>Clean truck. Angle grind bent support bar from carriage. Straighten in press. Grind ends ready to reweld back in truck.<br>Heat and beat tyne carrier back into shape. Cut and weld support angle on carrier where it was cracked. Weld support bar back in place. Straighten bent cammera mount and replace missing bolt. Put back online. |
| 1510480                    | Check steer wheel bearings   | GOSMOND                           | 31/01/2023 | Internal                       | 4257.0   | \$0.00      | Clean and re-pack Steer Wheel Bearings,<br><br>Replace Tie Rod End/s,<br><br>Repack steer wheel bearings, reassemble and test ok. Replace worn out lhs tie rod end. Cleanup after job. Put back online.  |
| 1499026                    | 4250 II 250hr service<br>0250 Hour Service   | GOSMOND                           | 31/01/2023 | Internal                       | 4257.0   | \$0.00      | Steam clean equipment as necessary.<br><br>250hr Service<br><br>Clean truck. Perform 4250hr pm service. Put back online.   |

| Job No.                    | Description   | Mechanic                          | Date       | Job Type                       | Eng. Hrs | Retail | Notes   |
|----------------------------|---|-----------------------------------|------------|--------------------------------|----------|--------|---|
| <b>Owner:</b> ADAP001      |   |                                   |            |                                |          |        |   |
| <b>Equip. Code:</b> H15952 |   | <b>Description:</b> HYSTER H155FT |            |                                |          |        |   |
| <b>Make:</b> HYSTER        |   | <b>Model:</b> H155FT              |            | <b>Serial No.:</b> L006V03566T |          |        |   |
| 1498796                    | Non start   | GOSMOND                           | 2/12/2022  | Internal                       | 4003.0   | \$0.00 | Repair Attachment as necessary,<br><br>Diagnose non start. Ignition relay trigger from FM1 module failed. Replace FM1 module and get coded. Test ok. Put truck back online.<br>Steam clean equipment as necessary.  |
| 1497665                    | 4000 II 4000hr service<br>Hyster L006_4000Hr Service<br>Kit_Dsl_H155FT MB. 4000 Hour<br>Service | GOSMOND                           | 2/12/2022  | Internal                       | 4003.0   | \$0.00 | 4000hr Service,<br><br>Clean truck. Carry out 4000hr pm service. Calibrate transmission. Blow out evaporator. Put back online.<br>Steam clean equipment as necessary.   |
| 1489405                    | 3750 II 250hr service<br>0250 Hour Service  | GOSMOND                           | 16/11/2022 | Internal                       | 3815.0   | \$0.00 | 250hr Service<br><br>Clean truck. Perform 3750hr pm service. Adjust a/c belt. Put back online.<br>Steam clean equipment as necessary.   |
| 1477033                    | 3500 II 500hr service Hyster<br>L006_0500Hr Service<br>Kit_Dsl_H155FT MB. 0500 Hour<br>Service  | 511 Planning B                    | 10/10/2022 | Internal                       | 3499.0   | \$0.00 | Clean truck.<br><br>Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.<br><br>Carry out 3500hr pm service. Top up coolant. Put back online. |
| 1477639                    | Faulty seat switch  | GOSMOND                           | 7/09/2022  | Internal                       | 3304.0   | \$0.00 | Repair Seat Switch Wiring,<br><br>Diagnose issue with seat switch. Traced to corrosion on cushion type seat switch. Repurposed timeout switch in seat base to use as seat switch for the fm1. Tidy up wiring an test ok. Put back online.                           |
| 1464324                    | 3250 II 250hr service<br>0250 Hour Service  | 511 Planning A                    | 31/08/2022 | Internal                       | 3257.0   | \$0.00 | Steam clean equipment as necessary.<br><br>250hr Service<br><br>Clean Truck. Perform 3250hr pm service. Put back online.  |

| Job No.                    | Description   | Mechanic                          | Date       | Job Type                       | Eng. Hrs | Retail   | Notes   |
|----------------------------|---|-----------------------------------|------------|--------------------------------|----------|----------|---|
| <b>Owner:</b> ADAP001      |   |                                   |            |                                |          |          |   |
| <b>Equip. Code:</b> H15952 |   | <b>Description:</b> HYSTER H155FT |            |                                |          |          |   |
| <b>Make:</b> HYSTER        |   | <b>Model:</b> H155FT              |            | <b>Serial No.:</b> L006V03566T |          |          |   |
| 1472335                    | Forktrack fault   | GOSMOND                           | 16/08/2022 | Internal                       | 3499.0   | \$0.00   | Remove ancillary items and Repair Wiring as necessary, Refit ancillary items,<br><br>Diagnose fort track issue not allowing log on. Found damage to plugs on fm1 module from piece of wood. Straighten pins and test ok. Antenna destroyed so ordered part to replace it. Fitted temp antenna to get truck back online.<br><br>Repair Attachment as necessary,<br><br>Run cable for new antenna. Test ok. Reassemble truck. Put back online.<br>Repair Handbrake Lever as required, |
| 1465792                    | Repair Park Brake   | GOSMOND                           | 18/07/2022 | Internal                       | 3033.0   | \$0.00   | Free up seized Lhs park brake lever. Put back online. Steam clean equipment as necessary.   |
| 1461021                    | 3000 II 3000hr service. 0250 Hour Service Hyster L006_1000Hr Service Kit_Dsl_H155FT MB. 1000 Hour Service | GOSMOND                           | 8/07/2022  | Internal                       | 3032.0   | \$0.00   | 3000hr Service<br><br>Clean truck. Perform 3000hr pm service. Calibrate transmission. Put back online. Cleanup after job.   |
| 1455744                    | Damaged Tyne carrier  | GOSMOND                           | 2/06/2022  | External                       | 2793.0   | \$346.35 | Damaged Tyne carrier<br>Cut out support bar and straighten, weld back in place. Remove lhs tyne carrier, beat and heat back into shape. Weld up split side and cut and weld in support bracket. Refit tyne and carrier. Put back online.  |
| 1446284                    | 2750 II 250hr service. 0250 Hour Service  | GOSMOND                           | 11/05/2022 | Internal                       | 2734.0   | \$0.00   |   |
| 1440231                    | Customer Damage - Repairs to tyne carrier   | GOSMOND                           | 23/03/2022 | External                       | 2720.0   | \$167.00 | Customer Damage - Repairs to tyne carrier<br>Repair Tyne Latch as necessary,<br>Straighten bent lhs tyne carrier. Put back online.  |
| 1439413                    | 2750hr service II 250hr type service. 0250 Hour Service   | GOSMOND                           | 23/03/2022 | Internal                       | 2720.0   | \$0.00   | 250hr Service<br><br>Clean truck. Perform 2750 hr pm service. Tighten belts. Missing tilt pin anchor. Make one and fit. Put back online.  |
| 1439991                    | Replaced cracked beacon light bracket   | GOSMOND                           | 22/03/2022 | Internal                       | 2720.0   | \$0.00   | Repair Revolving/Flashing/Strobe light as required,<br><br>Notice cracked beacon/light bracket. Make new reinforcing plate and remount beacon and lights. Put back online.  |

| Job No.                    | Description  | Mechanic                          | Date       | Job Type                       | Eng. Hrs | Retail   | Notes  |
|----------------------------|--|-----------------------------------|------------|--------------------------------|----------|----------|--|
| <b>Owner:</b> ADAP001      |  |                                   |            |                                |          |          |  |
| <b>Equip. Code:</b> H15952 |  | <b>Description:</b> HYSTER H155FT |            |                                |          |          |  |
| <b>Make:</b> HYSTER        |  | <b>Model:</b> H155FT              |            | <b>Serial No.:</b> L006V03566T |          |          |  |
| 1439144                    | Forklift H15952 is having issues with the seat switch occasionally.            | GOSMOND                           | 17/03/2022 | Internal                       | 2720.0   | \$0.00   | Repair Seat Switch Wiring,<br><br>Diagnose issue with seat switch. Unable to recreate problem. Check wiring and pad position ok.<br><br>Repair Seat as necessary,  |
| 1437642                    | Customer Damage 9.3.22 - Bent Tyne Carrier                                     | GOSMOND                           | 9/03/2022  | External                       | 2647.0   | \$180.00 | Will put back online and monitor problem.<br>Customer Damage 9.3.22 - Bent Tyne Carrier<br>Repair Tyne Latch as necessary,<br>Diagnose bent lhs tyne carrier.<br>heat and straighten tyne carrier.<br>NOTE: Photos on j/n 1421704<br>Put back online.  |
| 1421704                    | Scheduled Service - 2500hr service. .0500 Hour Service                         | GOSMOND                           | 9/03/2022  | Internal                       | 2647.0   | \$0.00   | Travel to site,<br><br>Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.<br><br>Steam clean equipment as necessary.<br><br>Travelled to site and located unit. Carried out service as per schedule. Cleaned unit and returned to service. (noted damaged lh tyne carrier that was fixed on another job) |
| 1422865                    | Parts to Job #1415690 Scheduled Service - 2250hr service 0250 Hour Service     | 511 Planning C                    | 23/12/2021 | Internal                       | 2309.0   | \$0.00   | Perform 2500hr pm service. Put back online.  |
| 1422862                    | Parts to Job #1417223 - Scheduled Service - 5000hr service. .1000 Hour Service | 511 Planning C                    | 23/12/2021 | Internal                       | 2309.0   | \$0.00   |  |
| 1417214                    | Scheduled Service - 2250hr service.  | 511 Planning D                    | 20/12/2021 | Internal                       | 2093.0   | \$0.00   |  |
| 1415690                    | Scheduled Service - 2250hr service 0250 Hour Service                           | WHILL                             | 20/12/2021 | Internal                       | 2292.0   | \$0.00   | 250hr Service<br><br>Replace Fan Belt,<br><br>Carried out service as per schedule. Replaced cracked serp belt.   |
| 1418783                    | Adjust loose lift chain  | GOSMOND                           | 3/12/2021  | Internal                       | 2300.0   | \$0.00   | Adjust Lift Chain to correct specification,<br><br>Adjust RHS lift chain which had come loose. Fitted nylock nuts to fix problem permanently. (supplied by customer).<br>Put back online.  |

| Job No.                    | Description  | Mechanic                          | Date       | Job Type                       | Eng. Hrs | Retail | Notes   |
|----------------------------|--|-----------------------------------|------------|--------------------------------|----------|--------|---|
| <b>Owner:</b> ADAP001      |  |                                   |            |                                |          |        |   |
| <b>Equip. Code:</b> H15952 |  | <b>Description:</b> HYSTER H155FT |            |                                |          |        |   |
| <b>Make:</b> HYSTER        |  | <b>Model:</b> H155FT              |            | <b>Serial No.:</b> L006V03566T |          |        |   |
| 1411440                    | Scheduled Service - 2000hr service II 2000hr type. Hyster L006_2000Hr Service Kit_Dsl_H155FT MB. 2000 Hour Service | WHILL                             | 12/11/2021 | Internal                       | 1970.0   | \$0.00 | Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.<br><br>Travel to site,<br><br>2000hr Service<br>Steam clean equipment as necessary.<br><br>250hr Service   |
| 1399820                    | Scheduled Service - 1750hr service II 250hr type. .0250 Hour Service   | GOSMOND                           | 14/09/2021 | Internal                       | 1730.0   | \$0.00 | Clean truck. Perform 1750hr pm service. Put back online. Repair Main Electrical Control Panel as necessary,<br><br>Diagnose no crank. FM1 module not triggering relays. Order new unit. Truck offline.<br><br>Labour<br><br>Travel to site,<br><br>Pickup parts. No parts as wasn't picked up by tnt in adelaide. Travel to site.<br><br>Replace Main Electrical Panel,<br><br>Pickup parts and travel to job. Remove old fm1 and fit new one. Ring up and get coded. Test ok. Refit all panels. Put back online. |
| 1401601                    | Non crank  | GOSMOND                           | 13/09/2021 | Internal                       | 1730.0   | \$0.00 | Adjust Lift Chain to correct specification,<br><br>Adjust loose lift chains. Put back online. Steam clean equipment as necessary.   |
| 1397236                    | Adjust Lift Chains   | GOSMOND                           | 20/08/2021 | Internal                       | 1593.0   | \$0.00 | Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.<br><br>Clean truck. Perform 1500hr pm service. Adjust lift chains. Adjust fan belt. Put back online. Repair Air Conditioner as necessary,<br><br>Modify system with more filtration. Remove top of heater box and blow out all dust. Fabricate soft ride accumulator bracket and fit. Put back online.                                 |
| 1385084                    | Scheduled Service - 1500hr service II 500hr type. Hyster L006_0500Hr Service Kit_Dsl_H155FT MB. 0500 Hour Service  | GOSMOND                           | 12/07/2021 | Internal                       | 1494.0   | \$0.00 |   |
| 1376165                    | Repair poor a/c performance  | GOSMOND                           | 12/05/2021 | Internal                       | 1289.0   | \$0.00 |   |

| Job No.                    | Description                                      | Mechanic                          | Date       | Job Type                       | Eng. Hrs | Retail | Notes   |
|----------------------------|--|-----------------------------------|------------|--------------------------------|----------|--------|---|
| <b>Owner: ADAP001</b>      |  |                                   |            |                                |          |        |   |
| <b>Equip. Code: H15952</b> |  | <b>Description: HYSTER H155FT</b> |            |                                |          |        |   |
| <b>Make: HYSTER</b>        |  | <b>Model: H155FT</b>              |            | <b>Serial No.: L006V03566T</b> |          |        |   |
| 1369135                    | Scheduled Service - 1250hr service II 250hr type | GOSMOND                           | 28/04/2021 | Internal                       | 1283.0   | \$0.00 | Steam clean equipment as necessary.<br><br>250hr Service  |
| 1362813                    | swap tines with unit 56                          | GOSMOND                           | 9/03/2021  | Internal                       | 1024.0   | \$0.00 | Clean truck. Perform 1250hr pm service. Put back online. Refit Forks/Tynes and ancillary items,<br><br>Swap bent tyne off truck to better one on H15956. Put back online.   |
| 1350037                    | Scheduled Service - 1000 Hour Service            | GOSMOND                           | 2/03/2021  | Internal                       | 1024.0   | \$0.00 | Steam clean equipment as necessary.<br><br>1000hr Service<br><br>Adjust Transmission Control Valve to correct specification ,<br><br>Clean truck. Perform 1000hr pm service. Calibrate transmission. Put back online.   |
| 1334229                    | Scheduled Service - 750hr service II 250hr type  | GOSMOND                           | 9/11/2020  | Internal                       | 795.0    | \$0.00 | Steam clean equipment as necessary.<br><br>250hr Service  |
| 1336954                    | CW - Loose mast chain - Parked up                | GOSMOND                           | 30/10/2020 | Internal                       | 693.0    | \$0.00 | Clean truck. Perform 750hr pm service. Put back online. Adjust loose lift chain. Put back online.   |
| 1308289                    | Scheduled Service- 500hr service II 500hr type.  | GOSMOND                           | 28/09/2020 | Internal                       | 534.0    | \$0.00 | Steam clean equipment as necessary.<br><br>Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.<br><br>Repair Air Conditioner as necessary ,<br><br>Clean truck. Perform 500hr pm service. Tidy up wiring around fuel filter to ease access. Remove a/c recirculation pipe and block off. Put back online. Clean up workshop. |
| 1325942                    | Losing Power - Park brake sticking               | GOSMOND                           | 9/09/2020  | Internal                       | 406.0    | \$0.00 | Repair Handbrake Lever as required,   |
| 1323288                    | Fork keeps cutting out while in use - Parked up  | WHILL                             | 27/08/2020 | Internal                       | 364.0    | \$0.00 | Diagnose low power. Park brake dragging. Free up seized park brake levers. Test ok. Put back online. Repair Fleet Management System as required, Confirmed fault. Traced to faulty seat switch. Replaced seat switch<br>Unable to claim warranty for non genuine part   |

| Job No.                    | Description  | Mechanic                          | Date       | Job Type                       | Eng. Hrs | Retail   | Notes   |
|----------------------------|--|-----------------------------------|------------|--------------------------------|----------|----------|---|
| <b>Owner:</b> ADAP001      |  |                                   |            |                                |          |          |   |
| <b>Equip. Code:</b> H15952 |  | <b>Description:</b> HYSTER H155FT |            |                                |          |          |   |
| <b>Make:</b> HYSTER        |  | <b>Model:</b> H155FT              |            | <b>Serial No.:</b> L006V03566T |          |          |   |
| 1320082                    | Seat switch faulty                                       | GOSMOND                           | 12/08/2020 | External                       | 369.0    | \$354.50 | Repair Seat as necessary,<br><br>Diagnose shutting down. Check seat switch and wiring. Reposition seat switch and test. ok. Make and fit spacers to cab air filter can so I can get the filter out. Put back online |
| 1308313                    | 250hr service  | GOSMOND                           | 19/06/2020 | Internal                       | 1271.0   | \$0.00   | Seat switch replaced by Wayde on another job whilst I was on leave.<br>Steam clean equipment as necessary.<br><br>250hr Service<br><br>Adjust Lift Chain to correct specification,                                  |
| 1302929                    | Scheduled Service- 100hr service                         | GOSMOND                           | 9/06/2020  | Internal                       | 127.0    | \$0.00   | Clean truck. Carry out 250hr PM service. Adjust loose lift chains.<br>Steam clean equipment as necessary.<br><br>100Hr Service  |
| 1301471                    | Rework before unit can go in service<br>- refer to Notes | GOSMOND                           | 27/05/2020 | Internal                       | 2.0      | \$0.00   | Carry out 100hr initial service. Clean truck. Replace engine oil and filter. Take oil sample. Calibrate Transmission.<br>Adjust Accumulator Pressure  |
| 1299421                    | Warranty - Cabin Dust Ingress                            | 501WORKSHOP                       | 20/05/2020 | External                       | 3.0      | \$32.01  | Adjust accumulator pressure. Top up hydraulic oil level.<br>Adjust front camera. Modify seat switch for eng shutdown.   |
| 1297765                    | Modify Load Guard  | TBIRBAS                           | 13/05/2020 | Cap Prep                       | 3.0      | \$0.00   | Repair Load Guard as necessary,<br><br>modified as required   |
| 1297560                    | Add A/C Filtration                                       | 511 Planning D                    | 12/05/2020 | Internal                       | 2.0      | \$0.00   |   |

| Job No.                    | Description               | Mechanic                          | Date      | Job Type                       | Eng. Hrs | Retail            | Notes   |
|----------------------------|---------------------------|-----------------------------------|-----------|--------------------------------|----------|-------------------|---|
| <b>Owner:</b> ADAP001      |                           |                                   |           |                                |          |                   |   |
| <b>Equip. Code:</b> H15952 |                           | <b>Description:</b> HYSTER H155FT |           |                                |          |                   |   |
| <b>Make:</b> HYSTER        |                           | <b>Model:</b> H155FT              |           | <b>Serial No.:</b> L006V03566T |          |                   |   |
| 1200005                    | Prep for Rent; Timberlink | ECACERES                          | 9/04/2019 | Cap Prep                       | 2.0      | \$0.00            | <p>Refit Mast and ancillary items,</p> <p>Refit Hydraulic Hose/s and ancillary items,</p> <p>Remove ancillary items and Load Guard, inspect and report,</p> <p>Install Light/s</p> <p>Refit Forks/Tynes and ancillary items,</p> <p>Refit Load Guard and ancillary items,</p> <p>Refit Attachment and ancillary items,</p> <p>Assist tech to fit new mast, and install hoses,load guard and other attachment.</p> <p>Install Hard Labels,</p> <p>Fit Fleet Management System as required,</p> <p>Remove ancillary items and Repair Wiring as necessary, Refit ancillary items,</p> <p>Install Radio,</p> <p>Install Battery Isolator,</p> <p>Fit Full Camera Kit,</p> <p>Repair Revolving/Flashing/Strobe light as required,</p> <p>Carry out New Equipment Predelivery to correct specification.</p> <p>Removed facias and fitted fm1. Fitted new seatvswitch. Fitted uhf and fm radios. Fitted and wired up speakers. Fitted radio aerials. Inverted flashing light bracket. Mase up new cabling and fitted battery isolator.</p> |
| <b>Equipment Total:</b>    |                           |                                   |           |                                |          | <b>\$6,474.82</b> |   |
| <b>Customer Total:</b>     |                           |                                   |           |                                |          | <b>\$6,474.82</b> |   |