

ADAPT-A-LIFT GROUP PTY LTD

Service History Listing Active Units

Date: 19/06/2026

Time: 11:00:37AM

For Equipment Code From: H56188 To: H56188

For Customer Code From: All To: All

For Date Posted From: All To: All

For Branch Code From: All To: All

Don't Show Cost

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H56188		Description: MANITOU MLT-X 735 T LSU - ENGINE RE-BUILD					
Make: MANITOU		Model: MLT-X 735 T LSU		Serial No.: 956044			

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H56188		Description: MANITOU MLT-X 735 T LSU - ENGINE RE-BUILD					
Make: MANITOU		Model: MLT-X 735 T LSU		Serial No.: 956044			
1679721	QUOTE QUARANTINE - ENGINE OIL LEAK	GGARCIA	9/12/2024	Internal	3793.0	\$0.00	<p>Travel to site,</p> <p>Carry out Inspection and Diagnosis of Electrical System</p> <p>travel to site find unit check for engine oil leak check engine oil level found no oil on dip stick complete intake side of engine and valve cover covered in oil radiator covered in oil and dirt check coolant level and found very low coolant level, also signs for coolant leak from cylinder head try to start engine - engine feels to be under significant load suspect internal engine failure remove air cleaner and found pipe from air cleaner to engine not connected try again to start engine with eather to try see how much damage is done engine will not fire up remove customers pallet folks from front of unit using crane</p> <p>Remove ancillary items and remove Radiator from unit, Inspect and report,</p> <p>Remove ancillary items and remove engine from unit.</p> <p>remove ,radiator ,turbo cooler ,and transmission cooler ,remove fan assembly ,remove muffler ,remove bonnet ,remove engine assembly ,</p> <p>Overhaul Engine assembly as required,</p> <p>Carry out equipment condition assessment</p> <p>Steam clean equipment as necessary.</p> <p>Remove ancillary items and Repair Frame, Body or Chassis as necessary, Refit ancillary items,</p> <p>clean and wash the unit ,clean engine bay,bring the unit inside the workshop ,repair boom cover ,repair aircon bracket ,refit engine ecu ,refit floor matting</p> <p>Refit engine to unit, refit ancillary items,</p> <p>replace ring gear (fly wheel)refit engine mount ,install engine to the unit ,install fan ,refit elelrical wirring and</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H56188	Description: MANITOU MLT-X 735 T LSU - ENGINE RE-BUILD						
Make: MANITOU	Model: MLT-X 735 T LSU			Serial No.: 956044			
							<p>hoses ,</p> <p>Carry out preventative maintenance service and safety inspection in line with the agreed scope of work. Report on condition of equipment and additional work requirements.</p> <p>Remove ancillary items and Repair Wiring as necessary, Refit ancillary items,</p> <p>Replace Fan Belt,</p> <p>R&R Belt Tensioner</p> <p>replace fuel filter(primary and water seperator filter)change engine oil ,replace oil filter ,clean air filter ,replace alternator belt ,refit aircon belt ,install fan belt tensioner bearing and pulley ,replace fan belt ,install angle gear box yoke refit alternator belt cover</p> <p>Check/Inspect/Diagnose Fuel system, bleed Fuel system to remove air,</p> <p>Refit Drive Shaft Assembly, Refit ancillary items,</p> <p>Remove ancillary items and Repair Hydraulic Oil Leak as necessary. Refit ancillary items,</p> <p>repair and replace park pad ,refit park brake caliper ,bleed fuel system ,diagnose and repair elelrical wirring ,replace relay ,replace cardan shaft ,install bolt repair transmission leak ,repair wirring of reverse fan</p> <p>Refit Radiator to unit, Refit ancillary items,</p> <p>refit radiator and hoses ,refit shroud ,refit tilt cylinder pin ,top up coolant ,topup transmission oil</p> <p>refit fan cover ,refit operator step ,repair bonnet ,refit bonnet ,troubleshoot and repair wirring of transmission ,replace forward relay ,</p> <p>Repair Hydraulic Control Card/Controller</p> <p>Load software as required to calibrate the unit,</p> <p>fully rebuilt engine and prep for reinstall. checked over macine when done. replaced strain sensor and calibrated</p>

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
Owner: ADAP001							
Equip. Code: H56188		Description: MANITOU MLT-X 735 T LSU - ENGINE RE-BUILD					
Make: MANITOU		Model: MLT-X 735 T LSU		Serial No.: 956044			
1675481	TECHNICIAN INITIATED JOB	BMONGELLI	23/11/2024	Internal	7890.0	\$0.00	Check/Inspect/Diagnose Cylinder Travel to site, Carry out Inspection and Diagnosis of Attachment unit stalling drive unit and found stalling test unit and found staving for fuel check wiring to fuel primer pump found wiring not correct wiring was bypassed to the reverse fan and was only working when fan activated causing low fuel pressure to engine rewire fuel pump to correct sorce and test operation all ok reverse fan not working check found no hose to fan and compressor being intermitten suspect compressor faulty test unit operation and found to be all working ok LH front hub seal leaking 250hr Service
1674818	Scheduled Service - 0250 Hour Service	BMIRTSCHIN	22/11/2024	Internal	3743.0	\$0.00	Change eng oil and filter, change air filters, blow out radiator core, replace belts, wash unit, check fluid levels, calibrate and test function of machine.
1674984	ELECTRICAL REPAIRS - SLOW HYDRAULICS -	BMIRTSCHIN	21/11/2024	Internal	35999.0	\$0.00	
1670314	TROUBLESTARTING	BMIRTSCHIN	4/11/2024	Internal	3620.0	\$0.00	
1669284	DEHIRE INSPECTION	JNEYLAND	31/10/2024	Internal	35999.0	\$0.00	clean all earth and battery contacs run new wire to fuel pump and replace battery
1663900	NO START - BATTERY	BMIRTSCHIN	11/10/2024	Internal	3620.0	\$0.00	Remove and Replace Drive Axle Seal/s
1663900	no start	BMIRTSCHIN	11/10/2024	Internal	3620.0	\$0.00	travel to site for slow hydraulic when i got to site found the hydraulics working fine but notice front left hub seal leaking so ran parts to see if we had parts in stock we did so travled back to work shop to get parts and then to c&m to get axle sleeve then travled back to site to replavce hub seal and sleeve to axle then travel back to workshop
1657254	prep for hire, fit hay forks	JALDEMITA	17/09/2024	Internal	3620.0	\$0.00	Fit Jump Start Plug to Equipment, Check Diff oil level, top up oil level as required, Prepare For Hire - Workshop Steam clean equipment as necessary. Grease All Points on Unit, repair wiring signal ,repair reverse fan,repiai wiring roof light,adjust park brake

Job No.	Description	Mechanic	Date	Job Type	Eng. Hrs	Retail	Notes
---------	-------------	----------	------	----------	----------	--------	-------

Owner: ADAP001

Equipment Total:	\$0.00
Customer Total:	\$0.00