

Number	Type	Date Open	Date Closed	Kilometres Cl	HoursClosed	Fuel Usage Cl	Fault	Repairer / Notes
S-7578	A - 250	01/23/2026	01/22/2026	0	10,250	2	0	ACTUALLY DONE AT 10332 HRS.
S-7450	C - 1000	11/11/2025	11/25/2025	0	10,000	1	0	ACTUALLY DONE AT 10119HRS.
S-7254	A - 250	09/01/2025	09/02/2025		9,750	25	0	
								Internal Workshop - Field Service leaking eng oil from fill tube + dipstick tube. replace filltube cap and dipstick? actually done at 9561 hrs.
S-7073	B - 500	07/01/2025	07/07/2025	0	9,500	50	0	
R-8616	Grease line	06/10/2025	06/24/2025			9,484	0	10540 Internal Workshop - Field Service Repaired broken grease line
R-8593	Flashing light	06/03/2025	06/24/2025			9,484	0	10492, 10561 SAY AUTO ELETRICAL Repaired by steph SAY Electrical
								Internal Workshop - Field Service Bottom bucket pins looked like they were dry. Removed grease lines and started auto greaser, lines pumped grease out. Adapted hose and pumped grease into bushes. Grease wont stay in as rubber seals are gone and bucket needs shimming. Bucket
R-8592	Auto Greaser	06/03/2025	06/04/2025			9,374	0	10494 needs to come off for repairs.
R-8553	Emergency stop	05/20/2025	05/22/2025			9,319	0	10364 Steph has fitted 3 x e stops 1x rear 1xsteps 1x cab Also changed battery isolator to proper lockable one.
R-8501	Steps	04/28/2025	05/22/2025			9,319	0	Internal Workshop - Field Service Had Damien bring mag drill out and drill holes out so that when the steps get broken off again its just replacing nut and bolt.' Fitted new steps to both sides, parts supplied by porter hire.

S-6830	A - 250	02/20/2025	05/15/2025	9,250	25	0	Movement in bucket crowd right hand pin.
							Reported Problem: REAR DIFF PINS AND BUSHES QUOTE TO REMOVE AXLE REPLACE 1 LEAKING DUO SEAL REMOVE 2 HUBS REMOVE 2 AXLE HOUSING VISUALLY INSPECT INTERNALS FOR A FAILURE **** UPDATE **** FOUND ALL INTERNAL GEARS IN SATISFACTORY CONDITION BEARINGS IN PINION SLIGHTLY NOTCHY AND ROLLING TORQUE IS LOW BEARINGS ON DIFF CENTRE HAS SIGNS OF WEAR/ PITTING 1X HUB HAD 2 BENT/ DEFORMED STEEL BRAKE DISCS THE OTHER HUB SHOWED NO SIGNED OF DAMAGED BRAKE DISCS QUOTE UPDATED TO REPLACE DIFF CENTRE BEARINGS, PINION BEARINGS, RESET DIFF CENTRE IN HOUSING, REPLACE 2 DUO SEALS, REPLACE 6 STEEL DISCS IN 1 HUB ASSEMBLE AXLE FIT TO MACHINE FILL WITH OIL TEST AXLE REPAIRS
R-8568	REAR DIFF	05/23/2025	05/02/2025	9,206		0	Internal Workshop - Field Service
R-8499	Alternator	04/28/2025	04/28/2025	9,206		0	Internal Workshop - Field Service
R-8497	Battery	04/28/2025	04/28/2025	9,206		0	Internal Workshop - Field Service
R-8084	Radiator cap	10/25/2024	04/28/2025	9,206		0	9354 Internal Workshop - Field Service Needs new radiator cap, losing coolant from the cap
S-6580	C - 1000	10/08/2024	10/22/2024	9,000	1,0	0	Internal Workshop - Field Service Serviced at 9036hrs
R-7784	Seat	08/26/2024	08/26/2024	8,824		0	Internal Workshop - Field Service Seat had to much movement from being worn out and hurting operators back. Jay soured seat from somewhere on the gold coast and tom and i fitted
R-7736	Hub Leak	08/06/2024	08/26/2024	8,824		0	8822 Internal Workshop - Field Service Inspected cant find any fresh leaks
R-7642	REAR DOOR	07/04/2024	08/26/2024	8,824		0	Internal Workshop - Field Service Ordered new latch assembly from porters and fitted to machine
R-7577	Oil leak	06/19/2024	08/26/2024	8,824		0	8420 Internal Workshop - Field Service Checked and duo SEAL has taken up
R-7396	Tail light	04/08/2024	08/26/2024	8,824		0	7977 Internal Workshop - Field Service Tail; lights working
R-7086	Steps	01/19/2024	08/26/2024	8,824		0	7522 Internal Workshop - Field Service REPAIRED BOTH STEPS.
S-6386	A - 250	07/12/2024	08/15/2024	0 8,750	25	0	ACTUALLY DONE AT 8760HRS
S-6324	B - 500	06/24/2024	06/25/2024	0 8,500	50	0	Rear door latch and cable need replacing, bent brackets and se agrade REPLACE WIRING TO SEAT. REPLACED CAMAERA SYSTEM
R-8412	Seat	03/17/2025	06/11/2024			0	FITTED TURBO TIMER.
S-6252	A - 250	05/24/2024	05/23/2024	0 8,250	25	0	

R-7051	heal plates	01/16/2024	04/10/2024		8,124	0	Internal Workshop - Fabrication Boilys went to site welded new heel 7505 plates on.
R-7358	bucket heal plates	04/08/2024	04/03/2024	0	8,102	0	Internal Workshop - Fabrication Replaced heal plates on bucket these had to be welded on buy Brett.
R-7144	lock	02/06/2024	02/20/2024		7,997	0	Internal Workshop - Field Service Outside lock on panel for aircon filter 7609 is not working keeps opening
R-6909	Auto Greaser	09/30/2023	02/20/2024		7,997	0	Porter Equipment Replaced main grease pump. Faulty.
S-6075	C - 1000	02/21/2024	02/20/2024	0	7,998	1,0	
S-5967	A - 250	12/08/2023	12/07/2023	0	7,750	25	actually serviced 7732
R-6916	Air Conditioning	11/23/2023	11/23/2023		7,681	0	A Grade Auto Repair Replaced compressor, TX valve and drier. Regas system. Cycling at 10 degrees. Suspect blocked evaporator core.
S-5746	B - 500	08/22/2023	10/13/2023	0	7,500	50	Oil dip stick tube remove clean and tighten as it was loose Check coolant leak found tell tell hole leaking on water pump Serviced at 7508hrs have brought back to 7500 to align hours
S-5776	A - 250	09/06/2023	09/06/2023	0	7,313	31	REPLACED GREASE PUMP DUE TO OLD ONE FAILING PORTORS DONE SERVICE INVOICE YET TO BE ATTACHED
R-5331	Isolation switch	10/11/2022	09/01/2023	0	0	0	5456, 5594 Other. Report any major concerns (take photos). Isolation switch cabinet door is broken Based on audit conducted by Jay on 1/9/23 this repair has been completed in the last 12 months.
R-5222	Bucket	09/27/2022	09/01/2023	0		0	5387, 6028 Internal Workshop - Fabrication Damaged. Check bucket cutting edge, teeth, underside of adapters & side plates for wear. Bucket floor still needs welding. Based on audit conducted by Jay on 1/9/23 this repair has been completed in the last 12 months.
S-5568	C - 1000	06/13/2023	06/21/2023	0	6,997	99	
R-5989	Intercooler	03/10/2023	05/26/2023	0	6,874	0	6159 Intercooler hose is worn and has crack in it,
S-5417	A - 250	04/12/2023	05/16/2023	0	6,843	30	
R-6081	Alternator, Batteries	03/15/2023	03/15/2023		6,637	0	A Grade Auto Repair, Internal Workshop Replaced alternator and belt due to bearing ceasing. Replaced batteries due to alternator damaging batteries. Alternator fitted by A Grade Auto. Batteries supplied by Truck Line Ipswich. Invoice attached.
R-5898	Seat	02/24/2023	03/02/2023	0	6,588	0	6088 Internal Workshop jay removed seat SEATS R US replaced seat base with new one. jay fitted seat

R-6179	Cutting Edge	02/28/2023	02/28/2023		6,588	0		Internal Workshop - Field Service Max & Thomas - Removed old cutting edge. Cleaned surfaces. Bolted on new cutting edge. Supplied by WPA.
R-6178	Turbo	02/28/2023	02/28/2023		6,588	0		Internal Workshop Max & Thomas - Disconnected oil hose, intake and exhaust from turbo. Unbolted exhaust manifold and removed turbo and manifold as one. Removed old gaskets, cleaned surfaces. Replaced gaskets and bolts and refitted manifold/turbo. Re-attached intake/exhaust/oil lines. Bolts and gaskets supplied by Torque Power.
R-5668	Window washer	12/22/2022	02/28/2023	0	6,374	0	5842, 6027	Internal Workshop - Field Service Not Working. Wiper, washer & horn function properly. Washer not working
S-5277	B - 500	02/13/2023	02/14/2023	0	6,534	53	0	Internal Workshop - Field Service Tom serviced
R-5711	Air con	12/21/2022	02/09/2023	0	6,500	0	5832	A Grade Auto Repair Other. Check aircon for operation. Not working properly aircon completely shut off yesterday for over an hour before turning back on. Steph fixed; awaiting invoice with further details.
R-5435	Seat	11/08/2022	02/09/2023	0	6,500	0	5593	Internal Workshop - Fabrication, Internal Workshop - Field Service Needs a new seat back of it is completely damaged
R-5703	Brakes	12/15/2022	01/18/2023	0	6,381	0	5815, 5818	Porter Equipment Not Working. Conduct daily brake test. Brakes not working properly. Porters repaired; refer to attached invoice.
R-5440	UHF Radio	11/07/2022	01/12/2023	0	6,382	0	5580	A Grade Auto Repair Not Working. UHF operational or hand held available. UHF not working, loose connection maybe, no power but turns on by itself sometimes A Grad found loose wiring and repaired. Invoice attached.
R-3970	Tyre	03/02/2022	12/13/2022	0		0	4304	
R-5348	Hydraulic oil	10/13/2022	11/24/2022	0	6,267	0	5469	Internal Workshop - Field Service Other. Hydraulic oil level is in sight glass to work for shift. Hydraulic fluid looks a odd dark colour through sight glass, also slow Hydraulic leak in front lift arm connection rod, tom has photos to show jay
R-5220	E Stop	09/27/2022	11/24/2022	0	6,267	0	5386	Other. Emergency stop button working properly. This machine has no E stops inside or outside. Max: e stop not required at Dinmore, and has come like that from factory.

S-5087	A - 250	11/16/2022	11/24/2022	0	6,267	26	0	Internal Workshop - Field Service Bottom heel plates on bucket need new pad welded on before it wears down onto bucket. Tail lights still need bulbs put in new assembly's. Right hand side step / ladder bent (Troy said he will straighten with digger). Partly removed steel tube for lift cylinder right side and welded up crack in it. Park brake pads will need to be changed on next service.
R-5159	Engine Oil	09/13/2022	10/12/2022	0	6,000		0	5324 Other. Engine oil level is within range on dip stick to work for shift. Oil is still In safe range but on the low end still waiting for engine oil to be sent to top up from last service
R-4978	Lights	08/19/2022	10/12/2022	0	6,000		0	Replace LHS and RHS tail light lenses.
S-4963	C - 1000	10/04/2022	10/12/2022	0	6,000	96	0	
R-5163	Fuel pump	09/19/2022	09/19/2022		5,931		0	Replaced main fuel pump supplied by Torque Power due to old pump shearing main drive coupling. Jay completed on site.
R-4977	Door	08/19/2022	08/22/2022	0	5,798		0	Rear door needs repair. didnt have grease to top up auto greaser didnn't have hyd oil to top up both rear tail lights smashed
S-4802	A - 250	08/19/2022	08/20/2022	0	5,798	24	0	repaired rear door lock changed bucket teeth
R-4547	Coolant leak	06/22/2022	07/22/2022	0	5,633		0	4820, 5003 Other. Check engine coolant level . Radiator: Filling coolant weekly still has a slow leak from area max patched
R-4909	Scales	07/07/2022	07/07/2022		5,554		0	Precia Molen Recalibrated scales.
R-4592	Steering	07/04/2022	07/04/2022	0	5,554		0	4922 Damaged. Other : Major Concerns (Take pics) . Left hand side steering stop needs replacing. Porters replaced the steering bump stop, RHS tail light lens, and reverse camera monitor, Porter Equipment Porters completed service.
S-4666	B - 500	07/05/2022	07/04/2022	0	5,555	51	0	Invoice attached.
R-3622	Transmission	11/28/2021	05/20/2022	0	5,266		0	3953 Porter Equipment Tyranny fluid leaking into front dif due too broken dif lock seal. Porters fixed.
S-4592	A - 250	05/20/2022	05/20/2022	0	5,266	22	0	
R-3416	Windscreen	10/12/2021	05/12/2022	0	5,235		0	3799, 3811, 3 Glass Repairer Not in line of operator vision. Will be closed as per workshop meeting discussion with Jay and Graeme 12/05/2022.

R-4184	Scales	04/14/2022	05/05/2022	0	5,221	0	4451	Not Working. Other: Major Concerns (Take pics). Auto level not working. Scales weighing but not registering weight once bucket is empty. As per workshop meeting 12/05/2022 Jay said Troy repaired onsite 'last week'.
R-4126	Steps	04/05/2022	04/07/2022	0	5,090	0	4419	Damaged. Check grab handles, steps & walk ways. Rock got caught between tyre and stairs , stairs have a slight bend in them: Tory fixed onsite 07/04/2022.
R-3862	Service	02/08/2022	03/31/2022	0	0	0	4146	Serviced, all good. As per workshop meeting and discussion with Jay 01/04/2022.
S-4363	C - 1000	03/16/2022	03/29/2022	0	5,038	2,2	0	Porter Equipment Service carried out by Porters Equipment. Front diff lock seal repaired under warranty. Jay re-tightened and put 11 litres of engine oil in on site (called the job through so no paperwork). If it happens again the oil filter will need to be replaced.
R-4038	Oil filter	03/16/2022	03/16/2022	0	4,979	0	0	
S-4362	A - 250	02/17/2022	02/16/2022	0	4,820	49	0	Porter Equipment 250hr service 4820hrs
R-3665	UHF	12/08/2021	12/08/2021	0	4,420	0	0	Internal Workshop Jay fit new UHF handpiece supplied by Maxi parts. Jay rang for this so there is no job card.
R-3651	Battery	12/05/2021	12/05/2021	0	4,395	0	0	Internal Workshop Replaced 2 x N200 batteries.
R-3415	Other	06/25/2021	11/17/2021	0	4,330	0	3038	NA - problem fixed itself.
S-4272	A - 250	11/17/2021	11/17/2021	0	4,330	7	0	Porter Equipment 250hr Service - 4330hrs
R-3479	Brake lights	10/26/2021	11/16/2021	0	4,323	0	3852	Fixed.
R-3473	Aircon	10/24/2021	11/16/2021	0	4,323	0	3842, 3920	Fixed.
R-3414	Flashing light	06/25/2021	11/16/2021	0	4,323	0	3036	Internal Workshop Replaced.
R-3292	Air filter	09/21/2021	11/16/2021	0	4,323	0	3680, 3734, 38	Internal Workshop Done at service A service - 4031
R-3293	Battery	09/06/2021	09/07/2021	0	0	0	3555	Internal Workshop New battery - done by Max
S-3552	A - 250	05/20/2021	06/18/2021	0	3,750	25	0	Internal Workshop Service done by Max
S-3958	B - 500	05/06/2021	05/06/2021	0	3,500	70	0	Coolant Filter replaced
R-2526	Oil sample	02/22/2021	02/22/2021				0	Fuel filters replaced
S-3358	A - 250	02/22/2021	02/22/2021	0	3,250	25	0	Back brake light repaired
S-3957	A - 250	01/04/2021	01/04/2021	0	3,000	20	0	KOWA Normal engine oil sample received
S-2658	C - 1000	11/12/2020	11/12/2020	0	2,800	83	0	Service done by Robert
								Replaced roof
								Internal Workshop B service done
								Adjusted aircon belt
								Defects: Window broken from float

R-1220	Tyres	10/26/2020	10/26/2020			0	Millards Replaced 2 x tyres @ Rochedale Aeolus 29.5 -25 28PL G24 LS Inv 293859 - 26/10/2020
S-3956	A - 250	10/12/2020	10/12/2020	0 2,750	19	0	
S-525	B - 500	09/18/2020	09/18/2020	0 2,552	24	0	Internal Workshop Service done
S-401	A - 250	08/03/2020	07/29/2020	0 2,303	33	0	Internal Workshop Service done Filled up auto greaser DEFECTSL fire extinguisher bag torn & perished (4.5kg) LH steel wheel chock missing Porters NSW 2000K service done Replaced filters & oils Took samples Replaced all belts DEFECTS: LHR hub seal leaking
S-178	C - 1000	05/13/2020	05/13/2020	0 1,970	99	0	Grease lines at dog bones crushed Service done - only did engine oil & filter & fuel filters P550949 oil filter was used
S-57	B - 500	02/27/2020	02/27/2020	1,610	1,6	0	
S-2863	A - 250	11/20/2019	11/20/2019	0 1,330	1,3	0	Internal Workshop Service done, all oil samples done Fuel filters replaced
S-2864	C - 1000	09/18/2019	09/18/2019	0 979	979	0	internal workshop Service done, all oil samples done DEFECTS: Work to be done on the bucket to stop rocks falling back on greaseline and protect RAMS,
S-2865	A - 250	07/29/2019	07/29/2019	0 714	714	0	Internal workshop Service done, all oil samples done Fuel filter replaced All oil samples done DEFECTS: Work to be done on the bucket to stop rocks falling back on greaseline and protect RAMS,