

Number	Type	Date Open	Date Closed	Kilometres Cl	HoursClosed	Fuel Usage	Cl Fault	Repairer / Notes	Cost / Invoice	
S-7592	B - 500	02/05/2026	01/29/2026	0	5,500	50	0		\$0.00	
R-8908	HYD Leak	09/19/2025	12/02/2025			5,240	0	11289 Internal Workshop - Field Service	Removed and changed o ring	\$0.00
R-8818	Grease nipple	08/22/2025	11/21/2025			5,196	0	11070 Replaced nipple		\$0.00
								Boom cracked		
								Grab plat on stick cracked		
								Hyd oil filters not changed weren't supplied also need to change hyd oil		
S-7360	C - 1000	10/10/2025	11/08/2025		5,000	1,000	0	ACTUALLY DONE AT 5031HRS.		\$0.00
								Internal Workshop - Field Service	Replaced handrail bolts as they were loose and thin	
								hosepower	Steel pipes on dipper for hitch lines have been damaged and leaking.	
R-8806	HYD Hose	08/08/2025	08/08/2025			4,605	0	Bypassed steel lines and ran soft hoses to keep running and removed steel pipes to repair.		\$0.00
R-8834	Sprockets	08/29/2025	07/24/2025			4,468	0	rdw RDW FITTED NEW SPROCKETS AND BOLTS.		\$0.00
R-8227	Windscreen Replacement	01/06/2025	07/16/2025			4,474	0	10371, 9625, Window replaced		\$0.00
R-8549	Window Washers	05/14/2025	07/11/2025			4,474	0	10327 Wiper and washers work		\$0.00
R-8330	BOOM CYLINDER	02/11/2025	07/11/2025			4,474	0	9823 Internal Workshop - Field Service	Checked cant see boom creeping	\$0.00
								Internal Workshop - Field Service	Replaced handrail bolts as they were loose and thin	
								Boom cracked same spot as unit 602		
S-7086	B - 500	07/03/2025	07/11/2025		4,500	50	0	ACTUALLY DONE AT 4477 HRS		\$0.00
R-8600	Aircon	06/02/2025	06/10/2025			4,301	0	10473 Internal Workshop - Field Service	Just the cover filter is fine	\$0.00
								Internal Workshop - Field Service	REPLACED CHAINS AND GROUSERS UNDER	
R-8367	Tracks	02/26/2025	05/21/2025			44,098	0	WARRANTY STILL GOT TO DO SPROCKETS.		\$0.00
								All parts supplied by Turners Engineering and some were warranty. Tom and kai carried out		
R-8504	Quick Hitch	04/22/2025	05/19/2025			4,174	0	10191, 10266 work.		\$0.00
								Internal Workshop - Field Service	REPLACED WHOLE QUICKHITCH WITH BRAND NEW	
								TURNERS ONE.		
								REBUILT ROCK GRAB WITH NEW PIN.		
S-6909	D - 4000	04/11/2025	04/10/2025		0	4,000	4,000	0	ACTYUALLY DONE AT 3983 HRS.	\$0.00
R-8353	Cutting Edge	02/20/2025	02/25/2025			3,802	0	9884 Cutting edge changed by tom on service day. Edge supplied by Wear Parts		\$0.00
S-6723	B - 500	12/19/2024	12/19/2024		0	3,500	50	0	Internal Workshop - Field Service	\$0.00
R-7920	UHF Radio	09/11/2024	09/20/2024			3,001	0	9076 A Grade Auto Repair	A grade repaired on service day	\$0.00
								Internal Workshop - Field Service	Tensioned track on service day Also hard to get right	
R-7908	Tracks	09/10/2024	09/20/2024			3,001	0	9062, 9165	due to chains seizing up and being kinked.	\$0.00
S-6394	C - 1000	07/12/2024	09/20/2024		3,000	98	0		Cracks on dipper arm where plate is welded for grab	\$0.00
R-7903	Ripper	09/09/2024	09/11/2024			2,937	0	Internal Workshop - Field Service	REPLACED RIPPE BOOT.	\$0.00
R-7781	UHF Radio	08/16/2024	09/03/2024			2,884	0	8866 Repaired by A GRAD AUTO		\$0.00
R-7344	Windows	03/23/2024	08/15/2024			2,766	0	7941, 8084, 9	Fixer Windscreens RPLACED WINDSCREEN	\$0.00
S-6355	B - 500	07/04/2024	07/05/2024		0	2,500	48	0	grab cylindr leaking slightly from gland	\$0.00
R-7341	Quick Hitch	03/28/2024	05/13/2024			2,210	0	7953 Internal Workshop - Field Service	Straightened hard pipes	\$0.00
R-7311	Grouser	03/19/2024	04/08/2024			2,068	0	7908 Internal Workshop - Field Service	One grouser plate missing 2 bolts	\$0.00
R-7371	UHF Radio	04/10/2024	03/22/2024			2,020	0	agrade	Replaced uhf with standard radio. Full details on invoice attached.	\$0.00
								changed 1 grouser plate + bolts		
								resealed leaking bung on control valve		
								grab cylinder leaking		
								Changed bucket teeth, Supplied by WPA		
S-6088	C - 1000	02/26/2024	03/22/2024		2,020	96	0		Removed cleaned and changed loose bolts on mud bucket, Bolts supplied by WPA	\$0.00
R-7305	Bucket Teeth	03/20/2024	03/20/2024			2,004	0	Internal Workshop - Field Service	remove replace	\$0.00

R-7244	Grouser	03/04/2024	03/04/2024	1,907	0	Internal Workshop - Field Service	Greg found 2x bolts missing on grouser plate. Removed plate, cleaned faces and replaced with new bolts/ plates\ Supplied by Porter Equipment	\$0.00		
R-7015	Grouser	01/06/2024	02/14/2024	1,936	0	7467 Internal Workshop - Field Service	Sourced new bolts from rd's Removed grouser plate cleaned and fitted new plate and bolts	\$0.00		
R-7111	Quick Hitch	02/01/2024	02/06/2024	1,739	0	7571 Internal Workshop - Fabrication	Repair major crack around lifting lug, gouge out crack, reweld with a full penetration weld. Repair front welds from quickhitch to ears/pickup gouge out till no crack present reweld and blend. Inspect rest of quick hitch for cracks, no visible cracks present.	\$0.00		
R-6779	Tracks	11/17/2023	12/09/2023	1,540	0	7327	replaced 2 grouser plates and bolts supplied by porters	\$0.00		
R-6778	Steps	11/17/2023	12/06/2023	1,527	0	7326	Access step on undercarriage bent	\$0.00		
S-5957	B - 500	12/06/2023	12/06/2023	0 1,500	44	0	actually done at 1520	\$0.00		
R-6742	Grab teeth	11/02/2023	11/01/2023	0	1,314	0	Internal Workshop - Field Service	Grab teeth and ripper boot worn down . Changed out with new set , supplied from WPA.	\$0.00	
R-6732	Scratches	10/25/2023	10/31/2023	1,313	0	7172	Internal Workshop - Field Service	Cleaned up scratch areas and touched up with paint	\$0.00	
R-6707	Cutting Edge	10/26/2023	10/26/2023	0	1,290	0	Internal Workshop - Field Service	Replace / spin	\$0.00	
R-6373	Ram seal	06/21/2023	09/15/2023	0	1,051	0	6560	Internal Workshop - Field Service	Re sealed grab cylinder hose	\$0.00
S-5752	C - 1000	08/22/2023	09/13/2023	0 1,051	1,0	0		Checked grab leak clean and re seal hyd hose	\$0.00	
R-6538	GP Bucket	08/21/2023	08/14/2023	0	890	0	Internal Workshop - Field Service	replaced side cutter, supplied by Porters	\$0.00	
R-6504	Pin bolts	08/03/2023	08/03/2023	0	844	0		replaced bolt	\$0.00	
R-5982	HYD Fitting Leak	03/07/2023	05/26/2023		530	0	6137		\$0.00	
S-5531	B - 500	05/26/2023	05/26/2023	0 530	530	0		No ac filters provided Fitted since service.	\$0.00	