

Number	Type	Date Open	Date Closed	Kilometres	HoursClose	Fuel Usage	Fault	Repairer / Notes	Cost / Invoice
R-9135	Dust seals	02/23/2026						12074 Internal Workshop - Field Service CAB SEALS NEED ATTENSION.	\$0.00
R-9103	Door handle	02/17/2026						12033 Door catch loose	\$0.00
R-9077	CRACKED WINDOW	01/19/2026						11884 Fixer Windscreens FRONT BOTTOM WINDOW CRACKED	\$0.00
R-8932	Grouser	10/15/2025						11442 Internal Workshop - Field Service Track bolts coming loose Internal Workshop - Field Service . Quick hitch: dog bones, cracks, pins, bushes, shims, wear.	\$0.00
R-8854	shims	08/27/2025						11108 Shims missing, gap & heaps of play	\$0.00
R-8539	Oil leak	05/12/2025						10308 Oil leak inside back right door	\$0.00
R-8469	Quick Hitch	04/07/2025						10115 Cracked hitch Other cracks aswell	\$0.00
R-8085	Bonnet	10/25/2024						9359 Internal Workshop - Fabrication Bonnet is cracked and rubbers coming off	\$0.00
R-7875	Carrier rollers	09/04/2024						8980 Internal Workshop - Field Service RHS CARRIER ROLLER DAMAGED BENT.	\$0.00
R-7712	Mirror	07/24/2024					8730, 9217, 9331	Internal Workshop - Field Service Crack on right mirror	\$0.00
R-7625	safety pin	06/26/2024						8486 Internal Workshop - Field Service No safety pin on machine	\$0.00
T-160	Retighten Wheels	03/20/2024							\$0.00
T-157	Retighten Wheels	02/23/2024							\$0.00
S-7734	B - 500	04/14/2026	04/13/2026	12,500	0			Internal Workshop - Field Service ACTUALLY DONE AT 12567HRS Replaced Door striker (Porters) and removed some movement in door, may need to replace latch	\$0.00
R-7552	dust seals	06/17/2024	02/03/2026		0			8409, 8985, 8991, 8 to properly fix.  Hitch and dog bones need to be removed checked and repaired then shimmed properly Hand rails and engine bay door cracked Pilot hyd lines leaking	\$0.00
S-7448	C - 1000	11/10/2025	11/07/2025	12,000	0			ACTUALLY DONE AT 12031 HRS	\$0.00
R-8923	Belt tensioner	10/10/2025	10/10/2025	0	11,956	0		Internal Workshop - Field Service Replaced belt tensioner, supplied by Porters Internal Workshop - Field Service Steph added body detner to inside of cab whilst doing evap	\$0.00
R-7552	Dust seals, Noise	06/17/2024	10/10/2025	0	11,956	0		8409, 8985, 8991, 8 job. This has reduced noise	\$0.00
R-7578	Wipers	06/19/2024	07/30/2025		11,780	0		8425 A Grade Auto Repair Working	\$0.00
R-8061	Cracks	10/18/2024	07/16/2025		11,708	0		10136, 9319 Fixer Windscreens Window replaced	\$0.00
R-7711	Steps	07/24/2024	06/16/2025		11,557	0		8729 Internal Workshop - Fabrication Repaired step as per last job card this is a double up	\$0.00
R-7826	Steps	08/30/2024	06/10/2025		11,509	0		8954 Internal Workshop - Fabrication Heated up step bent out and welded up cracks	\$0.00
R-8599	Radiator cap	06/02/2025	06/06/2025		11,509	0		10475 Internal Workshop - Field Service Changed radiator cap and adjusted levels. Engine bay door badly cracked and seal needs replacing Carrier roller needs replacing Hitch needs to be removed inspect bushes/ pins and re shims lot of play/slop	\$0.00
S-6996	B - 500	06/02/2025	06/06/2025	11,500	0			Repaired broken hand rail bracket	\$0.00
R-8418	Air Conditioner	03/17/2025	03/13/2025		11,134	0		FOUND LOW GAS. FULL DEATAILS ATTACHED. Replaced top rad coolant hose as it has small split Replaced intake hose to turbo had internal wire poking through Replaced grease nipples on hitch and greased  Need 6x new final drive bungs as they are all worn down Hitch and dog bone need shimming and hitch need welding	\$0.00
S-6835	D - 2000	02/20/2025	02/20/2025	11,000	0			ACTUALLY DONE AT 11062 HRS	\$0.00
R-8392	Air Conditioner	02/03/2025	02/03/2025			0		A Grade Auto Repair Clean evaporator and Regas.	\$0.00
R-7383	Quick Hitch	04/11/2024	12/03/2024		10,711	0		8007, 9109, 9340, 9 Internal Workshop - Fabrication Damien repaired cracks up on site and on machine	\$0.00
R-7886	Aircon	09/05/2024	11/01/2024		10,578	0		9019 A Grade Auto Repair A grade repaired	\$0.00
S-6396	B - 500	07/12/2024	10/15/2024	10,500	0				\$0.00

R-7894	Quick Hitch	09/06/2024	09/11/2024		10,344	0	9031, 9039	hosepower Steel pipe that runs down dipper to hitch damaged. Had hose power run a rubber hose to keep going.	\$0.00
R-6838	Windscreen	12/09/2023	08/15/2024		10,186	0	7406	Fixer Windscreens REPLACED FRONT WINDOW.	\$0.00
R-7724	Bucket Teeth	07/29/2024	07/26/2024	0	10,142	0		Internal Workshop - Field Service replaced bucket teeth, supplied by WPA	\$0.00
R-7648	HYD Hose	07/05/2024	07/05/2024		10,019	0		Hosepowewr Quick hitch hose was damaged and already had hose power on site. Got them to make and fit new hose 1x	\$0.00
S-6337	C - 1000	07/01/2024	07/05/2024		10,000	0		Removed bucket cylinder steel pipe and sent to workshop to be repaired as it had crack. Re fitted back to machine.	\$0.00
R-7455	Quick Hitch	05/01/2024	07/02/2024		10,005	0	8100	Internal Workshop - Field Service Cut new grooves in pin and replaced circlips	\$0.00
R-7631	Quick Hitch	07/01/2024	07/01/2024		10,005	0		Internal Workshop - Field Service Removed cylinder for hitch and stripped. Replaced seals. Sourced seals from seal invasions.	\$0.00
R-7630	Quick Hitch	07/01/2024	07/01/2024		10,019	0		Internal Workshop - Field Service Removed and sent to workshop to be welded up. New main pin made also as old one was worn. Fitted back to machine with new grease nipples and greased	\$0.00
R-6814	Quick Hitch	11/23/2023	03/25/2024		9,622	0	7357, 7363	Internal Workshop - Fabrication Welds on hitch cracking. Whilst down for ac fault had danny grind out cracks and weld up.	\$0.00
R-7363	Air con	04/10/2024	03/22/2024	0	0	0		A Grade Auto Repair Checked for gas leaks found none removed evaporator and it was full off mud cleaned and reassembled and adjusted gas level. Full details attached.	\$0.00
R-7257	Quick Hitch	03/07/2024	03/20/2024	0	9,611	0	7822	Internal Workshop - Field Service Hitch tongue pin lost circlip. Cleaned and replaced circlip.	\$0.00
R-7173	HYD Hose	02/13/2024	03/05/2024		9,535	0	7666	removed broken bolt and replaced clamp with new bolt	\$0.00
S-6105	B - 500	03/04/2024	03/05/2024	0	9,500	0		actually done at 9535hrs	\$0.00
R-7241	Quick Hitch	03/04/2024	03/04/2024		9,522	0		Internal Workshop - Field Service Removed quick hitch Toung and sent to workshop for welding repairs. Got dropped off back to site and fitted back to machine. Replaced grease nipple and greased.	\$0.00
R-7110	Safety bar	02/01/2024	02/23/2024		9,474	0	7568	Internal Workshop - Field Service Machine control lock out bar broken	\$0.00
R-7188	Alternator	02/22/2024	02/21/2024	0	9,466	0		Internal Workshop - Field Service replaced alternator with one supplied by A-Grade	\$0.00
R-7185	Cab	02/21/2024	02/21/2024	0	9,466	0		Internal Workshop - Field Service replaced the lever with one sourced from porters	\$0.00
R-6631	Steps	09/27/2023	02/14/2024	0	9,425	0	7015	Internal Workshop - Fabrication Step Has been hit with rock and pushed step in and crack in the metal on step	\$0.00
R-7079	Batteries	01/22/2024	01/22/2024	0	9,312	0		Internal Workshop - Field Service replaced 2 batteries and joining cable. from maxiparts	\$0.00
R-6801	Wiring harness	11/30/2023	11/30/2023	0	9,145	0		A Grade Auto Repair Repair	\$0.00
R-6713	Window tint	10/26/2023	11/30/2023	0	0	0			\$0.00
R-6641	Grouser	09/28/2023	10/27/2023	0	9,000	0	7030	Internal Workshop - Field Service removed 23 grouser plates and replaced with new bolts from porters. High torqued up to 1030ftb	\$0.00
S-5888	D - 2000	10/30/2023	10/26/2023	0	9,000	0			\$0.00
R-6565	slew motor	09/07/2023	09/15/2023	0	8,820	0		Internal Workshop - Field Service REPLACED WHOLE HYDRAULIC MOTOR ON SLEW DUE TO ON ONE HAVING CRACK IN HOUSING. Slew motor sourced from porter group and jay changed on site	\$0.00
R-6053	Windscreen	03/24/2023	09/08/2023			0	6236	Replaced as per Jay Audit 8/9/23	\$0.00
R-6938	UHF	09/01/2023	09/01/2023		8,786	0		A Grade Auto Repair Supply and fit new UHF.	\$0.00
R-5481	Bucket	11/28/2022	09/01/2023	0		0	5715, 5742, 5952	Internal Workshop - Fabrication Damaged. Check attachments for cracks & wear on bucket, rippers, & pick up pins. Bucket cracked. Based on audit conducted by Jay on 1/9/23 this repair has been completed in the last 12 months.	\$0.00

R-5152	Bucket	09/14/2022	09/01/2023	0	0	0	5333	Damaged. Ground engaging gear: locks, pins, wear. Sieve bucks cracked Based on audit conducted by Jay on 1/9/23 this repair has been completed in the last 12 months.	\$0.00
R-5900	Hydraulic leak	02/25/2023	07/03/2023	0	7,018	0	6095	Cleaned down machine n service day Found valve on main control valve leaking Found slew motor leaking Re sealed both, cleaned down and checked again all good . *parts supplied by porters*	\$0.00
S-5572	B - 500	06/13/2023	06/26/2023	0	8,556	€	0	Resealed slew motor ( Parts supplied by porter group ) Resealed valve block on control valve Washed machine down Checks for leaks	\$0.00
R-4673	Grab	07/07/2022	06/14/2023	0		0	4957, 5081	Ground engaging gear: locks, pins, wear. Stiff arm grab broken No longer on this machine.	\$0.00
R-5991	Quick, Quick Hitch	03/13/2023	05/26/2023	0	8,402	0	6164, 6219, 6249		\$0.00
R-5922	Aircon	03/02/2023	05/26/2023	0	8,402	0	6134	A Grade Auto Repair Repaired by A Grade.	\$0.00
R-5901	Seat	02/25/2023	05/26/2023	0	8,402	0	6097		\$0.00
R-5853	Seat	02/08/2023	05/26/2023		8,402	0		Seats R Us Operator seat arm rest needs changed cushion is buggered	\$0.00
R-4957	Dipper	08/15/2022	05/26/2023	0	8,402	0	5179, 5856	Other. Dipper: check cracks, pins, bushes & shims for wear. Needs shiming	\$0.00
R-6046	Windows	03/22/2023	03/23/2023	0	8,167	0	6220	Replaced bottom front window supplied by Portors Internal Workshop - Field Service Max replaced battery supplied by Battery World Browns	\$0.00
R-5862	Batteries	02/09/2023	02/09/2023		7,953	0		Plains. Invoice attached.	\$0.00
R-5749	UHF	01/21/2023	02/08/2023		7,952	0	5951	Max Hayes	\$0.00
R-5734	Seat	01/18/2023	02/08/2023	0	7,952	0	5934	Max Hayes	\$0.00
R-5687	Electrical	12/12/2022	02/08/2023	0	7,952	0	5788	Internal Workshop - Field Service Other. Report any major concerns (take pics). Ecu fault on monitor for engine.	\$0.00
R-5678	Hydraulic leak	12/21/2022	02/08/2023	0	7,952	0	5834	Internal Workshop - Field Service Other. Check for any oil / fluid leaks. Leaking hyd hoses from bottom of pump	\$0.00
R-5675	Grouser	01/12/2023	02/08/2023	0	7,952	0	5892	Internal Workshop - Field Service Other. Chain links & grousers condition. Loose grouser plates	\$0.00
R-5488	Ram seal	11/24/2022	02/08/2023		7,952	0	5693		\$0.00
R-4405	Quick Hitch	06/01/2022	02/08/2023	0	7,952	0	4671, 5169, 5178, 5	Internal Workshop - Fabrication Other. Check attachments (if item failed - take photo). Weld on quick hitch has re-appeared	\$0.00
S-5203	C - 1000	01/10/2023	02/08/2023	0	7,952	€	0	Internal Workshop - Field Service No samples done had no bottles Coolant had been changed late last year for blown coolant hose no need to change again Operator seat arm rest needs changed cushion is buggered (R-5853).	\$0.00
R-5425	Grease nipple	11/15/2022	11/18/2022	0	7,615	0	5629		\$0.00
R-5214	Bracket	09/28/2022	11/03/2022		7,531	0	5395	Other. Broken seat brackets	\$0.00
R-5116	Locks	09/06/2022	11/03/2022	0	7,531	0	5298	Other. Check all dust seals are in good condition & working effectively. Window lock broken	\$0.00
R-5340	Bolts	10/19/2022	10/27/2022		7,498	0	5495	Other. . R/H upper Radiator support bolt is missing as per photo	\$0.00
R-5311	Air con	10/12/2022	10/27/2022		7,498	0	5464	Not Working. . Ac not working	\$0.00
R-5272	UHF	10/04/2022	10/27/2022	0	7,498	0	5421	Damaged. UHF operatial or hand held available. Hand piece damaged due to being jammed in the door.	\$0.00
S-5020	B - 500	10/24/2022	10/27/2022	0	7,498	€	0	quick hitch hose changed on service day by hydraulink drivers door window lock needs replacing 2x	\$0.00
R-5150	Teeth	09/14/2022	09/28/2022	0	7,333	0	5329, 5330	Other. Check attachments for cracks & wear on bucket, rippers, & pick up pins. Outer teeth need replacing asap	\$0.00
R-4821	Hydraulic fan motor	07/27/2022	08/08/2022	0	7,020	0	5080	Damaged. Check for any oil / fluid leaks. Fan motor has blown hose leaking hydraulic oil	\$0.00

R-4791	Air Conditioner	07/26/2022	08/08/2022		7,020	0	5070, 5112	Not Working. . Aircon needs regas	\$0.00
R-4674	Hydraulic oil	07/07/2022	07/21/2022	0	6,930	0	4960	Other. Hydraulic oil level with boom & dipper all the way out. Had to check with stiff arm grab attached, is a bit low , caused by stiff arm , can't get low enough	\$0.00
R-4669	Fire extinguisher	07/07/2022	07/21/2022	0	6,930	0	4958, 5023	Other. Fire extinguisher charged & in date. Just out of date	\$0.00
R-4663	Isolation switch	07/07/2022	07/21/2022	0	6,930	0	4961, 5024	Other. Equipment is isolated against unexpected start-up or movement. Needs lock to secure isolation switch	\$0.00
R-4662	Roller	07/07/2022	07/21/2022	0	6,930	0	4959	Other. Roller condition (top & bottom). Can't see; needs to be dug out.	\$0.00
R-4660	Grab	07/07/2022	07/21/2022	0	6,930	0	4956, 5022	Damaged. Report any major concerns (take pics). Grab broken	\$0.00
R-4570	UHF	06/27/2022	07/21/2022	0	6,930	0	4866	Other. UHF. UHF mount missing. Max - fitted new mount.	\$0.00
R-4569	Bucket	06/27/2022	07/07/2022	0	6,900	0	4867	Other. Check attachments (if item failed - take photo). Headboard on tilt bucket cracked Max: has been cracked forever doesn't effect use	\$0.00
R-4446	Quick Hitch	06/08/2022	07/07/2022		6,900	0	4712	Damaged. Crack hitch. Max: inspected with jay, okay to keep using	\$0.00
R-4410	Grab rail	06/01/2022	07/07/2022	0	6,900	0	4669	Damaged. Check grab handles, steps & walk ways. Blind side protection rail broken at the weld Max: welded up on service	\$0.00
R-4392	Steps	05/30/2022	07/07/2022	0	6,900	0	4650	Damaged. Check grab handles, steps & walk ways. Track steps bent both sides Max: pulled straight	\$0.00
S-4621	D - 2000	06/08/2022	07/05/2022	0	6,900	0			\$0.00
R-4409	Tilt Bucket	06/01/2022	06/30/2022	0	6,825	0	4670	Other. Hydraulic hoses for leaks. RHS fitting on tilt hose keeps coming loose Max: tightened fitting Glass Repairer Replace No photo - asked to re-record fault on all units.13/09 Replaced front	\$0.00
R-3221	Windscreen	08/20/2021	05/25/2022	0	6,624	0	2936, 3439, 3454,	3 windscreen by MC Auto.	\$0.00
R-3911	Steps	02/14/2022	05/20/2022	0	6,511	0	4221, 4239, 4252, 4363, 4373		\$0.00
R-3612	Air Conditioner	11/13/2021	05/20/2022	0	6,511	0	3926, 4251	Internal Workshop	\$0.00
								Internal Workshop hitch badly cracked, removed and sent to work shop for repairs l/h arm rest ripped top windscreen badly cracked needs replacing hyd tank breather/ relief valve broken bucket cylinder steel line clamp rubber missing r/h side top hand rail cracked needs welding tilt bucket reapirs, removed pin cleaned drill new hole for grease and re shimmed. ( bearings will need replacing)	
S-4511	B - 500	05/05/2022	05/17/2022	0	6,594	0		will shoot ian or jay a message to order parts needed	\$0.00
R-4222	Grease nipple	04/27/2022	05/12/2022	0	13,071	0	4489		\$0.00
R-4196	Pins	04/21/2022	05/12/2022	0	6,511	0	4470, 4604, 4651, 4660		\$0.00
R-4071	Pins	03/20/2022	03/29/2022	0	6,401	0	4364		\$0.00
R-3767	Hydraulic fitting	01/19/2022	03/24/2022	0	6,379	0	4085, 4088, 4241, 4	Max ordering new one.	\$0.00
R-4024	Bucket	03/09/2022	03/23/2022	0	6,379	0	4326		\$0.00
R-4019	Hydraulic hose	03/08/2022	03/23/2022	0	6,379	0	4320, 4322, 4353, 4365		\$0.00
R-4009	UHF	03/05/2022	03/23/2022	0	6,379	0	4306		\$0.00
R-3928	Battery	02/16/2022	03/23/2022	0	6,379	0	4254		\$0.00
R-3927	Bucket Teeth	02/16/2022	03/23/2022	0	6,379	0	4255		\$0.00
R-3750	Door lock	01/11/2022	02/14/2022	0	0	0	4060	Max - latch has been replaced. Service sheet created before service checklist was changed. E-jobcard shows 500hr service but items completed was 1000hr service, so has been changed to a C on 5/5/22.	\$0.00
S-4275	C - 1000	01/14/2022	01/12/2022	0	6,051	0			\$0.00
R-3455	Steps	09/13/2021	12/02/2021	0	5,866	0	3612		\$0.00
R-3198	Radiator	07/30/2021	12/02/2021		5,866	0	3589, 3682	Internal Workshop Replaced bottle	\$0.00

S-4032	A - 500	11/09/2021	11/17/2021	0	5,809	0	Internal Workshop	AC filters in kit are wrong. No coolant filter supplied.	\$0.00
R-2457	UHF	02/14/2021	10/05/2021		5,633	0	1619, 3560	Internal Workshop	Beacon works 2 way works
R-3332	Pin	09/21/2021	10/01/2021	0	0	0	3683	Internal Workshop	Done by Max
R-3140	Aircon	08/09/2021	08/23/2021	0	0	0	3354	Internal Workshop	Checked and repaired. Jay signed off spreadsheet.
R-3140	Air Conditioner	08/09/2021	08/23/2021			0	3354	Internal Workshop	Checked and repaired. Jay signed off spreadsheet.
R-2458	Grabs	02/14/2021	07/30/2021			0	1617	Internal Workshop	Done by Max
S-3743	B - 1000	07/23/2021	07/30/2021	0	5,290	0		Internal Workshop	Done by Max. Overflow radiator cracked - needs to be replaced.
S-3202	A - 500	12/02/2020	12/02/2020	0	4,585	0		Internal workshop	Service done Checked a/c - cleaned out evaporator & regassed E service done Quick hitch removed for repairs DEFECTS: Hydraulic breather snapped
S-185	C - 2000	05/22/2020	05/20/2020	0	3,981	0			Windscreen cracked All hydraulic filters replaced
S-23	A - 500	10/14/2019	10/14/2019	0	3,506	0			Service done, Internal workshop
R-2218	Battery	09/02/2019	09/02/2019		3,351	0			Replaced both N150 batteries, checked charging system - all ok, spray terminals with protector spray
R-2217	Grease nipple	08/23/2019	08/23/2019		3,345	0		Internal workshop	Removed broken grease nipples & replace - heat up quick hitch bushes to melt hard grease out - fill grease of machine, preheat & weld up quick hitch jaw
R-2216	Grab teeth	06/24/2019	06/24/2019		3,167	0		Internal workshop	Oxy cut grab teeth off - fitted new teeth & weld keeper plates on
S-2919	B - 1000	05/01/2019	05/01/2019	0	3,000	0			Service done, DEFECTS: need intercooler line, need quick hitch RAM seals, windscreen cracked again, needs new RHS mirror
R-2215	Aircon	02/14/2019	02/14/2019		2,785	0		Porters NSW	Inspected a/c system for electrical faults and examine for pressure leaks
R-2212	Isolator	12/20/2018	12/20/2018		2,608	0		Internal workshop	Fitted isolator switch with red lockout, fitted new LED rotating beacon
S-2918	A - 500	11/04/2018	11/04/2018	0	2,463	0		Internal Workshop	Service done, Replaced bolts on steps hand rails, blew out aircon filter DEFECTS: need intercooler line, need quick hitch RAM seals, windscreen cracked again, needs new RHS mirror
R-2211	Hammer service	08/27/2018	08/27/2018			0			Hammer was serviced on 27/08/2018
S-2917	C - 1000	05/23/2018	05/23/2018	0	1,945	0		Internal workshop	Replaced flashing light bulb, greased slew
S-2916	B - 500	01/10/2018	01/10/2018	0	1,439	0		Internal Workshop	Service done Hydraulic filters replaced
R-2208	Oil filter	09/06/2017	09/06/2017		976	0			Replaced oil filter with the correct one and replaced air con filters with the correct items
S-2908	C - 1000	08/23/2017	08/23/2017	0	926	92	0	internal workshop	Service done Hyd breather filter replaced
S-2907	B - 500	04/11/2017	04/11/2017	0	464	46	0		Service done