

5/25/2021

Pressure Tests • eStandard Solutions



Pressure Tests - 10BFA7227CF0C5778 - 2021-05-25

Authoring Information

Created By Shawn Patey
 7808753459
TC Registration 25-1118 (Expires: 2020-11-01)
Facility Fusion Tank Services
 780-875-3459
 6007 52nd ave
 Lloydminster, AB
 T9V 2S7
Created 2021-05-25 07:38:38
Updated 2021-05-25 07:38:38
Client
Company Larson Management Inc.
 5101-63st
 Lloydminster, AB
 T9V 2E7
Contact 780-205-9243

Tank Data
Ser. No. 10BFA7227CF0C5778
Unit Number LARSON 18-B (PUP)
TC Spec. DOT 407
Date of mfr. 2011-12-01
Cert. date 2011-12-01
VIN 10BFA7227CF0C5778
Tank mfr. BRENNER
Assembler BRENNER
TCRN or CRN CT-0195
MDIN CT-0195
CTMV Orig. Test Date 2011-12-01
CTMV Cert Date 2011-12-01
MAWP 25 psi
Test P. 45 psi
Mfd. head thick 9.525 mm
Min. head thick 7.440 mm
Mfd. shell thick 5.969 mm
Min. shell thick 5.660 mm
Exposed Surface 63.9 m2
Cap. 29526 litres
Lining Type Insulated
Lining N/A
Original Test Date 2011-12-01
Number of PRV's 1

Pressure Test
Inspection Date 2021-05-25

5/25/2021

Pressure Tests • eStandard Solutions

Inspection Expiry Date 2026-05-25

Test Medium Water

No. of Compartments 1

Compartments	Start (psi)	End (psi)	Hold Time
Compartment 1	0	45	60

Test Results When venting devices are removed, they are bench tested and meet the requirements for the tank
 Pass

Product piping with all valves and accessories in place and operative must be pressure tested at not less than 80% MAWP
 Pass

When removed from the pressure supply, the test pressure is retained for the specified time for the pneumatic or hydrostatic test
 Repair

Inspect the entire area of the head, shell and welds for leaks or deformation. If defects found note the location on the report
 Pass

Defects Hoses/Other
 TANK PRESSURE GAUGE INACCURATE.
 AIR LINE OFF FORT VALE HAS SPLIT.

REMOVED AND REPLACED TANK PRESSURE GAUGE.
 INSTALLED UNION AND NEW LINE.

PRV List

Type of PRV	Manufacturer	PRV Criteria	Discharge Pressure	Opening Pressure	Reseating Pressure	Disposition
# 1						
PRESSURE/VACCUM	FORT VALE	psi	90%CFR 370794 SCFH AT 40 PSIG VAC FLOW -3000 SCFH AT 12 HG	30 PSIG 10 HG	+/- 2.5% 30 PSIG -0+5% 10HG	Reinstalled

Tank Disposition

Current Disposition Tank Repaired / Re-Tested / Returned to Service

Approval

Inspector
 Shawn Patey

Tester
 SHAWN PATEY



Upper Coupler Inspections - 10BFA7227CF0C5778 - 2021-05-25

Authoring Information

Created By Shawn Patey
 7808753459
TC Registration 25-1118 (Expires: 2020-11-01)
Facility Fusion Tank Services
 780-875-3459
 6007 52nd ave
 Lloydminster, AB
 T9V 2S7
Created 2021-05-25 07:39:46
Updated 2021-05-25 07:39:46
Client
Company Larson Management Inc.
 5101-63st
 Lloydminster, AB
 T9V 2E7
Contact 780-205-9243

Tank Data

Ser. No. 10BFA7227CF0C5778
Unit Number LARSON 18-B (PUP)
TC Spec. DOT 407
Date of mfr. 2011-12-01
Cert. date 2011-12-01
VIN 10BFA7227CF0C5778
Tank mfr. BRENNER
Assembler BRENNER
TCRN or CRN CT-0195
MDIN CT-0195
CTMV Orig. Test Date 2011-12-01
CTMV Cert Date 2011-12-01
MAWP 25 psi
Test P. 45 psi
Mfd. head thick 9.525 mm
Min. head thick 7.440 mm
Mfd. shell thick 5.969 mm
Min. shell thick 5.660 mm
Exposed Surface 63.9 m2
Cap. 29526 litres
Lining Type Insulated
Lining N/A
Original Test Date 2011-12-01
Number of PRV's 1

Upper Coupler Inspection

Inspection Date 2021-05-25

Inspection Expiry Date 2026-05-25
Inspection Corroded or abraded areas
 Pass
 Cracks or defects in welds
 Pass
 Dents or distortions
 Pass
Defects No defects found.

PRV List

Type of PRV	Manufacturer	PRV Criteria	Discharge Pressure	Opening Pressure	Reseating Pressure	Disposition
# 1						

Tank Disposition

Current Disposition Passed / No Defects Found

Approval



Inspector
Shawn Patey



Tester
SHAWN PATEY

Service provided by eStandard Solutions.