



J20-14

		9312 - 110A Street Westlock, AB Canada 780-349-4282		Quality Control Record INTERNAL VISUAL / LINING INSPECTION				QF-042 Rev: 6 PAGE 1 OF 1	
				Tank S/N 5HTDL4238E5J25776		WO No. SV-24701		Inspection Date MAY 3- 2024	
Owner Larson Management Inc. 240, 6715 8th Street NE Calgary, AB T2E 7H7		Mfr HEIL		Tank Spec DOT407		Mfr Date Sep 2013		Retest Required On May 2029	
		Assembler HEIL		Min Thickness, Heads (in) .322 IN		Min Thickness, Shell (in) .228 IN		Special Services NO	
Phone No		Tank Type TRIDEM TANKER				Certification Date Sep 2013		Original Test Date Sep 2013	
Tank is Lined YES	Tank is Insulated NO	Both	Inspection Location WESTLOCK		VIN 5HTDL4238E5J25776		Material 5454-H32		
Owners's Serial No TRI-114		TCRN / MDIN / CRN		Unit No TRI-114		MAWP 35PSI		# Compartments 1	
LINING INSPECTION				Yes	No	N/A	Complies Concerns Fails		
Internal lining Inspection				X			6. Gauge cans (temp. press.) N/A		
Comments:							7. Sump X		
WF MPI: If QT or NQT w/o PWHT: Tank passed Inspection?				Yes	No	N/A	8. Piping X		
Comments:						X	9. Nozzle X		
INTERNAL VISUAL EXAMINATION				Complies	Concerns		10. Internal valves X X		
1. Head surfaces				X			11. Dumps N/A		
2. Shell welds, seams and surface				X			12. Internal grounding N/A		
3. Baffle welds and surfaces				X			13. Overlay patches (None allowed) NO		
4. Manways, signs of leakage				X			14. Corrosion strips NO		
5. Float can				X			- If yes, provide Location MC330/331 / TC331/341/11/51/60 tanks only		
Comments/Description of concerns (include severity of defects, how they were noticed. Use QF-070 to document any repairs)				1. Is tank QT or NQT			N/A		
				2. Stress relieved after manufacture? (New Tanks)			N/A		
				3. If applicable: Stress relief after repair? Complete/Local?			N/A		
				Location:			N/A		
				4. Off-truck remote emergency shutdown?			N/A		
Current Disposition of Tank Tested									
New Tank Entered in to Service ☐ Returned to Service ☒ Repair Required ☐ Condemned (removed from service) ☐									
CERTIFICATE OF INSPECTION COMPLIANCE We certify that the statements in this report are correct and the said unit has been inspected in accordance with D.O.T. Regulations, Transport Canada Regulations and Alberta Regulations.									
Wabash Mfg Inc - TC TDG Certificate of Registration #25-93									
Inspector Signature 									
Name: MAURY LITKE									
Title: INSPECTOR									
Date MAY 3- 2024									

		9312 - 110A Street Westlock, AB Canada 780-349-4282		Quality Control Record PRESSURE TEST REPORT				QF-044	
				Tank S/N 5HTDL4238E5J25776		WO No SV-24701		Rev: 6 Page 1 of 1 Test Date MAY 3 - 2024	
Owner Larson Management Inc. 240, 6715 8th Street NE Calgary, AB T2E 7H7		Mfr HEIL		Tank Spec DOT407		Mfr Date Sep 2013		Retest Required On May 2029	
		Assembler HEIL		Min Thickness, Heads (in) .322 IN		Min Thickness, Shell (in) .228 IN		Special Services NO	
Phone No		Tank Type TRIDEM TANKER				Certification Date Sep 2013		Original Test Date Sep 2013	
Tank is Lined YES	Tank is Insulated NO	Both	Inspection Location WESTLOCK	VIN 5HTDL4238E5J25776				Material 5454-H32	
Owners's Serial No TRI-114		TC/RN / MDIN / CRN		Unit No TRI-114		MAWP 35PSI		# Compartments 1	
Test Pressure 52.5 PSI		Test Medium WATER							
PREPARATION		Complies N/A	Concerns	Fails	Re-test after repair	PIPING & ACCESSORIES		Complies N/A	Concerns
1. External & Internal visual (& thickness if required) done		X				1. Assemble hose and piping on unit		X	
2. Select proper gauges and SRV		X				2. Mount test head at top of piping		X	
3. Inspect reclosing vents, inert & red flag		X				3. Press to 80% MAWP & disconnect		X	
COMPARTMENT HYDRO TEST		Complies N/A	Concerns	Fails	Re-test after repair	4. Check for leaks & 10 min retention		X	
1. Mount test head at top. Visible from safe distance		X				5. Bleed off pressure & drain		X	
2. Fill test compartment		X				COMPLETION		Complies N/A	Concerns
3. Pressure up to Test pressure & disconnect hose		X				1. Flush per 300WP		N/A	
4. Check for leaks &/or 10min retention/Bleed off pressure to MAWP/10min retention		X				2. Tag valve & placard if required		N/A	
5. Apply soap water, check for leak and/or Bleed off pressure		N/A				3. Sticker as appropriate		X	
6. Activate vent to confirm set pressure. Bleed off pressure & drain		X				4. Original Wabash file. Copies to owner		X	
PRV		Compartment 1		Compartment 2		PRV Test Report QF-046		MC330/331 / TC331/341/11/51/60 tanks only	
Make GIRARD						Completed and Attached?		1. Is tank QT or NQT N/A	
Serial Number 82096002001						YES		2. Stress relieved after manufacture? (New Tanks) N/A	
Set Pressure 42 PSI 10" HG								3. If applicable: Stress relief after repair? N/A	
Compartment 3		Compartment 4		Compartment 5				Location: N/A	
								4. Off-truck remote emergency shutdown? N/A	
Comments/Description of concerns (include severity of defects, how they were noticed. Use QF-070 to document any repairs)						TANK VOLUME (LITERS)		38,000	
Current Disposition of Tank Tested									
New Tank Entered in to Service ☐ Returned to Service ☒ Repair Required ☐ Condemned (removed from service) ☐									
CERTIFICATE OF INSPECTION COMPLIANCE We certify that the statements in this report are correct and the said unit has been inspected in accordance with D.O.T. Regulations, Transport Canada Regulations and Alberta Regulations.									
Wabash Mfg Inc - TC TDG Certificate of Registration #25-93									
Inspector Signature 					Tester Signature 				
Name: MAURY LITKE					Name: FREDDIE TUBOG				
Title: INSPECTOR					Title: TESTER				
Date: MAY 3- 2024					Date: MAY 3- 2024				

		9312 - 110A Street Westlock, AB Canada 780-349-4282		Quality Control Report UPPER COUPLER INSPECTION				QF-058	
				Rev: 2		PAGE 1 OF 1			
Owner Larson Management Inc. 240, 6715 8th Street NE Calgary, AB T2E 7H7		Tank S/N 5HTDL4238E5J25776		WO No SV-24701		Test Date: MAY 3- 2024			
		Tank Mfr HEIL		Tank Spec DOT407		Mfr Date Sep 2013			
		Assembler HEIL		Min Thickness, Heads (in) .322 IN		Min Thickness, Shell (in) .228 IN			
Phone No.		Tank Type TRIDEM TANKER		Certification Date Sep 2013		Retest Required On May 2029			
Tank is Lined YES		Tank is Insulated NO		Both		Inspection Location WESTLOCK			
Owners's Serial No. TRI-114		TCRN / MDIN / CRN		Unit No TRI-114		MAWP 35PSI			
Trailer Mfr		HEIL		Trailer Material STEEL		Trailer Mfr Date Sep 2013			
PREPARATION		Complies	Concerns	Fails	Re-test after repair	VISUAL OF HIDDEN AREA			
1. Trailer Blocked		X				1. Corrosion X			
2. Kingpin Gauge on Hand		X				2. Abrasion X			
UPPER COUPLER		Complies	Concerns	Fails	Re-test after repair	3. Cracks X			
1. Kingpin 90° ± 1° for 19"		X				4. Dents X			
2. Upper Plate Not Down 1/8" at 10"		X		X	X	5. Distortions X			
3. Upper Plate Not Down 1/4" at 19"		X		X	X	6. Weld Defects X			
4. Upper Plate Not 0.65" within 19"		X				7. Other Weakness X			
5. Loose or Missing Bolts		X				8. Repaired as Necessary X			
6. Remove Upper Coupler		X				COMPLETION			
7. Replace Upper Coupler		X				1. Original Wabash File X			
						2. Copies to Owner X			
Comments/Description of concerns (include severity of defects, how they were noticed. Use QF-070 to document any repairs) FABRICATE & INSTALL NEW UPPER COUPLER									
Current Disposition of Trailer Coupler Tested:									
Returned to Service ☒				Repair Required ☐					
CERTIFICATE OF INSPECTION COMPLIANCE We certify that the statements in this report are correct and the said unit has been inspected in accordance with D.O.T. Regulations, Transport Canada Regulations and Alberta Regulations.									
Wabash Mfg Inc - TC TDG Certificate of Registration #25-93									
Inspector Signature 									
Name: MAURY LITKE									
Title: INSPECTOR									
Date: MAY 3- 2024									