

J20.22

Pressure Tests - 5HTDL4238D5J25050 - 2020-12-21

Authoring Information

Created By

Shane Arps

17808753459

Facility

Fusion Tank Services

780-875-3459 6007 52nd ave Lloydminster, AB

T9V 2S7

Created

2020-12-21 11:05:12

Updated

2020-12-21 11:05:12

Client

Company

Goulet Trucking

Dollard

Shaunavon, SK

SON 2M0

Contact

306-210-0226

Tank Data

Ser. No.

5HTDL4238D5J25050

Unit Number

GOULET TRI-85

TC Spec.

DOT 407

Date of mfr.

2012-10-01

Cert. date

2012-10-01

VIN

5HTDL4238D5J25050

Tank mfr.

Heil Heil

Assembler

N/A

TCRN or CRN

MDIN

N/A

CTMV Orig. Test

CTMV Cert Date

2012-10-01

Date

2012-10-01

MAWP

35 psi

Test P.

52.5 psi

Mfd. head thick

.375 in

Min. head thick

Mfd. shell thick

.322 in

.250 in

Min. shell thick

.228 in

Exposed Surface

919 ft2

Cap.

10000 gallons

Lining

Sherglass FF

Original Test Date

2012-10-01

Pressure Test

Inspection Date

2020-12-21

Inspection Expiry

2025-12-21

Date

PRV set to discharge P

42 psi

Test Medium

Air

No. of

1

Compartments

Compartment 1

Start (psi)

End (psi)

Hold Time

52.5

52.5

60

Test Results

When venting devices are removed, they are bench tested and meet the requirements for the tank

Pass

Product piping with all valves and accessories in place and operative must be pressure tested at not less than 80% MAWP

Repair

When removed from the pressure supply, the test pressure is retained for the specified time for the pneumatic or hydrostatic test

Pass

Inspect the entire area of the head, shell and welds for leaks or deformation. If defects found note the location on the report

Pass

Defects

Welds/Structure

-pin hole on vent line weld (repair)


Valves/PRV/Manways

- -titan head flange leaks (replace gasket)
- -vent line flange leaks (replace gasket)

Tank Disposition

Current Disposition Tank Repaired / Re-Tested / Returned to Service

Approval



Tester

Shane Arps

Inspector Shane Arps

Service provided by eStandard Solutions.



Upper Coupler Inspections - 5HTDL4238D5J25050 - 2020-12-21

Authoring Information

Created By

Shane Arps

17808753459

Facility

Fusion Tank Services

780-875-3459 6007 52nd ave Lloydminster, AB

T9V 2S7

Created

2020-12-21 11:11:19

Updated

2020-12-21 11:11:19

Client

Company

Goulet Trucking

Dollard

Shaunavon, SK

S0N 2M0

Contact

306-210-0226

Tank Data

Ser. No.

5HTDL4238D5J25050

Unit Number

GOULET TRI-85

TC Spec.

DOT 407

Date of mfr.

2012-10-01

Cert. date

2012-10-01

VIN

5HTDL4238D5J25050

Tank mfr.

Heil

Assembler

Heil

TCRN or CRN

N/A

MDIN

N/A

CTMV Orig. Test

2012-10-01

Date

CTMV Cert Date

2012-10-01

MAWP

35 psi

Test P.

52.5 psi

.....

02.0 po.

Mfd. head thick

.375 in

Min. head thick

.322 in

Mfd. shell thick

.022 111

wird. Shell thic

.250 in

Min. shell thick

.228 in

Exposed Surface

919 ft2

Cap.

10000 gallons

Lining

Sherglass FF

Original Test Date

2012-10-01

Upper Coupler Inspection

Inspection Date

2020-12-21

Inspection Expiry

2025-12-21

Date

Inspection

Corroded or abraded areas

Pass

Cracks or defects in welds

Pass

Dents or distortions

Pass

Defects


No defects found.

Tank Disposition


Current Disposition

Passed / No Defects Found

Approval



Inspector Shane Arps



Tester Shane Arps

Service provided by eStandard Solutions.