



Internal Visual Inspections - 12-9158 - 2021-08-18

Authoring Informati	ion
Created By	Shane Arps
	17808753459
Facility	Fusion Tank Services
	780-875-3459 6007 52nd ave
	Lloydminster, AB
	T9V 2S7
Created	2021-08-18 07:53:22
Updated	2021-08-18 07:53:22
Client	
Company	Larson Management Inc.
	5101-63st
	Lloydminster, AB
	T9V 2E7
Contact	780-205-9243
Tank Data	
Ser. No.	12-9158
Unit Number	Larson T67
TC Spec.	TC 406Crude
Date of mfr.	2011-09-01
Cert. date	2011-09-01
VIN	2H9AEBHG9CT002158
Tank mfr.	Hutchinson
MDIN	8932
MAWP	20.7 Kpa
Test P.	34.5 Kpa
Mfd. head thick	6.35 mm
Min. head thick	4.39 mm
Mfd. shell thick	6.35 mm
Min. shell thick	4.39 mm
Exposed Surface	84.5 m2
Cap.	38000 litres
Original Test Date	2011-09-01
Internal Visual Insp	ection
Inspection Date	2021-08-18
Inspection Expiry Date	2026-08-18

Inspection

Lining test completed if lined as per 7.2.2.1(c)

Not Applicable

Enter the tank and inspect for: dents, gouges, cracks, corrosion, abrasions or signs of leakage in the shell or heads including bulkheads as per 7.2.2.1(a)

Pass

Inspect piping, valves and gaskets for damage as per 7.2.2.1(a)

Repair

Inspect every weld for cracks, defects or signs of leakage as per 7.2.2.1(b)

Repair

Corroded areas are thickness tested if found as per 7.2.2.1(d)

Not Applicable

Defects

Welds-Structure

-#1,6,7, and 8 baffles cracked at bottom both sides (repair)

Piping

-load line worn through (remove/replace)

PRV List

Type of PRV

PRV Manufacturer Criteria Discharge Pressure Opening Pressure Reseating Pressure


Disposition

Tank Disposition


Current Disposition

Tank Repaired / Re-Tested / Returned to Service

Approval



Inspector Shane Arps



Tester Shane Arps

Service provided by eStandard Solutions.



Pressure Tests - 12-9158 - 2021-08-18

Authoring Information	on		
Created By	Shane Arps 17808753459		
Facility	Fusion Tank Services 780-875-3459 6007 52nd ave Lloydminster, AB T9V 2S7		
Created	2021-08-18 08:00:37		
Updated	2021-08-18 08:00:37		
Client			
Company	Larson Management Inc. 5101-63st Lloydminster, AB T9V 2E7		
Contact	780-205-9243		
Tank Data			
Ser. No.	12-9158		
Unit Number	Larson T67		
TC Spec.	TC 406Crude		
Date of mfr.	2011-09-01		
Cert. date	2011-09-01		
VIN	2H9AEBHG9CT002158		
Tank mfr.	Hutchinson		
MDIN	8932		
MAWP	20.7 Kpa		
Test P.	34.5 Kpa		
Mfd. head thick	6.35 mm		
Min. head thick	4.39 mm		
Mfd. shell thick	6.35 mm		
Min. shell thick	4.39 mm		
Exposed Surface	84.5 m2		
Сар.	38000 litres		
Original Test Date	2011-09-01		
Pressure Test			
Inspection Date	2021-08-18		
Inspection Expiry Date	2026-08-18		
Test Medium	Air		
No. of Compartments	1		
Compartment 1	Start (psi)	End (psi)	Hold Time 60

Test Results

When venting devices are removed, they are bench tested and meet the requirements for the tank

Pass

Product piping with all valves and accessories in place and operative must be pressure tested at not less than 80% MAWP

Pass

When removed from the pressure supply, the test pressure is retained for the specified time for the pneumatic or hydrostatic test

Pass

Inspect the entire area of the head, shell and welds for leaks or deformation. If defects found note the location on the report

Pass

Defects

No defects found.

PRV List

Type of PRV	Manufacturer	PRV Criteria	Discharge Pressure	Opening Pressure	Reseating Pressure	Disposition
# 1						
PRESSURE/VACCUM	Tiona	psi	494084 SCFH @ 6.25 PSI	3.63 psi 1 HG	3.63 psi 1 HG	Reinstalled
# 2						
PRESSURE/VACUUM	Tiona	psi	494084 @ 6.25 psi	3.63 psi 1 HG	3.63 psi 1 HG	Reinstalled

Tank Disposition


Current Disposition Passed / No Defects Found

Approval

Inspector Shane Arps

Tester Shane Arps

Service provided by eStandard Solutions.





Upper Coupler Inspections - 12-9158 - 2021-08-18

Authoring Informati	on
Created By	Shane Arps 17808753459
Facility	Fusion Tank Services 780-875-3459 6007 52nd ave Lloydminster, AB T9V 2S7
Created	2021-08-18 08:04:56
Updated	2021-08-18 08:04:56
Client	
Company	Larson Management Inc. 5101-63st Lloydminster, AB T9V 2E7
Contact	780-205-9243
Tank Data	
Ser. No.	12-9158
Unit Number	Larson T67
TC Spec.	TC 406Crude
Date of mfr.	2011-09-01
Cert. date	2011-09-01
VIN	2H9AEBHG9CT002158
Tank mfr.	Hutchinson
MDIN	8932
MAWP	20.7 Kpa
Test P.	34.5 Kpa
Mfd. head thick	6.35 mm
Min. head thick	4.39 mm
Mfd. shell thick	6.35 mm
Min. shell thick	4.39 mm
Exposed Surface	84.5 m2
Cap. Original Test Date	38000 litres 2011-09-01
Original Test Date	2011-09-01
Upper Coupler Insp	ection
Inspection Date	2021-08-18
Inspection Expiry Date	2026-08-18
Inspection	Corroded or abraded areas Repair
	Cracks or defects in welds Pass
	Dents or distortions Pass

Upper Coupler Inspections » eStandard Solutions Defects Welds-Structure -pin failed (remove/replace) **PRV List** PRV Discharge Opening Reseating Type of PRV Manufacturer Criteria Pressure Pressure Pressure Disposition # 1 Tank Disposition **Current Disposition** Tank Repaired / Re-Tested / Returned to Service Approval

Tester

Shane Arps

Inspector

Shane Arps

Service provided by eStandard Solutions.

