



Pressure Tests - 5HTDL292XD5F25342 - 2021-07-06

Authoring Information

Created By	Shane Arps 17808753459
Facility	Fusion Tank Services 780-875-3459 6007 52nd ave Lloydminster, AB T9V 2S7
Created	2021-07-05 10:43:32
Updated	2021-07-05 10:43:32

Client

Company	Larson Management Inc. 5101-63st Lloydminster, AB T9V 2E7
Contact	780-205-9243

Tank Data

Ser. No.	5HTDL292XD5F25342
Unit Number	LARSON 310016 (PUP)
TC Spec.	DOT 407
Date of mfr.	2013-06-01
Cert. date	2013-06-01
VIN	5HTDL292XD5F25342
Tank mfr.	Heil
Assembler	Heil
TCRN or CRN	N/A
MDIN	N/A
CTMV Orig. Test Date	2013-06-01
CTMV Cert Date	2013-06-01
MAWP	35 psi
Test P.	52.5 psi
Mfd. head thick	.375 in
Min. head thick	.309 in
Mfd. shell thick	.250 in
Min. shell thick	.220 in
Exposed Surface	622 ft2
Cap.	7270 gallons
Lining	Sherglass FF
Original Test Date	2013-06-01

Pressure Test

Inspection Date	2021-07-06
Inspection Expiry Date	2026-07-06
Test Medium	Air

No. of
Compartments
Compartment 1

1

Start (psi)	End (psi)	Hold Time
52.5	52.5	60

Test Results

When venting devices are removed, they are bench tested and meet the requirements for the tank

Pass

Product piping with all valves and accessories in place and operative must be pressure tested at not less than 80% MAWP

Pass

When removed from the pressure supply, the test pressure is retained for the specified time for the pneumatic or hydrostatic test

Pass

Inspect the entire area of the head, shell and welds for leaks or deformation. If defects found note the location on the report

Pass

Defects

No defects found.


PRV List

Type of PRV # 1	Manufacturer	PRV Criteria	Discharge Pressure	Opening Pressure	Reseating Pressure	Disposition
PRESSURE/VACCUM	GIRARD	psi	484718 SCFH @ 52.5 psi	42 psi 10 HG	42 psi 10 HG	Reinstalled


Tank Disposition

Current Disposition Passed / No Defects Found

Approval



Inspector
Shane Arps



Tester
Shane Arps



Upper Coupler Inspections - 5HTDL292XD5F25342 - 2021-07-06

Authoring Information

Created By	Shane Arps 17808753459
Facility	Fusion Tank Services 780-875-3459 6007 52nd ave Lloydminster, AB T9V 2S7
Created	2021-07-05 10:46:26
Updated	2021-07-05 10:46:26

Client	
Company	Larson Management Inc. 5101-63st Lloydminster, AB T9V 2E7
Contact	780-205-9243

Tank Data	
Ser. No.	5HTDL292XD5F25342
Unit Number	LARSON 310016 (PUP)
TC Spec.	DOT 407
Date of mfr.	2013-06-01
Cert. date	2013-06-01
VIN	5HTDL292XD5F25342
Tank mfr.	Heil
Assembler	Heil
TCRN or CRN	N/A
MDIN	N/A
CTMV Orig. Test Date	2013-06-01
CTMV Cert Date	2013-06-01
MAWP	35 psi
Test P.	52.5 psi
Mfd. head thick	.375 in
Min. head thick	.309 in
Mfd. shell thick	.250 in
Min. shell thick	.220 in
Exposed Surface	622 ft2
Cap.	7270 gallons
Lining	Sherglass FF
Original Test Date	2013-06-01

Upper Coupler Inspection

Inspection Date	2021-07-06
Inspection Expiry Date	2026-07-07

Inspection

Corroded or abraded areas

Pass

Cracks or defects in welds

Pass

Dents or distortions

Pass

Defects

No defects found.



PRV List

Type of PRV	Manufacturer	PRV Criteria	Discharge Pressure	Opening Pressure	Reseating Pressure	Disposition
# 1						

Tank Disposition

Current Disposition Passed / No Defects Found

Approval



Inspector
Shane Arps

Tester
Shane Arps

Service provided by eStandard Solutions.