

020-1  
BULE-MAR



# Vehicle Inspection Report

Traffic Safety Services  
Monitoring and Compliance, Investigations and Enforcement  
Transportation and Economic Corridors  
Government of Alberta

TSIS File # 515112  
Certificate# 4000411127 (OC)

### Vehicle Information

Make Prevost	Model H341	Year 1999	Plate Number N/A	Jurisdiction OC
Vehicle Identification Number (VIN) 2PCH33418X1012958		Vehicle Status OOP- active		
Component	Violation Description	Section/Act		
Brakes	Air compressor build up 85-100 exceeds 2 min	Sec.3A(2)(a) CVIM		
Suspension	Sway bar links are worn	Sec. 2(2)(d) CVIM		
Body	Engine compartment door fails to hold in open position	Sec. 8(1)(b) CVIM		
* Body	Entry door leaking air / does not lock as intended	Sec. 8(28)(a) CVIM		
Body	Floor near muffler rotted / coated with spray foam(fire hazard)	Sec. 8(4)(a) CVIM		
* Wheels	All Wheel rim stud holes worn / oblonged	Sec. 9(10)(b) CVIM		
Wheels	Drive axle output seal level 3 leak	Category of fluid leaks		
* Fixed Lock on Door / All rims replaced. New Feb/2026 Dann bh				

### Comments for Vehicle Owner

- Unsafe   
  Revoked   
  Not Revoked   
  Not applicable

Name of Investigator F. Lotocki	Badge Number 8670	Agency Vehicle Safety	Office Red deer
Signature Of Owner/Operator		Failure to report indicated repairs by: may result in prosecution. Report to <a href="mailto:frank.lotocki@gov.ab.ca">frank.lotocki@gov.ab.ca</a>	