

COPY



O.E. Motors
(780) 980-2132
service@oemotors.ca
7002 39th St, , Leduc, AB, Canada, T9E 0W1
Company Business/GST
number:790109706RT0001

Invoice # 53650
Against Estimate#: 16335
Created: Apr 22, 2026
Invoiced: Apr 27, 2026
Service Advisor: Janaya Lingnau

Richard Rutherford

1980 Rolls-Royce Silver Shadow
VIN: SRL41412
Mileage in: 19815 km
Mileage Out: 19819 km
License Plate:

Customer Notes

opi
**SHUT OFF SWITCH IN TRUNK

Vehicle Inspection Report

An inspection of the vehicle was performed. During the inspection, it was found that the engine oil pan and transmission oil pan have oil leaks. The windshield washer system is not functioning.

The front wheel bearings have noticeable play and require adjustment. The parking brake does not hold properly and also requires adjustment.

During the test drive, a knocking noise was noted coming from the front suspension. Upon further inspection, it appears that the front shock absorbers may not be properly tightened. It is recommended to remove, inspect for any damage, and properly tighten as needed.

To meet inspection requirements, the following repairs are required:

- * Repair the windshield washer system
- * Adjust front wheel bearings
- * Adjust parking brake
- * Inspect and properly secure front shock absorbers

OPI - Out of Province Vehicle Inspection

Authorized

Item	Name	Description	Price x Qty / Hrs	Amount	Disc./Fees	Subtotal
1	Out of Province Vehicle Inspection	Perform a Out of Province Vehicle inspection as per the outlined criteria by the Automotive & Light Truck Vehicle Inspection Manual issued by the Government of Alberta.	\$97.50 x 2	\$195.00		\$195.00
				Amount:	Disc: \$-0.00	Subtotal:
				\$195.00		\$195.00

Approved by Richard Rutherford on Apr 22, 2026 11:00 am



O.E.Motors
(780) 980-2132
service@oemotors.ca
7002 39th St , Leduc, AB, Canada, T9E 0W1
Company Business/GST
number:790109706RT0001

Invoice # 53650
Against Estimate#: 16335
Created: Apr 22, 2026
Invoiced: Apr 27, 2026
Service Advisor: Janaya Lingnau

Date and Time	Receipt No	Payment Method	Amount	Service Amount	
Apr 27, 2026 5:27 pm	13706	Card - Debit	\$213.56		
		xxxx-xxxx-5607			
		Auth code			
		701265			
				Service Amount	\$195.00
				Part	\$0.00
				Labor	\$195.00
				Add: Fees	\$8.39
				Shop supplies	\$8.39
				Subtotal	\$203.39
				Sales Taxes (Sales Tax - 5%)	\$10.17
				Invoice Total	\$213.56
				Paid to date	\$213.56
				Remaining Balance	\$0.00

By signing this document, you agree to the Terms and Conditions mentioned below.

Signature: Richard Rutherford

Disclaimer:

Thank you for your business. The work is complete and your payment is due upon pickup of the vehicle.

Payment Terms: Payment is due upon completion of work. A storage fee of \$25 per day applies to vehicles not retrieved within 5 business days of the completion notice

Mechanics liens may be placed on vehicles until repairs are paid for in full.
Please contact us promptly if you have any questions about anything we did.

Important Notice:

O.E. Motors has moved. Our new address is 7002 39 St, Leduc, AB T9E 0W1
Located in Leduc Business Park