



[PRESSURE TEST REPORT P1]

1

J03-4
AUG

Date: September 11, 2022

Bassett Petroleum Dist. Ltd.
TC Reg: 25-0883
182-55202 825 HWY
Sturgeon County, AB, T8L5C1
780-449-2577

Client: Bassett Petroleum Distributors Ltd
Address: 182-55202 825 HWY
City: Sturgeon County, AB
Postal Code: T8L5C1
Phone: 780-449-2577

Tank serial number: TR127

VIN: 2AEAPUAK11R000433

Tank Type: DOT406

Orig. test date: Aug 2001

Vacuum: N

Corrosive Service: N

Date of MFG: Aug 2001

Comp/Cert date: Aug 2001

CTMV orig. Test date: _____

CTMV Cert Date: _____

Manufacturer: Advance Engineered Products

Assembler: Advance E.P.

TCRN: _____

MDIN: _____

MAWP: 3.3 Psi

Test Pressure: 5 Psi

Man. Thickness Head: .250 IN

Min. Thickness Head: .235 IN

Man. Thickness Shell: .188 IN

Min. Thickness Shell: .173 IN

Exposed surface area: 1- 271.9 2- 110.7 3- 100.9 4- 281.7 Sq.Ft.

Volumetric Capacity: 1- 3170 2- 1585 3- 1453 4- 3302 USG

Lining Material: N/A

Compartment #	Start test pressure	End test pressure	Hold Time
1	5	5	1 hr
2	5	5	1 hr
3	5	5	1 hr
4	5	5	1 hr
5			

Pressure Test

	Pass	Fail	Rep.	NA
When venting devices are removed, they are bench tested and meet the requirements for the tank	☒	☐	☐	☐
Product piping with all valves and accessories in place and operative must be pressure tested at not less than 80% MAWP	☒	☐	☐	☐
When removed from the pressure supply, the test pressure is retained for the specified time for the pneumatic or hydrostatic test	☒	☐	☐	☐
Inspect the entire area of the heads and shell including all welds for leaks or deformation.	☒	☐	☐	☐

*If a pneumatic test is authorized and completed. The test time can remain at 10 minutes if a soapy solution is applied to all areas of the tank that may produce a leak.



Such as: flanges, connections, manways, openings, welds etc. The time can be increased to one hour with no noticeable drop in pressure in lieu of soaping the exterior surfaces.

Defect and location

Tank Disposition

- ☒ Pass ☐ Repaired/Re-tested/Returned to service
☐ Fail/removed from service ☐ Removed from facility

Inspector name: Colin MacLennan

Tester name: Colin MacLennan

Inspector Signature: [Signature]

Tester Signature: [Signature]

Date signed: September 11, 2022

Date signed: September 11, 2022

Inspection expires: September 11, 2027

Markings applied: Yes



[INTERNAL INSPECTION REPORT I1]

1

Date: September 11, 2022

Bassett Petroleum Dist. Ltd.
TC Reg: 25-0883
182-55202 825 HWY
Sturgeon County, AB, T8L5C1
780-449-2577

Client: Bassett Petroleum Distributors Ltd
Address: 182-55202 825 HWY
City: Sturgeon County, AB
Postal Code: T8L5C1
Phone: 780-449-2577

Tank serial number: TR127

VIN: 2AEAPUAK11R000433

Tank Type: DOT406

Orig. test date: Aug 2001

Vacuum: N

Corrosive Service: N

Date of MFG: Aug 2001

Comp/Cert date: Aug 2001

CTMV orig. Test date: _____

CTMV Cert Date: _____

Manufacturer: Advance Engineered Products

Assembler: Advance E.P.

TCRN: _____

MDIN: _____

MAWP: 3.3 Psi

Test Pressure: 5 Psi

Man. Thickness Head: .250 IN

Min. Thickness Head: .235 IN

Man. Thickness Shell: .188 IN

Min. Thickness Shell: .173 IN

Exposed surface area: 1- 271.9 2- 110.7 3- 100.9 4- 281.7 Sq.Ft.

Volumetric Capacity: 1- 3170 2- 1585 3- 1453 4- 3302 USG

Lining Material: N/A

Lining test completed if lined as per 7.2.2.1(c)	Pass ☒	Fail ☐	Rep. ☐	NA ☐
Enter the tank and inspect for: dents, gouges, cracks, corrosion, abrasions or signs of leakage in the shell or heads including bulkheads as per 7.2.2.1(a)	Pass ☒	Fail ☐	Rep. ☐	NA ☐
Inspect piping, valves and gaskets for damage as per 7.2.2.1(a)	Pass ☒	Fail ☐	Rep. ☐	NA ☐
Inspect every weld for cracks, defects or signs of leakage as per 7.2.2.1(b)	Pass ☒	Fail ☐	Rep. ☐	NA ☐
Corroded areas are thickness tested if found as per 7.2.2.1(d)	Pass ☒	Fail ☐	Rep. ☐	NA ☐


Defect and location

Tank Disposition

☒ Pass ☐ Repaired/Re-tested/Returned to service
☐ Fail/removed from service ☐ Removed from facility

Inspector name: Colin MacLennan Tester name: Colin MacLennan

Inspector Signature: 

Tester Signature: 

Date signed: September 11, 2022

Date signed: September 11, 2022

Inspection expires: September 11, 2027

Markings applied: Yes