

PARKSIDE WELDING AND REPAIR

Box 96
Parkside, Saskatchewan S0J 2A0
Canada
Tel: (306) 747-2000

INVOICE

Invoice No: 9163
Date: 01/08/2024
Page: 1

Sold to:

Jaran Farms
Jason Ranger
Box 397
Leask, Sk S0J 1M0

13413.88

Chq# 2023
Aug 12/24

Business No.: 829318617

Item No.	Qty	Unit	Description	Tax	Unit Price	Amount
			2012 KENWORTH W900 Plate#093JCX PO#964556			
			PARTS			
Parts - Repair	4	Each	Drive axle brake drums 16 5x7 PWR BD16127	PE	109.88	439.52
Parts - Repair	4	Each	Drive axle brake shoes w hardware 16 5x7 (4709) PWR 077S236N	PE	99.99	399.96
Parts - Repair	2	Each	LH drive axle S-cams PWR 12010315 01	PE	82.08	164.16
Parts - Repair	2	Each	RH drive axle S-cams PWR 12010315 02	PE	82.08	164.16
Parts - Repair	2	Each	Drive axle S-cam bushing kits PWR CSK1022	PE	27.11	54.22
Parts - Repair	4	Each	Drive axle wheel seals PWR 47691XT	PE	69.45	277.80
Parts - Repair	4	Each	Drive axle flange gaskets PWRSTM330-3107	PE	3.25	13.00
Parts - Repair	32	Each	Drive axle 5/8" fine nylock nuts	PE	0.60	19.20
Parts - Repair	4	Each	Drive axle wheel bearing set 429 PWR SET429	PE	131.21	524.84
Parts - Repair	4	Each	Drive axle wheel bearings set 430 PWR SET430	PE	107.36	429.44
Parts - Repair	4	Each	Drive axle brake pots (3030LS) PWR M1R3030TCLS	PE	64.03	256.12
Parts - Repair	4	Each	Drive axle slack adjuster PWR 135S1034	PE	165.29	661.16
Parts - Repair	2	Each	Steer axle brake drums 16 5x5 PWR 151 6501BA	PE	249.28	498.56
Parts - Repair	4	Each	Steer axle brake shoes 16 5x5 PWR 078M041R	PE	49.99	199.96
Parts - Repair	2	Each	Steer axle brake shoe hardware kit PWR 8HK078	PE	25.55	51.10
Parts - Repair	1	Each	LH steer axle s-cam PWR CAM389L	PE	136.23	136.23
Parts - Repair	1	Each	RH steer axle s-cam PWR CAM389R	PE	136.23	136.23
Parts - Repair	1	Each	Steer axle s-cam bushing kit PWR CSK1022	PE	27.11	27.11
Parts - Repair	2	Each	Steer axle wheel seals PWR 35058XT	PE	59.86	119.72
Parts - Repair	2	Each	Steer axle hub cap gaskets PWR STM330-3024	PE	2.80	5.60
Parts - Repair	2	Each	Steer axle wheel bearings (set 427) PWR SET427	PE	117.35	234.70
Parts - Repair	2	Each	Steer axle wheel bearings (set 428) PWR SET428	PE	84.96	169.92
Parts - Repair	2	Each	Steer axle brake pots (type 24LS) PWR HD24SLS	PE	77.91	155.82
Parts - Repair	2	Each	Steer axle slack adjusters PWR 40020221	PE	166.71	333.42
Parts - Repair	2	Each	Driveshaft u-joints (SPL250) PWR SPL2503X	PE	279.99	559.98
Parts - Repair	1	Each	8" convex heated mirror (LH side is not working) PWR 12283	PE	53.75	53.75
Parts - Repair	1	Each	Mudflaps retro tape plate kit PWR NRS3000	PE	44.99	44.99
Parts - Repair	1	Each	U-joint @ trans output (SPL170) PWR SPL1704X	PE	190.55	190.55
Parts - Repair	1	Each	Steer axle brake shoe CORE PWR 078M04IRCORE	PE	40.50	40.50
Freight - R	1		Freight Charge - Repair	PE	75.00	75.00
			Subtotal			6,440.72
			PE - GST 5%, PST Exempt GST			322.08
Thank you for your business.				Total Amount		6,762.80
				Amount Paid		0.00
				Amount Owning		6,762.80

PARKSIDE WELDING AND REPAIR

Box 96
Parkside, Saskatchewan S0J 2A0
Canada
Tel: (306) 747-2000

INVOICE

Invoice No: 9184
Date: 01/08/2024
Page: 1

Sold to:

Jaran Farms
Jason Ranger
Box 397
Leask, Sk S0J 1M0

Business No.: 829318617

Item No.	Qty	Unit	Description	Tax	Unit Price	Amount
			2019 DOEPKER SUPER 8 LEAD & PUP TRAILERS Lead Trailer Plate#000LJA PO#038718 Pup Trailer Plate#001LJA PO#038719			
			PARTS			
Parts _ Repair	10	Each	16 5X7 brake drums PWR BD16127	PE	109.88	1,098.80
Parts _ Repair	10	Each	16 5x7 brake shoes (4707) PWR 046S236N	PE	99.99	999.90
Parts _ Repair	10	Each	S-cam bushing kits PWR CSK4181	PE	32.48	324.80
Parts _ Repair	5	Each	LH S-cam PWR 349L	PE	56.24	281.20
Parts _ Repair	5	Each	RH S-cam PWR 349R	PE	53.74	268.70
Parts _ Repair	10	Each	Wheel seals PWR RM-T03	PE	52.50	525.00
Parts _ Repair	10	Each	Wheel hub gaskets PWR STM330-3009	PE	2.83	28.30
Parts _ Repair	10	Each	Shocks PWR>6546 16	PE	117.35	1,173.50
Parts _ Repair	10	Each	Wheel bearings (set 413) PWR SET413	PE	52.48	524.80
Parts _ Repair	10	Each	Wheel bearings (set 414) PWR SET414	PE	77.49	774.90
Parts _ Repair	10	Each	Wheel bearing grease #2 PWR.30177-T	PE	8.60	86.00
Parts _ Repair	4	Each	ABS Speed sensors PWR.528140	PE	62.11	248.44
			Subtotal:			6,334.34
			PE - GST 5%, PST Exempt GST			316.74
<i>Thank you for your business.</i>				Total Amount		6,651.08
				Amount Paid		0.00
				Amount Owning		6,651.08

Fwd: Your Engine Parts Canada Order Confirmation (#7950)


Brett Skarpinsky <skarpinskyautomotive@hotmail.com>
To: Jaran Farms <admin@jaranfarms.com>

Mon, Oct 21, 2024 at 4:21 PM

Sent from my iPhone

Begin forwarded message:

From: Engine Parts Canada <sales@epcparts.ca>
Date: October 21, 2024 at 4:07:21 PM CST
To: skarpinskyautomotive@hotmail.com
Subject: Your Engine Parts Canada Order Confirmation (#7950)
Reply-To: sales@epcparts.ca



Thanks for your order

Order #7950

Items shipped to 54 main street, MJW Accounting, Shellbrook, Saskatchewan, S0J 2E0,
Can



**4359487 - Cummins ISX15 High
Pressure Fuel Pump | 4384016**

D4359487

Core Charge: D4359487 Core Charge - \$1000
included in the price

CA\$5,095.00 CAD

Qty: 1

CA\$5,095.00
CAD

Subtotal:

CA\$5,095.00 CAD

Shipping:	CA\$55.00 CAD
GST:	CA\$257.50 CAD
PST:	CA\$309.00 CAD
Grand total:	CA\$5,716.50 CAD
Payment method:	Visa or Mastercard
Shipping method:	Quoted Shipping (Ground) for CA\$55.00 CAD

Shipping address

Brett Skarpinsky
JARAN FARMS LTD
54 MAIN STREET
MJW ACCOUNTING
SHELLBROOK, SASKATCHEWAN S0J 2E0
CANADA
13067477637

[Check order status](#)

Billing Address

Brett Skarpinsky
JARAN FARMS LTD
54 MAIN STREET
MJW ACCOUNTING
LEASK, SASKATCHEWAN S0J 1M0
CANADA
13067477637



Engine Parts Canada
enginepartscanada.ca

[Go shopping](#)