

Work Order on 2018 New Holland T8.390 Tractor

Harder's Iron Horse Garage
 Box 168
 Dundurn SK S2K 1K0
 3069147725
 ingan.harder02@gmail.com
 CST/HST Registration No 703148313RT0001

INVOICE

BILL TO

INVOICE # 1618
 DATE 08/02/2025
 DUE DATE 08/02/2025
 TERMS Due on receipt

ACTIVITY	QTY	TAX	RATE	AMOUNT
Shop Rate T8.390 New Holland replace range and power shift transmissions flushed out lines and transferred all exterior parts to new transmissions disassembled axles to repair and install brakes and axle stub shafts	1	GST	15,000.00	15,000.00
Parts brake plate	8	GST	94.00	752.72
Parts brake friction plate	8	GST	209.94	1,679.52
Parts piston	2	GST	361.37	722.74
Parts oring	8	GST	3.02	24.16
Parts shield	1	GST	64.94	64.94
Parts seal	1	GST	134.20	134.20
Parts gasket	1	GST	84.27	84.27
I certify that the above parts and services are for item use and location			SUBTOTAL (1ST @ 5%) TOTAL	18,462.56 923.14 19,385.69

All amounts must be paid in full before equipment will be released
 We Payroll to
 Box 168
 Dundurn SK
 S2K 1K0
 Or call 306-914-7725 to arrange pickup
 Thank you.

Signature _____

BALANCE DUE

\$19,385.69

INVOICE

BILL TO

INVOICE # 1599
 DATE 03/04/2025
 DUE DATE 03/04/2025
 TERMS Due on receipt

ACTIVITY	QTY	TAX	RATE	AMOUNT
Parts filter	1	GST	188.27	188.27
Parts filter	1	GST	153.05	153.05
Exc filter	2	GST	1.25	2.50
Parts gasket	1	GST	29.48	29.48

I hereby authorize you that the above parts and services are for Lake Superior
 Signature: _____

SUBTOTAL 87,617.62
 GST @ 5% 4,380.86
 TOTAL 91,998.50
BALANCE DUE \$91,998.50

ACTIVITY	QTY	TAX	RATE	AMOUNT
Shop Rate New Holland T8.390 low tractor into shop go through complete transmission and rear end systems to diagnose what is causing Transmission low pressure issue found that the park brake clutch pack had failed and is sending fillings and debris throughout the whole transmission and hydraulic system disassembled and removed range transmission from tractor removed valves and range clutches and gears found filling and contamination in valves removed parkbrake/FWA clutch packs while disassembling I noticed the engineering flaw that caused failure, the glued seal where oil goes from shaft to clutch piston had failed the new style range transmission has an updated shaft with oiling to correct this issue, speed transmission and two shaft need to be changed also to match up with new style range transmission this is the best option since we have already seen signs of contamination at the transmission clutch packs	1	GST	10,000.00	10,000.00
Parts updated reman range transmission	1	GST	24,156.25	24,156.25
Parts core for reman range transmission will need find out if its worth shipping back for credit	1	GST	1,438.30	1,438.30
Parts new speed transmission	1	GST	48,683.29	48,683.29
Parts FWA upgrade shaft	1	GST	2,327.74	2,327.74
Parts tube	1	GST	251.70	251.70
Parts screen	1	GST	205.68	205.68
Parts switch	1	GST	102.40	102.40
Parts gasket	1	GST	79.96	79.96

pd RBC NSF
Repair 2012 NH T-8390 TRACTOR

Harder's Iron Horse Garage
 Box 188
 Duncburn SK 53K 1K0
 3069147725
 lsgan.harder02@gmail.com
 GST/HST Registration No. 703148313RT0001

INVOICE

BILL TO

INVOICE # 1632
DATE 08/19/2025
DUE DATE 08/19/2025
TERMS Due on receipt

DESCRIPTION	QTY	TAX	RATE	AMOUNT
Shop Rate New Holland T8.350 completed assembly of transmissions reassembled everything that was previously removed from tractor had to clean rust from all the bolts and a lot of time and research was needed to figure out where everything needed to go	1	GST	20,000.00	20,000.00
Hydraulic oil	10	GST	110.00	1,100.00
Enviro	10	GST	3.34	33.40
Enviro	9	GST	1.10	9.90
Anti-freeze	9	GST	16.99	152.91
jugs				
Parts	1	GST	350.00	350.00
Deisel lue:				
Parts	1	GST	6,397.20	6,397.20
Engine controller. Software and programming				
Parts	2	GST	123.56	247.12
exhaust clamo				
Parts	1	GST	19.97	19.97
gasket				
Parts	10	GST	4.22	42.20
bol				

All invoices must be paid in full before use or prior to be released

Mail Payment to
 Box 188
 Duncburn SK
 53K 1K0

Or call 1-301-914-7725 to arrange pickup
 Thank you.

DESCRIPTION	QTY	TAX	RATE	AMOUNT
Parts	6	GST	4.84	29.04
bol				
Parts freight	1	GST	50.00	50.00
Parts	1	GST	188.27	188.27
filter				
Parts	1	GST	153.05	153.05
filter				
Eho filter	2	GST	1.10	2.20
Shop supplies	1	GST	250.00	250.00
Parts	1	GST	216.10	216.10
filter head				
Parts	1	GST	1,090.17	1,090.17
steering sensor				
Parts	1	GST	1.83	1.83
snap ring				
Parts	1	GST	2,500.00	2,500.00
used New Holland GPS antenna				
Shop Rate	1	GST	1,500.00	1,500.00
Diagnose steering sensor issue for auto steer disassemble left front steering knuckle and replace sensor set up and calibrate auto steer				

ACTIVITY	QTY	TAX	RATE	AMOUNT
Shop Rate Repair issues with tractor after it has been assembled and test driven electric fuel pump not working, removed, and disassembled, it was seized from riding for so long	1	GST	5,000.00	5,000.00
Engine controller randomly going offline tested at powers, grounds and communication was going to a trim controller, all tested good replaced controller and reprogrammed				
front axle suspension not working tested electrical at good found stuck valve in manifold, cleaned and tested				
pto not turning on, switch was sticking, cleaned and tested				
3 point hitch load coil error turn off the loady sensor, set have working one on the other side				
hydraulic remote valves not working contaminated oil causing valves to stick took apart flushed and cleaned tested				
brakes only working on one side pressure tested and found two hoses were hooked up backwards from the factory				
replaced hydraulic filters after testing tractor				
Air conditioning trim	1	GST	112.00	112.00

I certify that the above parts and services are for farm use
 Signature _____

SUBTOTAL	39,445.36
GST @ 5%	1,972.28
TOTAL	41,417.64
BALANCE DUE	\$41,417.64

All revenues must be paid in full before equipment will be released
 Make Payment to
 010 100
 Ontario St
 SSM 100
 Or call 1-800-414-7729 to arrange pickup
 Thank you.