



137-139 Henty Street, Casterton Victoria 3311

ABN:71 633 754 631

Licence:Arctick License AU50216

Phone: 03 5581 1142

Email: jarradmotorscasterton@gmail.com

Website: www.jarradmotors.com.au

SERVICE HISTORY

VIN: ZC08AS4JJE2000287

Make: McCormick

Model: CX80

Year: 2001

DATE	DESCRIPTION
14/03/2024	<p>Odometer: 7,324 Total: \$2,585.33 Job No: CJ8441 Inv No: CI10815</p> <p>service & battery not charging - fuel priming issue - make bracket so bonnet shuts, Tractor Service Every 250hr</p> <p>Tractor Service Every 250hr:</p> <p>Carried out Service on Tractor</p> <ul style="list-style-type: none">-Replace engine oil and filter-Change Fuel Filter and Bleed Fuel System <p>General Check over Tractor</p> <ul style="list-style-type: none">-Clean cab air filters-Check all Lights including Beacon, work lights and interior lights-Check and adjust Door latch and striker-Lubricate and Grease Tractor and all attachments i.e. Loader, 4in1 etc.-Check tightening torque of the wheel bolts-Check tyre inflation pressure and wear-Check Battery electrolyte level and terminals. check engine cranking speed-Electronic diagnosis: reading and cancelling alarms - calibration and settings-Check window washer fluid-Clean front window and check wiper condition-Check operation of wipers and washers-Check operation of seat adjustment-Check mechanical and electronic controls for transmission, 3 point linkage, hydraulic remote valves, front end loader and PTO etc.-Check seat belt condition <p>Engine</p> <ul style="list-style-type: none">-Clean air cleaner element-Check the Engine coolant level-Inspect Radiator, coolant Hoses, water pump and engine for signs of coolant leaks-Clean Radiator and coolers-Check Fuel sediment trap for water and contaminants-Check the Engine Belt and Tensioner

Driveline and Hydraulic system

- Check oil level of transmission and hydraulic system
- Check oil level in front axle and final drives
- Check parking brake and Lubricate mechanism
- Check clutch and brake fluid level
- Check oil lines for damage and leaks

Front End Loader

- Inspect pins for wear and missing/broken bolts
- Inspect oil lines for rubbing and leaks
- Tighten loader frame mounting bolts
- Check locking system for Euro hitch

28/05/2023 **Odometer:** 7,278.6 **Total:** \$6,703.88 **Job No:** CJ7281 **Inv No:** CI8660

clutch issue- stiff and riding clutch when letting clutch out, service as well

03/05/2023

traveled to site (travel charged on inv CI8606)

checked clutch

found clutch to be slipping, will need to be replaced

.....

Removed loader, split tractor, removed clutch and fly wheel

Sent fly wheel away to be machined

Refit fly wheel and new clutch

Reassembled tractor

Regas A/C

Topped up trans oil

Changed engine oil and oil filter

Changed fuel filter

Changed air filter

Checked/topped up fluid levels

Refit loader

Removed and re welded exhaust tip as required

Test drove, all okay

14/01/2021 **Odometer:** **Total:** \$599.35 **Job No:** **Inv No:** 4796

minor service McCormick cx80, hand throttle doesn't work, customer is unsure if its the cable or something else

Travelled to site

McCormick: 6559 HOUR SERVICE

- Removed and replaced engine oil
- Removed and replaced oil filter
- Removed and replaced fuel filter
- Check over, okay

Checked hand throttle, clip had come off customer will fit

A/C belt needs to be replaced, customer will replace

09/06/2020

Odometer:

Total: \$437.90

Job No: 1349

Inv No: 2628

check hydraulic oil levels- top up if needed, leaking under the cab?perished, take 1/2inch hose to replace.

- Check tractor for fuel and oil leak

- Found oil leak at loose fitting on steering box

- Tightened up fitting and stopped leak

- Found fuel leak due to a pin hole in hose.

- Shortened hose and stopped fuel leak

- Filled with oil and left the rest of the drum at site
