

Submission	Section Name	Name	Unit #	Date	Unit Hours	Description of Work	Total Time to Complete Work
28017	Work Completed	Doug	404	12/01/2022	20208	Switch grapple rotate wires.	1
28047	Work Completed	Wade	404	12/08/2022	20311	Drove to Sat yard and fixed an oil leak on the grapple.	1
28050	Work Completed	Doug	404	12/09/2022	20368	Engine oil service.	1.5
28313	Work Completed	Doug	404	01/04/2023	20608	Service engine oil and fuel. Needs primer pump.	2
28333	Work Completed	Doug	404	01/05/2023	20627	Changed 90 degree #16 SIC union on left hand side of the...(Did not finish sentence).	2
28626	Work Completed	Wade	404	02/06/2023	20852	Drove out to Sat yard and changed oil.	2
28896	Work Completed	Ken	404	03/09/2023	21157	Valve bank leak in head-lots of leaks in head. Replaced boom hose.	3.5
29022	Work Completed	Wade Sanchuck	404	03/15/2023	21196	fixed oil leak in head, changed hose on head, changed engine oil, fixed collent leak	9
29043	Work Completed	Doug VanDerVlugt	404	04/10/2023	21397	flipped cab then bolted back down	1.5
29165	Work Completed	Wade Sanchuck	404	04/24/2023	21397	fix hood that was not closing, straighten hood	6
29166	Work Completed	Wade Sanchuck	404	04/25/2023		finished fixing hood and painting all the burn marks from welding	4
29172	Work Completed	Wade Sanchuck	404	04/27/2023	21397	checked A/C and lights on unit	1
29213	Work Completed	Wade Sanchuck	404	05/17/2023	21484	boosted the loader and fixed the exhaust pipe	1
29523	Work Completed	Doug VanDerVlugt	404	08/17/2023	21397	removed XA2 modules by battery box	1
29605	Work Completed	Herman Peters	404	05/31/2023	21397	wash log loader	12
29606	Work Completed	Herman Peters	404	06/01/2023	21397	wash log loader	12
29607	Work Completed	Herman Peters	404	06/02/2023	21397	wash log loader	12
29608	Work Completed	Herman Peters	404	06/05/2023	21397	wash log loader	6
29780	Work Completed	Dustin Hackworth	404	09/25/2023	21397	Removed Jacks	0
29782	Work Completed	Herman Peters	404	09/25/2023	21397	removed tracks	3
29806	Work Completed	Wade Sanchuck	404	10/10/2023	21397	weld truck side plates on	6
29809	Work Completed	Wade Sanchuck	404	10/11/2023	21397	weld slide plates on frame	9
29812	Work Completed	Dustin Hackworth	404	10/12/2023	21397	Help Wade with slide plates	3
29816	Work Completed	Wade Sanchuck	404	10/12/2023	21397	weld truck slides on frame	4
29888	Work Completed	Dustin	404	10/25/2023	21516	help with tracks	2
29891	Work Completed	Doug	404	10/25/2023	21516	install right idler, repair leak, clean	10
29912	Work Completed	Doug	404	10/27/2023	21516	installed track pin, tighten LH rail, removed final drive	7
29930	Work Completed	Doug	404	10/30/2023	21516	washed final drive, disassembled most of the planetary	12
29936	Work Completed	Doug	404	10/31/2023	21519	remove final drive motor, pressed planetary apart, replaced sprocket side dual core seal	9.5
29943	Work Completed	Doug	404	11/01/2023	21516	cleaned and assembled two halves of the planetary mount	7
29947	Work Completed	Wade	404	11/02/2023	21516	assist with final drive	1
29951	Work Completed	Doug	404	11/02/2023	21516	assembled planetary, installed motor on final drive, installed printer and tablet mount	11
29956	Work Completed	Dustin	404	11/02/2023	21516	final drive assemble,	7
29992	Work Completed	Doug	404	11/07/2023	21559	change turbo sensor	1
30106	Work Completed	Doug	404	11/24/2023		remove and rebuild new hose	1.5
30182	Work Completed	Wade	404	12/04/2023	21920	fold cab down	1
30184	Work Completed	Dustin	404	12/04/2023	21946	charge cab and hood pump/ manually pump cab down, bolt cab down	6.5
30192	Work Completed	Wade	404	12/05/2023	21930	replace fuse on head pump	2
30210	Work Completed	Wade	404	12/07/2023	21961	install hood pump, replace some fuses	3
30254	Work Completed	Wade	404	12/15/2023	22074	repair cab tilt switch	4.5
30274	Work Completed	Phillip	404	12/05/2023	21968	change grapple cylinder pin	4
30320	Work Completed	Wade	404	12/19/2023	22086	changed oil	1
30427	Work Completed	Wade	404	01/08/2024	22226	change hyd filter and boost to get running	2
30545	Work Completed	Wade	404	01/22/2024	22304	install head fittings	2
30560	Work Completed	Wade	404	01/23/2024	22304	replaced hose for head wiring	3
30586	Work Completed	Dustin	404	01/25/2024	22331	service - change oil and all filters	4.5
30592	Work Completed	Wade	404	01/25/2024	22331	repair wiring harness	3
30601	Work Completed	Wade	404	01/26/2024	22339	change a grapple hose	1

30625 Work Completed	Dustin	404 01/29/2024	22349 put door back on by radiator	3
30626 Work Completed	Wade	404 01/29/2024	22384 put stump pans on	3
30774 Work Completed	Dustin	404 02/09/2024	22561 replaced bottom bushing on boom, repair wiring for rotate on grapppler, greased fitting on bottom of boom.	7
30778 Work Completed	Wade	404 02/10/2024	22561 removed boom pin and changed boom bushings, repair grapple rotate	7
30812 Work Completed	Dustin	404 02/13/2024	22590 change oil and filters	2
30832 Work Completed	Dustin	404 02/14/2024	22590 replace hoses	4
30867 Work Completed	Wade	404 02/20/2024	22734 repaired oil leak on boom	1.5
30924 Work Completed	PJL Oilfield	404 02/24/2024	22734 unable to shut down	3
30990 Work Completed	Wade	404 03/05/2024	22948 replaced blower motor	5.5
30995 Work Completed	Dustin	404 03/05/2024	22952 oil service	1
31002 Work Completed	Dustin	404 03/06/2024	22952 replace two electrical harnesses,	9
31004 Work Completed	Wade	404 03/06/2024	22953 change wiring harness one for engine and one for engine to machine.	10
31010 Work Completed	Wade	404 03/07/2024	22953 put the ECU from 411 on 404 still not working	2
31011 Work Completed	Dustin	404 03/07/2024	22953 oil and fuel service	2
31019 Work Completed	PJL Oilfield	404 03/09/2024	22973 check all fluids and air filters	2
31166 Work Completed	Wade	404 04/23/2024	23105 install step on side	2
31167 Work Completed	Dustin	404 04/26/2024	23105 service hyd filters, engine oil and case filters	4
31183 Work Completed	Dustin	404 04/25/2024	23105 service left and right swing drives and final drive	4
31459 Work Completed	Wade	404 07/17/2024	23105 removed grapple tongues for line boring and removed cyl's	4
31466 Work Completed	Wade	404 07/18/2024	23105 weld cracks on head and removed foot boom	9
31468 Work Completed	Wade	404 08/14/2024	23105 removed bushings from boom, cleaned pin holes	4
31471 Work Completed	Dustin	404 07/19/2024	23105 clear all grease, prep for welding	6
31557 Work Completed	Wade	404 08/08/2024	23105 put new bushings in the boom, put boom back together	5
31591 Work Completed	Dustin	404 08/14/2024	23116 drain and refill final drives and engine oil	4
31592 Work Completed	Wade	404 08/15/2024	23116 install new wiring harness for head on boom and stick, install guards	7
31593 Work Completed	Dustin	404 08/15/2024	23116 change fuel filters, hyd filters, refill swing drives, change air filters,	9
31595 Work Completed	Wade	404 08/16/2024	23116 change hoses on stick	6
31613 Work Completed	Dustin	404 08/20/2024	23116 change hose on stick, blue lock tight on keeper bolts on stick,	12
31615 Work Completed	Wade	404 08/20/2024	23116 install new bushings on the grapple and welded the harness back on removed both cyl'd for tongs, turn them so the hoses are facing the tongs, grease head, change hose from	4
31617 Work Completed	Dustin	404 08/21/2024	23116 head to stick	10
31633 Work Completed	Dustin	404 08/23/2024	23116 grease entire machine, install top latch on escape door in cab,	2
31638 Work Completed	Doug	404 08/23/2024	23105 inspect pressures, replaced cab side boom foot bushing, check over unit	9.5
31640 Work Completed	Wade	404 08/23/2024	23116 assisted Doug with changing bushings on boom	3
31644 Work Completed	Doug	404 08/26/2024	23121 welded 5 cracks, replaced o-rings on accumulator, replaced 5 missing bolts for hose clamps	7
31665 Work Completed	Doug	404 08/29/2024	23121 replace grease fitting and finish greasing	1
31685 Work Completed	Doug	404 09/05/2024	23125 tighten tracks	0.5
31690 Work Completed	Doug	404 09/06/2024	23130 topped up A/C, replaced grease line, adjusted side door latch	1.5
31742 Work Completed	Doug	404 09/18/2024	23148 replaced missing steel line clamp on stick	1.5
31825 Work Completed	Phillip	404 10/10/2024	23186 change arm rests	1
32064 Work Completed	Doug	404 11/12/2024	23162 changed #16 hose between stick and grapple	1
32199 Work Completed	Dustin	404 11/28/2024	23190 tighten down 3 cab bolts	1
32217 Work Completed	Wade	404 12/01/2024	23228 repair oil leak	5.5
32290 Work Completed	Dustin	404 12/10/2024	23386 repair o-ring on top of boom	3
32321 Work Completed	Dustin	404 12/13/2024	23458 install grapple cyl'd	3
32333 Work Completed	Dustin	404 12/14/2024	23462 change out hyd hose and add oil,	6
32391 Work Completed	Dustin	404 12/20/2024	23595 change hose on grapple cyl'd	2
32413 Work Completed	Dustin	404 12/29/2024	23665 build and install two hoses	3
32432 Work Completed	Dustin	404 01/02/2025	23688 replace grapple cyl'd hose	3

32453 Work Completed	PJL	404 01/05/2025	23772 change oil and filter, fuel filter and tighten hyd filter	3
32479 Work Completed	Doug	404 01/07/2025	23744 replaced hose from sitck to head #16, splice printer wires	2
32571 Work Completed	Doug	404 01/17/2025	23908 replaced grapple hose	2.5
32643 Work Completed	Doug	404 01/30/2025	24124 replaced o-ring on stick, removed door latch and installed new one	4
32663 Work Completed	Doug	404 02/03/2025	24127 split track, removed sprocket and final drive	7
32690 Work Completed	Doug	404 02/13/2025	24149 prep final drive motor, installed final drive, add hyd oil, install sprockets, started on tracks	16
32692 Work Completed	Doug	404 02/14/2025	24149 assembled track and tighten	3
32710 Work Completed	PJL	404 01/16/2025	23908 weld ear on, instal pin and cyld	2
32719 Work Completed	PJL	404 01/19/2025	23995 oil chang and filters - oil and fuel	3
32761 Work Completed	PJL	404 01/31/2025	24189 top up hyd oil, bad track motor	5
32894 Work Completed	Doug	404 02/24/2025	24246 service	2
32959 Work Completed	Phillip	404 03/06/2025	24343 repair oil leak on valve bank, and hyd line clamp on top of boom,	8
32964 Work Completed	Phillip	404 03/07/2025	24353 change air intake sensor	4
33005 Work Completed	PJL	404 03/12/2025	24410 remove broken bolts and install new ones on the sprocket, reinstal track	6
33007 Work Completed	Phillip	404 03/12/2025	24410 remove broken sprocket bolts and install new ones	7
33160 Work Completed	Phillip	404 05/13/2025	24496 motor oil change, and all filters, change hyd filters, hyd tank breather and oil on final and swing drives.	10
33162 Work Completed	Phillip	404 05/14/2025	24496 recharge A/C and install new pump bolts change boom cyld hoses, grapple tilt cyld hose and hard servicing grapple teeth, repair line and hoses	5
33174 Work Completed	Phillip	404 05/22/2025	24496 between stick and grapple	10
33177 Work Completed	Phillip	404 05/23/2025	24496 hard servicing grapple teeth	5
33188 Work Completed	Phillip	404 05/27/2025	24497 changed bushing on right side boom cylinder, installed guards	6
33328 Work Completed	Doug	404 07/08/2025	24559 A/C issues, checked compressor repair main wire goint to grapple, reseal relief valves for grapple rotate, change hose between stick and	1.5
33373 Work Completed	Phillip	404 07/17/2025	24645 grapple	6
33384 Work Completed	Phillip	404 07/18/2025	24645 remove rotate grapple motor	3
33764 Work Completed	Wade	404 10/03/2025	24721 inspect fuel leak, replaced return hose	3.5
33790 Work Completed	Doug	404 10/10/2025	24698 repair joy stick	1
33844 Work Completed	Doug	404 10/16/2025	24691 tighte up loose fitting	1
34345 Work Completed	Doug	404 12/17/2025	24712 serviced,	3.5
34352 Work Completed	Doug	404 12/18/2025	24712 changed out batteries	1.5
34358 Work Completed	Phillip	404 12/19/2025	24771 repair electrical on grapple	8
34386 Work Completed	Doug	404 12/29/2025	24801 inspected door latch, needs to be replaced	3
34578 Work Completed	PJL	404 01/25/2026	24963 oil change and filters, oil, fuel and air	3
34645 Work Completed	Phillip	404 01/29/2026	25078 repair electrical issue on grapple, straighten out hyd hoses on grapple	6
34793 Work Completed	Doug	404 02/25/2026	25196 service 500hrs, changed pilot and case filter, replaced door sensor	3
34933 Work Completed	PJL	404 03/04/2026	25280 change #2 grapple hose	4
35005 Work Completed	Doug	404 03/20/2026	25333 replaced brushes on alternator, boosted, replaced alterntor	9
35020 Work Completed	Doug	404 03/24/2026	25371 tighten loose joystick screws, replaced tool cyld grease nipple	1.5
35027 Work Completed	Rylan	404 03/25/2026	25392 change hose on boom	4
35030 Work Completed	Rylan	404 03/26/2026	25417 oil change and filter	4
35032 Work Completed	Doug	404 03/26/2026	25410 changd fuel pressure sensor	2.5
35250 Work Completed	Doug	404 06/16/2026	removed wide side of grapple	2.5
35474 Work Completed	Kyle	404 08/19/2026	25163 repaired hyd leak on grapple,	4
35476 Work Completed	Kyle	404 08/20/2026	25108 service and repair, replace two lights, repair oil leak on grapple, replace A/C compressor, charge A/C	8
35491 Work Completed	Doug	404 08/25/2026	25506 changed #8 grapple hose, boxx o-ring on grapple cyld, removed cylinder	5.5
35536 Work Completed	Josh	404 09/08/2026	25507 replaced high side ac line and charge system	4