

Date: February 5/2024

Pilgrim Bros. Ventures Ltd.
 TC Reg: 25-0992; Exp: 2023-11-01
 19267 PDR 9A Road
 Wonowon, B.C. V0C 2N0
 250-772-3082

Client: AquaFlow Trucking Ltd
 Address: PO Box 138
 City: Wonowon, BC
 Postal Code: V0C2N0
 Phone: 250-772-3082

☐ Lined ☐ Insulated ☐ Both lined and insulated
☐ Loaded by vacuum ☐ Corrosive service ☐ Dedicated service: _____

Tank serial number:
 Tank Spec: DOT 407
 Lining Material: SHERGLASS FF
 Date of MFR: 01/13
 CTMV orig. Test date:
 Manufacturer: HEIL
 TCRN: N/A
 MAWP: 30 psi
 Man. Thickness Head: 0.375 in
 Man. Thickness Shell: 0.250 in
 Exposed surface area: 1126 SQ FT

Unit Number: 531A
 VIN: 5HTDL4931D5L26116
 Orig. test date: 01/13
 Comp/Cert date: 01/13
 CTMV Cert Date:
 Assembler:
 MDIN: N/A
 Design Pressure: 45 psi
 Min. Thickness Head: 0.328 in
 Min. Thickness Shell: 0.232 in
 Volumetric Capacity: 12200 G

Corroded or abraded areas are thickness tested 7.2.4	Pass ☐	Fail ☐	Rep. ☐	NA X
Cracks or defects in welds	Pass X	Fail ☐	Rep. ☐	NA ☐
Dents, distortions or any other condition that might render the tank unsafe for use	Pass X	Fail ☐	Rep. ☐	NA ☐

The upper coupler must be removed even if it is welded to the tank if it obstructs the inspector from conducting a proper inspection. When re-fitted to the tank, the upper coupler should be inspected for distortion/deflection, clearance, kingpin wear and to ensure all required fasteners are in place and tight.

Defect and location

Constructed of: ☐ Quenched and Tempered steel (QT) ☐ Non-quenched (NQT)
☐ Stress relieved after Mfr.
☐ Stress relieved after repair: ☐ Local stress relief
☐ Complete stress relief

Tank Disposition

X Pass
☐ Fail/removed from service

☐ Repaired/Re-tested/Returned to service
☐ Removed from facility

Inspector name: Andreas Schneider
 Inspector Signature: _____
 Date signed: Feb 05/2024
 Inspection expires: Feb 28/2029 "UC"

Tester name: _____
 Tester Signature: _____
 Date signed: _____
 Markings applied: 02/24 UC 992

Services Provided by:
eStandard Solutions