

TRIM(WOHH.WOWH_MODEL)	WOWH_DESC	WOWH_ORDER_N	WOWH_INVOICE_DATE	WOWH_METER	Comments	Full Rep Code
P19-W-018	ISUZU FRR600 LONG EWP	235645	26/08/2024 0:00	364808	PREPARED FOR AUCTION, Completed by: david.jones@porterplant.com.au on: Aug 26, 2024	GR - GENERAL REPAIRS
P19-W-018	ISUZU FRR600 LONG EWP	216457	21/04/2023 0:00	364808	DAMAGE TO BUMPER, BONNET, L/H TOOL BOX, R/H/F DOOR, L/H STEP, REAR, TOOL BOX, DRIVERS SEAT, , REMOVE AND REFIT-, FRONT BUMPER, BONNET, L/H TOOL BOX FITTINGS, L/H STEP, R/H/F DOOR, REAR TOOL BOX, , REPAIR-, FRONT BUMPER, BONNET, L/H TOOL BOX, R/H/F DOOR, REAR TOOL BOX, , PAINT, FRONT BUMPER, BONNET, L/H TOOL BOX, R/H/F DOOR, REAR TOOL BOX, AS PER SMASH REPAIRER QUOTE# 3583	CD - CUSTOMER DAMAGE
P19-W-018	ISUZU FRR600 LONG EWP	214990	14/03/2023 0:00	364808	CARRIED OUT RETURN FROM HIRE INSPECTION, REPORT & PHOTOS SUPPLIED, PO 182027 - EPV	PI - PLANT INSPECTION
P19-W-018	ISUZU FRR600 LONG EWP	210269	16/11/2022 0:00	361846	AFTER HOURS TOWING CHARGES - SALVAGE VEHICLE, AFTER HOURS CALL OUT TO ATTEND TOOLANGI TENNIS, RESERVE, SALVAGE VEHICLE TO HIGHER GROUND., PO 177327 - EAGLE TOWING & SALVAGE	CD - CUSTOMER DAMAGE
P19-W-018	ISUZU FRR600 LONG EWP	209665	26/10/2022 0:00	361846	CARRIED OUT 3MTH TOWER SERVICE, PO 176651 - EPV	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	207705	19/10/2022 0:00	361840	CARRIED OUT MAJOR SERVICE & REPAIRS, REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS, BRAKE & CLUTCH ADJUSTMENT, REMOVE MAF SENSOR, & DEGREASE, CHECK & ADJUST VALVE CLEARANCES, DPD HOSE & PCV ELEMENT CHANGED OUT, AMT SERVICE &, FLUIDS CHANGED, HEADLIGHTS ADJUSTED, REPLACED WIPER BLADES, REPLACED DIFF & GEAR OIL., D/S SEAT BELT NOT RETRACTING, FOUND TO BE WORN, REMOVED & REPLACED SEAT BELT ASSY, TORQUE TO SPEC, TEST, OK., RH LOWER MIRROR GLASS CRACKED, REMOVED & REPLACED DAMAGED GLASS, CLEANED & ADJUSTED, OK., LH UPPER MIRROR GLASS CRACKED, REMOVED & REPLACED DAMAGED GLASS, CLEANED & ADJUSTED, OK., LHR LAMP ASSEMBLY BASE & LENS CRACKED & FATIGUED, REMOVED DAMAGED LAMP ASSY, CHECK WIRING, ALL OK., S & F NEW LAMP ASSY TO REAR, TEST, OK., PO 174637 - EMA	PS - PLANNED SERVICE
P19-W-018	ISUZU FRR600 LONG EWP	207200	22/08/2022 0:00	352960	REPAIRED REAR SPRINGS, 28/7/22 - RH SPRING HAD COMPLETELY SNAPPED & LH SPRING HAS SNAPPED THE CENTRE BOLT WHICH LIKELY FAILED DUE TO, OVERCOMPENSATING FOR THE DAMAGE ON THE RH SPRING PACK, REPLACE BOTH REAR SPRINGS & THE RH SPRING IS TO BE, BUFFED UP TO COMPENSATE/COUNTERBALANCE FOR WEIGHT TO RHS., REMOVE DAMAGED REAR SPRINGS, CHECKED BUSHES & SUSPENSION COMPONENTS, INSPECTION SATISFACTORY., CLEAN LOCATION, INSTALL NEW REAR SPRING ASSEMBLIES INTO PLACE, USING CORRECT VEHICLE MANUFACTURE STANDARDS, & SPEC SETTINGS, ALL OK. INSTALLED WHEELS BACK ON VEHICLE, TORQUE ALL NUTS TO CORRECT SPEC, ALL OK., CARRY OUT INSPECTION, LOWERED VEHICLE, TEST DROVE, ALL OK., PO 173274 - EMA	MR - MECHANICAL REPAIR
P19-W-018	ISUZU FRR600 LONG EWP	206139	09/08/2022 0:00	352960	CARRIED OUT MINOR SERVICE, 28/7/22 - REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS, GREASED, TOPPED UP COOLANT, REPLACED WIPER BLADES., BRAKE TEST - RH 7MM, LH 7MM, RHR 6MM, LHR 6MM. ROAD TEST., PO # 173257 - EMA	PS - PLANNED SERVICE
P19-W-018	ISUZU FRR600 LONG EWP	206358	04/08/2022 0:00	351664	CARRIED OUT 12MTH TOWER SERVICE INCL A/I & W/TEST, REPLACED HYDRAULIC OIL & HYDRAULIC FILTERS, PO 173493 - EPV	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	205687	02/08/2022 0:00	343898	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, HV WET TESTS, PO 172702 - SETCO	ET - ELECTRICAL TEST
P19-W-018	ISUZU FRR600 LONG EWP	205692	22/07/2022 0:00	351664	REPLACED 4 DRIVE TYRES - POS 3/4/5/6, REAR INNER BACK TYRES ARE BALD, 4 X 235/75R17.5 GOODRIDE MD738 16PR 143/141J, PO 172711 - BEAUREPAIRS BAYSWATER	TC - TYRE CHANGE/REPLACMENT
P19-W-018	ISUZU FRR600 LONG EWP	204536	21/06/2022 0:00	343898	REPAIR DAMAGED ITEMS FOUND DURING TRUCK SERVICE, 28/5/22 - REMOVED & REPLACED UNSERVICEABLE LH QUARTER PANEL WITH NEW., REMOVED & REPLACED UNSERVICEABLE LH HEADLAMP ASSY WITH NEW, SET/AIM ADJUSTMENTS, CHECK OPERATION, ALL OK., REMOVED & REPLACED UNSERVICEABLE LH INDICATOR WITH NEW., REPLACED MISSING REAR MUD FLAPS WITH NEW., PO 171734 - EMA	CD - CUSTOMER DAMAGE
P19-W-018	ISUZU FRR600 LONG EWP	203432	31/05/2022 0:00	343898	CARRIED OUT MINOR TRUCK SERVICE, 24/5/22 - REPLACED OIL FILTER, FUEL FILTERS & PCV FILTER, GREASED, REPLACED WIPER BLADES., PO 170586 - EMA	PS - PLANNED SERVICE
P19-W-018	ISUZU FRR600 LONG EWP	202411	28/04/2022 0:00	340563	CARRIED OUT 9MTH TOWER SERVICE & REPAIRS, REPLACED 1 X UNSERVICEABLE BOOM REST RUBBER., REPAIRED GELCOAT ON LOWER BOOM REST AREA., WAIT TIME FOR TRUCK TO ARRIVE FOR BOOKED SERVICE., PO 169410 - EPV	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	202296	27/04/2022 0:00	340545	REPLACED STEER TYRES AND STEER ALIGNMENT, CHECKED PRESSURE, BALANCE TRUCK, STEER ALIGNMENT & ADJUSTED STEERING., 2 X 235/75R17.5 GOODRIDE CR960A 16PLY, PO 169321 - BEAUREPAIRS BAYSWATER	TC - TYRE CHANGE/REPLACMENT

P19-W-018	ISUZU FRR600 LONG EWP	202180	21/04/2022 0:00	340352	REPLACED BLOWN HEADLIGHT GLOBE, LH HEADLIGHT NOT WORKING, TESTED, FOUND BLOWN GLOBE IN UNIT,, REMOVED & REPLACED WITH NEW GLOBE, TESTED, ALL OK., CARRY OUT HEADLIGHT AIM AS PER MANUFACTURER SPECS, ALL OK., PO 169173 - EMA	ER - ELECTRICAL REPAIR
P19-W-018	ISUZU FRR600 LONG EWP	201081	21/04/2022 0:00	333013	CARRIED OUT BRAKE INSPECTIONS & ADJUSTMENT, 1/3/22 - DRIVER REPORTED BRAKES PULLING UP SLOW & ENGINE LIGHT ON., BRAKE CHECK, JACKED UP VEHICLE, CARRY OUT BRAKE THICKNESS TEST,, WITHIN LIMITS, CARRY OUT REQD ADJUSTMENTS., RHf 8MM, LHf 7.5MM, RHR 8MM, LHR 8MM., ENGINE LIGHT ON, CARRY OUT DIAGNOSTIC SCAN - P0907, P0401, P0700,, CLEARED CODES, ROAD TESTED, CONNECT SCAN TOOL TO INSPECT ANY, ADDITIONAL CODES, NIL CODES, ALL OK., PO 168011 - EMA	MR - MECHANICAL REPAIR
P19-W-018	ISUZU FRR600 LONG EWP	200970	21/04/2022 0:00	336155	CARRIED OUT MINOR TRUCK SERVICE, REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS & PCV FILTER, REPLACED WIPER BLADES,, TOPPED UP COOLANT, GREASED. CARRIED OUT BRAKE TEST POST SERVICE/BRAKE ADJUSTMENTS,, VEHICLE TAKEN TO ROLLING BRAKE CHECK - REPORT GOOD, NIL DEFECTS., PO 167900 - EMA	PS - PLANNED SERVICE
P19-W-018	ISUZU FRR600 LONG EWP	202006	19/04/2022 0:00	338562	REPAIRED BOOM PROXY SWITCH, TOWER NOT WORKING, CHECKED & FOUND LEGS WON'T OPERATE, CHECKED ALL, WIRING & FOLLOWED CIRCUITS, EVENTUALLY FOUND AN INTERMITTENT FAULT, WITH BOOM PROXY SWITCH, REFITTED PROXY CORRECTLY & CHECKED OPERATION, A FEW TIMES FROM SCRATCH, ALL OK., PO 169027 - EPV	BE - BREAKDOWN - ELECTRICAL
P19-W-018	ISUZU FRR600 LONG EWP	202005	19/04/2022 0:00	338562	REPLACED BROKEN BOLTS ON FOOTPLATE & REPAIR PLATES, LHF FOOTPLATE RETAINING BOLTS BROKEN & RETAINING PLATES BENT,, REMOVED BROKEN BOLTS, 2 CAME OUT OK, 3RD BOLT TOOK MUCH, LONGER. REPLACED ALL BOLTS, STRAIGHTENED PLATES & REFITTED, FOOTPLATE., PO 169027 - EPV	CD - CUSTOMER DAMAGE
P19-W-018	ISUZU FRR600 LONG EWP	199628	21/02/2022 0:00	328157	CARRIED OUT 6MTH TOWER SERVICE INCL WEIGHT TEST, REPLACED HYDRAULIC FILTER, FIBREGLASS COVER & GREEN NON-FLUSH SUIT BUTTON, PO 166472 - EPV	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	198774	18/02/2022 0:00	325772	REPLACED 2 DRIVE TYRES, 21/1/22 - COLLECT VEHICLE, REMOVE REAR DRIVE TYRES, REPLACED WITH 2 X NEW, CARRIED OUT TYRE ROTATION, TORQUED WHEEL NUTS TO SPEC,, RETURN VEHICLE TO YARD., PO 165357 - EMA	TC - TYRE CHANGE/REPLACEMENT
P19-W-018	ISUZU FRR600 LONG EWP	198593	14/02/2022 0:00	325315	CARRIED OUT MAJOR TRUCK SERVICE, 18/01/2022 - REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS, REMOVED & REPLACED AIR FILTER,, REPLACED WIPER BLADES & TOP UP COOLANT, GREASE, BRAKE & CLUTCH ADJUSTMENT, ROAD TEST., PO 165357 - EMA	PS - PLANNED SERVICE
P19-W-018	ISUZU FRR600 LONG EWP	196476	03/02/2022 0:00	315750	REPAIRED BRAKES, 10/11/21 - BRAKES LOCKED ON, ISOLATE & RELEASE HAND BRAKE, SPIN WHEELS, LH FWD HEAVY, INPSECT, CHECK & ADJUST BRAKES,, ROAD TEST - VEHICLE PULLS TO LEFT & DRIVES LEFT WHILE BRAKING, ALSO BRAKES ARE VERY SENSITIVE., CARRY OUT BRAKE SYSTEM AIR VALVE INSPECTION, FOUND VARIOUS FATIGUED AIR VALVES, ORDER NEW PARTS. FIND FATIGUED AIR, LINES, CUT OUT BAD SECTION, FIT AIRLINE JOINERS, REPLACED VARIOUS AIR VALVES WITH NEW, CARRY OUT FOOT BRAKE VALVE, INSPECTION, INOPERATIVE, CONTRIBUTING TO BRAKES LOCKING UP, REPLACE FOOT VALVE, CARRY OUT BRAKE BLEED, CARRY OUT, BRAKE PRESSURE TEST AT EACH WHEEL & MANUAL SUPPLY, BRAKE MASTER ALL FOUND TO BE SATISFACTORY., BRAKE LININGS FOUND TO BE AT FAULT, REMOVED FRONT BRAKES ASSY AS PER ISUZU MANUAL, REINSTALLED NEW GENUINE ISUZU, BRAKE LININGS, REINSTALLED BRAKE ASSY WITH NEW LININGS, VEHICLE NOW FOUND SATISFACTORY., TAKE VEHICLE TO ISUZU FOR ROLLING BRAKE PRESSURE TEST, NOW SATISFACTORY., PO 163124 - EMA	MR - MECHANICAL REPAIR
P19-W-018	ISUZU FRR600 LONG EWP	198821	03/02/2022 0:00	318163	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, HV WET TESTS, PO 165626 - SETCO	ET - ELECTRICAL TEST
P19-W-018	ISUZU FRR600 LONG EWP	196477	03/02/2022 0:00	315750	REPLACED 4 TYRES, 4 X 235/75R17.5 - STRIP & FIT, TORQUE WHEEL NUTS & FIT WNI., PO 163124 - EMA	TC - TYRE CHANGE/REPLACEMENT
P19-W-018	ISUZU FRR600 LONG EWP	197962	21/12/2021 0:00	318163	REPLACED BOOM REST RUBBER, BOOM REST RUBBER UNSERVICEABLE, REPLACED BOOM REST RUBBER,, DRILLED OUT BROKEN BOLT, REPLACED BOLT., PO 164726 - EPV	GR - GENERAL REPAIRS
P19-W-018	ISUZU FRR600 LONG EWP	197470	13/12/2021 0:00	312921	CARRIED OUT MINOR TRUCK SERVICE & REPAIRS, 10/9/21 - REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS & AIR FILTER, REPLACED WIPER BLADES,, BRAKE & CLUTCH ADJUSTMENT, CHECK FLUID LEVELS & GREASE, REMOVE MAF SENSOR, CLEAN & INSPECT., ATTEMPTED TO TIGHTEN FRONT SWAY BAR TO AXLE BUSH, WILL NOT CLAMP ANY FURTHER., FRONT LEAF SPRING HANGERS LOOSE, TIGHTEN BOTH SIDES., 2 X DRAWER SLIDERS LOOSE, REMOVED DRAWERS, INSERT NEW RIVETS., ADJUSTED HANDBRAKE & CARRIED OUT PARK BRAKE TEST., PO 160603 - EMA	PS - PLANNED SERVICE
P19-W-018	ISUZU FRR600 LONG EWP	194926	01/12/2021 0:00	307909	REPAIRED HEAD UNIT, 23/9/21 - PICK UP VEHICLE FROM LILYDALE YARD, REMOVED DASH TRIMS FOR ACCESS, REMOVED RADIO, SENT AWAY FOR, REQD TOUCH SCREEN REPAIRS. REINSTALLED HEAD UNIT & ALL REMOVED DASH TRIMS, CARRIED OUT TESTING, ALL OK., PO 161410 - EMA	ER - ELECTRICAL REPAIR

P19-W-018	ISUZU FRR600 LONG EWP	196585	22/11/2021 0:00	312921	CARRIED OUT BRAKE INSPECTION, BRAKE THICKNESS CHECK - FRONT RH 3.0MM, FRONT LH 3.0MM, REAR RH 5.0MM, REAR LH 4.0MM., NOTIFY MANAGER VEHICLE IS UNFIT TO CONTINUE TO OPERATE., PO 160603 - EMA	MR - MECHANICAL REPAIR
P19-W-018	ISUZU FRR600 LONG EWP	195150	12/11/2021 0:00	309596	CLEARED FAULT CODES, CALL OUT AFTER HOURS, ENGINE LIGHT & TRANSMISSION LIGHT ON DASH, CARRY OUT DIAGNOSTIC SCAN., OPERATOR FAULT, DRIVER RESTING HAND ON GEAR SHIFTER WHEN OPERATING CAUSING THE TRANSMISSION TO LOCK OUT., CLEARED CODE, CARRY OUT TEST DRIVE, RESCANNED VEHICLE, NIL CODES., PO 161700 - EMA	GR - GENERAL REPAIRS
P19-W-018	ISUZU FRR600 LONG EWP	194236	12/11/2021 0:00	312921	CARRIED OUT MINOR TRUCK SERVICE, REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS & AIR FILTER, REPLACED WIPER BLADES, BRAKE & CLUTCH, ADJUSTMENT, PARK BRAKE TEST, GREASED, REMOVED MAF SENSOR, CLEANED & INSPECTED., PO 160603 - EMA	PS - PLANNED SERVICE
P19-W-018	ISUZU FRR600 LONG EWP	195945	12/11/2021 0:00	312921	REPLACED CENTRE BEARING & FRONT & REAR BRAKES, TAIL SHAFT BEARING FOUND UNSERVICEABLE, REMOVE BEARING, CLEAN, FIT REPLACEMENT BEARING, GREASE AS REQD., FIT DRIVESHAFT, TORQUE TO SPEC., ALL BRAKES FOUND TO BE OUT OF LIMITS, REMOVE WHEELS, HUBS & DRUMS, DISASSEMBLE BRAKE COMPONENTS, CLEAN HUBS, & BEARINGS, INSPECT BEARINGS & REPACK WITH GREASE, SEND BRAKE SHOES & DRUMS FOR MACHINING, DRUMS REPORTED, OUT OF LIMITS, REPLACE DRUMS WITH NEW, RELINE NEW SHOES WITH LININGS, RADIUS GRIND DRUMS TO SHOES, FIT NEW, STUDS TO DRUMS, TORQUE TO SPEC, REASSEMBLE BRAKES, REPLACE HUB SEALS, REPACK HUBS WITH GREASE, FIT HUBS, & DRUMS, SET CORRECT PRELOAD TO HUBS AS PER SPECS, SET BRAKES TO REQUIRED GAP DISTANCES, REINSTALLED WHEELS, & TORQUED WHEEL NUTS TO SPEC, FIT WNI, TEST DRIVE, CARRY OUT FURTHER ADJUSTMENT, ALL OK., PO 160603 - EMA	MR - MECHANICAL REPAIR
P19-W-018	ISUZU FRR600 LONG EWP	195768	26/10/2021 0:00	310204	CARRIED OUT 3MTH TOWER SERVICE, LH BASKET TILT COVER MISSING - REPLACED. RH TELE CYLINDER PIN COVER MISSING - REPLACED., PO 162351 - EPV	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	195582	22/10/2021 0:00	304490	SUPPLIED 2 REMOTE BATTERIES, PO 162154 - EPV	ER - ELECTRICAL REPAIR
P19-W-018	ISUZU FRR600 LONG EWP	194073	06/10/2021 0:00	304490	CARRIED OUT DIAGNOSTIC SCANS, 3/9/21 - ENGINE LIGHT ON - CARRY OUT DIAGNOSTIC SCAN, CODES PRESENT: P0613 ECU EEPROM ERROR, P0401 EGR FLOW, INSUFFICIENT, P0700 TRANS CONTROL MALFUNCTION. CHECK OVER TRANSMISSION WIRING HARNESS & CONNECTORS, INSPECTED ALL, PLUGS, WASHED & CLEANED ALL TERMINALS & CONNECTIONS. RESCAN - CODES ALL GOOD. CARRIED OUT TEST DRIVE & DATA, DOWNLOAD OF OPERATIONAL FUNCTIONS, NIL DEFECTS, ALL FOUND SATISFACTORY., PO 160442 - EMA	BM - BREAKDOWN - MECHANICAL
P19-W-018	ISUZU FRR600 LONG EWP	192549	10/09/2021 0:00	295693	REPLACED 2 TYRES DUE TO UNREPAIRABLE PUNCTURES, PUNCTURED 2 REAR TYRES AFTER DRIVING OVER SOMETHING ON THE ROAD, CALL OUT AFTER HOURS, INSPECTED REAR DRIVE TYRES., FOUND 2 PUNCTURES, REMOVED 2 X DRIVE TYRES & FIT 2 NEW TYRES- 235/75R17.5, BALANCE, TORQUE WHEEL NUTS, FIT & ALIGN WNI,, ROAD TEST, OK., PO 158594 - EMA	TD - REPLACMENT OF DAMAGED TYRE
P19-W-018	ISUZU FRR600 LONG EWP	193651	10/09/2021 0:00	303343	REPLACED 2 DAMAGED TYRES - 235/75R17.5, MOVE VEHICLE TO EMA WORKSHOP, 2 X DRIVE TYRES HAVE DAMAGED SIDE WALLS, REMOVE & REPLACE WITH NEW, BALANCED., TORQUE WHEEL NUTS, FIT & ALIGN WNI, ROAD TEST, RETURNED TO DOWNER DEPOT., PO 159895 - EMA	TD - REPLACMENT OF DAMAGED TYRE
P19-W-018	ISUZU FRR600 LONG EWP	192314	23/07/2021 0:00	295689	CARRIED OUT 12MTH TOWER SERVICE INCL A/I & W/TEST, HAD TO WAIT 1.25HRS FOR TRUCK AS IT WAS ON STAND DOWN. RH BASKET PIVOT PIN COVER BROKEN OFF., REFITTED WITH NYLON BOLT. REPLACED HYDRAULIC FILTERS & HYD OIL., PO 158295 - EPV	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	191911	23/07/2021 0:00	284288	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, HV WET TESTS., PO 157888 - SETCO	ET - ELECTRICAL TEST
P19-W-018	ISUZU FRR600 LONG EWP	190136	28/05/2021 0:00	284288	CARRIED OUT 9MTH TOWER SERVICE & REPAIRS, RH STABILISER FOOTPLATE RETAINING PLATE BOLT BROKEN, REMOVED FOOTPLATE, REMOVED BROKEN BOLT, REFITTED, FOOTPLATE & REPLACED BOLT., PO 156037 - EPV	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	186378	23/02/2021 0:00	273483	CARRIED OUT 6MTH TOWER SERVICE INCL WEIGHT TEST & REPAIRS, TOWER STOPS WORKING INTERMITTENTLY, HAD TOWER GOING FOR 3 HOURS BEFORE IT STARTED TO FAULT, IT STARTED DOING IT, INTERMITTENTLY WHICH MADE IT DIFFICULT TO DIAGNOSE, AFTER ABOUT 3 HRS WAS ABLE TO DETERMINE FAULT WAS IN RADIO REMOTE, SYSTEM, REMOVED & SENT AWAY FOR REPAIRS, ON RETURN REFITTED REMOTE SYSTEM & OPERATED THROUGH ALL FUNCTIONS & TESTED., PO 151998 - EPV	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	185502	04/02/2021 0:00	269569	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, BUCKET LINER TEST & TRAVEL, PO 151004 - SETCO	ET - ELECTRICAL TEST

P19-W-018	ISUZU FRR600 LONG EWP	184598	14/01/2021 0:00	269569	CHECKED FAULT ON TOWER REMOTE, REMOTE CUTTING OUT, DRIVER REPORTS REMOTE CONTROL NOT WORKING, SET UP TOWER & CHECKED, OK, DID THIS 3 TIMES FROM SCRATCH, & RAN TRUCK FOR 1/2 HOUR, STILL OK, TURNED UNIT OFF WITH TOWER IN THE AIR, LEFT FOR 1/2 HOUR, RESTARTED TRUCK & OPERATED, AGAIN FOR 1/2 HOUR, ALL OK, GOT DRIVER TO SET UP TOWER & I WATCHED WHILST HE OPERATED IT, CANNOT FAULT UNIT AT THIS TIME,, DRIVER TO MONITOR., PO 150090 - EPV	ER - ELECTRICAL REPAIR
P19-W-018	ISUZU FRR600 LONG EWP	182576	14/12/2020 0:00	268562	REPAIRED CRACKED TURRET, PREPARE CRACKED AREA, WELD UP AS REQD, PAINT REPAIRED AREA, CARRY OUT DYNAMIC TEST - OK, S & F UNINSULATED LABEL., PO 147942 - EPV	MR - MECHANICAL REPAIR
P19-W-018	ISUZU FRR600 LONG EWP	182201	29/10/2020 0:00	268492	CARRIED OUT 3MTH TOWER SERVICE, PO 147557 - EPV	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	182194	29/10/2020 0:00	261312	REPAIRED HYDRAULIC PUMP LEAK, HYDRAULIC PUMP LEAKING, USED OMFB GEAR PUMP KIT UNI 27L S ROT, PO 147557 - EPV	HR - HYDRAULIC REPAIR
P19-W-018	ISUZU FRR600 LONG EWP	179961	07/09/2020 0:00	256947	REPLACED TIMER RELAY, TOWER STOPPED WORKING, OVERRIDE WAS USED TO PACK UNIT UP,, CHECKED UNIT & AFTER SOME TIME FOUND TIMER RELAY, UNSERVICEABLE, SOURCED NEW RELAY, FITTED & TESTED, ALL OK., PO 145373 - EPV	ER - ELECTRICAL REPAIR
P19-W-018	ISUZU FRR600 LONG EWP	178144	17/08/2020 0:00	254294	WELDING REPAIRS TO CRACKED TURRET, CRACK INSIDE TURRET, CHECK & REPAIR CRACKS INSIDE TURRET, NEAR LIFT CYLINDER PIVOT, PREPARE CRACKED AREAS, CARRY OUT, WELD REPAIRS TO FRONT FACE, LHS & RHS TURRET AS REQD., PO 143665 - EPV	GR - GENERAL REPAIRS
P19-W-018	ISUZU FRR600 LONG EWP	178153	17/08/2020 0:00	254252	CARRIED OUT 12MTH TOWER SERVICE INCL A/I & W/TEST, HYDRAULIC OIL TEST KIT, REPLACE HYDRAULIC FILTERS, PO 143665 - EPV	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	177730	30/07/2020 0:00	238779	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, HV WET TESTS, TRAVEL, PO 143351 - SETCO	ET - ELECTRICAL TEST
P19-W-018	ISUZU FRR600 LONG EWP	174362	19/05/2020 0:00	238779	REPLACED BROKEN BOLT OF RH BASKET, RH BASKET PIN BROKEN, RH BASKET IN COVER BROKEN OFF & BOLT, BROKEN IN PIN, DRILLED OUT BROKEN BOLT & REFITTED COVER., PO 140592 - EPV	MR - MECHANICAL REPAIR
P19-W-018	ISUZU FRR600 LONG EWP	173779	01/05/2020 0:00	238779	CARRIED OUT 9MTH TOWER SERVICE & REPAIRS, LEFT REAR FOOT PLATE - RETAINING PLATE BOLTS BROKEN & PLATE, BENT, REMOVED BROKEN BOLTS, STRAIGHTEN FOOT PLATES, REFITTED, FOOT PLATES WITH NEW BOLTS., PO 140091 - EPV	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	168524	06/02/2020 0:00	213609	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, HV WET TESTS & TRAVEL, PO 135100 - SETCO	ET - ELECTRICAL TEST
P19-W-018	ISUZU FRR600 LONG EWP	168808	23/01/2020 0:00	224834	CARRIED OUT 6MTH TOWER SERVICE INCL WEIGHT TEST, REPLACED HYDRAULIC FILTER, PO 135445 - EPV	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	167259	10/12/2019 0:00	213609	INVESTIGATED PROBLEM WITH TOWER, TOWER STOPPED WORKING ON JOB, DRIVER WAS ABLE TO GET IT, STOWED, WHEN BACK AT YARD TOWER SET UP & WORKED OK, SET UP, FROM SCRATCH 3 TIMES & OPERATED ALL FUNCTIONS, UNABLE TO, FAULT, UNSURE WHAT HAPPENED., PO 133910 - EPV	MR - MECHANICAL REPAIR
P19-W-018	ISUZU FRR600 LONG EWP	164897	28/10/2019 0:00	211488	CARRIED OUT 3MTH TOWER SERVICE, PO 131511	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	162746	03/09/2019 0:00	191890	R#BUS011893033	RE - REGISTRATION
P19-W-018	ISUZU FRR600 LONG EWP	160980	05/08/2019 0:00	191890	CARRIED OUT 12MTH TOWER SERVICE INCL A/I & W/TEST, 2 X ELBOW PIN COVERS UNSERVICEABLE, REPLACED COVERS. BOLTS, BROKEN IN LOWER CYLINDER COVER, REPLACED BOLTS., PO 127895 - EPV	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	160858	05/08/2019 0:00	191890	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, HV WET TESTS + TRAVEL, PO 127788 - SETCO	ET - ELECTRICAL TEST
P19-W-018	ISUZU FRR600 LONG EWP	157292	23/05/2019 0:00	191890	CARRIED OUT 9MTH TOWER SERVICE, RUBBER FLAP OVER TOP BOOM AT ELBOW MISSING, REPLACED RUBBER, FLAP, BOLTS BROKEN IN LOWER LEVEL CYLINDER COVER, REMOVED, BOLTS & REFITTED COVER., PO 124753	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	151841	14/02/2019 0:00	173276	REPAIRED LEVEL CYLINDER COVER & TOP BOOM PIVOT PIN COVER, LEVEL CYLINDER COVER BROKEN OFF - REMOVED BROKEN BOLTS &, REFITTED COVER., TOP BOOM PIVOT PIN COVER BROKEN OFF - REMOVED BROKEN BOLTS &, REFITTED COVER., PO 119931	MR - MECHANICAL REPAIR
P19-W-018	ISUZU FRR600 LONG EWP	151837	14/02/2019 0:00	173859	COMPLETED 6 MONTH TOWER SERVICE INCL WEIGHT TEST, PO 119924	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	151512	08/02/2019 0:00	169484	CARRIED OUT ROUTINE 6MTH ELECTRICAL TESTS, HV DRY TEST, HV WET TESTS, TRAVEL, PO 119629	ET - ELECTRICAL TEST
P19-W-018	ISUZU FRR600 LONG EWP	149852	27/12/2018 0:00	164718	REPAIRS TO TRANSMITTER/REMOTE CONTROL, SWAPPED SPARE INTO TRUCK & SENT THIS ONE FOR REPAIR TO QLD, PO 118283	ER - ELECTRICAL REPAIR
P19-W-018	ISUZU FRR600 LONG EWP	149851	27/12/2018 0:00	169484	SUPPLIED 2ND BATTERY FOR RADIO REMOTE AS MISSING, PO 118282	ER - ELECTRICAL REPAIR
P19-W-018	ISUZU FRR600 LONG EWP	147867	12/12/2018 0:00	157577	CALIBRATED SPARE REMOTE & SENT ORIGINAL FOR REPAIR., TOWER WAS OEPRATING SLOWLY, FOUND SLOW FROM REMOTE BUT OK, FROM BASE CONTROLS. SWAPPED TRANSMITTER WITH DOWNER, SPARE, ALL FUNCTIONS OK, ORIGINAL REMOTE SENT FOR REPAIR., PO 116512 - REPAIR REMOTE	ER - ELECTRICAL REPAIR
P19-W-018	ISUZU FRR600 LONG EWP	146858	24/10/2018 0:00	157577	COMPLETED 3m TOWER SERVICE. CHECKED OVER., P/O 115577	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	144674	07/09/2018 0:00	149322	R#WEB007150640, POSTED DOWNER, ATTEN: CLAIRE BENDAL, PO BOX 4993, MELBOURNE VIC 3001	AS - ATTACHMENT SERVICES

P19-W-018	ISUZU FRR600 LONG EWP	143702	21/08/2018 0:00	149322	COMPLETED 12m TOWER SERVICE, WEIGHT TEST & ANNUAL INSPECTION, REPLACED BROKEN BOLTS TO COVER AT TELE BOOM & LOWER, LOWER CYLINDER COVER., FITTED NEW RETAINER TO LF STABILISER FOOT PLATE, REPLACED, BROKEN BOLTS., PO#112471	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	142807	01/08/2018 0:00	137146	COMPLETED 6m DRY ELECTRICAL TESTS, P/O 111759	ET - ELECTRICAL TEST
P19-W-018	ISUZU FRR600 LONG EWP	138991	01/06/2018 0:00	137069	REPLACED MISSING COVERS TO RH UPPER CYL & BASKET PIVOT PINS, REPLACED COVER MISSING FROM RH UPPER LEVEL CYL PIN &, REPLACED COVER MISSING FROM RH BASKET PIVOT PIN, PO#108675	CD - CUSTOMER DAMAGE
P19-W-018	ISUZU FRR600 LONG EWP	138841	01/06/2018 0:00	137069	COMPLETED 9m TOWER SERVICE, P/O 108675	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	137993	22/05/2018 0:00	137146	FITTED UPGRADED FRONT & REAR SPRINGS WITH EXTRA LEAF., REMOVED WHEELS. REMOVED SPRINGS. FITTED UPGRADED SPRINGS, WITH EXTRA LEAF. RESET SPRINGS AND ADDED EXTRA LEAF., FITTED NEW PINS, BUSHES SHACKLES & HANGERS AS REQUIRED., GREASED THE SPRING PINS. REFIT ALL REMOVED PARTS IN REVERSE, ORDER, P/O 107960	MJ - MAJOR REPAIR
P19-W-018	ISUZU FRR600 LONG EWP	133039	06/02/2018 0:00	121974	REPLACED FAULTY TIMER RELAY. STABILISERS NOW ENGAGING., PO#103872	ER - ELECTRICAL REPAIR
P19-W-018	ISUZU FRR600 LONG EWP	132318	05/02/2018 0:00	109814	COMPLETED 6m ELECTRICAL TEST, COMPLETED HV DRY TEST., PO#103321	ET - ELECTRICAL TEST
P19-W-018	ISUZU FRR600 LONG EWP	132590	05/02/2018 0:00	121594	DRILLED OUT BROKEN BOLTS & REFITTED LOWER TELE BOOM COVER, PO#103502	CD - CUSTOMER DAMAGE
P19-W-018	ISUZU FRR600 LONG EWP	132600	05/02/2018 0:00	122601	COMPLETED 6m TOWER SERVICE. REPLACED HYDRAULIC FILTER, REPLACED MISSING LH COVER OVER BASKET PIVOT PIN., PO#103511	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	128536	01/11/2017 0:00	109814	COMPLETED 3m TOWER SERVICE. REPLACED MISSING RUBBER FLAP, FROM LOWER BOOM., P/O 100271	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	126060	07/09/2017 0:00	100759	REPLACED FAULTY TIMER RELAY., TOWER WAS NOT WORKING. NO POWER TO TOWER SAFETY RELAY SYSTEM, FOUND FAULT IN TIMER RELAY. FITTED NEW, CHECKED OPERATION, ALL OK., PO#98058	ER - ELECTRICAL REPAIR
P19-W-018	ISUZU FRR600 LONG EWP	123962	19/07/2017 0:00	92487	COMPLETED 12m TOWER SERVICE, BOLT BROKEN IN TELE BOOM COVER, REPLACED BROKEN BOLT., CYLINDERS TEST LOAD 180kg., PO#96214	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	123859	07/07/2017 0:00	92681	COMPLETED 6m ELECTRICAL SERVICE, P/O 96113	ET - ELECTRICAL TEST
P19-W-018	ISUZU FRR600 LONG EWP	123235	06/06/2017 0:00	92681	SUPPLIED REMOTE BATTERY, P/O 95553	GR - GENERAL REPAIRS
P19-W-018	ISUZU FRR600 LONG EWP	121559	16/05/2017 0:00	84131	COMPLETED 9m TOWER SERVICE. CHECKED OVER., P/O 94017	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	119782	07/04/2017 0:00	92681	COMPLETED 80,000km SERVICE. REPLACED OIL, FUEL & AIR FILTER., REPLACED WIPERS. CHECKED OVER. GREASED. CHECKED & ADJUSTED, BRAKES & CLUTCH. TIGHTENED LOOSE LH DOOR CHECK STOP., RESECURED LHR REVERSE SENSOR. REPAIRED LHR CLEARANCE LIGHT, WIRING.	PS - PLANNED SERVICE
P19-W-018	ISUZU FRR600 LONG EWP	119343	21/03/2017 0:00	92391	REPLACED STEER TYRES - 235/76R17.5 JHH309 HIFLY X2, P/O 92391	TC - TYRE CHANGE/REPLACEMENT
P19-W-018	ISUZU FRR600 LONG EWP	118792	07/03/2017 0:00	76080	REPLACED DRIVE TYRES (POS 3 - 4), TYRES WERE FROM STEER AND, WAS USED AS A RUNOUT DUE TO PREVIOUS DAMGED TYRES, P/O 91988	TC - TYRE CHANGE/REPLACEMENT
P19-W-018	ISUZU FRR600 LONG EWP	117240	30/01/2017 0:00	57807	COMPLETED 6m TOWER SERVICE & WEIGHT TEST, COMPLETED GEL COAT REPAIR AT LOWER CORNERS IN BASKET., P/O 90659	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	116684	06/01/2017 0:00	57807	COMPLETED 6m ELECTRICAL (HIGH & LOW VOLTAGE) TESTS, P/O 90207, COMPLETED AT LILYDALE DEPOT.	ET - ELECTRICAL TEST
P19-W-018	ISUZU FRR600 LONG EWP	116498	03/01/2017 0:00	65901	COMPLETED 60,000km MAJOR SERVICE. REPLACED OIL, AIR & FUEL, FILTERS. ADJUSTED BRAKES & CLUTCH. REPLACED WIPER INSERTS., REFILLED WIPER BOTTLE WITH WASHER FLUID. REMOVED MAF SENSOR, AND DEGREASED. LUBED & INSPECTED CUPBOARD LATCHES & STRUTS, LUBED DOOR HINGES. COMPLETED PARK BRAKE TEST AS PER ADR35.5., CHECKED & ADJUSTED VALVE CLEARANCES. REPLACED DPD HOSE & PCV, FILTER. REPLACED TRANSMISSION FLUID. ADJUSTED HEADLIGHTS., NOTE: REAR INBOARD WHEELS NOT LOOKING AT FURTHER.	PS - PLANNED SERVICE
P19-W-018	ISUZU FRR600 LONG EWP	115535	01/12/2016 0:00	57807	CALLED ONSITE TO INSPECT STABILISER LEGS NOT PACKING UP., WAS UNABLE TO FIND CAUSE OF FAULT; NEEDS TO GO TO DEALER., P/O 89348	BE - BREAKDOWN - ELECTRICAL
P19-W-018	ISUZU FRR600 LONG EWP	115246	29/11/2016 0:00	55672	REPLACED FAILED ESTOP. RETURNED & FITTED NEW RELAY., P/O 89146	BE - BREAKDOWN - ELECTRICAL
P19-W-018	ISUZU FRR600 LONG EWP	114175	31/10/2016 0:00	55672	REPLACED 2x TYRES (POS 5-6), P/O 88264	TC - TYRE CHANGE/REPLACEMENT
P19-W-018	ISUZU FRR600 LONG EWP	114127	31/10/2016 0:00	55656	COMPLETED 3m TOWER SERVICE. REPLACED LED LIGHT, FOR STABILISER ENGAGED INDICATOR., P/O 88243	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	112297	29/09/2016 0:00	39848	COMPLETED 45,000km SERVICE. CHANGED ENGINE OIL & FILTERS, CHANGED FUEL & AIR FILTERS. DRAINED & REPLACED GEARBOX, & AMT OIL. CLEANED PAN. REMOVED AND REPLACED GASKETS &, REASSEMBLED. ADJUSTED BRAKES - FAIR WAY OUT & HARD TO ACCESS, TIGHTENED LOOSE RH DOOR CHECK. AJUSTED ENGINE BELTS AS, LOOSE. TIGHTENED BATTERY TERMINALS & TOPPED UP LEVELS AS, LOW. DISASSEMBLED FRONT OF HEADLIGHTS & AIM AS REQUESTED., REPLACED BLOWN LEFT FRONT PARKER GLOBE. REMOVED & REPLACED, DPD HOSE. PARK BRAKES TESTED., PO#86878	PS - PLANNED SERVICE
P19-W-018	ISUZU FRR600 LONG EWP	112826	27/09/2016 0:00	39848	0	RE - REGISTRATION
P19-W-018	ISUZU FRR600 LONG EWP	110198	01/08/2016 0:00	39848	COMPLETED 12m TOWER SERVICE, WEIGHT TEST & ANNUAL INSPECTION, COVER OVER BASKET PIVOT PIN BROKEN, REPLACED COVER., PO#85164	AS - ATTACHMENT SERVICES

P19-W-018	ISUZU FRR600 LONG EWP	109508	26/07/2016 0:00	35832	REPLACED 2x DRIVE TYRES., 1 HAD SIDEWALL DAMAGE, OTHER SIDE REPLACED TO MATCH, P/O 84560	TC - TYRE CHANGE/REPLACEMENT
P19-W-018	ISUZU FRR600 LONG EWP	109773	08/07/2016 0:00	31145	COMPLETED 12m ELECTRICAL TESTS, P/O 84802, COMPLETED ONSITE AT LILYDALE	ET - ELECTRICAL TEST
P19-W-018	ISUZU FRR600 LONG EWP	108479	01/07/2016 0:00	31145	REPAIRED WATER DAMAGED REMOTE., REMOTE LEFT IN EWP DURING TRAVEL ALLOWING IT TO BE EXPOSED, TO THE ELEMENTS., P/O 83934	Other
P19-W-018	ISUZU FRR600 LONG EWP	107648	01/06/2016 0:00	31145	COMPLETED MINOR TRUCK SERVICE. REPLACED OIL & FUEL FILTERS., REPLACED WIPER INSERTS. ADJUSTED BRAKES. CHECKED PARK BRAKE., LUBED LOCKERS ETC. CLEANED PCV FILTER., P/O 832229	PS - PLANNED SERVICE
P19-W-018	ISUZU FRR600 LONG EWP	107784	24/05/2016 0:00	29936	REPLACED MISSING TELE CYLINDER PIN COVER., REFITTED MASTER LEVEL CYLINDER COVER AS IT WAS BROKEN OFF., P/O 83329	Other
P19-W-018	ISUZU FRR600 LONG EWP	106981	13/05/2016 0:00	29344	COMPLETED 9m TOWER SERVICE., COMPLETED AT 254hrs, P/O 82678	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	104302	29/02/2016 0:00	17426	CHECKED OPERATION OF BASKET ROTATE SWITCH., BASKET ROTATE DIRECTION TESTED WITH ADAM MILLS. TESTED OK., CHECKED FOR SLEW SWITCH BACK TO FRONT ALL OK., MISSING LED COVER IN TRANSMITTER, PARTS ORDERED., P/O 80701	Other
P19-W-018	ISUZU FRR600 LONG EWP	102768	31/01/2016 0:00	17326	COMPLETED 6 MONTH TOWER SERVICE & WEIGHT TEST., LH BASKET PIN COVER TEMPORARILY REPLACED, NEW ONE ORDERED., REFITTED CRACKED LH ELBOW PIN COVER, NEW ONE REQUIRED., REMOVED & STRAIGHTENED L/R STABILISER FOOT RETAINING PLATE., REFITTED WITH NEW BOLTS. CHECKED & FOUND PLUGS HAD BEEN PULL, OUT OF ARROW BOARD, REFITTED.	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	102897	29/01/2016 0:00	10391	COMPLETED 6MTH ELECTRICAL TEST., COMPLETE 6m ELECTRICAL TEST, P/O 79641	AS - ATTACHMENT SERVICES
P19-W-018	ISUZU FRR600 LONG EWP	102808	29/01/2016 0:00	17416	COMPLETED 15,000KM SERICE., ADJUSTED HANDBRAKE. REPLACED OIL & PCV FILTERS. GREASED., CLEANED WATER TRAP. CHECK & ADJUSTED BRAKES, HAND & FOOT., ADJUSTED CLUTCH. DRAINED AIR TANKS. TIGHTENED MANIFOLDS &, EXHAUST SYSTEM.	PS - PLANNED SERVICE