

TRIM(WOHH.WOWH_MODEL)	WOWH_DESC	WOWH_ORDER_N	WOWH_INVOICE_DATE	WOWH_METER	Comments	Full Rep Code
P19-W-019	ISUZU FRR600 LONG EWP	235656	11/09/2024 0:00	432187	PREP FOR AUCTION, Completed by: wilson.wang@porterplant.com.au on: Sep 11, 2024	GR - GENERAL REPAIRS
P19-W-019	ISUZU FRR600 LONG EWP	231974	21/05/2024 0:00	432187	CARRIED OUT DETAIL WASH & FULL INSPECTION, ISSUES NOTED AT SERVICE - NEEDS WASH, NEEDS WHEEL ALIGNMENT & INSPECT CRACKS AROUND TOP BOOM CYLINDER., COMPLETE DETAIL WASH & POLISH TOWER READY FOR NEXT ELECTRICAL TEST, UNIT FILTHY., STEERING PULLS, ROAD TEST, YOU HAVE TO HOLD STEERING WHEEL TO RIGHT TO GO STRAIGHT, IF YOU LET GO TRUCK GOES, LEFT VIOLENTLY, BOTH FRONT STEER TYRES WORN OUT., CRACK AROUND TOP BOOM EXTENSION CYLINDER, WEB SUPPORT ABOVE BASKET LEVELLING CYLINDER, REMOVE ALL COVERS,, EXT BOOM RUBBING AGAINST INNER TOP BOOM, SUSPECT WEAR PAD FAILURE, CRACK IN CIRCLE MODE AROUND OUTER TOP, BOOM PIVOT PIN BOSS, CRACKS NOTED ON RH LOWER SIDE OF TOP BOOM AT KNUCKLE END., PO 199727 - EPV	GR - GENERAL REPAIRS
P19-W-019	ISUZU FRR600 LONG EWP	229709	03/05/2024 0:00	428720	MAJOR REPAIRS., NDT TESTING AS REQUIRED. COMPLETELY DETAIL, WASH, AND POLISH, TOWER READY FOR ELECTRICAL TESTING AS UNIT IS EXTREMELY DIRTY., EXTENSION BOOM WEAR PADS ARE WORN OUT, BOOM IS SITTING TO ONE SIDE. CRACKING AROUND TOP BOOM KNUCKLE AREA., PO # 197516 EPV, ASSET TO BE EXCHANGED 3/05/24. PO # CANCELLED.	MR - MECHANICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	229408	22/03/2024 0:00	431007	CLEARED ABS FAULT CODES, AFTERHOURS CALL OUT - ENGINE LIGHT ON, ABS LIGHT PRESENT ON DASH. CARRIED OUT DIAGNOSTIC SCAN - WHEEL SPEED, SENSOR OVER SPEED LHR, DRIVER ADVISED VEHICLE'S REAR WHEEL SPUN WHEN TAKING OFF FROM INTERSECTION, CLEAR, FAULT LIGHTS & INSPECTED LHR SPEED SENSOR, FOUND SATISFACTORY, TEST DROVE VEHICLE, NIL DEFECTS., PO 197175 - EMA	ER - ELECTRICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	227300	22/03/2024 0:00	425432	REPAIRED REAR SPRING, 22/1/24 - CARRY OUT VISUAL INSPECTION OF REAR SUSPENSION, REAR SPRINGS BOTH DAMAGED & UNSERVICEABLE -, BROKEN LEAF/S & CENTRE BOLTS, ORDER PARTS, REMOVE REAR SPRINGS, PINS & BUSHES, CARRIED OUT IAW WITH, ISUZU MAINTENANCE SERVICE & REPAIR MANUAL, CARRIED OUT VISUAL INSPECTION OF CHASSIS FOR ANY DEFECTS -, NIL FINDINGS. CARRY OUT CLEANING OF CHASSIS & DIFF, INSTALLED NEW REAR SPRING ASSEMBLIES AS PER MANUAL., CARRIED OUT TORQUE CHECKS ON ALL SUSPENSION HARDWARE USING CORRECT VEHICLE MANUFACTURE, STANDARDS & SPECS, NOW FOUND SATISFACTORY, REINSTALLED WHEELS, TORQUE ALL NUTS TO CORRECT SPEC,, CARRY OUT INSPECTION, FOUND SATISFACTORY, TEST DROVE, CARRIED OUT AFTER INSTALLATION TESTS &, INSPECTIONS, RETORQUED AS REQD, NOW SATISFACTORY TO MANUFACTURERS SPECS., PO 195093 - EMA	MR - MECHANICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	228462	01/03/2024 0:00	428303	CARRIED OUT 6MTH TOWER SERVICE INCL WEIGHT TEST, REPLACED HYDRAULIC FILTER., CHANGE CDD MOUNT FROM A BOW SHACKLE TO HAMMER LOCK., COVER MISSING FROM INSIDE OF TOP BOOM AT KNUCKLE ASSY, REMOVED BROKEN NYLON BOLTS & REFITTED COVER, WITH NEW NYLON BOLTS AS COVER WAS FOUND IN THE CAB., PO 196258 - EPV	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	228510	27/02/2024 0:00	427550	REPAIRED DAMAGED FRONT TRACK ROD & WHEEL BEARINGS, DRIVER REPORTED NOISE IN FRONT END, CARRY OUT DETAILED INSPECTION, TRACK ROD & WHEEL BEARINGS DAMAGED,, ORDERED PARTS. REMOVED & REPLACED TRACK ROD WITH NEW AS PER ISUZU MANUAL, REMOVED & REPLACED FRONT, WHEEL BEARINGS WITH NEW AS PER ISUZU MANUAL, SET & ADJUST VEHICLE STEERING ALIGNMENT, CARRIED OUT, OPERATIONAL FUNCTIONAL TESTING, NOW SATISFACTORY, RETURNED VEHICLE TO YARD., PO 196307 - EMA	CD - CUSTOMER DAMAGE
P19-W-019	ISUZU FRR600 LONG EWP	228520	27/02/2024 0:00	428720	REPAIRED PLUG & WIRING FOR TRANSMISSION, CALL OUT TO SITE AT COCKATOO FOR FLAT BATTERIES & TRANSMISSION LIGHT ON DASH., JUMP STARTED VEHICLE, CHECKED BATTERY CHARGE RATE, FOUND SATISFACTORY, CARRIED OUT DIAGNOSTIC SCANNING, OPEN CIRCUIT, INSPECTED TRANSMISSION, FOUND LOOSE PLUG & BROKEN WIRING, CARRIED OUT REPAIRS, TESTED, NOW, SATISFACTORY, FOLLOWED VEHICLE BACK TO YARD, RESCANNED DIAGNOSTICS, NIL CODES PRESENT, ALL OK., PO 196313 - EMA	BE - BREAKDOWN - ELECTRICAL

P19-W-019	ISUZU FRR600 LONG EWP	227298	08/02/2024 0:00	425432	BRAKES AND COMPONENT REPLACEMENT/OVERHAUL, 22/1/24 - ALL BRAKES FOUND WORN TO MAX WEAR LIMITATIONS, REMOVED ALL WHEELS, REMOVED ALL BRAKES/DRUMS &, BEARINGS, CARRIED OUT IAW AS PER MANUAL, HAVE BRAKES & DRUMS SENT AWAY FOR OVERHAUL (DELIVER & PICK UP),,, ALL NEED TO BE REPLACED, DRUMS FOUND TO BE OVERSIZED & UNSERVICEABLE. CARRIED OUT BEARING CLEANING,, INSPECTION & REPACKING, FOUND SATISFACTORY. CLEANED, INSPECTED & PACK ALL BRAKE HUBS, CARRIED OUT REASSEMBLY, OF ALL BRAKE & HUB ASSEMBLIES IAW AS PER MANUAL, SET BRAKES AS REQD, REINSTALLED ALL WHEELS & TORQUE TO SPEC,, CARRIED OUT TESTING, OK, HAVE INDEPENDENT BRAKE ROLL TEST CARRIED OUT, OK, CARRIED OUT FINAL BRAKE ADJUSTMENTS,, NOW FOUND SATISFACTORY., WHEEL CYLINDERS FOUND FATIGUED, LEAKING & UNSERVICEABLE, FURTHER VISUAL INSPECTION CARRIED OUT, CARRIED OUT, REMOVAL & REPLACEMENT AS PER MANUAL & SPECS, CARRIED OUT ALL SYSTEM BLEED, CARRIED OUT TESTING, OK., PO 195091 - EMA	MR - MECHANICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	227296	08/02/2024 0:00	425432	CARRIED OUT MINOR TRUCK SERVICE, REPLACED ENGINE OIL & OIL FILTER, REPLACED PCV FILTER & FUEL FILTERS, TOPPED UP WASHER BOTTLE, GREASED,, REPLACED WIPER BLADES, REPLACED A/C COMPRESSOR BELT & COOLING FAN BELT., PO 195089 - EMA	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	227301	08/02/2024 0:00	425432	REPAIRED DIFF HOUSING ANCHOR POINT, 22/1/24 - CARRY OUT INSPECTION, LHR DIFF HOUSING CRACKED AT U-BOLT ANCHOR POINT, ACCESS HAS BEEN MADE WITH, BRAKE & REAR SPRING REPAIRS, GRIND AWAY CRACKED & FATIGUED ANCHOR POINT, CARRY OUT REQD WELDING &, FABRICATION WORK, INSPECT FOR FURTHER DAMAGES, IF NIL FINDINGS DEEM SATISFACTORY FOR WORK. HAVE VEHICLE, INDEPENDENTLY INSPECTED BY VEHICLE BODY BUILDER, OK., PO 195094 - EMA	MR - MECHANICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	223439	01/01/2024 0:00	411203	***CANCELLED - NO INVOICE RECEIVED***, FRONT END WHEEL ALIGNMENT, PO 191209 - EMA	WA - AXLE CORRECTION/ALIGNMENT
P19-W-019	ISUZU FRR600 LONG EWP	226176	21/12/2023 0:00	419142	CARRIED OUT BUSHFIRE MITIGATION, TRAVEL TO SITE, CHECK FIRE EXT, NAP SACK, RAKE HOE, EXHAUST, FIT INSPECTION STICKER., PO 193948 - EMA	PI - PLANT INSPECTION
P19-W-019	ISUZU FRR600 LONG EWP	224516	18/12/2023 0:00	419412	REPLACED LOST EWP REMOTE & REPAIRED WIRING, 20/11/23 - REPORTED BY YARD MGR TO REPLACE LOST REMOTE, QUOTE TO REPLACE MISSING REMOTE & REPLACE, TRANSMITTER, PICK UP VEHICLE & RETURN TO EMA, CUSTOM MAKE EWP REMOTE & TRANSMITTER TO SUIT NEW REMOTE,, REMOVE & REPLACE RADIO TRANSMITTER & CONTROL UNIT, CARRIED OUT OPERATIONAL FUNCTIONAL TESTING., INSPECT EWP REMOTE AS TO WHY IT IS NOT OPERATIONAL, CARRIED OUT NECESSARY REPAIRS TO WIRING LOOM OR UNIT,, CARRIED OUT FUNCTIONAL TESTING OF UNIT, FUSE & MICRO SWITCH FOUND REMOVED & DISABLED, RECONNECTED UNIT,, CARRIED OUT OPERATIONAL FUNCTIONAL TESTING, ALL OK. RETURN VEHICLE TO BEACONSFIELD YARD., PO 192274 - EMA, REPORTED BY MARTIN KNOX 0407 306 889, DOWNER PO # 22776533	CD - CUSTOMER DAMAGE
P19-W-019	ISUZU FRR600 LONG EWP	225985	14/12/2023 0:00	419142	REPAIRED EXHAUST BRAKE, EXHAUST BRAKE LEAKS UNDER LOAD, NOT EFFECTIVE UNDER OPERATIONAL USE, CARRIED OUT DETAILED INSPECTION,, VARIOUS HARDWARE FOUND FATIGUED, ISOLATED VEHICLE FOR MAINTENANCE, REMOVED & REPLACED VARIOUS PARTS,, CARRIED OUT TESTING, NIL LEAKS, NOW SATISFACTORY., PO 193772 - EMA	BM - BREAKDOWN - MECHANICAL
P19-W-019	ISUZU FRR600 LONG EWP	224147	04/12/2023 0:00	419084	CARRIED OUT 3MTH TOWER SERVICE, PO 191864 - EPV	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	223482	24/11/2023 0:00	416000	REPLACED REAR SUSPENSION CENTRE BOLTS, 8/10/23 - DURING MAINTENANCE INSPECTION REAR SUSPENSION CENTRE BOLTS FOUND TO BE BROKEN & SPRING PACKS, HAD SHIFTED, REMOVED & REPLACED BOTH REAR SUSPENSION CENTRE BOLTS WITH NEW AS PER ISUZU MANUAL, TORQUED, ALL REQD HARDWARE, CARRIED OUT OPERATIONAL FUNCTIONAL TESTING & RETORQUED ALL HARDWARE, ALL OK., PO 191252 - EMA	MR - MECHANICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	223441	24/11/2023 0:00	416000	INSTALLED NEW LH DOOR PANEL & DOOR INDICATOR, 6/10/23 - LH DOOR INDICATOR & PANEL/GUARD DAMAGED BY OPERATOR, CARRY OUT INSPECTION, LH DOOR PANELS MISSING & INDICATOR MISSING, ORDERED NEW PARTS, REMOVED DAMAGED &, BROKEN ATTACHMENT HARDWARE, PREPPED DOOR FOR NEW PANELS, INSTALLED NEW PANEL & DOOR INDICATOR, CARRIED, OUT OPERATIONAL TESTING, OK., PO 191209 - EMA	CD - CUSTOMER DAMAGE
P19-W-019	ISUZU FRR600 LONG EWP	223438	24/11/2023 0:00	416000	CARRIED OUT MINOR TRUCK SERVICE, 6/10/23 - REPLACED ENGINE OIL & OIL FILTER, REPLACED AIR FILTER & FUEL FILTERS, GREASED, REPLACED WIPER BLADES,, TOPPED UP WASHER BOTTLE, BRAKE THICKNESS CHECK, AJDUSTED BRAKE & CLUTCH AS REQD, ROAD TEST., PO 191209 - EMA	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	224426	03/11/2023 0:00	418775	REPLACED 4 DRIVE TYRES, 4 X 235/75R17.5 132/130M BS M716, PO 192179 - BRIDGESTONE DOVETON	TC - TYRE CHANGE/REPLACEMENT
P19-W-019	ISUZU FRR600 LONG EWP	223287	11/10/2023 0:00	411203	CARRIED OUT ELECTRICAL TESTING, HV DRY TEST, HV WET TESTS., PO 191050 - SETCO	ET - ELECTRICAL TEST

P19-W-019	ISUZU FRR600 LONG EWP	222093	19/09/2023 0:00	411203	CARRIED OUT 12MTH TOWER SERVICE INCL A/I & W/T, REPLACED HYDRAULIC OIL & FILTERS X 2., SEVERAL BROKEN NYLON BOLTS, DRILLED & TAPPED OUT BROKEN NYLON BOLTS & S & F NEW X 3., CDD ROPE EXPIRES 17/9/23, S & F 2 X NEW CDD ROPE., PO 189677 - EPV	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	221563	25/08/2023 0:00	405502	CARRIED OUT REPAIRS OF ITEMS FOUND DURING SERVICE, BOTTOM OF BASKET IS WEARING THROUGH ON THE FRONT SIDE BOTTOM RADIUS OF BASKET, REPAIRED BY, FIBREPLUS, DROP OFF AND PICK UP INCL., LH WEAR STRIP ON BOTTOM OF BASKET IS LIFTING OFF THE BOTTOM & ALL THE GELCOAT IS DAMAGED AROUND IT., NEEDS TO BE REBOUNDED TO BASE OF BASKET & GELCOAT END OVER, REPAIRED BY FIBREPLUS, DROP OFF &, PICK UP INCL., P/S/R STABILISER FOOT KEEPER PLATE BOLTS ARE BROKEN, UNABLE TO REMOVE ON SITE, REMOVE BROKE BOLTS., STRAIGHTEN KEEPER PLATES & S&F NEW CSK UNBRACOS, REMOVE FOOT PLATE AS REQD, BOLTS RUSTED IN., REMOVED BROKEN BOLTS, RETAPPED THREADS, FITTED FOOT PLATE & S&F NEW BOLTS., PO 189032 - EPV, (REFER TO TOWER SERVICE AS PER WO 218407)	MR - MECHANICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	220742	11/08/2023 0:00	407303	CARRIED OUT MINOR TRUCK SERVICE & REPAIRS, REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS & PCV FILTER, GREASED, REPLACED WIPER INSERTS., D/S SEAT BELT FOUND WORN & TORN, CLEANED CABIN FOR ACCESS, REMOVED SEAT TRIMS, REMOVED & REPLACED, SEAT BELT WITH NEW, REINSTALLED ALL TRIMS, CARRIED OUT FUNCTIONAL TESTING, ALL OK., PO 188136 - EMA	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	221233	11/08/2023 0:00	407303	REPAIRED HANDBRAKE, CARRIED OUT INSPECTION, REAR PARK BRAKE NOT HOLDING VEHICLE, REMOVED ALL TYRES & BRAKE DRUMS, REAR LININGS, FOUND TO BE WITHIN MEASUREMENT, REMOVED & REPLACED PARK BRAKE WHEEL CYLINDERS & PARK BRAKE CHAMBERS., REASSEMBLED BRAKE ASSEMBLIES AS PER ISUZU MAINTENANCE MANUAL, BLED HYDRAULIC BRAKING SYSTEM & CARRIED, OUT FUNCTIONAL TESTING, NOW SATISFACTORY., PO 188136 - EMA	MR - MECHANICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	218321	21/06/2023 0:00	400439	CARRIED OUT MINOR TRUCK SERVICE & REPAIRS, 31/5/23 - REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS, GREASED, REPLACED WIPER BLADE INSERTS., TRAY ACCESS GATE WON'T OPEN, BENT BACK METAL SLIDE THAT HAD BEEN STOOD ON, CLEAN OUT SLIDE., RHR TOOLBOX HINGE BROKEN, REPLACED HINGE., RHR TOOLBOX CENTRAL LOCK, REMOUNT ACTUATOR., REFILLED EMPTY KNAPSACK., MISSING WNI, RETORQUED WHEEL & FIT NEW WNI., AIR PRESSURE SENSOR AIR LEAK, ADJUSTED/TIGHTENED UP., PO 185714 - EMA	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	218407	14/06/2023 0:00	400728	CARRIED OUT 9MTH TOWER SERVICE, 29/5/23 - TRAVELLED TO BEACONSFIELD BUT WAS UNABLE TO RETRIEVE UNIT FROM LINESMAN, RESCHEDULED., 2/6/23 - TRAVELLED TO BEACONSFIELD, SERVICE & INSPECTION COMPLETED., TO BE BOOKED INTO WORKSHOP FOR OTHER REPAIRS TO SCUFF PLATE ON BOTTOM OF BASKET, DAMAGE TO BOTTOM RADIUS, OF BASKET & BROKEN SCREWS ON PSR STABILISER FOOT RETAINING PLATES., PO 185789 - EPV	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	216390	09/05/2023 0:00	388923	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, HV WET TESTS, PO 183752 - SETCO	ET - ELECTRICAL TEST
P19-W-019	ISUZU FRR600 LONG EWP	216115	18/04/2023 0:00	388923	REPLACED 6 TYRES & BALANCED, TYRES WORN TO LIMITS & BEYOND, 2 X 235/75R17.5 132/130M BS R156, 4 X 235/75R17.5 132/130M BS M716, PO 183390 - BRIDGESTONE DOVETON	TC - TYRE CHANGE/REPLACEMENT

P19-W-019	ISUZU FRR600 LONG EWP	214242	31/03/2023 0:00	388923	REPAIRED DPD & EGR FAULTS, 25/2/23 - DPD SYSTEM FOUND FAULTED/RESTRICTED, CARRIED OUT VISUAL SYSTEM INSPECTION,, REMOVE & CLEAN ALL ENGINE & DPD SYSTEM SENSORS, NOW OK, CARRIED OUT OBD2 SCANNING DIAGNOSTICS,, CARRIED OUT DPD SYSTEM BURN REGEN, VARIOUS BURNS CANCELLED BY OPERATORS, CARRIED OUT VEHICLE, OPERATIONAL FUNCTIONAL TESTING, REMOVE DPD SYSTEM FOR VISUAL INTERNAL INSPECTION & TREATMENT, CLEANING, STRIP DOWN DPD COMPONENTS & CARRIED OUT SYSTEM TREATMENT CLEAN, FLUSH SYSTEM OF, TREATMENT, REASSEMBLE DPD COMPONENTS & SYSTEM, REINSTALLED & TESTED, CARRIED OUT DPD SYSTEM, REGEN PROGRAMMING, ALL OK., 2/3/23 - DURING DIAGNOSTIC SCAN OF DPD SYSTEM REGEN, FUEL INJECTION SYSTEM FOUND TO BE OVER-, FUELING, CAUSING VEHICLE TO GO INTO LIMP MODE, CARRIED OUT INJECTOR VALVE TRIMS, FOUND TO BE AT, EXTREME LEVEL OF OVER FUELING, CARRIED OUT VALVE TIMING INSPCTION & ADJUSTMENT, REMOVED ALL, ENGINE INJECTORS & FUEL RAIL, SENT INJECTORS AWAY FOR BENCH TESTING, FAILED - ALL NEED REPLACING., REMOVE INTERCOOLER AS HIGH VOLUME OF ENGINE OIL FOUND WITHIN, SENT AWAY FOR CLEANING &, INSPECTION, REINSTALLED ONCE COMPLETED. INSPECTED & CLEANED FUEL RAIL & ALL SENSORS, INSTALLED, NEW INJECTORS & REINSTALLED FUEL SYSTEM AS PER ISUZU MANUAL, NOW SATISFACTORY. CARRIED OUT, INJECTOR PROGRAMMING & FUNCTIONAL TESTING, ALL OK, DRAINED & REPLENISHED ENGINE OIL, REPLACED, ALL ENGINE OIL & FUEL FILTERS WITH NEW, CARRIED OUT TEST DRIVE & ENGINE INSPECTION, ALL OK., 2/3/23 - DURING INSPECTIONS OF FUEL SYSTEM ENGINE EGR & OIL COOLER & INLET MANIFOLD FOUND, RESTRICTED/BLOCKED & EGR VALVE INOPERABLE, REMOVED & INSPECTED ALL ENGINE EGR COOLERS &, EGR VALVE, COMPLETELY BLOCKED & UNSERVICEABLE, CARRIED OUT ENGINE INLET & COOLER HOUSING, CLEANING & INSPECTED, CARRIED OUT CLEANING & INSPECTION OF ALL REMOVED ENGINE COMPONENTS,, PREPPED ENGINE, CARRIED OUT EGR VALVE BENCH TESTING - FAILED, INSTALLED & REASSEMBLED INLET, MANIFOLD, EGR & ENGINE COOLERS, EGR VALVE & ALL COMPONENTS AS PER ISUZU MANUAL, CARRIED OUT, OPERATIONAL FUNCTIONAL TESTING, ALL OK, TEST DRIVE, ALL OK., PO 181176 - EMA	MR - MECHANICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	213492	03/03/2023 0:00	386657	INSTALLED NEW FILTER HOUSING, 4/2/23 - VEHICLE WOULD NOT START - FUEL FILTER HOUSING DAMAGED, SPEAK WITH OPERATOR & DISCUSS CONCERNS, CARRY OUT INSPECTIONS, INSPECTED BATTERIES - SATISFACTORY,, INSPECTED FUEL PRIME SYSTEM, FUEL LEAKING FROM HOUSING, DAMAGED FROM ROCKS OR HITTING A BRANCH., REMOVED HOUSING & INSTALLED NEW FILTER HOUSING, PRIMED SYSTEM, STARTED & OPERATED VEHICLE, ALL OK., FOLLOWED OPERATOR BACK TO YARD, REINSPECTED VEHICLE, ALL OK., PO 180393 - EMA	MR - MECHANICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	214000	21/02/2023 0:00	387700	CARRIED OUT 6MTH TOWER SERVICE INCL W/T & REPAIRS, REPLACED HYDRAULIC FILTER., D/S DOOR INDICATOR NOT WORKING, REMOVED INNER DOOR TRIM, S & F NEW GLOBE, TESTED OK, REPLACED DOOR TRIM., CHANGE OVER SWITCH AT LEG CONTROLS IS SPINNING IN THE ENCLOSURE, REMOVED COVER, TIGHTENED SWITCH BASE, WITH SWITCH IN CORRECT POSITION, REPLACED ENCLOSURE LID., BOTH THE INNER & OUTER UPPER BOOM PINS AT THE KNUCKLE ARE MISSING THEIR COVERS, COVERS FOUND ON DECK, OF TRUCK, CLEANED OLD SILICON FROM BOOM, PIN & COVER, GLUE COVER BACK IN PLACE WITH SIKAFLEX, REFITTED, OUTER COVER WITH NEW NYLON BOLT., SKID PLATE ON BOTTOM OF BASKET COMING LOOSE & MULTIPLE LARGE CHIPS IN GELCOAT. MAKE ARRANGMENTS FOR, REPAIRS IN WORKSHOP., P/S/R STABILISER FOOT RETAINING PLATE HAS BROKEN BOLT, UNABLE TO REMOVE ON SITE, ARRANGE FOR REPAIR, TO BE COMPLETED IN WORKSHOP., PO 180891 - EPV	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	213518	07/02/2023 0:00	386500	FITTED NEW DECAL, RATING DECAL FADED & UNREADABLE, CLEANED SURFACE & FITTED NEW DECAL., PO 180393 - EPV	GR - GENERAL REPAIRS
P19-W-019	ISUZU FRR600 LONG EWP	212868	03/02/2023 0:00	385541	CARRIED OUT TRUCK SERVICE & REPAIRS, REPLACED ENGINE OIL & OIL FILTER, REPLACED REPLACED FUEL FILTERS & PCV FILTER, REPLACED WIPER BLADES, GREASED., MAIN FUEL FILTER HOUSING FOUND CRACKED & LEAKING, REMOVED & REPLACED HOUSING WITH NEW, PRIME FUEL SYSTEM,, CARRIED OUT LEAK CHECK, NIL FOUND, ALL OK., PO 179784 - EMA	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	212876	03/02/2023 0:00	385900	REPLACED FAULTY PTO RELAY, CALLED OUT TO SITE, SPOKE TO OPERATOR, PTO NOT ENGAGING, INSPECTED & FOUND PTO RELAY UNSERVICEABLE,, REPLACED WITH NEW, TESTED FUNCTIONS, ALL OK., PO 179784 - EMA	BM - BREAKDOWN - MECHANICAL

P19-W-019	ISUZU FRR600 LONG EWP	212463	17/01/2023 0:00	382557	RESET TIMER RELAY FOR STABILISER LEGS, CALL OUT TO DOWNER YARD, STABILISER LEGS WON'T ENGAGE, ENGAGED PTO & TURNED SYSTEM ON., FOUND SIGNIFICANT DELAY IN SYSTEM STARTING TIME, TOOK ABOUT 1.5 MINS BEFORE SYSTEM WOULD TURN ON., CHECKED ALL PROXY SWITCHES, FOUND NO ISSUES. TOOK COVERS OFF AT TURRET TO LOOK FOR ANY OBVIOUS, ELECTRICAL ISSUES, FOUND TIMER RELAY SET TO 1.5MINS CAUSING SYSTEM TO TAKE THAT LONG TO ENGAGE., RESET RELAY TO 30 SECONDS TO STILL ALLOW TIME FOR SYSTEM TO SELF-CHECK PRIOR TO OPERATION., REFITTED ALL COVERS REMOVED BY DRIVER PREVIOUSLY., PO 179381 - EPV	ER - ELECTRICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	211962	21/12/2022 0:00	380516	S & F NEW TIMER RELAY, LEGS NOT WORKING, TRAVEL TO CRANBOURNE, INSPECTED BOOM PROXIES & FOUND BODY OF STRAP PROXY CRACKED., S & F NEW PROXY BUT NO CHANGE, INSPECTED BOOM STOWED PROXY & FOUND UNDAMAGED BUT NO SUPPLY AT ALL., CHECKED ALL FUSES, OK, CHANGED TIMER RELAY IN BOX WITH A STANDARD RELAY & UNIT STARTED TO WORK., DIDN'T HAVE TIMER RELAY IN STOCK SO DRIVER FOLLOWED ME BACK TO WORKSHOP. S & F NEW TIMER RELAY, TEST, OK., PO 178913 - EPV	BE - BREAKDOWN - ELECTRICAL
P19-W-019	ISUZU FRR600 LONG EWP	211375	15/12/2022 0:00	376341	BUSHFIRE MITIGATION CHECK, FOUND VEHICLE WAS MISSING FIRE EXT FOR FIRE FIGHTING MITIGATION, S & F BRACKET, S & F FIRE EXT TO BRACKET, SECURE AS REQD, ALL OK., PO 178420 - EMA	GR - GENERAL REPAIRS
P19-W-019	ISUZU FRR600 LONG EWP	210677	25/11/2022 0:00	376341	S & F NEW KEY & CHIP TO SPARE REMOTE, REMOTE LOST ON SITE BY DRIVER., REMOVE COVER FROM RECEIVER, IDENTIFY THE CHIP REQD, REMOVE OLD CHIP & INSTALL NEW., REMOVE OLD S/N LABEL & FIT LABEL TO MATCH NEW CHIP & KEY. INSTALL NEW KEY & FIT STICKER, TO REMOTE INSIDE BATTERY RECESS OF SPARE REMOTE, PROGRAM REMOTE TO RECEIVER &, TEST ALL FUNCTIONS ARE CORRECT, CLEAN REMOTE READY FOR USE. SUPPLY, DATE & PUT NEW, BATTERY INTO CHARGER., PO 177689 - EPV	CD - CUSTOMER DAMAGE
P19-W-019	ISUZU FRR600 LONG EWP	210632	25/11/2022 0:00	375829	CARRIED OUT 3MTH TOWER SERVICE, 1 X RUBBER BLOCK MISSING FROM UPPER BOOM REST, S & F NEW RUBBER BLOCK., PO 177650 - EPV	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	210362	23/11/2022 0:00	375882	CARRIED OUT MINOR TRUCK SERVICE, 10/11/22 - REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS, REPLACED PCV FILTER, GREASED., REPLACED WIPER BLADES, CHECKED BRAKES, CLUTCH & TYRES, ROAD TESTED., PO 177426 - EMA	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	209222	26/10/2022 0:00	369051	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, HV WET TESTS, PO 176153 - SETCO	ET - ELECTRICAL TEST
P19-W-019	ISUZU FRR600 LONG EWP	208230	21/09/2022 0:00	369051	CARRIED OUT MINOR TRUCK SERVICE, REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS, REPLACED WIPER BLADES., BRAKE THICKNESS CHECK - RHF 7MM, LHF 7MM, RHR 7.5MM, LHR 7.5MM, TYRE WEAR CHECK - RHF 6.69MM, LHF 6.64MM, RHR INNER 11.61MM OUTER 9.94MM, LHR INNER 11.20MM OUTER 9.25MM, CHECK TORQUE OF WHEEL NUTS & WNI ALIGNMENT., PO 175166 - EMA	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	205955	14/09/2022 0:00	363040	***CANCELLED - DUPLICATE - WORK DONE UNDER PO 172982 & WO 205957***, REPAIR AIR LEAKS, CONNTACTED BY JAMES CLARK DOWNER., CONTACT# 0409 182 821 EMA TO REPAIR MONDAY 25/7/22, PO 172974 - EMA	-
P19-W-019	ISUZU FRR600 LONG EWP	205957	31/08/2022 0:00	363378	REPLACED REAR PARK BRAKE WHEEL CYLINDERS, REPORT BRAKES NOT WORKING EFFECTIVELY, DRIVER REPORTS BRAKES FAILED WHILE DOING 60KMH, HAD TO PUMP UP BRAKES TO GET WORKING., VEHICLE TAGGED OUT ONSITE IN PAKENHAM. MARK FROM EMA #0409 093 941 WAS CONTACTED, VEHICLE TO BE TOWED, 22/7/22 - VEHICLE TOWED FROM PAKENHAM TO LILYDALE WORKSHOP, REINSTALLED REMOVED DRIVESHAFT (FOR TOWING), VEHICLE TAKEN TO INDEPENDENT BRAKE SPECIALIST FOR ROLLING BRAKE TEST., CARRIED OUT EXTENSIVE INSPECTION OF BRAKE SYSTEM & PARK BRAKE WHEEL CYLINDERS, PREPARED REPORT OF FINDINGS., REMOVED 2 X UNSERVICEABLE PARK BRAKE WHEEL CYLINDERS & FITTED NEW TO RHR & LHR. REASSEMBLED COMPONENTS AS PER SPECS., CARRIED OUT BRAKE BLEED OF SYSTEM, INSPECTED, ALL OK, ROAD TEST, TAKEN FOR ROLLING BRAKE TEST, ALL FOUND TO BE SATISFACTORY., PO 172982 - EMA	MR - MECHANICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	207149	22/08/2022 0:00	365114	CARRIED OUT 12MTH TOWER SERVICE INCL A/I & W/TEST, NOTE - CDD ROPES HAVE BEEN CHANGED FROM 3.5 TURNERS TO 2.5 BY EMA., PO 174054 - EPV	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	205328	22/07/2022 0:00	361802	CARRIED OUT MINOR TRUCK SERVICE & REPAIRS, 5/7/22 - REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS, GREASED, REPLACED WIPER BLADES, DIAGNOSTIC SCAN - NO CODES., COOLING SYSTEM NOT REACHING CORRECT OPERATING TEMPERATURE, REMOVED & REPLACED BOTH THERMOSTATS - FAULTY, REPLENISHED, COOLANT, TESTED COOLING SYSTEM, ALL OK., AIR LEAK FOUND WHEN PTO ENGAGED, FOUND A SMALL RUB THROUGH IN THE AIR LINE, REMOVED DAMAGED AIR LINE & FITTED NEW, TESTED, OK., DRIVERS SEAT BELT SHOWING A SMALL FRAY, REPAIRED, VEHICLE NOW TO SPEC FOR SAFETY., PO 172329 - EMA	PS - PLANNED SERVICE

P19-W-019	ISUZU FRR600 LONG EWP	205693	22/07/2022 0:00	363040	REPLACED AIR LINE TO REAR PARK BRAKE, AIR SUPPLY LINE X 2 TO THE REAR PARK BRAKE CHAMBER HAS RUBBED THROUGH, DRAINED PNEUMATIC SYSTEM, REMOVED DAMAGED, COMPONENTS, S & F NEW AIR LINE INTO POSITION, BUILD UP SYSTEM PRESSURE, CARRIED OUT FUNCTION & OPERATIONAL CHECK, ALL OK., CARRIED OUT LEAK DETECTION - NONE FOUND., PO 172709 - EMA	MR - MECHANICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	205060	04/07/2022 0:00	353950	AFTER HOURS CALL OUT TO TOW VEHICLE, CALL OUT TO BEACONSFIELD/EMERALD RD, GUYS HILL, VEHICLE BOGGED - TOWED TO SAFE GROUND., PO 172094 - EAGLE TOWING	CD - CUSTOMER DAMAGE
P19-W-019	ISUZU FRR600 LONG EWP	203524	30/05/2022 0:00	353950	CARRIED OUT 9MTH TOWER SERVICE, PO 170683 - EPV	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	201956	13/05/2022 0:00	349521	CARRIED OUT MINOR TRUCK SERVICE, 12/4/22 - REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS, AIR FILTER BLOWN OUT, GREASE, REPLACE WIPER BLADES., ISSUES WITH FUEL SUCTION CONTROL VALVE AND REAR BRAKES ACTIONED (ON OTHER INVOICES.), PO 168988 - EMA	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	202829	13/05/2022 0:00	349521	REPLACED FUEL SUCTION CONTROL VALVE, 12/4/22 - FUEL SUCTION CONTROL VALVE NOT WORKING, CARRIED OUT OBD DIAGNOSTIC, SHOWING INCORRECT FUEL FLOW,, CARRIED OUT INSPECTION, REMOVED & REPLACED WITH NEW UNIT, CARRIED OUT PROGRAMMING, CARRIED OUT, OPERATIONAL FUNCTION CONTROL, NOW FOUND SATISFACTORY., PO 168988 - EMA	MR - MECHANICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	202828	13/05/2022 0:00	349521	CARRIED OUT REAR BRAKE OVERHAUL, 12/4/22 - BRAKES FOUND TO BE WORN TO MAX LIMITS. REMOVED ALL WHEELS, REMOVED ALL BRAKE/WHEEL HUBS,, INSPECTED BRAKE COMPONENTS, OK, WASHED/CLEANED & INSPECTED WHEEL BEARINGS, OK, ORGANISE BRAKE, COMPANY TO COLLECT BRAKES FOR OVERHAUL, RECEIVE DRUMS & CLEAN, PREP REAR DRUM, ZERO REAR BRAKE, ADJUSTORS, INSTALL ALL LININGS, ENSURE ABS SENSORS AREN'T PUSHED TOO FAR IN, USE NEW SPLIT PINS,, ASSEMBLE REAR BEARINGS TO SPEC, INSTALL AXLE, WHEELS & TORQUE TO SPEC, ADJUST REAR BRAKES, PACK, NEW BEARINGS & INSTALL TO FRONT, ASSEMBLE, INSTALL & PRE-LOAD TO SPEC, NEW HUB SEALS, INSTALL WHEELS, & ADJUST BRAKES, TORQUE WHEELS TO SPEC, TEST DRIVE & BED BRAKES IN, TAKE VEHICLE FOR INDEPENDENT, BRAKE ROLL TEST & INSPECTION - ALL FOUND OPERATIONAL/SATISFACTORY., PO 168988 - EMA	MR - MECHANICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	202395	09/05/2022 0:00	345856	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, HV WET TESTS, PO 169386 - SETCO	ET - ELECTRICAL TEST
P19-W-019	ISUZU FRR600 LONG EWP	199591	12/04/2022 0:00	341187	REPLACED SWITCHES & HANDBRAKE ALARM, 10/2/22 - CABIN ALARM - OPERATOR REFUSES TO USE VEHICLE DUE TO LOW TONE ALARM., COLLECT VEHICLE FROM BEACONSFIELD & RETURN TO WORKSHOP, CARRY OUT DIAGNOSIS,, CARRY OUT TROUBLESHOOTING, REPLACED BOTH BROKEN DOOR SWITCHES, ALARM STILL, GOING OFF, SPEAK WITH MANUFACTURER RE POSSIBLE FAULT, RECOMMENDED FAULTS IN, AIR TANK LOW PRESSURE SWITCHES, DROP AIR PRESSURE, REMOVE SWITCHES, REPLACED, ALL LOW WARNING TANK SENSORS, START VEHICLE & BUILD AIR PRESSURE, ALARM STOPPED, BUZZING, RETURN VEHICLE TO DEPOT., 11/2/22 - ALARM GOING OFF AGAIN, FIND FAULT WITH REDARC HANDBRAKE ALARM, REPLACED, WITH NEW, NOW SATISFACTORY., PO 166430 - EMA	ER - ELECTRICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	200309	25/03/2022 0:00	342131	REPAIRED CRACKS IN BASKET FLOOR, REPAIR CRACKED BASKET FLOOR, DAMAGE IN THE CENTRE ON THE RADIUS HAS BROKEN THROUGH & FLOOR MOVES SLIGHTLY., HAS HAD GELCOAT APPLIED TO SEAL BUT NO STRUCTURAL REPAIRS, PO 167190 - EPV	GR - GENERAL REPAIRS
P19-W-019	ISUZU FRR600 LONG EWP	200971	23/03/2022 0:00	345856	REPLACED 4 DRIVE TYRES - POS 3/4/5/6, 4 X 235/75R17.5 SP 442 132/130M TL, PO 167902 - BEAUREPAIRES DANDENONG	TC - TYRE CHANGE/REPLACEMENT
P19-W-019	ISUZU FRR600 LONG EWP	199913	25/02/2022 0:00	342131	MULTIPLE COVERS BROKEN AND MISSING, MARK UP COVERS & DRILL & TAP TO SUIT M10 NYLON BOLTS, INSTALL NEW COVERS WITH NEW BOLTS., PO 166772 - EPV	CD - CUSTOMER DAMAGE
P19-W-019	ISUZU FRR600 LONG EWP	200093	25/02/2022 0:00	342131	CARRIED OUT 6MTH TOWER SERVICE INCL WEIGHT TEST, PO 166973 - EPV	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	198524	18/02/2022 0:00	338024	REPAIRED HEAD UNIT, 14/01/22 - NO RADIO, NIL SOUND, RADIO NOT WORKING, INSPECT & CARRY OUT UNIT RESET, REMOVED RH DOOR TRIM, CARRIED OUT SPEAKER INSPECTION,, POWER AT SPEAKER, REPLACED SPEAKER - STILL NO SOUND, REINSTALLED OLD SPEAKER & DOOR TRIM, REMOVED DASH TRIM & HEAD UNIT, SEND AWAY, FOR REPAIRS. INSTALLED REPAIRED HEAD UNIT, SET CAMERA SETTINGS, CARRIED OUT OPERATIONAL TEST, ALL OK., PO 165009 - EMA	BE - BREAKDOWN - ELECTRICAL
P19-W-019	ISUZU FRR600 LONG EWP	199372	18/02/2022 0:00	340827	CARRIED OUT MINOR TRUCK SERVICE, 04/02/22 - REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS, REPLACED PCV KIT, TOPPED UP COOLANT, GREASED, REPLACED WIPER BLADES,, CARRIED OUT DIAGNOSTIC SCAN, BRAKE & CLUTCH ADJUSTMENT., PO 166198 - EMA	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	198239	01/02/2022 0:00	336085	CARRIED OUT MINOR TRUCK SERVICE & REPAIRS, REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTER & AIR FILTER, REPLACED WIPER BLADES, GREASED., LH BEAN OUT, BLOWN BULB, REPLACED GLOBE. REPLACED GREASE NIPPLE ON LH SPRING. COOLANT LEAK, TIGHTENED, RADIATOR HOSES. BRAKE & CLUTCH ADJUSTMENT, CLEAN & INSPECT MAF SENSOR., PO 165009 - EMA	PS - PLANNED SERVICE

P19-W-019	ISUZU FRR600 LONG EWP	196480	01/12/2021 0:00	320347	REPLACED WINDSCREEN, FIT REPLACEMENT, TRANSFER SERVICE STICKERS., PO 163126 - EMA	CD - CUSTOMER DAMAGE
P19-W-019	ISUZU FRR600 LONG EWP	194082	01/12/2021 0:00	311452	REPLACED DAMAGED LH OUTER RIM, 7/9/21 - LH OUTER RIM DAMAGED, STRIPPED TYRE FROM RIM TO INSPECT, UNABLE TO REPAIR DAMAGE, ORDER REPLACEMENT., FIT SPARE TYRE TO LH OUTER POSITION & TORQUE WHEEL NUTS TO SPEC, HAVE TYRE FITTED TO NEW RIM, PICK UP FROM, LILYDALE & RETURN TO WORKSHOP, REMOVE LH OUTER & INSTALLED ORIGINAL TYRE TO POSITION, TORQUE WHEEL NUTS, TO SPEC, REPLACED DAMAGED WNI WITH NEW, REINSTALLED SPARE TO POSITION, RETURN TO LILYDALE YARD., PO 160455 - EMA	CD - CUSTOMER DAMAGE
P19-W-019	ISUZU FRR600 LONG EWP	196280	01/12/2021 0:00	324185	CARRIED OUT BRAKE INSPECTION, TRAVEL TO DEPOT, CARRIED OUT BRAKE INSPECTION - FWD BRAKES 4MM, REAR BRAKES 6MM. ADJUSTED AS REQ'D., PO 162912 - EMA	MR - MECHANICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	194923	30/11/2021 0:00	318001	***CANCELLED - NO INVOICE RECEIVED FOR THIS JOB***, RH DOOR DAMAGED, REQUIRES REPLACEMENT, PO 161408 - EMA	CD - CUSTOMER DAMAGE
P19-W-019	ISUZU FRR600 LONG EWP	196687	22/11/2021 0:00	328343	CARRIED OUT 3MTH TOWER SERVICE & REPAIRS, PIN COVER MISSING ON INSIDE OF LOWER BOOM AT FRONT KNUCKLE, S & F NEW PIN COVER USING SILICON., PIN COVER ON OUTSIDE OF UPPER BOOM AT KNUCKLE MISSING & NYLON BOLT IS BROKEN, SOURCE NEW COVER & INSTALL ONCE, IN STOCK. COVER ON LOWER BOOM AT THE TURRET PIN BROKE, SOURCE NEW COVER & FIT ONCE IN STOCK., PO 163338 - EPV	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	194924	12/11/2021 0:00	320347	REPAIRED DPD SYSTEM, 29/9/21 - ENGINE LIGHT ON, CARRY OUT SCAN, DPD FORCED BURN BUT SYSTEM WON'T GET UP TO TEMP, SUSPECT DPD FILTER, BLOCKED, REMOVED DPD PROBES, CLEAN & REFIT, CARRY OUT FORCED BURN, STILL SAME RESULT, SUSPECT #4 INJECTOR, MEASURING UP TOO HIGH., 4/10/21 - TEMP ISSUE, ALLOW VEHICLE TO GET TO REQD TEMP, THERMOSTAT NOT OPENING, DPD SYSTEM FILTER BLOCKED,, DRAINED COOLING SYSTEM, CARRY OUT IAW MAINTENANCE MANUAL REPLACEMENT OF THERMOSTATS, REPLENISHED COOLANT, WITH NEW, RUN VEHICLE TO TEMP, LEAK CHECK CARRIED OUT, NIL LEAKS, NOW SATISFACTORY., REPLACED LH DOOR SEAL WITH NEW., 5/10/21 - REMOVED DPD FILTER, DISASSEMBLE, CARRY OUT COLD CHEMICAL WASH, SOAK FOR 8 HRS, FLUSH WITH FRESH, WATER, BLOW DRY ASSEMBLY & REASSEMBLE, REINSTALL DPD FILTER TO EXHAUST SYSTEM, START VEHICLE & BUILD TEMP,, CARRY OUT BURN, CARRY OUT ODB SCAN, NIL FAULT CODES, OK., PO 161408 - EMA	MR - MECHANICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	196332	12/11/2021 0:00	320347	REPLACED 4 DRIVE TYRES, ALL DRIVE TYRES FOUND UNROADWORTHY, REMOVE WHEELS, STRIP & FIT NEW TYRES, REINSTALL WHEELS, TORQUE WHEEL, NUTS TO SPEC, FIT WNI., PO 161408 - EMA	TC - TYRE CHANGE/REPLACEMENT
P19-W-019	ISUZU FRR600 LONG EWP	195863	04/11/2021 0:00	318001	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, HV WET TESTS, PO 162444 - SETCO	ET - ELECTRICAL TEST
P19-W-019	ISUZU FRR600 LONG EWP	193766	30/09/2021 0:00	316030	REPAIRED FRONT BRAKES & OTHER ITEMS, REPAIR ITEMS FOUND DURING TRUCK SERVICE. REMOVE WHEELS, WHEEL BEARINGS & HUB ASSEMBLY, REMOVE GREASE FROM HUBS, READY FOR DRUMS TO BE MACHINED, REMOVE BRAKE LINERS, REASSEMBLED FRONT BRAKES, BLED FRONT BRAKES, TEST DRIVE, OK., FLOOR MATS REPLACED. SEAT COVER TORN & DAMAGED, REPLACED WITH NEW., PO 160056	MR - MECHANICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	193765	30/09/2021 0:00	316030	CARRIED OUT 315KM SERVICE, REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS, AIR FILTER BLOWN OUT, REPLACED WIPER BLADES, BRAKE & CLUTCH, ADJUSTMENT, TOP UP FLUIDS WHERE REQD, GREASED, REMOVE MAF SENSOR, CLEAN & INSPECT, TEST PARK BRAKE., PO 160056	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	194592	23/09/2021 0:00	318001	REFIT PIN COVER AFTER BEING KNOCKED OFF, REMOVE BROKEN BOLT & REFIT COVER WITH NEW NYLON BOLT, PO 161028 - EPV	CD - CUSTOMER DAMAGE
P19-W-019	ISUZU FRR600 LONG EWP	193661	10/09/2021 0:00	315462	SUPPLY & REPLACE REMOTE BATTERIES, REMOTE ISSUES, INSPECTION CARRIED OUT, REMOTE BATTERIES NOT HOLDING CHARGE, S & F BATTERIES,, CARRY OUT FUNCTIONAL TEST, OK., PO 159910 - EMA	ER - ELECTRICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	192657	31/08/2021 0:00	311452	REPLACED 2 DRIVE TYRES - POS 3 + 5, 2 X 235/75R17.5 SP442, 132/130M TL, PO 158708 - BEAUREPAIRES DANDENONG	TC - TYRE CHANGE/REPLACEMENT
P19-W-019	ISUZU FRR600 LONG EWP	193358	25/08/2021 0:00	312829	CARRIED OUT 12MTH TOWER SERVICE INCL A/I & W/TEST, ONLY ONE BANK OF LED'S WORKING IN D/S CAB STROBE LIGHT, REMOVE ROOF BAR TO ACCESS, ONE OF THE STROBE LIGHT MOUNTING BOLTS, REMOVED LED STROBE & WIRED IN NEW LIGHT,, PROGRAM FLASH PATTERN TO MATCH P/S, MOUNTED NEW LIGHT, WHEN BOLTS TIGHTENED LIGHT, STOPPED WORKING, FOUND GROUND WIRE HAD PULLED OUT OF JOINER, REPAIRED & MOUNTED LIGHT., POWER LINE EXCLUSION DISTANCE DECAL FADED & UNREADABLE FROM BASKET, REMOVED,, CLEANED AREA & REPLACED DECAL., "LV COVER" DECALS ON BOOMS FADED TO WHITE, S & F ALL 4 DECALS TO BOOMS., "UNINSULATED" DECALS ON TURRET HAVE FADED TO WHITE, S & F DECALS & TRIMMED TO SUIT PLACEMENT., PO 159506 - EPV	AS - ATTACHMENT SERVICES

P19-W-019	ISUZU FRR600 LONG EWP	193359	25/08/2021 0:00	312829	REPAIRED GEL COAT CHIPS ON BOOMS & BASKET, CLEANED ALL AFFECTED AREAS WITH ACETONE, APPLIED COAT OF GEL COAT & RESIN TO ALL AFFECTED AREAS,, ALSO APPLIED TO DAMAGED AREA TO SEAL OUT MOISTURE UNTIL REPAIR CAN BE COMPLETED., PO 159506 - EPV	CD - CUSTOMER DAMAGE
P19-W-019	ISUZU FRR600 LONG EWP	192058	24/08/2021 0:00	309162	S & F i-ARS UNIT, PO 158036 - EMA, AUTHORISED BY SIMON LEECH 14/7/21	AR - ADDITIONAL WORK
P19-W-019	ISUZU FRR600 LONG EWP	192148	24/08/2021 0:00	309162	CARRIED OUT TRUCK SERVICE, REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS, AIR FILTER BLOWN OUT, REPLACED WIPER BLADES &, TOPPED UP WASHER BOTTLE, BRAKE & CLUTCH ADJUSTMENT, REMOVE MAF SENSOR, CLEAN & INSPECT, ROAD TEST., PO 158110 - EMA	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	192149	24/08/2021 0:00	309162	REPLACED REAR SPRINGS, REAR SPRINGS FATIGUED & DAMAGED - VEHICLE RESTING ON SPRING OVER RIDES, SPRING PACK FOUND INVERTED., JACK UP VEHICLE TO INSPECT FURTHER, EXCESSIVE MOVEMENT FOUND IN FORWARD MOUNTING PINS & BUSHES,, EXCESSIVE WEAR DAMAGE & FATIGUE FOUND ON TOP SPRING LEAFS - LH & RH WHERE SPRING PACK HAS BEEN, CONSTANTLY RESTING ON SPRING OVER RIDES. REMOVE WHEELS, REMOVE LH & RH SPRING PACKS, PREPPED, NEW SPRINGS, INSTALLED HANGARS TO NEW SPRINGS, REPLACED ALL HARDWARE WITH NEW, INSTALLED SPRINGS,, TIGHTEN & TORQUE HARDWARE TO SPEC, CARRY OUT TEST DRIVE & RE-TORQUE HARDWARE., PO 158110 - EMA	MR - MECHANICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	192065	24/08/2021 0:00	309162	BASKET CONTROL UNIT FIT OUT, INSTALLATION OF REMOTE HOLDER. FIT TOWER REMOTE CRADLE TO LH TOOLBOX, RUN LOOM FROM TOOLBOX, TO CAB, SECURE ALL WIRING, SECURE EARTH TO CAB UNDER DASH, RUN WIRING TRIGGER TO PARK BRAKE, SWITCH, FIT FUSE MINI PIGGY BACK FUSE TO FUSE BOX, FIT SENSOR PAD TO REMOTE, FIT SENSOR TO, CRADLE BOX & ADJUST., PO 158045 - EMA, APPROVED BY SIMON LEECH 14/7/21	ER - ELECTRICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	190653	11/06/2021 0:00	302540	REPLACED DAMAGED RUBBER BOOT ON JOYSTICK, POSSIBLE WATER DAMAGE TO REMOTE, RUBBER BOOT ON JOYSTICK DAMAGED ENABLING WATER TO ENTER, REPLACED BOOT, & CLEANED OUT REMOTE, TEST., PO 156614 - SHERRIN RENTALS	CD - CUSTOMER DAMAGE
P19-W-019	ISUZU FRR600 LONG EWP	190481	08/06/2021 0:00	302540	REPLACED STEER TYRES AND BALANCED, 2 X 235/75R17.5 SP 341 132/130M TL, PO 156401 - BEAUREPAIRES DANDENONG	TC - TYRE CHANGE/REPLACEMENT
P19-W-019	ISUZU FRR600 LONG EWP	190141	28/05/2021 0:00	298859	CARRIED OUT 9MTH TOWER SERVICE & REPAIRS, LEVEL CYLINDER, BASKET & BOOM TIP HAVE MULTIPLE GELCOAT CHIPS, CLEANED AREAS & APPLIED A COAT OF GELCOAT, RESIN MIX TO AFFECTED AREAS. LEVEL CYLINDER COVER HAS BROKEN NYLON BOLT, DRILLED & TAPPED OUT BROKEN BOLT,, REFITTED COVER WITH NEW NYLON BOLT. FACE DECAL COMING OFF THE ARROWBOARD CONTROLLER, GLUED FACE BACK DOWN., PO 156041 - EPV	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	188966	05/05/2021 0:00	187871	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, BUCKET LINER TEST, PO 154730	ET - ELECTRICAL TEST
P19-W-019	ISUZU FRR600 LONG EWP	187837	06/04/2021 0:00	187871	SUPPLIED LHF INDICATOR GLOBE TO DRIVER TO FIT, PO 153528 - EPV	ER - ELECTRICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	186987	11/03/2021 0:00	187871	CARRIED OUT 12MTH WINCH SERVICE INCL WEIGHT TEST, LIFT UP LOCKER DOORS, THE GAS STRUT MOUNTING PINS ARE ALL LOOSE, TIGHTENED ALL MOUNTING PINS & ROD END CLEVISSES ONTO THE, ROD., PO 152608 - EPV	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	186989	11/03/2021 0:00	287871	REPLACED BROKEN BOLTS, REPAIR CUST DAMGED FOUND DURING 6MTH TOWER SERVICE. ALL NYLON BOLTS IN UPPER BOOM END COVER AROUND EXTENSION BOOM, BROKEN, DRILLED OUT & TAPPED OUT BROKEN BOLTS, REFITTED COVER WITH NEW NYLON BOLTS., PO 152608 - EPV	CD - CUSTOMER DAMAGE
P19-W-019	ISUZU FRR600 LONG EWP	185929	23/02/2021 0:00	284856	REPLACED SPRING PACKS, HANGERS & SHACKLES, FRONT SUSPENSION & CHASSIS HANGERS & HANGER SWAY BAR BUSHES, REMOVE WHEELS & SWAY BAR, PUSH OUT BUSHES & PREP, REMOVE UNSERVICEABLE LEAF SPRINGS & HANGER, REMOVE FRONT CHASSIS, HANGER, GRIND OFF REAR OF FRONT LEAF SPRING CHASSIS HANGER - RIVETED IN, INSTALL IN REVERSE, INSERT NEW SWAY BAR BUSHES, FRONT & REAR (OF FRONT LEAF SPRING) HANGERS, BOLT ON & TORQUE TO SPEC, LUBE NEW LEAF SPRING PINS & BUSH, PUT WHEEL BACK, ON & LOWER VEHICLE, TORQUE WHEEL NUTS TO SPEC, TORQUE U BOLTS, LEAF SPRING BUSH PIN NUTS & CHASSIS HANGERS, TORQUE CHECK, SEAL ALL, TEST DRIVE & SETTLE SUSPENSION, SENT FOR ALIGNMENT AFTER SERVICE., PO 151459 - EMA, AUTH AS PER EMAIL FROM SIMON LEECH 5/2/21	MR - MECHANICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	185488	29/01/2021 0:00	283907	REPLACED 2 MISSING COVERS, S & F NEW COVERS WITH NEW NYLON BOLTS, PO 150995 - EPV	GR - GENERAL REPAIRS
P19-W-019	ISUZU FRR600 LONG EWP	183288	26/11/2020 0:00	274484	CARRIED OUT 3MTH TOWER SERVICE, PO 148721 - EPV	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	182297	02/11/2020 0:00	261609	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, HV WET TESTS, TRAVEL, PO 147634 - SETCO	ET - ELECTRICAL TEST

P19-W-019	ISUZU FRR600 LONG EWP	179513	27/08/2020 0:00	261609	CARRIED OUT 12MTH TOWER SERVICE INCL A/I & W/TEST, GELCOAT WORN THROUGH ON THE EXTENSION BOOM IN SEVERAL, LOCATIONS, APPLIED GELCOAT RESIN MIX AS IT MORE DURABLE, GELCOAT ALONE,, GELCOAT WORN THROUGH THE UPPER BOOM AT THE BOOM REST,, APPLIED A GELCOAT RESIN MIX,, UPPER BOOM CYLINDER COVERS HAVE SEVERAL CHIPS IN GATHERING, GELCOAT EXPOSING THE FIBREGLASS, APPLIED GELCOAT RESIN MIX., BASKET ROTATOR COVER HAS BROKEN NYLON BOLTS, DRILLED &, TAPPED OUT BROKEN BOLTS & REFITTED COVER WITH NEW NYLON, BOLTS., LEVELING MASTER CYLINDER COVER HAS 1 BROKEN NYLON BOLT,, WHILE REMOVING COVER ANOTHER BOLT BROKE, DRILLED & TAPPED, OUT BOTH BOLTS & FITTED WITH NEW., UPPER BOOM CYLINDER COVER HAS A BROKEN NYLON BOLT, DRILLED &, TAPPED OUT BOLT & REFITTED WITH NEW., SILICON AROUND LV COVER AT BOOM TIP TO EXTENSION BONDING, POINT, CUT AWAY THE PEELING SILICON & CLEANED BOTH SURFACES,, THEN APPLIED NEW SIKAFLEX & SMOOTHED & CLEANED AREA., HYDRAULIC OIL LEAK FROM AROUND BASKET TILT VALVE AT BASKET,, REMOVED COVER, CLEANED AREA WITH BRAKE CLEANER & CHECKED, ALL FITTINGS, FOUND SEVERAL LOOSE, TIGHTENED FITTINGS &, OPERATED, NO SIGNS OF LEAKS, CHECKED OTHER FUNCTIONS ON THE, VALVE BANK & FOUND ALL TO BE OK, REPLACED COVERS., PO 144917 - EPV	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	175176	05/06/2020 0:00	250152	CARRIED OUT TRUCK "A" SERVICE, ENGINE OIL & OIL FILTER. INCL TRAVEL FROM BEACONSFIELD YARD., PO 141304 - EPV	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	175196	05/06/2020 0:00	250152	CARRIED OUT 9MTH TOWER SERVICE, PO 141304 - EPV	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	173672	14/05/2020 0:00	239567	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, BUCKET LINER TEST & TRAVEL, PO 139979	ET - ELECTRICAL TEST
P19-W-019	ISUZU FRR600 LONG EWP	170468	25/02/2020 0:00	239567	CARRIED OUT 6MTH TOWER SERVICE INCL WEIGHT TEST, CLEANED THE TELE BOOM., PO 137077 - EPV	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	166565	02/12/2019 0:00	222341	CARRIED OUT 3MTH TOWER SERVICE & REPAIRS, CLEANED THE TELE BOOM. REPLACED BROKEN OR MISSING NYLON, BOLTS ON COVERS. EMERGENCY PUMP HANDLE MISSING, CHECKED, REGULAR LOCATION, LOCATED, CHECKED ALL, LABELLED TURNED RE, HANDLE LOCATION. RUST MARKS ON TURRET FROM PINS, ETC., CLEANED RUST MARKS OFF, LUBRICATED ALL PINS, PIVOTS, ETC., PO 133250 - EPV	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	165134	18/11/2019 0:00	213354	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, HV WET TESTS + TRAVEL, PO 131724 - SETCO	ET - ELECTRICAL TEST
P19-W-019	ISUZU FRR600 LONG EWP	163253	25/09/2019 0:00	213354	CHECKED GEARBOX WARNING LIGHT COMING ON, CHECKED DTC P0407, NOT PRESENT, REQUIRES FURTHER, INVESTIGATION., PO 130003 - PATTERSON CHENEY	BM - BREAKDOWN - MECHANICAL
P19-W-019	ISUZU FRR600 LONG EWP	162590	19/09/2019 0:00	211239	CARRIED OUT 12MTH TOWER SERVICE INCL A/I & W/TEST, BASKET RETAINER BOLTS LOOSE, TIGHTENED & SEALED. CLEAR, RUBBISH FROM CONTROLS. CLEANED RUBBISH FROM TURRET., PO 129332 - EPV	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	162750	03/09/2019 0:00	201626	R#BUS011893033	RE - REGISTRATION
P19-W-019	ISUZU FRR600 LONG EWP	159886	30/07/2019 0:00	201626	REPLACED LOST REMOTE CONTROL WITH NEW UNIT, PO 126865 - SHERRIN	GR - GENERAL REPAIRS
P19-W-019	ISUZU FRR600 LONG EWP	159743	08/07/2019 0:00	201626	FITTED TWO NEW BATTERIES, MOTOR HAS BEEN HARD TO START, NOW IT WON'T START, TESTED THE, BATTERIES, ONE FAULTY & OTHER POOR, ORGANISED NEW BATTERIES, & PICKED UP, CLEANED THE CARRIER, FITTED NEW BATTERIES,, STARTED & CHECKED THE CHARGE RATE, OK., PO 126748	BE - BREAKDOWN - ELECTRICAL
P19-W-019	ISUZU FRR600 LONG EWP	158023	03/06/2019 0:00	196906	CARRIED OUT TRUCK "A" SERVICE, REPLACED 2 BADLY TORN REAR WHEEL MUDFLAPS, PO 125397	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	158024	03/06/2019 0:00	196906	CARRIED OUT 9MTH TOWER SERVICE, PO 125400	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	155431	02/05/2019 0:00	186133	ELECTRICAL TEST, PO 123185, CARRIED OUT ELECTRICAL TEST, HV DRY TEST, HV WET TESTS., PO 123185	ET - ELECTRICAL TEST
P19-W-019	ISUZU FRR600 LONG EWP	155769	29/04/2019 0:00	186133	AIR SUSPENSION SEAT SHOULDER/GAS STRUT IS FAULTY, PO 123460, FITTED NEW AIR SUSPENSION SEAT SHOCKER, AIR SUSPENSION SEAT SHOCKER/GAS STRUT IS FAULTY, INSPECTED,, CHECKED CONTROLS, AIR HOSES, SWITCHES, ETC, LOCATED WEEPING, SHOCKER/GAS STRUT IN THE SEAT, ORDERED & PICKED UP NEW ONE,, TRAVELLED TO BEACONSFIELD, FITTED & TESTED NEW SHOCKER,, CONFIRMED WITH THE DRIVER ALL OK., PO 123460	HR - HYDRAULIC REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	154868	11/04/2019 0:00	186133	6MTH TOWER SERVICE AND WEIGHT TEST, PO 122729, CARRIED OUT 6MTH TOWER SERVICE INCL WEIGHT TEST, PO 122729	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	154759	02/04/2019 0:00	186133	REPLACE 4 TYRES, PO 122615 - BRIDGESTONE DOVETON, REPLACED 4 TYRES - POS 5/6/7/8, 4 X 235/75R17.5 132/130M BS M716, PO 122615	TC - TYRE CHANGE/REPLACEMENT
P19-W-019	ISUZU FRR600 LONG EWP	154680	28/03/2019 0:00	174224	TOP BOOM RAM COVERS BROKEN, PO 122569, REPAIRED DAMAGED TOP BOOM RAM COVERS, INSPECTED DAMAGE, LOCATED PART #, ORGANISED NEW COVERS &, COLLECTED, FITTED & CHECKED THE FIT OF THE COVERS, OK., PO 122569	CD - CUSTOMER DAMAGE
P19-W-019	ISUZU FRR600 LONG EWP	149226	12/12/2018 0:00	166745	COMPLETED 3 MTH TOWER SERVICE, CLEANED THE BOOMS,, REPLACED COVER BOLTS & REMOVED BROKEN PIECES., 3 MONTH TOWER SERVICE, PO 117747	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	148767	12/12/2018 0:00	157339	REPLACED 2 X STEER TYRES, PO 117323	TC - TYRE CHANGE/REPLACEMENT

P19-W-019	ISUZU FRR600 LONG EWP	149227	12/12/2018 0:00	166745	COMPLETED "B" SERVICE. REPLACED AIR CLEANER ELEMENTS., COOLANT LOW SO PRESSURE TESTED, TIGHTENED LOOSE CLAMPS., TOPPED UP, CHECKED AND ADJUSTED. ORGANISED BEAUREPAIRS TO, FIT 2 FRONT TYRES. REPLACED THE PCC BREATHER ELEMENT., REPLACED WIPER BLADES. RH TAIL LIGHT PROTECTIVE BRACKETS, BENT, BOLTS MISSING, STRAIGHTENED & REPLACED BOLTS., NEEDS REAR BRAKES RELINING, NEED TO ORGANISE WITH ADAM., TRUCK "B" SERVICE, PO 117748	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	147816	03/12/2018 0:00	162623	REPAIRED HYDRAULIC OIL LEAK, OIL LEAK FROM TURRET AREA, OPERATE PTO AND INSPECT INSIDE, TURRET, HIGH VOLUME LEAK. - REMOVED TURRET COVER, WHEN, OPERATING LEAKS & TOWER. FOUND OIL LEAKING FROM MAIN, PRESSURE BLOCKED. LOWER BLANK PLUG LEAKING., LARGE AMOUNT OF HYDRAULIC OIL ALL OVER TRAY / DECK AREA -, REMOVED PLUG, RESEALED PLUG. REFITTED TESTED OPERATION, PERFECT. WASHED INSIDE TURRET & SURROUNDS. TOPPED UP, HYDRAULIC OIL 10Litres, P/O 116459	BH - BREAKDOWN - HYDRAULIC
P19-W-019	ISUZU FRR600 LONG EWP	147131	08/11/2018 0:00	155911	REPAIRED ROOF MOUNTED WORK LIGHTS., CHECKED ALL LIGHTS WIRING ETC. LOCATED AND REPAIRED, DAMAGED WIRING, REPLACED THE BLOWN FUSE. TESTED. OK, P/O 115847	ER - ELECTRICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	146056	05/11/2018 0:00	157339	REPLACED 2x LHS TYRES POSITION 5/6, 1x TYRE REPLACED DUE TO PUNCTURE, 1x WORN, PO#114808	TC - TYRE CHANGE/REPLACEMENT
P19-W-019	ISUZU FRR600 LONG EWP	146783	01/11/2018 0:00	157339	REPLACED BASKET COVER., P/O 115502	CD - CUSTOMER DAMAGE
P19-W-019	ISUZU FRR600 LONG EWP	145632	01/10/2018 0:00	149008	COMPLETED 12M SERVICE, WEIGHT TEST & ANNUAL INSPECTION, REPLACED HYDRUALIC & WATER FILTERS., 3rd ARROW BOARD SEGMENT IS BROKEN - ORDERED & PICKED UP, PART. REMOVED WHOLE ARROW BOARD TO ACCESS AND CHANGED THE, SEGMENT. OK. TESTED OK, LOCKER REMOTE SWITCH IS COMING OUT OF THE DASH - REFITTED, SECURED., P/O 114402	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	144675	07/09/2018 0:00	148365	R#WEB007150625, POSTED DOWNER, ATT: CLAIRE BENDALL, PO BOX 4993, MELBOURNE 3001	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	144728	03/09/2018 0:00	148365	COMPLETED 6m WET & DRY ELECTRICAL TESTS, P/O 113462	ET - ELECTRICAL TEST
P19-W-019	ISUZU FRR600 LONG EWP	143649	17/08/2018 0:00	148365	REPLACED WORN REAR TYRES, REPLACED LHR OUTER & RHR INNER. BOTH NEW TYRES ARE IN RHR, POSITIONS., P/O 112423	TC - TYRE CHANGE/REPLACEMENT
P19-W-019	ISUZU FRR600 LONG EWP	143398	14/08/2018 0:00	147506	REPAIRED PUNCTURED TYRE, P/O 112211	TP - PUNCTURE REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	139104	01/06/2018 0:00	140418	COMPLETED 140,000km 'A' SERVICE., REPLACED ENGINE OIL & FILTER. ADJUSTED BELTS., INSPECTED DRIVELINE & CHASSIS. GREASED. ADJUSTED, PARK BRAKE. CHECKED OVER., P/O 108869	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	139105	01/06/2018 0:00	140418	COMPLETED 9m TOWER SERVICE, P/O 108870	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	137597	04/05/2018 0:00	125373	COMPLETED HV WET & DRY TESTING, PO#107607	ET - ELECTRICAL TEST
P19-W-019	ISUZU FRR600 LONG EWP	134660	01/03/2018 0:00	125373	REPLACED RH LOW BEAM BLOWN HEADLIGHT GLOBE, CHECKED ALL LIGHTS. OK, PO#105223	ER - ELECTRICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	133789	01/03/2018 0:00	117359	COMPLETED 120,000km SERVICE. REPLACED ENGINE OIL & FILTER, REPLACED FUEL, PCV & AIR FILTERS. ADJUSTED BELTS. REPLACED, BELTS CONDITION. REPLACED GEARBOX, DIFF AND TRANSMISSION, OILS. ADJUSTED BRAKES & PARK BRAKE., BRAKES: FRONT AND REAR 45mm, REPLACED WIPER INSERTS., PICKED UP TRUCK AT DOVETON AS PER CUSTOMER REQUEST., PO#104456	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	103368	01/03/2018 0:00	117359	COMPLETED 6m TOWER SERVICE & WEIGHT TEST, TOPPED UP HYDRAULIC OIL., DEGREASED AND STEAM CLEANED THE TURRET, TRAY ETC, PO#104424	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	133774	16/02/2018 0:00	123728	REPLACED 4x TYRES 5,6,7 & 8, TYRES 5 & 6 WERE SWAPPED TO 1 & 2. BALANCED STEER TYRES., PO#104428	TC - TYRE CHANGE/REPLACEMENT
P19-W-019	ISUZU FRR600 LONG EWP	134217	15/02/2018 0:00	117359	COMPLETED 6 MONTH ELECTRICAL TEST, P/O 104870	ET - ELECTRICAL TEST
P19-W-019	ISUZU FRR600 LONG EWP	127749	01/02/2018 0:00	97140	CHECKED FAULT CODES. NOT CHARGED FOR PROCEDURE, PO#99501	ER - ELECTRICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	132204	19/01/2018 0:00	117359	REPLACED BLOWN HEADLIGHT GLOBE, PO#103238	ER - ELECTRICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	131520	09/01/2018 0:00	116189	REPLACED DAMAGED TYRE, P/O 102723	TD - REPLACEMENT OF DAMAGED TYRE
P19-W-019	ISUZU FRR600 LONG EWP	128749	02/01/2018 0:00	102096	REPLACED WORN TYRE. ROTATED WITH SPARE., P/O 100458	TC - TYRE CHANGE/REPLACEMENT
P19-W-019	ISUZU FRR600 LONG EWP	130677	14/12/2017 0:00	111029	REPLACED 2x WORN DRIVE TYRES, P/O 102040	TC - TYRE CHANGE/REPLACEMENT
P19-W-019	ISUZU FRR600 LONG EWP	129851	01/12/2017 0:00	106456	COMPLETED 3m TOWER SERVICE, REPLACED FAULTY STABILISER LEG ENGAGED LIGHTS., PO#101445	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	129676	01/12/2017 0:00	104718	COMPLETE 105,000km SERVICE. REPLACED ENGINE OIL & FILTER., LUBRICATED ALL POINTS & PIVOTS. REPLACED FUEL FILTERS &, CLEANED WATER TRAP. CHECKED TYRE PRESSURES. ADJUSTED BRAKES, HAND & FOOT. ADJUSTED CLUTCH. DRAINED AIR TANKS. TIGHTENED, MANIFOLDS & EXHAUST SYSTEM. SERVICED AIR CLEANER., PO#101314	PS - PLANNED SERVICE

P19-W-019	ISUZU FRR600 LONG EWP	126371	01/12/2017 0:00	81928	COMPLETED 75,000km SERVICE. REPLACED ENGINE OIL & FILTER, LUBED ALL POINTS & PIVOTS. REPLACED FUEL FILTERS & CLEANED, WATER TRAP. CHECKED TYRE PRESSURES. ADJUSTED BRAKES, HAND, & FOOT. ADJUSTED CLUTCH. DRAINED AIR TANKS. TIGHTENED, MANIFOLDS & EXHAUST SYSTEM . REPLACED RH HEADLIGHT SPLIT, COVER. PLACED LH COVER BEHIND CAB SEAT. REPLACED WIPER, INSERTS., P/O 98300	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	129657	27/11/2017 0:00	104718	REPLACED MAGNETIC CYLINDER SENSOR, PO#101286	GR - GENERAL REPAIRS
P19-W-019	ISUZU FRR600 LONG EWP	127711	18/10/2017 0:00	104718	REPAIRED DAMAGED FOOT PLATE, 4x RETAINING BOLTS BROKEN OFF AND FOOT PLATE KEEPER, MISSING. DRILLED OUT BROKEN BOLTS & SOURCED NEW KEEPER., REPLACED ALL BOLTS & KEEPER AND REFITTED FOOTPLATE., PO#99463	GR - GENERAL REPAIRS
P19-W-019	ISUZU FRR600 LONG EWP	127116	09/10/2017 0:00	97140	COMPLETED 90,000km SERVICE. REPLACED ENGINE OIL & FILTER., REPLACED FUEL & PCV FILTERS. ADJUSTED BRAKES, HAND & FOOT., ADJUSTED CLUTCH. DRAINED AIR TANKS. REPLACED TRANSMISSION, OIL & FILTER. REPLACED DPD HOSES., CARRIED OUT RECAL TO SHACKLE PIN LOCK PLATE INSTRUCTIONS., LUBRICATED DOOR HINGE/CATCH TO STOP DOOR CLUNKING., REPLACED WIPER INSERTS., PO#98949	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	127287	06/10/2017 0:00	93412	COMPLETED 'A' SERVICE. REPLACED ENGINE OIL & FILTER, REPLACED FUEL FILTER., SERVICE KEY FOR THE HANDBRAKE/DOOR ALARM WOULDN'T WORK, EVEN, WHEN THE KEY IS IN AND ON. ALARM STILL WENT OFF AND THE, HANDBRAKE WOULD NOT RELEASE. REPAIRED BY LOCATING A KEY, FIRST, KEY NEEDS TO BE IN AND ON TO RELEASE THE HANDBRAKE TO, ENABLE THE REAR BRAKES TO BE ADJUSTED. HAD TO DISCONNECT THE, RH DOOR SWITCH TO ADJUST THE BRAKES. BRAKES ADJUSTED OK., RECONNECTED THE SWITCH., PO#99085	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	126431	13/09/2017 0:00	81943	COMPLETED 12m TOWER SERVICE, ANNUAL INSPECTION & WEIGHT TEST, PASSED TEST. BRACKET HAD 22kg COVER STICKER ON IT. WRONG, LABEL. REMOVED OLD STICKER. CLEANED AREA. REPLACED THE 22kg, LABELS WITH LV COVER LABELS., PO#98358	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	126331	12/09/2017 0:00	81943	REPLACED TIMER RELAY DUE TO NO POWER AT RECEIVER., CHECKED WHY THERE IS NO POWER AT RECEIVER. INTERMITTENT, PROBLEM NOTICED IN K1 TIME REALY (TIM-06), NEW TIMER RELAY, REPLACED., BOOM FUNCTION TESTED WITH REMOTE AND PASSED. RHS REAR WORK, LIGHT REPLACED DUE TO DAMAGE., PO#98270	ER - ELECTRICAL REPAIR
P19-W-019	ISUZU FRR600 LONG EWP	125696	08/09/2017 0:00	64101	COMPLETED 60,000km SERVICE. REPLACED ENGINE OIL & FILTER, LUBRICATED ALL POINTS & PIVOTS. REPLACED FUEL & PCV FILTERS., CLEANED WATER TRAP. RESET TYRE PRESSURES. ADJUSTED TAPPETS., REPLACED CLUTCH AND BRAKE FLUIDS. REPLACED GEARBOX & DIFF, OILS. REPLACED D P D HOSES. ADJUSTED BRAKES, HAND & FOOT., ADJUSTED CLUTCH. DRAINED AIR TANKS. TIGHTENED MANIFOLDS &, EXHAUST SYSTEM. SERVICED AIR CLEANER. REPLACED COOLANT., PO#97747	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	124963	04/09/2017 0:00	81943	COMPLETED 6m ELECTRICAL TESTS., CARRIED OUT HV DRY TEST, P/O 97117	ET - ELECTRICAL TEST
P19-W-019	ISUZU FRR600 LONG EWP	122983	23/06/2017 0:00	81943	REPLACED WORN DRIVE TYRES POS 5-8, P/O 95370	TC - TYRE CHANGE/REPLACEMENT
P19-W-019	ISUZU FRR600 LONG EWP	123019	13/06/2017 0:00	78018	CREDIT FOR OVERCHARGE ON INVOICE	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	121397	01/06/2017 0:00	78018	COMPLETED 9m TOWER SERVICE. TIGHTENED LH REAR WORK LIGHTS., REPAIRED AND LUBED TIE DOWN RATCHETS AS THEY WERE JAMMING., CHECKED OVER., P/O 93875, COMPLETED IN BEACONSFIELD.	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	121340	10/05/2017 0:00	61915	REPAIRED DAMAGED EXHAUST, P/O 93824	CD - CUSTOMER DAMAGE
P19-W-019	ISUZU FRR600 LONG EWP	117626	17/02/2017 0:00	59233	COMPLETED 6 MONTH SERVICE AND WEIGHT TEST - ALL OK, COMPLETED 6m TOWER SERVICE & WEIGHT TEST, P/O 90970	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	118064	15/02/2017 0:00	61915	REPLACED TWO STEER TYRES - ONE STEER TYRE WAS DAMAGED, STEER TYRES - 235/75R17.5, P/O 91352	TC - TYRE CHANGE/REPLACEMENT
P19-W-019	ISUZU FRR600 LONG EWP	117352	25/01/2017 0:00	49512	COMPLETED 6m ELECTRICAL (HIGH & LOW VOLTAGE) TESTS, P/O 90754, COMPLETED AT BEACONSFIELD	ET - ELECTRICAL TEST
P19-W-019	ISUZU FRR600 LONG EWP	117253	24/01/2017 0:00	55577	REPAIRED DAMAGED WIRING TO RHR WORK LIGHT. TESTED - ALL OK.	CD - CUSTOMER DAMAGE
P19-W-019	ISUZU FRR600 LONG EWP	115076	21/12/2016 0:00	49512	COMPLETED 3m TOWER SERVICE. FITTED 2x FLURO LIGHTS, ON THE TOP LOCKER TO ILLUMINATE THE TRAY AREA AS REQUESTED., FITTED WORK LIGHT TO THE LH REAR SIDE OF THE TOP LOCKER, ABOVE THE LEG. REPAIRED DAMAGED WIRING TO RH REAR WORK LIGHT, P/O 88981	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	114759	14/11/2016 0:00	47926	COMPLETED 45,000km SERVICE. REPLACED OIL, FUEL & PCV FILTERS, CHECKED & ADJUSTED BRAKES & FOOT VALVE. ADJUSTED CLUTCH., REPLACED WIPER BLADES. GREASED & CHECKED OVER., P/O 88701	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	114092	07/11/2016 0:00	42044	REPLACE 2x WORN TYRES, PO#88229	TC - TYRE CHANGE/REPLACEMENT
P19-W-019	ISUZU FRR600 LONG EWP	113701	19/10/2016 0:00	42044	REPLACED 2 DAMAGED UNREPAIRABLE TYRES., CUSTOMER HIT SOMETHING ON ROAD. DAMAGED 2x LEFT REAR TYRES, PO#87943	TD - REPLACEMENT OF DAMAGED TYRE
P19-W-019	ISUZU FRR600 LONG EWP	112827	27/09/2016 0:00	31475	0	RE - REGISTRATION

P19-W-019	ISUZU FRR600 LONG EWP	109959	01/08/2016 0:00	31475	COMPLETED 12m SERVICE & WEIGHT TEST, BOLTS ON LOWER BOOM, MOOM REST REQUIRE MODIFYING -, REMOVED WASHERS FROM UNDER BOLTS ALSO SHORTENED BOLTS., EMERGENCY PUMP HANDLE MISSING - EMERGENCY PUMP LEAKING OIL, GOING TO BE FIXED UNDER WARRENTY., COVER MISSING FROM UPPER LEVEL CYLINDER DIVET - REPLACED, COVER & BOLT., FRONT BODY BOLTS LOOSE - TIGHTENED ALL BOLTS., PO#84969	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	109775	08/07/2016 0:00	30456	COMPLETED 12m ELECTRICAL TESTS, P/O 84803	ET - ELECTRICAL TEST
P19-W-019	ISUZU FRR600 LONG EWP	108948	30/06/2016 0:00	30456	COMPLETED 30,000km SERVICE. REPLACED OIL & FUEL FILTERS., REPALCED WIPER INSERTS. REPAIRED RH DOOR HINGE. ADJUSTED, BRAKES. CHECKED TOOLBOX LOCKS - ALL OK., P/O 84232	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	106978	13/05/2016 0:00	22455	COMPLETED 9m TOWER SERVICE., COMPLETED AT 158hrs., P/O 82676	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	103695	23/02/2016 0:00	16413	COMPLETED 15,000km SERVICE, REPLACED OIL, FUEL & PCV FILTERS. REPAIRED ABS DASH., AIMED HEADLIGHTS AS REQUIRED. GREASED. CLEANED WATER TRAP., RESET TYRE PRESSURES. CHECKED & ADJUSTED BRAKES, HAND & FOOT, ADJUSTED CLUTCH. DRAINED AIR TANKS. TIGHTENED MANIFOLDS &, EXHAUST SYSTEM. SERVICED AIR CLEANER., P/O 80271	PS - PLANNED SERVICE
P19-W-019	ISUZU FRR600 LONG EWP	102898	29/01/2016 0:00	10915	COMPLETED 6 MTH ELECTRICAL TEST., COMPLETE 6m ELECTRICAL TESTS, P/O 79642	AS - ATTACHMENT SERVICES
P19-W-019	ISUZU FRR600 LONG EWP	101765	21/01/2016 0:00	10915	COMPLETED 6m TOWER SERVICE & WEIGHT TEST., FITTED REQUIRED SAFETY LABELS., COMPLETED AT 43hrs., P/O 78901	AS - ATTACHMENT SERVICES