

TRIM(WOHH.WOWH_MODEL)	WOWH_DESC	WOWH_ORDER_N	WOWH_INVOICE_DATE	WOWH_METER	Comments	Full Rep Code
P19-W-023	ISUZU FRR600 LONG EWP	235649	11/09/2024 0:00	309883	PREP FOR AUCTION, Completed by: wilson.wang@porterplant.com.au on: Sep 11, 2024	GR - GENERAL REPAIRS
P19-W-023	ISUZU FRR600 LONG EWP	215513	01/05/2023 0:00	309883	COMPLETED PREDELIVERY INSPECTION. GREEN TAGGED., CARRIED OUT INSPECTION & COMPLETED REPORT. SENT REPORT TO MANAGER.	PD - PRE-DELIVERY INSPECTION
P19-W-023	ISUZU FRR600 LONG EWP	216462	21/04/2023 0:00	309883	DAMAGE TO FRONT BUMPER, BONNET, L/H TOOL BOX, L/H STEP, R/H STEP, REMOVE AND REFIT-, FRONT BUMPER, BONNET, L/H TOOL BOX, L/H STEP, R/H STEP, REPAIR-, FRONT BUMPER, BONNET, L/H TOOL BOX, PAINT-, FRONT BUMPER, BONNET, L/H TOOL BOX, PARTS-, R/H STEP, L/H STEP, R/H BAR LIGHT, REPLACE MISSING BASKET PIVOT PIN COVER	CD - CUSTOMER DAMAGE
P19-W-023	ISUZU FRR600 LONG EWP	214982	14/03/2023 0:00	309883	CARRIED OUT RETURN FROM HIRE INSPECTION, REPORT & PHOTOS SUPPLIED, PO 182026 - EPV	PI - PLANT INSPECTION
P19-W-023	ISUZU FRR600 LONG EWP	210732	28/02/2023 0:00	309410	REPAIRED BLOWN HYDRAULIC LINES, 22/11/22 - HYDRAULIC LEAK, DECK COVERED IN OIL, BLOWN HYDRAULIC LINES X 2, UNABLE TO STOW EWP., TRAVEL TO SITE, INSPECT & MARKED ALL HYD LINES, REMOVED ALL HYD LINES FROM EWP, HAVE CUSTOME LINE MADE, FOR REPLACEMENT, REINATALLED ALL HYD LINES, TIGHTEN TO SPEC. CARRIED OUT REAR DECK CLEAN OF ALL, OPERATORS TOOLS & RUBBISH, CLEAN DOWN HYD OIL MESS. CARRIED OUT OPERATIONAL CHECKS. CARRIED OUT, DEGREASE & HOT WASH OF VEHICLE & EWP, CARRIED OUT BOOM POLISHING SO VEHICLE IS COMPLIANT, TOPPED, UP HYD OIL LEVEL, REISNTALLED ACCESS PANELS, CARRIED OUT FURTHER OPERATIONAL CHECKS. ALL OK., PO 177757 - EMA	BH - BREAKDOWN - HYDRAULIC
P19-W-023	ISUZU FRR600 LONG EWP	210680	24/01/2023 0:00	309280	REPAIRED DPD SYSTEM, CALL OUT 19/11/22 FOR DPD ISSUES, CARRIED OUT DIAGNOSTIC SCAN, FOUND DPD SYSTEM NOT COMPLETING BURNS., FOUND OPERATOR HAD CANCELLED 20 BURNS, CARRIED OUT FORCED BURNS, UNABLE TO CONDUCT AS SYSTEM, TIMED OUT DUE TO BEING OVERFULL, TAGGED OUT VEHICLE & MOVED TO WORKSHOP. CARRIED OUT DPD DATA, DOWNLOAD, SYSTEM FULL - THERMOSTATS FAILED, DRAINED COOLANT SYSTEM, REMOVED & REPLACED THERMOSTATS, WITH NEW, BM - BREAKDOWN - MECHANICAL REPLENISHED COOLANT SYSTEM WITH NEW COOLANT, BLEED SYSTEM., DPD SYSTEM REMOVED, WASHED & CLEANED, REASSEMBLED WITH NEW GASKETS, CARRIED OUT DPD REGENERATION., CARRIED OUT SYSTEM OPERATIONAL CHECKS, ROAD TESTED, ALL OK. RETURN VEHICLE TO YARD., PO 177695 - EMA	BM - BREAKDOWN - MECHANICAL
P19-W-023	ISUZU FRR600 LONG EWP	212693	20/01/2023 0:00	309882	COMPLETED PREDELIVERY INSPECTION. GREEN TAGGED., CHECKED ALL FLUIDS & LIGHTS, OK. GREASED & CHECKED BRAKES, ALL OK. CHECKED KING PINS &, WHEEL BEARINGS, OK. REPLACED 1kg FIRE EXTINGUISHER & FIRST AID KIT. FITTED NEW UHF & ASSOCIATED COMPONENTS.	PD - PRE-DELIVERY INSPECTION
P19-W-023	ISUZU FRR600 LONG EWP	211469	15/12/2022 0:00	309401	DAIGNOSE BLOWN TELE BOOM HOSE, AFTER HOURS CALL OUT - 2.00AM TO 4.00AM, HDYRAULIC HOSE BLOWN, TELE HOSE BLOWN, NOT ABLE TO RETRACT BOOM BUT WAS ABLE TO STOW, ENOUGH TO DRIVE, THEN OVER ROAD INTERLOCKS TO RAISE STABILISERS, & GET BACK TO LILYDALE YARD., PO 178535 - EPV	BH - BREAKDOWN - HYDRAULIC
P19-W-023	ISUZU FRR600 LONG EWP	210645	29/11/2022 0:00	309050	CARRIED OUT MINOR TRUCK SERVICE, REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS & PCV FILTER, REPLACED WIPER BLADES., RHR WNI SHOW NUTS LOOSE, TIGHTENED TO SPEC. BRAKE CHECK - RHF & LHF 8MM, RHR & LHR 8MM., PO 177660 - EMA	PS - PLANNED SERVICE
P19-W-023	ISUZU FRR600 LONG EWP	210241	29/11/2022 0:00	307505	REPLACED LH HEADLIGHT ASSEMBLY, LH HEADLIGHT ASSY FULL OF WATER, UNSERVICEABLE., REMOVE DAMAGED UNIT & INSTALL NEW., ADJUSTED & AIMED HEADLIGHT, TESTED, OK., PO 177289 - EMA	BE - BREAKDOWN - ELECTRICAL
P19-W-023	ISUZU FRR600 LONG EWP	209336	23/11/2022 0:00	302748	REPLACED REAR HANGARS ON FRONT SUSPENSION, 13/10/22 - CALL OUT, VEHICLE REPORTED WITH FRONT SUSPENSION NOISE, CARRIED OUT INSPECTION., FOUND LHF & RHF HANGARS & SHACKLES HAD EXCESSIVE MOVEMENT, LH HANGAR BROKEN., MOVED TO EMA WORKSHOP, REMOVED & REPLACED LHF & RHF HANGARS & SHACKLES AS PER SPECS., TORQUED ALL HARDWARE TO SPEC, TEST DRIVE, CARRY OUT RE-TORQUE OF ALL COMPONENTS., RETURN VEHICLE TO LILYDALE YARD., PO 176273 - EMA	MR - MECHANICAL REPAIR
P19-W-023	ISUZU FRR600 LONG EWP	210268	16/11/2022 0:00	303784	TOWING CHARGE DUE TO FLAT TYRE, TOWED FROM PAKENHAM TO BEAUREPAIRES BAYSWATER, PO 177326 - EAGLE TOWING & SALVAGE	CD - CUSTOMER DAMAGE
P19-W-023	ISUZU FRR600 LONG EWP	209531	20/10/2022 0:00	303784	REPLACED PUNCTURED/DAMAGED TYRE - POS 2, 1 X 235/75R17.5 SP 341 132/130M TL & BALANCED, PO 176507 - BEAUREPAIRES BAYSWATER	TD - REPLACMENT OF DAMAGED TYRE
P19-W-023	ISUZU FRR600 LONG EWP	209201	20/10/2022 0:00	298191	REPLACED ALL BRAKES, DRIVER STRUGGLING TO STOP VEHICLE, INSPECTED & FOUND ALL BRAKES AT MAXIMUM WEAR INDICATION., REMOVED ALL BRAKES AS PER SPECS, HAVE SENT BRAKES FOR OVERHAUL, WASH & CLEAN BEARINGS., PREPARE & CLEAN SITES FOR REINSTALLATION, REASSEMBLE ALL BRAKES, INSTALL AS PER SPECS., BLEED BRAKES, TEST, ALL OK., PO 176133 - EMA	MR - MECHANICAL REPAIR

P19-W-023	ISUZU FRR600 LONG EWP	208018	14/10/2022 0:00	298195	CARRIED OUT MINOR TRUCK SERVICE, 8/9/22 - REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS, PCV FILTER, REPLACED WIPER BLADES,, REPAIRED PUNCTURE TO LHR TYRE, GREASED, ROAD TEST., BRAKE THICKNESS CHECK - RHF 4MM, LHF 4MM, RHR 5MM, LHR 5MM., PO 174949 - EMA	PS - PLANNED SERVICE
P19-W-023	ISUZU FRR600 LONG EWP	208996	05/10/2022 0:00	298191	CARRIED OUT 12MTH TOWER SERVICE INCL A/I & W/TEST, 2 X BOLTS BROKEN IN BASKET MOUNT ON BOOM TIP, HAD TO REMOVE LEVEL CYLINDER TO GAIN ACCESS,, DRILLED OUT BROKEN BOLTS, RETAPPED & REPLACED., REMOVED COVER TO ACCESS 2ND BOLT, DRILLED OUT, RETAPPED & REPLACED BOLT., LOWER BOOM LEVEL LINK PIN COVER MISSING, DRILLED OUT BROKEN BOLT, MADE UP NEW COVER, FROM OLD COVER & FITTED., REPLACED HYDRAULIC FILTERS., PO 175936 - EPV	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	208112	21/09/2022 0:00	290984	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, HV WET TESTS, PO 175041 - SETCO	ET - ELECTRICAL TEST
P19-W-023	ISUZU FRR600 LONG EWP	203188	31/08/2022 0:00	280815	REPLACED 6 DAMAGED TYRES, 17/5/22 - REPORTED THAT OPERATOR HAD DRIVEN OVER A BOX OF NAILS SPILT ON THE ROAD,, 2 STEERS & 4 REAR TYRES NEED REPLACEMENT. STRIP DAMAGED TYRES FROM RIMS, CARRY, OUT WHEEL ROTATION, REPLACED 6 TYRES WITH NEW TYRES ON RIMS., 4 X 9R22.5 TRUCK TYRES & 2 X STEER TYRES, PO 170218 - EMA	TP - PUNCTURE REPAIR
P19-W-023	ISUZU FRR600 LONG EWP	206081	09/08/2022 0:00	290931	AFTER HOURS CALL OUT TO REPLACE BATTERIES, 24/7/22 - CALL OUT ON SUNDAY NIGHT 8PM TO MONTMORENCY, VEHICLE ON CONSTANT SHUT DOWN & NOT RESTARTING,, FOUND BOTH BATTERIES UNSERVICEABLE, REMOVE & REPLACED BATTERIES WITH NEW, CHECKED OPERATION, FOUND, VEHICLE WOULD STILL NOT START, CHECKED ELECTRICAL SYSTEM, FOUND E-STOP FAULTY, REMOVED E-STOP ASSY &, REPLACED WITH NEW, CARRY OUT SYSTEM CHECK, ALL OK., PO 173145 - EMA	BE - BREAKDOWN - ELECTRICAL
P19-W-023	ISUZU FRR600 LONG EWP	206082	09/08/2022 0:00	290984	CARRIED OUT MINOR TRUCK SERVICE, 26/7/22 - REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS, TOPPED UP COOLANT,, GREASED, REPLACED WIPER BLADES, ROAD TESTED. BRAKE THICKNESS CHECK DONE., FRONT RH 4MM, FRONT LH 4MM, REAR RH 7MM, REAR LH 7MM., PO 173146 - EMA	PS - PLANNED SERVICE
P19-W-023	ISUZU FRR600 LONG EWP	205147	18/07/2022 0:00	285591	REPAIRED DRIVERS DOOR HINGE, 28/6/22 - CALL OUT TO SITE, CHECK MAIN CABIN, LOOSE DRIVERS DOOR STAY & DOOR HINGE, LUBRICATED THE DOOR HINGE & DOOR STAY,, CARRIED OUT ADJUSTMENT TO ENSURE CORRECT ALIGNMENT, RETIGHTENED TO CORRECT TORQUE AS PER SPECS, NOW OK., PO 172182 - EMA	GR - GENERAL REPAIRS
P19-W-023	ISUZU FRR600 LONG EWP	203880	23/06/2022 0:00	274743	REPLACED SEAT SENSOR, 26/5/22 - CALL OUT TO SITE, FOUND BROKEN WIRING IN SEAT, REMOVED SEAT BASE,, REMOVED UNSERVICEABLE SENSOR PAD, REPLACED SENSOR, CHECKED OPERATION., PO 171062 - EMA	BE - BREAKDOWN - ELECTRICAL
P19-W-023	ISUZU FRR600 LONG EWP	203228	21/06/2022 0:00	284120	CARRIED OUT 9MTH TOWER SERVICE, E-STOP BUTTON ON REMOTE CONTROL IS BROKEN, REPLACED BUTTON & CHECKED, ALL OK., PO 170338 - EPV	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	203189	16/06/2022 0:00	28815	CARRIED OUT MINOR TRUCK SERVICE, 17/5/22 - REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS,, REPLACED WIPER BLADES, GREASED., CARRY OUT DIAGNOSTIC SCAN, NO FAULT CODES RECORDED, NIL, DEFECTS REPORTED., PO 170218 - EMA	PS - PLANNED SERVICE
P19-W-023	ISUZU FRR600 LONG EWP	203116	16/06/2022 0:00	280111	REPAIRED 2 X DAMAGED TYRES & 2 DAMAGED RIMS, 12/5/22 - BOTH LHR RIMS DAMAGED & UNSERVICEABLE, LHR OUTER SIDE WALLS OF TYRES WERE DAMAGED & UNSERVICEABLE., JACK UP VEHICLE, REMOVED WHEELS, REMOVE & STRIP TYRES FROM RIMS, INSTALL & FIT NEW TYRES TO NEW RIMS., REFITTED NEW WHEELS TO VEHICLE, TORQUE TO CORRECT SPECS, ALL OK., PO 170218 - EMA	TD - REPLACEMENT OF DAMAGED TYRE
P19-W-023	ISUZU FRR600 LONG EWP	201079	21/04/2022 0:00	273567	REPLACED 2 TYRES, CARRIED OUT INSPECTION & ROTATED LH & RH INNER TYRES WITH OUTER TYRES., INSTALLED 2 SECOND HAND TYRES WITH SAME TREAD PATTERN AS INNERS., INSTALLED & TORQUED TO SPEC, NOW ROADWORTHY., PO 168010 - EMA	TC - TYRE CHANGE/REPLACEMENT
P19-W-023	ISUZU FRR600 LONG EWP	201303	19/04/2022 0:00	274743	REPLACED SEAT BELT FOR DRIVERS SEAT, SEAT BELT REPORTED IN UNROADWORTHY STATE., REMOVED ALL ACCESS TRIMS, ISOLATED BATTERIES, CARRIED OUT BELT REMOVAL & REPLACED WITH NEW., CARRIED OUT OPERATIONAL CHECKS, ALL OK, REINSTALLED ALL REMOVED PANELS, CONNECTED BATTERIES., PO 168250 - EMA	GR - GENERAL REPAIRS
P19-W-023	ISUZU FRR600 LONG EWP	201302	07/04/2022 0:00	274743	CARRIED OUT MINOR TRUCK SERVICE, REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS, TOPPED UP HYDRAULIC OIL, TOPPED UP COOLANT,, REPLACED WIPER BLADES, GREASED, REMOVE MAF SENSOR & CLEAN & INSPECT, ROAD TEST., PO 168250 - EMA	PS - PLANNED SERVICE
P19-W-023	ISUZU FRR600 LONG EWP	201547	01/04/2022 0:00	274739	CARRIED OUT 6MTH TOWER SERVICE INCL WEIGHT TEST, WAITING TIME - WAITING FOR UNIT TO SHOW UP. REPLACED HYDRAULIC FILTER., LOWER LEVEL CYLINDER COVERS BORKEN OFF, DRILLED OUT BROKEN BOLTS & REFITTED COVERS., PO 168521 - EPV	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	200746	23/03/2022 0:00	267490	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, HV WET TESTS, PO 167684 - SETCO	ET - ELECTRICAL TEST

P19-W-023	ISUZU FRR600 LONG EWP	198919	18/02/2022 0:00	267490	REPLACED BEACONS & FUSES, 25/01/22 - OPERATOR REPORTED FAULT WITH BOTH BEACONS, CARRIED OUT INSPECTION, BLOWN FUSE, REPLACED & TESTED - FAILED., CARRIED OUT POWER TEST, POWER AT BEACONS BUT STILL NOT WORKING, BEACONS BLOWN, REQUIRE REPLACEMENT, ORDER PARTS., FIT NEW BEACONS, CARRIED OUT TERMINATION OF WIRING, REPLACED FUSES, CARRIED OUT LIGHT CHECK, NOW OK., PO 165735 - EMA	BE - BREAKDOWN - ELECTRICAL
P19-W-023	ISUZU FRR600 LONG EWP	199236	18/02/2022 0:00	265615	REPLACED TURBO, 1/2/22 - VEHICLE LOW ON POWER - INVESTIGATE BLOWN TURBO, CARRIED OUT DIAGNOSTIC SCAN - NIL CODES, CARRIED OUT OPERATIONAL TESTING -, TURBO FOUND ONLY OPERATING AT 30%, REPORTED TO ISUZU, THEY SUGGESTED VEHICLE HAS UNSERVICEABLE TURBO, ORDERED PARTS., 2/2/22 - REMOVED & REPLACED TURBO IN ACCORDANCE WITH MANUAL, CARRIED OUT OPERATION CHECK, ALL OK., PO 166045 - EMA	BM - BREAKDOWN - MECHANICAL
P19-W-023	ISUZU FRR600 LONG EWP	198918	18/02/2022 0:00	267490	CARRIED OUT MINOR TRUCK SERVICE, 25/01/22 - REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS, REPLACED WIPER BLADES, REPLACED PCV KIT, CLUTCH & BRAKE ADJUSTMENT, GREASED., PO 165735 - EMA	PS - PLANNED SERVICE
P19-W-023	ISUZU FRR600 LONG EWP	198920	18/02/2022 0:00	267490	REPLACED STEER TYRES, 25/01/22 - REMOVED UNSERVICEABLE TYRES, CARRIED OUT TYRE ROTATION, HAVE TYRES OVERHAULED, INSTALLED & TORQUED TO SPEC, ALL OK., PO 165735 - EMA	TC - TYRE CHANGE/REPLACMENT
P19-W-023	ISUZU FRR600 LONG EWP	197430	21/01/2022 0:00	258208	CARRIED OUT MINOR TRUCK SERVICE, 2/12/21 - REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS, REPLACED LH CABIN PARKER GLOBE., GREASED, REPLACED WIPER BLADES, BRAKE & CLUTCH ADJUSTMENT, CLEAN MAF SENSOR., PO 164167 - EMA	PS - PLANNED SERVICE
P19-W-023	ISUZU FRR600 LONG EWP	198508	21/01/2022 0:00	258208	REPAIRED AIRCON, GAIN ACCESS TO MODE SWITCH MOTOR, DISCONNECT ACTUATOR ARM, TRY TO MANUALLY MOVE VENT CONTROL - STUCK., PRESS MODE BUTTON, MODE CHANGES & ACTUATOR MOTOR MOVES, ITEM STUCK IN VENT, REMOVED DASH TOP &, INSPECTED AIR BOX VENTS, LOCATED & REMOVED ITEMS IN VENTS, REFITTED & TESTED, OK., PO 164167 - EMA	AC - AIR-CONDITION REPAIR
P19-W-023	ISUZU FRR600 LONG EWP	197432	21/01/2022 0:00	257316	AFTER HOURS CALL OUT TO CLEAR FAULT CODES, 25/11/21 - AFTER HOURS CALL OUT - TRANSMISSION ISSUE, FAULT LIGHT ON, CARRY OUT DIAGNOSTIC SCAN -, CODES P0700 TRANSMISSION CONTROL & P0907 GATE SELECT. CLEAR CODES, TEST DRIVE, RESCAN TRUCK., NIL CODES, NIL DEFECTS. CARRY OUT INSPECTION OF LOOMS, NIL DEFECTS., PO 164167 - EMA	ER - ELECTRICAL REPAIR
P19-W-023	ISUZU FRR600 LONG EWP	197997	22/12/2021 0:00	258204	CARRIED OUT 3MTH TOWER SERVICE, PO 164758 - EPV	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	197176	03/12/2021 0:00	254934	REPAIRED PUNCTURE, 8/11/21 - DRIVE TO SITE TO CHANGE SPARE TYRE FOR PUNCTURE REPAIR RHR, REMOVE SPARE & FIT REPAIRED TYRE., TORQUE TO SPEC, FIT WNI., PO 163043 - EMA	TP - PUNCTURE REPAIR
P19-W-023	ISUZU FRR600 LONG EWP	196423	03/12/2021 0:00	254934	INSPECTED PROBLEM WITH AIRCON, 8/11/21 - INSPECT A/C, CONDENSOR FAN ON, A/C BELT GOOD, A/C COMPRESSOR ENGAGED, A/C PRESSURE SWITCH GOOD., PIPES COLD, A/C SITE GLASS LIQUID/GAS GOOD, AIR FEELS COLD, CYCLE VENT - NONE, VENT STUCK ON CENTRE DASH, DEMISTER ONLY. VEHICLE NEEDS TO BE RETURNED TO WORKSHOP TO PULL DASH APART TO INSPECT., PO 163043 - EMA	AC - AIR-CONDITION REPAIR
P19-W-023	ISUZU FRR600 LONG EWP	196574	01/12/2021 0:00	255492	REPLACED STEER TYRES, S & F 2 X 235/75R17.5 TYRES, TORQUE WHEEL NUTS TO SPEC., PO 163229 - EMA	TC - TYRE CHANGE/REPLACMENT
P19-W-023	ISUZU FRR600 LONG EWP	196276	01/12/2021 0:00	253185	PUNCTURE REPAIRED, CALL OUT TO SITE, PUNCTURE ON RHR OUTER TYRE, JACK UP & REMOVE TYRE, INSTALLED SPARE, TORQUE ALL NUTS., CARRIED OUT BRAKE ADJUSTMENT. TAKE TYRE FOR PUNCTURE REPAIR. TO BE REFITTED WHEN VEHICLE NEXT AVAIL., PO 162910 - EMA	TP - PUNCTURE REPAIR
P19-W-023	ISUZU FRR600 LONG EWP	194145	01/12/2021 0:00	246809	CLEARED FAULT CODES & REPLACED SEAT SENSOR, 9/9/21 - CALL OUT TO SITE, ENGINE LIGHT ON DASH & IARS ENGAGED, CARRY OUT OBD2 SCAN, TRANSMISSION CODE., OPERATOR RESTING HAND ON GEAR SELECTOR WHEN DRIVING. INSPECTED IARS SYSTEM, SEAT SENSOR CABLE, DAMAGED, REMOVED & REPLACED SEAT SENSOR, CARRY OUT OBSERVATION TESTING - SATISFACTORY., PO 160493 - EMA	ER - ELECTRICAL REPAIR
P19-W-023	ISUZU FRR600 LONG EWP	195796	22/11/2021 0:00	251632	REPLACED LH MIRROR ASSEMBLY, LH MIRROR ASSEMBLY BROKEN - OPERATOR DAMAGE. REMOVED DAMAGED MIRROR ASSY, REPLACED WITH NEW, POSITION &, TIGHTEN, SECURE MIRROR, CLEAN GLASS, POSITION TO SUIT DRIVER., PO 162378 - EMA	CD - CUSTOMER DAMAGE
P19-W-023	ISUZU FRR600 LONG EWP	195946	22/11/2021 0:00	252755	INSPECTED & REPAIRED BRAKES, 12/10/21 - PARK BRAKE NOT HOLDING, JACK VEHICLE, CARRY OUT BRAKE INSPECTION, ADJUST AS REQD, TEST, OK., PO 162095 - EMA, 26/10/21 - INSPECT BRAKES, BRAKE THICKNESS CHECK - FRONT RH 5.0MM, FRONT LH 5.0MM, REAR RH 8.0MM, REAR LH 8.0MM., ADJUST AIR BRAKES, FRONT 42 INDIVIDUAL CLICKS OUT, REAR 24 INDIVIDUAL CLICKS OUT., PO 162540 - EMA	MR - MECHANICAL REPAIR

P19-W-023	ISUZU FRR600 LONG EWP	195017	19/10/2021 0:00	250275	CARRIED OUT MINOR TRUCK SERVICE, REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS, BLOW OUT AIR FILTER, REPLACE WIPER BLADES, BRAKE & CLUTCH, ADJUSTMENT, GREASED, REMOVE MAF SENSOR - CLEAN & INSPECT. REPAIRED DAMAGED EXHAUST HEAT WRAP AFTER DPD FILTER., PO 161515 - EMA	PS - PLANNED SERVICE
P19-W-023	ISUZU FRR600 LONG EWP	195029	19/10/2021 0:00	250275	REPLACED REAR BRAKES, REAR BRAKES FOUND WORN TO MAXIMUM WEAR LIMITATIONS, REMOVED ALL WHEELS, REMOVED ALL BRAKE/WHEEL HUBS,, INSPECTED ALL BRAKE COMPONENTS - FOUND SATISFACTORY, WASHED/CLEANED & INSPECTED WHEEL BEARINGS - FOUND SATISFACTORY,, HAVE BRAKES OVERHAULED & WORN COMPONENTS REPLACED, INSTALL NEW LININGS, RESET POSITION OF ABS SENSORS & ENSURE, WORKING CORRECTLY, ASSEMBLE REAR BRAKES, CARRIED OUT IAW AS PER MANUAL, INSTALLED WHEELS & TORQUED TO SPEC,, SET & ADJUST REAR BRAKES, TEST DRIVE, OK., PO 161515 - EMA	MR - MECHANICAL REPAIR
P19-W-023	ISUZU FRR600 LONG EWP	195154	12/10/2021 0:00	247310	CARRIED OUT 12MTH TOWER SERVICE INCL A/I & W/TEST, REPLACED HYDRAULIC FILTERS, HYD OIL TEST KIT, PO 161707 - EPV	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	194277	30/09/2021 0:00	243053	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, HV WET TESTS, PO 160657 - SETCO	ET - ELECTRICAL TEST
P19-W-023	ISUZU FRR600 LONG EWP	193153	30/09/2021 0:00	234562	REPLACED 4 DRIVE TYRES - POS 3/4/5/6, STRI & FIT 4 X 235/75R17.5 TYRES, TORQUE WHEEL NUTS AND FIT WNI., PO 159269 - EMA	TC - TYRE CHANGE/REPLACEMENT
P19-W-023	ISUZU FRR600 LONG EWP	192550	10/09/2021 0:00	234562	FABRICATED BUCKET HARD LID, MAKE ALLOY HARD LID FOR EWP BASKET - MEASURE BUCKET, FABRICATE LID, FIT HANDLES & PINCH WELD, TEST FIT LID,, FITS AS REQD, SECURE., PO 158593 - EMA	GR - GENERAL REPAIRS
P19-W-023	ISUZU FRR600 LONG EWP	192548	10/09/2021 0:00	234562	CLEARED FAULT CODES, 12/7/21 - CALLED OUT TO SITE, CARRY OUT DIAGNOSTIC SCAN, RECORD CODES - U2105, U2106, C0226, P1915, P0401, P0700,, INSPECT TRANSMISSION FOR DEFECTS, REMOVE AND RECONNECT ASSOCIATED CONNECTORS, CLEAR CODES, MANUAL, BURN CARRIED OUT, ROAD TEST, RESCAN VEHICLE, NIL CODES EVIDENT., PO 158593 - EMA	ER - ELECTRICAL REPAIR
P19-W-023	ISUZU FRR600 LONG EWP	193152	30/08/2021 0:00	243053	CARRIED OUT MINOR TRUCK SERVICE, REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTERS, BLOW OUT AIR FILTER, REPLACED WIPER BLADES &, TOP UP WASHER BOTTLE, CARRIED OUT BRAKE & CLUTCH ADJUSTMENT, TOP UP FLUIDS WHERE REQD, GREASED,, REMOVED MAF SENSOR, CLEAN & INSPECT, ROAD TEST. REMOVED & REPLACED DRIVE & A/C BELTS, SET TO REQD, TENSIONS., PO 159269 - EMA	PS - PLANNED SERVICE
P19-W-023	ISUZU FRR600 LONG EWP	191476	06/07/2021 0:00	234562	CARRIED OUT 9MTH TOWER SERVICE, INCL WAITING TIME FOR TRUCK TO RETURN FROM TRUCK SERVICE., PO 157402 - EPV	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	188328	15/04/2021 0:00	222996	CARRIED OUT 6MTH TOWER SERVICE, PO 153999 - EPV	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	187406	07/04/2021 0:00	214461	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, HV WET TESTS, PO 153065 - SETCO	ET - ELECTRICAL TEST
P19-W-023	ISUZU FRR600 LONG EWP	184601	14/01/2021 0:00	214461	REPAIRED WIRING TO ENGINE HIGH IDLE MODULE, DRIVER REPORTS TOWER CUTS OUT & ENGINES DROP OFF INTERMITTENTLY, HE OPERATED TOWER WHILST I WATCHED, INITIALLY ALL WORKED, THEN ENGINE REVS DROPPED & RETURNED TO HIGH IDLE, CHECKED WIRING IN CABIN, RELAY OK, TRACED WIRING TO ENGINE HIGH IDLE, MODULE, REMOVED MODULE FROM DASH, REMOVED REAR PANEL & FOUND FAULTY CONNECTION, REFITTED WIRE & ENGINE REVS NOW OK,, REASSEMBLED MODULE & REFITTED, CHECKED OPERATION, ALL OK., PO 150092 - EPV	BE - BREAKDOWN - ELECTRICAL
P19-W-023	ISUZU FRR600 LONG EWP	184603	14/01/2021 0:00	213132	CARRIED OUT 3MTH TOWER SERVICE, PO 150092 - EPV	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	183141	24/11/2020 0:00	203987	FITTED NEW DISTRIBUTOR TO TOWER, TOWER NOT WORKING, FOUND NO POWER TO TURRET SYSTEM, AS SOON AS YOU ENGAGE POWER OF TOWER EMERGENCY STOP SIDE CUTS, IN & TURNS OFF TRUCK, BYPASSED SAFETY, REALISE SR 1 & 2 SET UP LEGS, TESTED EMERGENCY STOP SIDE OF TOWER & FOUND POWER UP, AT TURRET BY NOT GOING DOWN TO RECEIVER IN LOWER TURRET SECTION. ISOLATED WIRES & FOUND THE BLUE/RED & BROWN WIRES IN, THE DISTRIBUTOR SLIP RING HAVE CROSSED & CONNECTED WITH MULTIPLE WIRES IN DISTRIBUTOR, UNIT WILL NOW REQUIRE NEW MOOG, SLIP RING, PACKED UP UNIT & ORGANISED PARTS & WHEN UNIT CAN BE FIXED,, REMOVED OLD DISTRIBUTOR, FITTED NEW DISTRIBUTOR, THIS TOOK A LONG TIME AS THE WIRES WERE VERY SMALL & DIFFICULT TO CHANGE, OVER AS THE COLOUR CODING WAS DIFFERENT TO THE ORIGINAL, ON COMPLETION OF WIRING NEW DISTRIBUTOR IN CHECKED ALL, OPERATIONS & FUNCTIONS, ALL OK., PO 148548 - EPV	BE - BREAKDOWN - ELECTRICAL
P19-W-023	ISUZU FRR600 LONG EWP	181977	24/11/2020 0:00	204366	S & F I-ARS - ANTI ROLL AWAY SYSTEM, HAVE VASS CERTIFICATION CARRIED OUT, DECOMMISSION PARK SAFE SYSTEM., PO 147352 - EMA	AR - ADDITIONAL WORK
P19-W-023	ISUZU FRR600 LONG EWP	182185	29/10/2020 0:00	203122	CARRIED OUT 12MTH TOWER SERVICE INCL A/I & W/TEST, PO 147548 - EPV	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	180735	01/10/2020 0:00	194376	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, HV WET TESTS, PO 146165 - SETCO	ET - ELECTRICAL TEST
P19-W-023	ISUZU FRR600 LONG EWP	177465	21/07/2020 0:00	194376	REPAIRS TO TOWER SO IT OPERATES ON REMOTE, TOWER NOT WORKING ON REMOTE, TRAVEL TO & FROM DOWNER YARD, IN LILYDALE TO BEACONSFIELD, REPAIRS TO TOWER, NOW WORKING., PO 143110 - EPV	BE - BREAKDOWN - ELECTRICAL
P19-W-023	ISUZU FRR600 LONG EWP	177067	13/07/2020 0:00	191728	CARRIED OUT 9MTH TOWER SERVICE, PO 142717 - EPV	AS - ATTACHMENT SERVICES

P19-W-023	ISUZU FRR600 LONG EWP	173766	01/05/2020 0:00	180390	CARRIED OUT 6MTH TOWER SERVICE INCL WEIGHT TEST, TOWER STOPPED WORKING INTERMITTENTLY, TOOK A WHILE TO, TRACE FAULT TO HANDBRAKE SWITCH, REPLACED SWITCH & TESTED,, ALL OK NOW., PO 140078 - EPV	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	170964	05/03/2020 0:00	168395	CARRIED OUT ELECTRICAL TEST, HV DRY TEST, HV WET TESTS, PO 137529 - SETCO	ET - ELECTRICAL TEST
P19-W-023	ISUZU FRR600 LONG EWP	169212	10/02/2020 0:00	168395	REPAIRED WIRING, PTO NOT ENGAGING, WENT THROUGH WIRING SCHEMATICS TO FIND, WHAT MAY BE PROBLEM, CHECKED ALL WIRING CONNECTIONS AT, RELAY PANEL UNDER DASH, AFTER A TIME FOUND A LOOSE, CONNECTION ON RELAY BLOCK, TOUCHED THIS WIRE & FAULT, OCCURRED AS DRIVE DESCRIBED, REMOVE WIRE, TIGHTENED, CONNECTION, REFITTED INTO PANEL & REFITTED RELAY, ALL OK., PO 135865 - EPV	BE - BREAKDOWN - ELECTRICAL
P19-W-023	ISUZU FRR600 LONG EWP	168490	15/01/2020 0:00	168395	CARRIED OUT 3MTH TOWER SERVICE & REPAIRS, RH WORK LIGHT NOT WORKING, REPAIRED BROKEN WIRE., PO 135074 - EPV	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	165817	26/11/2019 0:00	165489	REPLACED BROKEN CENTRE BOLT & MISSING EXHAUST PIPE NUT, DRIVE TO YARD INPSECT VEHICLE, REAR RIGHT CENTRE BOLT, BROKEN, AXLE HAS MOVED FORWARD, WAIT FOR OPERATOR TO, REMOVE GEAR & TAKE VEHICLE BACK TO EMA WORKSHOP, REMOVE, RRH SPRING CLAMP IN PLACE READY FOR CENTRE BOLT, FIT CENTRE, BOLT TO SPRING, REPLACE BUSHING IN SPRING, LIFT SPRING INTO, PLACE, TIGHTEN ALL HARDWARE TO SPEC, RETURN VEHICLE TO YARD., PO 132452 - EQUIPMENT MANAGEMENT AUSTRALIA	BM - BREAKDOWN - MECHANICAL
P19-W-023	ISUZU FRR600 LONG EWP	164108	02/10/2019 0:00	159801	R#BUS012325678	RE - REGISTRATION
P19-W-023	ISUZU FRR600 LONG EWP	163297	01/10/2019 0:00	147471	CARRIED OUT 6MTHLY ELECTRICAL TEST, HV DRY TEST, BUCKET LINER TEST, PO 130038 - SETCO	ET - ELECTRICAL TEST
P19-W-023	ISUZU FRR600 LONG EWP	163507	25/09/2019 0:00	159801	CARRIED OUT 12MTH TOWER SERVICE INCL A/I & W/TEST & REPAIRS, REPLACED BROKEN BOLTS IN COVER OVER MAIN END OF BOOM, PO 130233	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	158966	24/06/2019 0:00	147471	CARRIED OUT 9MTH TOWER SERVICE & REPAIRS, BROKEN BOLT IN BOOM TIP MOUNT, DRILLED OUT BROKEN BOLT., TOOK A WHILE AS TAPPING OUT HOLE, TOP GOT JAMMED ON OLD, THREAD, BROKE TOP OFF IN HOLE, WAS ABLE TO REMOVE BROKEN, TAP & FINISH TAPPING HOLE, FITTED NEW BOLT., START BUTTON ON REMOTE CONTROL BROKEN, REPLACED START, BUTTON., OIL LEAK FROM LOWER BOOM HOLDING VALVE, LOCATED LEAK, COMING, FROM A LOOSE FITTING, TIGHTENED, CLEANED, OPERATED & CHECKED, PO 126221	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	156021	29/04/2019 0:00	139573	6MTH TOWER SERVICE AND WEIGHT TEST, PO 123704, CARRIED OUT 6MTH TOWER SERVICE AND WEIGHT TEST, ENGINE NOT REVING UP WHEN TOWER OPERATED, CHECKED & FOUND, NO POWER GOING THROUGH DISTRIBUTOR ON HIGH IDLE CIRCUIT,, FOUND SPARE WIRE IN DISTRIBUTOR & SWAPPED THIS OVER TO HIGH, IDLE CIRCUIT, TESTED, ALL OK., PO 123704	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	153962	28/03/2019 0:00	125082	EWP TEST, PO 121907, CARRIED OUT ELECTRICAL TEST, HV DRY TEST, HV WET TESTS, PO 121907	ET - ELECTRICAL TEST
P19-W-023	ISUZU FRR600 LONG EWP	149853	27/12/2018 0:00	125082	CARRIED OUT 3 MTH TOWER SERVICE & INVESTIGATE EMERGENCY STOP, ALL 3 EMERGENCY STOPS ON TRAY NOT WORKING, BYPASSED SLIP, RINGS BUT FAULT STILL THERE, WANTED TO TEST FURTHER BUT, DOWNER ARRANGED FOR REPAIRS TO BE DONE ELSEWHERE., PO 118284	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	147865	12/12/2018 0:00	113178	INSPECTED FOR REPORTED PTO DROP OUT, COULD NOT FAULT., PTO DROPS OUT INTERMITTENTLY, OPERATED TOWER THROUGH ALL, FUNCTIONS 3 TIMES FROM SCRATCH, NOT ABLE TO GET IT TO FAULT., MR MADE DRIVER AWARE & HE WILL LET EPV KNOW IF IT HAPPENS AGAIN, P/O 116509	MR - MECHANICAL REPAIR
P19-W-023	ISUZU FRR600 LONG EWP	145901	03/10/2018 0:00	113178	R#WEB007429672, POSTED TO DOWNER FLEET, ATT CLAIRE BENDALL, PO BOX 4993 MELBOURNE VIC 3001	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	145533	01/10/2018 0:00	113178	COMPLETE 12m TOWER SERVICE, WEIGHT TEST & ANNUAL INSPECTION, REPLACED FAULTY SYNC BUTTON ON REMOTE, P/O 114276	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	144730	03/09/2018 0:00	107452	COMPLETED 6m WET & DRY ELECTRICAL TESTS, TRAVELLED TO SITE., P/O 113464	ET - ELECTRICAL TEST
P19-W-023	ISUZU FRR600 LONG EWP	143701	21/08/2018 0:00	107452	CHECKED HI/LOW CUTTING OUR INTERMITTENTLY. NO FAULT FOUND, OPERATED FOR OVER 1/2hr NOT ABLE TO FAULT. LEFT STATIONARY, IN AIR & CHECKED AGAIN STILL NOT ABLE TO FAULT. WILL KEEP, IN TOUCH WITH DRIVER, PO#112469	GR - GENERAL REPAIRS
P19-W-023	ISUZU FRR600 LONG EWP	140550	02/07/2018 0:00	14248	COMPLETED 9m TOWER SERVICE., REPLACED BROKEN BOLT IN TELE BOOM COVER, P/O 109958	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	139115	01/06/2018 0:00	98636	REPLACED FAULTY PTO VALVE SOLENOID, PTO WORKING INTERMITTANTLY. CHECKED AND FOUND SUSPECT, PTO VALVE. REPLACED THIS VALVE & WILL MONITO, P/O 108876	HR - HYDRAULIC REPAIR

P19-W-023	ISUZU FRR600 LONG EWP	136194	01/05/2018 0:00	92303	FITTED NEW UPGRADED FRONT & REAR SPRINGS, SPRINGS HAVE BEEN RESET WITH EXTRA LEAF, REPLACED SPRINGS, PINS & BUSHES AS REQUIRED., NOTE: NEW UPGRADED SPRINGS SUPPLIED BY ISUZU AUST. UNDER, GOODWILL., THE FOLLOWING REPAIRS WERE COMPLETED UNDER WARRANTY.; 17-Z-03 F-SERIES SHACKLE PIN LOCK PLATE RECALL. COMPLETED, RECALL AS PER INSTRUCTIONS, CARRIED OUT F-SERIES ISRI SEAT EARTH CABLE REWORK AS PER, SERVICE BULLETIN 230/16, P/O 106494	MJ - MAJOR REPAIR
P19-W-023	ISUZU FRR600 LONG EWP	136291	11/04/2018 0:00	92136	COMPLETED 6m TOWER SERVICE & WEIGHT TEST, P/O 106558	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	135637	10/04/2018 0:00	89115	REPAIRED & CLEANED OIL LEAK AT FRONT LEFT STABILISER LEG, CHECKED HYDRAULIC OIL LEAK FROM LR STABILISER. OPERATED &, LOCATED LEAK COMING FROM PLUG. REMOVED & INSPECTED. NOT, ABLE TO SEE ANY FAULT, CLEANED, REFITTED & OPERATED &, CHECKED ALL OK. WASHED OFF OIL & WEIGHT TESTED. OK., P/O 106073	MR - MECHANICAL REPAIR
P19-W-023	ISUZU FRR600 LONG EWP	135204	13/03/2018 0:00	80711	COMPLETED WET TEST. CLEANED. REPAIRED GEL COAT DAMAGE., P/O 120989	ET - ELECTRICAL TEST
P19-W-023	ISUZU FRR600 LONG EWP	130682	11/01/2018 0:00	80711	COMPLETED 3m TOWER SERVICE, PO#102047	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	127714	18/10/2017 0:00	70562	REPLACED FAULTY BOOM PROXY SWITCH, P/O 99465	ER - ELECTRICAL REPAIR
P19-W-023	ISUZU FRR600 LONG EWP	126663	04/10/2017 0:00	68381	COMPLETED 12m TOWER SERVICE, ANNUAL INSPECTION & WEIGHT TEST, P/O 98532	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	126656	15/09/2017 0:00	57459	COMPLETED 6m ELECTRICAL TESTS, P/O 98526	ET - ELECTRICAL TEST
P19-W-023	ISUZU FRR600 LONG EWP	122537	28/06/2017 0:00	57459	COMPLETED 9m TOWER SERVICE. REPLACED BROKEN BOLTS IN BOOM, COVER.	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	122689	21/06/2017 0:00	50824	PROGRAM NEW REMOTE & INSTALL RECEIVER., P/O 95023	CD - CUSTOMER DAMAGE
P19-W-023	ISUZU FRR600 LONG EWP	120198	11/04/2017 0:00	50807	COMPLETED 6m TOWER SERVICE AND WEIGHT TEST., REPLACED HYDRAULIC FILTERS. CHECKED OVER., P/O 92975	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	120017	01/04/2017 0:00	44338	COMPLETED SIX MONTH ELECTRICAL TESTS, P/O 92853	ET - ELECTRICAL TEST
P19-W-023	ISUZU FRR600 LONG EWP	119836	01/04/2017 0:00	50824	REPLACED 4 WORN TYRES (POS 1-2,5-6), BALANCED NEW STEER TYRES., P/O 92708	TC - TYRE CHANGE/REPLACEMENT
P19-W-023	ISUZU FRR600 LONG EWP	117681	01/03/2017 0:00	44338	JOB CANCELLED, NOT DONE YET., REPLACE 1x BLOWN TYRE, P/O 91010	TC - TYRE CHANGE/REPLACEMENT
P19-W-023	ISUZU FRR600 LONG EWP	115598	16/12/2016 0:00	44338	COMPLETED 3m TOWER SERVICE. CHECKED OVER & GREASED., P/O 89403, COMPLETED AT 385hrs	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	115914	13/12/2016 0:00	29820	CARRIED OUT SERVICE S PER SCHEDULE., ALL NECESSARY CHECKS CARRIED OUT & FOUND SATISFACTORY, TO, INCLUDE: LIGHTS, HORN, SEATS, SEAT BELTS, AIR CON., TRANSMISSION & DIFF OILS, TYRE PRESSURES & WEAR, WHEEL NUT, INDICATORS. OIL & COOLANT LEAKS, EXHAUST, UNIVERSALS,, SHOCKER, SPRINGS, BUSHES & U-BOLTS, FRONT WHEEL BEARINGS &, KING PINS. BRAKE WEAR, BRAKE & CLUTCH ADJUSTMENT., WIPER BLADES, ALL LEVELS & REPLACE/REPLENISH WHERE REQ'D., CHANGED OIL, REPLACED OIL, FUEL & AIR FILTERS & GREASED, WHERE REQUIRED. LUBED AND INSPECTED CUPBOARD LATCHES &, STRUTS. LUBED DOOR HINGES. PARK BRAKE TEST CARRIED OUT., RH REVERSE LIGHT FOUND INOPERABLE - REPLACED WITH NEW. PCV, FILTER REPLACED WITH NEW., PO#89674	PS - PLANNED SERVICE
P19-W-023	ISUZU FRR600 LONG EWP	113812	24/10/2016 0:00	29820	0	RE - REGISTRATION
P19-W-023	ISUZU FRR600 LONG EWP	112061	26/09/2016 0:00	29820	COMPLETED 30,000km SERVICE. TIGHTENED AC BELT., REMOVED REAR RIGHT SHACKLE GREASE NIPPLE ADAPTER. REPAIRED, THREAD & REPLACED MISSING GREASE NIPPLE., RESET DASH WARNING. TEST DRIVEN & CARRIED OUT PARK BRAKE, TEST., PO#86710	PS - PLANNED SERVICE
P19-W-023	ISUZU FRR600 LONG EWP	112139	19/09/2016 0:00	29740	COMPLETED 12m SERVICE, ANNUAL INSPECTION & WEIGHT TEST, WEIGHT TESTED: DRIFTED 50mm IN 30min JUST INSIDE ALLOWABLE., HYDRAULIC OIL LEAK FROM RR STABILISER: COMING FROM SEAL, REPAIRED UNDER WARRANTY. REPLACED RETURN FILTER LINE., REPLACED HIGH PRESSURE FILTER., PO#86768	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	112292	09/09/2016 0:00	26483	COMPLETE 12m ELECTRICAL TESTS, COMPLETED HV DRY TEST., PO#86875	ET - ELECTRICAL TEST
P19-W-023	ISUZU FRR600 LONG EWP	108889	27/06/2016 0:00	20030	COMPLETED 9m TOWER SERVICE, P/O 84195, COMPLETED @ 198hrs	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	106380	01/05/2016 0:00	14700	COMPLETED 15,000km SERVICE. REPLACED OIL & FUEL FILTER., ADJUSTED REAR BRAKES. COMPLETED HAND BRAKE TEST., REPLACED REVERSE ALARM. DRILLED HOLES & EXTENDED WIRING., P/O 82184	PS - PLANNED SERVICE
P19-W-023	ISUZU FRR600 LONG EWP	105253	01/04/2016 0:00	11940	COMPLETED 6m TOWER SERVICE, REPLACED BEWARE LABEL, HV/LV & DRY ONLY LABELS., P/O 81335	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	104616	05/03/2016 0:00	10829	COMPLETED FIRST SERVICE, P/O 80904, NOTE: WAS BOOKED IN FOR 15,000KM BUT DEALER DID UNDER 1ST, SERVICE FREE OF CHARGE	PS - PLANNED SERVICE
P19-W-023	ISUZU FRR600 LONG EWP	104618	04/03/2016 0:00	10185	COMPLETED 6m ELECTRICAL TEST, P/O 80906	AS - ATTACHMENT SERVICES
P19-W-023	ISUZU FRR600 LONG EWP	100616	03/12/2015 0:00	2028	CREDIT INVOICE 63488 DUE TO PORTER'S TRANSPORTING THE, VEHICLES TO DOWNER UTILITIES	-
P19-W-023	ISUZU FRR600 LONG EWP	101065	01/12/2015 0:00	2700	COMPLETED MODIFICATIONS AS REQUESTED., REMOVED CABINETS AS REQUESTED. MODIFIED CABLE REEL., MODIFIED HANDRAIL & ADDITIONAL KICK BOARDS., P/O 76008	AR - ADDITIONAL WORK
P19-W-023	ISUZU FRR600 LONG EWP	100122	20/11/2015 0:00	2028	EASTLINK, 27/10 14:50 POLICE/WELLINGTON-BORONIA/CANTERBURY	-