

TRIM(WOHH.WOWH_MODEL)	WOWH_DESC	WOWH_ORDER_N	WOWH_INVOICE_DATE	WOWH_METER	Comments	Full Rep Code
P33-N-058	TIPPER 10T HINO	253705	07/10/2025 0:00	450040	PREPARED FOR AUCTION., REMOVED CUSTOMERS DECALS FROM DOORS. COMPLETED QUICK DETAIL OF INTERIOR., Completed by:chris.stack@porterplant.com.auon:Oct 07, 2025	GR - GENERAL REPAIRS
P33-N-058	TIPPER 10T HINO	250217	01/08/2025 0:00	449042	CARRIED OUT PRE START REPAIRS, DIAGNOSE & REPAIR NO START ON SITE, START TRUCK & DRIVE BACK TOW WORKSHOP., REPLACED REVERSE LIGHT ASSEMBLIES., 1ST DRIVE ON PASSENGER SIDE AIRBAG WORN, REPLACED AIRBAG ASSEMBLY., CAB MOUNTS WORN, REPLACED CAB MOUNT BUSHES., TORQUE ROD BUSHES WORN ON DRIVE AXLES, REPLACED REAR TORQUE RODS & CAB MOUNTS AS REQUESTED & QUOTED., DROP TRUCK BACK TO FULTON HOGAN., PO 216792 - ALLTRACK ENGINEERING	MR - MECHANICAL REPAIR
P33-N-058	TIPPER 10T HINO	250303	29/07/2025 0:00	449042	CARRIED OUT PLANNED SERVICE, CARRY OUT TRUCK SERVICE, REPLACE ALL FILTERS, REPLACE ENGINE OIL & CHECK OVER ALL FLUID LEVELS, CHECK ALL BRAKES,, CHECK ALL TYRES & TYRE PRESSURES, CHECK ALL UNDERBODY & SUSPENSION COMPONENTS, CHECK BATTERY & ALL LIGHTING, OPERATIONS, CHECK ALL HOSES & BELTS, FILL WASHER BOTTLE & CHECK WIPERS, GREASE ALL GREASE POINTS., PO 216849 - ALLTRACK ENGINEERING	PS - PLANNED SERVICE
P33-N-058	TIPPER 10T HINO	242483	06/03/2025 0:00	441661	CARRIED OUT HV INSPECTION REPORT, COMPLETED GENERAL INSPECTION & REPORT AS PER CUSTOMER REQUEST, PO 209770 - ZAMTECH	PI - PLANT INSPECTION
P33-N-058	TIPPER 10T HINO	243702	03/03/2025 0:00	441850	REPLACED EGR VALVE & GASKETS & CLEARED CODES, CHECK FOR ENGINE LIGHT ON & LIMP MODE ACTIVATES INTERMITTENTLY, REMOVED & REPLACED EGR VALVE & GASKETS,, CLEARED ALL CODES & ROAD TESTED VEHICLE, ALL OK., PO 210907 - CITY HINO	MR - MECHANICAL REPAIR
P33-N-058	TIPPER 10T HINO	241946	18/02/2025 0:00	441661	CARRIED OUT POST REPAIR INSPECTION, 30/1/25 - INSPECTED AIR COMPRESSOR FOR OIL LEAKS, NO OIL LEAKS FOUND AT COMPRESSOR. LOCATED EXCESSIVE OIL, AT BOTTOM AIR DRYER ASSY, INDICATES EXCESSIVE WEAR ON PISTON IN AIR COMPRESSOR. ADVISED BY DRIVER THAT, ENGINE LIGHT ON DASH, CONNECTED SCAN TOOL & LOCATED MULTIPLE CAN COMMUNICATION FAULTS, CLEAR FAULTS, & TEST DRIVE, ENGINE LIGHT DID NOT APPEAR ON TEST DRIVE. (WHEN MOVING TRUCK AROUND YARD 2 DAYS LATER ENGINE, LIGHT EMITTED, WILL NEED HINO GENUINE TO DIAGNOSE FURTHER.), 11/2/25 - ATTEND VEHICLE, SET TIMING ON MOTOR, REMOVE SHROUDS & AIRBOX ASSY, REMOVE HEAT SHIELDS, REMOVE, INTAKE PIPE TO TURBO & INTERCOOLER HOSES, GAIN ACCESS TO AIR COMPRESSOR, REMOVE AIR LINES, DRAIN COOLANT,, REMOVE COOLANT LINES & OIL RETURN LINE TO BLOCK, REMOVE COMPRESSOR AS REQD CLEAN AREA., 12/2/25 - RECEIVED NEW COMPRESSOR, SWAP GEAR OVER TO NEW AIR COMPRESSOR, RESET TIMING, FIT AIR COMPRESSOR, AS REQD, REASSEMBLE LINES, FIT NEW COMPRESSOR FILTER, REFIT GUARD & AIR BOOTS, REFILL COOLANT, TEST DRIVE, VEHICLE & CHECK FOR ANY LEAKS, OK. RETURN TO SERVICE., PO 209194 - ZAMTECH, BOOKED IN FOR 23/1/25, QUOTE SUPPLIED	MR - MECHANICAL REPAIR
P33-N-058	TIPPER 10T HINO	240567	19/12/2024 0:00	440104	CLEAR REGO INSPECTION DEFECTS, RECEIVE VEHICLE IN YARD, CONFIRM ADR35 DEFECT, INSPECT BRAKING SYSTEM, NON GENUINE HINO, SECOND TANK NOT, RETAINING PRESSURE, TRACE LINES & INSPECT CHECK VALVES, SUSPECT PROTECTION VALVE ISSUE, SPEAK TO CLIENT, REGARDING 2ND OPINION BEFORE DISMANTLING DUE TO HIGH COST OF PART, APPROVED TO TAKE TO ABC FOR, CONFIRMATION, RECEIVE BACK & CHECK WORKS, OK, NOTE TO CLIENT REGARDING REPLACEMENT OF AIR COMPRESSOR., REMOVED & REPLACED AIR COMPRESSOR, CHECK AIR SYSTEM, FOUND QUAD VALVE & AIR DRYER FAULTY, FOUND OIL &, WATER CONTAMINATION., DEFECT CLEARANCE GIVEN., PO 207964 - ZAMTECH	MR - MECHANICAL REPAIR
P33-N-058	TIPPER 10T HINO	237297	01/10/2024 0:00	434859	REPLACED AIRBAG & DOOR SWITCH, AIRBAG ASSEMBLY LEAKNG & INOPERABLE PARK BRAKE, BUILT UP AIR, FOUND AIR LEAK FROM CAB AIR BAG, DRIVERS SEAT SEEMS TO BE WORKING CORRECTLY, BUILT UP AIR AGAIN &, CHECKED UNDERNEATH TRUCK FOR LEAKS, CAN'T FIND ANY OTHERS. REPLACED OLD CAB AIRBAG WITH NEW ONE., INSPECT FUSES & CABIN, FOUND THAT FUSES ARE OK, AFTERMARKET DOOR SWITCH FITTED & APPEARS TO BE DISCONNECTED, VIA LOOSE WIRE IN THE CAB, CHECK VEHICLE FOR HAND BRAKE ALARM INOPERATIVE, FOUND DOOR SWITCH DAMAGED, REPLACE, & RETEST HAND BRAKE ALARM, ROAD TEST, ALL GOOD., PO 204809 - ALLTRACK ENGINEERING	MR - MECHANICAL REPAIR

P33-N-058	TIPPER 10T HINO	235400	12/08/2024 0:00	431857	REPLACED HEADLIGHT ASSEMBLY, BLOWN HEADLIGHT, SUPPLY, INSTALL & WIRE UP NEW D/S HEADLIGHT ASSY, PICK UP HIGH BEAM CIRCUIT FOR DRIVING, LIGHT OPERATION, TEST OPERATION OF LIGHTS, ALL GOOD., PO 202861 - ALLTRACK ENGINEERING	ER - ELECTRICAL REPAIR
P33-N-058	TIPPER 10T HINO	235618	08/08/2024 0:00	431857	REPAIRED HEADLIGHT & REPLACED BEACON GLOBE, CHECKED FOR D/S LOW BEAM HEADLIGHT NOT WORKING, FOUND HID GLOBE NOT PLUGGED IN, PLUG IS BURNT & MELTED, & NEEDS REPLACEMENT, RECOMMEND REPLACING HEADLIGHT ASSEMBLY., CHECK VEHICLE FOR INOPERATIVE BEACON, FOUND BLOWN GLOBE & ROTATING REFLECTOR HAS COME OFF TRACK,, REPLACED 24V H1 BE GLOBE, CLIPPED ROTATING REFLECTOR BACK IN PLACE & ALIGNED DRIVE BELT, SCREW AMBER, COVER BACK ON & TEST OPERATION, BOTH BEACONS OPERATING CORRECTLY., PO 203096 - ALLTRACK ENGINEERING	BE - BREAKDOWN - ELECTRICAL
P33-N-058	TIPPER 10T HINO	233926	24/07/2024 0:00	430904	REPAIRED GEARBOX & REPLACED CLUTCH & FLYWHEEL, ISSUES CHANGING GEARS, ROUGH RIDE, BEING TOWED TO VCV NEWCASTLE 26/6/24., CHECK FOR VIBRATION, GEARBOX REAR BEARING FAILED - INSPECTED GEARBOX IN DRIVEWAY, REFILLED WITH OIL & TOOK SAMPLE,, JUMP STARTED VEHICLE DUE TO BEING FLAT, CHECKED DRIVELINE ANGLES & MEASURED SUSPENSION HEIGHTS, EXAMINED, LEVELLING RODS & FOUND ONE BENT, REMOVED GEARBOX & CLUTCH TO INSPECT, WILL REQUIRE NEW GEARBOX, DISCUSSED, WITH CUSTOMER., FAILED GEARBOX - CARRY OUT DIAGNOSIS WHY TRANSMISSION HAS FAILED & REPORT BACK TO CUSTOMER, CHECK RIDE, HEIGHTS, FOUND RUNNING AT DUMPED HEIGHT, THE CAUSE WAS THE AIR HEIGHT VALVE MOUNTING APPEARED DAMAGED &, BENT, STRAIGHTEN MOUNT BRACKET & CHECK CLEARANCE THROUGHOUT TRAVEL, ADJUST HEIGHT TO 240MM ON REAR AXLE,, MEASURE DRIVELINE ANGLES, RUN THROUGH DRIVELINE ANALYSER PROGRAMME, OK, REMOVE TRANSMISSION, FIT CORRECT, INPUT & CHANGE OVER OUTPUT HOUSING & FLANGE, REPLACE CLUTCH DUE TO DAMAGE ON FLYWHEEL WITH CLUTCH PLATE, WHIPPING, REASSEMBLE & FIT TRANSMISSION, FIT PIPING/OIL/PTO AS NEEDED, TEST DRIVE & CHECK OVER., REPLACE MISSING REAR MUDFLAP., PO 201863 - VCV NEWCASTLE	MR - MECHANICAL REPAIR
P33-N-058	TIPPER 10T HINO	233931	02/07/2024 0:00	419503	INSPECTION & QUOTE OF GEARBOX FAULT, VEHICLE TOWED INTO YARD & ONTO HEAVY VEHICLE HOIST, RAISE TIPPER BODY FOR INSPECTION OF GEARBOX FAULT,, QUOTED JOB, HOWEVER VEHICLE WAS RETURNED TO OTHER WORKSHOP FOR WARRANTY REPAIR, REASSEMBLED, SURROUNDING JOB SO VEHICLE COULD BE REMOVED FROM HOIST FOR URGENT TOW, TOWED VEHICLE OFF HOIST, ONTO STREET FOR COLLECTION., INCL - VEHICLE STORAGE/HOIST HOLD UP CHARGE FOR 6 WEEKS., PO 201448 - CPR	BM - BREAKDOWN - MECHANICAL
P33-N-058	HINO HD SS2848 AIR	232098	01/07/2024 0:00	419503	WORK ORDER CANCELLED. WARRANTY REPAIR., ISSUES CHANGING GEARS, ROUGH RIDE, PO CANCELLED FOR CPR - PP MANAGER CONTACTING WAGGA TRUCKS REGARDING WARRANTY	GR - GENERAL REPAIRS
P33-N-058	HINO HD SS2848 AIR	233383	01/06/2024 0:00	419503	REPAIRED HYDRAULIC OIL LEAK, DEFECT CLEARANCE - HYDRAULIC OIL LEAK, PO 200955 - CPR	HR - HYDRAULIC REPAIR

P33-N-058	HINO HD SS2848 AIR	226901	01/03/2024 0:00	419272	<p>FITTED NEW TRANSMISSION, POSSIBLE CLUTCH FAILED - TRUCK TOWED TO WORKSHOP., LIFTED TRUCK ON HOIST, DRAINED TRANS OIL, REMOVED TAILSHAFT, PTO PUMP &amp; PTO, FOUND DAMAGE ON OUTPUT OF, TRANSMISSION, REMOVED AIR LINES &amp; AUX SECTION OF TRANSMISSION, FOUND EXTENSIVE DAMAGE, REMOVED GEAR LINKAGES, &amp; WIRING, REMOVED TRANSMISSION, REMOVED CLUTCH &amp; INSPECTED, FOUND CLUTCH WORN, REMOVED FLYWHEEL &amp; HAD, MACHINED, FOUND LEAKING REAR MAIN CRANK SEAL, REPLACED CRANK SEAL, REFITTED FLYWHEEL WITH NEW CLUTCH., DUE TO EXTENSIVE DAMAGE ORDERED EXCHANGE TRANSMISSION, SWAPPED REQD PARTS TO TRANSMISSION INCL BELLHOUSING., GEAR SELECTOR ON TRANSMISSION BADLY WORN, ORDERED NEW PART &amp; FITTED, FITTED TRANSMISSION, CONNECTED ALL, SHIFT LINKAGES, WIRING, FITTED PTO &amp; SHIMMED, FITTED PUMP, FITTED TAILSHAFT, FILLED WITH OIL, ADJUSTED CLUTCH, WASHED, DOWN &amp; ROAD TESTED. FOUND BAD DRIVELINE VIBRATION., TEST DRIVE TRUCK, FOUND BAD VIBRATION ON BODY CAN BE FELT, CHECK RIDE HEIGHT, CHANGE TO MINIMUM, TEST DRIVE AGAIN,, VIBRATION STILL THERE, CHANGE RIDE HEIGHT TO MAXIMUM, TEST DRIVE, VIBRATION STILL THERE. CHECK DRIVELINE ANGLES, &amp; SET RIDE HEIGHT TO MIDDLE, TEST DRIVE, VIBRATION STILL THERE. REMOVE JACKSHAFT &amp; DRIVE, STILL VIBRATING, REMOVE, PROF SHAFT FROM GEARBOX &amp; SECURE, TEST ENGAGE GEARBOX ON DRIVE, ALL OK, NO VIBRATION, REMOVE PROF SHAFT., REPAIR JACK SHAFT &amp; PROF SHAFT BY CONTRACTOR, REFIT REPAIRED UNITS, TEST DRIVE, NOT OK. SWITCH TYRES THAT MATCH, THE CONDITION - 1ST DIFF RHS &amp; 2ND DIFF LHS, TEST DRIVE, NOT OK, INSTALL 2.5 WEDGES ON 1ST DRIVE DIFF, CHECK ANGLE., WITHIN SPEC, TEST DRIVE, NOT OK. REMOVE ALL DRIVE TYRES &amp; FIT NEW TYRES FROM STOCK, TEST DRIVE, NOT OK BUT BETTER., REFIT PROF SHAFT, SECURE &amp; TIGHTEN SCREWS, ALL OK. DROP DOWN TRUCK &amp; TEST DRIVE, VIBRATION IS LESS THAN INITIAL, TEST DRIVES, REMOVE ALL TYRES ON DRIVE, REFIT ORIGINAL TYRES, REFIT JACK SHAFT, TEST DRIVE, SMALL AMOUNTS OF, VIBRATION, CHECK OVER ALL DRIVE ANGLES, RIDE HEIGHT &amp; SENT SPECS TO HINO, HINO ADVISED TO INSTALL NEW WEDGES, &amp; REDUCE TO 0.5, REPLACE WEDGES FROM 2.5 TO 0.5, TENSIONED U BOLTS, ALL OK, TEST DRIVE, ALL OK - VIBRATION GONE., DOUBLE CHECK U BOLT TENSION, CHECK OVER PROF SHAFT BOLTS, ALL OK, CHECK OVER OUTPUT SHAFT GEARBOX PLAY., ALL OK., PO 194647 - WAGGA TRUCKS, FIT NEW CLUTCH &amp; EXCHANGE GEARBOX AS PER QUOTE ATTACHED - CHRIS C APPROVED 19/1/24, DAVID S APPROVED AN EXTRA \$1350.50 FOR TRANSMISSION LEVER &amp; REAR CRANKSHAFT SEAL NEED TO BE REPLACED, TOTAL \$22,202.75, BROCK APPROVED AN EXTRA \$\$4812.50 FOR SLIP JOINT &amp; SHAFT TUBE REPLACE/REPAIRS, TOTAL \$27,015.25</p>	BM - BREAKDOWN - MECHANICAL
P33-N-058	HINO HD SS2848 AIR	227214	01/02/2024 0:00	419503	<p>REPLACED DAMAGED WINDSCREEN., NB: SUBLET TO WAGGA WINDSCREEN DOCTOR, PO 194999 - WAGGA TRUCKS</p>	CD - CUSTOMER DAMAGE
P33-N-058	HINO HD SS2848 AIR	226324	31/01/2024 0:00	414083	<p>CARRIED OUT DEFECT REPAIRS &amp; CLEARANCE, HVIS REPAIRS - AS PER ATTACHED - DEFECT#AHV1486912, ON AXLE 2 - MORE THAN 30% BRAKE IMBALANCE BETWEEN WHEELS (LHS LOW EFFICIENCY), CARRIED OUT BRAKE ADJUSTMENT., ON AXLE 3 - MORE THAN 30% BRAKE IMBALANCE BETWEEN WHEELS (LHS LOW EFFICIENCY), CARRIED OUT BRAKE ADJUSTMENT., TRANSMISSION OIL LEAK FROM REAR OF TRANSMISSION AREA, INSPECTED LEAK, COMING FROM THE FLANGE AT THE BACK OF, THE GEARBOX., GOING INTO LIMP MODE &amp; THEN IT JUST DIES., PO 194102 - ALLTRACK ENGINEERING</p>	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	225390	28/11/2023 0:00	414083	<p>CARRIED OUT REGO INSPECTION PINK SLIP, CARRIED OUT REGO CHECK, CHECKED FOR AIR LEAK ON LHS BODY AIRBAG, FOUND 2 ON THE MAIN AIR LINE ON CAB, &amp; ONE AT JOINER, REPAIRED ALL, BOTH OK., PO 193107 - ALLTRACK ENGINEERING</p>	PI - PLANT INSPECTION
P33-N-058	HINO HD SS2848 AIR	222429	01/10/2023 0:00	402038	<p>SUPPLIED FUEL CAP, PO 190043 - ALLTRACK ENGINEERING</p>	GR - GENERAL REPAIRS
P33-N-058	HINO HD SS2848 AIR	222160	31/08/2023 0:00	402038	<p>CARRIED OUT TRUCK SERVICE, REPLACED ENGINE OIL &amp; OIL FILTER, REPLACED AIR FILTER &amp; FUEL FILTER, CHECKED &amp; ADJUSTED FLUID LEVELS., CHECKED ALL BRAKES &amp; CARRIED OUT ADJUSTMENT, CHECKED TYRES &amp; PRESSURE, FILLED WASHER BOTTLE., GREASED ALL GREASE POINTS, TEST DRIVE., PO 188792 - ALLTRACK ENGINEERING</p>	PS - PLANNED SERVICE
P33-N-058	HINO HD SS2848 AIR	221345	31/08/2023 0:00	402038	<p>REPAIRED AIRCON, REMOVE COMPRESSOR &amp; DRAIN OIL TO CHECK FOR CONTAMINANTS, OIL HAS METAL FLAKES THROUGHOUT., RECOMMEND FLUSH &amp; REPLACE RECEIVER DRIER., REMOVED RECEIVER DRIER &amp; FLUSH ALL A/C COMPONENTS THOROUGHLY, S &amp; F NEW A/C BELT, COMPRESSOR &amp;, RECEIVER DRIER, COMPLETED REGAS &amp; CHECKED OPERATION OF A/C SYSTEM, PRESSURES LOOK GOOD &amp; VENT, TEMPERATURE IS COLD., PO 188792 - ALLTRACK ENGINEERING, QUOTE APPROVED BY DAVID S ON 17/8</p>	AC - AIR-CONDITION REPAIR

P33-N-058	HINO HD SS2848 AIR	220378	27/07/2023 0:00	401413	REPLACED RING FEEDER, ATTEND TRUCK IN FH YARD, SUPPLY, INSTALL & WIRE UP NEW TRAILER SOCKET & TEST ALL OUTPUTS, ALL GOOD., CHECK OPERATION OF BOTH REVERSE CAMERAS, ALL WORKING., COLLECT TRUCK FROM FH YARD, START PROCESS OF REMOVING RING FEEDER, REMOVE OLD RING FEEDER & CLEAN UP MOUNT., S & F NEW BUSHINGS, S & F NEW RING FEEDER, TENSIONED RETAINING NUT WITH BAR & POLE, FIT SPLIT PIN, FIT DUST COVER., TEST OPERATION, ALL GOOD., PO 187680 - ALLTRACK ENGINEERING, AS PER QUOTE ATTACHED - APPROVED BY ALISTAIR	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	215980	01/06/2023 0:00	384459	S & F NEW BLOWER FAN, CALL OUT TO FH YARD, BLOWER FAN MOTOR NEEDS REPLACING, S & F NEW BLOWER FAN., PO 183196 - ALLTRACK ENGINEERING	AC - AIR-CONDITION REPAIR
P33-N-058	HINO HD SS2848 AIR	213667	01/04/2023 0:00	378244	REPLACED NOX SENSOR & ADBLUE FILTER, INJECTOR & NOZZLE, 8/2/23 - ISSUE CAUSING THE TRUCK TO GO INTO LIMP MODE, INSPECTED SYSTEM FOR CAUSE OF DERATING., FOUND NOX SENSOR FAULTY READING, INSPECTED ADBLUE NOZZLE & FOUND IT BLOCKED, TESTED ADBLUE, PUMP & FOUND IT HAS FLOW. SPOKE WITH JAMIE & DECIDED TO REPLACE ADBLUE NOZZLE & FILTER BEFORE, WE WASH THE TANK AND/OR REPLACE PUMP., 9/2/23 - REPLACED ADBLUE NOZZLE & ADBLUE FILTER, RAN ENGINE & CARRIED OUT FAULT CODE TEST., FOUND CODE P204F, FOLLOWED INSTRUCTIONS FROM DAVID & ORDERED NEW NOX SENSORS., 14/2/23 - SERVICE CALL TO GROVES AVE, REPLACED NOX SENSORS, INSPECTED & CLEANED BATTERY, TERMINALS, WAS ABLE TO CLEAR CODES, DOWN TO COMMUNICATION ERROR WITH MY COMPUTER., PO 180572 - RYAN HALL SPEED CENTRE - PH:0422 834 421, 16/2/23 - LIMP MODE, CHECKED ALL RELEVANT CIRCUITS, SENSORS & HARNESS CONNECTIONS & ROAD TESTED., CARRIED OUT SYSTEMS RESETS, ERASED STORED DTC'S & RETESTED, NO FAULTS EVIDENT DURING, TESTING, ALL OPERATING WITHIN SPECS., PO 180659 - CITY HINO NSW	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	213698	21/02/2023 0:00	383570	CARRIED OUT PLANNED SERVICE, REPLACED ENGINE OIL & OIL FILTER, REPLACED AIR FILTER & FUEL FILTER, CARRIED OUT BRAKE ADJUSTMENT., REMOVED & REPLACED DIFF PLUG, GREASED, FILLED WASHER BOTTLE, TEST DRIVE., SCAN TRUCK & CHECK FOR TRUCK DERATING, UNABLE TO DIAGNOSE, TRUCK TO BE TAKEN TO HINO., PO 180128 - ALLTRACK ENGINEERING	PS - PLANNED SERVICE
P33-N-058	HINO HD SS2848 AIR	214110	21/02/2023 0:00	384459	CARRIED OUT AIRCON REPAIRS, CHECK VEHICLE FOR A/C NOT COLD, FOUND SYSTEM LOW ON GAS, CHECK SYSTEM FOR LEAKS, NOTHING OBVIOUS., COMPLETED REGAS & CHECKED OPERATION OF A/C SYSTEM, PRESSURES LOOK GOOD & VENT TEMP IS 10 DEGREES, CELSIUS, BLEW DEBRIS OUT OF CONDENSOR WITH COMPRESSED AIR., NOTE - INTERIOR FAN IS NOISY, RECOMMEND REPLACEMENT IF MORE PROBLEMS OCCUR., PO 181029 - ALLTRACK ENGINEERING	AC - AIR-CONDITION REPAIR
P33-N-058	HINO HD SS2848 AIR	210040	01/02/2023 0:00	372380	CARRIED OUT SCAN OF FAULT CODES, DERATE, FULL CHECK OVER, ENGINE LIGHT ON VEHICLE, OVERHEATING, EXCESSIVE MOVMENT FROM OUTPUT SHAFT ON WO# 210271, 8/11/22 - CARRIED OUT SCAN OF FAULT CODES - ENGINE LIGHT ON, MULTIPLE CODES DETECTED & CLEARED, RAN TRUCK & FOUND NO ENGINE LIGHT RETURNING., PO 177168 - ALLTRACK ENGINEERING	ER - ELECTRICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	211518	14/12/2022 0:00	378244	CARRIED OUT REGO INSPECTION & REPAIRS, CARRY OUT PRE RMS INSPECTION, CARRY OUT NECESSARY REPAIRS INCL LIGHTING & ELECTRICAL REPAIRS., DIAGNOSE & REPAIR MULTIPLE AIR LEAKS, REMOVE & REPLACE AIR HOSE, REMOVE & REPLACE DOUBLE END, FITTING, ROAD TEST & CHECK AIR LEAKS, ALL GOOD., PO 178575 - ALLTRACK ENGINEERING	RE - REGISTRATION
P33-N-058	HINO HD SS2848 AIR	210862	01/12/2022 0:00	370015	REPLACED LOST FUEL CAP WITH LOCKING ONE., PO 177906 - ALLTRACK ENGINEERING	CD - CUSTOMER DAMAGE
P33-N-058	HINO HD SS2848 AIR	210271	28/11/2022 0:00	374772	CARRIED OUT HEAVY VEHICLE REGO CHECK, VEHICLE REGISTRATION INSPECTION, PO 177351 - ALLTRACK ENGINEERING, BOOKED @ ALLTRACK 5/12/22 HVIS INSPECTION 15/12/22, NSW 21/9/22 EXCESSIVE MOVEMENT IN GEARBOX OUTPUT SHAFT	RE - REGISTRATION
P33-N-058	HINO HD SS2848 AIR	208296	21/09/2022 0:00	370015	CARRIED OUT 370KM SERVICE, REPLACED ALL FILTERS INCL OIL, FUEL & AIR FILTERS., REPLACED ENGINE OIL & CHECKED ALL FLUID LEVELS., BRAKES - FRONT 3MM, REAR 5-6MM, TYRES - FRONT 70% APPROX, REAR 90% APPROX., PO 175224 - ALLTRACK ENGINEERING	PS - PLANNED SERVICE

P33-N-058	HINO HD SS2848 AIR	208338	16/09/2022 0:00	367106	REPAIRED PTO OPERATION, FAULT WITH PTO NO RAISING PROPERLY, TEST PUMP, DUMP OIL, REMOVE PUMP & REPLACE., FIT NEW BREATHER & RETURN FILTER, WHEN FITTING FILTER REALISED FILTER HOUSING, ASSEMBLY DAMAGED, EMPTY OIL OUT AGAIN, REMOVE TANK, RECOVER OLD FILTER &, COMPONENTS OUT OF TANK, CLEAN OUT TANK & REFIT, FILL WITH OIL & TEST., PO 175282 BH - BREAKDOWN - HYDRAULIC - HAWKESBURY HYDRAULICS, FULTON HOGAN SUPPLIED A PO INSTEAD OF CONTACTING PORTER PLANT FOR A PO., BRAD WILL PAY BY EFT & THEN HAWKESBURY HYD WILL SEND NEW INVOICE WITH OUR DETAILS ON IT.	
P33-N-058	HINO HD SS2848 AIR	206723	09/08/2022 0:00	367106	REPLACED WORN SELECTOR LINKAGE ON GEARBOX, 2/8/22 - DIAGNOSE & REPAIR SELECTOR LINKAGE, REMOVED & REPLACED SELECTOR LINKAGE BALL JOINT., PO#173706 - ALLTRACK ENGINEERING	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	203016	28/05/2022 0:00	360658	CARRIED OUT SCHEDULED TRUCK SERVICE, REPLACED ENGINE OIL & OIL FILTER, REPLACED FUEL FILTER & AIR FILTER, CHECKED ALL FLUIDS & LIGHTS, GREASED., PO#170097 - ALLTRACK ENGINEERING	PS - PLANNED SERVICE
P33-N-058	HINO HD SS2848 AIR	199805	27/05/2022 0:00	354233	S & F NEW EXCHANGED SUPPLY PUMP, CHECK AS VEHICLE LOOSES POWER, CARRIED OUT TRUCK SCAN & CHECKED FUEL PRESSURES, NEEDS TO BE SENT AWAY FOR CHECKS, FOR OVERHAUL. FITTED EXCHANGED SUPPLY PUMP (6MTHS WARRANTY ONLY ON PART), BLEED FUEL SYSTEM & ROAD TEST, OK., WARRANTY REPAIR - REBOUND ROLLER RECALL HT04008062E0, REPLACED REBOUND ROLLER., PO#166663 - CITY HINO IVECO - ARNDELL PARK	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	203523	26/05/2022 0:00	361147	REPAIRED OPERATION OF HEADLIGHTS, 20/5/22 - CHECK & ADJUST CLUTCH. CHECK VEHICLE FOR HIGH BEAM/SPOT LIGHTS, INOPERATIVE, FOUND MISSING POWER FEED TO SPOT LIGHT RELAY, LOCATED, OPEN CIRCUIT & REPAIRED, TEST OPERATION, ALL GOOD., PO#170685 - ALLTRACK ENGINEERING	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	194740	25/11/2021 0:00	351197	CARRIED OUT 350KM SERVICE & REPAIRS, 27/9/21-1/10/21 - REPLACED OIL, AIR & FUEL FILTERS, REPLACED ENGINE OIL, PRIME FUEL SYSTEM, GREASE &, CARRY OUT SAFETY CHECK., DIAGNOSE STEERING ISSUES, CHECK OVER ALL SUSPENSION COMPONENTS, REPLACE 4 CONTROL ARM TRACK RODS/, TORQUE RODS, REMOVE, REPAIR & REPLACE STEERING COLUMN, ROAD TEST, ALL OK., PO 161192 - ALLTRACK ENGINEERING	PS - PLANNED SERVICE
P33-N-058	HINO HD SS2848 AIR	195732	12/11/2021 0:00	344579	CARRIED OUT DEFECT REPAIRS & CLEAR DEFECTS, CARRY OUT REPAIRS TO OBTAIN REGO INSPECTION, PO# 162305	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	196544	12/11/2021 0:00	344579	CARRIED OUT PRE REGO CHECK, 20/10/21 - CARRY OUT PRE RMS INSPECTION AT WORKSHOP, CHECK OVER ALL COMPONENTS INCL SUSPENSION & BRAKES, LIGHTING,, EXTERIOR & INTERIOR OF BODY, REPORT FINDINGS TO CUSTOMER., PO 162305 - ALLTRACK ENGINEERING	RE - REGISTRATION
P33-N-058	HINO HD SS2848 AIR	194831	29/09/2021 0:00	344579	CARRIED OUT REPAIRS TO DPF SYSTEM, 30/6/21 - DIAGNOSE ENGINE LIGHT ON, CHECK FAULT CODES, FOUND MALFUNCTION OF SCR & NOX SENSOR, CLEAR CODES, RESET, PARAMETERS, CHECK ENGINE LIGHT, OK, IF PROBLEM PERSISTS, NOX SENSORS WILL NEED TO BE REPLACED., 8/7/21 - TRUCK RETURNED WITH RECURRING LIGHT, RETEST & SCANNED CODES, REMOVED & REPLACED BOTH NOX SENSORS,, ROAD TEST, ALL OK., PO 161294 - ALLTRACK ENGINEERING	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	189906	19/05/2021 0:00	341318	CARRIED OUT 340KM SERVICE, REPLACED ENGINE OIL & OIL FILTER, REPLACED AIR FILTERS & FUEL FILTERS, REPLACED DRIVE BELT, OIL FILTER &, BREATHER FILTER, REPLACED 3 X WIPER INSERTS, BLEED FUEL SYSTEM & START TRUCK, GREASE ALL POINTS, TEST DRIVE, OK., P/O 155776	PS - PLANNED SERVICE
P33-N-058	HINO HD SS2848 AIR	188972	27/04/2021 0:00	339286	REBUILD STEERING BOX, 21/4/21 - ADJUSTED FREE PLAY IN STEERING, PO 154494, 27/4/21 - DIAGNOSE STEERING BOX TO BE FAULTY, REMOVE STEERING COLUMN & ALLOW REMOVAL OF STEERING BOX, UNBOLT & REMOVE, STEERING BOX, GET REPLACEMENT, REBUILD STEERING BOX & FIT TO TRUCK, RE-ALIGN ALL STEERING COMPONENTS & REFIT, FILL WITH, OIL & CONNECT ALL PUMP HOSES, START TRUCK & BLEED SYSTEM, TEST DRIVE, ALL OK., PO 154494	BM - BREAKDOWN - MECHANICAL
P33-N-058	HINO HD SS2848 AIR	188971	21/04/2021 0:00	338268	REPAIRED REVERSE CAMERA, REWIRED CAMERA CABLES & FIT NEW REVERSE CAMERA MONITOR., PO 154494	ER - ELECTRICAL REPAIR

P33-N-058	HINO HD SS2848 AIR	188742	01/04/2021 0:00	335543	CARRIED OUT MAJOR REPAIRS, CHECKED & FOUND FRONT SHOCKS LEAKING, DRAG LINK & FRONT TIE RODS HAVE EXCESSIVE MOVEMENT, REPLACED WORN FRONT, SHOCKS, DRAG LINK & TIE ROD END MOUNTS SEIZED IN PLACE, HEATED COMPONENTS & REMOVED, FITTED NEW DRAG LINK & TIE ROD, ENDS, CARRIED OUT FRONT STEER ALIGNMENT, CONNECTED 7MM OF TOE & 2 DEGREES OF CASTOR, VEHICLE NOW TRACKING STRAIGHT, & FRONT END MUCH TIGHTER. CHECKED & FOUND RING FEEDER LOCKING UP INTERNALLY, UNABLE TO REBUILD, HOUSING WORN,, REMOVED & REPLACED RING FEEDER., PO 154448	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	187119	01/03/2021 0:00	331909	REPLACED MAIN POWER SWITCH FOR SPREADER PANEL, CUSTOMER REPORTED TRAILER LIGHTS INOPERABLE, DIAGNOSE SPREADER SWITCH PANEL INOPERABLE, ON INSPECTION MAIN POWER, SWITCH LOOSE ON SPREADER PANEL & OPEN CIRCUIT, REMOVED & REPLACED MAIN POWER SWITCH, TESTED OPERATION, OK, CHECK, LIGHTING OPERATION, ALL OK AT TIME OF INSPECTION., P/O 152747	ER - ELECTRICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	183478	25/11/2020 0:00	324625	REPAIRED DEFECTS FROM RMS REGISTRATION INSPECTION., CARRIED OUT REPAIRS & CLEARED DEFECTS. REPLACED LHS MIRROR. REPLACED MUDFLAPS & REAR MARKER PLATES. FITTED AIR, BRAKE VALVE. TIGHTENED ALL AIR FITTINGS. WIRED UP NEW TAIL LIGHT. TESTED ALL FUNCTIONS & ROAD TESTED. CLEARED DEFECTS., P/O 148933	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	178980	01/09/2020 0:00	321908	CHECKED ENGINE LIGHT ON & REPLACED AIR TANK AIR FITTING., CUT OUT OLD TRACK ROD BARS SEIZED INTO BRACKETS & REPLACED., REPAIRED AXLE 3 TOP SHOCK MOUNTS. REPLACED ALL REAR SHOCKS., REPLACED UNDERSIZED SHOCK MOUNTING BOLTS. REPLACED AIR TANK, AIR FITTING. WELDED SPLITS IN SIDE OF AIR TANK FROM RUBBING, ON FRAME RAILS. REPAIRED AIR TANK BRACKET & REMOUNTED TANK, CENTRALISED TO AVOID RUBBING. REPLACED LHS MIRROR EXTERIOR, HOUSING. REPLACED NUMBER PLATE LIGHT. PTO SWITCH APPEARED, TO BE WORKING CORRECTLY. CHECKED ENGINE LIGHT ON P204F, CATALYST REDUCTION PROBLEM ADVISE CUSTOMER TO SEE DEALER., NO DIFFERENTIAL PRESSURE SENSOR READING., P/O 144419	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	178601	01/08/2020 0:00	321906	REPAIRED DRIVER SEAT., DIAGNOSED & REPAIRED DRIVERS SEAT. FOUND SEAT INTERNALS, FAULTY. REMOVED & STRIPPED SEAT. FOUND BROKEN DAMPENER AIR, BAG. REPLACED WITH NEW PARTS & REASSEMBLED. REFITTED SEAT, & ADJUSTED., P/O 144034	GR - GENERAL REPAIRS
P33-N-058	HINO HD SS2848 AIR	172148	01/05/2020 0:00	313405	CLEANED OUT RADIATOR & INTERCOOLER. TESTED - OK, REPAIR OVERHEATING ISSUE, P/O 138592	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	173520	01/05/2020 0:00	313892	REPLACED FAILED CLUTCH & MACHINED FLYWHEEL., BLED & ADJUSTED CLUTCH. REPLACED GEARBOX OIL., REPAIRED AIR LEAKS. REPAIRED DRIVERS SEAT BASE. FITTED NEW, CONTROL PANEL. REPLACED SEAT SHOCK ABSORBER. REPLACED, HEIGHT CONTROL VALVE. REPLACED FAULTY DRIVING LIGHTS., P/O 139824	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	173247	01/04/2020 0:00	303075	REPLACED LEAKING A/C PIPE. RECHARGED A/C SYSTEM. TESTED., CHECK A/C NOT WORKING. FOUND LEAKING PIPE., P/O 139564	AC - AIR-CONDITION REPAIR
P33-N-058	HINO HD SS2848 AIR	171989	23/03/2020 0:00	312779	REPLACED WORN STEER TYRES., P/O 138461	TC - TYRE CHANGE/REPLACEMENT
P33-N-058	HINO HD SS2848 AIR	170647	01/02/2020 0:00	305449	REPAIRED DEFECTS & COMPLETED REGO CLEARANCE., REPLACED BLOWN CLEARANCE LIGHT ON LHF OF CAB. REPAIRED, FAULTY WINDSCREEN WASHERS & FILLED RESERVOIR. CHECKED, REPORTS SPEEDO NOT WORKING & ENGINE LIGHT ON. CHECKED CODES, FOUND P0500 - VEHICLE SPEED SENSOR. CLEARED CODES & ROAD, TESTED. ENGINE LIGHT CAME ON & SPEEDO STOPPED WORKING., FITTED NEW SPED SENSOR, CLEARED CODES & ROAD TESTED - OK., P/O 133967	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	167337	01/02/2020 0:00	305449	COMPLETED 300,000km SERVICE. REPLACED OIL, AIR, FUEL FILTERS, REPACKED WHEEL BEARINGS. COMPLETED ENGINE TUNE UP., REPLACED EXHAUST MANIFOLD GASKETS. CHECKED OVER. GREASED., P/O 133967	PS - PLANNED SERVICE
P33-N-058	HINO HD SS2848 AIR	167563	01/02/2020 0:00	305449	REPLACED FAILED A/C COMPRESSOR., CHECKED A/C. FOUND FAULTY PRESSURE SWITCH & BADLY, CONTAMINATED OIL DUE TO FAILING A/V COMPRESSOR. SOURCED NEW, PRESSURE SWITCH & RECEIVER DRIER & FITTED SUPPLIED, COMPRESSOR AND COMPLETED SYSTEM FLUSH. VAC SYSTEM & CHARGE, WITH REFRIGERANT. TESTED, ALL OK., P/O 133967	AC - AIR-CONDITION REPAIR

P33-N-058	HINO HD SS2848 AIR	170648	01/02/2020 0:00	305449	REPAIRED LEAKING HYDRAULIC PUMP. REPAIRED AIR LEAKS., CHECKED FOR PTO GETTING STUCK HALFWAY UP. FOUND & REPAIRED, AIR LEAK ON DIVERTER VALVE. REPLACED PUSH FITTING. FOUND, FURTHER AIR LEAKS AT ELECTRIC OVER AIR SOLENOIDS FOR HYD, CONTROLS. REPAIRED SOLENOIDS. MORE AIR LEAKS FOUND AT HOIST, VALVE. REMOVED HOIST VALVE AND HAD REPAIRED. REFITTED TO, TRUCK. FOUND HYD PUMP LEAKING OIL, DRAINED & SAVED HYD OIL., SPLIT PUMP FROM PTO. CLEANED & TOOK FOR REPAIR. REFITTED, TO TRUCK. FILLED WITH OIL & TESTED - ALL OK., P/O 133967	HR - HYDRAULIC REPAIR
P33-N-058	HINO HD SS2848 AIR	167460	11/12/2019 0:00	298126	R#I-0350334865	RE - REGISTRATION
P33-N-058	HINO HD SS2848 AIR	166006	12/11/2019 0:00	298126	R#P18003258836	RE - REGISTRATION
P33-N-058	HINO HD SS2848 AIR	163935	30/09/2019 0:00	298126	STRAIGHTENED STEERING WHEEL. REPLACED HYD SIGHT GLASS., REMOVED STEERING SHAFT AT STEERING BOX. STRAIGHTENED, STEERING WHEEL & REFITTED SHAFT, CHECKED ALL OK, CHECKED HYDRAULIC OIL LEAK. REPLACED SIGHT GLASS, CHECKED, ALL OK., P/O 130656	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	163858	26/09/2019 0:00	297308	REPAIRED BROKEN REAR CROSS MEMBER., ATTENDED TRUCK BROKEN DOWN WITH COMPLAINT OF AIR LOSS. UPON, INSPECTION FOUND REAR CROSS MEMBER & AIR TANK SNAPPED OFF/, OUT. TEMPORARILY REPAIRED AIR LINES TO BUILD UP AIR TO GET, VEHICLE TO WORKSHOP. CUT OUT OLD CROSSBEAM, FABRICATED NEW, BEAM & WELDED INTO POSITION. INSTALLED NEW SHOCK &, INSTALLED AIR TANK. FOUND BROKEN WIRING ON REAR DIFF., JOINED WIRES & COVERED WITH CONDUIT. SECURED INTO PLACE,, ALL OK, P/O 130577	BM - BREAKDOWN - MECHANICAL
P33-N-058	HINO HD SS2848 AIR	161183	02/08/2019 0:00	292392	COMPLETED 290,000km SERVICE. REPLACED ENGINE OIL & FILTER, REFITTED MUDFLAP ON LHR., BRAKES: FRONT & REAR 50%, P/O 128100	PS - PLANNED SERVICE
P33-N-058	HINO HD SS2848 AIR	160876	30/07/2019 0:00	280208	REPLACED HYDRAULIC PUMP, INSPECTED COMPLAINT OF GEARBOX LEAKING & GETTING HOT., BROUGHT TRUCK TO SHED & CHECKED GEARBOX LEVEL. FOUND IT TO, BE OVERFULL. TOOK TO WASH BAY & CLEANED DOWN LEAK. BROUGHT, BACK INTO SHED & DRAINED ALL HYDRAULIC & GEARBOX OIL., REMOVED PTO - WASHED & TOOK TO SUBCONTRACTORS FOR REPAIRS., PUMP WAS FOUND TO BE UNSERVICEABLE, A NEW PUMP WAS SUPPLIED, BY SUBCONTRACTOR. FITTED PTO & CHECKED BACKLASH. ALL OK., SHORTENED MAIN SUPPLY HOSE ON PTO. FILLED HYDRAULIC TANK, & GEARBOX UP. STARTED & TESTED, TEST DROVE & WASHED DOWN., REINSPECTED, ALL OK., SUBCON COMMENTS - INSPECTED PTO PUMP AS IT WAS PUMPING OIL, INTO THE GEARBOX. DISMANTLED PUMP & INSPECTED. UPON, EXAMINATION, FOUND SIGNIFICANT DAMAGE & PUMP TO BE, UNSERVICEABLE. ORDERED NEW PUMP. DISMANTLED, STRIPPED, & ASSESSED PTO. ORDERED NEW SEALS & RESEALED. INSTALLED, EXISTING FITTINGS FROM OLD TO NEW & REASSEMBLED., P/O 127801	HR - HYDRAULIC REPAIR
P33-N-058	HINO HD SS2848 AIR	160029	10/07/2019 0:00	290246	ADJUSTED CLUTCH., CHECKED CLUTCH & OPERATION. FOUND TO BE WAY OUT OF, ADJUSTMENT. CARRIED OUT CLUTCH ADJUSTMENT & TEST DROVE, ALL OK., P/O 126999	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	159018	20/06/2019 0:00	287840	REPLACED FAILED COMMON RAIL LIMITER VALVE., CONNECTED LAPTOP & READ FAULT CODES. CHECKED & TESTED FUEL, SYSTEM. CHECKED ALL ENGINE WIRING PLUGS & HARNESSSES. CHECKED, COMMON RAIL PRESSURE SENSOR ALL OK. REMOVED COMMON RAIL, LIMITER VALVE & SWAPPED WITH TEST UNIT. TEST DROVE. VEHICLE, DID NOT FAULT. ORDERED NEW LIMITER VALVE AND FITTED. CONNECT, LAPTOP & TEST DROVE. CLEARED ALL STORED FAULTS. PRESSURE, CLEANED ENGINE & CHASSIS. ALL OK., P/O 126267	BM - BREAKDOWN - MECHANICAL
P33-N-058	HINO HD SS2848 AIR	157426	01/06/2019 0:00	287598	REPLACED FAILED AIR COMPRESSOR, CHECKED ENGINE LIGHT FLASHING, & AD BLUE LIGHT ON. CHECKED, CODES, TESTED ADBLUE PUMP & INJECTOR, RESET SCR MEMORY., CARRIED OUT 3 DRIVE CYCLES. CLEARED ALL FAULT CODES., DRAINED COOLANT, REMOVED INTAKE PIPING & COOLANT PIPING, TO AIR COMPRESSOR. REMOVED DRIVE GEAR FROM OLD COMPRESSOR, & FITTED TO NEW. FITTED AIR COMPRESSOR USING NEW SEALS O', RINGS & SECURED. REFITTED ALL HOSES & PIPING & SECURED., REFILLED COOLING SYSTEM. PRESSURE CLEANED, CARRIED OUT, TEST DRIVE, CHECKED FOR LEAKS & TOPPED UP COOLING SYSTEM., ALL OK., P/O 124853	BM - BREAKDOWN - MECHANICAL
P33-N-058	HINO HD SS2848 AIR	149653	06/03/2019 0:00	264248	CHECKED ENGINE LIGHT ON. CHECKED FAULT CODES, ALL OK., CHECKED WARNING LIGHTS ON DASH. FOUND ADBLUE WARNING ON, CONNECTED DIAGNOSTIC COMPUTER & CHECKED FOR FAULT CODES., NONE PRESENT. CARRIED OUT FUNCTION TESTS ON AD BLUE SYSTEM,, ALL TESTS OK. MORE DIAGNOSTICS REQUIRED., PO#118122	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	153302	01/03/2019 0:00	278090	REPLACED WORN DRIVE TYRES (POS 3-10), P/O 121332	TC - TYRE CHANGE/REPLACEMENT

P33-N-058	HINO HD SS2848 AIR	153884	01/03/2019 0:00	278090	REPLACE SECOND A/C HOSE & REGAS, P/O 121849, REPLACED FAULTY SECOND A/C HOSE & REGASSED AIR CONDITIONER, LOCATED FAULT WITH A/C. FOUND LOW ON GAS & FAULTY A/C HOSE., REPLACED A/C HOSE & COMPLETED AN A/C SERVICE. ADDED OIL &, DYE & PRESSURE TESTED, ALL OK., P/O 121849	AC - AIR-CONDITION REPAIR
P33-N-058	HINO HD SS2848 AIR	151258	22/01/2019 0:00	264248	REPLACED 2x TYRES., PO#119419	TC - TYRE CHANGE/REPLACEMENT
P33-N-058	HINO HD SS2848 AIR	148544	27/11/2018 0:00	264248	COMPLETED 260,000km SERVICE. REPLACED ENGINE OIL & FILTER, REPLACED FUEL FILTERS. GREASED., P/O 117080	PS - PLANNED SERVICE
P33-N-058	HINO HD SS2848 AIR	147409	26/11/2018 0:00	173746	REPLACED DAMAGED WINDSCREEN, PO#116048	CD - CUSTOMER DAMAGE
P33-N-058	HINO HD SS2848 AIR	147817	22/11/2018 0:00	264238	REPLACED BLOWN FUSE TO CHASSIS CONTROL & REVERSE LIGHTS., ABS LIGHT ON DASH, CHECKED FUSES, FOUND A CHASSIS CONTROL, FUSE BLOWN. HOOKED UP COMPUTER, FOUND FAULT CODE FOR AIR, WHEEL GAP., CARRIED OUT DATA MONITOR ON WHEEL SENSORS, LH 2nd DRIVE, WOULD ONLY START READING AT 20km, REMOVED WHEELS, BRAKE, DRUM, CLEANED OUT WHEEL, PUSHED SENSOR BACK IN TOWARDS WHEEL, REFITTED BRAKE DRUM AND WHEELS. TEST DROVE, CLEARED CODES, AND ABS LIGHT DIDN'T COME BACK ON, NO FURTHER PROBLEMS. ALL, OK., PO#116938, CARRIED OUT REPAIRS TO CLEAR DEFECTS AFTER PIT INSPECTION., AS PER DEFECT NOTICE #AHV1213051., TIGHTENED LOOSE BODY MOUNT BOLTS. FAULT FIND CAUSE OF, INOPERATIVE REVERSE LIGHTS. REMOVED, REPLACED AND WIRED IN, NEW REVERSE LIGHTS. LOCATED AND REPLACED BLOWN FUSES., REPLACED MISSING REFLECTORS. INSPECTED CRACK IN SUBFRAME., CARRIED OUT WELD REPAIRS AS REQUIRED. INSPECTED WEAR IN, REAR PIVOT POINTS. MANUFACTURED NEW PIN AND FIXED IN PLACE., WELDED CRACKS AS REQUIRED., NEED P/O 116460	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	148542	22/11/2018 0:00	256572	R#I-0333206229	RE - REGISTRATION
P33-N-058	HINO HD SS2848 AIR	148311	19/11/2018 0:00	256572	CTP R# P1809079783	RE - REGISTRATION
P33-N-058	HINO HD SS2848 AIR	145164	28/09/2018 0:00	256572	REPLACED CRACKED SITE GLASS. TOPPED UP HYDRAULIC OIL., CHECKED SMOKE COMING FROM GEARBOX AREA, OPERATED PTO, DROVE, VEHICLE AROUND YARD, COULD NOT GET TO SMOKE, REMOVED GEARBOX, LEVEL BUNG, OPERATED PTO NO PRESSURE BYPASSING FROM PTO., TEST DROVE VEHICLE TO GET TO OPERATING TEMP, OPERATED PTO, COULD NOT GET TO FAULT. FOUND HYDRAULIC OIL LEAKING FROM, SITE GLASS, REMOVED AND REPLACED SITE GLASS AS WAS CRACKED., CHECKED OIL LEVEL, FOUND EXCESSIVELY LOW, TOPPED UP, HYDRAULIC OIL WITH 35ltrs OF OIL. WASHED DOWN LEAK, TEST, DROVE. RECHECKED, ALL OK., PO#113893	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	145026	07/09/2018 0:00	234839	REPAIRED A/C HOSE. COMPLETED A/C SERVICE, AND CHECKED ALL PRESSURES & PERFORMANCE, ALL OK., PO#113714	AC - AIR-CONDITION REPAIR
P33-N-058	HINO HD SS2848 AIR	144607	05/09/2018 0:00	234839	COMPLETED B SERVICE. REPLACED ENGINE OIL & FILTER, REPLACED BLOCKED AIR FILTERS. REPLACED FUEL/WATER FILTER, INSPECTED COMPLAINT OF AIR LEAK AT GEARBOX, COULD NOT FAULT, AT TIME OF INSPECTION., PO#113345	PS - PLANNED SERVICE
P33-N-058	HINO HD SS2848 AIR	140341	13/06/2018 0:00	234839	JUMP STARTED TRUCK AT DRIVERS HOUSE., JC#47412	BE - BREAKDOWN - ELECTRICAL
P33-N-058	HINO HD SS2848 AIR	136675	18/04/2018 0:00	234839	COMPLETED 235,000km SERVICE. REPLACED ENGINE OIL & FILTER, REPLACED FUEL FILTERS. GREASED ALL NIPPLES / LUBE POINTS., GREASED PIVOTS. ADJUSTED BRAKES. GREASED TURNTABLE., FILLED OUT SERVICE STICKER. CHANGED AD-BLUE. ROTATED, BALLRACE 360deg., REMOVED AND BLEW OUT EXTREMELY DIRTY AIR FILTERS. COMPLETED, WELD REPAIRS TO AIR TANK. REMOVED MOUNTING BRACKET FROM, CROSSMEMBER. REPAIRED, PLATED AND REFITTED. REWIRED, REVERSE BUZZER. REPLACED AIR HOSE MOUNT TANK., REPLACED BOTH REAR DRIVE SHOCK ABSORBERS., PO#106867	PS - PLANNED SERVICE
P33-N-058	HINO HD SS2848 AIR	135599	01/03/2018 0:00	222703	REPAIRED RUBBED THROUGH ABS WIRING. SERVICED A/C. OK, CHECKED ENGINE RUNNING HOT, FOUND RADIATOR TO BE BLOCKED, WITH DIRT & ROAD GRIME. BLEW OUT RADIATOR., INVESTIGATED COMPLAINT OF NOISY CAB FAN. REMOVED PAPER THAT, WAS STUCK ACROSS FAN AIR PICK UP FILTER., CHECKED ABS LIGHT ON. FOUND ABS SENSOR WIRE RUBBED THROUGH, ON REAR AXLE. COMPLETED TEMP REPAIR, SOLDERED HARNESS, REFIT, ORDERED NEW SENSOR. REPAIRED BROKEN AIR TANK MOUNT ABOVE, REAR AXLE, MOST LIKELY CAUSE OF THE RUBBED WIRE., CHECKED COMPLAINT OF RAM NOT LIFTING, COULD NOT FAULT., CHECKED A/C NOT GETTING COLD. CHECKED & SERVICED AS REQUIRED, REPLACED RECEIVER DRIER AND REGASSED. ALL OK., P/O 106055.	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	133981	19/02/2018 0:00	226866	REPLACED 4x DRIVE TYRES. POS 7-10, P/O 104650	TC - TYRE CHANGE/REPLACEMENT



P33-N-058	HINO HD SS2848 AIR	133631	13/02/2018 0:00	222703	BLEW OUT RADIATOR & AIR CON CONDENSER AS RUNNING HOT., CHECKED RADIATOR AND AIR CON CONDENSER AS TRUCK WAS, RUNNING HOT. FOUND RADIATOR HAD A LARGE AMOUNT OF DIRT, AND DUST PRESENT. BLEW OUT AND CLEANED OUT RADIATOR, AND AIR CONDITIONING CONDENSER., REPAIRED FAULTY REVERSE LIGHT AND BUZZER - FITTED NEW LIGHT., CHECKED AIR CONDITIONING SYSTEM, CHECKED SYSTEM PRESSURES, FOUND OK. FOUND NO AIRFLOW ON RECIRCULATE SETTING, REMOVED, & CLEANED RUBBISH FROM INLET SCREEN., PO#104316	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	126900	30/01/2018 0:00	203437	WORK NOT COMPLETED, JOB CANCELLED, PO#98738	CD - CUSTOMER DAMAGE
P33-N-058	HINO HD SS2848 AIR	131432	08/01/2018 0:00	222155	COMPLETED 220,000km SERVICE. REPLACED ENGINE OIL & FILTER., GREASED TURNTABLE. CHANGED AD-BLUE FILTER., ROTATED BALLRACE 360DEG. REPLACED FUEL FILTERS., REPLACED BOTH BLOWN FRONT PARK LIGHT GLOBES, P/O 102465	PS - PLANNED SERVICE
P33-N-058	HINO HD SS2848 AIR	131431	04/01/2018 0:00	222161	REPLACED WORN STEER TYRES, P/O 102643	TC - TYRE CHANGE/REPLACEMENT
P33-N-058	HINO HD SS2848 AIR	130192	06/12/2017 0:00	218446	REPLACED FAILED FUEL SENSOR, CHECKED TRUCK WILL NOT START, TILTED BULLBAR & CAB., INSPECTED ENGINE BAY AND WIRING. ENSURE VEHICLE HAD, SUFFICIENT FUEL. CONNECTED COMPUTER, NP PRESENT FAULTS, DATA, MONITORED VARIOUS SENSORS, FOUND RAIL PRESSURE SENSORS, READING ERRATIC. TESTED WIRING HARNESS, TESTED SENSOR., ORDERED NEW SENSOR, REMOVED AND REPLACED SENSOR WITH NEW,, VERIFIED REPAIRED. RECHECKED ALL OK., P/O 101709	BM - BREAKDOWN - MECHANICAL
P33-N-058	HINO HD SS2848 AIR	130228	05/12/2017 0:00	206802	0	RE - REGISTRATION
P33-N-058	HINO HD SS2848 AIR	127999	18/10/2017 0:00	206802	REPLACED TIE ROD END & CLEARED DEFECT, LIFTED TIPPER BODY AND REMOVED FRONT TORQUE ROD. PRESSED OLD, BUSHES OUT AND NEW BUSHES IN. REFITTED TORQUE ROD. REPEATED, PROCEDURE ON REAR TORQUE ROD. LOWERED TIPPER BODY, CHECKED, OVER. CLEARED DEFECTS., PO#99730	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	126370	01/10/2017 0:00	203437	BLEW OUT INTERCOOLER & REPLACED RIDE HEIGHT VALVE ROSE JOINT, REPLACED BROKEN ROSE JOINT ON RIDE HEIGHT CONTROL VALVE., CLEANED OUT RADIATOR CORE., CLEANED OUT RADIATOR CORE USING HOT WASH AND BLOW DRY., ENGINE REMAINED COOL ON TEST DRIVE., PO#98299	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	125941	05/09/2017 0:00	183599	REPLACED 4x WORN TYRES, P/O 97935	TC - TYRE CHANGE/REPLACEMENT
P33-N-058	HINO HD SS2848 AIR	126340	01/09/2017 0:00	203437	COMPLETED 200,000km SERVICE. REPLACED ENGINE OIL & FILTERS., GREASED ALL NIPPLES, LUBE POINTS. GREASED PIVOTS., ADJUSTED BRAKES. GREASED TURNTABLE. REPLACED SERVICE STICKER, REPLACED AD-BLUE, ROTATED BALL RACE 360., PO#98182	PS - PLANNED SERVICE
P33-N-058	HINO HD SS2848 AIR	122372	05/06/2017 0:00	183599	ADJUSTED CLUTCH. TESTED - OK., P/O 94731	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	121946	15/05/2017 0:00	183599	CLEARED FAULT CODES & TESTED, ALL OK. NOTHING ACTIVE., CLEANED ALL PUMP WIRING CONNECTIONS., PENGINE LIGHTS ON., P/O 93814	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	120456	26/04/2017 0:00	176222	RELACED 4x WORN DRIVE TYRES, P/O 93181	TC - TYRE CHANGE/REPLACEMENT
P33-N-058	HINO HD SS2848 AIR	120763	26/04/2017 0:00	181641	REPLACED HOIST ROCKER SWITCH & TESTED ALL OPERATIONS. OK., REPAIR HOIST CONTROL SWITCH, P/O 93413	ER - ELECTRICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	119496	01/04/2017 0:00	158486	REPLACED LOWER HEIGHT CONTROL ROD BANJO. ADJUSTED, ALL OK, P/O 92593	MR - MECHANICAL REPAIR
P33-N-058	HINO HD SS2848 AIR	119885	01/04/2017 0:00	178418	COMPLETE 180,000km SERVICE. REPLACED OIL & FUEL FILTERS., CLEANED AIR FILTER. TIGHTNED BOTTOM HOIST BOLTS AS THEY WERE, LOOSE. REPLACED FAILED RHR CLEARANCE LIGHT. CHECKED OVER., P/O 92741	PS - PLANNED SERVICE
P33-N-058	HINO HD SS2848 AIR	115125	25/11/2016 0:00	158486	COMPLETED 160,000km 'A' SERVICE. REPLACED OIL & FUEL FILTERS, REPLACED AIR FILTER. CHECKED & TOPPED UP FLUIDS. CHECKED, OVER., P/O 89027	PS - PLANNED SERVICE
P33-N-058	HINO HD SS2848 AIR	111857	06/09/2016 0:00	143535	CLEANED OUT DUST FILLED RADIATOR., CHECKED AND CLEANED RADIATOR., DROVE VEHICLE ONTO RAMPS. TILTED DOWN BULLBAR AND REMOVED, PROTECTIVE SCREEN. BLEW OUT RADIATOR & INTERCOOLER WITH, COMPRESSED AIR TO REMOVE DUST. WASHED DOWN WITH PRESSURE, WASHER UNTIL CLEAR WATER CAME THROUGH OTHER SIDE., STARTED UP TRUCK RAN FAN, PRESSURE WASHED DOWN AGAIN., REINSTALLED PROTECTIVE SCREEN. LIFTED UP BULL BAR INTO, POSITION. CHECKED OPERATION, ALL OK., PO#86519	Other
P33-N-058	HINO HD SS2848 AIR	110872	09/08/2016 0:00	140735	COMPLETED 'B' SERVICE. REPLACED OIL FILTER. REFILLED OIL., CHANGED FUEL FILTERS AND BLEED SYSTEM. DRAINED DIFF OIL &, TRANSMISSION FLUID. REPLACED BOTH AIR FILTERS. GREASED ALL, LUBRICATION POINTS. FOUND MULTIPLE LEAKING SHOCKS. FITTED, SERVICE STICKER., REPLACED LEAKING SHOCKS FOUND DURING SERVICE. UNBOLTED &, REMOVED LH & RH FRONT & REAR DRIVE SHOCK ABORBERS &, REPLACED WITH NEW., PO#85615	PS - PLANNED SERVICE

P33-N-058	HINO HD SS2848 AIR	109702	13/07/2016 0:00	138997	REMOVED AND REPLACED TENSIONER AND IDLER PULLEY., REMOVED FAN BELT AND FOUND TENSIONER HAD BROKEN., REFITTED FAN BELT AND CHECKED OPERATION., DRAINED COOLANT, REMOVED THERMOSTAT HOUSING., REPLACED O-RINGS AND CLEANED SURFACES. REFITTED HOUSING, AND REFILLED COOLANT, WASHED DOWN ENGINE AND CAB., P/O #84738	Other
P33-N-058	HINO HD SS2848 AIR	108377	08/06/2016 0:00	134830	REPLACED WORN DRIVE TYRES POS 3-6, P/O 83863	TC - TYRE CHANGE/REPLACEMENT
P33-N-058	HINO HD SS2848 AIR	108316	07/06/2016 0:00	134837	REPLACED FAILED BATTERIES. TIDIED WIRING TO REVERSE CAMERA., P/O 83864	Other
P33-N-058	HINO HD SS2848 AIR	105281	22/03/2016 0:00	123400	ADJUSTED CLUTCH TO SPECS & TESTED OPERATION. ALL OK., CHECKED OVER & FOUND CLUTCH FORK RIDING ON THROW OUT BEARING, P/O 81369	UR - UNPLANNED REPAIR
P33-N-058	HINO HD SS2848 AIR	104556	05/03/2016 0:00	120352	COMPLETED 120,000KM SERVICE. REPLACED PARKLIGHT GLOBE., REPLACED OIL, FUEL & AIR FILTERS. GREASED. REPLACED FUEL, FILTER BOLT & ORING. ADJUSTED BRAKES., P/O 80867	PS - PLANNED SERVICE
P33-N-058	HINO HD SS2848 AIR	103917	22/02/2016 0:00	117738	REPLACED 2 WORN TYRES (POS1-2), P/O 80431	TC - TYRE CHANGE/REPLACEMENT
P33-N-058	HINO HD SS2848 AIR	103670	16/02/2016 0:00	116402	REPLACED WORN DRIVE TYRES (POS 7-10), P/O 80255	TC - TYRE CHANGE/REPLACEMENT
P33-N-058	HINO HD SS2848 AIR	101063	08/12/2015 0:00	106916	REVERTED REMOTE WIRELESS TIPPER SYSTEM TO MANUAL SYSTEM, TESTED - OK, PO 78543	Other
P33-N-058	HINO HD SS2848 AIR	100748	08/12/2015 0:00	99400	NSW REGISTRATION PAID = P33-N-058 ON CREDIT CARD	RE - REGISTRATION
P33-N-058	HINO HD SS2848 AIR	100522	30/11/2015 0:00	94996	REPLACED FILTER. REFILLED ADBLUE., CHECKED ELECTRIC WIRING, PLUGS & COMPUTERS. COMPUTERS HAD TO, BE REPROGRAMMED., PO 78140	Other
P33-N-058	HINO HD SS2848 AIR	99340	04/11/2015 0:00	99400	COMPLETED 100,000km SERVICE. REPLACED OIL, AIR, FUEL FILTERS, REPLACED GEAR & DIFF OILS., P/O 77249, NSW 14/4 THERMOSTAT HOUSING WEEPING - WARRANTY, NSW 14/4 RHR TORQUE ROD BUSH WORN - WARRANTY	PS - PLANNED SERVICE
P33-N-058	HINO HD SS2848 AIR	96822	24/08/2015 0:00	86369	CLEARED DEFECT NOTICE, P/O 75071, DEFECT ISSUED FOR CRACKED WINDSCREEN.	Other
P33-N-058	HINO HD SS2848 AIR	95712	24/07/2015 0:00	81672	REPLACED WORN STEER TYRES & FRONT AXLE DRIVE 3-6, P/O 74298	TC - TYRE CHANGE/REPLACEMENT
P33-N-058	HINO HD SS2848 AIR	95470	17/07/2015 0:00	80441	COMPLETED 80,000km SERVICE. ADJUSTED CLUTCH., COMPLETE SERVICE & ADJUST CLUTCH, P/O 74078	PS - PLANNED SERVICE
P33-N-058	HINO HD SS2848 AIR	95388	01/07/2015 0:00	56436	REPLACED HYDRAULIC PUMP & RELIEF VALVE., P/O 73969	UR - UNPLANNED REPAIR
P33-N-058	HINO HD SS2848 AIR	94892	01/07/2015 0:00	56436	REPLACED AIR FILTERS., NSW 14/4 AIR FILTER NEEDS TO BE REPLACED, P/O 73481	Other
P33-N-058	HINO HD SS2848 AIR	91961	30/03/2015 0:00	56436	REPLACED FOUR DRIVE TYRES - POS 7 - 10, P/O 71379	TC - TYRE CHANGE/REPLACEMENT
P33-N-058	HINO HD SS2848 AIR	91458	16/03/2015 0:00	51000	COMPLETED 50,000km SERVICE., P/O 70991, NOTE: AIR FILTER NEEDS TO BE REPLACED. THERMOSTAT HOUSING, WEEPING. RHR TORQUE ROD BUSH WORN.	PS - PLANNED SERVICE
P33-N-058	HINO HD SS2848 AIR	89066	27/12/2014 0:00	22323	RESEALED PTO OUTPUT SHAFT & REPLACED HYDRAULIC PUMP., FILLED HYDRAULIC OIL., P/O 69265	UR - UNPLANNED REPAIR
P33-N-058	HINO HD SS2848 AIR	88429	08/12/2014 0:00	22323	12 MONTHS REGISTRATION PAID BY C/CARD - EXPIRY 08/12/2015, 12 MONTHS INSURANCE PAID BY C/CARD - EXPIRY 08/12/2015	RE - REGISTRATION
P33-N-058	HINO HD SS2848 AIR	85123	05/09/2014 0:00	22323	REPLACED BROKEN REAR SHOCK ABSORBER., REPLACE SHOCKER, P/O 66253	UR - UNPLANNED REPAIR
P33-N-058	HINO HD SS2848 AIR	84576	15/08/2014 0:00	18794	MODIFIED TOW HITCH TO SUIT FULTON HOGAN REQUIEMENTS, AS AGREED BETWEEN DEAN AND DAN, P/O 65815	AR - ADDITIONAL WORK
P33-N-058	HINO HD SS2848 AIR	84496	13/08/2014 0:00	18794	REPLACED FAILED PTO PUMP WITH HEAVY DUTY UNIT, P/O 65725	UR - UNPLANNED REPAIR
P33-N-058	HINO HD SS2848 AIR	85379	01/08/2014 0:00	18794	RESEALED PTO PUMP & REFILLED HYDRAULIC TANK & GEAR BOX OILS., CALL OUT TO SITE, GEARBOX LEAKING OIL, FOUND HYD OIL IN, GEARBOX - NEEDED TRUCK BACK TO WORKSHOP TO RESEAL PTO PUMP, P/O 66466	UR - UNPLANNED REPAIR
P33-N-058	HINO HD SS2848 AIR	83643	21/07/2014 0:00	18794	COMPLETED 'A' 60,000km SERVICE, P/O 64952	PS - PLANNED SERVICE
P33-N-058	HINO HD SS2848 AIR	83034	04/07/2014 0:00	14643	CHANGED AND RELOCATE TOW HITCH AS REQUESTED BY DEAN & DAN, P/O 64488	MW - MODIFIED WORKS
P33-N-058	HINO HD SS2848 AIR	82954	01/07/2014 0:00	14643	REPLACED TOGGLE SWITCH & TRAILER PLUG, P/O 82954	Other
P33-N-058	HINO HD SS2848 AIR	83400	01/07/2014 0:00	14643	WESTLINK M7 TOLLS, 26/05/14 @ 18:04 M2 INTERCHANGE - NORTH WESTERLY	-
P33-N-058	HINO HD SS2848 AIR	82658	23/06/2014 0:00	14296	ENGINE LIGHT ON DASH CAUSED BY CONTAMINATED ADBLUE TANK, P/O 62412	UR - UNPLANNED REPAIR
P33-N-058	HINO HD SS2848 AIR	82660	19/06/2014 0:00	14643	REPLACED HYDRAULIC PUMP SEALS & TOPPED UP HYD OIL & GEAR OIL, P/O 64211	UR - UNPLANNED REPAIR
P33-N-058	HINO HD SS2848 AIR	77419	31/01/2014 0:00	3703	COMPLETED 5000KM SERVICE, PARTS ONLY., P/O 60373	PS - PLANNED SERVICE