

K01-15

Giesbrecht HD Repairs LTD.
P.O. Box 5
Bezanston AB T0H 0G0
7802851490
giesbrechtrepairs@hotmail.com



INVOICE

BILL TO
Bluehills Harvesting Ltd
Box 957
La Crete Alberta T0H2H0

INVOICE # 2307
DATE 02/02/2025
DUE DATE 02/02/2025
TERMS Due on receipt

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
------	----------	-------------	-----	------	--------

DATE	ACTIVITY	DESCRIPTION	QTY	RATE	AMOUNT
24/01/2025	Labour	Unit LB-02 S/N:2D9EB53C571004141 Wash lowbed, move into shop, place on jack stands Remove wheels, drums, brakes, etc. Pre-inspect for repairs, create a repair and parts list. Remove all broken/worn parts (brake pots). S-cams, slacks, airbag, Cam bushings, shocks, etc). Order parts pick up at FGI under customer's account Replace 2nd and 3rd axle brake pots Replace one airline valve to pot Replace all shocks with new hardware Install Cam tubes and S-Cams Install LH front axle airbag Drill broken bolts and tap dust shield mounting Install new dust shields rear axle left, and right Remove and replace junction box rear of trailer Replace multiple marker lights with grommets Repair marker light wiring along frame Repair multiple air leaks, replace partial airline. Tie up wiring and airlines Replace all wheel seals Replace all brake shoes Replace 5 brake drums and reused one good Replace all hub nuts with pro torque lockers Replace rear axle right hubcap Replace all hubcap gaskets Fill all hubs with 75W-90 Set brakes, install wheels with all new corrosion rings Torque wheels, place trailer back on floor and double check all repairs. Clean up work area.	50	115.00	5,750.00
	Parts/Supplies	Gear oil Shock hardware Air line	1	150.00	150.00
Note		SUBTOTAL			5,900.00

Cracks on neck and low bed marked, but not repaired
First and second axle fn functional bushings, worn out. Need to be
replaced
Middle axle left outside rim out of service

GST @ 5%
TOTAL
BALANCE DUE

295.00
~~5,195.00~~
\$6,195.00

TAX SUMMARY

RATE	TAX	NET
GST @ 5%	295.00	5,900.00