

Maintenance History 199K

SER# 1GTHK23637F523917

Work Order ID	Description	Sublet Vendor Labor \$	Part \$	Total \$	Odometer Reading
3903	-POWELL REPAIR, -RECONDITION TRANSMISSION -REPLACE HVAC CONTROL MODULE	\$1,617.71	\$435.47	\$2,053.18	174875 on 7/4/2012 1:08:34 PM
4612	-KREGS REPAIR, -REPLACE FRONT AND REAR SHOCKS	\$148.00	\$622.00	\$770.00	201000 on 12/11/2013 11:25:05 AM
12966	-INTEGRA TIRE REPAIR, -REPLACE PITMAN ARM -PERFORM WHEEL ALIGNMENT	\$170.00	\$579.80	\$749.80	250000 on 8/11/2015 2:26:21 PM
16442	-REPLACE BOTH UPPER CONTROL ARMS -PERFORM WHEEL ALIGNMENT	\$409.95	\$385.00	\$794.95	319385 on 3/7/2017 1:17:23 PM
19161	-REDLINE REPAIR, -REPLACE POWER STEERING HOSE	\$121.00	\$87.47	\$208.47	322531 on 4/3/2017 2:17:03 PM
19162	-SHINING ARMOUR REPAIR, -REPLACE EGR VALVE -REPLACE IGNITION TUMBLER -REPLACE BELT & TENSIONER -REPLACE EXHAUST HANGER INSULATOR	\$468.00	\$357.92	\$825.92	336700 on 10/10/2017 2:24:00 PM

19163	-COUNTRY SERVICE REPAIR, -REPLACE #6 GLOW PLUG	\$148.00	\$40.90	\$188.90	331829 on 7/19/2017 2:34:54 PM
19169	-REPLACE WINDSHIELD	\$0.00	\$220.00	\$220.00	323000 on 4/24/2017 2:09:43 PM
19244	- REPLACE P/S HIGH PRESSURE HOSE & TOP UP FLUID	\$0.00	\$137.60	\$137.60	348606 on 3/19/2018 10:35:30 AM
22546	- REPLACE STEERING BOX - REPLACE UPPER CONTROL ARM WITH BALL JOINTS - REPLACE LOWER BALL JOINTS - REPLACE PITMAN & IDLER ARM - REPLACE INNER & OUTER TIE ROD ENDS - PERFORM WHEEL ALIGNMENT - REPLACE FUEL FILTER - REPLACE P/S LINE - SERVICE TRANSMISSION - DYNASTY DIESEL & REPAIR - YORKTON	\$1,210.00	\$2,172.57	\$3,382.57	429084 on 9/3/2019 2:59:50 PM
25314	- REPLACE SEAT CUSHION & COVER - REPLACE POWER STEERING LINE - REPAIR POWER STEERING PUMP	\$0.00	\$645.21	\$645.21	476650 on 11/26/2020 10:33:19 AM
25613	- REPLACE HEATER FAN MOTOR - REPAIR WIRING	\$0.00	\$104.94	\$104.94	481101 on 2/19/2021 4:02:04 PM
Totals:		\$4,292.66	\$5,788.88	\$10,081.54	