

T-07

2014 (black) Kenworth T800 Tridrive

SERIAL# 1XKDP4TX6ER968124

Unit #	Date	Hours	Odometer	Description
T-07	Saturday, January 7, 2023	19,185	566,624	Changed clutch brake
T-07	#####	0	585,591	Change left and right windshields, changed left and right wiper blades, installed front fender supports
T-07	#####	0	585,591	Changed bearings on clutch linkage x2
T-07	#####	0	585,591	changed O-ring on diff lock axle #3
T-07	#####	0	585,591	Straighten gear shifter, change diff lock switch, change shocks on axle 1
T-07	Thursday, April 13, 2023	0	585,591	Changed air dryer purge valve, change all V-rod bushings on axles 2, 3, and 4
T-07	#####	0	0	Replaced LH tierod
T-07	Thursday, June 15, 2023	0	0	Change coolant reservoir tank
T-07	Thursday, July 6, 2023	0	0	Changed thermostat, put air compressor on
T-07	#####	N/A	N/A	Coolant sensor , Coolant reservoir
T-07	#####	0	0	Wheel Alignment, clutch setup
T-07	#####	20,260	599,299	Changed intake sensor
T-07	#####	20,276	599,502	Replaced exhaust pressure sensor
T-07	#####	20,312	600,827	Changed clutch brake
T-07	#####	20,452	605,725	Replaced dampener pulley on crankshaft
T-07	#####	21,108	626,994	Output seal #2 axle. Input seal #3 axle.
T-07	#####	N/A	N/A	#3 LH Inspect Brakes, S-cams, wheel seals
T-07	Thursday, May 16, 2024	N/A	N/A	LH Steering wheel seal, brakes shoes, brake pot, and shock replaced #3 RH Wheel seal
T-07	Friday, May 17, 2024	N/A	N/A	Replaced cab blower motor. Replaced windshields. RH Steering wheel seal, brake pot, grease nipples.
T-07	Saturday, May 18, 2024	N/A	N/A	Replaced hood bushings, RH Sleeper shock. RH Steering shock.
T-07	#####	N/A	N/A	Change #1 cross member gussets. Install actuator. Install brake valve.
T-07	Tuesday, June 4, 2024	N/A	N/A	Installed new rear motor mounts.
T-07	Friday, June 7, 2024	N/A	N/A	Repair wiring for LH ABS sensor. Repair RH stack bushing.
T-07	#####	N/A	N/A	Changed axle gasket
T-07	#####	N/A	N/A	Replaced Clutch brake
T-07	#####	N/A	N/A	replace motor mounts
T-07	#####	N/A	N/A	change clutch brake
T-07	#####	N/A	N/A	switch fuel pressure sensor
T-07	Tuesday, March 25, 2025	N/A	N/A	repair RH fender Light wiring
T-07	Tuesday, March 25, 2025	N/A	N/A	replace centre drive RH shock
T-07	Monday, May 12, 2025	N/A	N/A	inspect brakes, bushings, and s-cams
T-07	#####	N/A	N/A	replace cross member and gussets
T-07	Thursday, May 15, 2025	N/A	N/A	replace driver seat belt, replace air hose above tranny
T-07	Friday, May 16, 2025	N/A	N/A	replace fuel pump gasket, replace master swithes, replace hood rests