

Horizon Truck & Trailer Repair

CUSTOMER Bluehills Harvesting
ADDRESS Box 957 Lacrete, AB. T0H
PH. 280 P.O. NO.

Jan 11/2024

T07

609816

MAKE			YEAR		MODEL	
SERIAL NUMBER						
MOTOR NUMBER			TRANS NUMBER		LICENSE	
CASH	CHARGE	D.P.	WARRANTY	DEPOSIT	SERVICE SALESMAN	
☐	☐	☐	☐	\$		

☐ CHECK ALL WHEEL TORQUES AFTER 50 KM'S

WORK DESCRIPTION

Diagnosed loss of coolant. No external leaks

- Found faulty cylinder head.
- Replaced cylinder head
- measured cylinder liner protrusions (ok)
- welded crossmember under radiator mount while rads were removed.
- Installed pyro probe and gauge.

**WORK ORDER / INVOICE No. 2167**[illegible]

PAY THIS AMOUNT

*ARE FOR LABOUR ONLY. MATERIALS ADDITIONAL. THIS COMPANY DOES NOT ASSUME ANY RESPONSIBILITY WHATEVER FOR VEHICLES OR
 **OR REPAIRS, STORAGE OR OTHER PURPOSES. OR FOR ARTICLES LEFT IN SAME VEHICLE DRIVEN BY OUR EMPLOYEES AT OWNERS RISK

DATE _____

SIGNATURE

2% PER MONTH CHARGED ON OVERDUE ACCOUNTS