



SOUTH COUNTRY
EQUIPMENT

Box 129
Highway 6 & 22
Southey, SK S0G 4P0
Phone: 306-726-2155
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

Internal Used Stock No. 142942	Internal Used Stock No. 142942	Invoice Number: [REDACTED]
		Invoice Date: 9/5/2023
		Location: [REDACTED]
		Work Order Number: [REDACTED]
		Payment Type: Account
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	
		Page: 1 of 3

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2000 JD 9650 WALKER COMBINE	5961	H09650W685419	H09650W685419	

/GLOPCLEAN9650 F Internal

COMPLAINT:

01 GREENLIGHT/RECONDITIONING CLEANING CHECKLIST

CORRECTION:

sep hours 4220

WASH COMPLETE MACHINE(OPEN & WASH BEHIND ALL SHIELDS) WAX IF REQUIRED REMOVE ANY OTHER DEALER DECALS INSTALL SCE DEALERSHIP DECALS ALL FACTORY SAFETY AND MODEL DECALS IN GOOD CONDITION REMOVE CAB FLOORMAT AND CLEAN MAT AND FLOOR CLEAN SEAT AND REMOVE STAINS IF NECESSARY VACUUM CAB THOROUGHLY CLEAN INSTRUMENT PANEL, OPERATOR CONTROLS, UPHOLSTERY, AND AIR DELIVERY LOUVERS CLEAN WINDOWS AND MOLDINGS(OPEN WINDOWS TO CLEAN EDGES WHERE APPLICABLE) ELIMINATE ANY CAB ODORS AND INSTALL AIR FRESHENER IF REQUIRED PAINT AREAS THAT ARE BADLY SCRATCHED/DAMAGED-INCLUDING BUCKETS, GRAPPLES, WHEELS, EXHAUST, PLATFORM AUGERS(COMPLETE AUGER), CHOPPER FINS, FEEDERHOUSE DRUMS, BALER PICKUPS

Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
SERVACCESS	SERVICE ACCESSORIES	1.00	96.00	96.00	\$96.00	N
Labor: \$1,943.00	Parts: \$0.00	OL&M: \$0.00	Misc: \$96.00	Sub-Total: \$2,039.00		

Gen2- Internal

COMPLAINT:

02 DIAGNOSE DISPLAYS NOT READING

CORRECTION:

Tried putting in a test motherboard just to check and the bottom display was still blank. Ordered a new display and put it in and everything worked. The only thing not working is the fuel gauge which is blank and there is a E02 96.03 code which is fuel level signal voltage too high. Sales will repair fuel gauge later.

Part Number	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind
AH155932	MODULE	1.00	1,687.23	1,687.23	\$1,687.23	N
AH155932-CR	CORE for:Module	-1.00	136.00	136.00	(\$136.00)	N
Miscellaneous	Description	Quantity	List Price	Net Price	Extended Price	Taxed Ind

CONTINUED ON NEXT PAGE->



SOUTH COUNTRY
EQUIPMENT

Box 129
Highway 6 & 22
Southey, SK S0G 4P0
Phone: 306-726-2155
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

Internal Used Stock No. 142942	Internal Used Stock No. 142942	Invoice Number: [REDACTED] Invoice Date: 9/5/2023 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: Account Page: 2 of 3
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2000 JD 9650 WALKER COMBINE	5961	H09650W685419	H09650W685419	

Gen2- Internal							
SERVACCESS	SERVICE ACCESSORIES	1.00	23.36	23.36	\$23.36	N	
Labor: \$389.25		Parts: \$1,551.23	OL&M: \$0.00	Misc: \$23.36	Sub-Total: \$1,963.84		

GEN50- Internal

COMPLAINT:

03 INSTALL ALL MISSING SHIELDS

CORRECTION:

Put all missing shields on the combine. all the mounting brackets was removed as well so had to install them as well.

<u>Miscellaneous</u>	<u>Description</u>	<u>Quantity</u>	<u>List Price</u>	<u>Net Price</u>	<u>Extended Price</u>	<u>Taxed Ind</u>
----------------------	--------------------	-----------------	-------------------	------------------	-----------------------	------------------

SOUTH COUNTRY
EQUIPMENT

CONTINUED ON NEXT PAGE->



SOUTH COUNTRY
EQUIPMENT

Box 129
Highway 6 & 22
Southey, SK S0G 4P0
Phone: 306-726-2155
www.southcountry.ca

Moose Jaw, SK 306-692-2371
Mossbank, SK 306-354-2411
Assiniboia, SK 306-642-3366
Emerald Park, SK 306-721-5050
Weyburn, SK 306-842-4686
Southey, SK 306-726-2155
Raymore, SK 306-746-2110
Montmartre, SK 306-424-2212



JOHN DEERE

Invoice To Account No: 0

Deliver To:

SERVICE INVOICE

Internal Used Stock No. 142942	Internal Used Stock No. 142942	Invoice Number: [REDACTED] Invoice Date: 9/5/2023 Location: [REDACTED] Work Order Number: [REDACTED] Payment Type: Account Page: 3 of 3
Bus Phone:	Bus Phone:	
Prv Phone:	Prv Phone:	

Make/Model:	Meter:	Serial Number:	Eq ID:	Fleet No:
JOHN DEERE 2000 JD 9650 WALKER COMBINE	5961	H09650W685419	H09650W685419	

GEN50- Internal								
SERVACCESS	SERVICE ACCESSORIES	1.00	15.57	15.57	\$15.57	N		
Labor: \$259.50	Parts: \$0.00	OL&M: \$0.00	Misc: \$15.57	Sub-Total: \$275.07				

Customer PO No:

Tax Exempt No:

Advisor: [REDACTED]

Labor: \$2,591.75
Parts: \$1,551.23
OL&M: \$0.00
Misc: \$134.93
Grand Total: \$4,277.91

*** DOCUMENT COPY ***

GST Registration No: 897357802

G/L Entries	Br	Dpt	Acct	Sub	Ref	Description
	00	00	160	1	142942	USED AG EQUIPMENT
	06	40	382	1	678157	INTERNAL LABOR-AG
	00	00	178	16	678157	WORK IN PROCESS PARTS -MJ
	06	40	482	1	678157	COS INTERNAL LABOR-AG
	06	40	544	1	678157	SUPPLIES EXPENSE
	06	30	366	2	678157	JD PARTS-COUNTER
	00	00	166	6	678157	JD PARTS-MOOSE JAW
	06	30	466	2	678157	JD PARTS-COUNTER

TERMS AND CONDITIONS

Terms: Cash, Visa, Mastercard, AgriCard, John Deere Financial.

I hereby authorize the above repair work be done along with the use of necessary materials. You and your employees may operate the above machine for purposes of testing, inspection or delivery. I agree to pay cash for such repair parts and labour on delivery of machine(s) or on terms satisfactory to you, and until paid in full, any unpaid balance shall constitute a lien on this machinery. I further agree that you will not be held responsible for loss or damage to said machinery from fire, theft or other causes beyond your control.

Received by:Date: