

Service Job	Invoice No	Date	Customer Id	Customer Name	Cost Cent	Prob	Type of Call	Equip ID	Hrs	Kms	Job Description	Work Done	Labor Cost	Material Cost	Subcontra ctor Cost	Other Cost	Total Cost
61949	74675	11/26/2024	1HM360HB	ID - TIPPER	186G	R	Sundries	1VL263	28125.000	0	Fit Strips To Mud Flaps,Grease all lube Points Pivot warn	BRING TRAILER IN DIAGNOSE WHY BIN NOT GOING DOWN, FOUND PIVOT PINS WORN AND NEED REPLACING	77.38	0	0	15	92.38
57065	70262	08/20/2024	1HM360HB	ID - TIPPER	186G	R	Chassis	1VL263	28125.000	0	FIT R/OUT TYRES X7 + DISPOSAL X7	CHECK AND REPORT ON TYRES GENERAL CONDITION FOUND MULTIPLE TYRES WORN/TREAD BELOW SPEC REMOVED FRONT AXLE RH OUTER TYRE REMOVED FRONT REAR AXLE LH AND RH TYRES REMOVED REAR REAR AXLE LH X2 TYRES TAKE X7 TYRES OVER TO RUBANDS ASSIST PAUL TO REMOVE X7 TYRES FROM STORAGE AND DELIVER TO RUBANDS FOR SWAP GET X7 BACK IN WORK SHOP TO FIT WASH RIMS TO REMOVE DIR AND MUD REFIT ALL REMOVED TYRES AND TORQE TO SPEC	201.93	0	0	0	201.93
55874	68474	07/30/2024	1HM360HB	ID - TIPPER	186G	R	Tyres	1VL263	0.0000	0	Decomission Inspection	CARRY OUT DECOMISSION INSPECTION	669.92	525	0	0	1194.92
55718	66617	07/26/2024	1HM360HB	ID - TIPPER	186G	R	Sundries	1VL263	28125.000	0	CARRY OUT A SERVICE	REMOVED AND TURNED LOGO MUDFLAPS CARRIED OUT TRAILER SERVICE & INSPECTION. - CHECKED ALL LIGHTS & REFLECTORS. - INSPECTED, GREASED & ADJUSTED WHEEL BEARINGS. - CHECKED & LUBRICATED SUSPENSION POINTS & HITCH. - INSPECTED CHASSIS FOR CRACKS, RUST & DAMAGE. - CHECKED TYRE CONDITION & PRESSURES. - CHECKED HITCH FOR PLAY & ADJUSTED.	263.94	0	0	15	278.94
54964	66270	07/12/2024	1HM360HB	ID - TIPPER	192G	S	Service Tra	1VL263	28125.000	0	REPAIR FAULTY TRAILER WIREING	NOTES: SMALL CRACK ON SHOCK BRACKET ON REAR AXLE - PREVIOUSLY WELDED. 8 X TYRES LOW TREAD HUB METER (INOP) LUKE BEEN INFORMED REPAIRED DAMAGED WIRES IN TRAILER LOOM NEAR PLUG END REWired DAMAGED SECTION AND INSTALLED NEW TRAILER PLUG	234.93	0	0	12	246.93
54158	65138	06/27/2024	1HM360HB	ID - TIPPER	187G	R	Electrical	1VL263	0.0000	0	rhf mudflap and bracket fallen off	CONNECT AND TEST ALL OK STRAIGHTENED MUDFLAP BRACKET REMOVED BROKEN MUDFLAP REPAIRED BRACKET AND WELDED BACK INTO PLACE. FITTED NEW MUDFLAP.	139.92	0	0	40	179.92
53802	64558	06/20/2024	1HM360HB	ID - TIPPER	192G	R	Sundries	1VL263	0.0000	0	B-TYPE SERVICE	METER INOP FOR READING. CARRIED OUT TRAILER SERVICE & INSPECTION. - CHECKED ALL LIGHTS & REFLECTORS. - INSPECTED, GREASED & ADJUSTED WHEEL BEARINGS. - CHECKED & LUBRICATED SUSPENSION POINTS & HITCH. - INSPECTED CHASSIS FOR CRACKS, RUST & DAMAGE. - CHECKED TYRE CONDITION & PRESSURES. - CHECKED HITCH FOR PLAY & ADJUSTED. -. BRAKES ADJUSTED. - TIGHTENED MUDFLAP BRACKET. - ADJUSTED 3RD & 4TH AXLE.	117.66	20.81	0	20	158.47
50961	60188	04/23/2024	1HM360HB	ID - TIPPER	192G	S	Service Tra	1VL263	0.0000	0		NOTES: ODOMETER GAUGE NOT WORKING BALL RACE HAS MOVEMENT.	176.49	6.64	0	20	203.13
50725	60677	04/18/2024	1HM360HB	ID - TIPPER	186G	R	Tyres	1VL263	0.0000	0	TYRE + RIM - RUBAND AIR LEAK	DRIVER TO APPLY & RELEASE BRAKES WHILE I CHECKED FOR LEAKS COMING FROM BOOSTERS. FOUND A CONNECTOR LEAKING UNDER REAR OF TRUCK. REPLACED FITTING.	0	725	0	0	725
50708	59809	04/18/2024	1HM360HB	ID - TIPPER	192G	R	Brake	1VL263	28125.000	0		REPLACE HYDRAULIC HOSE AND MAKE SPARE.	39.22	0	0	7.5	46.72
48559	60797	03/22/2024	1HM360HB	ID - TIPPER	187G	R	Hydraulic	1VL263	28125.000	0	REPLACE DAMAGED HYD HOSE		90.1	329.39	0	5	424.49
48222	59284	03/18/2024	1HM360HB	ID - TIPPER	192G	R	Tyres	1VL263	0.0000	0	Fit Two New Tyres (Tyreright Sublet)		22.53	160	0	0	182.53

									trailer brake lights operate when park lights on	INSPECT AND CONFIRM FAULT. ATTEMPT TO DIAGNOSE AND REPAIR ISSUE. DISCONNECT REAR LIGHTS AND INSTALLED ONE AT A TIME FOUND FAULT TO STILL BE PRESENT. UNABLE TO LOCATE SOURCE OF FAULT, BELIEVE TO BE IN MAIN LEAD IN DRAW BAR.					
										CARWELL CARRIED OUT DIAGNOSIS AND REPAIRS					
46042	55944	02/02/2024	1HM360HB ID - TIPPER: 192G	R	Electrical	1VL263	28125.000	0			330	300	0	0	630
45833	54739	01/30/2024	1HM360HB ID - TIPPER: 192G	R	Tyres	1VL263	28125.000	0	LHR TYRE FLAT Tarp Pulley Missing Pin	LHR TYRE FLAT SPRAYED WHERE GRUB SCREW WENT INTO UNBOLTED GRUB SCREW CLEANED THREADLINED PULLEY UP WITH HOLE IN BAR THEN RETIGHTENED GRUB SCREW	21.25	698.19	0	5	724.44
45429	54725	01/19/2024	1HM360HB ID - TIPPER: 192G	R	Bodywork	1VL263	28125.000	0			36.5	0	0	0	36.5
									TRAILER SERVICE, BROKEN SHOCK MOUNTS ON DOLLY, CHECK ALL BRAKES. RAM STICKS WHEN ALMOST DOWN.	CARRIED OUT REPAIRS REMOVED OLD BRAKE SHOCK BOLTS ON FRONT AXLE CUT NEW BOLTS TO FIT WELDED ON BOLTS ON BOTH SIDES, BOLTED SHOCKS INTO AXLE MOUNTS CARRIED OUT SERVICE GREASED & ADJUSTED ALL BRAKES GREASED POINTS FOR TRAY CHECKED ALL LIGHTS / REFLECTORS					
45191	53845	01/15/2024	1HM360HB ID - TIPPER: 192G	R	Service Tra	1VL263	28125.000	0		CHECKED WHEEL BEARINGS REMOVE THE BROKEN LH TARP WIRE & FIT NEW TEST OPERATION	403	12.88	0	20.25	436.13
									Tarp repairs						
										REFITTED FRONT LHS MUDFLAP RAIL THAT WAS BROKEN REMOVE THE BROKEN LH TARP WIRE & FIT NEW TEST OPERATION					
45016	53840	01/11/2024	1HM360HB ID - TIPPER: 192G	R	Sundries	1VL263	28125.000	0		REFITTED FRONT LHS MUDFLAP RAIL THAT WAS BROKEN	148	39	0	7.5	194.5
45009	53818	01/10/2024	1HM360HB ID - TIPPER: 192G	R	Tyres	1VL263	0.0000	0	Fit 2nd Hand Tyre & New Rims (Tyreright Sublet) Inspect Marker Lights		21.25	1427.28	0	5	1453.53
										INSPECTED ISSUE TRAVELLED & COLLECTED PARTS INSTALLED NEW LIGHT ON DRIVER SIDE FOUND WIRING DAMAGED AT REAR DESTROYED BY TYRES ONCE REPAIRED TEST - ALL OK RECONNECTED TRAILER TO THE TANK					
44844	53627	01/08/2024	1HM360HB ID - TIPPER: 192G	R	Electrical	1VL263	0.0000	0			361.5	144	0	18.25	523.75
42530	50519	11/10/2023	1HM360HB ID - TIPPER: 192G	R	Tyres	1VL263	28125.000	0	tyre fitment	ARRANGE SUBLET	0	80	0	0	80
40698	48272	10/03/2023	1HM360HB ID - TIPPER: 192G	R	Tyres	1VL263	0.0000	0	Fit Tyre (Tyreright Sublet) REPLACE DAMAGED MUDFLAP AND MARKER PLATE	ARRANGE SUBLET STRAIGHTEN GUARD BRACKET REPLACE BOTH OUTTER MUDFLAPS & MARKER PLATES	0	80	0	5	85
40062	46364	09/22/2023	1HM360HB ID - TIPPER: 192G	R	Sundries	1VL263	0.0000	0			111	861.53	0	5.55	978.08
39475	45680	09/11/2023	1HM360HB ID - TIPPER: 192G	R	Tyres	1VL263	28125.000	0	Fit Tyres (Tyreright Sublet) LHF MARKER LIGHT AND LH BRAKE INOP.RINGFEEDER BUSH U/S	ARRANGE SUBLET CUT AND KNOCKED OLD RINGFEEDER BUSH OUT FIT NEW BUSH IN TCOUPLING REWired LH CLEARANCE LIGHT REWired BRAKE LIGHT ON LH SIDE	0	320.04	0	5	325.04
38678	44866	08/24/2023	1HM360HB ID - TIPPER: 192G	R	Electrical	1VL263	28125.000	0			219	0	0	10.95	229.95
38588	44855	08/23/2023	1HM360HB ID - TIPPER: 192G	R	Hydraulic	1VL263	0.0000	0	repairs to damaged hydraulic line and coupling rhr brake booster leaking	ARRANGE SUBLET INSPECTED ISSUE - BOOSTER REMOVED BOOSTER COLLECTED NEW BOOSTER UP STAI RD BOOSTER NEEDED TO BE ADJUSTED AROUND PUT INTO PRESS & SHIFTED INTO REQUIRED LOCATION CUT ROD TO LENGTH AFTER MEASURING INSTALLED NEW BOOSTER - FITTED HOSES WITH NEW CLAMPS ADJUSTED BRAKES ON AXLE	0	490.27	0	5	495.27
37944	43895	08/09/2023	1HM360HB ID - TIPPER: 192G	R	Brake	1VL263	0.0000	0		TESTED ALL OK CONNECTED TRALIER AIR & DIAGNOISED AIR LEAK ISSUE FOUND BELOW BASE WAS CRACKED COLLECTED PART NUMBERS TRAVELLED TO COLLECT PARTS CUT AWAY BASE / BAIT DUE TO INTERNAL STUD BREAKING AWAY REMOVED BAG INSTALLED WITH NEW ALL OK INSTALLED REPLACE TAIL LIGHT	113.25	156	0	5.7	274.95
									Air Bag Not Pumping Air						
36581	42408	07/14/2023	1HM360HB ID - TIPPER: 192G	R	Suspensior	1VL263	0.0000	0			390.5	317.5	0	20	728

									CARRY OUT TRAILER C SERVICE, CHECK LH DOLLY BRAKES, NOT SITTING FLUSH WITH DRUM.	DEADJUSTED BRAKES & REMOVED HUB NUTS & WHEELS					
										KNOCKED ALL BEARINGS OUT, CLEANED FOUND 2 BEARINGS. 2 X AXLES OF BRAKES BUSHES REPLACED ALL BEARING & HUBD RE FIR					
										CARRIED OUT INSPECTION WELDED NEW STUD MOUNT ONTO F/RIGHT BOTTOM SHOCKIE MOUNT FIR 3 X CLEARANCE LIGHTS- RAN NEW WIRE THROUGH	3086.58	2403.83	0	120	5610.41
35187	41782	06/20/2023	1HM360HB ID - TIPPER' 192G	S	Service Tra	1VL263	0.0000	0	CHECK AND ADJUST BRAKES	ADJUSTED BRAKES ON TRAILER					
29215	34060	03/30/2023	1HM360HB ID - TIPPER' 192G	R	Brake	1VL263	28125.000	0	REPAIR LIGHTS	BRAKES REQUIRE REPLACEMENT FOUND BROKEN WIRE BETWEEN PLUG AND BALLRACE , REPAIRED AND TESTED OK WELDING REPAIRS COMPLETED BY WELDING WORKS	35.46	0	0	5	40.46
26133	33424	02/15/2023	1HM360HB ID - TIPPER' 192G	R	Electrical	1VL263	0.0000	0			128.45	511.5	0	12.42	652.37
25653	29731	02/06/2023	1HM360HB ID - TIPPER' 192G	INT-R	Sundries	1VL263	0.0000	0	tarp guides(missed off service job 21871) Repair Handle	SUBLET/TARP MISSED ON sj 21871 REMOVE HANDLE & TAKE TO WELDING WORKS TO BE REPAIRED, GRIND DOWN AND REFIT ON TRAILER	0	1140	0	0	1140
25336	31854	01/30/2023	1HM360HB ID - TIPPER' 192G	R	Bodywork	1VL263	0.0000	0			177.47	107.5	0	0	284.97
24716	29195	01/13/2023	1HM360HB ID - TIPPER' 186G	R	Tyres	1VL263	0.0000	0	FIT R/OUT TYRE X1 + DISPOSAL X1		0	170.91	0	0	170.91
23711	27707	12/08/2022	1HM360HB ID - TIPPER' 192G	INT-R	Sundries	1VL263	0.0000	0	tarp guides(missed off previous job)	ARRANGE SUBLET	0	1140	0	5	1145
22926	27215	11/23/2022	1HM360HB ID - TIPPER' 186G	R	Tyres	1VL263	0.0000	0	FIT R/OUT TYRES X2 + DISPOSAL X2 damaged tarp winding shaft and pulley at front rhs	STRAIGHTEN TARP / LOSSEN CABLE OFF REMOVE WINDER RODA & PLUGS USED PRESS TO BEND ROD BACK TO NORMAL SHAPE PICKED IP NEW BEARINGS / PLUGS & FITTED FITTED ROD BACK ON TO TRAILER FITTED CABLES BACK TO TENSIO AS NEEDED CLEANED UP WORK AREA	0	341.82	0	0	341.82
22891	27190	11/22/2022	1HM360HB ID - TIPPER' 192G	INT-R	Sundries	1VL263	0.0000	0			567.36	53.13	0	28.5	648.99
22375	27193	11/11/2022	1HM360HB ID - TIPPER' 192G	INT-R	Sundries	1VL263	0.0000	0	replace damaged cables and guides REPAIR TARP GUIDES	REMOVE LATCHES & REST LENGTH STRETCHED TARP ALL THE WAY REMOVED LINES TO ANCHOR TESTED - ALL OK READJUSTED & TESTED AGAIN ALL OK	851.6	41.41	0	43	936.01
										FOLLOW UP NEEDS NEW CABLES SLIDING BUSHES VERY SOON NO HARD COPY CJD HUB	297.13	0	0	20	317.13
21871	27240	10/31/2022	1HM360HB ID - TIPPER' 192G	INT-R	Sundries	1VL263	0.0000	0	HUB METER CJD						
20196	24565	09/21/2022	1HM360HB ID - TIPPER' 192G	R	Bodywork	1VL263	0.0000	0			0	98.12	0	5	103.12
19198	22634	09/01/2022	1HM360HB ID - TIPPER' 186G	R	Tyres	1VL263	0.0000	0	ADV GL74 TRAILER TYRE X4 + DIS X4 + ROT X2 Service		0	1629.06	0	0	1629.06
18909	22192	08/26/2022	1HM360HB ID - TIPPER' 192G	INT-S	Chassis	1VL263	0.0000	0		CARIIED OUT SERVICE AS PER SERVICE SHEET INSTALL NEW HUB METRE	192.57	98.12	0	9.6	300.29
18091	24948	08/09/2022	1HM360HB ID - TIPPER' 121G	R	Bodywork	1VL263	0.0000	0	Repairs to the bin on the quad		0	0	5800	0	5800
14678	17401	05/25/2022	1HM360HB ID - TIPPER' 192G	R	Electrical	1VL263	0.0000	0	WIRING REPAIRS	REPAIR DRAW BAR WIRING AND FIT NEW TRAILER PLUG	85.42	0	0	0	85.42
11367	14211	03/07/2022	1HM360HB ID - TIPPER' 187G	R	Tyres	1VL263	0.0000	0	STRIP AND FIT TYRES S1B SERVICE	STRIP & FIT TYRES S1 SERVICE COMPLETE SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. CHANGE ENGINE OIL AND FILTER. CHANGE AIR FILTER. CHANGE FUEL FILTER. CHECK ALL OTHER FLUID LEVELS. NEW SHOES & DRUMS ON FRONT AXLES	175.98	840	0	8.75	1024.73
										SHOES WORN DOWN TO RIVETS CUT OLD CHAIN GATHERED NEW WITH EXTRA LINKS INSTALLED ON SERVICE					
11290	16202	03/04/2022	1HM360HB ID - TIPPER' 187G	S	Service Tra	1VL263	0.0000	0	Brake repairs		175.5	244.5	0	13.74	433.74
11291	14127	03/04/2022	1HM360HB ID - TIPPER' 187G	R	Brake	1VL263	0.0000	0	REPLACE TRAILER CHAIN		292.5	713.22	0	14.6	1020.32
										FOLLOW UP REPAIR LADDER AT REAR	223.35	8.54	0	11.15	243.04
10068	11248	02/07/2022	1HM360HB ID - TIPPER' 192G	R	Bodywork	1VL263	0.0000	0							

									S1 service	COMPLETE SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. CHANGE ENGINE OIL AND FILTER. CHANGE AIR FILTER. CHANGE FUEL FILTER. CHECK ALL OTHER FLUID LEVELS.					
9031	10386	01/14/2022	1HM360HB ID - TIPPER: 192G	INT-S	Service Tra	1VL263	0.0000	0			211.95	64.5	0	10.55	287
8656	10445	01/04/2022	1HM360HB ID - TIPPER: 186G	R	Tyres	1VL263	0.0000	0	STRIP AND FIT TYRES REPLACE LEAKING AIRBAGS	STRIP AND FIT TYRES 1VL263	0	110	0	0	110
7181	7927	11/22/2021	1HM360HB ID - TIPPER: 192G	R	Suspensior	1VL263	0.0000	0		REPLACE LEAKING AIRBAGS 1VL263 S1 SERVICE COMPLETE SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. CHANGE ENGINE OIL AND FILTER. CHANGE AIR FILTER. CHANGE FUEL FILTER. CHECK ALL OTHER FLUID LEVELS.	129	490	0	6.4	625.4
6631	7247	11/09/2021	1HM360HB ID - TIPPER: 192G	S	Service Tra	1VL263	0.0000	0		REPAIRS 1vl263	214.07	9.84	0	15.65	239.56
6632	7303	11/09/2021	1HM360HB ID - TIPPER: 192G	R	Bodywork	1VL263	0.0000	0		WHILE CARRYING OUT SERVICE FOUND REAR LH INDICATOR NOT WORKING FOUND WHEN TRAILER PLUG WAS MOVED ALL LIGHTS ENGAGED 1VL263 TARP REPAIRS 1VL263	228.38	0	0	11.35	239.73
6113	6464	10/27/2021	1HM360HB ID - TIPPER: 192G	R	Bodywork	1VL263	0.0000	0		TARP REPAIRS	29.25	0	0	0	29.25
5554	6272	10/11/2021	1HM360HB ID - TIPPER: 186G	R	Tyres	1VL263	0.0000	0	PUNCTURE REPAIR X1 REPLACE ALL AIR BAGS	PUNCTURE REPAIR X1 1LV263	0	54.54	0	0	54.54
5053	6392	09/28/2021	1HM360HB ID - TIPPER: 192G	R	Suspensior	1VL263	0.0000	0		REPLACE AIR BAGS 1VL263	1028.87	2331.31	0	21	3381.18
4621	6055	09/17/2021	1HM360HB ID - TIPPER: 192G	S	Service Tra	1VL263	0.0000	0		S1B SERVICE A-FRAME BUSHES AIR LEAKS BOOSTER RODS/CLEVIS LOOSE MUDFLAPS TOW EYE BUSH ELECTRICAL 1VL263	374.29	44	0	19.76	438.05
4622	5322	09/17/2021	1HM360HB ID - TIPPER: 192G	R	Bodywork	1VL263	0.0000	0		CHANGE OUT LEAKING HYDRAULIC COUPLINGS REPLACED COUPLINGS CHECKED FOR LEAKS 1LV263	807.33	434.97	0	30	1272.3
4471	4032	09/14/2021	1HM360HB ID - TIPPER: 187G	R	Hydraulic	1VL263	0.0000	0		REPLACE DAMAGED RIM 1LV263	47.1	139.64	0	3.8	190.54
4227	5058	09/07/2021	1HM360HB ID - TIPPER: 187G	R	Tyres	1VL263	0.0000	0		REPLACE DAMAGED RIM	152.03	310	0	0	462.03
3811	4260	08/30/2021	1HM360HB ID - TIPPER: 186G	R	Tyres	1VL263	0.0000	0	REPLACE ALLOY RIM 8.25X22.5 X1 HIFLY HH104 11R22.5 TYRES X4 + STRIP & FIT X2 + DIS X6	REPLACED ALLOY RIM HIFLY HH104 11R22.5 TYRES X4 + STRIP & FIT X2 + DIS X6	0	352	0	0	352
3429	4265	08/19/2021	1HM360HB ID - TIPPER: 186G	R	Tyres	1VL263	0.0000	0			0	1502	0	0	1502
3030	2623	08/10/2021	1HM360HB ID - TIPPER: 187G	S	Annual Sen	1VL263	0.0000	0	S1 INSPECTION & REPAIR		117.75	54.06	0	5.89	177.7
2801	2309	08/04/2021	1HM360HB ID - TIPPER: 187G	R	Tyres	1VL263	0.0000	0	PUNTURE REPAIR		0	54.55	0	0	54.55
1613	1347	07/06/2021	1HM360HB ID - TIPPER: 187G	INT-S	Service Tra	1VL263	0.0000	0	S1 service		185.93	6.02	0	9.3	201.25
1084	1105	06/24/2021	1HM360HB ID - TIPPER: 187G	R	Tyres	1VL263	0.0000	0	REPLACE TYRES		192.27	769	0	9.62	970.89
836	1072	06/18/2021	1HM360HB ID - TIPPER: 187G	S	Service Tra	1VL263	0.0000	259363	S1 SERVICE & REPAIR		488.18	369.48	0	24.41	882.07
837	1075	06/18/2021	1HM360HB ID - TIPPER: 187G	R	Trays/Buck	1VL263	0.0000	0	REPAIR TRAY & TOW EYE LIGHT REPAIR	LIGHT REPAIR. REPAIR & REPLACE LHS TAIL LIGHT ASSY. REMOVED FAULTY LIGHT & FOUND DAMAGED WIRE TO TAIL LIGHT. REPLACED AND INSTALLED NEW LIGHT. CRACK REPAIR	484.81	2484.7	0	24.24	2993.75
210511-00	SVC00264C	05/20/2021	1H0360 ID - TIPPER: 187_INT	R	Electrical	1VL263			Crack repair		109.05	55	0	5.46	169.51
210422-00	SVC00263C	04/30/2021	1H0360 ID - TIPPER: 187_INT	R	Sundries	1VL263	23/4/21			SUBLET TO BESSER ENGINEERING TO HAVE CRACKS REPAIRED. REMOVED WHEELS AT BESSERS, REFITTED ONCE JOB DONE.	235.5	230	527.32	0	992.82

									GREASE & CHECKS	GREASE & CHECKS.					
210414-00	SVC002627	04/20/2021	1H0360	ID - TIPPER	187_INT	S	Service	1VL263	N/A						
									S1 service	GREASED ALL POINTS. CHECKED AND ADJUSTED BRAKES. CHECKED ALL OVER TRAILER FOR ANY ISSUES. (FAULTS: BIG CRACKS IN FRONT OF TRAILER) S1 SERVICE	45.05	4.81	0	2.26	52.12
210325-00	SVC002617	03/30/2021	1H0360	ID - TIPPER	187_INT	S	Service	1VL263	30/3/21						
									REPLACE TYRES	CARRY OUT SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. CHECK ALL ELECTRICAL SYSTEMS, SUSPENSION AND, TYRES. CHECK AND ADJUST BRAKES. CHECKED ALL WHEEL BEARINGS. CHECK ALL HYDRAULIC SYSTEMS AND COUPLINGS. REPAIRED LH INDICATOR. EARTH WIRE WAS BROKEN IN HALF. FIXED ALL AIR LEAKS. FITTED NEW BOLT FOR SHOCKY 3RD AXLE AS IT WAS SNAPPED. TIGHTENED OTHER SHOCKY AS WAS LOOSE. REPLACE TYRES.	152.08	353.9	0	7.6	513.58
210326-00	SVC002618	03/30/2021	1H0360	ID - TIPPER	187_INT	R	Tyres	1VL263	26/3/21						
									Repair air leaks	REPLACE X 4 TRAILER TYRES. (DOWLING MCCARTHY TYRES, FIT HB OWN TYRES POS 5/6 AND' 11/12. STRIP & FIT 11R22.50 POSTION 2. REPAIR PUNCTURE POS 3 AND FLIP ON RIM.) REPAIR AIR LEAKS.	75.8	1620	0	3.79	1699.59
210326-00	SVC002618	03/30/2021	1H0360	ID - TIPPER	187_INT	R	Sundries	1VL263	30/3/21						
									REPAIR DAMAGED WIRING	REPLACED LEAKING BRAKE VALVE. REPLACED AIR HOSE AS IT WAS WORN AND KINKED. NEW TAILGATE CYLINDER. REPAIR DAMAGED WIRING.	185.68	199.32	0	9.28	394.28
210304-00	SVC002608	03/12/2021	1H0360	ID - TIPPER	187_INT	B	Electrical	1VL263	3/3/21						
									LIGHT REPAIR	TRAVEL TO TRUCK PARKED AT GAWLER. REMOVE & REPAIR DAMAGED SECTION OF TRAILER LIGHT REPAIR.	133.8	10	0	79.19	222.99
210222-00	SVC002607	03/05/2021	1H0360	ID - TIPPER	187_INT	R	Electrical	1VL263	22/2/21						
									PUNCTURE REPAIR	CUT OUT AND REMOVE DAMAGED SECTION OF TRAILER PLUG LIGHT HARNESS. ADD IN & JOIN UP NEW SECTION AND SECURE. TEST OPERATION OF LIGHTS. ALL OK. PUNCTURE REPAIR.	72.7	137.8	0	3.64	214.14
210218-00	SVC002607	02/25/2021	1H0360	ID - TIPPER	187_INT	R	Tyres	1VL263							
									GREASE & CHECKS	REMOVED PUNCTURED TYRE. TAKE TO DOWLING MCCARTHYS. R/R WITH RUN OUT TO STRIP AND FIT. RETURNED TO WORKSHOP. INSTALLED AND TENSIONED. S1 SERVICE	72.7	62.5	0	3.64	138.84
210212-00	SVC002598	02/23/2021	1H0360	ID - TIPPER	187_INT	S	Service	1VL263	12/2/21						
									FITT RUN OUTS	CARRY OUT SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. CHECK ALL ELECTRICAL SYSTEMS, SUSPENSION AND TYRES. CHECK AND ADJUST BRAKES. CHECK OVER TRAILER FOR CRACKS. FIT RUN OUTS	140.63	4.9	0	0	145.53
210212-00	SVC002598	02/23/2021	1H0360	ID - TIPPER	187_INT	R	Tyres	1VL263	12/2/21						
									300 HR SERVICE	REMOVE L & R TYRES/RIM ASSEMBLY. DELIVER TO MCCARTHY TYRES FOR TYRE REPLACEMENT. PICKUP & FIT TO UNIT, TORQUE WHEEL UNITS. COMPLETED SERVICE AS PER SERVICE SHEET. REPAIRED WIRING TO INDICATOR AND REPLACED INDICATOR.	206.6	375	0	10.33	591.93
210121-00	SVC002597	02/15/2021	1H0360	ID - TIPPER	186_INT	S	Service	1VL263							
									REPAIR CRACKS IN TRAY	REPAIRED TARP AND OPERATION. SET UP TRAILER IN WORKSHOP FOR REPAIRS. GOUGE AND WELD REPAIR CRACKING IN AND AROUND HOIST WELL, REAR PIVOT AND ALONG RAILS. SAND AND BLEND OUT ALL WELD ENDS AND RETURNS. FINAL INSPECTION POST REPAIR.	751.55	60.38	0	25	836.93
210121-00	SVC002588	01/28/2021	1H0360	ID - TIPPER	182_INT	R	Trays/Buck	1VL263							
											1272.25	0	0	150	1422.25

CARRY OUT SERVICE									S1 TRAILER SERVICE						
									CARRY OUT SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. CHECK ALL ELECTRICAL SYSTEMS, SUSPENSION AND TYRES. GREASED, CHECKED AND ADJUSTED BRAKES. NEW WIRE ROPE ON SPRING. CHECKED ALL LIGHTS. CHECKED WHEEL BEARINGS. CHECK ALL HYDRAULIC SYSTEMS AND COUPLINGS. INSPECT TOW COUPLING.						
201130-00	SVC002564	12/10/2020	1H0360	ID - TIPPER: 187_INT	S	Service	1VL263	30/11/20	Service	** CRACKS BACK OF TRAILER U/S (AS REPORTED LAST SERVICE) Trailer service S1 SERVICE	106.53	3.58	0	5.33	115.44
									CARRY OUT SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. CHECK ALL ELECTRICAL SYSTEMS, SUSPENSION AND, TYRES. CHECKED, GREASED AND ADJUSTED BRAKES. FOUND AND FIXED CRACKS. CHECKED WHEEL BEARINGS & LIGHTS. CHECK ALL HYDRAULIC SYSTEMS AND COUPLINGS. INSPECT TOW COUPLING. REPLACE DOLLY RIDE HIGHT VALVE						
200923-00	SVC002528	10/09/2020	1H0360	ID - TIPPER: 187_INT	R	Suspensor	1VL263		Replace blown air bag		109.05	214.46	0	5.46	328.97
200924-00	SVC002530	10/09/2020	1H0360	ID - TIPPER: 187_INT	R	Suspensor	1VL263		INSTALL RUN OUT TYRES		140.28	620.89	0	7.02	768.19
200907-00	SVC002520	09/18/2020	1H0360	ID - TIPPER: 187_INT	R	Tyres	1VL263		ELECTRICAL REPAIR	INSTALL RUN OUT TYRES - DOWLING MCCARTHY - SUBLET ONLY ELECTRICAL REPAIR	0	377.5	0	0	377.5
									INSPECT ELECTRICAL FAULT ON REAR TRAILER. FOUND MULTIPLE RUBBED THROUGH WIRES ON BOTH L & R SIDES OF REAR. REWired REVERSE LIGHTS AND TAIL/STOP LIGHTS AND TIED UP WIRE SO AS NOT TO RUB. SUSPENSION REPAIR						
200907-00	SVC002520	09/17/2020	1H0360	ID - TIPPER: 187_INT	R	Electrical	1VL263	N/A	Suspension repair		554.25	49.6	0	27.72	631.57
									JACK UP AND REMOVE ALL WHEELS. UNBOLT SHOCKS, LOWER EACH AXLE DOWN, PRESS OUT SPRING EYE BUSHES AND REPLACE. HAD TO USE HEAT ON A COUPLE OF BUSHES THAT WERE A BIT STUBBORN. CLEAN OUT EYES WITH WIRE WHEEL AND INSTALL NEW BUSHES. REPLACED X 2 SHOCKS ON 3RD AXLE. REPLACED A FRAME BUSHES. LIGHT REPAIR						
200907-00	SVC002520	09/17/2020	1H0360	ID - TIPPER: 187_INT	R	Suspensor	1VL263		LIGHT REPAIR		1308.13	2045.31	0	50	3403.44
									NEW TRAILER PLUG FOR LIGHTS. STRIPPED ALL WIRES, INSTALLED IN NEW PLUG. TESTED ALL LIGHTS - ALL OK. CHECK AND INSPECT PLUG, FIT UP WIRES IN THE RIGHT TERMINALS, NOTHING RUBBING OR CAUSING SHORT. RE-ASSEMBLED PLUG AND INSULATED. TESTED CIRCUIT - ALL OK S1 INSPECTION						
200819-00	SVC002508	08/27/2020	1H0360	ID - TIPPER: 187_INT	R	Electrical	1VL263	182,304KM	s1 inspection	Trailer service	230.68	45.2	0	24.04	299.92
									CARRY OUT SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. CHECKED TURNTABLE, ALL LIGHTS, WHEEL BEARINGS. FIXED INDICATOR ON TRAILER. WELD ANGLE TO A FRAME FOR LANDING LEG. CHECK ALL ELECTRICAL SYSTEMS, SUSPENSION AND TYRES. CHECK AND ADJUST BRAKES. CHECK ALL HYDRAULIC SYSTEMS AND COUPLINGS. INSPECT TOW COUPLING.						
200803-00	SVC002510	08/21/2020	1H0360	ID - TIPPER: 187_INT	S	Service	1VL263	23874KM			157.68	111.06	0	7.89	276.63

									Brake reline		BRAKE RELINE							
200814-00	SVC002506	08/21/2020	1H0360	ID - TIPPER: 187_INT	R	Brake	1VL263	23874KM			FIT NEW BRAKE SHOES ON BACK TWO AXLES RIGHT SIDE OF TRAILER.	216.56	410	0	10.83	637.39		
											ADJUST BRAKES							
200618-00	SVC002475	06/26/2020	1H0360	ID - TIPPER: 187_INT	S	Brake	1VL263	19/6/20			ADJUSTED BRAKES ON TRAILER - CHECKED BRAKES AS WELL.	22.53	0	0	1.13	23.66		
											TYRE REPAIR X4 RUN OUT							
											REMOVE AND LOAD UP TYRES TO DROP OFF AT DOWLINGS TO HAVE TYRES CHANGED. PICK UP AND REFIT TO TO TRAILER.							
200520-00	SVC002465	06/19/2020	1H0360	ID - TIPPER: 187_INT	R	Tyres	1VL263	20/5/20			** NO CHARGE FROM DOWLINGS AS PER MITCHELL JAFFRAY **	145.4	0	0	7.27	152.67		
											SERVICE & BRAKE REALIGN							
											TRAILER SERVICE S1 SERVICE							
											CARRY OUT SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. ADJUSTED BRAKES - FOUND 1 X BRAKE IN NEED OF REALIGN REMOVED RHS 2ND WHEEL AND DRUM - REPLACED SHOES AND REASSEMBLED ADJUST BRAKE AND TENSIONED WHEEL NUTS CHECK ALL ELECTRICAL SYSTEMS, SUSPENSION AND TYRES. CHECK ALL HYDRAULIC SYSTEMS AND COUPLINGS. INSPECT TOW COUPLING.							
200610-00	SVC002475	06/19/2020	1H0360	ID - TIPPER: 187_INT	S	Service	1VL263				TARP REPAIR	187.95	208.98	0	9.4	406.33		
											LOOSEN TARP WIRES. REMOVE L/H TENSION PULLEY AND REPAIR ALL THREADS. REMOUNT AND REMOVE TARP WIRE. INSTALL NEW TARP WIRE AND TIGHTEN. TESTED - ALL OK REPLACED REAR MUD FLAPS.							
200507-00	SVC002455	05/21/2020	1H0360	ID - TIPPER: 187_INT	R	Trays/Buck	1VL263	6/5/20			TRAILER SERVICE S1 SERVICE	294.38	104.94	0	14.72	414.04		
											S1 service							
											CARRY OUT SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. CHECK ALL ELECTRICAL SYSTEMS, SUSPENSION AND, TYRES. CHECK AND ADJUST BRAKES. CHECK ALL HYDRAULIC SYSTEMS AND COUPLINGS. INSPECT TOW COUPLING JESSE: GREASED TRAILER, LOOKED FOR CRACKS, CHECKED AND ADJUSTED BRAKES. CHECKED TURN TABLE FOR CRACKS/WEAR. PUT NEW BRAKES ON FL AXLE. PUT NEW SHOCK IN BL OF TRAILER. BOLT WAS SEIZED IN THE NUT. SPRAYED HEAPS OF RUST SPRAY TO GET IT OUT. RUBBER BUSHED ON THE SHOCK WERE SEIZED ONTO THE BOLT, KNOCKED THEM OFF. PUT NEW SHOCK IN. REPLACED BR SHOCK BOTTOM BOLT. HAD TO TAKE BRAKE BOOSTER OFF TO GET TO THE NUT. PUT NEW BOTTOM BOLT IN BRAKE BOOSTER BACK ON. REPLACED ALL MUFLAPS AND REFLECTORS ON THE BACK OF THE TRAILER.							
200420-01	SVC002445	04/30/2020	1H0360	ID - TIPPER: 187_INT	S	Service	1VL263	22/4/20			REPAIR HYDRALIC HOSE	652.61	763.83	0	32.63	1449.07		
											REPAIR HYDRALIC HOSE							
200402-00	SVC002435	04/17/2020	1H0360	ID - TIPPER: 187_INT	R	Hydraulic	1VL263				REPLACE HYDRAULIC HOSE ON A FRAME TO TRUCK PUNCHER REPAIR	78.9	137.94	0	3.95	220.79		
											puncher repair							
200106-00	SVC002385	03/06/2020	1H0360	ID - TIPPER: 187_INT	R	Tyres	1VL263	23/12/19			SUBLET REPAIRS REPAIR AIR LINE	0	0	382.5	0	382.5		
											Repair air line							
200213-00	SVC002405	03/06/2020	1H0360	ID - TIPPER: 187_INT	R	Sundries	1VL263	13/02/20			REPLACE 3/8 AIR BRAKE LINE	36.35	80.4	0	1.82	118.57		
200228-00	SVC002415	03/06/2020	1H0360	ID - TIPPER: 187_INT	R	Sundries	1VL263	28/2/20			S1 SERVICE & REPAIR	230.5	107.31	0	11.53	349.34		

									TARP REPAIR	TARP REPAIR					
										REMOVE TARP WINDER HANDLE, POSITION NEW HANDLE ASSEMBLY AND MODIFY MOUNT HOLES TO SUIT. TRAVEL TO TAS BEARING AND CHAIN FOR NEW PULLEY BELT. FIX AND TENSION TEST - ALL OK.					
200212-00	SVC00240	02/21/2020	1H0360	ID - TIPPER	187_INT	R	Trays/Buck	1VL263	11/2/20		218.1	400	0	10.91	629.01
									CALL OUT BLOW TYRE	CALL OUT BLOW TYRE					
200207-00	SVC00240	02/20/2020	1H0360	ID - TIPPER	187_INT	R	Tyres	1VL263	6/2/20		433.8	0	60	21.69	515.49
									Service & Repairs	SERVICE & REPAIRS					
										CARRY OUT SERVICE REPAIRS. REMOVE BRAKE BOOSTER, GRIND WELDS OFF FROM SHOCKY MOUNTS (BOTTOM). REMOVEY SHOCKY AND REPLACE WITH NEW BOTTOM MOUNT. REPLACE HYDRAULIC COUPLING.					
200109-00	SVC00238	01/31/2020	1H0360	ID - TIPPER	187_INT	R	Service	1VL263	8/1/20	REPAIR FLAT TYRE	402.95	810.66	0	20.15	1233.76
										REPAIR FLAT TYRE.					
191211-00	SVC00237	12/17/2019	1H0360	ID - TIPPER	187_INT	R	Tyres	1VL263	11/12/19	PUMP UP LHS 4TH AXLE TYRE.	36.35	0	0	1.81	38.16
190510-00	SVC00227	11/26/2019	1H0360	ID - TIPPER	186_INT	R	Tyres	1VL263	NA	replace rim and fit tyres	857.85	363	0	0	1220.85
									TYRE REPAIR	TYRE REPAIR.					
										REMOVE AND REPLACE BLOWN TYRE ON TRAILER.					
190805-01	SVC00230	08/23/2019	1H0360	ID - TIPPER	187_INT	R	Tyres	1VL263	n/a 5/8/19	(LED SIDE MARKER MISSED PREV SERVICE CALL 190722-0043)	230.5	62	0	11.52	304.02
									PUNCTURE REPAIR	1VL263 TRAILER					
										REPAIR PUNCTURED TYRE.					
										(RUBAND TYRES)	0	0	58.5	0	58.5
190812-00	SVC00231	08/14/2019	1H0360	ID - TIPPER	183_INT	R	Tyres	1VL263		S1 SERVICE & CLEARANCE LIGHTS					
										CARRY OUT SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS.					
										CHECK ALL ELECTRICAL SYSTEMS, SUSPENSION AND, TYRES. CHECK AND ADJUST BRAKES.					
										CHECK ALL HYDRAULIC SYSTEMS AND COUPLINGS.					
190722-00	SVC00229	07/26/2019	1H0360	ID - TIPPER	187_INT	S	Service	1VL263	JULY 2019	REPAIRED CLEARANCE LIGHTS AND REPLACED WORK LIGHT.	181.75	56	0	9.09	246.84
									TARP REPAIR	TARP REPAIR.					
										TEST TARP. FOUND HARD TO WIND. ADJUSTED AND REMOVED ROCKS. WINDING IMPROVED BUT					
190715-00	SVC00229	07/19/2019	1H0360	ID - TIPPER	187_INT	R	Trays/Buck	1VL263	JULY 19	NEEDS NEW BLOCKS AND BEARINGS.	72.7	0	0	3.64	76.34
									Repair indicator fault	REPAIR INDICATOR FAULT.					
										REPAIRED INDICATORS. TRACED WIRING FAULT. FOUND RUBBED THROUGH ON REAR COVER RHS.					
190531-00	SVC00226	06/27/2019	1H0360	ID - TIPPER	187_INT	R	Electrical	1VL263	JUNE 2019	REPAIRED AND TESTED. ALL OK.	254.45	0	0	12.72	267.17
									S1 service	S1 SERVICE					
										CARRY OUT SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE.					
										GREASE ALL LUBRICATION POINTS.					
										CHECK ALL ELECTRICAL SYSTEMS, SUSPENSION AND, TYRES. CHECK AND ADJUST BRAKES.					
190603-00	SVC00227	06/27/2019	1H0360	ID - TIPPER	187_INT	S	Service	1VL263	JUNE 2019	CHECK ALL HYDRAULIC SYSTEMS AND COUPLINGS.	78.9	7.04	0	3.94	89.88
									REPLACE TYRES 11R22.5	REPLACE TYRES 11R22.5					
										SUPPLY AND REPLACE 2ND AXLE TYRES.	0	703	0	0	703
190605-00	SVC00227	06/20/2019	1H0360	ID - TIPPER	187_INT	R	Tyres	1VL263	JUNE 2019	ELECTRICAL REPAIR.					
										ELECTRICAL REPAIR.					
										TRACE WIRING SHORT ON BRAKE/REVERSE LIGHTS. REMOVE & STRIP OUT ELECTRICAL LOOM					
190605-00	SVC00227	06/20/2019	1H0360	ID - TIPPER	187_INT	R	Electrical	1VL263	3 JUNE 201	FROM TOW EYE TO TRAILER. ALSO REPLACED TRAILER PLUGS. SECURE LOOM. TEST. ALL OK.	654.3	0	0	32.71	687.01

									brake repair	BRAKE REPAIR.					
190523-00	SVC002264	05/29/2019	1H0360	ID - TIPPER: 187_INT	R	Brake	1VL263	N/A		ADJUST BRAKES. INSPECT LINGINGS. STILL 70% REMAINING.	72.7	0	0	3.64	76.34
									AIR LEAK DOLLY	TIGHTEN UP HOSE CLAMPS.					
										AIR LEAK DOLLY.					
190509-00	SVC002255	05/21/2019	1H0360	ID - TIPPER: 187_INT	R	Sundries	1VL263	N/A		CHECK FOR AIR LEAK ON DOLLY. RESECURE LINES TO REAR AXLE BOOSTERS.	72.7	9	0	3.64	85.34
									REPLACE DOLLY SHOCKYS	REPLACE HOSE CLAMPS ON SERVICE VALVE ENDS OF BOOSTER LINES.					
										REPLACE DOLLY SHOCKYS.					
190430-00	SVC002255	05/20/2019	1H0360	ID - TIPPER: 187_INT	R	Suspensior	1VL263	N/A		REMOVE FRONT & REAR AXLE SHOCKYS ON DOLLY.	204.25	0	0	10.21	214.46
									CALL OUT FLAT TYRE	FIT UP NEW ONES.					
										PARTS CHARGED ON PREV SERVICE CALL.					
										CALL OUT FLAT TYRE.					
190430-00	SVC002255	05/20/2019	1H0360	ID - TIPPER: 187_INT	R	Tyres	1VL263	N/A		CALLED OUT TO HB BURNIE WORKSHOP. REMOVE FLAT TYRE FROM	433.8	1418	0	21.69	1873.49
									FIT CUSTOMERS OWN PRODUCT	REAR RIGHT INSIDE. FIT UP AND RE-MOUNT TYRE. RE-TORQUE NUTS.					
										1VL263 TRAILER					
										FIT CUSTOMERS OWN PRODUCT.					
										TYRE DISPOSAL					
190507-00	SVC002255	05/08/2019	1H0360	ID - TIPPER: 183_INT	R	Tyres	1VL263			(RUBAND TYRES)	0	0	40.5	0	40.5
									S1 service	S1 SERVICE					
										CARRY OUT SERVICE AND SAFETY CHECKS AS PER					
										REQUIRED SCHEDULE.					
										GREASE ALL LUBRICATION POINTS.					
										CHECK ALL ELECTRICAL SYSTEMS, SUSPENSION, AIR CONTROLS					
										TYRES. INSPECT BALL RACE TURNTABLE.					
190418-00	SVC002245	04/30/2019	1H0360	ID - TIPPER: 187_INT	S	Service	1VL263	N/A		CHECK ALL HYDRAULIC SYSTEMS AND COUPLINGS.	218.1	3.48	0	10.91	232.49
190322-00	SVC002225	03/26/2019	1H0360	ID - TIPPER: 121_INT	R	Tyres	1VL263			ADJUST RIDE HEIGHT AND REPAIR AIR LINES TO REAR AXLE BOOSTER.	0	693	0	0	693
									11R22.5 BYS98 SPORTRAK X 2	11R22.5 BYS98 SPORTRAK X 2 + DISPOSAL X 2 RUBAND 56307					
									REPLACE DRAWBAR/DEFECTS LIST	REPLACE DRAWBAR AND ATTEND TO DEFECTS LIST					
										AFTER TRANSPORT DEFECTED TRAILER.					
190207-00	SVC002220	02/28/2019	1H0360	ID - TIPPER: 187_INT	R	Sundries	1VL263	N/A		REPAIRED DAMAGED SKIRT ON RH FRONT OF BIN.	1109.95	243.57	0	50	1403.52
									REPLACE REV LIGHT	REPLACE REV LIGHT.					
										INSPECT FOUR FAULTY LIGHTS.					
190225-00	SVC002210	02/28/2019	1H0360	ID - TIPPER: 187_INT	R	Electrical	1VL263	N/A		REMOVE AND REPLACE ASSEMBLIES WITH NEW ONES FROM ASHDOWNS.	75.8	111.5	0	3.79	191.09
									REPAIR CRACKS IN BIN	REPAIR CRACKS IN BIN.					
										GOUGE OUT & WELD UP CRACKS AS REQUIRED.					
										REFIT REAR CORNER FROM ACCIDENT DAMAGE.					
										REFIT RELEASE HANDLE AND REPLACE TAIL GATE					
190131-00	SVC002135	02/20/2019	1H0360	ID - TIPPER: 187_INT	R	Trays/Buck	1VL263	N/A		LOCK. REPAIR MUDFLAP BRACKETS.	75.8	0	0	3.79	79.59
									REPAIR DAMAGE TO TAILGATE LOCK	REPAIR DAMAGE TO TAILGATE LOCK AND REPLACE SIDE AMBER LIGHT.					
										REPAIR TAILGATE ACTUATOR. REPLACE WEAR PLATES ON DOGS.					
										REMOVE & REPLACE BROKEN MUDGUARD. REPAIR DAMAGED SKIRT.					
181219-00	SVC002175	01/30/2019	1H0360	ID - TIPPER: 187_INT	A	Trays/Buck	1VL263			REPLACE BROKEN TAIL LIGHT,	545.25	814.48	0	27.26	1386.99
190121-01	SVC002190	01/21/2019	1H0360	ID - TIPPER: 121_INT	R	Tyres	1VL263	N/A	Puncture repair	REPAIR CRACK IN RHR BIN LINER.	0	50	0	0	50
190111-00	SVC002165	01/15/2019	1H0360	ID - TIPPER: 121_INT	R	Tyres	1VL263		11R 22.5 KRT03 X 4 + DISPOSAL	11R 22.5 KRT03 X 4 + DISPOSAL X 4 RUBAND 54257 CARRIED OUT IN BURNIE	0	1406	0	0	1406
									INSPECT W/AL & W/BEARINGS	INSPECT W/AL & W/BEARINGS.					
										REMOVE WHEELS, BRAKES, SCAMS, BEARINGS.					
										CHANGE X 2 BOOSTERS, ALL S CAMS & TUBES.					
										REPLACE ANCHOR PIN BUSHES. CLEAN OUT & REPACK BEARINGS. REPLACE WHEEL					
										SEALS					
										SLACK ADJUSTERS. REFIT BRAKE SHOES. CHECK WHEEL ALIGNMENT 33MM OUT					
										A FRAME BENT.					
181213-00	SVC002175	01/10/2019	1H0360	ID - TIPPER: 187_INT	R	Suspensior	1VL263	N/A			1656.85	2159.42	0	50	3866.27

									REPAIR LIGHTING FAULT	REPAIR LIGHTING FAULT.					
190103-00	SVC002184	01/10/2019	1H0360	ID - TIPPER: 187_INT	R	Electrical	1VL263	N/A		REPAIR INDICATOR FAULT. FOUND BLOWN CIRCUIT BREAKER IN TRUCK. TRACED WIRES AND FOUND RUBBED THROUGH ON LIGHT BRACKET ON REAR LHS. REMOVED GUARD AND REINSTALLED WIRES. TESTED AND FOUND BROKEN WIRE IN PARK LIGHT. REPAIRED. TESTED ALL OK.	257.55	3.5	0	12.87	273.92
									HIFLY 11R22.5 HH104 X 4						
181211-00	SVC002171	12/12/2018	1H0360	ID - TIPPER: 121_INT	R	Tyres	1VL263			HIFLY 11R22.5 HH104 X 4 FIT COP X 1 DISPOSAL X 5 CARRIED OUT BY RUBAND	0	1333	0	0	1333
181109-00	SVC002152	11/16/2018	1H0360	ID - TIPPER: 187_INT	S	Service	1VL263	N/A	SI SERVICE	CARRIED OUT THE REQUIRED SERVICE AND SAFETY INSPECTIONS AS PER SERVICE SHEET	109.05	3.5	0	5	117.55
181113-00	SVC002153	11/15/2018	1H0360	ID - TIPPER: 187_INT	R	Trays/Buck	1VL263	NO HUB	TARP REPAIR	FABRICATE NEW FRONT HOOP BRACKET FOR TRAILER TO REPLACED SNAPPED SECTION, TEST OPERATION ALL GOOD	109.05	0	0	5	114.05
									TARP REPAIR	REMOVED WIRE ROPES AND LOOSEN OF ADJUSTERS, PULL ROPES THROUGH AND FIT WIRE ROPE GRIPS.					
181025-00	SVC002142	10/31/2018	1H0360	ID - TIPPER: 187_INT	R	Trays/Buck	1VL263	N/A		ADJUST TENSION ON ROPES TO DRIVER REQUIREMENTS	78.9	0	0	6	84.9
181026-00	SVC002143	10/31/2018	1H0360	ID - TIPPER: 187_INT	R	Brake	1VL263		CALL OUT BRAKE REPAIR	CALL OUT TO RAILTON, CUT BRAKE HOSE, REATTACJE TO BRAKE BOOSTER, ALL OK.	218.1	0	0	11	229.1
181015-00	SVC002133	10/15/2018	1H0360	ID - TIPPER: 121_INT	R	Tyres	1VL263		FIT COP + DISPOSAL CARRIED OUT	FIT COP + DISPOSAL CARRIED OUT AT DELORAINE TYRE CENTRE	0	0	271	0	271
									Repair tarp	CALLOUT REPAIR PUNCTURE CARRIED OUT IN BURNIE AFTER HOURS REPAIR TARP.					
										REMOVE BROKEN BRACKET. FABRICATE NEW ITEM FROM STEEL.					
181001-00	SVC002123	10/10/2018	1H0360	ID - TIPPER: 187_INT	R	Trays/Buck	1VL263			FIT & TEST. ALL GOOD.	181.75	50	0	9.09	240.84
181003-00	SVC002131	10/03/2018	1H0360	ID - TIPPER: 121_INT	R	Tyres	1VL263		FIT COP X 2 + STRIP & FIT + DI REPLACE MUD GUARD BRACKET	FIT COP X 2 + STRIP & FIT + DISPOSAL CARRIED OUT BY RUBAND 145390 REPLACE MUD GUARD BRACKET.	0	0	132	0	132
										REMOVE 3 GUARDS. FIT NEW GUARD BRACKETS & REFIT MUDFLAPS. FIT NEW TAIL LIGHTS TO RHR & TIDY UP WIRING. FIT NEW REV LIGHT. REPAIR AIR LINES UNDER DOLLY WHERE KINKED. GET PIRTEK TO MODIFY AIR HOSE. SECURE HOSES WITH ZIP TIES. REPAIR AIR LEAK AT BURST VALVE. GREASE & ADJUST BRAKES. CALL OUT REPAIR BOOSTER & HYD HOSE					
180831-00	SVC002111	09/28/2018	1H0360	ID - TIPPER: 187_INT	R	Sundries	1VL263	N/A	CALL OUT BOOSTER AND HYD HOSE		690.65	1195.8	0	34.53	1920.98
										TRAVEL TO FLOWERDALE SITE COMPLETE SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE. GREASE ALL LUBRICATION POINTS. CHANGE ENGINE OIL AND FILTER. CHANGE AIR FILTER. CHANGE COOLANT. CHECK ALL OTHER FLUID LEVELS.	254.45	490.6	364.64	137.72	1247.41
180921-00	SVC002122	09/28/2018	1H0360	ID - TIPPER: 187_INT	R	Brake	1VL263		Puncture repair	PUNCTURE REPAIR CARRIED OUT BY JOHN WAYNE TYRES BURNIE	0	0	50	0	50
180918-00	SVC002111	09/18/2018	1H0360	ID - TIPPER: 121_INT	R	Tyres	1VL263	NOT SUPPL	TARP REPAIR	TARP REPAIR.					
										ADJUST BOTH TARP CABLES. FABRICATE & FIT TARP HOLD DOWNS MANUFACTURED OUT OF STEEL FROM STOCK.	187.95	50.38	0	9.4	247.73
									REPAIR WIRING	REPAIR WIRING.					
										CUT OUT A FRAME SECTION OF 7 CORE WIRING WHERE RUBBED THROUGH. FIT NEW PIECE AND SOLDER INTO PLACE. ZIP TIE UP. FIT NEW 7 PIN PLUG. TEST. ALL GOOD.	78.9	16.75	0	3.94	99.59
180814-00	SVC002083	08/22/2018	1H0360	ID - TIPPER: 187_INT	R	Electrical	1VL263	NA	REPLACE 3RD LHS BRAKE BOOSTER	REPLACE 3RD LHS BRAKE BOOSTER. BLOCKED OFF BRAKE BOOSTER TO ALLOW IT TO RETURN TO THE WORKSHOP. REPLACED BRAKE BOOSTER AND ADJUSTED THE BRAKES.					
180727-00	SVC002091	07/30/2018	1H0360	ID - TIPPER: 186_INT	R	Brake	1VL263				222.6	57.05	0	10	289.65

							Tarp repairs		TARP REPAIRS. DISASSEMBLED DAMAGED TARP,CLEANED AND SENT TO CAPE COUNTRY FOR REPLACEMENT SAMPLE. REASSEMBLED TARP AND FITTED. REPAIRED ADJUSTERS AND FITTED NEW ROPES. FITTED BRACKETS TO RESTRAIN THE CENTRE OF THE TARP.						
180706-00	SVC002084	07/27/2018	1H0360	ID - TIPPER: 186_INT	R		Trays/Buck	1VL263		CHECKED OPERATION.	1404.96	47.92	1130	50	2632.88
									REPLACE RELAY VALVE	DIAGNOSED FAULT WITH PARK BRAKE LOCKING ON.REPLACED SPRING BRAKE RELAY VALVE.					
180724-00	SVC002085	07/27/2018	1H0360	ID - TIPPER: 186_INT	R		Brake	1VL263			181.75	112.57	0	9	303.32
180706-00	SVC002082	07/13/2018	1H0360	ID - TIPPER: 186_INT	S		Service	1VL263		300 HR SERVICE	212.98	0	0	10	222.98
									REPLACE TOW EYE & TRAY REPAIRS	Gouge and remove tow eye. Grind and prep tow eye base. Fit and weld out new two eye to drawbar. Touch up repair with paint. Cut and remove worn alloy floor sheet form tray. Sand and prep floor for new sheets. Cut and fabricate new alloy floor sheets into tray. Weld out all new floor sheeting.					
180524-00	SVC002055	06/25/2018	1H0360	ID - TIPPER: 182_INT	R		Sundries	1VL263		Repair cracks under hoist well.	1238.41	1105.27	0	0	2343.68
180427-00	SVC002040	05/07/2018	1H0360	ID - TIPPER: 186_INT	R		Brake	1VL263		ADJUST BRAKES REPLACE LEAKING HYDRAULIC FITT	57.53	0	0	0	57.53
										REPLACED BOTH MALE AND FEMALE HYDRAULIC FITTINGS ON THE TRAILER AND TRUCK.					
180427-00	SVC002041	05/07/2018	1H0360	ID - TIPPER: 186_INT	R		Hydraulic	1VL263			57.53	136.48	0	0	194.01
180322-00	SVC002030	04/26/2018	1H0360	ID - TIPPER: 187_INT	R		Sundries	1VL263	N/A	DRAW BAR BOLT 600 HR SERVICE	84.11	0	0	0	84.11
										COMPLETED SERVICE AS PER SERVICE SHEET. REPLACED MISSING REFLECTORS AND WORN DELINIATED LINE SIGNS. REPLACED AXLE SIDE THRUST PLATES AND SINGLE USE THROUGH BOLTS. HAD TO REMOVE THE WHEELS TO REMOVE THE THROUGH BOLTS.					
180416-00	SVC002032	04/20/2018	1H0360	ID - TIPPER: 186_INT	S		Service	1VL263		THROUGH BOLT TENSION NEEDS CHECKING NEXT SERVICE.	1765.92	1019.2	0	50	2835.12
180316-00	SVC002017	03/29/2018	1H0360	ID - TIPPER: 121_INT	R		Tyres	1VL263		SPORTRAC 11R22.5 B5Y98 X 4 REPAIR CRACKS	0	1366	0	0	1366
										Set up and press rear tailgate frame section over straight. Replace chain in centre of tray.					
180315-00	SVC002016	03/26/2018	1H0360	ID - TIPPER: 182_INT	R		Sundries	1VL263			107.03	0	0	0	107.03
180314-00	SVC002016	03/20/2018	1H0360	ID - TIPPER: 186_INT	R		Hydraulic	1VL263		REPLACE LOOSE TRUNION BOLTS CALLOUT PUNCTURE REPAIR	178.38	0	0	9	187.38
										REPLACED LOOSE TRUNION BOLTS					
180228-00	SVC002008	02/28/2018	1H0360	ID - TIPPER: 121_INT	R		Tyres	1VL263		CALLOUT PUNCTURE REPAIR CARRIED OUT BY RUBAND FIT COP X 2 + DISPOSAL X 2 CARRIED OUT BY RUBAND	0	0	243	0	243
									ADJUST BRAKES	ADJUST BRAKES.					
180214-00	SVC002000	02/21/2018	1H0360	ID - TIPPER: 187_INT	S		Brake	1VL263	N/A	ADJUST BRAKES ON ALL AXLES AS REQUESTED.	35.68	0	0	1.78	37.46
									Replace tail gate cylinder	REPLACE TAIL GATE CYLINDER.					
										WAS REPORTED THAT TAIL GATE CYLINDER U/S AND NEEDS REPLACING. TRAVELLED TO LONG HILL. REMOVED OLD TAIL GATE CYLINDER. GRIND BUSH ON BOTTOM OF TRAY TO SUIT NEW CYLINDER AND USED FITTINGS AND AIR LINE TO SUIT EXISTING ONES ON TRAILER.					
180201-00	SVC001996	02/07/2018	1H0360	ID - TIPPER: 187_INT	R		Trays/Buck	1VL263	N/A	TEST OPERATION. ALL OK.	361.58	150	0	193.08	704.66
									REPLACE A FRAME BUSHES	REPLACE A FRAME BUSHES. REPLACED A FRAME BUSHES, REMOVED BRAKE BOOSTER AND TIGHTENED LOOSE SHOCK ABSORBER MOUNT.REPLACED THREE OTHER SHOCK ABSORBER MOUNTING BOLTS..					
180123-00	SVC001990	01/30/2018	1H0360	ID - TIPPER: 186_INT	R		Steering	1VL263			321.08	25.04	0	10	356.12
171117-00	SVC001955	11/30/2017	1H0360	ID - TIPPER: 187_INT	S		Service	1VL263	N/A	GREASE AND CHECKS REPLACE MUD FLAPS	71.35	6.96	0	3.57	81.88
										REPLACE MUD FLAPS.					
171019-00	SVC001943	10/31/2017	1H0360	ID - TIPPER: 187_INT	R		Sundries	1VL263	N/A	REPLACE MISSING AND DAMAGED MUD FLAPS.	142.7	250.88	0	7.14	400.72

170918-00	SVC00193	10/04/2017	1H0360	ID - TIPPER	186_INT	R	Suspensior	1VL263	NO HUB MI	TRAILER SUSPENSION REPAIRS	TRAILER SUSPENSION REPAIRS. WASHED DOWN THE TRAILER IN THE STEAM CLEANED BAY AND TOWED BACK TO THE WORKSHOP. REMOVED 2ND AXLE ASSEMBLY FROM THE DOLLY. REMOVED THE WHEELS FROM THE 1ST AXLE. PLACED THE CHASSIS ON STANDS AND PRESSED OUT BUSHES FROM THE 2ND AXLE FITTED NEW BUSHES. WELDERS REPLACED BROKEN SPRING HANGER AND WELDED UP CRACKS IN TRAY AND CHASSIS. REFITTED AXLE AND NEW SIDE THRUST WASHERS. REFITTED WHEELS AND PERFORMED WHEEL ALIGNMENT. TENSIONED WHEEL NUTS AND REPLACED TOW EYE BUSH.	1654.13	781.87	0	50	2486
										600 HR SERVICE	600 HR SERVICE. COMPLETED SERVICE AS PER SERVICE SHEET. REPAIRED NUMBER PLATE WIRING AND CLEARANCE LIGHTS LHS. REPLACED MISSING REFLECTORS. REMOVED LIGHT ASSEMBLYS AND REPAIRED TAIL LIGHT WIRING. CHECKED A FRAME BUSHES.					
170918-00	SVC00193	10/04/2017	1H0360	ID - TIPPER	186_INT	S	Service	1VL263	NO HUB MI	REMOVE AND REPAIR SUSPENSION	Gather gear and set up work area. Gouge off damaged suspension hanger front LHS. Grind and prep hanger base. Fabricate and fit new hanger into position. Weld out new hanger and bracing plates. Gouge out and repair various cracks in and around trailer suspension. Repair cracks in ally tray body around hoist well and alond side combing.	300.3	3.47	0	15	318.77
170921-00	SVC00192	09/28/2017	1H0360	ID - TIPPER	182_INT	R	Sundries	1VL263		REPLACE TRAILER PLUG	REPLACED TRAILER PLUG AND REPAIRED THE WIRING AS REQUIRED	1504.56	0	0	50	1554.56
										INSPECT CHASSIS, AIR LEAKS	INSPECT CHASSIS AND CHECK AIR LEAKS.	107.03	6.72	0	0	113.75
170911-00	SVC00192	09/21/2017	1H0360	ID - TIPPER	187_INT	R	Suspensior	1VL263	N/A	Repair tarp	AIR LEAKING FROM DOLLY LOCK CYLINDER. REMOVED AND REPLACED CYLINDER INSPECTED AND DOCUMENTED CRACKS AND DAMAGE TO SUB FRAME AND TRAY. CRACKS AT FRONT CROSS MEMBERS BOTH SIDES. CRACK AT 2ND HANGER LHS (HANGER NEARLY CRACKED OF CHASSIS) CRACKS AT BOTH FRONT HANGERS. TRAILER GROUNDED. TAGGED TO GO TO HOBART ON FLOAT. REPAIR TARP.	518.4	206.41	0	25.92	750.73
170908-00	SVC00192	09/15/2017	1H0360	ID - TIPPER	187_INT	R	Trays/Buck	1VL263	N/A	REMOVE ALUMINUM TRAY EXTENSION	ADJUST BOTH WIRE ROPES TO TENSION TARP. REMOVE ALUMINUM TRAY EXTENSION.	96.94	0	0	4.85	101.79
170803-00	SVC00190	08/30/2017	1H0360	ID - TIPPER	187_INT	R	Trays/Buck	1VL263	N/A	REPLACE A FRAME BUSHES	CUT WELDS RETAINING HIGH SIDE BIN EXTENSION. REMOVE TARP DRIVE BELT AND ROPES. LIFT OFF HIGH SIDES FOR STORAGE. CLEAN UP TOP OF BIN WHERE PRODUCT HAD BEEN TRAPPED. SMOOTHED REMAINING WELDS AND SWAPPED TARP FROM EXTENSION TO ORIGINAL POSITON. FABRICATE BRACKETS FOR FRONT MOUNT FIRST LOOP. DRILL & TAP MOUNTING HOLES. FIT FRONT SHAFT & PULLEYS. FIT NEW ROPE & TENSION UP. FIT NEW BELT & TEST ALL GOOD. FABRICATE 2 WIRE ROPE STAYS & FIT TO MIDDLE OF BIN. INSTALLED NEW TARP.	1455.4	177.6	0	50	1683
170810-00	SVC00190	08/30/2017	1H0360	ID - TIPPER	187_INT	R	Sundries	1VL263	N/A	11R22.5 SPORTRAK BYS598	REMOVED WORN A FRAME BUSHES AND AND INSTALLED NEW ONES. CARRIED OUT WHEEL RETORQUE ON RHS 1ST AXLE.	258.73	37.54	0	12.94	309.21
											11R22.5 SPORTRAK BYS598 X2 + DISPOSAL X 2 RUBAND DD 38822	0	703	0	0	703

									REPLACE GUARD	REPLACE GUARD.					
170804-00	SVC001904	08/16/2017	1H0360	ID - TIPPER: 187_INT	R	Sundries	1VL263	N/A		REPLACE DAMAGED MUD GAARD LHS REAR DOLLY.	71.35	265.01	0	3.57	339.93
170628-00	SVC001884	06/29/2017	1H0360	ID - TIPPER: 187_INT	R	Sundries	1VL263	N/A	GUARD AND TARP REPAIR	REPLACE MUD FLAPS.	131.71	35	0	6.58	173.29
									REPLACE BLOWN HYD HOSE	GUARD AND TARP REPAIR					
170607-00	SVC001874	06/09/2017	1H0360	ID - TIPPER: 187_INT	R	Hydraulic	1VL263	N/A		REPLACE BLOWN HYDRAULIC HOSE	107.11	247.03	0	5.35	359.49
									S1 A SERVICE	FOR TRAILER.					
										S1 A SERVICE,					
										COMPLETE SERVICE AND SAFETY CHECK AS PER REQUIRED SCHEDULE.					
170530-00	SVC001871	06/08/2017	1H0360	ID - TIPPER: 187_INT	S	Service	1VL263	N/A		REPLACED BROKEN GREASE NIPPLE ON 3RD AXLE.	104.93	3.48	0	5.25	113.66
									TRAY REPAIRS	TRAY REPAIRS.					
170509-00	SVC001854	05/17/2017	1H0360	ID - TIPPER: 187_INT	R	Trays/Buck	1VL263	N/A		CARRY OUT WELDING REPAIRS TO FLOOR AND TOP EXTENSION ON TRAILER.	174.88	0	1256.95	8.74	1440.57
									S1 A SERVICE	S1 A SERVICE					
170515-00	SVC001861	05/17/2017	1H0360	ID - TIPPER: 187_INT	S	Service	1VL263	N/A		COMPLETE SERVICE AND SAFETY CHECKS AS PER REQUIRED SCHEDULE.	69.95	3.48	0	3.49	76.92
170501-00	SVC001854	05/10/2017	1H0360	ID - TIPPER: 187_INT	R	Sundries	1VL263	N/A	REPLACE TAILGATE CYLINDER	REPLACE TAILGATE CYLINDER.	104.93	189.62	0	5.25	299.8
									RELIN BRKES	RELIN BRKES.					
170412-00	SVC001841	04/28/2017	1H0360	ID - TIPPER: 187_INT	R	Brake	1VL263	N/A		CARRY OUT BRAKE RELIN ON LEFT HAND 3rd AXLE.	73.01	190.35	0	3.65	267.01
									Replace hydraulic hose	REPLACE HYDRAULIC HOSE.					
										REMOVED OLD HOSE AND REPLACED WITH NEW HYDRAULIC HOSE ON FRONT OF TRAILER DRAW BAR.					
										REFER EQUIPMENT FAULT REPORT 27620 DATED 27.03.17.					
170328-00	SVC001834	03/31/2017	1H0360	ID - TIPPER: 187_INT	R	Hydraulic	1VL263	N/A			26.78	99.36	0	1.34	127.48
									11R22.5 OR305 TYRE X 6 + FIT R	11R22.5 OR305 TYRE X 6 + FIT RUNOUT X 1 + BOLT ON X 1 SEND TO BURNIE					
170321-00	SVC001834	03/24/2017	1H0360	ID - TIPPER: 121_INT	R	Tyres	1VL263	NA		RUBAND DD 33984	0	1634	0	0	1634
									S1A SERVICE	S1A SERVICE					
										COMPETE SERVICE AND SAFETY CHECK AS PER REQUIRED SCHEDULE.					
170317-00	SVC001831	03/23/2017	1H0360	ID - TIPPER: 187_INT	S		1VL263	N/A		GREASED TRAILER, VISUAL CHECK OVER ALL OK.	69.95	3.48	0	3.49	76.92
									S 1 A SERVICE	S 1 A SERVICE					
										CARRY OUT TRAILER SERVICE AND SAFETY CHECK AS PER REQUIRED SCHEDULE.					
170201-00	SVC001814	02/08/2017	1H0360	ID - TIPPER: 187_INT	S	Service	1VL263			CARRY OUT REPLACEMENT OF U/S AIR HOSES AND LEAKING HOIST HOSE UNDER BALL RACE.	314.78	276.51	0	15.74	607.03
									REPLACE AIR LINES	REPLACE AIR LINES					
170111-00	SVC001801	01/24/2017	1H0360	ID - TIPPER: 187_INT	R	Brake	1VL263	N/A		CARRY OUT REPLACEMENT OF AIR BRAKE HOSES ON A-FRAME.	53.55	0	0	2.68	56.23
									TRAY REPAIRS	TRAY REPAIRS.					
161221-00	SVC001794	01/10/2017	1H0360	ID - TIPPER: 187_INT	R	Trays/Buck	1VL263	N/A		CARRY OUT WELDING REPAIRS TO TRAY AND FRAME EXTENSION.	177.93	0	235	8.89	421.82
170109-00	SVC001794	01/10/2017	1H0360	ID - TIPPER: 187_INT	R	Tyres	1VL263	no reading	ADVANCE 11R22.5 TYRES X 4	ADVANCE 11R22.5 TYRES X 4	0	1109.09	0	0	1109.09
									ADVANCE 275/70R22.5 X 2	FIT NEW TYRES					
161207-00	SVC001781	12/08/2016	1H0360	ID - TIPPER: 187_INT	R	Tyres	1VL263	no reading		ADVANCE 275/70R22.5 X 2	0	609.1	0	0	609.1
									TAILLIGHT REPAIRS	TAILLIGHT REPAIRS					
161121-00	SVC001771	11/28/2016	1H0360	ID - TIPPER: 187_INT	R	Electrical	1VL263	N/A		CARRY OUT REPAIRS TO SIDE AND REAR TAILIGHT WIRING. SUBCONTRACTOR ONLY.	0	0	42	0	42
									BRAKE INSPECTION	BRAKE INSPECTION					
161017-00	SVC001754	10/21/2016	1H0360	ID - TIPPER: 187_INT	R	Brake	1VL263	N/A		CARRY OUT RELIN OF BRAKES	318.68	321	0	15.93	655.61
									Brake relin	FOUND TO BE LIMIT ON INSPECTIONS					
										BRAKE RELIN					
160826-00	SVC001731	09/07/2016	1H0360	ID - TIPPER: 187_INT	R	Brake	1VL263	N/A		CARRY OUT RELING OF BRAKES FRONT AXLE ,3rd AND 4th AXLES REBUSH CAMSHAFTS AS REQUIRED	433.13	875.01	0	21.66	1329.8

160629-00	SVC00170	07/12/2016	1H0360	ID - TIPPER	187_INT	R	Tyres	1VL263	N/A	CALLOUT - REPLACE FLAT TYRE	CALLOUT - REPLACE FLAT TYRE					
160627-00	SVC00170	06/30/2016	1H0360	ID - TIPPER	187_INT	R	Hydraulic	1VL263	N/A	Replace hydraulic hose	OUT OF HOURS CHANGE FLAT TYRE	420	0	0	44	464
										RELINER BRAKES	FABRICATE AND REPLACE HYDRAULIC HOSE AS REQUIRED	68.25	97.7	0	0	165.95
160607-00	SVC00169	06/17/2016	1H0360	ID - TIPPER	187_INT	R	Brake	1VL263	N/A	RELINER BRAKES	RELINER BRAKES					
										2 X TORNADO 11R22.5 TYRES	CARRY OUT RELINER OF BRAKES AND DRUM REPLACEMENT	273	946.5	0	15	1234.5
160601-00	SVC00169	06/09/2016	1H0360	ID - TIPPER	187_INT	R	Tyres	1VL263	no reading	2 X TORNADO 11R22.5 TYRES	2 X TORNADO 11R22.5 TYRES 2 X DISPOSAL TYRRIGHT BURNIE JOB# BUJC0005237	0	556.36	0	0	556.36
160601-00	SVC00169	06/09/2016	1H0360	ID - TIPPER	187_INT	R	Tyres	1VL263	no reading	2 X TORNADO 11R22.5 TYRES	2 X TORNADO 11R22.5 TYRES, 1 X FIT OWN RUNOUT, 1 X DISPOSAL. TYRRIGHT BURNIE JOB# BUJC0005108.	0	560	0	0	560
160601-00	SVC00169	06/09/2016	1H0360	ID - TIPPER	187_INT	R	Tyres	1VL263	no reading	2 X ADVANCE TYRES & WHEELS	2 X ADVANCE 11R22.5 GL671 TYRES, 2 X WHEELS. TYRRIGHT BURNIE JOB# BUJC0005256.	0	1190.9	0	0	1190.9
160523-00	SVC00165	05/27/2016	1H0360	ID - TIPPER	187_INT	R	Suspension	1VL263	N/A	REPLACE SHOCK ABSORBER	REMOVE AND REPLACE SHOCK ABSORBERS AS REQUIRED	68.25	128.6	0	0	196.85
160503-00	SVC00168	05/23/2016	1H0360	ID - TIPPER	187_INT	R	Trays/Buck	1VL263		REPLACE SWING DOWN LADDER	REPLACE SWING DOWN LADDER	68.25	210	0	0	278.25
										REPAIR CLEARANCE LIGHTS	REPAIR CLEARANCE LIGHTS					
160517-00	SVC00168	05/23/2016	1H0360	ID - TIPPER	187_INT	R	Electrical	1VL263	N/A		CARRY OUT REPAIRS TO TRAILER SIDE LIGHT WIRING	68.25	0	0	3.5	71.75
										TARP ADJUSTMENT	TARP ADJUSTMENT					
160502-00	SVC00167	05/06/2016	1H0360	ID - TIPPER	187_INT	R	Trays/Buck	1VL263	N/A		CARRY OUT ADJUSTMENT TO TARP WIRES	68.25	0	0	0	68.25
										REMOVE TARP & EXTENSION TOP	REMOVED OLD ROLLOVER TARP AND REMOVED EXTENSION TOP FITTED BY HOBART WORKSHOP.					
											CLEAN UP ALL AREAS WHERE EXTENSION HAD BEEN WELDED. REMOVE CROSS SHAFT AND BEARINGS	687.75	16	1254	0	1957.75
160311-00	SVC00164	05/04/2016	1H0360	ID - TIPPER	187_INT	R	Trays/Buck	1VL263		replace tarp	CARRY OUT FITTING OF NEW TARP ON BIN EXTENSION					
160323-00	SVC00165	04/28/2016	1H0360	ID - TIPPER	187_INT	F	Trays/Buck	1VL263			CARRY OUT REPLACEMENT OF BEARING CROSS SHAFT AND BEARINGS	1470.55	258.28	1090	0	2818.83
160411-00	SVC00166	04/12/2016	1H0360	ID - TIPPER	121_INT	F	Sundries	1VL263		ALUMINIUM BIN EXTENSION	FABRICATE AND FIT TRAILER EXTENSION CARRIED OUT BY JENSENS	0	0	0	0	0
160411-00	SVC00166	04/12/2016	1H0360	ID - TIPPER	121_INT	F	Sundries	1VL263		ALUMINIUM BIN EXTENSION	FABRICATION OF TRAILER EXTENSION CARRIED OUT BY JENSENS	0	0	12960	0	12960
160311-00	SVC00164	03/21/2016	1H0360	ID - TIPPER	187_INT	R	Sundries	1VL263		REPLACE MUDGUARDS	Removed and replaced mud guards on 1vl263.	204.76	100	0	0	304.76
										TARP AND TRAY REPAIRS	TARP AND TRAY REPAIRS					
											CARRY OUT REMOVAL OF ROLL OVER TARP AND TAKE TO WYNYARD AND HAVE REPAIRED AFTER BEING TORN REPLACE CENTRE POLE ON TARP TWICE AFTER REPLACEMENT IT WAS BENT AGAIN AND WAS THEN LEFT OUT					
											CARRY OUT WELDING REPAIR TO RIGHT HAND SIDE OF EXTENSION AFTER LARGE TEAR IN TOP					
											REFIT TARP ON TO EXTENSION AND RERIVET TARP SLIDE					
160216-00	SVC00163	03/10/2016	1H0360	ID - TIPPER	187_INT	R	Trays/Buck	1VL263			CARRY OUT REPLACEMENT OF REAR MAT WHICH WAS HANGING DOWN ON REAR SECTION THIS WAS DONE 3 TIMES AS IT WAS BEING RIPPED OFF	1538.79	166.65	440	50	2195.44
										REPLACE MAT IN REAR OF BIN	SUPPLY AND FIT MAT AT REAR OPENING OF TRAILER TO STOP PRODUCT LEAKING OUT	165.38	0	0	0	165.38
160224-00	SVC00164	03/02/2016	1H0360	ID - TIPPER	187_INT	R	Trays/Buck	1VL263		CHECK LIGHTS REPAIR AS NECESSA	REPAIR WIRING TO LEFT HAND FRONT CLEARANCE LIGHTS ON TRAY AND REPAIR BROKEN WIRES IN HARNESS TO RIGHT HAND TAIL LIGHTS	136.5	0	0	6.5	143
160213-00	SVC00164	02/29/2016	1H0360	ID - TIPPER	186_INT	R		1VL263	259,673 Kilo	REPAIR TRAP ROLLER	REPAIR TRAP ROLLER					
											CARRY OUT MODIFICATIONS TO TOP OF BIN TO ALLOW ROLL OVER TARP TO BE USED REMOVE TARP AND REPLACE BROKEN SPRING THAT WAS BROKEN INSIDE TARP POLE SET UP SPRING TO WORK CORRECTLY					
											SUPPLY AND FIT ROLLOVER TOP BRACKETS AND ALSO FIT PLATES TO ALLOW TARP TO BE SECURED WHEN ROLLED OVER MANUFACTURE STOP BRACKETS ON SIDE OF BIN EXTENSION					
											REMOVE TARP HANDLE AND MODIFY WITH 2 PEICES OF SQUARE TUBE TO ALLOW DRIVER TO ROLL TARP USING ONLY 1 UNIVERSAL					
											CUT OUT REAR SECTION OF TRAILER WHICH TAILGATE HAD JAMMED ON AND WELD CORNERS WHRE SPLIT FROM TAILGATE, FIT RUBBER FLAP ONTO REAR END OF BIN TO STOP PRODUCT SPILLING OUT THE BACK END					
											TEST AND OPERATE TARP SEVERAL TIMES ALSO FIT STRAP ASSY ON FRONT TO STOP TARP FROM LIFTING UP WHILE TRAVELLING					
160204-00	SVC00163	02/26/2016	1H0360	ID - TIPPER	187_INT	R	Sundries	1VL263		EXTEND HEIGHT OF ALLY TRAY USI	Extend the tray height to allow addition payload.	999.94	29.54	1865	0	2894.48
											Two bins were recovered from HBMI.					
											Both were cut down and the best bits turned into one bin, the height of the bin had to be lowered to give a clearance of 3600mm. The top of the bin was kept flat to give maximum payload and to keep the heigh down.					
											The tarp was installed a tarp pipe was fabricated and the uniort tested, a second universal was installed to allow the tarp handle to be positioned up the side of the tray.					
											The front of the tray under the existing tarp had to have a plate installed to prevent the loss of product from under the tarp.					
160122-00	SVC00162	02/25/2016	1H0360	ID - TIPPER	182_INT	F	Trays/Buck	1VL263				5611.23	742.38	0	50	6403.61
160212-00	SVC00163	02/24/2016	1H0360	ID - TIPPER	187_INT	R	Brake	1VL263	N/A	ADJUST BRAKES	Adjust trailer brakes.	68.25	0	0	0	68.25

160215-00	SVC001634	02/23/2016	1H0360	ID - TIPPER: 187_INT	R	Hydraulic	1VL263	N/A	Replace hydraulic hose	REPLACED HYDRAULIC HOSE	68.25	0	64.22	0	132.47
									CHANGE TYRES	CHANGE TYRES					
160211-00	SVC001633	02/22/2016	1H0360	ID - TIPPER: 187_INT	R	Tyres	1VL263	N/A		REPLACE PUNCTURED TYRES WITH SPARE RUNOUT TYRES (SPARE RUNOUTS ALREADY FITTED TO RIMS)	68.25	0	0	0	68.25
									REPAIRS TO TRAILER SUSPENSION	Repair trailer suspension mount The second axle had to be removed inc the air bag mounts to acess the damaged area. The suspension mount was torn from the right hand side of the chassis and the left had started to crack. The mount was cleaned up and reattached to the chassis. The left side was also repaired. The suspension was reinstalled and all removed items were refitted. The wheels were reinstalled and the trailer relocated out side.					
160114-00	SVC001621	02/17/2016	1H0360	ID - TIPPER: 182_INT	R	Trays/Buck	1VL263				3270.24	17.63	0	50	3337.87
									CALL OUT - HYD COUPLING FAULTS	1VL263					
160210-00	SVC001633	02/17/2016	1H0360	ID - TIPPER: 105	R	Hydraulic	1VL263			JOB CARRIED OUT - CALL OUT - FAILED HYD COUPLING, TEMP REPAIRS. REMOVE BROKEN TARP ASSEMBLY	183.75	0	0	0	183.75
160204-00	SVC001630	02/12/2016	1H0360	ID - TIPPER: 187_INT	R	Hydraulic	1VL263	N/A	REPLACE HYDRAULIC COUPLING	REPLACED FIALED HYDRAULIC COUPLING AS REQUIRED	34.13	138.75	0	0	172.88
151218-00	SVC001611	12/21/2015	1H0360	ID - TIPPER: 184_INT	R	Hydraulic	1VL263	N/A	Replace hydraulic hose	REMOVED AND REPLACE LEAKING HOSE, TEST OPERATION	78.75	66.27	0	0	145.02
									REPAIR LOOSE SHOCK/HYD HOSE	TENSIONED LOOSE SHOCK ABSORBER AND REPLACED THE HOIST HOSE, HOIST TO DRAW BAR.	102.38	55.3	0	0	157.68
151130-00	SVC001603	12/07/2015	1H0360	ID - TIPPER: 186_INT	R	Suspensior	1VL263		Check and Repair Lights	CHECK OUT LIGHTS, RH INDICATOR NOT WORKING, DISMANTLE PLUG, REFIT RH INDICATOR WIRING AND SEVERAL OTHERS, REASSEMBLED PLUG AND TEST OPERATION ALL OK	68.25	0	0	0	68.25
151125-00	SVC001601	12/02/2015	1H0360	ID - TIPPER: 186_INT	R	Electrical	1VL263	NO HUB MI			0	0	0	0	0
151123-00	SVC001597	11/25/2015	1H0360	ID - TIPPER: 121_INT	R	Tyres	1VL263		PUNCTURE REPAIRS - RUBAND	PUNCTURE REPAIRS - RUBAND	0	0	0	0	0
151123-00	SVC001595	11/25/2015	1H0360	ID - TIPPER: 121_INT	R	Tyres	1VL263		PUNCTURE REPAIRS - RUBAND Tarp repairs	PUNCTURE REPAIRS - RUBAND TARP REPAIRS. REMOVED FRONT TARP PULLEY SYSTEM.HAD BENT SHAFT REPLACED AND WORN PULLEY REPLACED. REMOVED END OF TARP FROM HEAD BOARD AND WELDED UP CRACK.REFITTED PULLEY SYSTEM AND REPLACED ADJUSTER ROLLER. REFITTED TARP AND ADJUSTED.	0	40.91	0	0	40.91
151109-00	SVC001545	11/18/2015	1H0360	ID - TIPPER: 186_INT	R	Bodywork	1VL263				580.14	2.4	0	0	582.54
									Tarp repairs	REPAIRED TARP FAULT REPAIRED BROKEN ADJUSTEMENT BOTL ON LH SIDE CABLE ADJUSTER INSTALLED NEW BEARING FOR ADJUSTER AND TARP PULLEY ADJUST TARPS TO ENSURE PULLING STRIAIGHT checked the lights. Found no lights on the tray. Repaired the wiring to the top left hand side and the park/clearance light. Broken wires was the issue.					
151005-00	SVC001590	11/03/2015	1H0360	ID - TIPPER: 186_INT	R	Sundries	1VL263				215.25	2.4	0	10	227.65
									CHECK LIGHTSREPAIR AS NECESSAR						
151005-00	SVC001587	10/28/2015	1H0360	ID - TIPPER: 186_INT	R	Electrical	1VL263				307.13	0	0	15	322.13
									W/POWER 11R 22.5 HN06 X 4	W/POWER 11R 22.5 HN06 X 4 + DISPOSAL X 4 + STRIP AND FIT X 3 RUBAND 17737					
150925-00	SVC001571	10/09/2015	1H0360	ID - TIPPER: 121_INT	R	Tyres	1VL263				0	1488	0	0	1488
									REPLACE LEAKING HOIST CYL HOSE	FABRICATE AND REPLACED LEAKING HYDRAULIC HOSE THAT WAS LEAKING AT THE CRIMP, TEST OPERATION ALL GOOD	164.85	62.13	0	8	234.98
150821-00	SVC001553	08/25/2015	1H0360	ID - TIPPER: 184_INT	R	Hydraulic	1VL263	N/A	SERVICE /REPLACE WIRE ROPE	SERVICE /REPLACE WIRE ROPE. REPLACED WIRE ROPE,REPLACED MISSING SHOCK ABSORBER BOLT AND CHECKED REMAINING BOLTS. REPLACED MISSING SIGN AND REAR SIGN. COMPLETED SERVICE AS PER SERVICE SHEET.					
150701-00	SVC001533	07/10/2015	1H0360	ID - TIPPER: 186_INT	S	Service	1VL263		REPLACE TRAILER PLUG AND REPA	TRAVELED TO HBMI TO REPLACE TRAILER PLUG AND REPAIR WIRING ON LIGHTING CIRCUIT	477.76	46.1	0	23	546.86
150617-00	SVC001527	06/30/2015	1H0360	ID - TIPPER: 184_INT	R	Electrical	1VL263	N/A			220.51	5.6	0	33	259.11
150216-01	SVC001461	03/18/2015	1H0360	ID - TIPPER: 186_INT	R	Sundries	1VL263		TIGHTEN HOIST BOLTS	CHECK AND TIGHTEN HOIST BOLTS	34.13	0	0	0	34.13
									CHECK LIGHTS REPAIR AS NECESSA	CHECKED WIRING AT THE REAR OF TRAILER ALL GOOD, SUPPLY AND FIT NEW 7 PIN PLUG.	68.25	5.6	0	3.5	77.35
150210-00	SVC001456	02/18/2015	1H0360	ID - TIPPER: 186_INT	R	Electrical	1VL263				0	81.82	0	0	81.82
150216-00	SVC001453	02/16/2015	1H0360	ID - TIPPER: 121_INT	R	Tyres	1VL263		PUNCTURE REPAIR RUBAND 113331 TIGHTEN REAR SHOCK ABSORBERS	PUNCTURE REPAIR RUBAND 113331 X 2 TIGHTEN REAR SHOCK ABSORBERS. REPLACED MISSING BOLT AND TIGHTENED REMAINING SHOCK ABSORBER BOLTS.					
150212-00	SVC001454	02/13/2015	1H0360	ID - TIPPER: 186_INT	R	Suspensior	1VL263	NO HUB MI			34.13	0	0	0	34.13
									Tarp repairs	REMOVED TRAP TIE DOWN BOLTS. REPLACED WITH NEW BARS. MAKE NEW TRAP STRAPS	147	5.46	0	7	159.46
141218-00	SVC001433	01/20/2015	1H0360	ID - TIPPER: 186_INT	R	Ancillary Ec	1VL263	NO HUB MI	REPAIR TRAY CHAIN AND DRAW BAR	REPAIR TRAY CHAIN AND DRAW BAR LEG WELD LUG BACK ON INNER SIDE OF TRAY, FITTED EXTRA PIECE OF CHAIN BETWEEN THE TOO POINTS. MADE UP AND FITTED NEW ANCHOR POINT FOR DRAWBAR LEG, REFITTED REAR RIGHT HAND SIDE MUDFLAP AND LIGHT COVER					
141231-00	SVC001441	01/20/2015	1H0360	ID - TIPPER: 186_INT	R	Ancillary Ec	1VL263	NO HUB MI			238.88	0	0	11.5	250.38

										Service and Clean	SERVICE AND CLEAN CLEANED TRAILER AND REMOVED DOG LOCK VALVE AND REFITTED NEW VALVE REMOVED BROKEN SHOCK ABSORBER BOLTS AND BRACKET. HAD NEW BRACKETS WELDED TO AXLE AND REFITTED SHOCK ABSORBERS WITH NEW BOLTS						
141204-00	SVC00142	01/19/2015	1H0360	ID - TIPPER	186_INT	R	Service	1VL263	NO HUB MI			1296.76	132.19	0	50	1478.95	
141218-00	SVC00142	12/19/2014	1H0360	ID - TIPPER	182_INT	R	Suspensior	1VL263		REPAIRS TO BROKEN SHOCK HANGER REPAIRS TO DOG LOCKS & TARP SH		210	0	0	10.5	220.5	
											REPAIR BROKEN SHOCK HANGER REPAIRS TO DOG LOCKS, REQUIRES PACKERS TO BE WELDED ON, REMOVE TARP COMPLETELY, SETUP WELDER, PREP & WELD CRACKS AS REQUIRED, CLEAN OUT ALL SHARP AREAS, CLEAN UP WELDS ETC	810.5	70.03	0	40.5	921.03	
140314-00	SVC00127	04/10/2014	1H0360	ID - TIPPER	182_INT	R	Trays/Buck	1VL263		TYRES W/LAKE CR944 11R X2 + DI							
140320-00	SVC00127	03/29/2014	1H0360	ID - TIPPER	121ADMIN	R	Tyres	1VL263	NO HUB MI			0	694	0	0	694	
140203-00	SVC00126	03/21/2014	1H0360	ID - TIPPER	186_INT	S	Service	1VL263	TBA	Service as per schedule WIRE IN REVERSE LIGHT		75	20.46	0	0	95.46	
140131-00	SVC00125	02/04/2014	1H0360	ID - TIPPER	186_INT	R	Electrical	1VL263				97.5	0	0	4.5	102	
140204-00	SVC00125	02/04/2014	1H0360	ID - TIPPER	121ADMIN	R	Tyres	1VL263	315044	PUNCTURE REPAIR + CALLOUT		0	160	0	0	160	
131220-00	SVC00123	12/27/2013	1H0360	ID - TIPPER	121ADMIN	R	Tyres	1VL263		W/LAKE CR944 11R X 2 + DISPOSA		0	694	0	0	694	
131202-00	SVC00122	12/05/2013	1H0360	ID - TIPPER	186_INT	R		1VL263		REPLACE DAMAGED BRAKE BOOSTER		20	0	0	0	20	
131021-00	SVC00119	10/22/2013	1H0360	ID - TIPPER	121ADMIN	R	Tyres	1VL263	N/A	GOODRICK 11R22.5 944 X2 + DISP Replace hydraulic hose		0	694	0	0	694	
131015-00	SVC00119	10/17/2013	1H0360	ID - TIPPER	186_INT	R	Hydraulic	1VL263				97.5	370.21	0	0	467.71	
130821-00	SVC00115	08/22/2013	1H0360	ID - TIPPER	121ADMIN	R	Tyres	1VL263	N/A	RUBAND 11R22.5 AAA X1 + DISPOS		0	342	0	0	342	
130816-00	SVC00115	08/20/2013	1H0360	ID - TIPPER	121ADMIN	R	Tyres	1VL263		11R22.5 ADVANCE GL74 X 1 + SER		0	522	0	0	522	
130708-00	SVC00113	07/10/2013	1H0360	ID - TIPPER	186_INT	R	Brake	1VL263	270239 km	REPAIR LEAKING AIR HOSE		65	8.58	0	3.5	77.08	
130702-00	SVC00112	07/02/2013	1H0360	ID - TIPPER	121ADMIN	R	Tyres	1VL263		FIT COP + DISPOSAL RUBAND 9957		0	32	0	0	32	
130626-00	SVC00112	06/28/2013	1H0360	ID - TIPPER	121ADMIN	R	Tyres	1VL263	N/A	G/RIDE 11R22.5 CR944 X2 + FIT Service		0	758	0	0	758	
											Completed service as per service sheet. Replaced tow eye bush. Replaced a frame spring chain ends.	227.5	77.73	0	11	316.23	
130603-00	SVC00111	06/05/2013	1H0360	ID - TIPPER	186_INT	S	Service	1VL263	274853 km			182.5	214	0	2.88	399.38	
130516-00	SVC00110	05/28/2013	1H0360	ID - TIPPER	184_INT	R	Electrical	1VL263	N/A	FIT LED REVERSE LIGHTS		0	694	0	0	694	
130510-00	SVC00109	05/10/2013	1H0360	ID - TIPPER	186_INT	R	Tyres	1VL263	258553	11R22.5 W/LAKE 944 X 2 + DISPO CHECK RIDE HEIGHT							
											11R22.5 W/LAKE 944 X 2 + DISPOSAL X 2 RUBAND 74332 CHECK RIDE HEIGHT. Removed lever off ride height valve and cycler the valve through lower and raise. Refitted lever.height OK.	25	0	0	0	25	
130314-00	SVC00107	03/22/2013	1H0101	ID - TRANS	186HEAVY	R	Suspensior	1VL263				32.5	92	0	0	124.5	
121019-00	SVC00099	11/28/2012	1H0101	ID - TRANS	186_INT	R	Suspensior	1VL263		REPLACE SHOCK ABSORBER TYRES RUBAND D/D 69686							
											REMOVE AND REPLACE SHOCK ABSORBERS AS REQUIRED TYRES RUBAND D/D 69686 CALL OUT - TYRES DION MORGAN	0	954	0	0	954	
120925-00	SVC00097	09/28/2012	1H0101	ID - TRANS	186_INT	R	Tyres	1VL263	N/A			0	684	0	0	684	
120706-00	SVC00092	07/10/2012	1H0101	ID - TRANS	186_INT	R	Tyres	1VL263	N/A	TYRES - RUBAND # 68359 TYRES X2							
											SUPPLY TYRES 11R22.5AAA166 X 2 AND SCRAP, RUBAND TYRES X 2 RUBAND 67233 101-6283 - DION MORGAN 10AA00CTA5 AAA 11R22.5 STRIP AND FIT SCRAP	0	704	0	0	704	
120524-00	SVC00090	06/20/2012	1H0101	ID - TRANS	186_INT	R	Tyres	1VL263		Puncture repair		0	40	0	0	40	
120515-00	SVC00089	05/17/2012	1H0101	ID - TRANS	186_INT	R	Tyres	1VL263				59	0	0	0	59	
120427-00	SVC00088	05/03/2012	1H0101	ID - TRANS	181_INT	F	Sundries	1VL263		FIT REFLECTIVE TAPE TO SIDES A							
120320-00	SVC00086	03/27/2012	1H0101	ID - TRANS	186_INT	R	Tyres	1VL263		TYRE REPAIRS RUBAND 64884		0	40	0	0	40	
120216-00	SVC00084	02/22/2012	1H0101	ID - TRANS	186_INT	R	Tyres	1VL263		TYRE REPAIRS RUBAND 64706		0	714	0	0	714	
110615-00	SVC00071	08/23/2011	1H0101	ID - TRANS	182_INT	R	Trays/Buck	1VL263		REPAIR TRAY SIDES AFTER ACCIDE		10771.5	4413.8	144	0	15329.3	
110706-00	SVC00072	08/15/2011	1H0101	ID - TRANS	186_INT	A	Electrical	1VL263		REPAIRS TO SIDE LIGHTS AFTER Service		354	39.5	0	0	393.5	
											SERVICE. Completed service as per service sheet. Drilled new mounting holes for tarp pullies and handles. Assemble tarp and fit to trailer.						
110708-00	SVC00073	07/22/2011	1H0101	ID - TRANS	186_INT	R	Service	1VL263				958.75	0	275	0	1233.75	
110509-00	SVC00070	06/07/2011	1H0101	ID - TRANS	122_INT	R	Tyres	1VL263		TYRE REPAIRS RUBAND 58083		0	40	0	0	40	
110406-00	SVC00067	04/06/2011	1H0101	ID - TRANS	122_INT	R	Tyres	1VL263	N/A	TYRE REPAIR RUBANDS 57525		0	40	0	0	40	
100819-00	CR000142	01/31/2011	1H0101	ID - TRANS	186_INT	W	Brake	1VL263	new trailer	WARRANTY REPAIR BRAKE INBALANC WARRANTY REPAIR BRAKE INBALANC		0	0	0	0	0	
											Warranty invoice short paid by by \$26.25 Repair brake inbalance. Chassis 6T9T24V97A0AFH144						
											The hubs were removed and the drums washed out to remove the preserver. The shoes were also cleaned out, and the wheel groups reassembled. the trailer was retested all ok.	206.5	0	0	0	206.5	

100818-00	SVC00055	09/06/2010	1H0101	ID - TIP TRU 186_INT	F	Sundries	1VL263	new trailer	PRE INSP AND PAPER WORK	pre rego inspection. Failed the initial brake test due to wax preserver not being cleaned off the drums, the unit was repaired and retested as required.	29.5	1.72	306.4	0	337.62
100826-00	SVC00056	08/26/2010	1H0101	ID - TIP TRU 189_INT	W	Brake	1VL263	0KMS	IMBALANCE	FIRST AXLE BRAKE IMBALANCE. REMOVE BOTH FROM AXLE DRUMS AND CLEAN UP BUILD UP ON LININGS. RETEST ON BRAKE BALANCE MACHINE	0	0	0	0	0

Applied filters:Posted_Date is on or after 01/01/1900Equipment_ID is 1VL263