ruck -Trailer ruck -Trailer and service and service

549 DAR POINT HAR MAR WINNIPEG MB R3G 2E622 204-632-5184 SACCIONES NO. CUSTOMES NO. CUST

CASH CUSTOMER

SOLD TO:

BOX 65 GRP 200 RR 2 WINNIPEG MB R3C 2E6

SHIP WARD

TO:

O: ""

WINNIPEG MB R3C 2E6

CUSTOMER P.O. REFERENCE NO.		GS7# R101819472	
08329	·	45	000/945
		PRICE/PER	EXTENSION
JOB#02 55 555 77 RE	PLACE REAR ENGINE MOUNT(S)		
	ACE BOTH REQAR ENGINE MOUNTS	•	
2 OEN 273302	ENGINE MOUNT \$91.80	BIL 61.20EA*	122.40
	(REF: 597390.00)		. *
2 OEN 288051	ENGINE MOUNT \$22.16	BIL 15.85EA*	31.70
2 OEN 200031	(REF: 597390.00)		
	PARTS SUBTO	TAT.	154.10
	LABOR SUBTO		275.00
•	SHOP SUPPLI		11.00
	** JOB SUBT		440.10
JOB#03 10 000 02 RE	PAIR EXHAUST LEAK AS REQUIRED	LAD NEW	
REMOVED LEAKING	TURBO DOWN PIPE. SEND OUT AND	ACKEUC	
	PLAQCED WITH NEW CLAMPS AND G	ASKEIS .	
CHECK FOR LEAKS	GOOD	.48 19.49EA	19.49
1 WLK 42068	5"X18" GALV FLEX PIPE \$22		351.51
1 MSC ELBOW	FLANGED ELBOW \$492.12 I	311, 331.312.	
	(REF: 597393.00)	77 T	371.00
	PARTS SUBTO		165.00
	LABOR SUBTO		6.60
	SHOP SUPPLIE		542.60
	** JOB SUBTO	JIAU	
	toons paper.		13468.78
	*TOTAL PARTS:		2860.00
	*TOTAL LABOR: *TOTAL OTHER:		2.25
	*TOTAL SHOP SUPPI	TEQ.	.114.40
	***SUB TOTAL:	1125.	16445.43
	***PST/taxable	-PROVINCE: MB	1151.18
	***GST - 1018194		822.27
RE TORQUE WHEELS	AFTER 200KM'S AFTER ANY WHEEL	OF INSTALLATION.	
	SION U-BOLTS AFTER 1,000 KM'S SH SALE - PAID WITH CREI	OT THEITED XXXXXXXXXXX	сx
* * * C A			
	NETTO DEPRESENTATIVE ALITHORIZE THE REPAIR AND SERV	VICE WORK LISTED ABOVE TO BE DONE	ALONG WITH MATERIAL
THE UNDERSIGNED OWNER OR DULY AUTHOR AND HEREBY GRANT YOU AND/OR YOUR EMP	RIZED REPRESENTATIVE, AUTHORIZE THE REPAIR AND SERV OYEES PERMISSION TO OPERATE THE VEHICLE HEREIN D IS UNDERSTOOD THAT FLEET BRAKE PARTS & SERVICE LI OSSESSION, FURTHER, I ACKNOWLEDGE FULL RESPONSIE ES RECOMMENDED CHECKING THE TORQUE IN FASTENER!	RESCRIBED ON STREETS, HIGHWAYS OF THE PROPERTY	OR ELSEWHERE FOR THE WHATEVER FOR DAMAGE
PURPOSE OF TESTING AND/OR INSPECTION. IT TO VEHICLES OR CONTENTS WHILE IN THEIR I	POSSESSION, FURTHER, I ACKNOWLEDGE FULL RESPONSI	SILITY FOR ANY DAMAGE RESULTING I S ON PASSENGER CARS/LIGHT TRUCK	S AND TRAILERS AT 30-50
WEATHER PROTECTION, WHEEL MANUFACTURE KM AND MEDIUM/HEAVY TRUCKS AND TRAILER!	AT 80-160 KM AFTER WHEEL INSTALLATION. THIS VEHICLE	WILL REQUIRE RE-TORQUEING OF U-BOWORK PERFORMED WILL BE FREE OF I	OLTS WITHIN 7 CALENDAP DEFECTS IN MATERIAL OF
DAYS OR 1000 KM IF THE U-BOLTS HAVE BEEN WORKMANSHIP, UNDER NORMAL USE AND SI	ERVICE, FOR A PERIOD OF NINETY (90) DAYS OR FOUR 1	HOUSAND (4000) MILES OR SIXTY-FO	OUR HUNDRED (6400) KM SERVICE, PAYMENT TO B
WHICHEVER OCCURS FIRST, FROM THE DATE OF THE DAYS FOLLOWING DATE OF INVOICE UN	ESS OTHERWISE SHOWN. A SERVICE CHARGE OF 2% PER I	MONTH (24% PER ANNUM) WILL BE CHA	RGED ON OVERDUE JUNT OF SERVICES
ACCOUNTS, AN EXPRESS MECHANIC'S LIEN IS I THERETO.	IS UNDERSTOOD THAT FLEET BRAKE PANTS & SERVICE. 00SSESSION, FURTHER, I ACKNOWLEDGE FULL RESPONSITE 6S RECOMMENDED CHECKING THE TORQUE IN FASTENER! 5 AT 80-180 KM AFTER WHEEL INSTALLATION. THIS VEHICLE REPLACED. FLEET BRAKE FREELY GUARANTEES THAT ALL REVICE, FOR A PERIOD OF NINETY (90) DAYS OR FOUR T F COMPLETION OF SUCH WORK. SEE OUR FULL WARRANTY ESS OTHERWISE SHOWN. A SERVICE CHARGE OF 2% PER I EREBY ACKNOWLEDGED ON THE VEHICLE DESCRIBED ON T	THE AUGUSTA ABABIN THE AND SHIP	_
WORK AUTHORIZED AND			
PAYMENT GUARANTEED BY	SUBTOTAL TAX ST	ATUS/STATE SALES TAX	PLEASE PAY
		1	18418.88

CASH SALE



Truck -Trailer
Parts and Service
www.fleetbrake.com

FLEET BRAKE PARTS & SERVICE

540 OAK POINT HIGHWAY WINNIPEG MB R3C 2E6 204-632-5184

INVOICE DATE	the state of the s
09/15/2020	01:53PM
INVOICE NO.	PAGE
50009739	2
CUSTOMER NO.	BRANCH
00105	* 5*

CASH CUSTOMER

SOLD TO:

BOX 65 GRP 200 RR 2 WINNIPEG MB R3C 2E6 IMRIE DEMOLITION SHIP WARD

TO:

WINNIPEG MB R3C 2E6

CUSTOMER P.O. REFERENCE N	0.		
08329	97		00/945
0032.		PRICE/PER	EXTENSION
2 272 726	3/4X4-1/2 HEX HD CAP SCREW G	4.60EA	9.20
2 PAU 079-726	HD TENSION WASHER 3/4" \$1.00	1.00EA	4.00
4 PAU 101-126	3/4-10 STOVER LOCKNUT \$2.16	2.16EA	4.32
2 PAU 063-526	- in and tenm DIT	4.75EA*	9.50
2 FAR PC1468-5/32			
	(REF: 597402.00)	9.28EA	37.12
4 FUL 12815	BUSHING, BANGO HO \$10.70 BIL		
	(REF: 597416.00)	45.22EA*	45.22
1 OEN 02-13031-00	1 CLUTCH SHAFT \$49.84 BIL	43.222.	
	(REF: 597414.00)	89.55EA*	89.55
1 OEN 02-12467-00	7 CLUTCH SHAFT \$135.44 BIL	69.3321	
	(REF: 597414.00)	1100 00FA*	1100.00
1 EAT 308925-25	15.5X2 EP 2050T \$1859.98 BIL	1100.00EA	220010
	(REF: 597400.00)	13.90EA	13.90
1 FUL 4305294	SHIFT LEVER HOUSHING \$16.04		71.29
1 EAT 105C137	YOKE, CLUTCH RELEASE \$82.26		35.00
1 FUL 4308226	RT-SERIES CL/HSG \$40.38 BIL	33.00EA	33.00
	(REF: 597437.00)	120 0053*	120.00
1 MSC MACHINE		120.00EA*	120.00
	(REF: 597411.00)	0000 2553*	9999.25
1 FRO 16210CP	10SPD TRANNS \$12694.52 BIL	9999.25EA	3333.23
	(REF: 597383.00)	0.45 5.453	947.54
1 ETN PT2000XCN0	11RA BOTTOM MOUNT EIGHT \$1093.30	947.54EA	. 26.67
1 ETN PTM2	8 BOLT METRIC MOUNTIN \$30.76	20.0711	231.15
15 BWL 122207-1	50W SYN TRANS MOBIL P \$17.78	15.41EA	2.25
	EHC		
1 ETN PTPBK1000	DUMP PUMP SUPP. BRKT \$127.97	110.91EA	110.91
1 2111 1111111	MISC SUBTOTAL		
	PARTS SUBTOTAL		12943.68
	LABOR SUBTOTAL		2420.00
	SHOP SUPPLIES	•	96.80
	** JOB SUBTOTAL		15462.73

I. THE UNDERSIGNED OWNER OR DULY AUTHORIZED REPRESENTATIVE, AUTHORIZE THE REPAIR AND SERVICE WORK LISTED ABOVE TO BE DONE, ALONG WITH MATERIAL, AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. IT IS UNDERSTOOD THAT FLEET BRAKE PARTS & SERVICE LTD. DOES NOT ASSUME ANY LIABILITY WHATEVER FOR DAMAGE PULL RESPONSIBILITY FOR ANY DAMAGE RESULTING FROM INADEQUATE COLD TO VEHICLES OR CONTENTS WHILE IN THEIR POSSESSION, FURTHER, I ACKNOWLEDGE FULL RESPONSIBILITY FOR ANY DAMAGE RESULTING FROM INADEQUATE COLD TO VEHICLES OR CONTENTS WHILE IN THEIR POSSESSION, FURTHER, I ACKNOWLEDGE FULL RESPONSIBILITY FOR ANY DAMAGE RESULTING FROM INADEQUATE COLD WEATHER PROTECTION. WHEEL MANUFACTURES RECOMMENDED CHECKING THE TORQUE IN FASTENERS ON PASSENGER CARS/LIGHT TRUCKS AND TRAILERS AT 30-160 KM AFTER WHEEL INSTALLATION. THIS VEHICLE WILL REQUIRE RE-TORQUEING OF U-BOLTS WITHIN 7 CALENDAR KM AND MEDIUM/HEAVY TRUCKS AND TRAILERS AT 80-160 KM AFTER WHEEL INSTALLATION. THIS VEHICLE WILL REGUIRE RE-TORQUEING OF U-BOLTS WITHIN 7 CALENDAR KM AND MEDIUM/HEAVY TRUCKS AND TRAILERS AT 80-160 KM AFTER WHEEL INSTALLATION. THIS VEHICLE WILL REGUIRE RE-TORQUEING OF U-BOLTS WITHIN 7 CALENDAR KM AND MEDIUM/HEAVY TRUCKS AND TRAILERS AT 80-160 KM AFTER WHEEL INSTALLATION. THIS VEHICLE WILL REGUIRE RE-TORQUEING OF U-BOLTS WITHIN 7 CALENDAR KM AND MEDIUM/HEAVY TRUCKS AND TRAILERS AT 80-160 KM AFTER WHEEL INSTALLATION. THIS VEHICLE WILL BE FREE OF DEFECTS IN MATERIAL OR DAYS OR 1000 KM IF THE U-BOLTS WHEEL THE PROTECTION OF SURTY FOUR HUNDRED (6400) KM AFTER WHEEL WARRANTY POLICY AT WWW.FLEETBRAKE.COM/SERVICE. PAYMENT TO BE WHICHEVER OCCURS FIRST, FROM THE DATE OF COMPLETION OF SUCH WORK, SEE OUR FULL WARRANTY POLICY AT WWW.FLEETBRAKE.COM/SERVICE. PAYMENT TO BE WHICHEVER OCCURS FIRST, FROM THE DATE OF COMPLETION OF SUCH WORK, SEE OUR FULL WARRANTY POLICY AT WWW.FLEETBRAKE.COM/SERVICE. PAYMENT TO BE WHICHEVER OF SUCH WORK PERFORMENT

SUBTOTAL

WORK AUTHORIZED AND PAYMENT GUARANTEED BY

TAX STATUS/STATE

SALES TAX PLEASE PAY

CONTINUED

PLEASE REMIT TO: C/O C25032 PO Box 2532 Station M CALGARY, AB TERMS

FLEET BRAKE PARTS & SERVICE

FLEET BRAKE BR5 540 OAK POINT HIGHWAY WINNIPES, MB. R3C 2E6 204-632-5184

540 OAK POINT HIGHWAY WINNIPEG MB R3C 2E6 204-632-5184

NVOICE DATE 09/15/2020 01:53PM PAGE 50009739 1 CUSTOMER NO. BRANCH 00105 5*

SALE

JSTOMER

IMRIE DEMOLITION

SHIP WARD

TO:

Batch #: 594

13:58:39

REF#: 00000015

GRP 200 RR 2 EG MB R3C 2E6

WINNIPEG MB R3C 2E6

09/15/20 APPR CODE: 015891

Trace: 15 VISA

Manual CP

083297

REFERENCE NO.

PRICE/PER

GST# R101819472

000/945

45

AMOUNT

**********0328

\$18,418.88

* * * C A S H ME

CONTACT INFO

MISCELLANEOUS

APPROVED THANK YOU / MERCI

RS PICKUP ETION DATE: 09/15/2020

SALE * * *

YEAR: 2005 MAKE/MODEL: FREIGHTLINER

FUJA6DE45LN42307

KILOMETERS: 218018

CUSTOMER COPY

INSP#:

JOB#01 90 002 00 RE & RE CLUTCH ASSY.

REPLACE CLUTCH ASSEMBLY .

307

BRING UNIT IN TO INSPECT. OIL EVERY WHERE . INSPECT AND FOUND A LARGE HOLE IN THE SIDE OF THE TRANSMISSION . ALMOST NO OIL IN TRANSMSSION . REMOVED DRIVE SHAFT AND DISCONNECT ALL LINES AND ELECTRICAL . REMOVED SHIFTER TOWER AND ALL BOLTS TO PULL TRANMSSION . REMOVED TRANSMSION CLUTCH AND FLY WHEEL . SEND FLYWHEEL OUT TO BE MACHINED . INSPECTED REAR MAIN SEAL AND NO LEAKS AT ALL REMOVED AND REPLACEDX CROSS SHAFT BUSHINGS . NEW BEARING RELEASE FORK . INSTALLED MACHINE FLYWHEEL AND NEW CLUTCH . INSTALLD TRANSMSSION . HOOKED UP ALL LINES AND WIING REMOVED . REPLACED SHIFT TOWER GASKET AND INSTALLED SHIFT TOWER . PTO HAD BEEN RUN DRY . REMOVED AND REPLACED PTO NEW GASKET AND MOUNTING STUDS SET TP PROPER BACK LASH . MADE UP NEW MOUNT FOR HYDRAULIC PUMP

. REINSTALLED DRIVE SHAFT AND GREASED . ADJUST CLUTCH

LINKAGE AND SET UP FREE PLAY

1	WLK 35806	V CLAMP	\$37.73	32.70EA	32.70
2	WLK 33970	5" STPD PREFORMED SEA	\$15.85	13.74EA	27.48
2	FAR 54-8D	45ELB, 1/2 FLx 1/2 MPT	\$5.77	5.46EA	10.92
4	PAU 079-583	1/2X1-1/2 HEX HD CAP S	\$1.66	1.66EA	6.64
8	PAU 101-122	HD TENSION WASHER 1/2"		1.08EA	8.64
_	PAU 063-522	1/2-13 STOVER LOCKNUT	\$0.68	0.67EA	2.68
_					

I. THE UNDERSIGNED OWNER OR DULY AUTHORIZED REPRESENTATIVE, AUTHORIZE THE REPAIR AND SERVICE WORK LISTED ABOVE TO BE DONE, ALONG WITH MATERIAL AND HEREBY GRANT YOU AND/OR YOUR EMPLOYEES PERMISSION TO OPERATE THE VEHICLE HEREIN DESCRIBED ON STREETS, HIGHWAYS OR ELSEWHERE FOR THE PURPOSE OF TESTING AND/OR INSPECTION. IT IS UNDERSTOOD THAT FLEET BRAKE PARTS & SERVICE LTD. DOES NOT ASSUME ANY LIABILITY WHATEVER FOR DAMAGE TO VEHICLES OR CONTENTS WHILE IN THEIR POSSESSION, FURTHER, I ACKNOWLEDGE FULL RESPONSIBILITY FOR ANY DAMAGE RESULTING FROM INADEQUATE COLD WEATHER PROTECTION. WHEEL MANUFACTURES RECOMMENDED CHECKING THE TORQUE IN FASTENERS ON PASSENGER CARS/LIGHT TRUCKS AND TRAILERS AT 30-50 KM AND MEDIUMHEAVY TRUCKS AND TRAILERS AT 80-180 KM AFTER WHEEL INSTALLATION. THIS VEHICLE WILL REQUIRE RE-TORQUEING OF U-BOLTS WITHIN 7 CALENDAY DAYS OR 1000 KM IF THE U-BOLTS HAVE BEEN REPLACED. FLEET BRAKE FREELY GUARANTEES THAT ALL WORK PERFORMED WILL BE FREE OF DEFECTS IN MATERIAL OR WORKMANSHIP, UNDER NORMAL USE AND SERVICE, FOR A PERIOD OF NINETY (90) DAYS OR FOUR THOUSAND (4000) MILES OR SIXTY-FOUR HUNDRED (8400) KM, WHICHEVER OCCURS FIRST, FROM THE DATE OF COMPLETION OF SUCH WORK, SEE OUR PULL WARRANTY POLICY AT WWY.FLEETBRAKE.COM/SERVICE, PAYMENT TO BE NET 30 DAYS FOLLOWING DATE OF INVOICE UNLESS OTHERWISE SHOWN. A SERVICE CHARGE OF 2% PER MONTH (24% PER ANNUM) WILL BE CHARGED ON OVERDUE ACCOUNTS. AN EXPRESS MECHANIC'S LIEN IS HEREBY ACKNOWLEDGED ON THE VEHICLE DESCRIBED ON THIS ORDER TO SECURE THE FULL AMOUNT OF SERVICES THERED.

WORK AUTHORIZED AND PAYMENT GUARANTEED BY

SUBTOTA

TAX STATUS/STATE

SALES TAX

PLEASE PAY *CONTINUED*