

Vehicle History

Search terms:

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-1046	Other	28/03/2025						Regan Bale	\$0.00
R-1047	Other	02/04/2025						Regan Bale	\$0.00
R-1050	Other	06/04/2025	01/05/2025	314,676	0	0		Regan Bale Replaced yellow button	\$50.00 R-1050
S-572	A - 15k	13/02/2025	13/02/2025	306,758 25,132		0		Regan Bale A service completed - replaced brake light switch due to leaking air	\$100.00 S-572
R-1012	Camera	05/02/2025	06/02/2025	0	0	0		Regan Bale Replaced camera 3, adjust camera turn off time to 30 minutes	\$50.00 R-1012
R-952	Other	08/10/2024	15/11/2024	0	0	0		Regan Bale Replaced drivers window regulator and spray felt track (order door latch)	\$50.00 R-952

Engine Rebuilt @ 771,385 kms

New head @ 270,742 km's

543,291 kms on Rebuild

44,000 kms approx on New head & Blow by test

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-930	coolant	01/08/2024	28/08/2024	0	0	0		Cummins South Pacific Pty Ltd Travel to customer site - connected laptop and take ecm download. Test drove truck and carried out blowby test, carried out checks to see if truck was pressurising to track coolant usage - all ok. Checked oil cap and under rocker cover for milky oil but everything clean.Carried on with confirming the suspected oil cooler leaking, only light oil on top of coolant, drained coolant to inspect condition. Coolant all clean only very light oil film from draining final couple of litres. Customer opted to monitor issues. Carried out engine restorer flush and test drive truck with cardboard in front of radiator. Return to yard and drain restore and flush system with fresh water. Gave customer instructions to refill system with water after final flush and run for few days to monitor oil ingress. Carried out blow test on k200	\$2,175.15 1354178
R-908	Other	08/08/2024	08/08/2024	287,897	0	0		Regan Bale Replaced heater core due to leaking	\$50.00 R-908
S-518	C - 100k	02/04/2024	02/04/2024	281,626 281,626	0	0		Regan Bale C service completed - replaced air cleaner element Changed diff and gear box	\$100.00 S-518
R-796	Annual Roadworthy Inspection	02/04/2024	02/04/2024	281,626	0	0		Regan Bale Annual roadworthy inspection completed - replaced LH rear airbag	\$50.00 R-796

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-767	Engine	30/01/2024	30/01/2024	270,742	0	0		Cummins South Pacific Pty Ltd Disassemble & strip engine apart to remove cylinder head. Clean up engine block deck surface. Strip parts off cylinder head and transfer onto new head and fit new cylinder head with new head gasket Fit valve cam and front cam plates with new O-rings Fit injector cam, fit front cam gears and set base timing. Refit front timing cover with new seal Refit rocker and injector shaft assemblies Perform engine overhead set, fit rocker cover with new gasket Engine brake kit	\$28,000.01 1126617
R-749	belt, coolant, Other, Turbo	05/12/2023	05/12/2023	270,773	0	0		Regan Bale Replaced belts, flushed coolant system, and replaced coolant. Replaced pyro sender and v band clamp off back turbo and exhaust flex clamps.	\$50.00 1917
S-480	A - 15k	21/08/2023	29/08/2023	260,919 15,334	0	0		Regan Bale A Service Completed	\$100.00 S-480
S-451	B - 30k	26/04/2023	03/05/2023	245,585 32,072	0	0		Regan Bale B Service Completed Fix fuel primer for fuel fitter	\$150.00 S-451
R-636	Other	13/04/2023	13/04/2023	424,000	0	0		Regan Bale Flushed coolant & replaced	\$50.00 1477
S-430	A - 15k	09/03/2023	09/03/2023	236,285 22,772	0	0		Regan Bale A Service Completed	\$100.00 S-430
R-561	Annual Roadworthy Inspection	14/12/2022	14/12/2022	223,518	0	0		Regan Bale Annual Roadworthy Inspection complete Replaced rear cab mounts & front cab shocks	\$50.00 0102
R-558	Cab	09/12/2022	09/12/2022	223,255	0	0		Regan Bale Replaced rear cab mounts	\$100.00 1458

Vehicle History

Search terms:

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-1155	Airbag	28/07/2025	28/07/2025	314,720	0	0		Regan Bale Replaced all air bags, all sway bar bushes and all torque rod bushes	\$50.00 435
R-1154	Shockers	28/07/2025	28/07/2025	314,720	0	0		Regan Bale Remove and replaced all drive shockers	\$50.00 439
R-1153	gearbox, Other	28/07/2025	28/07/2025	314,720	0	0		Regan Bale Removed top gearbox cover & inspect gears for wear. Refit cover remove bell housing, fit new input shaft and bearing	\$50.00 438
R-1152	Diff	28/07/2025	28/07/2025	314,720	0	0		Regan Bale Remove diff due to noise, replaced rear diff	\$50.00 436
R-1046	Other	28/03/2025	28/07/2025	314,720	0	0		Regan Bale Replaced RH window reg and track slide. Replaced front diff temp sensor, fixed various air leaks. Locker box door handle drivers side fixed. Fixed gauges	\$50.00 R-1046
R-1047	Other	02/04/2025	13/05/2025	314,170	0	0		Regan Bale Adjusted clutch and replaced yellow button due to leaking air	\$50.00 R-1047
R-1050	Other	06/04/2025	01/05/2025	314,676	0	0		Regan Bale Replaced yellow button	\$50.00 R-1050
S-572	A - 15k	13/02/2025	13/02/2025	306,758 25,132		0		Regan Bale A service completed - replaced brake light switch due to leaking air	\$100.00 S-572
R-1012	Camera	05/02/2025	06/02/2025	0	0	0		Regan Bale Replaced camera 3, adjust camera turn off time to 30 minutes	\$50.00 R-1012

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-952	Other	08/10/2024	15/11/2024	0	0	0		Regan Bale Replaced drivers window regulator and spray felt track (order door latch)	\$50.00 R-952
R-930	coolant	01/08/2024	28/08/2024	0	0	0		Cummins South Pacific Pty Ltd Travel to customer site - connected laptop and take ecm download. Test drove truck and carried out blowby test, carried out checks to see if truck was pressurising to track coolant usage - all ok. Checked oil cap and under rocker cover for milky oil but everything clean.Carried on with confirming the suspected oil cooler leaking, only light oil on top of coolant, drained coolant to inspect condition. Coolant all clean only very light oil film from draining final couple of litres. Customer opted to monitor issues. Carried out engine restorer flush and test drive truck with cardboard in front of radiator. Return to yard and drain restore and flush system with fresh water. Gave customer instructions to refill system with water after final flush and run for few days to monitor oil ingress. Carried out blow test on k200	\$2,175.15 1354178
R-908	Other	08/08/2024	08/08/2024	287,897	0	0		Regan Bale Replaced heater core due to leaking	\$50.00 R-908
S-518	C - 100k	02/04/2024	02/04/2024	281,626 281,626	0	0		Regan Bale C service completed - replaced air cleaner element Changed diff and gear box	\$100.00 S-518
R-796	Annual Roadworthy Inspection	02/04/2024	02/04/2024	281,626	0	0		Regan Bale Annual roadworthy inspection completed - replaced LH rear airbag	\$50.00 R-796

Number	Type	Date Open	Date	Kilometres	Hours	Fuel	Fault	Repairer / Notes	Cost / Invoice
			Closed			Usage			
R-767	Engine	30/01/2024	30/01/2024	270,742	0	0		Cummins South Pacific Pty Ltd Disassemble & strip engine apart to remove cylinder head. Clean up engine block deck surface. Strip parts off cylinder head and transfer onto new head and fit new cylinder head with new head gasket Fit valve cam and front cam plates with new O-rings Fit injector cam, fit front cam gears and set base timing. Refit front timing cover with new seal Refit rocker and injector shaft assemblies Perform engine overhead set, fit rocker cover with new gasket Engine brake kit	\$28,000.01 1126617
R-749	belt, coolant, Other, Turbo	05/12/2023	05/12/2023	270,773	0	0		Regan Bale Replaced belts, flushed coolant system, and replaced coolant. Replaced pyro sender and v band clamp off back turbo and exhaust flex clamps.	\$50.00 1917
S-480	A - 15k	21/08/2023	29/08/2023	260,919 15,334	0	0		Regan Bale A Service Completed	\$100.00 S-480
S-451	B - 30k	26/04/2023	03/05/2023	245,585 32,072	0	0		Regan Bale B Service Completed Fix fuel primer for fuel fitter	\$150.00 S-451
R-636	Other	13/04/2023	13/04/2023	424,000	0	0		Regan Bale Flushed coolant & replaced	\$50.00 1477
S-430	A - 15k	09/03/2023	09/03/2023	236,285 22,772	0	0		Regan Bale A Service Completed	\$100.00 S-430

Generated at: 29/07/2025, 13:32:11

Vehicle History

Search terms:

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-561	Annual Roadworthy Inspection	14/12/2022	14/12/2022	223,518	0	0		Regan Bale Annual Roadworthy Inspection complete Replaced rear cab mounts & front cab shocks	\$50.00 0102
R-558	Cab	09/12/2022	09/12/2022	223,255	0	0		Regan Bale Replaced rear cab mounts	\$100.00 1458
S-388	B - 30k	07/11/2022	07/11/2022	213,513 25,444	0	0		Regan Bale Completed B Service	\$100.00 S-388
R-534	Clutch, Engine, Other	28/10/2022	28/10/2022	212,355	0	0		Regan Bale Replace cluth, engine mounts & bolts Reseal rear cover & sump, Fly wheel machined Replace input shaft bearing Replace clutch fork bushes & clutch fork shaft	\$100.00 1448
R-499	Other	26/09/2022	26/09/2022	201,020	0	0		Regan Bale Replaced Front Cab/Shocks/Springs	\$100.00 1436
S-372	A - 15k	19/09/2022	19/09/2022	199,972 11,903	0	0		Regan Bale A Service Completed	\$100.00 S-372
S-357	B - 30k	28/07/2022	29/07/2022	188,069 29,215	0	0		TruckFix Pty Ltd B SERVICE - B SERVICE Change engine oil, change oil and fuel filters, check diff and gearbox oils, check steering components, check front and rear suspension, check air cleaner, check batteries and terminals, check front hub oil level, check and adjust brakes, grease vehicle, check belts and engine mounts.	\$308.00 2567

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-433	Other	15/06/2022	15/06/2022	174,855	0	0		Regan Bale Replaced Turntable jaws, jake brake switch, left bottom steer shocker rubbers & front left shocker drive. Tightened Cross member behind gearbox.	\$300.00 1408
R-401	Annual Roadworthy Inspection	17/05/2022	17/05/2022	169,174	0	0		Cobram Truck Repairs Truck Annual Roadworthy Complete NOTES: L/H/F Dve Shocker Leaking L/R Winder Operation L/H/R Brake booster leaking	\$77.00 00029433
T-127	Balance	10/05/2022	09/05/2022	0	0	0		Bridgestone Service Centre 295/80R22.5 152/148M BS R154 .WHEEL BALANCE SCT POS 1. COMPLETED ONSITE AT ROYANS. DEL DKT 206477.	\$729.00 471037
S-282	B - 30k	30/12/2021	05/01/2022	158,854 69,937	0	0		TruckFix Pty Ltd B SERVICE - B SERVICE Change engine oil, change oil and fuel filters, check diff and gearbox oils, check steering components, check front and rear suspension, check air cleaner, check batteries and terminals, check front hub oil level, check and adjust brakes, grease vehicle, check belts and engine mounts. Labour - Standard Labour The customer reported a clicking noise when depressing the clutch pedal, inspected the clutch linkage and found the pivot bearing at the front of the engine had movement, removed the linkage rods from the pivot and removed the pivot from the chassis, removed and replaced the bearing, refitted the pivot found the linkage rod rose joints worn, removed and replaced the rose joints, refitted the linkages and checked the clutch operation and adjustment, all ok.	\$385.00 2378

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-349	Other	12/12/2021	23/12/2021	154,615	0	0		TruckFix Pty Ltd Labour - Standard Labour The customer reported a fuel leak on the LHS side of the engine, inspected the leak and found the fuel return hose from the engine to the fuel cooler on the front of the radiator leaking, while the front bumper bar was removed for polishing removed all the required rubberized clamps and removed the hose, made a new hose and fitted, refitted and replaced any worn clamps, started the engine and checked the operation, all ok. During the services haven't been able to grease the front cab mounts because of the stainless panel that had been fitted, while the front bumper was removed obtained extendable grease hoses and fittings, fitted the grease hoses to the mounts and greased the mounts.	\$269.50 2322
R-338	Other	17/12/2021	17/12/2021	0	0	0		Cobram Panel Works Repaired Sunvisor and seal as necessary	\$480.50 12985

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-342	Other	03/12/2021	09/12/2021	152,002	0	0		TruckFix Pty Ltd Labour - Standard Labour The customer reported the vehicle has flat batteries and the volt gauge only showing 11 volts when it was running, jump started the vehicle and tested the alternator, found the alternator had failed, disconnected the batteries and removed the wiring from the alternator, removed the alternator belt and the alternator, swapped the belt pulley to the new alternator and fitted the alternator and refitted the belt, fitted the wiring, during the removal of the battery terminals found the LHS set of batteries had the top of the plastic battery case broken and causing the battery terminals to be corroded, removed and replaced the batteries, reconnected all the terminals, started the engine and checked the operation of the alternator, all ok. Checked the adjusted the clutch as required.	\$192.50 2296
S-255	A - 15k	04/11/2021	16/11/2021	142,788 13,812	0	0		TruckFix Pty Ltd A SERVICE - A - SERVICE Carried out grease and adjust the brakes, check and top up oil and water as required, check all lights and check over vehicle.	\$115.50 2266
R-324	Other	29/09/2021	29/09/2021	131,452	0	0		TruckFix Pty Ltd Checked the operation of the airbag height control valves and found them slow to respond, removed the airlines from the valves and removed the valves, swapped the air fittings to the new valves and fitted the new valves to the vehicle, fitted the air lines and adjusted the ride height to suit, checked the operation and for leaks, all ok.	\$154.00 2224

GEARBOX									
Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
S-229	A - 15k	17/09/2021	21/09/2021	128,976 40,059	0	0		TruckFix Pty Ltd A SERVICE - A - SERVICE Carried out grease and adjust the brakes, check and top up oil and water as required, check all lights and check over vehicle. Labour - Standard Labour During the service found the RHS exhaust bell flex leaking, removed the exhaust step bandage and found the flex had broken, removed the bell from the flex and cut off the broken piece of flex, refitted the bell and the bandage, checked the operation, all ok.	\$192.50 2192
S-196	B - 30k	19/08/2021	24/07/2021	88,917 88,917	0	0		TruckFix Pty Ltd INVOICE NOTES: B SERVICE - B SERVICE Change engine oil, change oil and fuel filters, check diff and gearbox oils, check steering components, check front and rear suspension, check air cleaner, check batteries and terminals, check the front hub oil level, check and adjust brakes, grease vehicle, check belts and engine mounts. Labour - Standard Labour Removed the old worn teflon pads from the turntable top, cleaned the top and fitted the new pads.	\$385.00 2084
R-241	Annual Roadworthy Inspection	15/03/2021	19/03/2021	88,914	0	0		Cobram Truck Repairs R/H Steer Wheel Seal/ L/H Air Tank Drain (cable broken) Fuel Hoses leaking besides motor/ clutch pedal missing L/H rear brake booster leaking	\$150.00 0151
R-142	Annual Roadworthy Inspection	15/03/2021	18/03/2021	88,914	0	0		Cobram Truck Repairs RWC Inspection	\$77.00 00027993

Generated at: 29/07/2025, 13:32:24

Vehicle History

Search terms:

Number	Type	Date Open	Date Closed	Kilometres Closed	Hours Closed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-133	Other	01/03/2021	05/03/2021	0	0	0		COBRAM PANEL WORKS LH Screen - supply & fit RH Screen - IF REQ	\$638.00 12122
T-1	New	29/01/2021	29/01/2021	75,907		0		Tate Maher FITTED x2 NEW BRIDGESTONE TYRES	\$50.00 579
S-8	B - 30k	09/10/2020	09/10/2020	0		0		TruckFix Pty Ltd REPLACED RADIATOR CAP	\$308.00 1816/ 0033
R-1	Radiator	02/10/2020	02/10/2020			0		FRANK MACHEDA REPLACED RADIATOR CAP WITH SECOND HAND ONE	\$100.00 619
R-2	Other	23/07/2020	23/07/2020	28,421		0		TruckFix Pty Ltd REMOVED AND REPLACED SLACK ADJUSTER, REOMED THE LEAKING LHS EXHAUST FLEX AND REPLACED, CLEANED BRAKE SHOE COMPONENTS, CLEANED WHEEL BEARINGS, ADDED NEW SEAL TO THE HUB	\$539.00 1751
R-3	Weight Calibration	20/05/2020	20/05/2020			0		Frank Macheda CARY OUT WEIGHT CALIBRATION	\$25.00
R-4	Annual Roadworthy Inspection	08/05/2020	08/05/2020	36,782		0		TruckFix Pty Ltd ANNUAL ROADWORTHY COMPLETED - REPLACED STEER BRAKES & DRUMS, REPLACED FRONT SLACK ADJUSTER, AND ROOF LIGHT	\$350.00 0049

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
S-7	B - 30k	18/02/2020	18/02/2020	0		0		TruckFix Pty Ltd ADJUSTED RH SLACKADJUSTER, REPLACED FUEL FILTERS	\$308.00 0012
T-2	New	20/10/2019	20/10/2019	65,000		0		Nicholas Macheda 2 X NEW BRIDGESTONE STEER - ROTATE DRIVE TYRES	\$50.00 540
R-5	Suspension	31/05/2019	31/05/2019	974,157		0		TruckFix Pty Ltd REMOVED AND REPLACED AIRBAG	\$77.00 1388
T-3	New	23/04/2019	23/04/2019	976,565		0		Tate Maher NEW DRIVE TYRES	\$100.00 526
R-6	Other	20/08/2018	20/08/2018	941,207		0		TruckFix Pty Ltd REPLACED RHS STEER AND ADJUSTED BRAKES	\$100.00 0001
S-6	B - 30k	29/07/2018	29/07/2018	0		0		TruckFix Pty Ltd FULL SERVICE (B)	\$308.00 1109
R-7	Engine	04/05/2018	04/05/2018	919,349		0		TruckFix Pty Ltd FITTED NEW CAMS, FITTED THE ROCKER GEAR WITH NEW INJECTOR ROCKERS - REFITTED ROCKER COVER	\$1,848.00 1848
R-8	Wheel Alignment - Prime Mover	08/03/2018	08/03/2018	906,000		0		ONSITE TRUCK & TRAILER WHEEL ALIGNMENT CARRIED OUT WHEEL ALIGNMENT / STRAIGHTENED STEERING WHEEL	\$545.00 5483
T-4	New	24/02/2018	24/02/2018	902,783		0		Frank Macheda FIT 2 NEW TOYO STEER TYRES	\$60.00 384
S-5	B - 30k	07/02/2018	07/02/2018	0		0		TruckFix Pty Ltd FULL SERVICE (B)	\$462.00 980

GEARBOX									
Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
R-9	Other	21/12/2017	21/12/2017	880,714		0		TruckFix Pty Ltd REPLACED HOSE FROM COMPRESSOR NEAR GEARBOX.	\$154.00 920
S-4	B - 30k	17/11/2017	17/11/2017	0		0		TruckFix Pty Ltd FULL SERVICE (B)	\$616.00 921
T-5	New	13/08/2017	13/08/2017	830		0		Nicsam Maintenance FIT TWO NEW TOYO STEER TYRES ON TRUCK	\$60.00 369

Generated at: 29/07/2025, 13:32:35

Vehicle History

Search terms:

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
T-6	New	25/06/2017	25/06/2017	816		0		Frank Macheda FIT 8 NEW STEELMARK DRIVE TYRES	\$180.00 365
R-10	Other	06/04/2017	06/04/2017	785		0		TruckFix Pty Ltd FITTED NEW GUARDS. REPLACED AIR HORN SWITCH. ADJUSTED DRIVE AIRBAGS AS REQUIRED. FIXE AIR LEAK IN AIR LINE.	\$616.00 727
T-7	New	11/02/2017	11/02/2017	771		0		Frank Macheda FIT TWO NEW REMINGTON STEER TYRES	\$120.00 411
S-3	B - 30k	27/12/2016	27/12/2016	0		0		TruckFix Pty Ltd FULL SERVICE (B)	\$308.00 632
R-11	Engine	10/10/2016	10/10/2016	771		0		TruckFix Pty Ltd RADIATOR REPAIRED. PULLED DOWN AND CHECKED ENGINE. ENGINE REBUILT	\$5,775.00 562
R-12	Lights	24/07/2016	24/07/2016			0		TruckFix Pty Ltd FITTED NEW LED HEAD LIGHTS	\$44.00 514
R-13	Battery	29/05/2016	29/05/2016			0		Frank Macheda REPLACE BOTH BATTERIES R/H/S P839-P806. BATTERIES SUPPLIED BY COBRAM MOBILE ELECTRICAL.	\$60.00 348
S-2	B - 30k	15/05/2016	15/05/2016	0		0		TruckFix Pty Ltd FULL SERVICE (B)	\$308.00 465
T-8	New	01/05/2016	01/05/2016	686		0		Frank Macheda 2 NEW STEER TYRES (GOODYEAR S100)	\$60.00 345

GEARBOX

Number	Type	Date Open	Date Closed	Kilometres Closed	HoursClosed	Fuel Usage Closed	Fault	Repairer / Notes	Cost / Invoice
T-9	Rotate	14/03/2016	14/03/2016	600		0		Frank Macheda ROTATE STEER TYRES	\$60.00 338
S-1	B - 30k	25/02/2016	25/02/2016	0		0		TruckFix Pty Ltd FULL SERVICE (B)	\$308.00 389
R-14	Lights	06/02/2016	06/02/2016			0		Frank Macheda CHANGED STANDARD HEADLIGHT GLOBES TO EXTREME VISION 130%	\$30.00 330
T-10	New	09/08/2015	09/08/2015	582		0		Frank Macheda FIT TWO NEW MAXES STEER TYRES.	\$120.00 318
T-11	New	12/07/2015	12/07/2015	574		0		Frank Macheda FIT 8 NEW GOODYEAR DRIVE TYRES.	\$120.00 316
T-12	New	02/11/2013	02/11/2013	322,948		0		Frank Macheda FIT 8 NEW DRIVE TYRES GOODYEAR G667	\$120.00 86

Generated at: 29/07/2025, 13:32:44

Vehicle Maintenance Record - KENWORTH K104B



Id: 061
Model: KENWORTH K104B
Vehicle Id: 1
Registration #: ZYY 624
Expiry Date: 9/06/2018
E-Tag: 131421775944
Notes: MASS MANAGEMENT: A039774

Year: 7/09/2007
Vin #: 6F0000007A435325
Engine Type: CUMMINS GEN2
Engine #: 79256224
Suspension: AIRGLIDE 200
Rear Axle:
Fwd Axle:
Gearbox:

Purchase Date: 12/09/2013
Purchased From: KENWORTH LAVERTON

MAINTENANCE HISTORY

Date	KM's	Maintenance Type	Problem	Repairer	Reference	Cost
29/01/2021	75907	Tyre Change		Tate Maher	579	50.00

Work Done: Fitted x2 new bridgetone tyres

Total Maintenance cost: \$46,053.00

0400 881 279

\$56,000 incl
15

\$54,000

Vehicle Maintenance Record - KENWORTH K104B



Id: 061
Model: KENWORTH K104B
Vehicle Id: 1
Registration #: ZYY 624
Expiry Date: 9/06/2018
E-Tag: 131421775944
Notes: MASS MANAGEMENT: A039774

Year: 7/09/2007
Vin #: 6F0000007A435325
Engine Type: CUMMINS GEN2
Engine #: 79256224
Suspension: AIRGLIDE 200
Rear Axle:
Fwd Axle:
Gearbox:

Purchase Date: 12/09/2013
Purchased From: KENWORTH LAVERTON

MAINTENANCE HISTORY

Date	KM's	Maintenance Type	Problem	Repairer	Reference	Cost
31/05/2019	974157	Other		TruckFix Pty Ltd	1388	77.00
Work Done: REMOVED AND REPLACED AIRBAG						
20/10/2019		Tyre Change		NICHOLAS MACHEDA	540	
Work Done: 2 X NEW BRIDGESTONE STEER - ROTATE DRIVE TYRES						
18/02/2020	21533	Truck B Service (Full service)		TruckFix Pty Ltd	0012	
Work Done: ADJUSTED RH SLACKADJUSTER, REPLACED FUEL FILTERS						
8/05/2020	36782	Other		TruckFix Pty Ltd	0049	
Work Done: ANNUAL ROADWORTHY COMPLETED - REPLACED STEER BRAKES & DRUMS, REPLACED FRONT SLACK ADJUSTER, AND ROOF LIGHT						
20/05/2020		WEIGHT CALIBRATION				
Work Done:						
23/07/2020	28421	Other		TruckFix Pty Ltd	1751	539.00
Work Done: REMOVED AND REPLACED SLACK ADJUSTER, REOMED THE LEAKING LHS EXHAUST FLEX AND REPLACED, CLEANED BRAKE SHOE COMPONENTS,						
2/10/2020		Other		FRANK MACHEDA	619	
Work Done: REPLACED RADIATOR CAP WITH SECOND HAND ONE						
9/10/2020	59075	Truck B Service (Full service)		TruckFix Pty Ltd	1816/	308.00
Work Done: REPLACED RADIATOR CAP						

Vehicle Maintenance Record - KENWORTH K104B



Id: 061
 Model: KENWORTH K104B
 Vehicle Id: 1
 Registration #: ZYY 624
 Expiry Date: 9/06/2018
 E-Tag: 131421775944
 Notes: MASS MANAGEMENT: A039774

Year: 7/09/2007
 Vin #: 6F0000007A435325
 Engine Type: CUMMINS GEN2
 Engine #: 79256224
 Suspension: AIRGLIDE 200
 Rear Axle:
 Fwd Axle:
 Gearbox:

Purchase Date: 12/09/2013
 Purchased From: KENWORTH LAVERTON

MAINTENANCE HISTORY

Date	KM's	Maintenance Type	Problem	Repairer	Reference	Cost
7/02/2018	894711	Truck B Service (Full service)		TruckFix Pty Ltd	980	462.00
Work Done:						
24/02/2018	902783	Tyre Change		Frank Macheda	384	60.00
Work Done: FIT 2 NEW TOYO STEER TYRES						
7/03/2018		WEIGHT CALIBRATION				
Work Done:						
8/03/2018	906000	Other		ONSITE TRUCK & TRAILER	5483	545.00
Work Done: CARRIED OUT WHEEL ALIGNMENT / STRAIGHTENED STEERING WHEEL						
4/05/2018	919349	Engine		TruckFix Pty Ltd	1848	1848.00
Work Done: FITTED NEW CAMS, FITTED THE ROCKER GEAR WITH NEW INJECTOR ROCKERS - REFITTED ROCKER COVER						
29/07/2018	933704	Truck B Service (Full service)		TruckFix Pty Ltd	1109	308.00
Work Done:						
20/08/2018	941207	Brakes		TruckFix Pty Ltd	0001	
Work Done: REPLACED RHS STEER AND ADJUSTED BRAKES						
23/04/2019	976565	Tyre Change		TATE MAHER	526	
Work Done: NEW DRIVE TYRES						

Vehicle Maintenance Record - KENWORTH K104B



Id: 061
 Model: KENWORTH K104B
 Vehicle Id: 1
 Registration #: ZYY 624
 Expiry Date: 9/06/2018
 E-Tag: 131421775944
 Notes: MASS MANAGEMENT: A039774

Year: 7/09/2007
 Vin #: 6F0000007A435325
 Engine Type: CUMMINS GEN2
 Engine #: 79256224
 Suspension: AIRGLIDE 200
 Rear Axle:
 Fwd Axle:
 Gearbox:

Purchase Date: 12/09/2013
 Purchased From: KENWORTH LAVERTON

MAINTENANCE HISTORY

Date	KM's	Maintenance Type	Problem	Repairer	Reference	Cost
10/10/2016	771,385	Other		TruckFix Pty Ltd	562	5775.00
Work Done: RADIATOR REPAIRED. PULLED DOWN AND CHECKED ENGINE. ENGINE REBUILT						
27/12/2016	756548	Truck B Service (Full service)		TruckFix Pty Ltd	632	308.00
Work Done:						
11/02/2017	771,116	Tyre Change		Frank Macheda	411	120.00
Work Done: FIT TWO NEW REMINGTON STEER TYRES						
6/04/2017	785,250	Other		TruckFix Pty Ltd	727	616.00
Work Done: FITTED NEW GUARDS. REPLACED AIR HORN SWITCH. ADJUSTED DRIVE AIRBAGS AS REQUIRED. FIXE AIR LEAK IN AIR LINE.						
25/06/2017	816,519	Tyre Change		Frank Macheda	365	180.00
Work Done: FIT 8 NEW STEELMARK DRIVE TYRES						
13/08/2017	830,729	Tyre Change		Nicsam Maintenance	369	60.00
Work Done: FIT TWO NEW TOYO STEER TYRES ON TRUCK						
17/11/2017	862996	Truck B Service (Full service)		TruckFix Pty Ltd	921	616.00
Work Done:						
21/12/2017	880714	Other		TruckFix Pty Ltd	920	154.00
Work Done: REPLACED HOSE FROM COMPRESSOR NEAR GEARBOX.						

Vehicle Maintenance Record - KENWORTH K104B



Id: 061
 Model: KENWORTH K104B
 Vehicle Id: 1
 Registration #: ZYY 624
 Expiry Date: 9/06/2018
 E-Tag: 131421775944
 Notes: MASS MANAGEMENT: A039774

Year: 7/09/2007
 Vin #: 6F0000007A435325
 Engine Type: CUMMINS GEN2
 Engine #: 79256224
 Suspension: AIRGLIDE 200
 Rear Axle:
 Fwd Axle:
 Gearbox:

Purchase Date: 12/09/2013
 Purchased From: KENWORTH LAVERTON

MAINTENANCE HISTORY

Date	KM's	Maintenance Type	Problem	Repairer	Reference	Cost
17/12/2015	636465	Other	C SERVICE	TruckFix Pty Ltd	330	462.00
Work Done:						
6/02/2016		Other		Frank Macheda	330	30.00
Work Done: CHANGED STANDARD HEADLIGHT GLOBES TO EXTREME VISION 130%						
25/02/2016	663756	Truck B Service (Full service)		TruckFix Pty Ltd	389	308.00
Work Done:						
14/03/2016		Tyre Change		Frank Macheda	338	60.00
Work Done: ROTATE STEER TYRES						
1/05/2016	686,311	Tyre Change		Frank Macheda	345	60.00
Work Done: 2 NEW STEER TYRES (GOODYEAR S100)						
15/05/2016	691,150	Truck B Service (Full service)		TruckFix Pty Ltd	465	308.00
Work Done:						
29/05/2016		Other		Frank Macheda	348	60.00
Work Done: REPLACE BOTH BATTERIES R/H/S P839-P806. BATTERIES SUPPLIED BY COBRAM MOBILE ELECTRICAL.						
24/07/2016		Other		TruckFix Pty Ltd	514	44.00
Work Done: FITTED NEW LED HEAD LIGHTS						

Vehicle Maintenance Record - KENWORTH K104B



Id: 061
 Model: KENWORTH K104B
 Vehicle Id: 1
 Registration #: ZYY 624
 Expiry Date: 9/06/2018
 E-Tag: 131421775944
 Notes: MASS MANAGEMENT: A039774

Year: 7/09/2007
 Vin #: 6F0000007A435325
 Engine Type: CUMMINS GEN2
 Engine #: 79256224
 Suspension: AIRGLIDE 200
 Rear Axle:
 Fwd Axle:
 Gearbox:

Purchase Date: 12/09/2013
 Purchased From: KENWORTH LAVERTON

MAINTENANCE HISTORY

Date	KM's	Maintenance Type	Problem	Repairer	Reference	Cost
3/05/2015	557,878	Truck B Service (Full service)		Frank Macheda	149	210.00
Work Done:						
16/05/2015	547,951	Other		TruckFix Pty Ltd	122	77.00
Work Done: REPLACED ODOMETER SCREEN.						
26/05/2015	558,384	Other		TruckFix Pty Ltd	143	77.00
Work Done: EXHAUST LEAK - RHS EXHAUST FLEX HAD COME AWAY FROM EXHAUST BELL. REFITTED.						
12/07/2015	574,115	Tyre Change		Frank Macheda	316	120.00
Work Done: FIT 8 NEW GOODYEAR DRIVE TYRES.						
29/07/2015	580,134	Truck B Service (Full service)		TruckFix Pty Ltd	201	693.00
Work Done: ALSO REPLACED HOSE ON RADIATOR. REPLACED BUSHES ON FRONT DIFF. TORQUE RODS.						
9/08/2015	582,430	Tyre Change		Frank Macheda	318	120.00
Work Done: FIT TWO NEW MAXES STEER TYRES.						
20/08/2015		Engine		TruckFix Pty Ltd	217	269.00
Work Done: FAULT WITH ENGINE LIGHTS AND HORTON FAN STAYING ON ALL THE TIME. CLEARED FAULTS AND FITTED NEW ECM.						
27/10/2015	606,694	Truck B Service (Full service)		TruckFix Pty Ltd	272	308.00
Work Done:						

Vehicle Maintenance Record - KENWORTH K104B



Id: 061
 Model: KENWORTH K104B
 Vehicle Id: 1
 Registration #: ZYY 624
 Expiry Date: 9/06/2018
 E-Tag: 131421775944
 Notes: MASS MANAGEMENT: A039774

Year: 7/09/2007
 Vin #: 6F0000007A435325
 Engine Type: CUMMINS GEN2
 Engine #: 79256224
 Suspension: AIRGLIDE 200
 Rear Axle:
 Fwd Axle:
 Gearbox:

Purchase Date: 12/09/2013
 Purchased From: KENWORTH LAVERTON

MAINTENANCE HISTORY

Date	KM's	Maintenance Type	Problem	Repairer	Reference	Cost
9/01/2015	499,286	Truck B Service (Full service)		TruckFix Pty Ltd	IV6	280.00
Work Done:						
12/01/2015		Other		Frank Macheda	280	60.00
Work Done: FIT TWO NEW BATTERIES L/H/S						
24/01/2015		Engine		Frank Macheda	284	60.00
Work Done: FIT NEW EXHAUST CLAMP, BOTTOM R/H/S						
5/02/2015		Other		Cobram Mobile Auto Electrical	4031	378.00
Work Done: HARD CORE BATTERY HCC27MF P620 P621						
10/03/2015	524,173	Electrical		TruckFix Pty Ltd	IV64	70.00
Work Done: TRAILER PLUG ELECTRICAL FAULT. PARKER LIGHT CIRCUIT PIN MISSING, REPLACED PIN.						
7/04/2015		Other		Cobram Panel Works	4103	245.00
Work Done: SUPPLY & FIT FRONT RH WINDSCREEN						
14/04/2015	526,415	Truck B Service (Full service)		TruckFix Pty Ltd	077	308.00
Work Done:						
14/04/2015	534,647	Other		TruckFix Pty Ltd	92	175.00
Work Done: REMOVED LHS STEER HUB CAP AND REMOVED THE OUTER BEARING, REMOVED THE HUB ASSEMBLY, REMOVED THE BRAKE SHOES. CLEANED						

Vehicle Maintenance Record - KENWORTH K104B



Id: 061
 Model: KENWORTH K104B
 Vehicle Id: 1
 Registration #: ZYY 624
 Expiry Date: 9/06/2018
 E-Tag: 131421775944
 Notes: MASS MANAGEMENT: A039774

Year: 7/09/2007
 Vin #: 6F0000007A435325
 Engine Type: CUMMINS GEN2
 Engine #: 79256224
 Suspension: AIRGLIDE 200
 Rear Axle:
 Fwd Axle:
 Gearbox:

Purchase Date: 12/09/2013
 Purchased From: KENWORTH LAVERTON

MAINTENANCE HISTORY

Date	KM's	Maintenance Type	Problem	Repairer	Reference	Cost
13/05/2014		Other		Cobram Panel Works	2947	245.00
Work Done: SUPPLY & FIT FRONT RH WINDSCREEN						
15/06/2014	414,582	Truck B Service (Full service)		Frank Macheda	128	180.00
Work Done:						
26/06/2014		Electrical		Cobram Mobile Auto Electrical	3574	61.00
Work Done: TEST INDICATORS. RESOLDER CRACKED JOINS AND TEST						
4/07/2014		Electrical		Cobram Mobile Auto Electrical	3666	99.00
Work Done: CHECK ALL LIGHTS. REPAIR BROKEN WIRING AND BAD CONNECTIONS. TEST						
27/08/2014	439886	Engine		Full on Truck Maintenance	53283	3243.00
Work Done: FITTED NEW MAIN BEARINGS & TENSIONED. FITTED NEW BIGEND BEARINGS AND TENSIONED. FITTED OIL PUMP AND PICKUP, CLEANED AND						
1/11/2014	469833	Truck B Service (Full service)		Frank Macheda	140	180.00
Work Done:						
1/11/2014		Gearbox/Diffs Service		Frank Macheda	245	150.00
Work Done: REPLACE BOTH DIFF OILS & GEARBOX OILS						
7/12/2014		Other		Frank Macheda	257	60.00
Work Done: REPLACE AIR HORN CONTROL VALVE						

Vehicle Maintenance Record - KENWORTH K104B



Id: 061
 Model: KENWORTH K104B
 Vehicle Id: 1
 Registration #: ZYY 624
 Expiry Date: 9/06/2018
 E-Tag: 131421775944
 Notes: MASS MANAGEMENT: A039774

Year: 7/09/2007
 Vin #: 6F0000007A435325
 Engine Type: CUMMINS GEN2
 Engine #: 79256224
 Suspension: AIRGLIDE 200
 Rear Axle:
 Fwd Axle:
 Gearbox:

Purchase Date: 12/09/2013
 Purchased From: KENWORTH LAVERTON

MAINTENANCE HISTORY

Date	KM's	Maintenance Type	Problem	Repairer	Reference	Cost
24/01/2014	350000	Engine		Graham Thomson Motors	KWCS163	6469.00
Work Done: TURBO FAILED, FITTED NEW TURBO & GASKETS, NEW EXHAUST FLEX & CLAMPS, NEW AIR CLEANER, TOPPED UP ENGINE OIL, REPLACED ALL INTAK						
2/02/2014		Other		Frank Macheda	125	180.00
Work Done: REPLACE THROTTLE SENSOR, REPAIR WIRING FROM SENSOR TO COMPUTER						
3/02/2014	1362336	Other		Full on Truck Maintenance	52768	323.00
Work Done: ECM WIRING & VALIDATION. WIRING LOOM BACK UNDER ENGINE, FOUND WIRING RUBBED & SHORTING OUT ON CUSHION CLAMP. FIXED.						
15/02/2014		Other		Frank Macheda	131	180.00
Work Done: REPLACE AIR HORN - CONTROL VALVE						
20/03/2014	381653	Engine		Full on Truck Maintenance	52874	364.00
Work Done: REPAIR ENGINE FAULT, FLASH CODE 435. FIT NEW FAULTY OIL PRESSURE TEMP SENSOR						
10/04/2014	388926	Clutch		Graham Thomson Motors	KWCS164	4945.00
Work Done: TOWED TRUCK TO BE REPAIRED. REAR MAIN LEAKING, REPLACED MAIL SEAL, REASSEMBLED. REPLACED OIL FILTER AND TOPPED UP WITH OIL.						
13/04/2014	419014	Truck B Service (Full service)		Frank Macheda	123	180.00
Work Done:						
18/04/2014		Other		Frank Macheda	148	60.00
Work Done: FIT WEIGHT GAUGE						

Vehicle Maintenance Record - KENWORTH K104B



Id: 061
 Model: KENWORTH K104B
 Vehicle Id: 1
 Registration #: ZYY 624
 Expiry Date: 9/06/2018
 E-Tag: 131421775944
 Notes: MASS MANAGEMENT: A039774

Year: 7/09/2007
 Vin #: 6F0000007A435325
 Engine Type: CUMMINS GEN2
 Engine #: 79256224
 Suspension: AIRGLIDE 200
 Rear Axle:
 Fwd Axle:
 Gearbox:

Purchase Date: 12/09/2013
 Purchased From: KENWORTH LAVERTON

MAINTENANCE HISTORY

Date	KM's	Maintenance Type	Problem	Repairer	Reference	Cost
Work Done:		Truck C Service (change		TruckFix Pty Ltd	980	462.00
12/09/2013		Annual Roadworthy Inspections		Cobram Truck Repairs	45608	220.00
Work Done: ROADWORTHY INSPECTION		Other	GPS	Cobram Mobile Auto Electrical	2969	439.00
23/09/2013		Truck B Service (Full service)		W & F Truck Repairs	111	180.00
Work Done: GPS TRACKER		Gearbox/Diffs Service		W & F Truck Repairs	071	60.00
5/10/2013	313911	Tyre Change		Frank Macheda	86	120.00
Work Done:		CAB REPAIRS		SHEPPARTON MOTOR PANEL	29075	10665.00
5/10/2013	313911	Truck B Service (Full service)		Frank Macheda	119	180.00
Work Done: CHANGE BOTH DIFF AND GEABOX OILS						
2/11/2013	322948					
Work Done: FIT 8 NEW DRIVE TYRES GOODYEAR G667						
7/11/2013	3177250					
Work Done: HEATER/AIR CON DASH CONTROLLER, TURNTABLE, CAB BUSH, CABIN PIN						
22/01/2014	358480					
Work Done:						

Vehicle Maintenance Record - KENWORTH K104B



Id: 061
Model: KENWORTH K104B
Vehicle Id: 1
Registration #: ZYY 624
Expiry Date: 9/06/2018
E-Tag: 131421775944
Notes: MASS MANAGEMENT: A039774

Purchase Date: 12/09/2013
Purchased From: KENWORTH LAVERTON

Year: 7/09/2007
Vin #: 6F0000007A435325
Engine Type: CUMMINS GEN2
Engine #: 79256224
Suspension: AIRGLIDE 200
Rear Axle:
Fwd Axle:
Gearbox:

MAINTENANCE HISTORY

Date	KM's	Maintenance Type	Problem	Repairer	Reference	Cost
5/10/2013	313911	Truck B Service (Full service)		W & F Truck Repairs	111	180.00
Work Done:						

Total Maintenance cost: \$46,053.00