

XO11LX	Service	03.01.2023	VKB Mechanical Repairs	C Service 904,263KMS
XO11LX	Tyres	25.01.2023	South West Car & Truck Tyres	Tyre Repair
XO11LX	Repairs		Razor	Tarp Motor
XO11LX	Repairs	05.02.2023	VKB Mechanical Repairs	Inspection & Test drive
XO11LX	Repairs	15.02.2023	Premium Tyre Service	Case Repair
XO11LX	Repairs	22.02.2023	DG Auto	Trace & Repair Broken Earth Wire
XO11LX	Repairs	07.03.2023	DG Auto	Check over all lights, trace and repair broken earth wire
XO11LX	B Service	12.03.2023	VKB Mechanical	B serviced truck and dog at 919,278klms
				removed and replaced engine oil+ filters
				removed and replaced fuel filters
				greased truck
				checked steering
XO11LX	Repairs	17.03.2023	DG Auto	checked diff and gear box oils
XO11LX	Repairs	17.03.2023	DG Auto	Engine Brake Warning light not working
XO11LX	B Service	01.04.2023	VKB Mechanical	truck and dog at 929,698klms
				removed and replaced engine oil+ filters
				removed and replaced fuel filters
				greased truck
				checked steering
XO11LX	Repairs	11.04.2023	South West Car & Truck Tyres	checked diff and gear box oils
XO11LX	Tyres	11.04.2023	South West Car & Truck Tyres	1x Minor Tyre Repair
XO11LX	Repairs	19.04.2023	DG Auto	Faulty Headlight replacement
XO11LX	Repairs	27.04.2023	J.F Sons Welding	Works carried out to Stonebuilt Truck body (Truck Rego) XO.11 LX
XO11XL	Repairs	29.04.2023	Freightliner & Mercedes-Benz Trucks Illawarra	Repairs to Fan Belt
XO11LX	Repairs	01.05.2023	DG Auto	XO11LX - Remove and replace headlights
XO11LX	Repairs	04.05.2023	Multispares	Air Filter
XO11LX	Repairs	08.05.2023	Gilbys Truck repairs	DIAGNOSE FAULTY ADBLUE PUMP, INSTALL & VERIFIED OPERATION, REPLACED AIR FILT
XO11LX	Repairs	18.05.2023	VKB Mechanical	put helicoils in for quarter guard on front of
XO11LX	Repairs	29.05.2023	Gilber & Roach	Air Spring
XO11LX	Service	05.06.2023	VKB Mechanical	B serviced truck and dog rego-XO11LX at
				950,413klms
				removed and replaced engine oil + filter
				- removed and replaced both fuel filters
				-replaced air filter
				-checked and adjusted brakes
				-greased
				-checked steering
				-checked drive line
				-changed 2x steering unis
				-changed 2x check valves
				- pulled air fittings out of air dryer to reseal
				fittings
				- fixed air leak on horton fan switch
XO11LX	Repairs	20.06.2023	DG Auto	Locate & Replace Blown Fuse
XO11LX	Repairs	22.06.2023	VKB Mechanical	Removed and replaced brake booster for trailer tail gate
XO11LX	Repairs	23.06.2023	VKB Mechanical	Removed and replaced oil pressure sensor sender
XO11LX	Repairs	25.06.2023	VKB Mechanical	Removed & Replaced Air connection between truck and trailer on left side,
				A Service Truck & Trailer

				Checked fluids, brakes, tyres, buses and grease
XO11LX	Repairs	28.06.2023	Southwest Autoglass	Replace Windscreen
XO11LX	Service	02.07.2023	VKB Mechanical	B Service 959,211 KMS
				Removed and replaced, engine oil and filter, fuel filters, air filters
				Checked drive line, brakes, lights, tyres, coolant, for air leaks,
XO11LX	Tyres	03.07.2023	South West Car & Truck Tyres	1x local road service, strip & Fit, tyre disposal fee and 1x continental HSR2 tyre
XO11LX	Repairs	12.07.2023	DG AUto	Clear Fault for Aftertreat light
XO11LX	Repairs	17.07.2023	DG Auto	repair short wiring, fuse
XO11LX	Repairs	30.07.2023	VKB Mechanical	Test Battery on Tarp- Found to be faulty, replaced battery
XO11LX	Repairs	05.08.2023	Gilbert & Roach	removed and replaced bottom sway bar
XO11LX	Repairs	10.08.2023	Impeccable Fleet Mainenance	bushes on kenworth t409, bolts were sized
				in needed portor power to push them out.
				Sensor-Low Coolant & HT/S super Duty OEM
				Attended Breakdown for stop engine light diagnosed as a faulty low coolant lightRemove Horton fan assembly. Carry out overhaul of
				Horton fan due to worn out clutch. Fit overhauled fan hub.
				Remove and Replace low coolant level switch
XO11LX	Repairs	11.08.2023	DG Auto	- TRAVEL TO BRINGELLY AFTER VEHICLE CAME BACK FROM WORK
				- CHECK FOR AFTER TREAT LIGHT ON
				- FOUND FUSE BLOWN AGAIN FOR AFTER DOSER PUMP
				- INSPECT VEHICLE WIRING FOR SHORT
				- UNABLE TO LOCATE SHORT
				- INSTALL NEW FUSE HOLDER AND WIRE FROM BATTERIES TO DOSER PUMP
				- TEST AFTER TREAT SYSTEM
				- FOUND WORKING OK
				968,627KMS
XO11LX	Repairs	14.08.2023	DG Auto	- TRAVEL TO BRINGELLY YARD AFTER VEHICLE FINISHED WORK
				- CHECK FOR AFTER TREAT LIGHT ON
				- FOUND BLOWN FUSE IN BATTERY BOX FOR DOSER PUMP
				- REPLACE FUSE
				- FOUND BLOWN AGAIN STRAIGHT AWAY
				- UNPLUG DOSED PUMP
				- FOUND FUSE DIDN'T BLOW
				- PLUG IN DOSER PUMP
				- FOUND FUSE WOULD BLOW STRAIGHT AWAY
				- FOUND SHORT IN DOSER PUMP
				- NOTIFIED ADRIAN RUNKO AS DOSER PUMP UNDER WARRANTY
				969,577KMS
XO11LX	Repairs	17.08.2023	Gilbys	CHECK ACTIVE FAULTS IN ECM FOR ADBLUE PUMP.
				CHECK FOR POWER @ ADBLUE PUMP.
				CHECK FOR LEAKS IN ADBLUE FITTINGS & LINES.
				CHECK FOR BLOCKAGES IN ANY ADBLUE LINES.
				CLEAN DOSER INJECTOR.
				REMOVE ADBLUE PUMP & FIT SPARE ADBLUE PUMP. START & RUN TEST, PUMP DIDNT POWER UP
				& DIDNT PUMP ANY ADBLUE.
				REMOVE OLD ADBLUE PUMP. REMOVE & REPLACED DAMAGED FITTING ON ADBLUE LINE.
				FIT
				NEW ADBLUE PUMP

XO11LX	Tyres	23.08.2023	South West Car & Truck Tyres	1x Minor Tyre Repair Strip & Fit, 1x 11R225 Runout Tyre
XO11LX	Repairs	10.09.2023	Impeccable Fleet Maintenance	XO11LX Carry out clutch adjustment & Repair loose mudflap, Carry Out B Service, Carry out hub seal replacement, adjust loose steering column,
XO11LX	Repairs	14.09.2023	DG AUto	- CHECK FOR SIDE MARKERS NOT WORKING TRUCK AND TRAILER
				- FOUND RHS ON TRUCK NOT WORKING AT ALL
				- TRACE AND REPAIR BROKEN WIRING IN REAR TAIL LIGHT BAR
				- FOUND 1x SIDE MARKER ON LHS ON TRUCK BODY NOT WORKING
				- TRACE AND REPAIR BROKEN WIRING
				- FOUND 2x SIDE MARKER LIGHTS NOT WORKING ON DOG TRAILER
				- TRACE AND REPAIR BROKEN WIRING TO BOTH
				- RE-TEST ALL SIDE MARKER LIGHTS
XO11LX	Repairs	25.09.2023	DG AUto	- FOUND WORKING OK
				- TEST ALL OTHER VEHICLE LIGHTS
				- TRAVEL TO BRINGELLY YARD
				- REMOVE DASH AND REPLACED 2x DASH LIGHT GLOBES
				- CHECK FOR NO BRAKE LIGHTS WORKING ON TRAILER
				- LOCATE BRAKE LIGHT FUSE BEHIND TRAILER PLUG BASE
				- FOUND FUSE BLOWN AND REPLACE
				- PULL PLUG APART AND REPAIR SHORT
XO11LX	Repairs	02.10.2023	Impeccable Fleet Maintenance	- RE-TEST ALL TRAILER LIGHTS
				- FOUND WORKING OK
XO11LX	Repairs	02.10.2023	Impeccable Fleet Maintenance	Carry Out A Service XO11LX- replace 2x drive shocks, replace all drove schocks and bushes, replace LED lamp dog trailer, replace all charge air piping and intake piping, remove turbo assembly from water pump
XO11LX	Tyres	04.10.2023	South West Car & Truck Tyres	1x Strip & Fit & Minor Tyre Repair
XO11LX	Tyres	04.10.2023	South West Car & Truck Tyres	1x Minor Tyre Repair & Strip & Fit
XO11LX	Tyres	19.10.2023	Adou Services & Tyres	8x Drive Tyres & 4x Strip & Fits
XO11LX	Parts	31.10.2023	Multispares	Fuel, Oil, & Air Fitters
XO11LX	Parts	04.11.2023	Multispares	Air Filter
XO11LX	Repairs/Service	19.11.2023	Impeccable Fleet	Carry Out Clutch Adjustment, Carry Out B Service
XO11LX	Repairs	20.11.2023	A & D Partners	MF10D31R x 4 & Fitting Charge
XO11LX	Service	10.12.2023	Impeccable Fleet	Carry out A Service
XO11LX	Repairs	13.12.2023	LVP Repairs	Grind Repair Multiple Cracks in hoistwell of bin, crack in sun frame and paint, repair 2 cracks on front axle hangers of b trailer
XO11LX	Repairs	08.01.2024	JF Sons Welding	XO11LX repair damage to right side of tailgate 11.5 hours labour
XO11LX	Repairs	11.01.2024	MSC Mechanical	KENWORTH T409 - REGO - XO11LX - 1,008,388KM
				Carried out NHVR checklist on Truck (XO11LX) -
				Found front shackle pins and bushes worn. Removed front hubs. Found wheel bearings worn.
				Removed and replaced left and right wheel bearings. -
				Replaced hub seals. Removed and replaced all front shackle pins and bushes. Pressed out old bushes.
				Pressed in new bushes. Welded in new bushes.
				Reassembled suspension. Replaced front axle shock rubbers. Reassembled front hubs.
				Adjusted wheel bearings. Replaced lock tabs and hub cap gaskets. -
				Filled hubs with diff oil. Replaced front axle brake shoes and brake drums.
				Tensioned wheel nuts.
				Found engine mounts worn front and rear.
				Removed and replaced engine mounts and bolts.
Replaced inoperable rear left taillight.				
				TRAILER - REGO YN73FT

				Carried out NHVR checklist on Trailer (YN73FT)
XO11LX	Tyres	15.01.2024	Royales Truck Services	1x Strip, Fit & Disposal
				Carried out general service.
				Replaced engine oil and filter.
				Replaced primary and secondary fuel filters.
				Replaced air filter.
				Carried out full chassis grease.
				Checked diff and gearbox oils.
				Checked all lights.
				Checked and adjusted front and rear brakes.
				Front brakes have 9 mm remaining.
				Rear brakes have 9 mm remaining.
				Trailer brakes have 10 mm remaining.
XO11LX	Repairs	28.02.2024	Southwest Autoglass	Supplied and installed right front windscreen on Kenworth T409
				- CHECK FOR AIR CONDITIONER NOT WORKING
				- PUT GAUGES ON TO CHECK GAS LEVEL
				- FOUND GAS LEVEL OK BUT PRESURES RUNNING HIGH
				- CHECK FOR CONDENSOR FANS WORKING
				- FOUND NOT WORKING
				- CHECK ALL FUSES
				- FOUND OK
				- WENT UP ON TOP OF ROOF
				- REMOVE COVER FROM REDDOT
				- FOUND RELAY FAULTY
				- REPLACE RELAY
				- RE-CHECK PRESURES
				- FOUND OK
				- RE-FIT COVER ON TO REDDOT
				- RE-TEST A/C WORKING
XO11LX	Tyres	13.03.2024	Sydney Tyre Sevic	2x Yokohama 295/80R22.5 Tyres
XO11LX	Repairs	19.03.2024	DG AUto	- CHECK FOR BRAKE LIGHTS NOT WORKING ON TRAILER
				- REPLACE BLOWN FUSE
				- TRACE AND REPAIR SHORTED WIRED AT REAR OF TRAILER
				- RE-TEST ALL TRAILER LIGHTS
				- FOUND LEFT HAND REAR BLINKER ON BODY INOPERATIVE
				- TRACE AND REPAIR BAD CONNECTION
				- RE-TEST
				- FOUND OK
				- CHECK FOR REAR RIGHT HAND PARKER ON TAIL LIGHT BAR INOPERATIVE
				- FOUND LIGHT FAULTY AND REPLACED
				- RE-TEST
				- FOUND OK
				- CHECK FOR AIR CONDITIONER BLOWER FAN ONLY WORKING ON SPEED 4
				- TRACE FAULT TO BLOWER FAN RESISTOR
				- REPLACE BLOWER FAN RESISTOR
				- RE-TEST
				- FOUND OK

				DOG TRAILER REGO.: YN-73FT
				- CHECK FOR RIGHT HAND REAR BLINKER INOPERATIVE
				- TRACE FAULT TO BAD CONNECTION ON PLUG AND REPAIRED
				- RE-TEST
				- FOUND OK
				Carried out general service.
				Replaced engine oil and filter.
				Replaced primary and secondary fuel filters.
				Replaced air filter.
				Carried out full chassis grease.
				Checked diff and gearbox oils.
				Checked all lights. Checked body bolts.
				Checked and adjusted front and rear brakes.
				Front brakes have 9 mm remaining.
				Rear brakes have 9 mm remaining.
				Trailer brakes have 9 mm remaining.
				TRAILER - REGO - YN73FT
				Carried out trailer service.
				Greased trailer.
				Adjusted brakes.
				- TRAVEL TO BRINGELLY YARD
				- REPLACE 2x WINDSCREEN WASHER JETS - ONE ON EACH WIPER
				- REPLACE BROKEN T-PIECE
				- RE-TEST WINDSCREEN WASHERS
				Inspected for vehicle hard to start.
				Found starter motor failed.
				Removed starter motor assembly.
				Fitted new starter motor.
				Tested operation.
				Replaced leaking cab airbags.
				Replaced fan and A/C belt.
				Replaced leaking coolant tap.
				Supply and Install the following to Vehicle with REGO:
				XO11LX
				409 Rigid Roll tarp
				CHECK FAULTS, FOUND FAULTS FOR ADBLUE PUMP & COMMUNICATION ISSUES, DIAGNOSE ADBLUE PUMP TO HAVE FAILED & ISSUE WITH COMMUNICATION TO ADBLUE PUMP
				ALSO. UPLOAD NEW SOFTWARE
				Rectify PTO Controls and Tailgate Inop- Remove and replace faulty pressure protection valve on truck
				Labour, Replace wire rope in roll tube.
				Find fault with gearbox, 90 degree drive of motor broken.
				Strip motorized arm, replace 90 degree drive and refit.
				Shorten wire rope on 4AD, tension cable.
				Labour, Replace wire rope after welder burnt through cable.
				Bend stop back to shape on P/Side.
				Carried out "B" Service.
XO11LX	Repairs	09.04.2024	MSC Mechanical	
XO11LX	Repairs	10.04.2024	DG Auto	
XO11LX	Repairs	03.05.2024	MSC Mechanical	
XO11LX	Repairs	07.06.2023	X- Tarps	
XO11LX	Repairs	19.06.2024	Gilbys Truck Repairs	
XO11LX	Repairs	28.06.2024	Sloanebuilt	
XO11LX	Repairs	11.07.2023	X- Tarps	
XO11LX	Repairs	12.07.2023	X- Tarps	

XO11LX	Service	05.08.2024	MSC Mechanical	Supplied and fitted new engine oil and filter.
				Supplied and fitted new primary and secondary fuel filters.
				Supplied and fitted new air filter.
				Cleaned cabin pollen filter.
				Carried out full chassis grease.
				Checked diff and gearbox oils.
				Checked all lights. Checked body bolts.
				Adjusted front and rear brakes.
				Front brakes have 10 mm remaining.
				Rear brakes have 8 mm remaining.
				Trailer brakes have 10 mm remaining.
				Replaced axle 3 slack adjusters.
				Replaced axle 3 right side airbag.
				Replaced inoperable LED clearance light on tipper body.
				Found air leak from governor valve hoses.
				Replaced hoses.
				Greased trailer.
Adjusted trailer brakes				
XO11LX	Repairs	19.08.2024	LVP Repairs	Grind and prep all cracks under bin in ram well
				Aluminium weld all prepped cracks
				Clean welds with wire wheel
				All costs include materials and labour
XO11LX	Repairs	02.09.2024	DG AUto	KENWORTH T409
				REGO.: XO-11LX
				KMS.: 52,029
				2/09/2024
				- TRAVEL TO BRINGELLY YARD
				- CHECK FOR AIR CONDITIONER NOT WORKING
				- FOUND FAULTY PRESURE SWITCH
				- BY-PASS PRESURE SWITCH
				- FOUND A/C WORKING OK
				- ORDERED NEW PRESURE SWITCH
				- CHECK FOR REDDOT FAN OPERATION
				- FOUND OK
				3/09/2024
				- REPLACE FAULTY A/C PRESURE SWITCH
- ADJUST RECIEVER DRIER AND BRACKET SO BONNET DOESNT HIT IT WHEN IT CLOSSES				
- TESTED OK				
XO11LX	Repairs	16.09.2024	Meridian Industries Pty Ltd	Remove Old Tarp of Truck Supply & Fit new Electric Powered PVC tarp
XO11LX	Repairs	21.10.2024	MSC Mechanical	Carried out "A" Service.
				Checked engine oil.
				Checked coolant.
				Checked belts.
				Carried out full grease chassis truck and trailer.
				Checked lights.
				Found oil leak at front diff yoke.
				Removed driveshaft.
Tightened yoke.				

				Refitted driveshaft.
XO11LX	Repairs	31.10.2024	Multispares	airbay Assy
				Removed and replaced axle 1 right side airbag.
XO11LX	Repairs	05.11.2024	MSC Mechanical	Bent top plate into shape.
				Replaced axle 4 right side airbag.
				Replaced compressor governor valve.
				Tested operation.
XO11LX	Tyres	11.11.2024	Sydney Tyre Service	8 x New Power 11R22.5 Tyres
XO11LX	Tyres	11.11.2024	Sydney Tyre Service	2 x New Power 11R22.5 Tyres & Road Service
				Carried out "B" Service.
				Supplied and fitted new engine oil and filter.
				Supplied and fitted new primary and secondary fuel filters.
				Supplied and fitted new air filter.
				Carried out full chassis grease.
				Checked diff and gearbox oils.
				Checked all lights. Checked body bolts.
				Checked and adjusted front and rear brakes.
				Front brakes have 9 mm remaining.
				Rear brakes have 10 mm remaining.
				Trailer brakes have 8 mm remaining.
				TRAILER - REGO - YN73FT
				Carried out trailer service.
				Greased trailer.
				Adjusted brakes.
				Checked lights.
				Checked clutch.
				Adjust clutch.
				T409 (XO11LX)
XO11LX	Repairs	08.01.2025	MM Plant & Diesel	Supplied Batteries
				X4 MF95D31R
				- TRAVEL TO BRINGELLY YARD
				- CHECK FOR AIR CONDITIONER INOPERATIVE
				- FOUND SYSTEM LOW ON GAS
				- DE-GAS REMAINING GAS
				- PRESURE TEST FOR LEAKS
				- REPLACE LEAKING O-RING ON COMPRESSOR
				- RE-GAS WITH LEAK DETECTOR
				- TEST WORKING
				- FOUND OK
				- CHECK FOR PARKING LIGHTS NOT WORKING ON TRUCK
				- TRACE AND REPAIR SHORT IN REAR LIGHT WIRING
				- RE-TEST WORKING
				- FOUND OK
				Travelled to vehicle broken down at Sunnyholt Road Parklea.
				Found top radiator hose split.
				Picked up parts on the way.
XO11LX	Repairs	10.02.2025	MSC Mechanical	Replaced both top radiator hoses and clamps.
				Filled with new coolant.

				Ran engine and bled.
				Returned to workshop
XO11LX	Repairs	17.02.2025	MSC Mechanical	Supplied and fitted new airbag to N/S front drive axle.
				Carried out "B" service.
				Supplied and fitted new engine oil and filter.
				Supplied and fitted new primary and secondary fuel filters.
				Supplied and fitted new air filter.
				Cleaned cabin pollen filter.
				Carried out full chassis grease.
				Checked diff and gearbox oils.
				Checked all lights. Checked body bolts.
				Checked and adjusted brakes.
				Truck -
				1st axle brakes have 8 mm remaining.
				2nd axle brakes have 7 mm remaining.
				3rd axle brakes have 10 mm remaining.
				Trailer -
				1st axle brakes have 10 mm remaining.
				2nd axle brakes have 10 mm remaining.
				3rd axle brakes have 10 mm remaining.
				4th axle brakes have 8 mm remaining.
				Carried out rear axle reline on 3rd axle of truck.
				NOTE - 1st drive diff leaking – reseal required.
				NOTE - Cylinder 1 manifold gasket starting to leak.
				TRAILER -
				Found various brakes to be low on dog trailer.
				Carried out brake reline on 1st, 2nd and 3rd axles both DS/ and P/S.
				Found D/S rear tail lights on Trailer not to be working.
				Found wires to be corroded for indicator and both brake lights.
				Fixed wiring for tail lights and fitted new brake lights and indicator light.
				Replaced wiper blades on truck.
XO11LX	Repairs	01.05.2025	BSC Auto Electrical	Tarp on truck not working find no power at switch
				trace back to batteries and find no power to solenoid
				diagnose circuit breaker faulty replace and test to be
				all ok
XO11LX	Repairs	20.05.2025	Muscat Trailers	LABOUR - REMOVE AND REPLACE TRUCK RINGFEDER COUPLING WITH MANUAL HAND OPERATED
				VARIANT AUS303, REMOVE AND REPLACE TRIOMATICS ON TRUCK TOWBAR, REMOVE AND REPLACE
				& PLUMB 4AD DRAWBAR ASSEMBLY, NEW TRIOMATICS ARE NOT COMPATIBLE WITH OLD STYLE
				TRIOMATICS - NEED TO REPLACE BOTH SIDES
				VARIOUS PARTS - RINGFEDER, DRAWBAR, ETC
				Carried out "A" service.
				Topped up engine oil.
				Checked coolant.
				Carried out full chassis grease.
				Check lights. Checked brakes.

XO11LX	Repairs	30.05.2025	MSC Mechanical Repairs	Checked and adjusted trailer brakes.
				Checked truck brakes.
				Found front drive slack adjusters worn.
				Supplied and fitted new adjusters.
				Found N/S booster leaking.
				Supplied and fitted new booster.
				Adjusted brakes.
				Found O/S airbag leaking.
				Supplied and fitted new airbag assembly.
				Repaired air leak at front steer.
XO11LX	Repairs	20.06.2025	MSC Mechanical Repairs	Supplied and fitted new air fittings.
				Travelled to Picton Road to inspect for Stop Engine Light on dash.
				Plugged into vehicle.
				Found code for low coolant.
				Topped up coolant – 7 Litres.
				Could not find any external leaks.
				Topped up engine oil – 3 Litres.
				Cleared faults.
				Returned to workshop.
				XO11LX
Carried out "B" service.				
Supplied and fitted new engine oil and filter.				
Supplied and fitted new primary and secondary fuel filters.				
Supplied and fitted new air filter.				
Supplied and fitted new cabin pollen filter.				
Carried out full chassis grease.				
Checked diff and gearbox oils.				
Checked all lights. Checked body bolts.				
Checked and adjusted brakes.				
1st axle brakes have 10 mm remaining.				
2nd axle brakes (New).				
3rd axle brakes have 9 mm remaining.				
Carried our brake reline on 1st drive axle.				
Removed wheels, brake drums and brake shoes.				
Supplied and fitted new brake shoes and hardware.				
Supplied and fitted new brake drums.				
Refitted wheels and tensioned.				
Adjusted brakes.				
Repaired lights.				
Repaired clearance light on O/S front of tipper body.				
TRAILER				
Carried out brake reline on rear axle.				
Supplied and fitted new brake shoes.				
Supplied and fitted new brake drums.				
Refitted wheels and tensioned.				
Carried out trailer service.				
Adjusted brakes.				
Greased trailer.				

				Supplied and fitted new shock to N/S rear.
				Fitted mudflaps on rear drive.
				Repaired windscreen washer jets.
XO11LX	Repairs	03.09.2025	MSC Mechanical Repairs	Inspected for coolant leak.
				Found water pump leaking.
				Removed belts and alternator.
				Drained coolant.
				Removed water pump.
				Supplied and fitted new water pump and O-ring.
				Supplied and fitted new belts.
				Refitted alternator.
				Refilled coolant.
				Fitted new dipstick for power steering bottle.
XO11LX	Tyres	12.09.2025	Sydney Tyre Services	2 x Goodyear 298/80R22.5 & Disposal
				KENWORTH T409 - REGO - XO11LX - 1,287,950KM
				Carried out "B" service.
				Supplied and fitted new engine oil and filter.
				Supplied and fitted new primary and secondary fuel filters.
				Supplied and fitted new air filter.
				Cleaned cabin pollen filter.
				Carried out full chassis grease.
				Checked diff and gearbox oils.
				Checked all lights. Checked body bolts.
				Adjusted brakes.
				1st axle brakes have 8 mm remaining.
				2nd axle brakes have 8 mm remaining.
				Found P/S 1st axle hub seal to be leaking.
				Replaced brake linings and brake drum.
				Repacked hubs and wheel bearings with grease.
				Fitted new lock tab washer.
				Tensioned wheel bearings and adjusted brakes.
				Supplied and fitted axle 2 new sway bar bushes.
				Supplied and fitted 2 x airbags on axle 2 right side.
				Supplied and fitted 2 x shocks on axle 2.
XO11LX	Repairs	29.09.2025	Daniels Automotive	Customer complaint of coolant loss. Traced and located coolant leak coming from a slightly burst lower radiator hose. Allowed engine to cool, then drained coolant system. Removed defective lower radiator hose and hose clamps. Supplied and fitted new lower radiator hose and new clamps. Refilled engine coolant, bled system through, and carried out thorough testing. Cooling system holding pressure and operating correctly – all OK.
XO11LX	Tyres	01.10.2025	Master Truck Service	2 x Haulstar 11R22.5 & 2 x disposal
XO11LX	Repairs	11.11.2025	Multispares	Window Regulator C/W Motor
XO11LX	Repairs	17.11.2025	Multispares	HEATER TAP - 3/8"THREAD 5/8" HOSE Cooant
XO11LX	Parts	17.11.2025	Multispares	1x Combo Switch Column Mounted
XO11LX	Tyres	22.11.2025	Sydney Tyre Service	2x NEW POWER 11R22.5 18PR ND818 DRIVE
				Carried out "B" service.
				Supplied and fitted new engine oil and filter.
				Supplied and fitted new primary and secondary fuel filters.

XO11LX	B Service	05.12.2025	MSC Mechanical Repairs	Supplied and fitted new air filter.
				Carried out full chassis grease.
				Checked diff and gearbox oils.
				Checked all lights. Checked body bolts.
				Checked and adjusted brakes.
				1st axle brakes have 9 mm remaining.
				2nd axle brakes have 8 mm remaining.
				3rd axle brakes have 8 mm remaining.
				Supplied and fitted new lights to rear.
				Supplied and fitted side clearance light.
				Supplied and fitted new reverse light.
				Supplied and fitted new brake light.
				Repaired exhaust.
				Supplied and fitted new bushes and bolts to engine pipe.
XO11LX	Parts	17.12.2025	Multispare	2x Drive Belts & Belt Tensioner
XO11LX	Repairs	03.12.2025	DG Auto	26/11/2025
				- TRAVEL TO BRINGELLY YARD
				- CHECK FOR AIR CONDITIONER BLOWER FAN NOT WORKING
				- TRACE FAULT TO AIR CONDITIONER BLOWER FAN FAULTY AND REPLACED
				- TEST AIR CONDITIONER OPERATION
- FOUND OK				
XO11LX	Repairs	09.12.2025	DG Auto	- RECIEVE PHONE CALL FROM ADRIAN VELLA AT 5.30AM
				- TRAVEL TO AMPOL SERRVICE STATION ON MAMRE ROAD KEMPS CREEK
				- CHECK FOR NO LIGHTS WORKING ON DOG TRAILER
				- FOUND TRAILER PLUG BASE BROKEN
				- REPLACE TRAILER PLUG BASE AND REPAIR WIRING
				- FOUND ALL LIGHTS WORKING EXCEPT FOR MARKER LIGHTS
				- TEST FUSES AND CIRCUT BREAKERS
				- FOUND TRAILER MARKER CIRCUT BREAKER TRIPPED
				- RESET CIRCUT BREAKER
- FOUND ALL LIGHTS WORKING OK ON DOG TRAILER				
XO11LX	Repairs	09.12.2024	B & K Truck Repairs	Breakdown llandilo -
				Travel to site , run engine and check ,
				remove turbo hoses inspect impeller
				shaft ,
				Test drive truck found turbo faulty ,
				R and r turbo and gaskets ,
				Clean all gasket surfaces ,
Reseal oil leak at oil pressure sendor ,				
clean all intake and exhaust piping				
XO11LX	B Service	10.02.2026	MSC Mechanical	Carried out "B" service.
				Supplied and fitted new engine oil and filter.
				Supplied and fitted new primary and secondary fuel filters.
				Supplied and fitted new air filter.
				Cleaned cabin pollen filter.
				Carried out full chassis grease.
				Checked diff and gearbox oils.
				Checked all lights. Checked body bolts.

				Checked and adjusted brakes.
				1st axle brakes have 8 mm remaining.
				2nd axle brakes have 7 mm remaining.
<b>XO11LX</b>	Repairs	13.02.2026	Quantum Mechanics	ECM Repair & Calibration Nox/Power Upgrade & Engine Light Repair
<b>XO11LX</b>	Tyres	4.03.2026	Eagle Truck Centre	Puncture Repair - Plug