

XN99CT	New Tyres	03.02.2022	South West Car & Truck Tyres	2 x new tyres
XN99CT	Repairs	01.04.2022	DG Auto Electrics	Repairs
XN99CT	New Tyres	04.04.2022	TYRE IMPORTS P CARINGBAH	new tyre
XN99CT	Repairs	12.04.2022	Pirtek	repairs -hose assembly
XN99CT	Service	28.04.2022	Stillwell Trucks NSW	service -electrical system
XN99CT	Repairs	05.05.2022	Heavy Hydraulics	axis pump, oil, hose, adaptors, filter
XN99CT	Service	30.06.2022	Stillwell Trucks NSW	service -electrical system
XN99CT	Repairs	15.07.2022	Daimler	Oils Filters Coolant
XN99CT	Repairs	16.07.2022	Daimler	Various Parts
XN99CT	Repairs	16.07.2022	Michael Onsite	Service & Repairs
XN99CT	Repairs	18.07.2022	Daimler	Clutch
XN99CT	Repairs	17.08.2022	Daimler	Breakdown Brake Hydraulic & Mechanical
XN99CT	Repairs	17.08.2022	Hydraulic Hoses	Hydraulic Hose repair, mounting brackets
XN99CT	Repairs	15.09.2022	South West Car & Truck Tyres	2x TYres
XN99CT	Repairs	20.09.2022	DG Auto Electrics	Air Conditioner Repairs
XN99CT	New Tyres	28.10.2022	SWCTT	2x New Tyres
XN99CT	Service	02.11.2022	MSC Mechanical	Service 370 559 KM
XN99CT	Tyre	13.02.2023	Royale Truck Service	Puncture Repair
XN99CT	Repairs	20.02.2023	Royales	1x tyre puncture
XN99CT	Repairs	08.03.2023	Royale Truck Service	1x Puncture Repair
XN99CT	Repair		South west	Tyre Change XN99CT
XN99CT	Repairs	08.05.2023	South West Car & Truck Tyres	Mlnro Tyre Repair Strip & Fit
XN99CT	Repairs	18.05.2023	VKB Mechanical	brake down on M7 to change header tank on truck and fill back up with water
XN99CT	Repairs	18.05.2023	Stillwell	Thermostat and Engine Cooling Repairs
XN99CT	Repairs	01.06.2023	Hydraulic Hoses	Hose Assmembly
XN99CT	Tyre	22.06.2023	South West Car & Truck Tyres	1x Strip & Fit Minor tyre Repair
XN99CT	Tyres	03.07.2023	South West Car & Truck Tyres	4x Haulstar Drive Tyres
XN99CT	Repairs	27.07.2023	DG Auto	Replace blinker light on LHS of Cabin, replace parker light globe in RHS headlight, replace no.plate light on trailer
XN99CT	Repairs	05.08.2023	Daimler Trucks	Entrance RH Bottom Right
XN99CT	Service	07.08.2023	MSC Mechanical	General Service 428,389KMS
XN99CT	Repairs	07.08.2023	MSC Mechanical	Carried out general service. Replaced engine oil and filter. Replaced primary and secondary fuel filters. Replaced air filter. Carried out full chassis grease. Checked diff and gearbox oils. Checked all lights. Checked body bolts. Checked front and rear brakes. Replaced air dryer filter. Inspected for vehicle faults on dash. Found code for downstream nox sensor inoperable. Removed exhaust covers. Tested sensor. Found faulty. Replaced sensor. Cleared faults. Replaced driver's side lower step box assembly. Fitted new rear left mudflap.
XN99CT	Repairs	14.08.2023	Royales	1x Mlnor Tyre Repair
XN99CT	Tyres	07.09.2023	Royal Truck Tyres	1x Continental Tyre 295/80R22.5 - Fitting & Disposal
XN99CT	Repairs	10.09.2023	Impeccable Fleet Maintenance	Remove and replace brake pads 3rd axle, remocve and replace air filters

XN99CT	Repairs	10.09.2023	DG Auto	<ul style="list-style-type: none"> <li>- CHECK FOR AIR CONDITIONER INOPERATIVE</li> <li>- FOUND SYSTEM LOW ON A/C GAS</li> <li>- DE-GAS REMAINING GAS</li> <li>- PRESURE TEST TO LOCATE LEAK</li> <li>- UNABLE TO LOCATE LEAK AT TIME OF DIAGNOSING</li> <li>- RE-GAS A/C SYSTEM</li> <li>- THEN FOUND A/C SYSTEM LEAKING</li> <li>- TRACE FAULT TO A/C CONDENSOR LEAKING</li> <li>- SOURCE AND ORDER NEW A/C CONDENSOR- DE-GAS REMAINING GAS FROM SYSTEM</li> <li>- REMOVE GRILL, MESH, ETC TO ACCESS CONDENSOR</li> <li>- REPLACE CONDENSOR</li> <li>- REPLACE A/C PRESURE SWITCH AS TO REPLACE, CONDENSOR HAS TO BE REMOVED</li> <li>- REPLACE O-RINGS FOR CONDENSOR</li> <li>- RE-FIT GRILL, MESH, ETC TO ACCESS CONDENSOR</li> <li>- RE-GAS A/C</li> </ul>
XN99CT	Repairs	17.09.2023	DG Auto	<ul style="list-style-type: none"> <li>- TRAVEL TO BRINGELLY WHEN VEHICLE FINISHED WORK</li> <li>- CHECK FOR WORKLIGHT ON LHS WING INOPERATIVE</li> <li>- REPLACE WORKLIGHT ON LHS WING</li> <li>- RE-TEST WORKING</li> <li>430,188KMS</li> </ul>
XN99CT	Tyres	03.10.2023	South West Car & Truck Tyres	2x Strip & Fit, Minor Tyre Repairs
XN99CT	Repairs	05.10.2023	Hydraulic Hoses	1x Hose Asseembly
XN99CT	Parts	04.11.2023	Multispares	Air Filter, 2x Fuel Filters, 2x Oil Filters
XN99CT	Repairs	06.11.2023	Royale Truck Service	2 x Tyre Puncture Repair
XN99CT	Repairs	08.11.2023	DG Auto	<p>MERCEDES ACTROS REGO.: XN-99CT KMS.:</p> <ul style="list-style-type: none"> <li>- TRAVEL TO BRINGELLY YARD</li> <li>- CHECK FOR AIR CONDITIONER INOPERATIVE</li> <li>- TEST A/C</li> <li>- FOUND COOLING TO 10 DEGREES VENT TEMPREATURE</li> <li>- OPEN CAB FRONT COVER</li> <li>- CHECK CABIN A/C FILTER</li> <li>- FOUND VERY DIRTY</li> <li>- REPLACED CABIN AIR FILTER</li> <li>- RE-TEST A/C</li> <li>- FOUND COOLING DOWN TO 5 DEGREES VENT TEMPREATURE NOW</li> <li>- A/C NOW TESTED OK</li> <li>- CHECK FOR LHS TAIL INOPERATIVE</li> <li>- FOUND PLUG DISCONNECTED</li> <li>- RE-CONNECT PLUG</li> <li>- RE-TEST LIGHTS</li> <li>- FOUND WORKING OK</li> </ul>
XN99CT	Repairs	15.11.2023	DG Auto	<p>MERCEDES ACTROS REGO.: XN-99CT KMS.: 448,800</p> <ul style="list-style-type: none"> <li>- TRAVEL TO BRINGELLY YARD AFTER VEHICLE CAME FROM WORKING</li> <li>- CHECK FOR TRAILER LIGHTS INOPERATIVE</li> <li>- TRACE FAULT TO TRAILER PLUG ON END OF SUZI COIL AND REPLACED</li> <li>- RE-TEST LIGHTS</li> </ul>

				<ul style="list-style-type: none"> <li>- FOUND OK</li> <li>- CHECK FOR WALKING FLOOR TRAILER NOT GETTING 12VOLT CHARGE</li> <li>- TRACE FAULT TO 12VOLT 2 PIN PLUG BASE</li> <li>- REPLACED - WAS AUTHOURISED BY ADRIAN RUNKO</li> <li>- TEST TRAILER</li> <li>- FOUND WORKING OK</li> </ul>
XN99CT	Repairs/Service	19.11.2023	Impeccable Fleet	Carry out Trailer A service, Replace Air Filter, Replace Rear N/S Guard
XN99CT	Repairs	21.11.2023	Daimler Trucks	<p>CARRIED OUT INSPECTION OF VEHICLE FOR OIL LEAK, CONFIRMED SUMP ASSEMBLY WAS DAMAGED AND REQUIRED REPLACEMENT. ONCE APPROVED, DRAINED THE ENGINE OIL AND REMOVE THE SUMP. FIT NEW SUMP AND FILLED WITH ENGINE OIL AS REQUIRED. TESTED FITMENT AND SEALING, CONFIRMED NO LONGER LEAKING, ALL OK.</p> <p>CARRIED OUT REPLACEMENT OF BRAKES ON ALL AXLES AS REQUIRED. REPLACED SLIDE KIT ON LEFT HAND SIDE OF 1ST DRIVE AXLE AS REQUIRED. CARRIED OUT BRAKE ROLLER TEST AND ROAD TESTED VEHICLE.</p> <p>REMOVED AND REPLACED AIR FILTER AS REQUIRED</p>
XN99CT	Tyres	25.11.2023	Adou Services & Tyres	2x new drive tyres
XN99CT	Repairs	28.11.2023	Impeccable Fleet	<p>XN99CT 451145</p> <p>Replace Fuel Tank Assembly</p> <p>R and R 2nd axle O/S wheels</p>
XN99CT	Tyres	21.12.2023	South west Car & Truck Tyres	3x Minor Truck Tyre Repair & 2x Strip & Fit
XN99CT	Repairs	03.01.2024	Heavy Automatics	<p>Diagnose fault and found PTO engagement shaft broken, upon futher inspection it was found the pump was siezed which caused the PTO failure.</p> <ul style="list-style-type: none"> <li>- Replace PTO and pump</li> <li>- Fit new return and pressure filter elements.</li> <li>- New hydraulic oil</li> <li>- New PTO engagement solenoid (old one was part of factory PTO)</li> <li>- Pressure set and test</li> <li>Walking floor 3200 PSI</li> <li>Tipper 2450 PSI</li> </ul>
XN99CT	Repairs	03.01.2024	Heavy Automatics	PTO Breakdown, replace PTO and pump, fit new return and pressure filter elements, new hydraulic oil, new PTO engagement solenoid
XN99CT	Repairs	10.01.2024	DG Auto	<p>TRAVEL TO BRINGELLY YARD</p> <ul style="list-style-type: none"> <li>- CHECK FOR AIR CONDITIONER NOT WORKING</li> <li>- FOUND SYSTEM LOW ON A/C GAS</li> <li>- DE-GAS REMAINING GAS</li> <li>- PRESURE TEST FOR LEAKS</li> </ul> <p>- FOUND LEAKING SUCTION HOSE REPLACE SUCTION A/C HOSE FROM COMPRESSOR TO FIREWALL</p> <ul style="list-style-type: none"> <li>- RE-PRESURE TEST</li> <li>- FOUND OK</li> <li>- CLEAN OUT CABIN A/C FILTER</li> <li>- RE-GAS A/C</li> </ul>
XN99CT	Tyres	29.01.2024	Sydney Tyre Service	4x Haulstar 11R22.5 146/145L HD602 Tyres
XN99CT	Repairs	29.01.2024	Daimler	Carry out Enginer Service, Carry out turntable re-kit, carry out reteach on gearbox
XN99CT	Repairs	11.02.2024	Daimler	<p>CARRIED OUT REPLACEMENT OF TURNTABLE AS REQUIRED/REQUESTED. GREASED UP</p> <p>TURNTABLE AND CHECKED OPERATION OF TURNTABLE WITH TURNTABLE TOOL. CHECKED</p>

				OPERATION WITH CUSTOMER PROVIDED TRAILER, CONFIRMED WORKING AS INTENDED
XN99CT	Repairs	25.03.2024	Daimler	CHECK AND REPORT LIGHT ON DASH DRIVING AND BRAKING CHARACTERISTICS CHANGED CONFIRM CUSTOMER COMPLAINT OF BRAKE CHARACTERISTICS FAULT ACTIVE ON DASH. PLUG IN XENTRY AND PERFORM INITIAL QUICK TEST AND FIND CODE FOR POWER TIMEOUT TO REAR BRAKE MODULATOR. REMOVE PLUG OFF REAR MODULATOR AND CHECK AND FIND NO POWER AT MODULATOR, REMOVE DASH PANELS FROM LEFT HAND SIDE ABOVE FUSEBOX TO GAIN ACCESS TO EBS MODULE. LOOK UP WIRING DIAGRAM AND CHECK OUTPUTS TO REAR MODULATOR, THERE IS NO POWER COMING OUT OF EBS MODULE BUT EARTH, CAN LOW AND CAN HIGH ARE OK. PERFORM CONTINUITY TEST FOR POWER WIRE BETWEEN EBS MODULE AND REAR MODULATOR AND CHECK FOR SHORTS TO GROUND, ALL GOOD. TRY PERFORMING EBS MODULE RESET BUT CODE REMAINS ACTIVE, VEHICLE HAS AN INTERNAL FAULT IN EBS MODULE AND REQUIRES A NEW ONE. RECEIVE NEW EBS MODULE, REMOVE OLD ONE FROM TRUCK AND CONNECT XENTRY AND LOAD NEW SOFTWARE AND PARAMETERS INTO TRUCK
XN99CT	Repairs	11.04.2024	DG Auto	- TRAVEL TO BRINGELLY YARD WHEN VEHICLE CAME BACK FROM WORK - CHECK FOR BRAKE LIGHT NOT WORKING RHS - FOUND FAULT IN REAR TAIL LIGHT - REPLACE WITH AFTERMARKET TAIL LIGHT - TEST ALL REAR LIGHTS - FOUND WORKING OK
XN99CT	Tyres	15.04.2024	Sydney Tyre Service	1x Service Call Puncture Repair Tyre
XN99CT	Repairs	19.04.2024	Multispares	Drive Belts x 2
XN99CT	Repairs	23.04.2024	Multispares	Drive Belt
XN99CT	Repairs	30.04.2024	Daimler Trucks	Fan Bracket, V-Ribbed Belts & Fan Shroud
XN99CT	Repairs	30.04.2024	Daimler Trucks	2x V-ribbed Belts
XN99CT	Repairs	13.05.2024	A & D Partners	MF210H51L Battery x 2 & Fitting
XN99CT	Repairs	13.01.2025	MSC Mechanical	MERCEDES BENZ ACTROS - REGO - XN99CT - 508,707KM Inspected for vehicle overheating. Found radiator externally blocked and plastic wrapped around fan. Removed radiator and intercooler assembly. Externally cleaned intercooler. Supplied and fitted new radiator. Fitted radiator and intercooler assembly. Fitted new top and bottom regulator hoses. Replaced fan hub assembly. Filled with new coolant. Road tested.
XN99CT	Repairs	15.01.2025	MSC Mechanical	MERCEDES BENZ ACTROS - REGO - XN99CT - 510,239KM Inspected for adblue fault on dash. Plugged into ECU. Found fault codes for before and after Nox Sensors. Supplied and fitted new Nox Sensors.

				Cleared faults. Road tested.
XN99CT	Repairs	10.03.2025	Macarhtur Hydraulics P/L	1x Hose Assembly
XN99CT	Tyres	14.03.2025	Sydney Tyre Service	1x Yokohama 295/80RR22.5 & 1 tyre disposal
XN99CT	Service	27.03.2025	MSC Mechanical Repairs	Carried out "B" service. Supplied and fitted new engine oil and filter. Supplied and fitted new primary and secondary fuel filters. Supplied and fitted new air filter. Cleaned cabin pollen filter. Carried out full chassis grease. Checked diff and gearbox oils. Checked all lights. Checked body bolts. Checked and adjusted brakes. 1st axle brakes have 8 mm remaining. 2nd axle brakes have 10 mm remaining. 3rd axle brakes have 10 mm remaining. Carried out axle 2 and 3 brake pad replacement. Tensioned all wheel nuts. Road tested
XN99CT	Repairs	01.05.2025	Macarhtur Hydraulics P/L	Rectify Oil Leak- Tightern Fitting on Hyd Pump & Replace Dowdy Seal
XN99CT	Tyres	12.05.2025	Sydney Tyre Service	2 x New Power 11R22.5 18PR Tyres
XN99CT	Repairs	30.05.2025	MSC Mechanical Repairs	Travel to Lucas Heights to replace blown airbag. Collected parts on the way. Removed and replaced airbag. Tested operation. Returned to workshop.
XN99CT	Tyres	26.09.2025	South West Car & Truck Tyres	2x 11R22.5 Haulstar Drive tyres
XN99CT	Tyres	26.09.2025	South West Car & Truck Tyres	2x 11R22.5 Haulstar Drive tyres
XN99CT	Repairs	18.11.2025	Daimler Trucks	CARRY OUT B ENGINE SERVICE ADDITIONAL SERVICE ITEMS NEEDED -DIFF -TRANS -COOLANT FLUSH (COOLANT CURRENTLY GREEN)