

Date	Instructions	Services	Completed By	Faults	Km	Fault No:
07/23/2022	Service		David Syson		560076	
12/11/2022	B Service, checked all fluids & oils, removed old steering box and refitted new steering box and refilled power steering fluid	B	FCDS		605120	
02/25/2023	B Service	B	David Syson		626392	
04/11/2023	B Service - number plate light on rear not working - repairs broken wire, airclean on airbag, replace airbag & main hose, tension governor valve bolts		David Syson		648202	
05/27/2023	B Sevice		David Syson		663378	
03/18/2023	Fix Deck Plate		David Syson		408028	
06/17/2023	LEDs on fuel tank rear LHS replaced, number plate light replaced, reverse beeper fixed		David Syson		670384	
08/26/2023	Carry out service, grease and check over, checked all oils and fluids, replaced governor valve, sump gasket is slightly leaking and bell housing is leaking	C	Fraser Coast Diesel Service		697934	
11/11/2023	Carry out service	B	David Syson		733477	
11/20/2023	Remove power divider and recondition due to high wear, refit power divider, adjust, road test & check		Brisbane Diff & Gearbox Services		735810	
01/13/2024	Heavy Vehicle Inspection Checklist	Annual	David Syson		759382	
01/27/2024	Carry out service	B	David Syson		762876	
02/22/2024	Diagnose and repair fault with ice pack not starting, repair main ground cable to engine & test		Onsite Auto Electrical	1	771320	
05/23/2024	replace clutch, replace rear structure gasket due to leaking, replace engine oil and oil filter while sump is off for rear structure, check & repair oil leak from fuel pump mount, replaced 2x cracked R/H front fuel tank "J" brackets, replace failed front cab mounts, replace failed indicator/wiper stalk, replaced leaking L/H rear drive hub seal	B	Brown & Hurley Burpengary	1	793731	
06/06/2024	Remove & replace turntable, test		Top Diesel Solutions		795506	
06/19/2024	Carry out service	C	David Syson		803848	
07/12/2024	Replace tail light, 6 pin plug		Onsite Auto Electrical		815635	
09/12/2024	Carry out service, remove and replace coolant heater top, top up both diffs, brakes adjusted, test drive	B	Top Diesel Solutions		842764	
11/23/2024	Carry out service	B	David Syson		882901	
12/07/2024	Diagnose and repair fault with Icepack, replace leaking condenser, re-gas & test		Onsite Auto Electrical		896472	
01/04/2025	Carry out service	C	David Syson		903317	
01/11/2025	Annual Service	Annual	David Syson		906234	
03/18/2025	Radiator repair		Brown & Hurley Mackay	1	926135	2653
05/29/2025	Alternator failure - new alternator fitted and new belts		Hartwigs Mechanical Services	1	950111	2654
06/06/2025	Inspected and found water pump leaking. Removed belts and drain collant. Remove old water pump and fit new o'ring onto pump. Cleaned surface and installed new pump. Filled with new coolant and coolant filter.		Brown & Hurley Parkhurst	1	955166	2655
06/28/2025	Carry out service	B	David Syson		968849	