

EAST GIPPSLAND ROAD MAINTENANCE P/L

T909 Kenworth Tipper

PO BOX 1442 BAIRNSDALE. 3875.

Ph 03 5152 2522

| | | |
|--------------------------|-------------|---|
| | | Kenworth T 909 XV 68 KS |
| SPECIFICATIONS | | |
| State mobile radio | | |
| Manufacturer | | Kenworth |
| Model | | T-909 |
| Manufacture date | | |
| Reg number | | XV68KS |
| Reg expiry date | | |
| Tare weight | | |
| GVM | | |
| GCM | | |
| Engine number | | |
| Engine make | | Cummins |
| Model | | Euro 5 |
| Type | | |
| Capacity (Litres) | | |
| Hp / Kw | | |
| Chassis number | | |
| Number location | | |
| Vin number | | 6F5000000KA456104 |
| Compressor | | |
| Wheelbase | | |
| Body type | | Tipper |
| Trailer brakes (Y/N) | | Y |
| Brakes (Air / Vac) | | Air |
| Transmission type | | Eaton Fuller |
| Transmission model | | |
| Gear Box Oils | | |
| Tyre size | | |
| Fuel filters x 2 | | |
| Oil filters x 2 | | |
| Air filter | | |
| Diff Oils | | |
| Air compressor filter | | |
| Trans filter | | |
| Batteries | | |
| Service Interva | 30000 Klims | |
| Bonnet stop cable | | |
| DATE | KM | SERVICE RECORD FOR KENWORTH T909 - XV 68KS |
| 31/03/2020 | 0 | Purchased Truck Gippsland Truck Centre Total PP \$333297.00 |
| 6/05/2020 | | Refurbish Truck Body & Repaint in Truck Color \$9130.00 |
| 30/04/2020 | | Refurbish Hydrolics from old T408 to New T909 Gary's Hyd \$7871.00 |
| 9/05/2020 | | TRP All Wash Bundle \$70.00 |
| 20/05/2020 | | PBS Assesment Chrisi's Body Works \$5500 |
| 18/05/2020 | | Re Work Trailer Draw Bar to PBS standard \$4472.00 Chrisi's Body Builders |
| 18/05/2020 | 5,500 | Plant Daily Inspection Notes : Nil |
| 25/05/2020 | 7,500 | Plant Daily Inspection Notes : Nil |
| 12/06/2020 | 11217 | 1St Service on Truck next Service 41K |
| 13/06/2020 | | Cleaning Gear \$33.00 GTC |
| 20/07/2020 | 27,839 | Plant Daily Inspection Notes : Nil |
| 27/07/2020 | | Plant Daily Inspection Notes : Nil |
| 3/08/2020 | 33,248 | Plant Daily Inspection Notes : Nil |
| 10/08/2020 | 35,389 | Plant Daily Inspection Notes : Nil |

| | | |
|------------|---------|--|
| 24/08/2020 | 37,293 | Plant Daily Inspection Notes : Nil |
| 28/08/2020 | 38,432 | Service as per Specs Notes : Nil |
| 31/08/2020 | 40,234 | Plant Daily Inspection Notes : Nil |
| 9/09/2020 | 40,110 | Clutch Adjustment GTC \$85.25 |
| 11/09/2020 | 41,300 | Rotate Tyres Riveria Tyres \$66.00 |
| 14/09/2020 | 43,664 | Plant Daily Inspection Notes : Nil |
| 21/09/2020 | 47,000 | Plant Daily Inspection Notes : Nil |
| 28/09/2020 | 48,685 | Plant Daily Inspection Notes : Nil |
| 6/11/2020 | | Fit Run Out Tyre |
| 11/11/2020 | 61,750 | Fit 2 Steer Tyres - Riviera Tyres |
| 20/11/2020 | 64,335 | Fit 8 Tyres - Riviera Tyres |
| 27/11/2020 | 66,462 | Fit 4 Drive Tyres - Riviera Tryes |
| 30/11/2020 | | Replace driver side windscreen - Tint a Car |
| 12/10/2020 | 51,814 | Plant Daily Inspection Notes : Nil |
| 26/10/2020 | 58,000 | Plant Daily Inspection Notes : Nil |
| 4/11/2020 | 60,000 | Plant Daily Inspection Notes : Nil |
| 17/11/2020 | 63,000 | Plant Daily Inspection Notes : Nil |
| 23/11/2020 | 66,600 | Plant Daily Inspection Notes : Nil |
| 30/11/2020 | 68,790 | Plant Daily Inspection Notes : Nil |
| 7/12/2020 | 71,876 | Plant Daily Inspection Notes : Nil |
| 14/12/2020 | | Filters - Lube, Fuel x 2, Air/Oil seperator - GTC |
| 14/12/2020 | 71,940 | 30K Service as per specks |
| 11/01/2021 | | Plant Daily Inspection Notes : Nil |
| 16/01/2021 | | Grease Truck & Clean |
| 25/01/2021 | 86,153 | Plant Daily Inspection Notes : Nil |
| 29/01/2021 | 83,746 | Fit two Trailer Tyres & Rotate Drive Tyres |
| 30/01/2021 | | Air Spring York Link end T Junction & Truck Consumables \$420.00 |
| 30/01/2021 | | Replaced Air Bag & Washed Truck |
| 17/02/2021 | | Wabco level valve \$139.00 GTC |
| 25/02/2021 | | Puncture Repair Truck \$55.00 Riveria |
| 22/02/2021 | 95,039 | Plant Daily Inspection Notes : Nil |
| 15/03/2021 | 103,630 | Plant Daily Inspection Notes : Nil |
| 19/03/2021 | 105,000 | 30K Service as per specks |
| 9/04/2021 | 111,768 | Fit 2 Toyo M149 & Balance \$1821.00 Riveria Tyres |
| 23/04/2021 | | Fit 2 Runout Tyres \$84.00 Riveria Tyres |
| 5/05/2021 | | Fit 2 New Batteries \$375.00 Bairnsdale Batteries |
| 27/05/2021 | | Filters - Lube, Fuel x 2, Air/Oil seperator - GTC \$187.53 |
| 24/05/2021 | | Fit Run Out Tyre - Riviera Tyre Service |
| 24/05/2021 | 134,300 | Plant Daily Inspection Notes : Nil |
| 28/05/2021 | 134,000 | Service As per Specks |
| 2/06/2021 | | Fit Recaps x 4 - Riviera Tyre Service \$58.00 |
| 7/06/2021 | | Garys Hydrolics Fit fitting \$47.00 |
| 7/06/2021 | 139,751 | Plant Daily Inspection Notes : Nil |
| 15/06/2021 | | Plant Daily Inspection Notes : Nil |
| 21/06/2021 | NMR | Plant Daily Inspection Notes : Nil |
| 28/06/2021 | 148,348 | Plant Daily Inspection Notes : Nil |
| 5/07/2021 | 150,411 | Plant Daily Inspection Notes : Nil |
| 12/07/2021 | 152,490 | Plant Daily Inspection Notes : Nil |
| 19/07/2021 | 154,103 | Plant Daily Inspection Notes : Nil |
| 21/07/2021 | 154,629 | Fit 4 Recaps - Riviera Tyres \$58.00 |
| 5/08/2021 | | Replace Shocker bushes on Drive |
| 26/07/2021 | | Plant Daily Inspection Notes : Nil |
| 2/08/2021 | 160,000 | Plant Daily Inspection Notes : Nil |
| 9/08/2021 | 162,130 | Plant Daily Inspection Notes : Nil |
| 13/08/2021 | | Tune Engine Adjust Clutch Replace leaking shocks under warranty \$286.00 GTC |
| 16/08/2021 | 165,300 | Plant Daily Inspection Notes : Service Due |
| 18/08/2021 | | Lube / Air & Fuel filters \$153.00 GTC |
| 20/08/2021 | 165,350 | Service As per Specks |
| 12/08/2021 | | Repair Rear of Trailer \$770.00 Jansons |

| | | |
|------------|---------|---|
| 20/09/2021 | 173,135 | Plant Daily Inspection 10000 Kms North Tipper |
| 1/10/2021 | | Premium Wash \$80.00 GTC |
| 29/09/2021 | | Repair Hinge on Trailer \$220.00 |
| 4/10/2021 | 174,647 | Clutch Adjustment GTC \$59.95 |
| 11/10/2021 | | New Tipper Tarp - CBB \$681.34 |
| 22/11/2021 | 193,460 | Daily Inspection report, Nil to report |
| 24/11/2021 | | Hose ends - Garys Hydraulics \$226.94 |
| 3/12/2021 | | Filters Lube, Fuel, Filter - Cabover - GTC \$147.47 |
| 3/12/2021 | | Air/Oil Separator GTC \$13.41 |
| 3/12/2021 | | Trailer Repairs - Tailgate, Light Lead, Trailer Brakes Bryan Skeen \$277.20 |
| 6/12/2021 | | Plant daily inspection nil to report. |
| 10/12/2021 | | Filter - Fuel GTC \$41.35 |
| 20/01/2022 | | Hub Cap Chrome GTC \$20.64 |
| 27/01/2022 | | Fit Run Out Tyre Riviera Tyre Service \$49.50 |
| 16/02/2022 | 218,724 | Fit 4 XZY2 Recaps - Riviera Tyre Service |
| 23/02/2022 | | Puncture Repair - Riviera Tyre Service \$55.00 |
| 4/03/2022 | | Height Control Valve, Drivers side side spotter mirror u/s, checked and replaced, Warranty - GTC \$285.34 |
| 9/03/2022 | | Filters - Lube, Fuel, Air/Oil Separator GTC \$166.74 |
| 18/03/2022 | | Supply and Fit RH Windscreen and Tint Tint a Car \$391.00 |
| 21/03/2022 | | Repair mud flap mount at l/h front of chassis Quad Dog Trailer - Jansons \$126.50 |
| 29/03/2022 | | Big Foot Grease, Hood Supports x 2, Cabover filter GTC \$639.36 |
| 29/03/2022 | | T/Less Chrome Rims x 8 - Riviera Tyre Service \$5,368.00 |
| 4/05/2022 | | Fit Run out tyre - Riviera Tyre Service \$55.00 |
| 26/05/2022 | | Repair Indicator Fault - KN Auto \$49.50 |
| 27/05/2022 | | 73100056A 5/3 Valve - Garys Hydraulic \$132.00 |
| 31/05/2022 | | Belt V Ribbed - GTC \$182.74 |
| 6/06/2022 | | Battery Tool Box Cover, Handles, Anchor Hooks - GTC \$825.29 |
| 10/06/2022 | | Filters - Lube, Fuel, Air/Oil, Fuel - GTC \$188.06 |
| 10/06/2022 | | Batteries x 4 - GTC \$761.60 |
| | 227,900 | Service vehicle as required, nil repairs required No service date supplied. |
| 20/06/2022 | | UHF Microphone - GTC \$49.01 |
| 22/06/2022 | 260,161 | Strip Tyre, Re Fit Firestone Super Single - Riviera Tyre Service \$139.00 |
| 8/07/2022 | 266,674 | Fit XDY Recaps x 4 - Riviera Tyre Service \$116.00 |
| 15/07/2022 | | ShockAbs, Airbag - GTC \$330.76 |
| 22/07/2022 | | Bush Rubber - GTC \$9.57 |
| 28/07/2022 | | Gasket AFM Device, Flange - Lipped - GTC \$80.93 |
| 9/08/2022 | | Pressure test intercooler system as loud whistle and loss of power, dismantled intercooler pipes and pressure tested, found no leaks, inspected found the exhaust dump pipe v band connecting the flexi pipe not mounted properly, Removed and refitted. - Jansons \$220.00 |
| 20/10/2022 | | Lube Filter Nano Net, Fuel Filter x 2, Air/Oil Separator - GTC \$206.50 |
| 21/10/2022 | | Fit 6 own Michelin Recaps - Riviera Tyre Service \$174.00 |
| 31/10/2022 | 320,000 | Adjust Clutch as requested by customer, Inspect engine mounts and front end as requested Found rear engine mounts, kingpins, shackle pins and bushes, radiator mounts and lower shocker rubbers require attention - GTC \$112.30 |
| 11/11/2022 | | 1616 BSPP Female, 16 Ryco E2 Energy, Spiral Guard 40mm Black Labour - Garyt's Hydraulic \$432.98 |
| 1/12/2022 | | 365/65225 Hankook AM15+ - Riviera Tyre \$1,811.00 |
| 16/12/2022 | | Kit - Shock Absorber A/G 400/4, Air Spring York Duratrac - GTC \$568.22 |
| 23/12/2022 | | Fit XDY Recaps x 8 - Riviera Tyres \$29.00 |
| 21/02/2023 | | Check and Adjust Trailer wheel bearings - Jansons \$220.00 |
| 10/03/2023 | | Handle - Rubber Hold Down, Governor valve, Chrome Trim, Lugnut cover - GTC \$338.69 |
| 29/03/2023 | | Fit Recaps x 2, Fit Run Out - Riviera Tyres \$64.00 |
| 30/03/2023 | | Filters - Lube, Fuel, Cabover Can, Air/Oil, Filter Cabover Clamp Hose x 2 Tecair 2 - GTC \$1137.30 |
| 4/04/2023 | 353,636 | Ad Blue light on dash, Found code relating to high fuel pressure, problem since fuel filter change, O ring on fuel filter pinched letting in air, Replaced fuel filter - GTC \$187.29 |

