

Fleet #	
Registration	
Make	KENWORTH
Model	T401
VIN / Chassis #	6F5000000WA418774

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
19/06/2026	41,759 kms	DAMAGED PANEL R-63985			\$0.00
06/05/2026		Retighten Wheels T-17023			\$0.00
28/04/2026	255,760 kms	DECOMISSION R-60732 Just removed stickers, replaced mudflats with plain ones and cleaned all the junk out of the truck	TRUCKLINE - 10 - A/C 510065		\$2,886.86
04/03/2026	41,575 kms	C - 100K/365Days S-28445 Front engine mounting broken Bonnet holder/bracket missing Radiator holder LHS broken Engine fan blades broken/worn Airleak underneath cab Oil leak LHS on engine underneath compressor			\$6,308.56
11/02/2026	36,814 kms	INDICATOR ISSUE R-56858 Fixed lhs indicator Broken wires			\$0.00
06/02/2026	36,327 kms	BRAKE ISSUES R-56488			\$154.00
02/02/2026	36,326 kms	TAIL LIGHT R-56188 GEARBOX CLEAN 18/6/26 NO INFO ON THIS JOB			\$0.00
18/12/2025	27,556 kms	A/C ISSUE R-54174 DENTONES REPAIR LEAK AND REGASS INV NO. 34668	DENTONE AUTO ELECTRICS - 10 (DICKENS MANAGEMENT) MQG		\$743.60
13/12/2025	25,773 kms	ENGINE COOLANT LEAK R-53697 REPLACED LEAKING COOLANT PIPE, BLED THE SYSTEM			\$336.37
18/11/2025	23,765 kms	NEW STEERS T-16245 2x 295-80R22.5 Bridgestone R154			\$1,489.49
21/10/2025	17,724 kms	REPAIRS R-51086 REPLACED WATER HOSE, REFILL AND BLEED RADIATOR , REPAIR AIRLEAK AT COMPRESSOR , REMOUNT AIRCLEANER BRACKET AND WELD BRACKETS	INLAND TRUCK CENTRES PTY LTD - 10		\$542.03
12/09/2025	12,766 kms	DRIVING LIGHT R-49451			\$545.50

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
06/09/2025	11,028 kms	B - 20K/180Days S-24579 Replaced fuel filter oil filter airfilter grease all lubrication points check all lights and turn table check oil in differential and gearbox			\$670.12
06/09/2025	11,028 kms	AIR CLEANER BRACKET R-49148 MQT401. KM11028. Carried out welding air cleaner housing mounts, fixed broken engine breather pipe,and welded a nut on the mount on engine side.			\$616.00
28/08/2025	197,000 kms	DRIVE TYRES T-13745 8x 11r22.5 haulstar HA602 drive			\$2,714.98
07/07/2025		DRIVING LIGHT, SPEEDO NOT WORKING R-44302 Was repaired by Dentone INV NO. 34038	DENTONE AUTO ELECTRICS - 10 (DICKENS MANAGEMENT) MQG		\$1,743.50
15/05/2025	189,037 kms	TRUCK ANNUAL INSPECTION - CERTIFICATE OF FITNESS I-2377			\$0.00
15/05/2025	189,037 kms	A - 10K/90Days S-22412 Did visually inspect fluids linnings linkages			\$385.00
08/05/2025		LOW COOLANT R-48632 Topped up coolant checked Eng. light has Gonne out now			\$0.00
19/03/2025	188,207 kms	B - 20K/180Days S-21125			\$922.43
10/03/2025	188,070 kms	AIR LEAK R-40739 replaced new relay valve			\$451.00
25/02/2025	184,985 kms	BULLBAR BOLTS R-37896			\$308.00
19/12/2024		A/C ISSUES R-37368 REPLACE PRESSURE SWITCH AND HOSE FLUSH AND REGASS. INV NO. 33233	DENTONE AUTO ELECTRICS - 10 (DICKENS MANAGEMENT) MQG		\$1,045.00
02/07/2024	177,851 kms	HEADLIGHT R-29393 Replaced with a new one, good to go.			\$77.00
02/07/2024	177,851 kms	HEADLIGHT R-29403 Replaced with a new one. Good to go.			\$77.00
30/06/2024	153,876 kms	WINDSCREEN R-13564 RAKESH REPLACE WINDSCREEN INV NO - 8			\$660.00
10/06/2024	177,780 kms	WASHERS INOP R-28289			\$38.50
08/06/2024	177,481 kms	DASH PANEL LOOSE R-28290 Tightened up nuts and bolts and replaced missing ones			\$154.00
07/06/2024	177,481 kms	HEADLIGHT CRACKED R-28291 replaced the headlight.			\$154.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
23/05/2024	176,825 kms	DRIVER SEAT R-16925 Air bag on drive seat is now good replaced with a new air bag.			\$646.65
03/05/2024	175,847 kms	TRUCK ANNUAL INSPECTION - CERTIFICATE OF FITNESS I-1579 Right side headlamp needs replacement (ordered)			\$0.00
03/05/2024	175,847 kms	A - 10K/90Days S-14328 Changed diff oils on the last diff Fitted new shock absorbers bushes on first diff Right side headlamp needs replacement (no stock)			\$508.77
28/03/2024	175,694 kms	A - 10K/90Days S-13690			\$385.00
28/03/2024	175,694 kms	AIR CLEANER BRACKET, AIR FILTER , BLINKER, BRAKE LIGHTS INOP, FRONT WHEEL BEARINGS, HUBSEAL, Park Light, REPLACE BRAKE LININGS, SHOCK ABSORBER R-25383 Replaced/Repairs			\$3,220.15
02/03/2024	173,890 kms	RUNOUTS T-7302 Replaced with 4 295 80 22.5 good year runouts			\$154.00
01/03/2024	173,890 kms	BROKEN MUDGUARD R-24226			\$148.87
20/02/2024	177,733 kms	REAR DIFF FAILURE R-24299 JOE AGOSTINI SUPPLY AND FIT RECO DIFF CENTRE INV NO. 520-06	J & A AGOSTINI REPAIRS & SERVICES PTY LTD		\$8,085.03
12/12/2023		STARTER MOTOR R-21151 REPLACE STARTER (matt did job)			\$1,100.00
08/11/2023	166,589 kms	COOLANT LEAK R-19836 Replaced	TRUCKLINE GRIFFITH - 10 - A/C 290155		\$620.18
25/10/2023	166,500 kms	HORTON FAN R-19306 FIT NEW HORTON FAN REPAIR KIT			\$1,210.53
23/10/2023	166,476 kms	CLUTCH BEARING FAILURE R-18250	J & A AGOSTINI REPAIRS & SERVICES PTY LTD		\$3,238.86
17/10/2023	166,476 kms	CLUTCH ADJUSTMENT, GEARBOX, OIL LEAK R-18920 Found inspection plate on bottom of gear box leaking drained oil Removed plate cleaned And re fitted with with silicone re filled gear box .. Checked clutch linkage Found a adjuster bolt had came out tightened bolt. Test drove unit clutch is working fine now and no oil leaking Found now..			\$462.00
17/09/2023	166,472 kms	CLEARANCE LIGHT R-15343 All lights working fine except for side blinker on bulbar needs new lamp	INLAND TRUCK CENTRES PTY LTD - 10		\$822.00
25/08/2023	166,446 kms	WIPER WASHERS INOP R-16926 Checked window washers Washers working fine think drive is pushing the wrong button			\$38.50
15/08/2023		OVERSIZE SIGN R-16784			\$163.06

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
10/08/2023	163,396 kms	CLUTCH FAILURE, DRIVING LIGHT, FUEL LEAK R-16646 FOUND BALL ROD ON CLUTCH LEVER BROKEN REPLACED WITH NEW ONE, FOUND FUEL FILTER DAMAGED RELACED WITH NEW FILTER, REPAIRED WIRING FOR DRIVING LIGHT ON LEFT HAND SIDE.			\$417.39
25/07/2023		HEADLIGHT BULB R-16351 TRAVEL OUT TO YARD TO REPAIR HEADLIGHT WIRING AND UPGRADE HEADLIGHTS TO LEAD DUE TO DRIVER COMPLAINT OF NO VISIBILITY / HARD TO SEE	DENTONE AUTO ELECTRICS - 10 (DICKENS MANAGEMENT) MQG		\$481.80
27/06/2023	160,542 kms	BALANCE, STEER TYRES T-4632 2 x 295 80 22.5 good year omnitrac + balance. Griffith stock Done 27/6 James			\$920.08
19/06/2023	159,049 kms	B - 20K/180Days S-8657 Replace filter kits and air cleaner and turntable rubber and pin both and replace mudguard on rear rhs broken			\$580.70
14/06/2023	158,828 kms	OIL LEAK R-13984 Eng oil leaking from oil pressure switch Removed and replaced both oil pressure switch and sensor			\$139.54
15/05/2023	150,977 kms	INDICATOR NOT WORKING R-12909 Repaired wiring still need a new indicator on RHS of bull bar Indicators are working fine now			\$0.00
10/05/2023	155,505 kms	HEADLIGHTS R-13701 Fit new headlight			\$359.94
01/05/2023	154,087 kms	TRUCK ANNUAL INSPECTION - CERTIFICATE OF FITNESS I-826 Carried out annual inspections, done.			\$0.00
24/04/2023	153,294 kms	AIR LEAK R-13378 Replaced			\$0.00
24/04/2023	153,294 kms	SUZI COIL LEAKING R-13413 Replaced			\$170.76
15/03/2023	148,596 kms	A - 10K/90Days S-7067 Carried out A service as per check list provided, done. Carried out replaced rear differential oil			\$96.25
02/03/2023	146,793 kms	WATER LEAK R-11849 Repaired coolant leak form a fitting below water pump had to make a new gasket used 50L coolant Test drove checked for coolant leak no leaks found now			\$0.00
23/02/2023	145,572 kms	BRAKE LIGHT R-11607 Repaired			\$0.00
11/02/2023	144,012 kms	OIL SEAL R-11222 REPLACE SEAL.			\$143.49
04/02/2023		A/C REPAIRS R-11479 TRAVEL OUT TO YARD TO DIAGNOSE FAULT WITH A/C EFFICIENCY NOT SATISFACTORY. FOUND WEEPING HOSE. REMOVE + REPLACE. VAC & REGAS	DENTONE AUTO ELECTRICS - 10 (DICKENS MANAGEMENT) MQG		\$563.20

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
24/01/2023		A/C REPAIRS R-10931 TRAVEL OUT TO YARD TO CARRY OUT A/C REPAIRS. REMOVE & REPLACE SEIZED COMP. FLUSH SYSTEM CHANGE DRIVER, PRESSURE TEST, VAC & REGAS	DENTONE AUTO ELECTRICS - 10 (DICKENS MANAGEMENT) MQG		\$1,434.40
20/12/2022	139,502 kms	BULLBAR R-9795 Pulled out / re fit bullbar assembly repaired bracket and run wire to driving lights and indicator lights both and oversize sign			\$0.00
15/12/2022	139,398 kms	ALTERNATOR R-9675 REPLACE ALTERNATOR			\$440.00
14/12/2022	139,274 kms	COMMISSION FOR SERVICE R-9535 SJR- REPAIR AND BRACE BULLBAR MOUNTS			\$2,946.15
11/05/2022	138,302 kms	A - 10K/90Days S-2614 A service complete done Repair clearance lights front bumper LHS DONE			\$0.00
11/05/2022	138,302 kms	TRUCK ANNUAL INSPECTION - CERTIFICATE OF FITNESS I-280 Annual inspection complete done			
17/03/2022	134,514 kms	C - 100K/365Days S-2122 C SERVICE COMPLETE DONE			\$328.47
22/11/2021	136,965 kms	C - 100K/365Days S-838 Carry out C service as per check sheet. DONE. Oil leaking from around sump need to wash and investigate. RHS kingpin grease not taking. Turntable Joist has movement. Multipul crossmember bolts loose. DONE.			\$194.84
22/11/2021	136,965 kms	MUDGAURD R-932 Replace RHS mad guard new one done			
22/11/2021	136,965 kms	TRUCK ANNUAL INSPECTION - CERTIFICATE OF FITNESS I-38 Annual inspection complete done			
70 Records				Total:	\$53,043.55