



Vehicle History Summary

Fleet #	
Registration	
Make	KENWORTH
Model	T409
VIN / Chassis #	6F50000008A439740
Build Date	2008

Date	Reading / Units	Type / Repairer Notes	Repairer
20/08/2026	463,218 kms	A - 10k S-2136 A Service, Fuel hose Leaks Hydraulic Coupling leaks 2x puncture repairs 3rd axle left and right inner	
18/06/2026		Fault R-3959 Replaced flat tyres	
04/06/2026	432,560 kms	A - 10k S-2112 A SERVICE	Internal Workshop
13/10/2025	380,977 kms	air leak, Brake Booster, Brakes, EXHAUST LEAK R-3534 adjusted steer brakes, tightened loose exhaust clamp, replaced leaking brake booster	
13/08/2025	359,895 kms	accelerator pedal R-2983 found pedal roller to be worn, replaced roller and pin test all ok 1 x pedal roller kit	Internal Workshop
17/07/2025	353,691 kms	A - 10k S-1924 Completed "A" service	Internal Workshop
10/12/2024	346,434 kms	C - 100k S-1329 C service and yearly Inspection completed.	Internal Workshop
10/12/2024	346,434 kms	Brakes, CLUTCH, Filter/Oil Change, Mounts, tail lights, TYRE, water washer, Window R-1334 REPAIRED THE FOLLOWING: LHS TAIL LIGHT 1ST DRIVE AXLE NEEDS TYRES 1ST DRIVE AXLE RHS BRAKES LHS STEER BRAKES DIFF OIL 4 GEAR BOX OIL CLUTCH ADJUSTMENT FRONT ENGINE MOUNTS DRIVERS POWER WINDOW INOP WASHERS INOP WINDOW TINT HARD TO SEE OUT OF.	Internal Workshop
03/12/2024	344,570 kms	Breakdown R-1250 travelled to maroota to clean check truck shut down, replaced fuel water seperator, test still no start, checked all fuel lines, found broken nose from filter to fuel pump, replaced nose, got good fuel pressure, vehicle started all okay.	Internal Workshop
08/11/2024	334,728 kms	horn R-1038	
07/11/2024		tailgate R-991 tailgate was repaired by a license repairer.	Internal Workshop
07/11/2024	336,389 kms	HEADLIGHTS R-1039 replaced blown globe drivers side headlight	
01/10/2024	320,020 kms	uhf R-729	Internal Workshop
01/10/2024	320,020 kms	A - 10k S-765 A Service Carried out A Service Checked all Levels. All ok	

Date	Reading / Units	Type / Repairer Notes	Repairer
22/08/2024	314,337 kms	HORTON FAN R-726	Internal Workshop
24/07/2024	309,419 kms	A - 10k S-764 A Service Carried out A Service Checked all Levels. All ok	
24/07/2024	309,419 kms	bar, LEAK R-747 3 air bags 1 sway bar 2 bushes crossmember air bag supply hose fuel hoses	Internal Workshop
25/06/2024	300,114 kms	B - 50k S-669 B service LHS Front bearing RHS 2nd axle drive 2 new tyres steer tyres	Internal Workshop
30/05/2024	299,620 kms	TYRE R-790 Replaced L/H 3rd axle tyres	Internal Workshop

Signed: _____

Name: _____

Date: _____