

## Vehicle History Detail

Fleet #	469108
Registration	
Make	KENWORTH
Model	T610 SAR
VIN / Chassis #	6F5000000LA469108

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
	143,284 kms 2,311 hrs	<b>B - 30k</b> S-1996	Workshop		\$0.00
	,	<b>B - 30k</b> S-3253 SIF: 46081718	Workshop		\$0.00
	,	<b>B - 30k</b> S-3254 Engine SIF: 46571196, Trans SIF: 46543730, Front Diff SIF: 46567140, Rear Diff SIF: 46570717	Workshop		\$0.00
		<b>C - Roadworthy</b> S-3255 Engine SIF: 46571196, Trans SIF: 46543730, Front Diff SIF: 46567140, Rear Diff SIF: 46570717	Workshop		\$0.00
		<b>B - 30k</b> S-3256 SIF: 46078028	Workshop		\$0.00
	-,	<b>B - 30k</b> S-3257 SIF: 46069643	Workshop		\$0.00
	,	<b>B - 30k</b> S-3258 SIF: 42443694	Workshop		\$0.00
	,	<b>B - 30k</b> S-4807 SIF: 46081718	Workshop		\$0.00
	,	<b>B - 30k</b> S-4808 Engine SIF: 46571196, Trans SIF: 46543730, Front Diff SIF: 46567140, Rear Diff SIF: 46570717	Workshop		\$0.00
		<b>C - Roadworthy</b> S-4809 Engine SIF: 46571196, Trans SIF: 46543730, Front Diff SIF: 46567140, Rear Diff SIF: 46570717	Workshop		\$0.00
	,	<b>B - 30k</b> S-4810 SIF: 46078028	Workshop		\$0.00
	*	<b>B - 30k</b> S-4811 SIF: 46069643	Workshop		\$0.00

Friday 14 November 2025 Page 1 of 6 www.gearbox.com.au

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
		<b>B - 30k</b> S-4812 SIF: 42443694	Workshop		\$0.00
		<b>C - Roadworthy</b> S-5195 SIF Engine: 43240881, SIF Trans: 42780615, SIF Front Diff: 42780769, SIF Rear Diff: 42780111	Workshop		\$0.00
	•	<b>B - 30k</b> S-5196 SIF Engine: 43240881, SIF Trans: 42780615, SIF Front Diff: 42780769, SIF Rear Diff: 42780111	Workshop		\$0.00
	•	<b>B - 30k</b> S-5197 SIF # 43241245	Workshop		\$0.00
	•	<b>B - 30k</b> S-5198 SIF #43254084	Workshop		\$0.00
	·	<b>B - 30k</b> S-5199 SIF # 43239659	Workshop		\$0.00
	•	<b>B - 30k</b> S-5200 SIF # 42784026	Workshop		\$0.00
	•	<b>B - 30k</b> S-5201 SIF #28848266 , SIF #42427795 , SIF #42427660 , SIF #42793370	Workshop		\$0.00
		<b>C - Roadworthy</b> S-5202 SIF # 28848266, SIF# 42427795 ,SIF #42427660, SIF # 42793370	Workshop		\$0.00
		<b>B - 30k</b> S-1517 SIF # 42787397	Workshop		\$0.00
	173,381 kms 2,803 hrs	<b>B - 30k</b> S-1518	Workshop		\$0.00
	143,284 kms 2,311 hrs	<b>B - 30k</b> S-1519	Workshop		\$0.00
	·	<b>B - 30k</b> S-1520 SIF # 28847302 , SIF # 41678214 , SIF # 41678299 , SIF# 28847278 ,	Workshop		\$0.00
	114,684 kms 1,830 hrs	C - Roadworthy S-1521	Workshop		\$0.00
	,	<b>B - 30k</b> S-1522 SIF # 28847302 , SIF # 41678214 , SIF#41678299 , SIF# 28847278	Workshop		\$0.00
	85,005 kms 1,347 hrs	<b>B - 30k</b> S-1523	Workshop		\$0.00
		<b>B - 30k</b> S-1993 SIF # 42787397	Workshop		\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
	173,381 kms 2,803 hrs	B - 30k S-1995	Workshop		\$0.00
	•	<b>B - 30k</b> S-1998 SIF # 28847302 , SIF # 41678214 , SIF # 41678299 , SIF# 28847278 ,	Workshop		\$0.00
	114,684 kms 1,830 hrs	C - Roadworthy S-2000	Workshop		\$0.00
	•	<b>B - 30k</b> S-2001 SIF # 28847302 , SIF # 41678214 , SIF#41678299 , SIF# 28847278	Workshop		\$0.00
	85,005 kms 1,347 hrs	B - 30k S-2003	Workshop		\$0.00
		<b>B - 30k</b> S-2970 SIF: 46550313	Workshop		\$0.00
		<b>B - 30k</b> S-2971 SIF: 46083969	Workshopy		\$0.00
15/05/2025		Chassis R-3473	Workshop		\$0.00
12/11/2024	698,740 kms 11,205 hrs	B - 30k S-12382	Workshop		\$0.00
07/11/2024	698,740 kms 11,205 hrs	B - 30k S-12358	Workshop		\$0.00
01/11/2024		Chassis R-1157	Workshop		\$0.00
31/10/2024		Engine R-1136	Workshop		\$0.00
31/10/2024		Engine R-1135	Workshop		\$0.00
11/10/2024	101,184 hrs	Puncture T-244 Pos 5 repaired Retention needed	Workshop		\$0.00
10/10/2024		Electrical R-805 will monitor. At this point no works will commence	Workshop		\$0.00
10/10/2024		Radiator / Cooling System R-909	Workshop		\$0.00
09/10/2024		Puncture T-251 Pos 9 repaired Retention needed	Workshop		\$0.00
02/10/2024		Engine R-869	Workshop		\$0.00
20/09/2024		Radiator / Cooling System R-788	Workshop		\$0.00
19/09/2024		B - 30k S-12233 R&R LHR brake shoes	Workshop		\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
18/09/2024		Air Conditioner R-727 Fault acknowledge, cabin filter will be changed. There is no flush for an AC system. Filters were replaced, truck is a land fill operator. smell will subside.	Workshop		\$0.00
18/09/2024		<b>B - 30k</b> S-12263 OIL SAMPLE SIF: 41802129	Workshop		\$0.00
18/09/2024		<b>Cab</b> R-716	Workshop		\$0.00
16/09/2024		Puncture T-204	Workshop		\$0.00
12/09/2024	666,405 kms	Cab R-702	Workshop		\$0.00
11/09/2024		Air Conditioner R-680	Workshop		\$0.00
09/09/2024		Steering R-644	Workshop		\$0.00
05/09/2024		Cab R-649 Windscreen repair Wednesday11/9/24 330pm	The Fixer windscreens		\$0.00
03/09/2024		Driver Damage R-603	Workshop		\$0.00
29/08/2024	658,225 kms	Radiator / Cooling System R-556	Workshop		\$0.00
29/08/2024	658,225 kms	Hydraulic cylinders/Hoses R-560	Workshop		\$0.00
29/08/2024	658,225 kms	Electrical R-555	Workshop		\$0.00
21/08/2024		Cab R-477	The Fixer windscreens		\$0.00
06/08/2024		Air Lines R-337	Workshop		\$0.00
06/08/2024		Air Lines R-323	Workshop		\$0.00
06/08/2024		Engine R-348	Diesel N LEK		\$0.00
30/07/2024		Engine R-336	Workshop		\$0.00
29/07/2024	,	<b>B - 30k</b> S-12113 OIL SAMPLE SIF: 41802005	Workshop		\$0.00
29/07/2024	•	Run Out T-119 Run out pos 8 Retention needed	Workshop		\$0.00
29/07/2024	645,145 kms	Engine R-325	Workshop		\$0.00
20/06/2024	617,542 kms 9,921 hrs	C - Roadworthy S-11795	Workshop		\$0.00
10/06/2024	617,542 kms 9,921 hrs	C - Roadworthy S-11821	Workshop		\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
10/06/2024	617,542 kms 9,921 hrs	<b>B - 30k</b> S-11820	Workshop		\$0.00
10/06/2024	617,542 kms 9,921 hrs	NHVR Heavy Vehicle Inspection I-70	Workshop		\$0.00
29/05/2024		Driveline R-75	Workshop		\$0.00
17/05/2024		Suspension R-52	Workshop		\$0.00
20/03/2024	·	<b>B - 30k</b> S-9059 SIF: 46550313	Workshop		\$0.00
03/01/2024	•	<b>B - 30k</b> S-9060 SIF: 46083969	Workshop		\$0.00
23/10/2023	·	<b>B - 30k</b> S-9874 SIF: 46081718	Workshop		\$0.00
17/08/2023		<b>C - Roadworthy</b> S-9876 Engine SIF: 46571196, Trans SIF: 46543730, Front Diff SIF: 46567140, Rear Diff SIF: 46570717	Workshop		\$0.00
17/08/2023	•	<b>B - 30k</b> S-9875 Engine SIF: 46571196, Trans SIF: 46543730, Front Diff SIF: 46567140, Rear Diff SIF: 46570717	Workshop		\$0.00
12/06/2023	•	<b>B - 30k</b> S-9877 SIF: 46078028	Workshop		\$0.00
12/04/2023	•	<b>B - 30k</b> S-9878 SIF: 46069643	Workshop		\$0.00
08/02/2023	·	<b>B - 30k</b> S-9879 SIF: 42443694	Workshop		\$0.00
21/11/2022	·	<b>C - Roadworthy</b> S-10699 SIF Engine: 43240881, SIF Trans: 42780615, SIF Front Diff: 42780769, SIF Rear Diff: 42780111	Workshop		\$0.00
21/11/2022	•	<b>B - 30k</b> S-10700 SIF Engine: 43240881, SIF Trans: 42780615, SIF Front Diff: 42780769, SIF Rear Diff: 42780111	Workshop		\$0.00
22/09/2022	,	<b>B - 30k</b> S-10701 SIF # 43241245	Workshop		\$0.00
04/08/2022		<b>B - 30k</b> S-10702 SIF #43254084	Workshop		\$0.00
07/06/2022		<b>B - 30k</b> S-10703 SIF # 43239659	Workshop		\$0.00
30/03/2022	•	<b>B - 30k</b> S-10704 SIF # 42784026	Workshop		\$0.00

Date	Reading	Type / Repairer Notes	Repairer	Invoice	Cost
25/01/2022	•	<b>C - Roadworthy</b> S-10706 SIF # 28848266, SIF# 42427795 ,SIF #42427660, SIF # 42793370	Workshop		\$0.00
25/01/2022	,	<b>B - 30k</b> S-10705 SIF #28848266 , SIF #42427795 , SIF #42427660 , SIF #42793370	Workshop		\$0.00
07/12/2021	,	<b>B - 30k</b> S-8314 SIF # 42787397	Workshop		\$0.00
14/10/2021	173,381 kms 2,803 hrs	<b>B - 30k</b> S-8315	Workshop		\$0.00
25/08/2021	143,284 kms 2,311 hrs	B - 30k S-8316	JWorkshop		\$0.00
10/07/2021		<b>B - 30k</b> S-8319 SIF # 28847302 , SIF # 41678214 , SIF#41678299 , SIF# 28847278	Workshop		\$0.00
10/07/2021	,	<b>B - 30k</b> S-8317 SIF # 28847302 , SIF # 41678214 , SIF # 41678299 , SIF# 28847278 ,	Workshop		\$0.00
10/07/2021	114,684 kms 1,830 hrs	C - Roadworthy S-8318	Workshop		\$0.00
26/05/2021	85,005 kms 1,347 hrs	B - 30k S-8320	Workshop		\$0.00
98 Records				Total:	\$0.00