

# Repair Order History

**Stock#:** 003JWH

**Rego:** 003JWH

**VIN:** 6F500000MA470902

**Model:** T659

**Body:**

**Color:** Color

**RO Date**      **RO#**

Line#	Product	Description
<b>11/10/2021      RH112630</b>		
101	CURG	CUSTOMER REPAIRS GRANT
102	LQ	Labour
103	n	Replace electrical trailer plugs for trailer lighting to heavy duty
104	n	type.
105	n	Install ABS/EBS wiring harness to rear of truck and install plug
106	n	assembly.
107	n	Install 2000 watt 240 volt inverter system and power point to truck
108	n	sleeper.
109	n	Install and wire USB power plug to sleeper.
110	WS	WORKSHOP SUPPLIES
111	OT122000RS2	2000W PURE SINE WAVE INVERTER
112	OTACX6530	FUSE HOLDER PANEL MOUNT
113	OTACX6525	200A MEGA FUSE SF51 BOLT ON
114	OT63218BL	DUES USB - CARLING SWITCH 2 PORT
115	OTREMOTERS	REDARC INVERTER REMOTE
116	OTACX1344	CABLE GLAND NYLON 32MM
117	OTACX1296	HEAT SHRINK DUAL WALL BLACK 24MM
118	OT82096	EBS 12V 7PIN SOCKET TRAILER LARGE
119	OT82196	EBS 12/24V 7 PIN PLUG TRAILER LGR
120	OT16730S	TRAILER PLUG 7PIN RND
121	OT16720S	TRAILER SOCKET 7 PIN ROUND LARGE
122	ITNA56484	CLIP
123	ITNA56487	CLIP
124	ws	POWER POINT
125	WS	240 VOLT POWER CABLE
126	WS	25MM CABLE
127	WS	EBS CABLE 7 CORE
129	WS	BATTERY LUGS
<b>10/11/2021      RH112927</b>		
101	CUS	CUSTOMER SERVICE
102	EV	ENVIRONMENTAL LEVY
103	ITZFGLF14000NN	LUBE FILTER NANO NET
104	OTFF5776	FUEL FILTER
105	ITZFGFS19764	FH230 PLUS ELEMENT -
106	ITZFGLF689	LUBE FILTER (REP.LF7
107	ITZFGHF6107	HYD.FILTER
108	ITZFGWF2126	ES WATER FILTER
109	ITZFGLF637	LUBE FILTER
110	OT121504	ATF DX-3 4L
111	ITZFGAF887KM	AIR FILTER
112	ITZFGAS2474	AIR OIL SEPARATOR
113	engineoil	ALL FLEET PLUS E900
114	transmissionoil	PREMIUM MONO 50
115	grease	OPTIMUM CHOICE GREASE
116	diffoil	HP GEAR OIL 85W/140
117	n	Carry out 1st srvice on new Kenworth. Only labour covered by KW not
120	n	parts.
<b>12/11/2021      RH112947</b>		
101	CUS	CUSTOMER SERVICE
102	LQ	Labour
103	n	Labour to perform first service. all parts covered by twin city
<b>10/11/2021      RH113032</b>		
101	CUS	CUSTOMER SERVICE
102	LQ	Labour
103	n	Carry out 1st service as per Kenworth service sheet.
<b>23/11/2021      RH113033</b>		
101	CUS	CUSTOMER SERVICE

# Repair Order History

**Stock#:** 003JWH

**Rego:** 003JWH

**VIN:** 6F5000000MA470902

**Model:** T659

**Body:**

**Color:** Color

**RO Date**      **RO#**

Line#	Product	Description
102	LQ	Labour
103	n	Carry out 1st service as per Kenworth service sheet
<b>23/11/2021      RH113034</b>		
101	CUR	CUSTOMER REPAIRS
102	LQ	Labour
103	n	Investigate hub oil leak on both sides of steer axle. Found hub cap
104	n	gaskets to be leaking. Remove and re-seal with new gaskets. Refill
105	n	hubs with oil to correct level. Return vehicle to service.
106	OT3434046	HUB CAP
107	OT3303009	GASKET FOR 6 HOLE HUB CAP
<b>07/03/2022      RH113901</b>		
101	CUS	CUSTOMER SERVICE
102	LQ	Labour
103	n	Carry out scheduled B service as per service checklist. Change engine
104	n	oil and filter. Change fuel filters. Grease truck. Adjust clutch and
105	n	brakes. Check all fluid levels. Check all lights, Check belts,
106	n	batteries and tyre condition. Jack up front end and check steering
107	n	and suspension components check for road worthiness and record any
108	n	faults found.
109	n	Carry out clutch adjustment.
110	n	Remove and replace RH front mudflap, supplied by customer.
111	n	Change AdBlue filter.
112	WS	WORKSHOP SUPPLIES
113	EV	ENVIRONMENTAL LEVY
114	OTAS2474	AIR OIL SEPARATOR
115	OTFS19764	ELEMENT
116	OTLF14000NN	LUBE FILTER
117	ENGINEOIL	VECTON 15W-40 CK-4/E9
118	GREASE	OPTIMUM CHOICE GREASE
<b>04/06/2022      RH114672</b>		
101	CUS	CUSTOMER SERVICE
102	LQ	Labour
103	n	Carry out scheduled C service. Change engine oil and filter. Change
104	n	fuel filters. Change Transmission oil. Change Diff oil. Grease truck.
105	n	Adjust clutch and brakes. Check all lights. Check all other fluid
106	n	levels. Check belts, batteries and tyre condition.
107	WS	WORKSHOP SUPPLIES
108	EV	ENVIRONMENTAL LEVY
109	OTX011623	AIR CLEANER ELEMENT
110	OTT224P	CARTRIDGE AIR DRYER
111	ITZFGLF9070	LUBE FILTER REPLACES
112	OTFF5776	FUEL FILTER
113	OTFS19764	ELEMENT
114	ITZFGLF689	LUBE FILTER (REP.LF7
115	ITZFGHF6107	HYD.FILTER
116	ITZFGLF637	LUBE FILTER
117	engineoil	VECTON 15W-40 CK-4/E9
118	diffoil	AXLE AP 85W/140
119	transmissionoil	RX MONO 40 CF
120	grease	SPHEEROL ULTRATAK
<b>13/09/2022      RH115605</b>		
101	CUS	CUSTOMER SERVICE
102	LQ	Labour
103	WS	WORKSHOP SUPPLIES
104	n	Carry out B service. Change engine oil and filter. Change fuel
105	n	filters. Grease truck. Adjust clutch and brakes. Check all fluid
106	n	levels. Check all lights, Check belts, batteries and tyre condition.
107	n	Jack up front end and check steering and suspension components, check
108	n	for road worthiness and record any faults found.

# Repair Order History

**Stock#:** 003JWH

**Rego:** 003JWH

**VIN:** 6F500000MA470902

**Model:** T659

**Body:**

**Color:** Color

**RO Date**      **RO#**

Line#	Product	Description
109	EV	ENVIRONMENTAL LEVY
110	engineoil	VECTON 15W-40 CK-4/E9
111	grease	SPHEEROL ULTRATAK
112	n	Replace rear left slack adjuster.
113	OTLF14000NN	LUBE FILTER
114	OTFF5776	FUEL FILTER
115	OTFS19764	ELEMENT
116	OTX011623	AIR CLEANER ELEMENT
117	OTA53275P1446	SLACK ADJUSTER
118	coolant	COOLANT

**01/11/2022      RH116020**

101	CUS	CUSTOMER SERVICE
102	LQ	Labour
103	WS	WORKSHOP SUPPLIES
104	n	Carry out B service. Change engine oil and filter. Change fuel
105	n	filters. Grease truck. Adjust clutch and brakes. Check all fluid
106	n	levels. Check all lights, Check belts, batteries and tyre condition.
107	n	Jack up front end and check steering and suspension components, check
108	n	for road worthiness and record any faults found.
109	n	Replace both right hand drive shocks.
111	ITZFGFLF14000NN	LUBE FILTER NANO NET
112	GREASE	SPHEEROL ULTRATAK
113	ENGINEOIL	VECTON 15W-40 CK-4/E9
114	OTX011623	AIR CLEANER ELEMENT
115	OTFF5776	FUEL FILTER
116	OTFS19764	ELEMENT
117	OTK37438K1T	KIT-SHOCK ABSORBER,A/G

**17/12/2022      RH116625**

101	CUS	CUSTOMER SERVICE
102	LQ	Labour
103	WS	WORKSHOP SUPPLIES
104	n	Carry out C service. Replace worn draw bar eye bush.
105	EV	ENVIRONMENTAL LEVY
106	OTQETN17237	ELEMENT
107	OTLF14000NN	LUBE FILTER
108	OTFF5776	FUEL FILTER
109	OTFS19764	ELEMENT
110	OTLF637	LUBE FILTER
111	OTA3380W1687	FILTER
112	OTX011623	AIR CLEANER ELEMENT
113	OT37FW1	HOOD HOOK RUBBER
114	OTT068395	BUSH-DRAW BAR EYE 50MM
115	DIFFOIL	AXLE AP 85W/140
116	TRANSMISSIONOIL	RX MONO 40 CF
117	engineoil	VECTON 15W-40 CK-4/E9
118	grease	SPHEEROL ULTRATAK

**18/02/2023      RH117128**

101	CUS	CUSTOMER SERVICE
102	LQ	Labour
103	WS	WORKSHOP SUPPLIES
104	engineoil	VECTON 15W-40 CK-4/E9
105	grease	SPHEEROL ULTRATAK
106	EV	ENVIRONMENTAL LEVY
107	OTC711006	SHOCK ABSORBER - REAR SUSPENSION
108	OTLF14000NN	LUBE FILTER
109	OT1202K065	SHOCK ABSORBER
110	n	Carry out B service. Change engine oil and filter. Change fuel
111	n	filters. Grease truck. Adjust clutch and brakes. Check all fluid
112	n	levels. Check all lights, Check belts, batteries and tyre condition.

# Repair Order History

**Stock#:** 003JWH

**Rego:** 003JWH

**VIN:** 6F5000000MA470902

**Model:** T659

**Body:**

**Color:** Color

**RO Date**      **RO#**

Line#	Product	Description
113	n	Jack up front end and check steering and suspension components, check
114	n	for road worthiness and record any faults found.
115	n	
116	n	Replaced rear shocks absorbers as required.
117	n	
118	n	
119	n	Brake check,
120	n	
121	n	
122	n	
123	n	Axle 1
124	n	
125	n	Left 95 %                      Right 95%
126	n	
127	n	Axle 2
128	n	
129	n	Left 95%                      Right 95%
130	n	
131	n	Axle 3
132	n	
133	n	Left 95%                      Right 95%

**24/03/2023      RH117478**

101	CUR	CUSTOMER REPAIRS
102	LQ	Labour
103	OTGK002	GASKET KIT 8 BOLT ROAD RANGER
104	n	Drain oil from transmission found excessive metal contamination.
105	n	Remove transmission from chassis. Strip and inspect. Found failure in
106	n	rear axillary to have failed. repair with parts supplied by twin city
107	n	/ Eaton. Refit transmission to chassis test drive to confirm repair
108	n	all ok. return to service.
109	OTDQ62DOT532	5/32 TUBE JOINER
110	OTCSC82052	BOLT

**27/04/2023      RH117834**

101	CUS	CUSTOMER SERVICE
102	LQ	Labour
103	WS	WORKSHOP SUPPLIES
104	n	Carry out B service. Change engine oil and filter. Change fuel
105	n	filters. Grease truck. Adjust clutch and brakes. Check all fluid
106	n	levels. Check all lights, Check belts, batteries and tyre condition.
107	n	Jack up front end and check steering and suspension components, check
108	n	for road worthiness, and record any faults found.
109	n	
110	n	Replaced wiper inserts.
111	n	Tightened loose PTO bolts as required.
112	n	
113	n	Advise,
114	n	Front structure area oil leak.
115	n	
116	n	Axle 1
117	n	Left 90%                      Right 90%
118	n	
119	n	Axle 2
120	n	
121	n	Left 80%                      Right 80%
122	n	
123	n	Axle 3
124	n	
125	n	Left 80%                      Right 80%
126	EV	ENVIRONMENTAL LEVY
127	ITZFGLF14000NN	LUBE FILTER NANO NET

# Repair Order History

**Stock#:** 003JWH

**Rego:** 003JWH

**VIN:** 6F5000000MA470902

**Model:** T659

**Body:**

**Color:** Color

**RO Date**      **RO#**

Line#	Product	Description
128	ITZFGFF5488	FUEL FILTER
129	ITZFGFS19764	FH230 PLUS ELEMENT -
130	ENGINEOIL	VECTON 15W-40 CK-4/E9
131	GREASE	SPHEEROL ULTRATAK
<b>04/08/2023      RH118805</b>		
101	CUS	CUSTOMER SERVICE
102	LQ	Labour
103	N	C Service
104	WS	WORKSHOP SUPPLIES
105	EV	ENVIRONMENTAL LEVY
106	SUB	REPLACE WINDSCREEN
107	N	Carried out C Service as per service sheet
108	ITZFGFL14000NN	LUBE FILTER NANO NET
109	ITZFGFF5776	FUEL FILTER
110	ITZFGFS19764	FH230 PLUS ELEMENT -
111	OTP625128	AIR FILTER
112	OTP550222	HYDRAULIC FILTER
113	OTLF689	LUBE FILTER
114	OTWF2127	COOLANT FILTER
115	ITZFGFL637	LUBE FILTER
116	ITZFGAS2474	AIR OIL SEPARATOR
117	OTT224P	CARTRIDGE AIR DRYER
118	ENGINEOIL	VECTON 15W-40 CK-4/E9
119	COOLANT	COOLANT
120	TRANSMISSIONOIL	RX MONO 40 CF
121	DIFFOIL	AXLE AP 85W/140
<b>31/08/2023      RH119096</b>		
101	CURG	CUSTOMER REPAIRS GRANT
102	LG	Labour Grant
103	WS	WORKSHOP SUPPLIES
104	CURG	CUSTOMER REPAIRS GRANT
105	OT16730S	TRAILER PLUG 7PIN RND
106	N	Diagnose and repair electrical fault with A-trailer causing lights to malfunction.
107	N	
108	N	Fault found to be trailer plug wiring. Replace trailer plug.
109	N	Install V-Dac tracking system.
110	N	Test repairs all OK. Return to service.
<b>23/09/2023      RH119332</b>		
101	CUS	CUSTOMER SERVICE
102	LQ	Labour
103	WS	WORKSHOP SUPPLIES
104	N	Carry out B service. Change engine oil and filter. Change fuel
105	N	filters. Grease truck. Adjust clutch and brakes. Check all fluid
106	N	levels. Check all lights, Check belts, batteries and tyre condition.
107	N	Jack up front end and check steering and suspension components, check
108	N	for road worthiness and record any faults found. Remove worn belts
109	N	and replace with new. Tighten loose belly bar bolts. Pressure wash
110	N	engine. Return truck to service.
111	engineoil	VECTON 15W-40 CK-4/E9
112	grease	SPHEEROL ULTRATAK
113	EV	ENVIRONMENTAL LEVY
114	ITZFGFL14000NN	LUBE FILTER NANO NET
115	ITZFGFF5776	FUEL FILTER
116	ITZFGFS19764	FH230 PLUS ELEMENT -
117	CU6PK1590	DAYCO BLUE LABEL BELT
118	CU12PK2290	BELT
<b>02/11/2023      RH119765</b>		
101	CUR	CUSTOMER REPAIRS
102	LQ	Labour

# Repair Order History

**Stock#:** 003JWH

**Rego:** 003JWH

**VIN:** 6F5000000MA470902

**Model:** T659

**Body:**

**Color:** Color

**RO Date**      **RO#**

Line#	Product	Description
103	WS	WORKSHOP SUPPLIES
104	N	Inspect engine for oil leak at front of engine to find leaking from
105	N	front structure housing. Drain oil ad coolant. Pull radiator forward
106	N	to gain access to front of engine. Remove intake piping, rocker cover
107	N	and sump. Pin time engine. Remove accessories from front cover.
108	N	Remove gear train and front structure. Clean and inspect all parts
109	N	for reuse. Refit front structure with new gasket and tension to spec.
110	N	Refit gear train and carry out engine base timing. Refit sump with
111	N	new gasket and tension to spec. Refit rocker cover and intake piping.
112	N	Remove worn front engine mounts and replace with new. Refit
113	N	accessories to front structure and resecur radiator. Fill engine
114	N	with new oil and refill with coolant. Start and run truck. Pressure
115	N	wash and road test to confirm repairs with all ok. Adjust clutch and
116	N	replace wiper blades. Return truck to service.
117	OT3687007	SEAL RECTANGULAR STRIP
118	OT3688113	PLUG, GEAR COVER
119	OT4393089	GASKET, GEAR HOUSING
120	OT5658175	GASKET, GEAR HOUSING
121	OT4299124	SEAL O RING INJECTOR
122	OT3685556	GASKET ADAPTER
123	CU4374074	SCREW, TWELVE POINT CAP
124	OT3685173	SEAL OIL
125	CU5719778	GASKET
126	OT4299125	SEAL O RING
127	OT5414049	GASKET, FUEL PUMP
128	OT4988280	GASKET HYDRAULIC PUMP
129	OT5440813	GASKET ACC DRIVE SUPPORT
130	OT4026684	GASKET OIL PAN
131	OT185848	GASKET AIR COMPRESSOR
132	OTLF14000NN	LUBE FILTER
133	OT3685701	SEAL, ORING
134	OTD131012	BUSHING FRONT ENGINE
135	OTK066404	BUSHING FRONT ENGINE
136	ENGINEOIL	VECTON 15W-40 CK-4/E9

**07/03/2024      RH120983**

101	CUS	CUSTOMER SERVICE
102	LQ	Labour
103	WS	WORKSHOP SUPPLIES
104	EV	ENVIRONMENTAL LEVY
105	OT308938583	CLUTCH KIT EATON
106	OTK4450PAC	CLUTCH KIT INC KW X SHAFTS
107	OTK4464	LEVER
108	OTE551135	LEVER-CLUTCH CONTROL
109	ITZFGLF14000NN	LUBE FILTER NANO NET
110	ITZFGFF5776	FUEL FILTER
111	ITZFGFS19764	FH230 PLUS ELEMENT -
112	ENGINEOIL	VECTON 15W-40 CK-4/E9
113	GREASE	SPHEEROL ULTRATAK
114	N	Carry out B service. Change engine oil and filter. Change fuel
115	N	filters. Grease truck. Adjust clutch and brakes. Check all fluid
116	N	levels. Check all lights, Check belts, batteries and tyre condition.
117	N	Jack up front end and check steering and suspension components, check
118	N	for road worthiness and record any faults found.
119	N	Remove and replace clutch assembly as clutch faulty. Removed tail
120	N	shaft and gearbox. Carry out a front of box RIT and new clutch. Refit
121	N	gearbox with new oil. Carry out test drive all OK
122	TRANSMISSIONOIL	RX MONO 40 CF
123	SUB	MACHINE FLYWHEEL
124	OTE440309	HALO O'RING KIT

**05/07/2024      RH122330**

# Repair Order History

**Stock#:** 003JWH

**Rego:** 003JWH

**VIN:** 6F5000000MA470902

**Model:** T659

**Body:**

**Color:** Color

**RO Date**      **RO#**

Line#	Product	Description
101	CUS	CUSTOMER SERVICE
102	LQ	Labour
103	WS	WORKSHOP SUPPLIES
104	EV	ENVIRONMENTAL LEVY
105	ITZFGLF14000NN	LUBE FILTER NANO NET
106	OTFF5776	FUEL FILTER
107	ITZFGAS2474	AIR OIL SEPARATOR
108	N	Carry out C service. Change engine,transmission and diff oils and
109	N	filters. Change fuel filters. Grease truck. Adjust clutch and brakes.
110	N	Check all fluid levels. Check all lights, Check belts, batteries and
111	N	tyre condition.
112	N	Jack up front end and check steering and suspension components, check
113	N	for road worthiness and record any faults found.
114	n	Removed and replaced air drier assembly.
115	ITZFGFS19764	FH230 PLUS ELEMENT -
116	ITZFGHF6107	HYD.FILTER
117	ITZFGLF689	LUBE FILTER (REP.LF7
118	ITZFGLF637	LUBE FILTER
119	ENGINEOIL	VECTON 15W-40 CK-4/E9
120	TRANSMISSIONOIL	RX MONO 40 CF
121	DIFFOIL	AXLE AP 85W/140
122	OT620300	AIR DRIER
123	OTP625128	AIR FILTER
124	GREASE	SPHEEROL ULTRATAK
<b>26/08/2024      RH122904</b>		
101	CUS	CUSTOMER SERVICE
102	LQ	Labour
103	WS	WORKSHOP SUPPLIES
104	EV	ENVIRONMENTAL LEVY
105	OTMBD190L	RED DRUM
106	OTKSMA3124707QP	KIT LINED SHOE MA312 Q+
107	OTWBK3DCRV	KIT-W/BRG DRIVE
108	N	Carried out defect repairs. Removed and replaced axle 2 both sides
109	N	brake drums, brake linings, bearings and hub seals.
110	RI	DEFECT CLEARANCE
111	N	Carry out clearance of defect notice AHV1531694 and lodge on RMS
112	N	system
<b>13/12/2024      RH124101</b>		
101	CUR	CUSTOMER REPAIRS
102	SUB	FILL DIESEL AND BLEED
103	N	ORGANISE MECHANIC TO ATTEND SITE IN WOLLONGONG TO FILL DIESEL, BLEED
104	N	AND START ENGINE.
<b>19/12/2024      RH124164</b>		
101	CUR	CUSTOMER REPAIRS
102	n	Sublet C & D Truck Repairs to replace left hand rear front air bag on
103	n	truck.
104	SUB	REPLACE AIR BAG
<b>14/03/2025      RH125026</b>		
101	CUS	CUSTOMER SERVICE
102	LQ	Labour
103	WS	WORKSHOP SUPPLIES
104	EV	ENVIRONMENTAL LEVY
105	ITZFGLF14000NN	LUBE FILTER NANO NET
106	ITZFGFF5776	FUEL FILTER
107	ITZFGFS19764	FH230 PLUS ELEMENT -
108	OTG334707QPMG2A	LINED SHOE KIT - MERITOR 23000LB Q + 7"
109	ITRE2208S1215	GASKET AXLE
110	OTMBD190L	RED DRUM
111	OTF13CR47693	SEAL -CR SCOTSEAL

# Repair Order History

**Stock#:** 003JWH

**Rego:** 003JWH

**VIN:** 6F5000000MA470902

**Model:** T659

**Body:**

**Color:** Color

**RO Date**      **RO#**

Line#	Product	Description
112	OT620300	AIR DRIER
113	N	Carry out B service. Change engine oil and filter. Change fuel
114	N	filters. Grease truck. Adjust clutch and brakes. Check all fluid
115	N	levels. Check all lights, Check belts, batteries and tyre condition.
116	N	Jack up front end and check steering and suspension components, check
117	N	for road worthiness and record any faults found.
118	N	Removed and replaced air dryer assembly.
119	N	Removed and replaced brake drum, brake linings and hub seal and
120	N	cleaned wheel bearing on LH side 1st drive axle.
121	ENGINEOIL	VECTON 15W-40 CK-4/E9
122	GREASE	SPHEEROL ULTRATAK
123	DIFFOIL	AXLE AP 85W/140

**21/05/2025      RH125711**

101	CUS	CUSTOMER SERVICE
102	LQ	Labour
103	WS	WORKSHOP SUPPLIES
104	EV	ENVIRONMENTAL LEVY
105	ITZFGLF14000NN	LUBE FILTER NANO NET
106	ITZFGFF5776	FUEL FILTER
107	ITZFGFS19764	FH230 PLUS ELEMENT -
108	ITZFGHF6107	HYD.FILTER
109	ITZFGLF689	LUBE FILTER (REP.LF7
110	ITZFGLF637	LUBE FILTER
111	ITZFGAS2474	AIR OIL SEPARATOR
112	OTT224P	CARTRIDGE AIR DRYER
113	N	Carry out C service. Change engine, transmission and diffs oils and
114	N	filters. Change fuel filters. Grease truck. Adjust clutch and brakes.
115	N	Check all fluid levels. Check all lights, Check belts, batteries and
116	N	tyre condition.
117	N	Jack up front end and check steering and suspension components, check
118	N	for road worthiness and record any faults found.
119	OTP625128	AIR FILTER
120	ENGINEOIL	VECTON 15W-40 CK-4/E9
121	TITAN	TITAN ATF DEXRON 3
122	DIFFOIL	AXLE AP 85W/140
123	TRANSMISSIONOIL	RX MONO 40 CF
124	GREASE	SPHEEROL ULTRATAK

**24/11/2025      RH127727**

101	CUS	CUSTOMER SERVICE
102	LQ	Labour
103	WS	WORKSHOP SUPPLIES
104	EV	ENVIRONMENTAL LEVY
105	ITZFGLF14000NN	LUBE FILTER NANO NET
106	ITZFGFF5776	FUEL FILTER
107	ITZFGFS19764	FH230 PLUS ELEMENT -
108	OT3100189	BELT V RIBBED
109	OT89440	TENSIONER BELT AUTOMATIC
110	N	Carry out B service. Change engine oil and filter. Change fuel
111	N	filters. Grease truck. Adjust clutch and brakes. Check all fluid
112	N	levels. Check all lights, Check belts, batteries and tyre condition.
113	N	Jack up front end and check steering and suspension components, check
114	N	for road worthiness and record any faults found.
115	N	Removed and replaced coolant hose clamp on top of engine.
116	N	Retightened mudguard bracket on 1st drive axle LH side.
117	N	Topped up steering oil.
118	N	Investigate charging issue found bad connection to positive terminal
119	N	on alternator. replace terminal found belt and tensioner worn.
120	N	Removed and replaced both belt and tensioner. Also found alternator
121	N	front bearing has play and noisy. Removed and replaced alternator.
122	N	Tested repairs all tested OK.

# Repair Order History

**Stock#:** 003JWH

**Rego:** 003JWH

**VIN:** 6F500000MA470902

**Model:** T659

**Body:**

**Color:** Color

**RO Date**      **RO#**

Line#	Product	Description
123	CURG	CUSTOMER REPAIRS GRANT
124	LG	Labour Grant
125	WS	WORKSHOP SUPPLIES
126	CURG	CUSTOMER REPAIRS GRANT
127	ENGINEOIL	VECTON 15W-40 CK-4/E9
128	GREASE	SPHEEROL ULTRATAK
129	TITAN	TITAN ATF DEXRON 3
130	OTALTA1771	ALT 12V 160A MITSUBISHI

**09/01/2026      RH128098**

101	CUS	CUSTOMER SERVICE
102	LQ	Labour
103	WS	WORKSHOP SUPPLIES
104	EV	ENVIRONMENTAL LEVY
105	OTMG650DB	MUDGUARD-DARK BLUE
106	OTD131012	BUSHING FRONT ENGINE
107	OTK066404	BUSHING FRONT ENGINE
108	OTD1310014	BUSHING-REAR ENGINE BAR
109	OTK066421	BUSHING SNUBBER BAR
110	OT4CM00234	AIRBAG SPRING CAP
111	OT1202K065	SHOCK ABSORBER
112	OT73D2002	BUSH-SHOCK ABSORBER
113	OTSSBK1	SPRAYSAFE BRACKET KIT
114	OTK066310	BUSH-RUBBER
115	OTMS24	PLATE-REINFORCING, MUDF
116	OTG334707QPMG2A	LINED SHOE KIT - MERITOR 23000LB Q + 7"
117	OTMBD190L	RED DRUM
118	OT57Y3308	TORQUE ROD BUSH AIR GLIDE
119	OTPMDS1720	DRESS STRIP - STAINLESS
120	OTSST1	SUPPORT-FENDER CHASSIS
121	OTA11205X2728	SEAL-PINION, MULTI LIP
122	OTK1T2638	KIT PINION NUT
123	OTA11205Y2729	SEAL-PINION, MULTI LIP
124	OTK1T2637	PINION NUT 160
125	OT15000070	BUMPER RUBBER
126	OT2417WKW	MUDFLAP
127	N	Removed and replaced all shock bushes.
128	N	Removed and replaced 2 x cab shocks.
129	N	Removed and replaced LH side cab airbag.
130	N	Removed and replaced cab mount rubber block.
131	N	Removed and replaced all drive guards and hardware.
132	N	Removed and replaced both 1st drive mudflaps.
133	N	Removed and replaced front and rear engine mounts.
134	N	Carried out A service and found 2 x missing studs on horton fan. Made
135	N	new studs and refitted horton fan hub.
136	N	Removed and replaced both 1st drive pinion seals.
137	N	Removed and replaced 1st drive torque rod bushes.
138	N	Removed and replaced 2nd drive axle brake drums and brake linings
139	N	both sides.

**17/11/2021      SH100476**

102	LQ	Labour
-----	----	--------

**23/11/2021      SH100477**

102	LQ	Labour
-----	----	--------