

SERVICE TAX INVOICE

Invoice To: 7636
Paccar Policy/Parts Warranty
64 Canterbury Road
BAYSWATER VIC 3153

Deliver To:
Fraser's Livestock Transport
332 Warwick - Killarney Rd
WARWICK QLD 4370

Document No.:	2043964
Document Date:	5/11/2020
Repair Order No.:	674173
RO Creation Date:	5/11/2020
Rego No.:	681SDZ
Make/Model:	KENWORTH T659
Vehicle ID No.:	6F500000CA446403
Fleet No:	
Odometer:	1589250
Engine Hours:	
Delivery Date:	
Invoice To:	7636
Customer ABN:	
P/Order No.:	TW1096
Page:	1 of 1

KW048 Fuel gauge not reading correctly - TW1096

KW048, Instruments, Gauges and Senders

<u>Part Number</u>	<u>Part Description</u>	<u>Quantity</u>
K152-526	SENDER-FUEL TANK 625MM RND	1.00

Advisor: Scott Astbury

Workshop Trading Hours: Mon-Fri 7am to 6pm, Sat 8am to 12pm
*** Refrigerant trading authority number: AU13435 ***

Bank Account Details for Direct Payments:

Bank: CBA Branch: Kyogle
BSB: 062563 Account No.: 10059314 Account Name: The Brown and Hurley Group Pty Ltd

Customer's Signature

SERVICE TAX INVOICE

Invoice To: 1686
Fraser's Fleet Holdings Pty Ltd
PO Box 1073
WARWICK QLD 4370

Deliver To:
Fraser's Livestock Transport
332 Warwick - Killarney Rd
WARWICK QLD 4370

Document No.:	2009999
Document Date:	23/09/2020
Repair Order No.:	669164
RO Creation Date:	14/09/2020
Rego No.:	681SDZ
Make/Model:	KENWORTH T659
Vehicle ID No.:	6F500000CA446403
Fleet No:	
Odometer:	559983
Engine Hours:	
Delivery Date:	
Invoice To:	1686
Customer ABN:	62151848378
P/Order No.:	15385
Page:	1 of 1

K011 Horton not cutting in auto matically, but cuts in manually.must be gone by 930 if possible. Driver waiting 0427
584 134 - Andrew

Inspected horton not cutting in.
run truck up to temp and found coolant temp 20 degress lower than oil temp.
Drained coolant and removed and repalced engine coolant temp sensor. refilled with coolant and run up and found to read all ok
and fan to kick in.
Fan cut in temp @ 100 deg
Cut out temp @ 95 deg

<u>Part Number</u>	<u>Part Description</u>	<u>Quantity</u>
4954905	SENSOR TEMP (COOLANT)	1.00

Advisor: MARK DILLON

Workshop Trading Hours: Mon-Fri 7am to 6pm, Sat 8am to 12pm
*** Refrigerant trading authority number: AU13435 ***

Bank Account Details for Direct Payments: _____ Customer's Signature
Bank: CBA Branch: Kyogle
BSB: 062563 Account No.: 10059314 Account Name: The Brown and Hurley Group Pty Ltd

SERVICE TAX INVOICE

Invoice To: 1686
CM FRASER & SONS PTY LTD
PO Box 1073
WARWICK QLD 4370

Deliver To:
Fraser's Livestock Transport
332 Warwick - Killarney Rd
WARWICK QLD 4370

Document No.:	1840192
Document Date:	24/02/2020
Repair Order No.:	650876
RO Creation Date:	21/02/2020
Rego No.:	681SDZ
Make/Model:	KENWORTH T659
Vehicle ID No.:	6F500000CA446403
Fleet No:	
Odometer:	454391
Engine Hours:	
Delivery Date:	
Invoice To:	1686
Customer ABN:	50058772866
P/Order No.:	13880
Page:	1 of 1

break

Attend breakdown at B&H Workshop- major oil leak

Lowered bullbar and raised bonnet. Ran engine to check for leak. Found main oil leak on block at compressor area. Upon further inspection found oil leaking from oil pressure switch. Removed and replaced switch. Took truck to wash bay, sprayed with kero and pressure cleaned as there was a large amount of oil on engine and tanks, etc. Cleaned up bay in workshop as there was a fair amount of oil that had dripped off the truck. (BK)

<u>Part Number</u>	<u>Part Description</u>	<u>Quantity</u>
1745-2443	SWITCH-LOW OIL PRESSURE	1.00
1324.05	PREMIUM BLUE 8600 5L OIL	1.00

Advisor: Alan Gordon

Workshop Trading Hours: Mon-Fri 8am to 5pm, Sat 8:30am to 11:30am

*** Refrigerant trading authority number: AU41293 ***

Bank Account Details for Direct Payments:

Bank: CBA Branch: Kyogle

BSB: 062563 Account No.: 10059314 Account Name: The Brown and Hurley Group Pty Ltd

Customer's Signature

SERVICE TAX INVOICE

Invoice To: 1686
CM Fraser & Sons Pty Ltd
PO Box 1073
WARWICK QLD 4370

Deliver To:
Fraser's Livestock Transport
332 Warwick - Killarney Rd
WARWICK QLD 4370

Document No.: 1598065
Document Date: 8/04/2019
Repair Order No.: 579323
RO Creation Date: 5/04/2019
Rego No.: 681SDZ
Make/Model: KENWORTH T659
Vehicle ID No.: 6F500000CA446403
Fleet No:
Odometer: 341288
Engine Hours:
Delivery Date:
Invoice To: 1686
Customer ABN: 50058772866
P/Order No.: 11790
Page: 1 of 1

K039 Inspect and pressure test charge air cooler and replace boost hoses.

Pressure test after cooler and remove and repalce boost hose and clamps, retest and found all ok.
Tested air compressor line and found all ok.

<u>Part Number</u>	<u>Part Description</u>	<u>Quantity</u>
367-400-060	CHARGE AIR HOSE	1.00
848-66X	CLAMP-HOSE,105-113MM	2.00

Advisor: MARK DILLON

Workshop Trading Hours: Mon-Fri 7am to 6pm, Sat 8am to 12pm
*** Refrigerant trading authority number: AU13435 ***

Bank Account Details for Direct Payments:

Bank: CBA Branch: Kyogle
BSB: 062563 Account No.: 10059314 Account Name: The Brown and Hurley Group Pty Ltd

Customer's Signature