

SERVICE TAX INVOICE

Invoice To: 2965
WAGNER INVESTMENTS PTY LTD
PO BOX 151
DRAYTON QLD 4350

Deliver To:
Wagners Holding Company Limited
ABN 49 622 632 848
11 Ballera Court
WELLCAMP QLD 4350

Document No.: 2569742
Document Date: 31/08/2022
Repair Order No.: 740302
RO Creation Date: 31/08/2022
Rego No.: XQ87HS
Make/Model: 2020 KENWORTH T659
Vehicle ID No.: 6F5000000LA467287
Fleet No: TKP767
Odometer:
Engine Hours:
Delivery Date: 07/03/2020
Invoice To: 2965
Customer ABN: 66011055271
P/Order No.: 5037986
Page: 1 of 1

K018 Repair damaged input shaft thread on Dan Front Diff Serial Number: 236310

Repair damaged input shaft thread on Dan Front Diff Serial Number: 236310

Put diff up into stand. Check input yoke nut, could not remove input nut at Mt Isa. Remove nut and found thread was picked up.
(Diff sent back originally without the yoke)

Strip down power divider assembly. Replace input shaft with another shaft from a failed diff. Shaft in good condition. Reassemble diff, refit yoke and new nut kit. Pack into frame.

<u>Part Number</u>	<u>Part Description</u>	<u>Quantity</u>
131008K	KIT-PINION OIL SEAL & NUT	1.00

Advisor: Ian Wayman

Workshop Trading Hours: Mon-Fri 7am to 6pm, Sat 8am to 12pm
*** Refrigerant trading authority number: AU13435 ***

Bank Account Details for Direct Payments:

Bank: CBA Branch: Kyogle
BSB: 062563 Account No.: 10059314 Account Name: The Brown and Hurley Group Pty Ltd

Customer's Signature

SERVICE TAX INVOICE

Invoice To: 26556
Wagner Investments Pty Ltd PPFS Account
PO Box 151
DRAYTON NORTH QLD 4350

Deliver To:
Wagners Holding Company Limited
ABN 49 622 632 848
11 Ballera Court
WELLCAMP QLD 4350

Document No.: 3758714
Document Date: 9/01/2026
Repair Order No.: 955959
RO Creation Date: 2/01/2026
Rego No.: XQ87HS
Make/Model: 2020 KENWORTH T659
Vehicle ID No.: 6F500000LA467287
Fleet No: TKP767
Odometer:
Engine Hours:
Delivery Date: 07/03/2020
Invoice To: 26556
Customer ABN: 66 011 055 271
P/Order No.: AU00045729
Page: 1 of 1

ESTDIFREB Strip down, clean and inspect Front DANA Serial Number: 251673

Strip down, clean and inspect parts. Found helical gear, power divider and output side gear damaged and hard facing coming off. Fit all new bearings, thrusts and seal. Fit updated power divider. Replace failed gears. Set pre load and backlash. Paint diff, put in shipping box, send to Mt Isa.

<u>Part Number</u>	<u>Part Description</u>	<u>Quantity</u>
504128	KIT-BEARING D190 D/S590	1.00
HS108	THRUST WASHER - SIDE GEAR	2.00
300HS100-1	THRUST WASHER	4.00
10011380	HELICAL SIDE GEAR ASSY	1.00
10005175	GEAR-SIDE OUTPUT PUMP TYPE	1.00
513878-A	KIT-MANIFOLD PARTS	1.00
132440-B	WASHER-THRUST, INPUT SHAFT DIF	1.00
512892-A	KIT - AIR LOCKOUT REPAIR D170/	2.00
504364-1	LUBE PUMP KIT	1.00
Comments: 1x Arrived 09/01		
FREIGHT	FREIGHT	1.00

Advisor: Ian Wayman

Workshop Trading Hours: Mon-Fri 7am to 6pm, Sat 8am to 12pm
*** Refrigerant trading authority number: AU13435 ***

Bank Account Details for Direct Payments:

Bank: CBA Branch: Kyogle
BSB: 062563 Account No.: 10059314 Account Name: The Brown and Hurley Group Pty Ltd

Customer's Signature

SERVICE TAX INVOICE

Invoice To: 2965
WAGNER INVESTMENTS PTY LTD
PO BOX 151
DRAYTON QLD 4350

Deliver To:
Wagners Holding Company Limited
ABN 49 622 632 848
11 Ballera Court
WELLCAMP QLD 4350

Document No.: 3699223
Document Date: 31/10/2025
Repair Order No.: 947190
RO Creation Date: 15/10/2025
Rego No.: XQ87HS
Make/Model: 2020 KENWORTH T659
Vehicle ID No.: 6F500000LA467287
Fleet No: TKP767
Odometer:
Engine Hours:
Delivery Date: 07/03/2020
Invoice To: 2965
Customer ABN: 66011055271
P/Order No.: AU00039892
Page: 1 of 1

ESTDIFREB

Strip down, clean and inspect Rear DANA Serial number 230769 (Bolts fallen out of the crown wheel)

Put diff in rebuild frame, found all bolts had had come out of the crown wheel. Remove carrier and check for damage, found severe fretting and diff not viable. Remove from roll over stand.

Order new diff centre. Paint new diff, put in transport box and send to Mt Isa:

**** New diff Serial Number: 341975 ****

<u>Part Number</u>	<u>Part Description</u>	<u>Quantity</u>
515740	DRIVEHEAD	1.00
FREIGHT	FREIGHT	1.00

Advisor: Ian Wayman

Workshop Trading Hours: Mon-Fri 7am to 6pm, Sat 8am to 12pm

*** Refrigerant trading authority number: AU13435 ***

Bank Account Details for Direct Payments:

Bank: CBA Branch: Kyogle

BSB: 062563 Account No.: 10059314 Account Name: The Brown and Hurley Group Pty Ltd

Customer's Signature

SERVICE TAX INVOICE

Invoice To: 2965
WAGNER INVESTMENTS PTY LTD
PO BOX 151
DRAYTON QLD 4350

Deliver To:
Wagners Holding Company Limited
ABN 49 622 632 848
11 Ballera Court
WELLCAMP QLD 4350

Document No.: 2822641
Document Date: 31/03/2023
Repair Order No.: 775238
RO Creation Date: 13/02/2023
Rego No.: XQ87HS
Make/Model: 2020 KENWORTH T659
Vehicle ID No.: 6F5000000LA467287
Fleet No: TKP767
Odometer:
Engine Hours:
Delivery Date: 07/03/2020
Invoice To: 2965
Customer ABN: 66011055271
P/Order No.: 5044053
Page: 1 of 1

K002

Strip, inspect, Quote to rebuild rear dana diff serial no HN05258228

Strip down rear dana diff, found crown wheel and pinion damaged beyond reasonable repair. Order and supply new diff.

<u>Part Number</u>	<u>Part Description</u>	<u>Quantity</u>
515762	HEAD AXLE R190D 5.25 NO YOKE	1.00

Comments: 1x arrived aw 27/2
S/N...283074

Advisor: Ian Wayman

Workshop Trading Hours: Mon-Fri 7am to 6pm, Sat 8am to 12pm
*** Refrigerant trading authority number: AU13435 ***

Bank Account Details for Direct Payments:

Bank: CBA Branch: Kyogle
BSB: 062563 Account No.: 10059314 Account Name: The Brown and Hurley Group Pty Ltd

Customer's Signature

SERVICE TAX INVOICE

Invoice To: 2965
WAGNER INVESTMENTS PTY LTD
PO BOX 151
DRAYTON QLD 4350

Deliver To:
Wagners Holding Company Limited
ABN 49 622 632 848
11 Ballera Court
WELLCAMP QLD 4350

Document No.: 2645698
Document Date: 30/09/2022
Repair Order No.: 746400
RO Creation Date: 5/09/2022
Rego No.: XQ87HS
Make/Model: 2020 KENWORTH T659
Vehicle ID No.: 6F5000000LA467287
Fleet No: TKP767
Odometer:
Engine Hours:
Delivery Date: 07/03/2020
Invoice To: 2965
Customer ABN: 66011055271
P/Order No.: TKP767
Page: 1 of 1

ESTDIFREB

Strip down, inspect, quote and rebuild DANA Rear Diff Serial Number: HNO5258228 (5.25) Sent down from Mt Isa. (New diff fitted at Mt Isa 230769)

*** BEARING KIT IN R/O SHED*****9/9/2022

Set up in roll over stand. Strip down and inspect. Found contamination in bearings, bearings breaking up. Crown wheel and pinion in good condition. Assemble diff with new bearings, thrusts and seals. Set preload and backlash. Wrap diff in plastic. Place into frame. Send diff to Mt Isa.

<u>Part Number</u>	<u>Part Description</u>	<u>Quantity</u>
504131	BEARING KIT	1.00
<i>Comments: QTY 1 X ARRIVED - RO SHED PM 9/9</i>		
HS108-1	THRUST WASHER - SIDE GEAR	2.00
300HS100-1	THRUST WASHER	4.00
131008K	KIT-PINION OIL SEAL & NUT	1.00
126187	PINION PILOT BEARING	1.00
<i>Comments: QTY 1 X ARRIVED - RO SHED PM 8/9</i>		
1U5517	Disc	2.00

Advisor: Ian Wayman

Workshop Trading Hours: Mon-Fri 7am to 6pm, Sat 8am to 12pm
*** Refrigerant trading authority number: AU13435 ***

Bank Account Details for Direct Payments:

Bank: CBA Branch: Kyogle
BSB: 062563 Account No.: 10059314 Account Name: The Brown and Hurley Group Pty Ltd

Customer's Signature

For Terms & Conditions, please see our website www.brownandhurley.com.au or ask at any of our branches.

www.brownandhurley.com.au

KYOGLE | DARRA | TOWNSVILLE | COFFS HARBOUR | ROCKHAMPTON | YATALA | TOOWOOMBA | TAMWORTH | CABOOLTURE